

YEAR 1 MONITORING REPORT

ADKIN BRANCH STREAM RESTORATION PROJECT PHASE 1 – WASHINGTON AVE. TO LINCOLN ST.

Lenoir County, North Carolina

Project ID No. 050656101



Submitted to:



NCDENR-Ecosystem Enhancement Program

2728 Capital Boulevard, Suite 1H 103

Raleigh, North Carolina 27604

Construction Completed: April 2011

Morphology Data Collected: October 2011

Vegetation Data Collected: October 2011

Submitted: January, 2012

Prepared by:



Florence & Hutcheson

CONSULTING ENGINEERS

&

Axiom Environmental, Inc.
218 Snow Avenue
Raleigh, North Carolina 27603

Design Firm:

Florence & Hutcheson, Inc.
5121 Kingdom Way, Suite 100
Raleigh, North Carolina 27607
919.851.6066
919.851.6846 (fax)

I HEREBY CERTIFY THAT THE DOCUMENTS CONTAINED HEREIN, UT TO THE LUMBER RIVER YEAR 1 MONITORING REPORT WERE PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.

SIGNED SEALED, AND DATED THIS _____ DAY OF _____ 2011.

Chris L. Smith, PE

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
1.0 EXECUTIVE SUMMARY.....	2
1.1 GOALS AND OBJECTIVES.....	2
1.2 VEGETATION.....	3
1.3 STREAM STABILITY.....	4
1.4 WETLANDS.....	5
1.5 NOTE.....	5
2.0 METHODOLOGY.....	5
3.0 RERFERENCES.....	6
APPENDIX A. PROJECT VICINITY MAP AND BACKGROUND TABLES.....	7
APPENDIX B. VISUAL ASSESSMENT DATA.....	14
APPENDIX C. VEGETATION PLOT DATA.....	41
APPENDIX D. STREAM SURVEY DATA.....	45
APPENDIX E. HYDROLOGIC DATA.....	75
APPENDIX F. CREDIT CALCULATION FIGURES.....	76

LIST OF FIGURES

<u>FIGURE</u>	<u>PAGE</u>
Figure 1. Vicinity Map.....	8
Figures 2.0-2.12. Current Condition Plan View.....	15
Figures 3.1-3.20. Vegetation Plot Photos and Problem Areas.....	33
Figures 4.1-4.17. Cross Section Plots and Photos.....	46
Figures 5.1-5.3. Longitudinal Profile Plots.....	64
Figures 6.1 & 6.2 Crest Gauge Photos.....	75
Figures D.1-D.5. Credit Calculation Figures.....	76

LIST OF TABLES

<u>TABLE</u>	<u>PAGE</u>
Table 1. Project Components and Mitigation Credits.....	10
Table 2. Project Activity and Reporting History.....	11
Table 3. Project Contacts Table.....	12
Table 4. Project Attributes Table.....	13
Table 5.1-5.3. Visual Stream Morphology Stability Assessment.....	29
Table 6. Vegetation Condition Assessment.....	32
Table 7. Vegetation Plot Criteria Attainment.....	41
Table 8. CVS Vegetation Plot Metadata.....	42
Table 9.1-9.2. CVS Stem Count Total and Planted by Plot and Species.....	43
Table 10.1-10.3. Baseline Stream Data Summary.....	68
Table 11. Monitoring Data - Dimensional Morphology Summary.....	71
Table 12.1-12.3. Monitoring Data - Stream Reach Data Summary.....	72
Table 13. Verification of Bankfull Events.....	75

1.0 EXECUTIVE SUMMARY

The following report summarizes the vegetation establishment and stream stability for Year 1 monitoring for Phase 1 of the Adkin Branch Stream Restoration Project (Site) in Lenoir County, North Carolina.

1.1 Goals and Objectives

The primary goals of the Adkin Branch Stream Restoration Project focus on:

- Restoring a stable dimension, pattern, and profile to Adkin Branch and UT to Adkin Branch (UT)
- Improving water quality
- Decreasing floodwater levels
- Restoring aquatic and riparian habitat
- Implementing best management practices (BMPs) for stormwater quality and retention

These goals will be achieved through the following objectives:

- Reducing sediment input to Adkin Branch by restoring 7,579 linear feet of stream to a stable dimension, pattern, and profile, and establishing a vegetated stream bank, floodplain, and terrace forest. Forest vegetation species were selected by studying a Reference Forest Ecosystem located directly upstream of the Project and reviewing species listed in *Classification of the Natural Communities of North Carolina: Third Approximation* (Schafale and Weakley 1990) for a Coastal Plain Levee Forest. A total of 32.44 acres of the conservation easement were reforested.
- Promoting floodwater attenuation and decreasing floodwater levels by excavating a gently sloping floodplain that begins at the bankfull discharge elevation and slopes up to the terrace elevation, in addition to increasing roughness in the floodplain by establishing a vegetated riparian buffer.
- Improving aquatic habitat by enhancing stream bed variability (ripple-pool sequence), and introducing woody debris in the form of rootwads, log vanes, and log sills. A ripple-pool sequence and woody debris structures will provide places for forage, cover, and reproduction for fauna and flora.
- Improving terrestrial habitat by restoring a forested riparian corridor through a highly urbanized environment, which has historically experienced vegetation maintenance and forest segmentation. This corridor will provide a diversity of habitats such as mature forest, early successional forest, riparian wetlands and uplands.
- Reducing nonpoint source pollution associated with urban land uses (i.e. maintained ball fields, roadways, residential communities, etc.) by providing a vegetated riparian buffer adjacent to streams to treat surface runoff. Reforestation of the Project resulted in a total of 1,171,272 sq. ft. (26.89 acres) of Neuse River Riparian Buffers (area within 200' of top of bank of channel that is at least 50' wide).
- Improving water quality by creating 0.69 acres of riparian stormwater wetland adjacent to the UT, implementing six (6) sand filter device BMPs along Adkin Branch for

stormwater runoff to retain sediments and nutrients prior to entering Adkin Branch, and removing creosote timber retaining walls throughout the project.

1.2 Vegetation

Stream Vegetation Success Criteria

Vegetation monitoring will be considered successful for stream mitigation credit if at least 260 stems/acre (trees and shrubs), both, volunteer and planted, are surviving at the end of five years. The interim measure of vegetative success for the site will be the survival of at least 320 3-year old stems per acre at the end of year three of the monitoring period and 280 4-year old stems per acre at the end of year four of the monitoring period (USACE et al. 2003).

Riparian Buffer Vegetation Success Criteria

Vegetation monitoring will be considered successful for riparian buffer mitigation credit if at least 320 native planted hardwood stems/acre (trees only) are surviving at the end of year five. Planted vegetation must include a minimum of at least two planted native hardwood tree species. There is no interim measure of vegetative success for riparian buffers.

Monitoring Results

Stem counts were based on an average of the evaluated vegetation plots. Based on the number of stems counted toward stream mitigation credit, average densities were measured at 467 planted stems per acre (excluding livestakes) surviving in year 1 (2011). Average densities for stems counted toward riparian buffer mitigation credit were measured at 340 planted stems per acre (excluding livestakes) surviving in year 1 (2011). The dominant species identified at the Site were planted stems of silky dogwood (*Cornus amomum*), river birch (*Betula nigra*), and southern red oak (*Quercus falcata*).

Eleven of the twenty-two individual vegetation plots met stream and buffer vegetation success criteria when counting planted stems alone. Three plots (Plots 10, 11, and 22) didn't meet stream vegetation success criteria based on planted stems alone; however, when including appropriate naturally recruited stems, such as hickory (*Carya* sp.) and sweetgum (*Liquidambar styraciflua*), these plots were above success criteria. Plot 22 had a total of 323 stems per acre, which is only slightly over the success criteria threshold of 320 stems per acre. Plot 17 met stream vegetation success criteria based on planted stems alone with 323 stems per acre, but did not meet riparian buffer vegetation success criteria, with only 283 planted tree stems per acre.

Generally, planted vegetation survival within the Site is doing poorly. Many of the planted trees died over the summer as the result of extreme hot, dry conditions. Stream benches and terrace slopes downstream of station 81+25 (Hurricane Irene repair areas) are characterized by exposed soil with little vegetation. The exposed benches are a result of sediment deposition from storm events, including Hurricane Irene. In addition, the permanent seed mixture that was spread on-site during stream repairs in February 2011 has not established on the benches and terrace slopes. Twenty-eight of the eighty-six planted ball and burlap trees adjacent to Holloway Park have died or appear to be in poor health. These issues encompass the majority of the Site and should be

monitored closely in subsequent monitoring years. Additional plantings/seeding may be necessary if improvement is not observed in future monitoring years.

Chinese privet (*Ligustrum sinense*) was sparsely scattered throughout the Site. One dense cluster of privet was observed between monitoring plots 14 and 15 as depicted on the Current Condition Plan View (CCPV) map (Figure 2.6). Invasive/exotic vegetation is not currently compromising the vegetative success of the Site. Vegetation ground coverage within the stormwater wetland was 100 percent.

1.3 Stream Stability

Year 1 monitoring surveys along Adkin Branch and its UT occurred in October, 2011. Significant stream bed scour was observed in the following locations (Figures 5.1-5.2):

- Reach 1: station 41+00 to 46+00
- Reach 2: station 68+71 to 74+64

This scour likely occurred during the storm events associated with Hurricane Irene in late August, 2011. Several of the existing pools in Reach 1 and 2 deepened and/or lengthened as a result of the storm events, but the log structures maintained grade control and the overall stability of the channel was not compromised. These pools are expected to adjust over time, but will be monitored closely in Year 2 to make sure that the log structures are not undermined. Only minor shifting of pools and riffles was observed throughout the remainder of the profile, which is expected in a sand bed system. The majority of stream banks and structures throughout the project are stable and functioning as intended. There is no evidence of trends toward significant change in channel pattern. Cross-sectional data indicates that the channel width to depth ratio is lowering as the channel matures (Figures 4.1-4.17). This change is expected as detailed in the proposed success criteria from the Baseline Monitoring Document (NCDENR, 2011).

Based on an overall visual assessment of the channel, Reach 2 appears to contain the majority of the problem areas on the Site. Twelve riffle segments were noted as unstable in Reach 2 as a result of the scour from large storm events, most notably, events associated with Hurricane Irene. Twelve bank segments were noted as eroding in Reach 2, due to a lack of vegetation along the stream banks. One log cross vane has been compromised in Reach 2 as a result of stream bank erosion around the vane arm (Figure 3.29). Six log structures are experiencing erosion on greater than 15 percent of the streambanks within their extent of influence and three log structures exhibit minor erosion around the vane arms. A Repair Plan has been developed to correct these problem areas, which includes the use of soil lifts, bank grading, and erosion control matting. The repair plan is expected to be implemented in 2012. Problem areas are depicted on the CCPV and photos are presented in Appendix B.

The soil lifts that were installed in January and February, 2011 are stable and the willow cuttings are well established along the stream banks.

Crest gauges installed on-site were inspected on 26 October, 2011. Crest Gauge 2 near station 75+25 was damaged during Hurricane Irene. The remaining crest gauges revealed that a bankfull event occurred at least once during 2011 (Table 13). Additional overbank evidence includes debris lines, and vegetation bent in the downstream direction. Evidence of bankfull events can be found in Appendix E.

1.4 Wetlands

No wetland monitoring areas were established for this project report.

1.5 Note

Summary information/data related to the occurrence of items such as beaver or encroachment and statistics related to performance of various project and monitoring elements can be found in the tables and figures in the report appendices. Narrative background and supporting information formerly found in these reports can be found in the Baseline Monitoring Report (formerly Mitigation Plan) and in the Mitigation Plan (formerly the Restoration Plan) documents available on EEP's website. All raw data supporting the tables and figures in the appendices is available from EEP upon request.

2.0 METHODOLOGY

The Year 1 Monitoring survey was completed using a Total Station. Each cross section is marked with two rebar monuments at their beginning and ending points. The rebar has been located vertically and horizontally in NAD 83-State Plane. Surveying these monuments throughout the Site ensured proper orientation. The survey data was imported into MicroStation for verification. The longitudinal stationing was developed from total station data and compared with previous year's data to ensure consistent beginning and ending points. RIVERMorph was used to analyze the profile and cross section data. Tables and figures were created using Microsoft Excel. The channel is entirely a sand bed system; therefore a pebble count was not conducted.

Vegetation was measured at twenty-two sample vegetation plots (10-meter by 10-meter) within the Site in September 2011 for Year 1 (2011) monitoring per guidelines established in *CVS-EEP Protocol for Recording Vegetation, Version 4.0* (Lee et al. 2006). The taxonomic standard for vegetation used for this document was *Flora of the Carolinas, Virginia, Georgia, and Surrounding Areas* (Weakley 2006). Vegetation plots are permanently monumented with 4-foot metal garden posts at each corner. In each sample plot, vegetation parameters monitored included species composition and species density. Visual observations of the percent cover of shrub and herbaceous species were documented by photograph. Photographs and vegetation plot information can be found in Appendices B and C.

Stormwater BMP devices will be monitored and maintained periodically, as necessary, to ensure the life of the devices. The City of Kinston has agreed to provide maintenance for the sand filter

BMP devices and the stormwater wetland for the life of the BMPs (30 years). A maintenance guideline manual will be provided to the City of Kinston by EEP.

3.0 REFERENCES


- Lee, Michael T., R. K. Peet, S. D. Roberts, and T. R. Wentworth. 2006. CVS-EEP Protocol for Recording Vegetation, Version 4.0 (<http://cvs.bio.unc.edu/methods.htm>).
- NCDENR-Ecosystem Enhancement Program. 2011. Baseline Monitoring Document and As-Built Baseline Report, Adkin Branch Stream Restoration Project, Phase 1 – Washington Ave. to Lincoln St., Lenoir County, North Carolina.
- Weakley, Alan S. 2006. Flora of the Carolinas, Virginia, Georgia, and Surrounding Areas (online). Available: http://www.herbarium.unc.edu/FloraArchives/WeakleyFlora_2006-Jan.pdf [January 6, 2006]. University of North Carolina Herbarium, North Carolina Botanical Garden, University of North Carolina, Chapel Hill, North Carolina.
- Schafale, M.P. and A.S. Weakley. 1990. Classification of the Natural Communities of North Carolina: Third Approximation. North Carolina Natural Heritage Program, Division of Parks and Recreation, North Carolina Department of Environment, Health, and Natural Resources. Raleigh, North Carolina.
- United States Army Corps of Engineers, United States Environmental Protection Agency, North Carolina Wildlife Resources Commission, North Carolina Division of Water Quality (USACE et al.). 2003. Stream Mitigation Guidelines.

APPENDICES

Appendix A. Project Vicinity Map and Background Tables

Lenoir County North Carolina

PROJECT AREA



Date: 06/15/11

Figure: 1


Vicinity/Asset Map



Florence & Hutcheson
CONSULTING ENGINEERS
5121 KINGDOM WAY, SUITE 100
RALEIGH, N.C. 27607
(919) 851-6066
License No: F-0258




Adkin Branch Phase I
PROJECT NO. 050656101
Lenoir County, North Carolina



FROM RALEIGH:

- Take I-40 East for approximately 6.5 miles to US 70 East
- Take US Hwy 70 East for approximately 68.5 miles to NC 1155
- Turn left and travel Northeast on NC 1155 thru Kinston for 1.7 miles
- Turn left onto Martin Luther King Jr Blvd. and travel for 0.5 miles
- Turn right onto the East Washington Ave. and travel 0.4 miles to the intersection with Adkin Branch Project. Site is Southeast of Washington Ave.

"The subject project site is an environmental restoration site of the NCDENR Ecosystem Enhancement Program (EEP) and is encompassed by a recorded conservation easement, but is bordered by land under private ownership. Accessing the site may require traversing areas near or along the easement boundary and therefore access by the general public is not permitted. Access by authorized personnel of state and federal agencies or their designees/contractors involved in the development, oversight and stewardship of the restoration site is permitted within the terms and timeframes of their defined roles. Any intended site visitation or activity by any person outside of these previously sanctioned roles and activities requires prior coordination with EEP."



Project Location and Directions

The Project is located on the southeast side of the City of Kinston, in Lenoir County, North Carolina and includes Adkin Branch and an unnamed tributary (UT) to Adkin Branch (Figure 1, Appendix A). Phase I of the Project begins at Washington Ave. and ends at Lincoln Street.

Directions to the Site:

- From Raleigh, North Carolina take I-40 east for approximately 6.5 miles to US Highway 70 east.
- Take US 70 east for approximately 68.5 miles to NC Highways 11 and 55
- Take a left turn and travel northeast on NC 11/55 through Kinston for 2.6 miles to the intersection with Adkin Branch
- The project study area is southeast of NC 11/55.

The subject project is an environmental restoration site of the NCDENR Ecosystem Enhancement Program (EEP) and is encompassed by a recorded conservation easement, but is bordered by land under private ownership. Accessing the site may require traversing areas near or along the easement boundary and therefore access by the general public is not permitted. Access by authorized personnel of state and federal agencies or their designees/contractors involved in the development, oversight and stewardship of the restoration site is permitted within the terms and timeframes of their defined roles. Any intended site visitation or activity by any person outside of these previously sanctioned roles and activities requires prior coordination with EEP.

Table 1. Project Components and Mitigation Credits

Mitigation Credits										
	Stream	Riparian Wetland		Non-riparian Wetland		Riparian Buffer **		Nitrogen Nutrient Offset		
								Pound Reduction	Buffer Restoration **	
Type	R	R	RE	R	RE	50'	50' - 200'		<= 50'	50' - 200'
Totals	7,787 *	N/A	N/A	N/A	N/A	562,799	696,704 *	3,990	0	31,751
Project Components										
Project Component -or- Reach ID	Stationing/Location			Existing Footage/Acreage	Approach (PI, PII etc.)	Restoration - or- Restoration Equivalent	Restoration Footage or Acreage	Mitigation Ratio		
Reach 1	Washington Ave. to Gordon St.			1,680	PII	R	1,727	Varies*		
Reach 2	Gordon St. to Lincoln St.			4,224	PII	R	4,270	Varies*		
Reach 3	UT to Adkin Branch.			1,200	PII	R	1,582	Varies*		
Riparian Buffers	50'			7.58	-	R	12.92	1 to 1		
	50' - 200'					R	13.97	Varies*		
Component Summation										
Restoration Level	Stream (linear feet)	Riparian Wetland (acres)		Non-riparian Wetland (acres)	Buffer (square ft.)	Upland (acres)				
		Riverine	Non-Riverine							
Restoration	7,579	N/A	N/A	N/A	1,171,272	N/A				
Enhancement		N/A	N/A	N/A	N/A	N/A				
Enhancement II	N/A									
Enhancement II	N/A									
Creation		N/A	N/A	N/A						
Preservation	N/A	N/A	N/A	N/A		N/A				
High Quality Preservation	N/A	N/A	N/A	N/A		N/A				
BMP Elements										
Element	Location	Purpose/Function		30 yr. Total Nitrogen Reduction (lbs)		Notes				
Stormwater Wetland	UT Adkin	Water Quality / Nutrient Uptake		N/A		-				
BMP #4 - Sand Filter	Miller St.	Water Quality / Infiltration		300		-				
BMP #5 - Sand Filter	Dover St.	Water Quality / Infiltration		750		-				
BMP #6 - Sand Filter	Seacrest St.	Water Quality / Infiltration		1,170		-				
BMP #7 - Sand Filter	Myrtle Ave.	Water Quality / Infiltration		600		-				
BMP #8 - Sand Filter	Holloway Dr.	Water Quality / Infiltration		180		-				
BMP #9 - Sand Filter	Shine St.	Water Quality / Infiltration		990		-				
* - Stream & Riparian Buffer Mitigation Credit numbers were adjusted based on proposed DWQ guidelines (DRAFT Regulatory Guidance for the Calculation of Stream and Buffer Mitigation Credit for Buffer Widths Different from Standard Minimum Widths, Version 4.5, July 20, 2010). See Appendix D for further explanation.										
** - Riparian Buffer areas may be used for stream & wetland mitigation, stream & riparian buffer mitigation, or nutrient offset credit (Estimating/Calculating Riparian Buffer Credits, EEP PPM Section 8.3.1.2).										

Table 2. Project Activity and Reporting History

Activity or Report	Data Collection Complete	Completion or Delivery
Restoration Plan		March 2007
Final Design – Construction Plans		May 2007
Bid Opening		October 2008
Begin Construction		March 2009
<i>Tropical Storm Ida</i>	<i>November 2009</i>	
Article 29 declared on original contractor		January 2010
Surety Contractor Begin Construction		June 2010
Tropical Storm Repairs Bid Opening		September 2010
Begin Tropical Storm Repairs Construction		December 2010
Construction Complete		April 2011
Baseline Monitoring Document	March 2011	July 2011
Year 1 Monitoring	October 2011	November 2011
Year 2 Monitoring		
Year 3 Monitoring		
Year 4 Monitoring		
Year 5 Monitoring		

Table 3. Project Contacts Table

Designer	Florence & Hutcheson, Inc. 5121 Kingdom Way, Suite 100 Raleigh, North Carolina 27607 Kevin Williams (919) 851-6066
Original Contractor	Appalachian Environmental Services 1165 W. Main St. Sylva, NC 28779 Mickey B. Henson
Surety Contractor	Environmental Quality Resources, LLC 1405 Benson Court, Suite C Baltimore, MD 21227 John Talley (443) 304-3310
Repair Contractor	Fluvial Solutions P.O. Box 28749 Raleigh, NC 27611 Peter Jelenevsky (919) 821-4300
Planting Contractor	Bruton Natural Systems (Fluvial Solutions Sub-contractor) PO Box 1197 Fremont, NC 27830 Charlie Bruton (919) 242-6555
Seeding Contractor	See Original Contractor, Surety Contractor, & Repair Contractor above.
Nursery Stock Suppliers	1) ArborGen - South Carolina SuperTree Nursery 2) Evergreen Partners of Raleigh 3) NC Division of Forest Resources
Monitoring Performers	
Stream Monitoring	Florence & Hutcheson, Inc. 5121 Kingdom Way, Suite 100 Raleigh, North Carolina 27607 Ryan Smith (919) 851-6066
Vegetation Monitoring	Axiom Environmental, Inc. 218 Snow Avenue Raleigh, North Carolina 27603 Corri Faquin (919) 414-2471

Table 4. Project Attributes Table

Project Information				
Project Name		Adkin Branch Stream Restoration Project – Phase I		
County		Lenoir		
Project Area (acres)		36		
Project Coordinates		035° 15' 13" N, 77° 33' 36" W (@ Lincoln St.)		
Project Watershed Summary Information				
Physiographic Province		Coastal Plain		
River Basin		Neuse		
USGS 8-digit HUC	3020202		USGS 14-digit HUC	3020202060030
NCDWQ Subbasin		03-04-05		
Project Drainage Area		5.46 sq. mi (at Lincoln St.)		
Watershed Land Use	Urban Land	76%	Agricultural Land	13%
	Mixed Forest / Disturbed Forest	7%	Evergreen Forest	4%
Reach Summary Information				
Parameters	Adkin Branch		UT to Adkin	
	Washington Ave. to Gordon St.	Gordon St. to Lincoln St.		
Length of reach (linear ft)	1727	4270	1582	
Valley Classification	VIII		VIII	
Drainage Area (acres)	3220	3495	78	
NCDWQ stream ID score	39.5		27	
NCDWQ Classification	C		C	
Pre-Existing Stream Type	G5	B5c	E5	
As-built Stream Type	B5c	B5c	C/E5	
Underlying mapped soils	Bibb		Kenansville	
Drainage Class	Poorly Drained		Well-drained	
Soil Hydric Status	Hydric		Non-Hydric	
Slope	0.0016	0.0014	0.0022	
FEMA Classification	AE			
Native Vegetation Community	Coastal Plain Levee Forest / Streamside Assemblage			
Percent composition of exotic invasive vegetation	5%	10%	5%	
Wetland Summary Information				
N/A				
Regulatory Considerations				
Regulation	Applicable	Resolved	Supporting Documentation	
Waters of the U.S. –Sections 404 and 401	Yes	Yes	Restoration Plan	
Endangered Species Act	Yes	Yes	Restoration Plan	
Historic Preservation Act	Yes	Yes	Restoration Plan	
CZMA/CAMA	No	--	--	
FEMA Floodplain Compliance	Yes	Yes	Restoration Plan	
Essential Fisheries Habitat	No	--	--	

Appendix B. Visual Assessment Data



Figures 2.0-2.12. Current Condition Plan View

**CURRENT CONDITIONS PLAN VIEW (CCPV)
OVERVIEW**

PROJECT REFERENCE NO. ADKIN BRANCH	FIGURE NO. 2.0
---------------------------------------	-------------------




NOT TO SCALE



11/15/2011
I:\Streams\Pro\Monitoring\Year 1\AdkinBranch_Monitoring\RI_psh_1.dgn
Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCOP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)




-MATCHLINE- SEE FIGURE NO. 2.2

LEGEND	
	THALWEG
	BANKFULL
	TOE OF SLOPE
	CONSERVATION EASEMENT LINE
	LOG CROSS VANE
	LOG VANE
	LOG SILL
	MONITORING CROSS SECTION (XS-)
	PRE-CONSTRUCTION TOP OF BANK
	PRE-CONSTRUCTION THALWEG

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YRI)	
SDP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	CHECKED BY: RKW
DATE: 11/11	

11/15/2011
 C:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YRI_ph_2.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)



-MATCHLINE- SEE FIGURE NO. 2.1



-MATCHLINE- SEE FIGURE NO. 2.3


LEGEND	
	THALWEG
	BANKFULL
	TOE OF SLOPE
	CONSERVATION EASEMENT LINE
	ROOTWAD
	LOG VANE
	LOG SILL
	MONITORING CROSS SECTION (XS-)
	PRE-CONSTRUCTION TOP OF BANK
	PRE-CONSTRUCTION THALWEG

11/15/2011
 R:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_3.dgn
 Florence & Hutcheson, Inc.











CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCP#: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)

PROJECT REFERENCE NO. ADKIN BRANCH	FIGURE NO. 2.3
	
CONSULTING ENGINEERS 5121 Kingdom Way, Suite 100 Raleigh, NC 27607 NC License No. P-0358	
	
SCALE	



LEGEND












-  THALWEG
-  BANKFULL
-  TOE OF SLOPE
-  CONSERVATION EASEMENT LINE
-  LOG CROSS VANE
-  LOG VANE
-  LOG SILL
-  MONITORING CROSS SECTION (XS-)
-  PRE-CONSTRUCTION TOP OF BANK
-  PRE-CONSTRUCTION THALWEG


11/15/2011
 R:\StreamProj\Monitoring\Year 1\AdkinBranch_Monitoring\RI_psh_4.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCD#: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	CHECKED BY: RKW
DATE: 11/11	

CURRENT CONDITIONS PLAN VIEW (CCPV)

LEGEND

	THALWEG
	BANKFULL
	TOE OF SLOPE
	CONSERVATION EASEMENT LINE
	LOG CROSS VANE
	LOG VANE
	LOG SILL
	MONITORING CROSS SECTION (XS-)
	PRE-CONSTRUCTION TOP OF BANK
	PRE-CONSTRUCTION THALWEG
	MINOR EROSION

















11/15/2011
 R:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_5.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCD#: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)

LEGEND


-  THALWEG
-  BANKFULL
-  TOE OF SLOPE
-  CONSERVATION EASEMENT LINE
-  ROOTWAD
-  LOG CROSS VANE
-  LOG VANE
-  LOG SILL
-  SOIL LIFT
-  MONITORING CROSS SECTION (XS-)
-  PRE-CONSTRUCTION TOP OF BANK
-  PRE-CONSTRUCTION THALWEG
-  SEVERE EROSION




11/15/2011
 R:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_6.dgn
 Florence & Hutcheson, Inc.














CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCOP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)

PROJECT REFERENCE NO. ADKIN BRANCH	FIGURE NO. 2.6
 CONSULTING ENGINEERS 5121 Kingdom Way, Suite 100 Raleigh, NC 27607 NC License No. F-0358	
25 0 50 SCALE	



LEGEND













-  THALWEG
-  BANKFULL
-  TOE OF SLOPE
-  CONSERVATION EASEMENT LINE
-  ROOTWAD
-  LOG VANE
-  LOG SILL
-  SOIL LIFT
-  MONITORING CROSS SECTION (XS-1)
-  PRE-CONSTRUCTION TOP OF BANK
-  PRE-CONSTRUCTION THALWEG
-  SEVERE EROSION
-  PRIVET


I:\5/2011\StreamProj\Monitoring\Year 1\AdkinBranch_Monitoring\RI_psh_7.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCP#: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)

LEGEND

-  THALWEG
-  BANKFULL
-  TOE OF SLOPE
-  CONSERVATION EASEMENT LINE
-  ROOTWAD
-  LOG VANE
-  LOG SILL
-  SOIL LIFT
-  MONITORING CROSS SECTION (XS-)
-  PRE-CONSTRUCTION TOP OF BANK
-  PRE-CONSTRUCTION THALWEG
-  MINOR EROSION



















11/15/2011
 R:\Stream_Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_8.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCOP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)

LEGEND

-  THALWEG
-  BANKFULL
-  TOE OF SLOPE
-  CONSERVATION EASEMENT LINE
-  ROOTWAD
-  LOG CROSS VANE
-  LOG SILL
-  SOIL LIFT
-  MONITORING CROSS SECTION (XS-)
-  PRE-CONSTRUCTION TOP OF BANK
-  PRE-CONSTRUCTION THALWEG
-  MINOR EROSION
-  MODERATE EROSION
-  SEVERE EROSION
-  BARE AREAS





-MATCHLINE- SEE FIGURE NO. 2.7

-MATCHLINE- SEE FIGURE NO. 2.9

11/15/2011
 R:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_9.dgn
 Florence & Hutcheson, Inc.


CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCD# 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)

PROJECT REFERENCE NO. ADKIN BRANCH	FIGURE NO. 2.9
 <p>Florence & Hutcheson CONSULTING ENGINEERS 5121 Kingdom Way, Suite 100 Raleigh, NC 27607 NC License No. F-0258</p>	
 <p>SCALE</p>	

LEGEND

	THALWEG		SOIL LIFT
	BANKFULL		FLOODPLAIN INTERCEPTOR (FPI)
	TOE OF SLOPE		MONITORING CROSS SECTION (XS-)
	CONSERVATION EASEMENT LINE		PRE-CONSTRUCTION TOP OF BANK
	ROOTWAD		PRE-CONSTRUCTION THALWEG
	LOG CROSS VANE		MINOR EROSION
	LOG VANE		MODERATE EROSION
	LOG SILL		SEVERE EROSION
			BARE AREAS



11/15/2011
 R:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_10.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCO#: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	
CHECKED BY: RKW	DATE: 11/11

CURRENT CONDITIONS PLAN VIEW (CCPV)


PROJECT REFERENCE NO. ADKIN BRANCH
 FIGURE NO. 2.10

Florence & Hutcheson
 CONSULTING ENGINEERS
 5121 Kingdom Way, Suite 100 Raleigh, NC 27607
 NC License No. F-0358



LEGEND	
	THALWEG
	BANKFULL
	TOE OF SLOPE
	CONSERVATION EASEMENT LINE
	LOG CROSS VANE
	DOUBLE STEP LOG CROSS VANE
	DOUBLE STEP LOG VANE
	LOG SILL
	SOIL LIFT
	MONITORING CROSS SECTION (XS-)
	PRE-CONSTRUCTION TOP OF BANK
	PRE-CONSTRUCTION THALWEG
	MODERATE EROSION
	BARE AREAS


-MATCHLINE- SEE FIGURE NO. 2.9




11/15/2011
 R:\Stream_Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_11.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCOP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	CHECKED BY: RKW
DATE: 11/11	

CURRENT CONDITIONS PLAN VIEW (CCPV)

PROJECT REFERENCE NO. ADKIN BRANCH	FIGURE NO. 2.11
	
CONSULTING ENGINEERS 5121 Kingdom Way, Suite 100 Raleigh, NC 27607 NC License No. F-0058	
25 0 50 SCALE	






LEGEND	
	THALWEG
	BANKFULL
	TOE OF SLOPE
	CONSERVATION EASEMENT LINE
	LOG SILL
	MONITORING CROSS SECTION (XS-)
	PRE-CONSTRUCTION TOP OF BANK
	PRE-CONSTRUCTION THALWEG

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCOP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	CHECKED BY: RKW
DATE:	DATE: 11/11

11/15/2011
 R:\Stream\Proj\Monitoring\Year 1\AdkinBranch_Monitoring\YR1_psh_12.dgn
 Florence & Hutcheson, Inc.

CURRENT CONDITIONS PLAN VIEW (CCPV)

PROJECT REFERENCE NO. ADKIN BRANCH	FIGURE NO. 2.12
	
CONSULTING ENGINEERS 5121 Kingdom Way, Suite 100 Raleigh, NC 27607 <small>NC License No. P-0258</small>	
 SCALE	



MATCHLINE- SEE FIGURE NO. 2.11

LEGEND	
	THALWEG
	BANKFULL
	TOE OF SLOPE
	CONSERVATION EASEMENT LINE
	LOG SILL
	MONITORING CROSS SECTION (XS-)
	PRE-CONSTRUCTION TOP OF BANK
	PRE-CONSTRUCTION THALWEG

CURRENT CONDITIONS PLAN VIEW (CCPV)	
ADKIN BRANCH (YR1)	
SCOP: 050656101	COUNTY: LENOIR
DESIGNED BY: RVS	CHECKED BY: RKW
DATE: 11/11	

11/15/2011
 C:\Stream\Proj\Monitoring\Year 1\AdkinBranch_MonitoringYR1_psh_13.dgn
 Florence & Hutcheson, Inc.

Table 5.1 Visual Stream Morphology Stability Assessment
Adkin Branch Stream Restoration Project, Phase I, 050656101
Adkin Branch Reach 1 - Washington Ave. to Gordon St. - 1,764 feet assessed

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	1. Vertical Stability (Riffle and Run units)	1. <u>Aggradation</u> - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		2. <u>Degradation</u> - Evidence of downcutting			3	152	91%			
	2. Riffle Condition	1. <u>Texture/Substrate</u> - Riffle maintains coarser substrate	All	N/A			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient	9	9			100%			
		2. <u>Length</u> appropriate	8	9			89%			
	4. Thalweg Position	1. Thalweg centering at upstream of meander bend (Run)	All	N/A			100%			
2. Thalweg centering at downstream of meander (Glide)		All	N/A			100%				
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%	N/A	N/A	N/A
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%	N/A	N/A	N/A
	3. Mass Wasting	Bank slumping, calving, or collapses			0	0	100%	N/A	N/A	N/A
Totals					0	0	100%	N/A	N/A	N/A
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs	17	17			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	17	17			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	17	17			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	17	17			100%			
	4. Habitat	Pool forming structures maintaing ~ Max Pool Depth : Mean Bankfull Depth ratio > 1.6 Rootwads/logs providing some cover at base-flow.	15	18			83%			

Table 5.2 Visual Stream Morphology Stability Assessment
Adkin Branch Stream Restoration Project, Phase I, 050656101
Adkin Branch Reach 2 - Gordon St. to Lincoln St. - 3,131 feet assessed (4,270 ft. total reach length)

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	1. Vertical Stability (Riffle and Run units)	1. <u>Aggradation</u> - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		2. <u>Degradation</u> - Evidence of downcutting			12	730	77%			
	2. Riffle Condition	1. <u>Texture/Substrate</u> - Riffle maintains coarser substrate	All	N/A			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient	14	14			100%			
		2. <u>Length</u> appropriate	13	14			93%			
	4. Thalweg Position	1. Thalweg centering at upstream of meander bend (Run)	All	N/A			100%			
2. Thalweg centering at downstream of meander (Glide)		All	N/A			100%				
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			12	345	89%	0%	0%	89%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%	N/A	N/A	N/A
	3. Mass Wasting	Bank slumping, calving, or collapses			3	100	97%	0%	0%	97%
Totals					15	445	86%	0%	0%	86%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs	31	31			100%	Notes: Three structures in Reach 2 exhibit minor erosion (<15%) around vane arms		
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	31	31			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	31	31			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	24	31			77%			
	4. Habitat	Pool forming structures maintaing ~ Max Pool Depth : Mean Bankfull Depth ratio > 1.6 Rootwads/logs providing some cover at base-flow.	31	31			100%			

**Table 5.3 Visual Stream Morphology Stability Assessment
Adkin Branch Stream Restoration Project, Phase 1, 050656101
UT to Adkin Branch: 1,622 feet assessed**

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	1. Vertical Stability (Rifle and Run units)	1. Aggradation - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		2. Degradation - Evidence of downcutting			0	0	100%			
	2. Rifle Condition	1. Texture/Substrate - Rifle maintains coarser substrate	All	N/A			100%			
	3. Meander Pool Condition	1. Depth Sufficient	32	32			100%			
		2. Length appropriate	32	32			100%			
	4. Thalweg Position	1. Thalweg centering at upstream of meander bend (Run)	All	N/A			100%			
2. Thalweg centering at downstream of meander (Glide)		All	N/A			100%				
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%	N/A	N/A	N/A
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does NOT include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%	N/A	N/A	N/A
	3. Mass Wasting	Bank slumping, calving, or collaps			0	0	100%	N/A	N/A	N/A
Totals					0	0	100%	N/A	N/A	N/A
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs	16	16			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	16	16			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	16	16			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does not exceed 15%. (See guidance for this table in EEP monitoring guidance document)	16	16			100%			
	4. Habitat	Pool forming structures maintaing ~ Max Pool Depth : Mean Bankfull Depth ratio > 1.6 Rootwads/logs providing some cover at base-flow.	14	16			88%			

Table 6 **Vegetation Condition Assessment**
Adkin Branch Restoration Site (EEP Project 7)

Planted Acreage¹ **33**

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Planted Acreage
1. Bare Areas	Areas along stream benches throughout the Site have exposed soils with very little vegetative cover.	0.10 acre	See legend on CCPV	6	1.53	4.6%
2. Low Stem Density Areas	Stem densities throughout the Site are low due to death of planted seedlings as the result of extreme dry, hot temperatures over the summer (Veg. Plots 7-12, 14, 16, 18, and 22)	0.025 acre	Veg. Plots	10	0.25	0.8%
Total				16	1.78	5.4%
3. Areas of Poor Growth Rates or Vigor	Vegetation growth throughout the Site is poor.	None	NA	NA	NA	NA
Cumulative Total				16	1.78	5.4%

Easement Acreage² **40.5**

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Easement Acreage
4. Invasive Areas of Concern ⁴	Privet is located between Vegetation Plots 14 and 15 (also sparsely scattered throughout site)	0.05 acre	See legend on CCPV	1	0.05	0.1%
5. Easement Encroachment Areas ³	NA	NA	NA	NA	NA	NA

¹ = Enter the planted acreage within the easement. This number is calculated as the easement acreage minus any existing mature tree stands that were not subject to supplemental planting of the understory, the channel acreage, crossings or any other elements not directly planted as part of the project effort.

² = The acreage within the easement boundaries.

³ = Encroachment may occur within or outside of planted areas and will therefore be calculated against the overall easement acreage. In the event a polygon is cataloged into items 1, 2 or 3 in the table and is the result of encroachment, the associated acreage should be tallied in the relevant item (i.e., item 1,2 or 3) as well as a parallel tally in item 5.

⁴ = Invasives may occur in or out of planted areas, but still within the easement and will therefore be calculated against the overall easement acreage. Invasives of concern/interest are listed below. The list of high concern species are those with the potential to directly outcompete native, young, woody stems in the short-term (e.g. monitoring period or shortly thereafter) or affect the community structure for existing, more established tree/shrub stands over timeframes that are slightly longer (e.g. 1-2 decades). The low/moderate concern group are those species that generally do not have this capacity over the timeframes discussed and therefore are not expected to be mapped with regularity, but can be mapped, if in the judgement of the observer their coverage, density or distribution is suppressing the viability, density, or growth of planted woody stems. Decisions as to whether remediation will be needed are based on the integration of risk factors by EEP such as species present, their coverage, distribution relative to native biomass, and the practicality of treatment. For example, even modest amounts of Kudzu or Japanese Knotweed early in the projects history will warrant control, but potentially large coverages of Microstegium in the herb layer will not likely trigger control because of the limited capacities to impact tree/shrub layers within the timeframes discussed and the potential impacts of treating extensive amounts of ground cover. Those species with the "watch list" designator in gray shade are of interest as well, but have yet to be observed across the state with any frequency. Those in *red italics* are of particular interest given their extreme risk/threat level for mapping as points where isolated specimens are found, particularly early in a projects monitoring history. However, areas of discrete, dense patches will of course be mapped as polygons. The symbology scheme below was one that was found to be helpful for symbolizing invasives polygons, particularly for situations where the condition for an area is somewhere between isolated specimens and dense, discrete patches. In any case, the point or polygon/area feature can be symbolized to describe things like high or low concern and species can be listed as a map inset, in legend items if the number of species are limited or in the narrative section of the executive summary.

Figures 3.1-3.20. Vegetation Plot Photos and Problem Areas



3.1 Vegetation Plot 1




3.2 Vegetation Plot 2



3.3 Vegetation Plot 3




3.4 Vegetation Plot 4



3.5 Vegetation Plot 5



3.6 Vegetation Plot 6



3.7 Vegetation Plot 7



3.8 Vegetation Plot 8




3.9 Vegetation Plot 9



3.10 Vegetation Plot 10




3.11 Vegetation Plot 11



3.12 Vegetation Plot 12



3.13 Vegetation Plot 13



3.14 Vegetation Plot 14



3.15 Vegetation Plot 15



3.16 Vegetation Plot 16



3.17 Vegetation Plot 17



3.18 Vegetation Plot 18



3.19 Vegetation Plot 19



3.20 Vegetation Plot 20



3.19 Vegetation Plot 21



3.20 Vegetation Plot 22



3.21 Severe bank erosion near 65+50



3.22 Moderate erosion near 71+50



3.23 Minor erosion near 76+75



3.24 Moderate erosion near 81+10



3.25 Severe erosion/bare benches near 83+00



3.26 Moderate erosion near 83+50



3.27 Moderate erosion near 84+25



3.28 Moderate erosion near 85+80



3.29 Severe erosion near 87+50



3.30 Moderate erosion near 91+50

Appendix C. Vegetation Plot Data

Table 7. Vegetation Plot Criteria Attainment

Vegetation Plot ID	Stream Vegetation Survival Threshold Met?	Buffer Vegetation Survival Threshold Met?	Tract Mean
1	Yes	Yes	Stream Veg. = 55% Buffer Veg. = 50%
2	Yes	Yes	
3	Yes	Yes	
4	Yes	Yes	
5	Yes	Yes	
6	Yes	Yes	
7	No	No	
8	No	No	
9	No	No	
10	No*	No*	
11	No*	No*	
12	No	No	
13	Yes	Yes	
14	No	No	
15	Yes	Yes	
16	No	No	
17	Yes**	No	
18	No	No	
19	Yes	Yes	
20	Yes	Yes	
21	Yes	Yes	
22	No*	No*	

*Based on planted stems alone, these plots don't meet success criteria; however, when including naturally recruited stems of appropriate species such as hickory (*Carya* sp.) and sweetgum (*Liquidambar styraciflua*) these plots were above 320 stems per acre (Plot 22 was only barely above 320 stems per acre).

**Meets vegetation survival threshold, however, total planted stems that have survived are barely above the threshold limit of 320 stems per acre.

Table 8. CVS Vegetation Plot Metadata

Report Prepared By	Corri Faquin 9/29/2011 9:51
Date Prepared	
database name	Axiom-EEP-2011-D.mdb
database location	C:\Axiom\Business\CVS
computer name	CORRI-PC
file size	42930176
DESCRIPTION OF WORKSHEETS IN THIS DOCUMENT-----	
Metadata	Description of database file, the report worksheets, and a summary of project(s) and project data.
Proj, planted	Each project is listed with its PLANTED stems per acre, for each year. This excludes live stakes.
Proj, total stems	Each project is listed with its TOTAL stems per acre, for each year. This includes live stakes, all planted stems, and all natural/volunteer stems.
Plots	List of plots surveyed with location and summary data (live stems, dead stems, missing, etc.).
Vigor	Frequency distribution of vigor classes for stems for all plots.
Vigor by Spp	Frequency distribution of vigor classes listed by species.
Damage	List of most frequent damage classes with number of occurrences and percent of total stems impacted by each.
Damage by Spp	Damage values tallied by type for each species.
Damage by Plot	Damage values tallied by type for each plot.
Planted Stems by Plot and Spp	A matrix of the count of PLANTED living stems of each species for each plot; dead and missing stems are excluded.
ALL Stems by Plot and spp	A matrix of the count of total living stems of each species (planted and natural volunteers combined) for each plot; dead and missing stems are excluded.
PROJECT SUMMARY-----	
Project Code	7
project Name	Adkin Branch
Description	Stream restoration
River Basin	
length(ft)	
stream-to-edge width (ft)	
area (sq m)	
Required Plots (calculated)	
Sampled Plots	22

Table 9. Total and Planted Stems by Plot and Species
 EEP Project Code 7. Project Name: Adkins Branch

		Current Plot Data (MY1 2011)																																				
Scientific Name	Common Name	Species Type	E007-AXE-0001			E007-AXE-0002			E007-AXE-0003			E007-AXE-0004			E007-AXE-0005			E007-AXE-0006			E007-AXE-0007			E007-AXE-0008			E007-AXE-0009			E007-AXE-0010			E007-AXE-0011			E007-AXE-0012		
			PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS	P-all	T			
<i>Acer rubrum</i>	red maple	Tree			3																																	
<i>Alnus serrulata</i>	hazel alder	Shrub	15	18	18																																	
<i>Baccharis halimifolia</i>	eastern baccharis	Shrub											1																									
<i>Betula nigra</i>	river birch	Tree	13	13	13	5	5	5	2	2	2	4	4	4	2	2	2				2	2	2							1	1	1	1	1	1	3	3	3
<i>Carpinus caroliniana</i>	American hornbeam	Tree												4	4	4														2	2	2						
<i>Carya</i>	hickory	Tree				2	2	8	4	4	10	1	1	1																			14			5		
<i>Cephalanthus occidentalis</i>	common buttonbush	Shrub																																				
<i>Cercis canadensis</i>	eastern redbud	Tree														3	3	3											1	1	1							
<i>Cornus amomum</i>	silky dogwood	Shrub	40	44	44																																	
<i>Crataegus</i>	hawthorn	Tree																																				
<i>Liquidambar styraciflua</i>	sweetgum	Tree			1			70			16																					4						
<i>Pinus</i>	pine	Tree						2			1								1																			
<i>Pinus taeda</i>	loblolly pine	Tree			9																																	
<i>Platanus occidentalis</i>	American sycamore	Tree			3																																	
<i>Populus deltoides</i>	eastern cottonwood	Tree						3																											2			
<i>Prunus serotina</i>	black cherry	Tree						9			6	1	1	1																								
<i>Quercus</i>	oak	Tree		1	1				1	1	1	2	2	2	4	4	4	1	1	1			1	1	1									1	1	1		
<i>Quercus falcata</i>	southern red oak	Tree				3	3	3	7	7	7	3	3	3	2	2	2	7	7	7	1	1	1	3	3	3	1	1	1	2	2	2	2	2	2	2	2	2
<i>Quercus nigra</i>	water oak	Tree							2	2	2	2	2	2				1	1	1																		
<i>Quercus phellos</i>	willow oak	Tree				1	1	1	2	2	7																											
<i>Quercus rubra</i>	northern red oak	Tree																				1	1	1														
<i>Robinia pseudoacacia</i>	black locust	Tree																																				
<i>Salix nigra</i>	black willow	Tree	2	11	11																																	
<i>Sassafras albidum</i>	sassafras	Tree						3			1																											
<i>Taxodium distichum</i>	bald cypress	Tree				1	1	1																														
<i>Ulmus alata</i>	winged elm	Tree																																				
Unknown	unknown											2	2	2																								
Totals	Stem count		70	87	103	12	12	105	18	18	53	15	15	17	15	15	15	9	9	10	4	4	4	4	4	4	1	1	1	6	6	24	4	4	11	5	5	5
	size (ares)		1			1			1			1			1			1			1			1			1			1			1			1		
	size (ACRES)		0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02		
	Species count		4	5	9	5	5	10	6	6	10	7	7	9	5	5	5	3	3	4	3	3	3	2	2	2	1	1	1	4	4	6	3	3	5	2	2	2
Stems per ACRE		2832.8	3521	4168	485.6	485.6	4249	728.4	728.4	2145	607	607	688	607	607	607	364.2	364.2	404.7	161.9	161.9	161.9	161.9	161.9	161.9	40.47	40.47	40.47	242.8	242.8	971.2	161.9	161.9	445.2	202.3	202.3	202.3	
Riparian Buffer Success Criteria	Stem count		15	25	32	12	12	103	18	18	52	13	13	13	15	15	15	9	9	9	4	4	4	4	4	1	1	1	6	6	24	4	4	11	5	5	5	
	size (ares)		1			1			1			1			1			1			1			1			1			1			1			1		
	size (ACRES)		0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02		
	Species count		2	3	6	5	5	9	6	6	9	6	6	6	5	5	5	3	3	3	3	3	3	2	2	2	1	1	1	4	4	6	3	3	5	2	2	2
Stems per ACRE		607.03	1012	1295	485.6	485.6	4168	728.4	728.4	2104	526.1	526.1	526.1	607	607	607	364.2	364.2	364.2	161.9	161.9	161.9	161.9	161.9	161.9	40.47	40.47	40.47	242.8	242.8	971.2	161.9	161.9	445.2	202.3	202.3	202.3	

*Bolded hardwood tree species are counted toward riparian buffer success criteria

- Color for Density
- Exceeds requirements by 10%
 - Exceeds requirements, but by less than 10%
 - Fails to meet requirements, by less than 10%
 - Fails to meet requirements by more than 10%


Appendix D. Stream Survey Data

Figures 4.1-4.17. Cross Section Plots and Photos

Adkin Branch, 05065611, Reach 1


XS-1 Riffle, Sta. 37+42

Baseline		MY1	
Sta.	Elev.	Sta.	Elev.
0.00	36.38	0.00	36.37
9.86	34.88	7.34	35.19
16.62	33.21	11.50	34.38
24.51	32.12	16.09	33.34
25.95	32.31	22.92	32.75
27.26	31.91	28.30	32.23
29.31	31.89	30.00	32.00
31.49	31.34	32.35	31.56
33.99	31.05	33.78	31.27
35.11	30.06	35.08	30.30
36.12	28.42	36.45	27.99
36.41	28.32	37.87	27.71
37.29	27.83	40.95	27.74
38.32	27.76	42.41	27.91
41.02	27.67	43.87	27.90
42.56	27.78	46.09	29.85
43.94	28.17	46.85	29.93
44.35	29.19	47.15	30.18
45.81	29.62	48.83	30.49
47.84	30.09	51.70	31.01
49.03	30.44	54.46	31.52
51.68	30.46	55.03	31.46
54.61	31.10	56.16	31.09
61.87	31.23	59.51	31.32
65.51	31.78	64.40	32.12
76.01	33.81	69.56	32.78
88.18	35.44	76.64	34.02
		83.37	34.75
		88.23	35.45




Adkin Branch, 05065611, Reach 1

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-2 Pool, Sta. 38+94	0.00	34.25	0.00	34.25
	8.48	33.22	7.85	33.40
	17.26	32.07	15.07	32.32
	23.59	31.03	21.85	31.54
	24.98	30.53	25.29	30.76
	28.19	30.53	27.97	30.78
	29.98	30.03	30.68	30.60
	32.23	29.44	31.72	29.57
	33.36	27.87	33.17	28.37
	35.19	27.83	34.15	27.78
	37.22	27.51	37.13	27.55
	40.78	27.20	41.68	27.30
	43.31	27.42	46.75	27.74
	45.59	27.62	48.16	29.58
	46.73	27.99	49.13	30.60
	47.22	28.30	50.42	31.25
	48.68	30.06	54.76	31.31
	49.68	30.87	60.32	32.07
	52.71	31.19	69.40	32.89
	54.58	31.01	75.04	33.37
59.11	31.81			
66.89	32.70			
75.41	33.42			




Adkin Branch, 05065611, Reach 1

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-3 Riffle, Sta. 44+67	0.00	34.68	0.00	34.65
	5.04	33.96	9.47	33.04
	13.96	32.14	17.77	31.45
	22.51	30.31	23.88	30.25
	27.04	29.77	28.88	29.69
	31.37	28.98	32.78	28.80
	32.48	28.31	34.56	28.24
	33.27	28.11	35.32	27.29
	34.34	27.84	38.06	26.72
	35.11	27.51	41.20	26.81
	36.05	27.31	42.66	27.07
	37.20	26.90	44.87	27.40
	40.71	26.93	46.91	28.74
	43.22	26.96	49.53	29.48
	44.45	27.35	53.45	29.45
	46.78	27.91	56.69	30.43
	49.43	28.97	62.83	31.49
	51.83	29.32	67.46	32.44
	52.60	29.12	71.00	33.27
	57.19	30.42		
64.81	31.73			
71.17	33.27			




Adkin Branch, 05065611, Reach 1

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-4 Pool, Sta. 46+81	0.00	33.26	0.00	33.25
	6.80	31.49	4.64	32.15
	9.47	31.14	10.74	31.01
	21.52	28.84	16.16	29.97
	24.22	28.46	20.27	29.21
	25.32	27.87	23.29	29.03
	26.50	27.73	25.51	28.82
	27.87	27.05	25.89	28.32
	29.15	26.40	26.84	27.40
	31.16	26.69	28.01	26.90
	35.70	26.65	29.61	27.03
	38.06	26.48	32.56	26.47
	39.91	27.10	34.68	26.88
	40.99	27.77	36.07	26.81
	41.64	28.45	38.75	26.99
	45.49	29.36	40.21	27.14
	49.30	30.12	41.73	28.64
	59.69	31.31	43.87	29.13
	71.76	32.43	45.81	29.32
			46.83	29.84
		53.19	30.66	
		59.66	31.43	
		66.17	32.13	
		71.22	32.40	




Adkin Branch, 05065611, Reach 1

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-5 Riffle, Sta. 51+47	0.00	31.97	0.00	31.94
	9.93	30.85	10.41	30.71
	19.77	29.78	20.29	29.67
	25.24	28.98	26.27	28.51
	28.26	28.18	30.50	27.53
	29.51	27.58	32.79	27.20
	30.76	27.26	33.94	26.70
	32.09	26.91	34.66	25.68
	33.29	26.29	35.74	25.16
	34.40	25.91	38.34	25.69
	35.72	25.88	39.54	26.90
	36.05	26.21	41.60	26.25
	37.13	26.13	42.45	26.47
	37.42	25.81	43.86	26.86
	38.94	25.78	45.98	27.71
	39.65	25.96	50.73	28.33
	41.28	26.38	56.05	29.10
	43.58	26.75	68.09	30.73
	45.04	26.82	76.66	31.44
	45.66	27.28		
47.79	27.86			
53.02	28.51			
62.00	30.27			
77.07	31.48			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-6 Pool, Sta. 64+81	0.00	28.96	0.00	28.97
	7.02	28.18	6.82	28.17
	11.82	27.13	8.32	27.81
	13.15	26.66	10.62	27.39
	17.98	26.08	12.11	27.21
	18.99	26.23	14.48	26.61
	20.64	26.63	17.51	26.27
	23.57	26.31	18.95	26.5
	24.13	25.60	20.94	26.6
	24.68	25.28	22.30	25.41
	24.68	23.77	23.66	23.77
	27.84	22.22	24.43	22.89
	30.39	21.92	25.79	22.12
	31.86	22.19	27.26	21.75
	33.54	22.48	28.97	21.87
	35.54	23.06	30.95	22.19
	35.50	24.22	32.79	22.9
	36.01	25.11	35.54	23.17
	37.14	25.43	36.52	25.33
	37.75	25.99	37.51	25.72
41.07	27.13	39.90	27.15	
43.93	27.64	44.55	27.92	
46.39	28.20	47.08	27.69	
46.83	27.64	53.27	28.35	
53.08	28.32	57.49	28.84	
57.39	28.93			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-7 Riffle, Sta. 70+00	0.00	28.97	0.00	28.94
	10.03	27.78	5.37	28.42
	19.73	26.44	12.29	27.57
	23.60	26.43	14.97	27.11
	25.40	24.69	19.28	26.39
	27.14	23.81	23.36	26.20
	28.16	22.91	24.78	25.12
	31.71	22.99	26.93	23.31
	35.41	22.94	27.76	22.57
	37.91	23.17	29.58	21.63
	38.15	23.50	32.22	21.34
	38.72	24.10	34.49	21.00
	39.07	24.73	35.67	21.14
	40.37	25.16	36.86	21.85
	42.38	25.59	37.72	23.15
	43.48	25.59	39.28	23.28
	44.04	25.73	40.25	24.11
	44.71	25.88	40.75	25.26
	45.38	26.12	44.21	25.94
	47.07	26.24	45.80	26.40
	49.69	26.73	51.40	26.82
	51.10	26.64	56.41	27.29
	52.80	27.04	61.50	28.09
	56.19	27.27	64.23	28.34
64.14	28.37			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-8 Pool, Sta. 74+30	0.00	26.81	0.00	26.71
	3.48	26.81	5.61	26.62
	5.42	26.72	8.41	26.01
	7.59	26.33	11.70	25.23
	10.42	25.65	13.96	24.83
	13.75	24.87	15.46	24.90
	15.67	24.76	16.73	24.35
	16.46	24.22	17.51	24.04
	17.26	24.03	18.78	23.26
	17.55	23.77	19.50	21.10
	18.71	23.53	21.17	20.96
	19.12	22.31	23.49	20.22
	20.33	21.48	25.14	19.92
	21.79	21.04	26.70	20.33
	23.56	21.08	28.88	23.07
	25.70	21.38	29.83	24.31
	26.90	21.83	31.43	24.81
	27.19	22.03	34.36	24.75
	27.84	22.62	35.54	24.29
	28.51	23.54	40.92	24.51
	29.74	24.08	42.66	24.75
	31.02	24.29	44.89	25.74
	32.55	24.55	47.75	25.93
	34.42	24.39	50.57	26.10
36.00	24.05			
39.62	24.20			
41.26	24.48			
42.56	24.69			
44.07	25.09			
45.16	25.92			
47.95	26.05			
50.57	26.19			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-9 Riffle, Sta. 75+78	0.00	25.93	0.00	25.85
	7.66	25.57	9.82	25.57
	17.12	25.22	18.42	25.31
	19.27	24.81	21.37	25.10
	21.25	24.71	23.69	23.98
	22.90	23.68	24.36	22.91
	24.09	22.76	24.84	22.08
	25.35	22.18	25.48	21.43
	26.15	21.99	27.92	21.72
	28.07	22.10	30.41	21.44
	30.42	22.06	32.18	21.30
	32.76	22.03	33.76	21.47
	34.84	22.18	34.93	21.83
	35.40	22.48	36.29	22.99
	36.25	22.93	39.05	24.14
	37.35	23.46	41.47	24.68
	37.90	23.96	46.43	25.70
	38.87	24.20	50.70	26.30
	40.34	24.53	56.70	26.47
	44.53	25.45		
47.94	26.17			
53.57	26.57			
56.49	26.59			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-10 Rifle, Sta. 79+82	0.00	27.66	0.00	27.60
	4.16	27.29	5.62	27.04
	9.94	26.38	10.79	26.16
	13.82	25.77	15.97	25.05
	14.67	25.38	18.44	24.69
	16.45	25.02	22.19	24.05
	18.00	24.75	24.47	23.63
	19.93	24.67	26.19	23.10
	22.47	23.84	27.45	22.55
	23.45	23.72	29.13	22.55
	24.08	23.35	30.09	21.94
	25.81	23.30	30.88	21.49
	27.52	22.08	32.29	21.17
	29.35	21.92	33.79	21.02
	31.31	21.71	36.21	20.79
	32.90	21.51	38.21	20.82
	36.04	21.37	39.77	21.19
	36.87	21.00	40.99	22.64
	38.52	21.10	42.97	23.39
	39.08	21.33	45.15	24.00
39.74	21.90	48.55	24.39	
42.09	23.26	57.04	24.64	
43.46	23.61	63.22	24.61	
45.42	24.02			
48.91	24.55			
57.40	24.68			
62.89	24.70			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-11 Pool, Sta. 82+30	0.00	25.95	0.00	25.92
	7.89	25.57	5.93	25.63
	13.55	24.56	11.34	24.82
	16.93	23.93	16.52	23.83
	20.82	23.23	19.62	23.35
	21.95	23.23	22.66	23.43
	23.29	23.19	23.72	20.27
	23.99	22.17	26.17	19.31
	24.66	22.05	29.54	18.51
	24.81	19.95	33.82	18.00
	26.88	19.74	35.36	18.53
	27.90	19.03	37.52	22.69
	32.61	18.48	41.20	23.56
	34.85	19.10	43.95	24.40
	36.94	20.18	55.09	25.09
	37.83	22.98	65.84	26.02
	39.80	23.21	73.06	26.48
	40.88	23.62		
	43.90	24.42		
	55.95	25.20		
63.52	25.89			
72.56	26.58			




Adkin Branch, 05065611, Reach 2

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-12 Pool, Sta. 85+88	0.00	26.87	0.00	26.82
	9.90	26.42	10.23	26.34
	20.27	25.71	18.48	25.77
	25.17	25.13	24.44	25.21
	27.75	24.59	28.45	24.37
	30.14	24.11	31.61	23.79
	32.91	23.61	33.25	23.30
	36.16	22.23	35.04	22.71
	38.20	21.28	37.43	22.37
	39.57	20.54	37.80	21.92
	39.96	19.63	38.37	20.91
	41.51	18.93	39.67	18.07
	44.70	19.29	41.51	17.63
	47.63	19.85	52.49	18.04
	50.43	20.45	52.66	19.66
	51.78	20.71	53.28	20.09
	53.07	21.65	54.79	21.05
	54.55	22.44	54.89	23.33
	56.58	23.61	55.80	23.61
	61.64	24.50	58.85	24.03
	64.51	25.16	62.90	24.53
	75.28	26.09	64.20	25.13
	82.52	26.90	69.12	25.34
		72.54	25.85	
		79.36	26.51	
		82.77	26.83	




Adkin Branch, 05065611, Reach 3

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-13 Pool, Sta. 11+64	0.00	31.88	0.00	31.86
	1.96	31.88	5.27	31.88
	2.82	31.88	8.53	31.81
	4.88	31.82	10.08	32.07
	7.13	31.90	11.50	31.63
	9.06	31.90	12.45	31.50
	9.86	31.87	13.28	31.37
	10.37	31.74	13.88	31.30
	11.06	31.67	14.37	31.45
	12.03	31.61	14.95	31.61
	12.62	31.53	16.18	31.97
	13.17	31.34	18.97	32.00
	13.88	31.16	24.40	32.05
	14.36	31.40		
	15.15	31.72		
	15.65	31.85		
	16.41	32.00		
	19.34	31.99		
	21.87	31.99		
	24.27	31.98		
24.44	32.04			



Adkin Branch, 05065611, Reach 3


	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-14 Riffle, Sta. 14+89	0.00	31.64	0.00	31.61
	1.38	31.49	3.27	31.38
	2.83	31.36	5.60	31.29
	4.92	31.33	8.34	31.22
	6.91	31.28	9.34	31.11
	8.50	31.24	10.53	30.92
	9.40	31.12	11.01	30.67
	10.03	31.02	11.83	30.55
	10.44	30.86	12.72	30.63
	10.60	30.80	13.61	30.74
	10.71	30.71	14.38	30.90
	11.02	30.66	15.92	31.22
	11.21	30.58	17.64	31.29
	11.58	30.63	21.76	31.26
	12.11	30.59	25.05	31.24
	12.54	30.52		
	12.93	30.68		
	13.48	30.79		
	13.97	30.89		
	14.38	30.88		
15.13	31.11			
16.12	31.24			
18.44	31.31			
22.90	31.30			
25.11	31.27			



Adkin Branch, 05065611, Reach 3


	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-15 Riffle, Sta. 19+28	0.00	30.66		
	3.30	30.56		
	8.61	30.26		
	13.27	30.23		
	16.31	30.25		
	17.22	30.22		
	17.98	29.94		
	18.60	29.73		
	18.81	29.70		
	19.03	29.59		
	19.26	29.32		
	19.86	29.33		
	20.39	29.47		
	20.64	29.66		
	20.90	29.87		
	21.92	30.01		
	23.19	30.22		
	25.19	30.49		
	28.07	30.62		
	32.50	30.92		
35.34	31.18			
38.62	31.46			
40.05	31.60			

No Data - Fallen Tree over Channel




Adkin Branch, 05065611, Reach 3

XS-16 Pool, Sta.23+64	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
	0.00	25.98	0.00	25.98
	4.96	25.72	6.84	25.58
	10.01	25.44	13.28	25.18
	13.01	25.18	15.96	24.85
	14.66	24.95	16.79	24.74
	16.29	24.81	17.94	24.69
	18.05	24.63	18.70	24.33
	18.59	24.33	19.22	24.27
	18.86	24.19	19.92	24.12
	19.43	24.13	20.71	24.34
	19.97	24.09	21.69	24.69
	20.33	24.25	22.47	24.82
	21.01	24.44	23.20	25.08
	21.98	24.77	25.85	25.20
	23.04	25.05	27.47	25.36
	23.97	25.20	30.40	25.86
	26.34	25.22		
	27.54	25.34		
	28.93	25.73		
	30.42	25.82		



Adkin Branch, 05065611, Reach 3

	Baseline		MY1	
	Sta.	Elev.	Sta.	Elev.
XS-17 Riffle, Sta. 23+87	0.00	26.01	0.00	26.03
	4.97	25.78	7.42	25.51
	8.45	25.52	11.90	24.98
	11.09	25.05	15.17	24.69
	14.03	24.80	16.79	24.53
	16.48	24.55	17.76	24.37
	17.40	24.37	18.54	24.03
	18.15	24.09	19.07	23.79
	18.64	23.89	19.53	23.65
	19.05	23.83	20.46	23.76
	19.61	23.79	20.94	23.93
	20.10	23.80	21.78	23.99
	20.44	23.80	22.97	24.17
	20.81	23.96	24.01	24.59
	21.79	23.98	27.80	24.67
	22.85	24.06	28.74	24.59
	23.96	24.61	29.57	24.59
	26.35	24.64	31.01	25.16
	29.26	24.54	33.77	25.77
	29.95	24.77		
32.07	25.44			
33.67	25.73			



Figures 5.1-5.3. Longitudinal Profile Plots

Figure 5.1 Reach 1 (Washington Ave. to Gordon St.) - Longitudinal Profile




Figure "Reach 2 (Gordon St. to Lincoln St.) - Longitudinal Profile




Figure Reach 3 (UT to Adkin Branch) - Longitudinal Profile




Table 10B. Baseline Stream Data Summary
Adkin Branch Stream Restoration Project - Phase I - Contract No. 070708001
Reach 1

Parameter	Existing Condition (Wash Ave. to Gordon)	Reference Reach (Johnson Mill)	Proposed (Wash Ave. to Gordon)	Reach 1 Baseline (Washington Ave. to Gordon St.)					
				Min	Mean	Med	Max	SD	n
Dimension and Substrate - Riffle									
Bankfull Width (ft)	20.90	21.20	22.00	14.84	15.95	14.99	18.03	1.80	3
Floodprone Width (ft)	29.40	34.90	40.00	28.45	42.14	41.72	56.25	13.90	3
Bankfull Mean Depth (ft)	1.95	2.25	1.38	0.92	1.35	1.42	1.70	0.40	3
Bankfull Max Depth (ft)	2.26	2.42	1.65	1.50	2.11	2.07	2.77	0.64	3
Bankfull Cross Sectional Area (ft ²)	40.90	47.60	30.30	13.78	21.57	25.23	25.69	6.75	3
Width/Depth Ratio	10.70	9.40	16.00	8.73	12.57	12.70	16.29	3.78	3
Entrenchment Ratio	1.40	1.60	1.80	1.90	2.67	2.31	3.79	0.99	3
Bank Height Ratio	-	-	-	1.00	1.00	1.00	1.00	0.00	3
d50 (mm)	-	-	-						
Profile									
Riffle Length (ft)	-	-	-	13.69	88.32	82.84	173.90	51.83	14
Riffle Slope (ft/ft)	0.0012	0.00001	0.0026	0.0002	0.0016	0.0013	0.0062	0.0016	14
Pool Length (ft)	-	-	-	11.36	24.52	24.15	46.88	8.60	19
Pool Max depth (ft)	3.18	3.56	3.44	2.11	2.99	2.86	4.33	0.72	19
Pool Spacing (ft)	183 - 231	91.1 - 130.0	88 - 132	22.73	95.81	94.46	180.40	41.64	18
Pattern									
Channel Beltwidth (ft)	30 - 50	50 - 1500	44 - 176						
Radius of Curvature (ft)	150 - 320	43 - 235	66 - 110						
Rc: Bankfull Width (ft/ft)	7.2 - 15.3	2.0 - 11.1	3.0 - 5.0						
Meander Wavelength (ft)	175 - 400	250 - 400	264 - 418						
Meander Width Ratio	1.43 - 2.39	2.4 - 70.9	2.0 - 8.0						
Substrate, bed and transport parameters									
Ri% / P%	-	-	-	73% / 27%					
SC% / Sa% / G% / C% / B% / Be%	-	-	-						
d16 / d35 / d50 / d84 / d95/ d _p / d _{sp} (mm)	-	-	-						
Reach Shear Stress (competency) lb/ft ²	N/A		N/A	N/A					
Max part size (mm) mobilized at bankfull	-		-	-					
Unit Stream Power (transport capacity) lbs/ft.s	0.075	0.197	0.220	0.325					
Additional Reach Parameters									
Drainage Area (SM)	4.60	13.50	5.03						
Impervious cover estimate (%)	-	-	-						
Rosgen Classification	G5	B5c	B5c	B5c					
Bankfull Velocity (fps)	1.20	1.70	1.70	1.95					
Bankfull Discharge (cfs)	50.00	80.90	50.00						
Valley length (ft)	-	-	1685	1685					
Channel Thalweg length (ft)	-	-	1750	1727					
Sinuosity (ft)	1.04	1.10	1.04	1.03					
Water Surface Slope (Channel) (ft/ft)	0.0005	0.0010	0.0016	0.00166					
BF slope (ft/ft)	-	-	-	0.00240					
Bankfull Floodplain Area (acres)	-	-	-						
Proportion over wide (%)	-	-	-						
Entrenchment Class (ER Range)	-	-	-						
Incision Class (BHR Range)	-	-	-						
BEHI VL% / L% / M% / H% / VH% / E%	-	-	-						
Channel Stability or Habitat Metric	-	-	-						
Biological or Other	-	-	-						

It should be noted that As-built conditions were completed at the end of construction. Many storm events had occurred between beginning of construction and end of construction that naturally modified constructed parameters.

Table 1004. Baseline Stream Data Summary
Adkin Branch Stream Restoration Project - Phase I - Contract No. 070708001
Reach 2

Parameter	Existing Condition (Gordon to Lincoln)	Reference Reach (Johnson Mill)	Proposed (Gordon to Lincoln)	Reach 2 Baseline (Gordon St. to Lincoln St.)					
				Min	Mean	Med	Max	SD	n
Dimension and Substrate - Riffle									
Bankfull Width (ft)	23.60	21.20	22.00	16.23	16.98	16.81	17.91	0.85	3
Floodprone Width (ft)	45.00	34.90	40.00	48.33	52.40	51.29	57.58	4.72	3
Bankfull Mean Depth (ft)	1.83	2.25	1.47	1.46	1.66	1.64	1.88	0.21	3
Bankfull Max Depth (ft)	2.98	2.42	1.76	2.21	2.38	2.26	2.68	0.26	3
Bankfull Cross Sectional Area (ft ²)	43.30	47.60	32.30	23.68	28.32	27.58	33.70	5.05	3
Width/Depth Ratio	12.90	9.40	15.00	9.53	10.30	10.25	11.12	0.80	3
Entrenchment Ratio	1.90	1.60	1.80	2.99	3.09	3.05	3.22	0.12	3
Bank Height Ratio	-	-	-	1.00	1.00	1.00	1.00	0.00	3
d50 (mm)	-	-	-	-	-	-	-	-	-
Profile									
Riffle Length (ft)	-	-	-	27.43	62.71	62.38	93.27	19.56	10
Riffle Slope (ft/ft)	0.0024	0.00001	0.0031	0.0002	0.0013	0.0010	0.0039	0.0013	10
Pool Length (ft)	-	-	-	14.20	56.38	56.82	113.64	27.38	39
Pool Max depth (ft)	4.14	3.56	3.67	2.74	4.23	4.22	6.48	0.76	39
Pool Spacing (ft)	59.62 - 117.86	91.1 - 130.0	88.0 - 132.0	17.05	73.45	69.60	164.78	32.96	38
Pattern									
Channel Beltwidth (ft)	75 -120	50 - 1500	44.0 - 176.0						
Radius of Curvature (ft)	40 - 146	43 - 235	66.0 - 110.0						
Rc: Bankfull Width (ft/ft)	1.7 - 6.2	2.0 - 11.1	3.0 - 5.0						
Meander Wavelength (ft)	224 - 260	250 - 400	264.0 - 418.0						
Meander Width Ratio	3.18 - 5.08	2.4 - 70.9	2.0 - 8.0						
Substrate, bed and transport parameters									
Ri% / P%	-	-	-	29% / 71% *					
SC% / Sa% / G% / C% / B% / Be%	-	-	-						
d16 / d35 / d50 / d84 / d95/ d _p / d _{sp} (mm)	-	-	-						
Reach Shear Stress (competency) lb/ft ²	N/A		N/A	N/A					
Max part size (mm) mobilized at bankfull	-		-	-					
Unit Stream Power (transport capacity) lbs/ft.s	0.106	0.197	0.230	0.321					
Additional Reach Parameters									
Drainage Area (SM)	5.30	13.50	5.50						
Impervious cover estimate (%)	-	-	-						
Rosgen Classification	B5	B5c	B5c	B5c					
Bankfull Velocity (fps)	1.30	1.70	1.80	1.99					
Bankfull Discharge (cfs)	55.00	80.90	55.00						
Valley length (ft)	-	-	4106	4106					
Channel Thalweg length (ft)	-	-	4246	4270					
Sinuosity (ft)	1.12	1.10	1.03	1.04					
Water Surface Slope (Channel) (ft/ft)	0.0007	0.0010	0.0014	0.0016					
BF slope (ft/ft)	-	-	-	0.0018					
Bankfull Floodplain Area (acres)	-	-	-						
Proportion over wide (%)	-	-	-						
Entrenchment Class (ER Range)	-	-	-						
Incision Class (BHR Range)	-	-	-						
BEHI VL% / L% / M% / H% / VH% / E%	-	-	-						
Channel Stability or Habitat Metric	-	-	-						
Biological or Other	-	-	-						

It should be noted that As-built conditions were completed at the end of construction. Many storm events had occurred between beginning of construction and end of construction that naturally modified constructed parameters.

Table 10f. Baseline Stream Data Summary
Adkin Branch Stream Restoration Project - Phase I - Contract No. 070708001
Reach 3

Parameter	Existing Condition (UT to Adkin Branch)	Reference Reach (UT to Wildcat Branch)	Proposed (UT to Adkin Branch)	Reach 3 Baseline (UT to Adkin Branch)					
				Min	Mean	Med	Max	SD	n
Dimension and Substrate - Riffle									
Bankfull Width (ft)	Mean 3.60	Mean 7.70	Mean 6.00	6.06	7.27	7.69	8.06	1.06	3
Floodprone Width (ft)	8.30	130.00	15.00	23.07	27.62	25.11	34.69	6.20	3
Bankfull Mean Depth (ft)	0.47	1.03	0.55	0.35	0.42	0.40	0.50	0.08	3
Bankfull Max Depth (ft)	3.40	1.56	0.85	0.72	0.81	0.82	0.90	0.09	3
Bankfull Cross Sectional Area (ft ²)	1.70	7.90	3.30	2.43	3.04	2.68	4.00	0.84	3
Width/Depth Ratio	7.60	7.50	11.00	15.15	17.75	16.12	21.97	3.69	3
Entrenchment Ratio	2.30	16.90	2.50	2.86	3.95	3.26	5.72	1.55	3
Bank Height Ratio	-	-	-	1.00	1.00	1.00	1.00	0.00	3
d50 (mm)	-	-	-	-	-	-	-	-	-
Profile									
Riffle Length (ft)	-	-	-	9.59	34.33	26.34	165.84	30.38	28
Riffle Slope (ft/ft)	0.0002	0.0021	0.0032	0.0012	0.0051	0.0044	0.0121	0.0031	28
Pool Length (ft)	-	-	-	4.26	21.38	23.26	52.81	12.04	32
Pool Max depth (ft)	1.45	1.90	1.36	0.64	1.59	1.32	2.95	0.70	32
Pool Spacing (ft)	21.63	14.0 - 16.6	12.0 - 36.0	13.49	42.26	37.22	93.07	20.82	30
Pattern									
Channel Beltwidth (ft)	50.00	13.8 - 19.4	12.0 - 36.0						
Radius of Curvature (ft)	93 - 105	10.9 - 15.3	12.0 - 18.0						
Rc: Bankfull Width (ft/ft)	26.0 - 29.3	1.4 - 2.0	2.0 - 3.0						
Meander Wavelength (ft)	212 - 517	22.5 - 29.0	18.0 - 48.0						
Meander Width Ratio	13.97	1.8 - 2.5	2.0 - 6.0						
Substrate, bed and transport parameters									
Ri% / P%	-	-	-	58% / 42%					
SC% / Sa% / G% / C% / B% / Be%	-	-	-						
d16 / d35 / d50 / d84 / d95/ d _p / d _{sp} (mm)	-	-	-						
Reach Shear Stress (competency) lb/ft ²	N/A		N/A	N/A					
Max part size (mm) mobilized at bankfull	-		-	-					
Unit Stream Power (transport capacity) lbs/ft.s	0.007	0.140	0.080	0.083					
Additional Reach Parameters									
Drainage Area (SM)	0.12	0.44	0.12						
Impervious cover estimate (%)	-	-	-						
Rosgen Classification	E5	E5	E5	E5					
Bankfull Velocity (fps)	2.10	1.20	1.10	1.44					
Bankfull Discharge (cfs)	3.50	9.20	3.50						
Valley length (ft)	1200	-	1200	1200					
Channel Thalweg length (ft)	1200	-	1615	1582					
Sinuosity (ft)	1.00	1.15	1.35	1.32					
Water Surface Slope (Channel) (ft/ft)	0.0001	0.0024	0.0022	0.0028					
BF slope (ft/ft)	-	-	-	0.0030					
Bankfull Floodplain Area (acres)	-	-	-						
Proportion over wide (%)	-	-	-						
Entrenchment Class (ER Range)	-	-	-						
Incision Class (BHR Range)	-	-	-						
BEHI VL% / L% / M% / H% / VH% / E%	-	-	-						
Channel Stability or Habitat Metric	-	-	-						
Biological or Other	-	-	-						

It should be noted that As-built conditions were completed at the end of construction. Many storm events had occurred between beginning of construction and end of construction that naturally modified constructed parameters.

Table 11. Monitoring Data - Dimensional Morphology Summary (Dimensional Parameters - Cross Section)
Adkin Branch Stream Restoration Project - Phase I
Contract No. 070708001

	Cross Section 1 (Riffle)							Cross Section 2 (Pool)							Cross Section 3 (Riffle)							Cross Section 4 (Pool)							Cross Section 5 (Riffle)																					
Dimension and substrate ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+															
Bankfull Width (ft)	14.84	12						24.28	18.49						18.03	19.72						17.42	16.08						14.99	16.25																				
Floodprone Width (ft)	56.25	44.63						72.2	71.85						41.72	52.82						39.81	42.63						28.45	49.93																				
Bankfull Mean Depth (ft)	1.7	1.85						1.97	2.57						1.42	1.61						1.46	1.59						0.92	1.16																				
Bankfull Max Depth (ft)	2.77	2.47						3.33	3.89						2.07	2.76						2.05	2.17						1.5	2.55																				
Bankfull Cross Sectional Area (ft ²)	25.23	22.2						47.75	47.44						25.69	31.85						25.48	25.55						13.78	18.8																				
Bankfull Width/Depth Ratio	8.73	6.49						12.32	7.19						12.7	12.25						11.93	10.11						16.29	14.01																				
Bankfull Entrenchment Ratio	3.79	3.72						2.97	3.89						2.31	2.68						2.29	2.65						1.9	3.07																				
Bankfull Bank Height Ratio	1	1						1	1						1	1						1	1						1	1																				
	Cross Section 6 (Pool)							Cross Section 7 (Riffle)							Cross Section 8 (Pool)							Cross Section 9 (Riffle)							Cross Section 10 (Riffle)																					
Dimension and substrate ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+															
Bankfull Width (ft)	15.1	18.04						17.91	16.15						16.57	15.76						16.81	15.69						16.23	17.72																				
Floodprone Width (ft)	57.39	57.49						57.58	64.23						50.57	50.57						51.29	56.7						48.33	51.64																				
Bankfull Mean Depth (ft)	2.94	3.16						1.88	2.85						1.93	2.76						1.64	2.01						1.46	1.61																				
Bankfull Max Depth (ft)	4.39	4.85						2.68	4.26						3.51	4.89						2.21	2.84						2.26	2.6																				
Bankfull Cross Sectional Area (ft ²)	44.41	57.01						33.7	45.98						31.92	43.57						27.58	31.55						23.68	28.48																				
Bankfull Width/Depth Ratio	5.14	5.71						9.53	5.67						8.59	5.71						10.25	7.81						11.12	11.01																				
Bankfull Entrenchment Ratio	3.8	3.19						3.22	3.98						3.05	3.21						3.05	3.61						2.99	2.91																				
Bankfull Bank Height Ratio	1	1						1	1						1	1						1	1						1	1																				
	Cross Section 11 (Pool)							Cross Section 12 (Pool)							Cross Section 13 (Pool)							Cross Section 14 (Riffle)							Cross Section 15 (Riffle)																					
Dimension and substrate ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+															
Bankfull Width (ft)	16.31	17.99						23.66	17.42						5.89	5.97						7.69	7.63						6.06	N/A																				
Floodprone Width (ft)	72.56	73.06						82.52	82.77						24.44	24.4						25.11	25.05						34.69	N/A																				
Bankfull Mean Depth (ft)	3.19	3.51						2.72	3.87						0.31	0.35						0.35	0.34						0.4	N/A																				
Bankfull Max Depth (ft)	4.71	5.43						4.68	4.74						0.71	0.67						0.72	0.67						0.9	N/A																				
Bankfull Cross Sectional Area (ft ²)	52.00	63.18						64.42	67.38						1.81	2.09						2.68	2.6						2.43	N/A																				
Bankfull Width/Depth Ratio	5.11	5.13						8.7	4.5						19	17.06						21.97	22.44						15.15	N/A																				
Bankfull Entrenchment Ratio	4.45	4.06						3.49	4.75						4.15	4.09						3.26	3.28						5.72	N/A																				
Bankfull Bank Height Ratio	1	1						1	1						1	1						1	1						1	N/A																				
	Cross Section 16 (Pool)							Cross Section 17 (Riffle)							<p align="center">NOTE:</p> <p>Reach 1 - Washington Ave. to Gordon St. - Cross-Sections 1 through 5</p> <p>Reach 2 - Gordon St. to Lincoln St. - Cross-Sections 6 - 12</p> <p>Reach 3 - UT to Adkin Branch - Cross-Sections 13-17</p> <p>Cross-section 15: Not able to survey due to fallen tree across cross-section</p>																																			
Dimension and substrate ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+																													Base	MY1	MY2	MY3	MY4	MY5	MY+	
Bankfull Width (ft)	11.59	9.14						8.06	7.82																																									
Floodprone Width (ft)	30.42	30.4						23.07	25.58																																									
Bankfull Mean Depth (ft)	0.46	0.43						0.5	0.48																																									
Bankfull Max Depth (ft)	1.11	0.96						0.82	0.94																																									
Bankfull Cross Sectional Area (ft ²)	5.34	3.91						4	3.76																																									
Bankfull Width/Depth Ratio	25.2	21.26						16.12	16.29																																									
Bankfull Entrenchment Ratio	2.62	3.33						2.86	3.27																																									
Bankfull Bank Height Ratio	1	1						1	1																																									

¹ = Based on current bankfull elevation, determined by field indicators of bankfull.

Table 12.1 Monitoring Data - Stream Reach Data Summary
Adkin Branch Stream Restoration Project - Phase 1 - Contract No. 070708001

Reach 1 (Washington Ave. to Gordon St.)

Parameter	Baseline						MY-1						MY-2						MY-3						MY-4						MY-5					
	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n
Dimension and substrate - Riffle only																																				
Bankfull Width (ft)	14.84	15.95	14.99	18.03	1.80	3	12.00	15.99	16.25	19.72	3.87	3																								
Floodprone Width (ft)	28.45	42.14	41.72	56.25	13.90	3	44.63	49.13	49.93	52.82	4.15	3																								
Bankfull Mean Depth (ft)	0.92	1.35	1.42	1.70	0.40	3	1.16	1.54	1.61	1.85	0.35	3																								
¹ Bankfull Max Depth (ft)	1.50	2.11	2.07	2.77	0.64	3	2.47	2.59	2.55	2.76	0.15	3																								
Bankfull Cross Sectional Area (ft ²)	13.78	21.57	25.23	25.69	6.75	3	18.80	24.28	22.20	31.85	6.77	3																								
Width/Depth Ratio	8.73	12.57	12.70	16.29	3.78	3	6.49	10.92	12.25	14.01	3.93	3																								
Entrenchment Ratio	1.90	2.67	2.31	3.79	0.99	3	2.68	3.16	3.07	3.72	0.53	3																								
¹ Bank Height Ratio	1	1	1	1	0	3	1	1	1	1	0	3																								
Profile																																				
Riffle Length (ft)	13.69	88.32	82.84	173.90	51.83	14	15.63	69.32	55.40	193.19	46.86	15																								
Riffle Slope (ft/ft)	0.000	0.002	0.001	0.006	0.002	14	0.000	0.003	0.003	0.012	0.003	15																								
Pool Length (ft)	11.36	24.52	24.15	46.88	8.60	19	12.78	38.13	38.35	90.91	20.95	19																								
Pool Max Depth (ft)	2.11	2.99	2.86	4.33	0.72	19	2.76	4.00	4.34	5.39	0.79	19																								
Pool Spacing (ft)	22.73	95.81	94.46	180.40	41.64	18	12.78	91.39	88.78	217.34	59.08	18																								
Pattern																																				
Channel Beltwidth (ft)																																				
Radius of Curvature (ft)																																				
Rc:Bankfull Width (ft)																																				
Meander Wavelength (ft)																																				
Meander Width Ratio																																				
Additional Reach Parameters																																				
Rosgen Classification				B5c						B5c																										
Channel Thalweg length (ft)				1727						1764																										
Simosity (ft)				1.03						1.05																										
Water Surface Slope (Channel) (ft/ft)				0.00166						0.0016																										
BF slope (ft/ft)				0.0024						0.00263																										
³ Ri% / P%				73% / 27%						59% / 41%																										
³ SC% / Sa% / G% / C% / B% / Be%																																				
³ d16 / d35 / d50 / d84 / d95																																				
² % of Reach with Eroding Banks																																				
Channel Stability or Habitat Metric																																				
Biological or Other																																				

Shaded cells indicate that these will typically not be filled in.

¹ = The distributions for these parameters can include information from both the cross-section surveys and the longitudinal profile.

² = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

³ = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

Table 12.2 Monitoring Data - Stream Reach Data Summary
Adkin Branch Stream Restoration Project - Phase 1 - Contract No. 070708001

Reach 2 (Caswell St. to Lincoln St.)

Parameter	Baseline					MY-1					MY-2					MY-3					MY-4					MY-5										
	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n	Min	Mean	Med	Max	SD	n
Dimension and substrate - Riffle only																																				
Bankfull Width (ft)	16.23	16.98	16.81	17.91	0.85	3	15.69	16.52	16.15	17.72	1.06	3																								
Floodprone Width (ft)	48.33	52.40	51.29	57.58	4.72	3	51.64	57.52	56.70	64.23	6.34	3																								
Bankfull Mean Depth (ft)	1.46	1.66	1.64	1.88	0.21	3	1.61	2.16	2.01	2.85	0.63	3																								
Bankfull Max Depth (ft)	2.21	2.38	2.26	2.68	0.26	3	2.60	3.23	2.84	4.26	0.90	3																								
Bankfull Cross Sectional Area (ft ²)	23.68	28.32	27.58	33.70	5.05	3	28.48	35.34	31.55	45.98	9.34	3																								
Width/Depth Ratio	9.53	10.30	10.25	11.12	0.80	3	5.67	8.16	7.81	11.01	2.69	3																								
Entrenchment Ratio	2.99	3.09	3.05	3.22	0.12	3	2.91	3.50	3.61	3.98	0.54	3																								
Bank Height Ratio	1	1	1	1	0	3	1	1	1	1	0	3																								
Profile																																				
Riffle Length (ft)	27.43	62.71	62.38	93.27	19.56	10	5.23	34.74	35.95	61.27	16.12	11																								
Riffle Slope (ft/ft)	0.0002	0.0013	0.0010	0.0039	0.0013	10	0.0003	0.0029	0.0015	0.0132	0.0039	11																								
Pool Length (ft)	14.20	56.38	56.82	113.64	27.38	39	7.56	65.31	61.25	157.78	33.20	45																								
Pool Max Depth (ft)	2.74	4.23	4.22	6.48	0.76	39	2.60	4.80	4.97	6.54	0.89	45																								
Pool Spacing (ft)	17.05	73.45	69.60	164.78	32.96	38	11.36	63.92	56.82	139.21	28.40	44																								
Pattern																																				
Channel Beltwidth (ft)																																				
Radius of Curvature (ft)																																				
Re:Bankfull Width (ft/ft)																																				
Meander Wavelength (ft)																																				
Meander Width Ratio																																				
Additional Reach Parameters																																				
Rosgen Classification	B5c					B5c																														
Channel Thalweg length (ft)	3096					3131																														
Sinuosity (ft)	1.04					1.04																														
Water Surface Slope (Channel) (ft/ft)	0.0016					0.00175																														
BF slope (ft/ft)	0.0018					0.00204																														
^a R ₁ % / P%	29% / 71%					5% / 95%																														
³ SC% / Sa% / G% / C% / B% / Be%																																				
³ d16 / d35 / d50 / d84 / d95																																				
² % of Reach with Eroding Banks																																				
Channel Stability or Habitat Metric																																				
Biological or Other																																				

Shaded cells indicate that these will typically not be filled in.

* Reach 2 is a predominately pool system due to need to drop grade at the lower end of the project.

1 = The distributions for these parameters can include information from both the cross-section surveys and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

Appendix E. Hydrologic Data

Table 13. Verification of Bankfull Events

Date	Crest Gauge Info		Gauge Reading (ft)	Gauge Elevation (ft)	Crest Elevation (ft)	Bankfull Elevation (ft)	Height above Bankfull (ft)	Photo
	Site	Sta.						
10/26/2011	3	22+65	1.96	25.51	27.47	26.07	1.40	6.1
10/26/2011	1	54+00	2.8	25.27	28.07	27.03	1.04	6.2




Figures 6.1 & 6.2 Crest Gauge Photos

Appendix F. Credit Calculation Figures

LEGEND



- E— EASEMENT BOUNDARY
- AS-BUILT TOP OF BANK
- ◻ < 50' BUFFER (0 RIPARIAN BUFFER OR NUTRIENT OFFSET BUFFER CREDIT)
- ◻ 50' BUFFER
- ◻ 50' – 200' BUFFER
- ◻ SEWER EASEMENT
- ◻ DITCH BUFFER CREDIT DEDUCTION
- ◻ VEGETATION PLOT



ADKIN BRANCH CREDIT CALCULATION FIGURES	
SCO#: 050656101	COUNTY: LENOIR
FIGURE D.1	
DATE: 01/05/12	









LEGEND


- E— EASEMENT BOUNDARY
- AS-BUILT TOP OF BANK
- ◻ < 50' BUFFER (0 RIPARIAN BUFFER OR NUTRIENT OFFSET BUFFER CREDIT)
- ◻ 50' BUFFER
- ◻ 50' – 200' BUFFER
- ◻ SEWER EASEMENT
- ◻ DITCH BUFFER CREDIT DEDUCTION
- ◻ VEGETATION PLOT





ADKIN BRANCH CREDIT CALCULATION FIGURES	
SCO#: 050656101	COUNTY: LENOIR
FIGURE D.2	
DATE: 01/05/12	

LEGEND

-  EASEMENT BOUNDARY
-  AS-BUILT TOP OF BANK
-  < 50' BUFFER (0 RIPARIAN BUFFER OR NUTRIENT OFFSET BUFFER CREDIT)
-  50' BUFFER
-  50' - 200' BUFFER
-  SEWER EASEMENT
-  DITCH BUFFER CREDIT DEDUCTION
-  VEGETATION PLOT



ADKIN BRANCH CREDIT CALCULATION FIGURES	
SCO#: 050656101	COUNTY: LENOIR
FIGURE D.3	
DATE: 01/05/12	





LEGEND









- EASEMENT BOUNDARY
- AS-BUILT TOP OF BANK
- < 50' BUFFER (0 RIPARIAN BUFFER OR NUTRIENT OFFSET BUFFER CREDIT)
- 50' BUFFER
- 50' - 200' BUFFER
- SEWER EASEMENT
- DITCH BUFFER CREDIT DEDUCTION
- VEGETATION PLOT




ADKIN BRANCH CREDIT CALCULATION FIGURES	
SCO#: 050656101	COUNTY: LENOIR
FIGURE D.4	
DATE: 01/05/12	



LEGEND

-  EASEMENT BOUNDARY
-  AS-BUILT TOP OF BANK
-  < 50' BUFFER (0 RIPARIAN BUFFER OR NUTRIENT OFFSET BUFFER CREDIT)
-  50' BUFFER
-  50' - 200' BUFFER
-  SEWER EASEMENT
-  DITCH BUFFER CREDIT DEDUCTION
-  VEGETATION PLOT



ADKIN BRANCH CREDIT CALCULATION FIGURES	
SCO#: 050656101	COUNTY: LENOIR
FIGURE D.5	
DATE: 01/05/12	