

Year 5 Monitoring Report for Stream Restoration of Bailey Fork

Burke County, NC
SCO # D04006-02



Prepared for:
NCDENR – EEP
2728 Capital Blvd, Suite 1H 103
Raleigh NC 27604



Submitted: February 2011

Prepared by:

Wetlands Resource Center
3970 Bowen Road
Canal Winchester, Ohio 43110
Project Manager: Cal Miller
P: (614) 864-7511
F: (614) 866-3691

And

EMH&T, Inc.
5500 New Albany Road
Columbus, Ohio 43054
Project Manager: Miles Hebert
P: (614) 775-4205
F: (614) 775-4802
Main: (614) 775-4500



Evans, Mechwart, Hambleton & Tilton, Inc.
Engineers, Surveyors, Planners, Scientists

Table of Contents

| | |
|--|-----------|
| I. Executive Summary | 1 |
| II. Project Background | 5 |
| A. Location and Setting | |
| B. Project Structure, Mitigation Type, Approach and Objectives | |
| C. Project History and Background | |
| D. Monitoring Plan View | |
| III. Project Condition and Monitoring Results | 16 |
| A. Vegetation Assessment | |
| 1. Soil Data | |
| 2. Vegetative Problem Areas | |
| 3. Vegetative Problem Areas Plan View | |
| 4. Stem Counts | |
| 5. Vegetation Plot Photos | |
| B. Stream Assessment | |
| 1. Hydrologic Criteria | |
| 2. Stream Problem Areas | |
| 3. Stream Problem Areas Plan View | |
| 4. Stream Problem Areas Photos | |
| 5. Fixed Station Photos | |
| 6. Stability Assessment | |
| 7. Quantitative Measures | |
| IV. Methodology | 33 |

List of Tables

| | |
|-------------|--|
| Table I. | Project Structure Table |
| Table II. | Project Mitigation Objectives Table |
| Table III. | Project Activity and Reporting History |
| Table IV. | Project Contact Table |
| Table V. | Project Background Table |
| Table VI. | Preliminary Soil Data |
| Table VII. | Vegetative Problem Areas |
| Table VIII. | Stem Counts for Each Species Arranged by Plot |
| Table IX. | Verification of Bankfull Events |
| Table X. | Stream Problem Areas |
| Table XI. | Categorical Stream Feature Visual Stability Assessment |
| Table XII. | Baseline Geomorphic and Hydraulic Summary |
| Table XIII. | Morphology and Hydraulic Monitoring Summary |

List of Appendices

Appendix A Vegetation Raw Data

1. Vegetation Monitoring Plot Photos
2. Vegetation Data Tables

Appendix B Geomorphologic Raw Data

1. Fixed Station Photos
2. Table B1. Qualitative Visual Stability Assessment
3. Cross Section Plots
4. Longitudinal Profiles
5. Pebble Count Plots
6. Bankfull Event Photos
7. Stream Problem Areas Plan View
8. Stream Problem Area Photos

I. EXECUTIVE SUMMARY

The Bailey Fork stream restoration project is located near Morganton in Burke County, North Carolina. Prior to restoration, the streambanks were denuded, actively eroding, and had nearly vertical profiles. Vegetative cover was minimal along the stream. The project goal for the restoration, completed during early 2006, was to modify the dimension, pattern, and profile of the existing stream channels to stable and self-maintaining conditions by utilizing natural channel design techniques and procedures. Elements of the restoration design included improved bedform features, enhanced aquatic habitat diversity, establishment of riffle-pool sequences, in-stream grade control structures, rootwad bank stabilization, and establishment of a native forested riparian plant community. The following report documents the Year 5 Annual Monitoring for the project.

Monitoring of the vegetation was completed in September 2010 following the Carolina Vegetation Survey methodology. Stem counts completed in 10 vegetation plots show an average density of 571 stems per acre for the site, which exceeds the success criteria of 320 stems per acre after three years and the allowable 10% mortality for 288 stems/acre after 4 years and 260 stems/acre after 5 years. In year 5, all vegetation plots have stem densities above the minimum. Additionally, a substantial number of recruit stems have been found in all plots. The recruit stems increase the total stem density across the site by 62% and help all plots to surpass the minimum criteria.

A few vegetative problem areas noted to be of low concern in 2009 were removed from the problem area table in 2010. These included scattered populations of problematic species (*Pueraria montana*) - kudzu) as well as an established population of one invasive species (*Sericea lespedeza*). The problematic species have been proactively managed by herbicide treatment and woody vegetation survival is high. The section along UT2 which was noted to have sparse vegetation along the stream banks in 2009, had been re-colonized by stabilizing vegetation in 2010.

This monitoring year, several features have been removed from the stream problem areas tables of previous monitoring years, as project reaches have remained stable through the monitoring period, and show overall evidence the reaches are maintaining profile equilibrium. In Year 5, several features have been removed from the stream problem areas tables of previous monitoring years. The majority of these areas were structures that have been embedded throughout the monitoring period or they are areas of bank scour that were repaired in the summer of 2009. It is important to note that the stream channels remain stable in these areas in 2010. Once the channel has remained stable throughout two consecutive years of monitoring, the structures are no longer considered problem areas and are removed from the table. Only one new scour area was observed on Lower Bailey Fork in 2010. The left bank near this station is heavily vegetated and appears stable. It is therefore predicted that this minimal scour area will not worsen, over time.

The 2010 visual stream stability assessment revealed that the majority of stream features are functioning as designed and built on the project reaches. The structures previously identified as problematic were vanes/J-hooks, each of which has become embedded in sand size sediment. However, the channel is stable at each location where aggradation has covered a structure. In past years, a few meanders were found in a limited state of erosion, and a few point bars had formed within the project reaches. The pools and riffles that were noted to be performing in a state unlike

that of the as-built conditions were the result of aggradation along the corresponding reaches. The depositional trends are considered a natural component of the sand-dominated watershed.

Dimensional measurements of the monumented cross-sections remain stable when compared to as-built conditions. The comparison of the yearly long-term stream monitoring profile data show stability with minor changes from as-built conditions that are suspected to be due to aggradation. The substrate of the constructed riffles and pools remain stable, with median particle sizes ranging from fine gravel to very coarse gravel for riffles, and medium sand, for pools. Based on the crest gage network installed on the project reaches, three bankfull events have been recorded since construction was completed.

The following tables summarize the geomorphological changes along the restoration reaches for each stream. The values in the tables are the median values for each parameter.

Upper Bailey Fork

| Parameter | Pre-Restoration | As-built | Year 1 | Year 2 | Year 3 | Year 4 | Year 5 |
|---------------------|-----------------|------------|------------|------------|------------|------------|------------|
| Length | 1,383.0 ft | 1,543.0 ft | 1,543.0 ft | 1,543.0 ft | 1,543.0 ft | 1,543.0 ft | 1,543.0 ft |
| Bankfull Width | 23.2 ft | 33.0 ft | 30.0 ft | 32.8 ft | 32.8 ft | 33.7 ft | 31.3 ft |
| Bankfull Mean Width | 3.1 ft | 2.3 ft | 3.0 ft | 2.6 ft | 2.6 ft | 2.6 ft | 2.7 ft |
| Bankfull Max Depth | 4.8 ft | 4.7 ft | 4.8 ft | 4.4 ft | 4.5 ft | 4.5 ft | 4.9 ft |
| Bankfull Mean Depth | 7.6 | 14.3 | 10.1 | 12.9 | 12.8 | 13.2 | 11.7 |
| Bankfull Ratio | 9.0 | 3.2 | 3.5 | 3.2 | 3.2 | 3.2 | 3.4 |
| Bank Height Ratio | 2.0 | 1.1 | 1.1 | 1.1 | 1.1 | 1.0 | 1.0 |
| Sinuosity | 1.1 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 |

Lower Bailey Fork

| Parameter | Pre-Restoration | As-built | Year 1 | Year 2 | Year 3 | Year 4 | Year 5 |
|---------------------|-----------------|------------|------------|------------|------------|------------|------------|
| Length | 1,125.3 ft | 1,170.4 ft | 1,170.4 ft | 1,170.4 ft | 1,170.4 ft | 1,170.4 ft | 1,170.4 ft |
| Bankfull Width | 28.7 ft | 31.5 ft | 32.4 ft | 32.7 ft | 32.9 ft | 31.8 ft | 32.9 ft |
| Bankfull Mean Width | 2.3 ft | 2.6 ft | 2.5 ft | 2.5 ft | 2.6 ft | 2.4 ft | 2.7 ft |
| Bankfull Max Depth | 4.8 ft | 4.3 ft | 4.4 ft | 4.3 ft | 4.3 ft | 4.1 ft | 4.7 ft |
| Bankfull Mean Depth | 7.8 | 12.1 | 12.8 | 12.9 | 12.8 | 13.3 | 12.3 |
| Bankfull Ratio | 7.9 | 3.4 | 3.2 | 3.2 | 3.2 | 3.3 | 3.2 |
| Bank Height Ratio | 2.0 | 1.1 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 |
| Sinuosity | 1.2 | 1.3 | 1.3 | 1.3 | 1.3 | 1.3 | 1.3 |

Unnamed Tributary 1

| Parameter | Pre- Restoration | As-built | Year 1 | Year 2 | Year 3 | Year 4 | Year 5 |
|------------------------|---------------------|------------|------------|------------|------------|------------|------------|
| Length | 1,648.1 ft | 1,758.1 ft | 1,758.1 ft | 1,758.1 ft | 1,758.1 ft | 1,758.1 ft | 1,758.1 ft |
| Bankfull Width | 23.2 ft | 22.0 ft | 16.1 ft | 15.5 ft | 15.5 ft | 15.7 ft | 16.4 ft |
| Bankfull Mean Depth | 3.1 ft | 1.2 ft | 0.9 ft | 0.9 ft | 0.9 ft | 0.9 ft | 1.0 ft |
| Bankfull Max Depth | 4.8 ft | 2.4 ft | 1.8 ft | 1.9 ft | 1.8 ft | 1.9 ft | 2.1 ft |
| Width/Depth Ratio | 7.8 | 22.7 | 18.5 | 16.5 | 17.1 | 18.5 | 17.0 |
| Entrenchment Ratio | 7.9 | 3.3 | 4.3 | 4.3 | 4.5 | 4.5 | 4.3 |
| Bank Height Ratio | 2.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 |
| Sinuosity | 1.3 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 |

Unnamed Tributary 2

| Parameter | Pre- Restoration | As-built | Year 1 | Year 2 | Year 3 | Year 4 | Year 5 |
|------------------------|---------------------|------------|------------|------------|------------|------------|------------|
| Length | 898.9 ft | 1,271.0 ft | 1,271.0 ft | 1,271.0 ft | 1,271.0 ft | 1,271.0 ft | 1,271.0 ft |
| Bankfull Width | 8.2 ft | 18.6 ft | 17.0 ft | 13.4 ft | 12.3 ft | 13.1 ft | 14.0 ft |
| Bankfull Mean Depth | 2.4 ft | 1.0 ft | 0.9 ft | 0.8 ft | 0.7 ft | 0.7 ft | 0.8 ft |
| Bankfull Max Depth | 3.5 ft | 1.9 ft | 1.6 ft | 1.3 ft | 1.2 ft | 1.4 ft | 1.6 ft |
| Width/Depth Ratio | 3.4 | 18.6 | 18.7 | 16.7 | 16.8 | 17.9 | 18.2 |
| Entrenchment Ratio | 9.9 | 3.6 | 4.0 | 5.0 | 4.8 | 4.5 | 4.8 |
| Bank Height Ratio | 1.6 | 1.0 | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 |
| Sinuosity | 1.1 | 1.5 | 1.5 | 1.5 | 1.5 | 1.5 | 1.5 |

II. PROJECT BACKGROUND

A. Location and Setting

The project site is located approximately 2 miles southwest of Morganton, Burke County, North Carolina. The site is located 1.7 miles southwest of the I-40/US 64 interchange, as shown in Figure 1. The stream channels included in this project are the mainstem of Bailey Fork, and two unnamed tributaries to Bailey Fork, designated as UT1 and UT2. The project reach along the mainstem includes a portion upstream of Propst Road (hereafter referred to as Upper) and a portion downstream of that road (hereafter referred to as Lower).

The directions to the project site are as follows:

From I-40, take US 64 south to Propst Road (SR 1112) and turn right. The project site is located on the north and south sides of Propst Road approximately 1,800 feet from the Propst Road and US 64 intersection.

B. Project Structure, Mitigation Type, Approach and Objectives

The primary, pre-existing land use within the immediate project site was agricultural. Based on photographic interpretation, the site had been historically utilized for agricultural row crop production and hayland. It is very likely the project site had been farmed since the Civil War era. The site was degraded by past land management practices including mechanical land clearing, straightening and dredging the stream channels. The project site was most recently utilized to produce hay for livestock feed. The stream banks were denuded, actively eroding, with vertical to undercut streambanks. Vegetative cover was minimal along the stream corridor, resulting in streambank erosion and lateral channel migration. The channels were deeply incised and laterally confined. Prior to restoration, the floodplain was functioning as an abandoned terrace perched above the bankfull elevation.

The project restoration goal was to restore channel dimension, pattern, and profile to stable and self-maintaining conditions utilizing natural channel design techniques and procedures. Physical restoration and water quality improvements were accomplished by meeting the restoration goals and objectives below:

- Design channels with the appropriate cross-sectional dimension, pattern, and longitudinal profile based on reference reach boundary conditions.
- Improve and create bedform and aquatic habitat features (riffles, runs, pools, and glides)
- Integrate, in conjunction with the stream restoration, a nested floodplain (bankfull bench) connected to the bankfull channel elevation (Priority Level II restoration) or raise the bed elevation of the stream reconnecting the bankfull elevation to the existing floodplain elevation (Priority Level I restoration).
- Restore channel and streambank stability by integrating in-stream grade control structures, root wads, and native revetment while also creating stable and functional aquatic and terrestrial habitat.
- Establish a native forested riparian plant community within a minimum 30-foot buffer, measured horizontally from the left and right top of bank. Eradicate exotic vegetation and protect the riparian corridor with a perpetual conservation easement.
- Provide aesthetic and educational opportunities.

BAILEY FORK STREAM RESTORATION

FIGURE 1: SITE VICINITY MAP


N.C. ECOSYSTEM ENHANCEMENT PROGRAM

M C M X X V I

Date: December, 2006

Job No. 2006-1626

Scale: 1" = 3000'



Restoration of the streams has met the objective of the project along both the mainstem of Thompsons Fork and the UT, providing the desired habitat and stability features required to improve and enhance the ecologic health of the streams for the long-term. Specifically, the completed restoration project has accomplished the items listed below.

Upper Bailey Fork:

- Reversed the effects of channelization using Priority Level II restoration techniques. The restoration has increased the median width/depth ratios from 7.6 to 11.7 after construction completion and 5 years of monitoring.
- Restored natural stream pattern, profile and dimension throughout the 1,543 l.f. stream reach, increasing channel sinuosity from 1.1 to 1.4, while creating a more stable relationship between the valley and bankfull slopes (the bankfull slope was greater than the valley slope under pre-existing conditions; the bankfull slope is now less than the valley slope).
- Stabilized eroding streambanks by providing an appropriately sized channel with stable streambank slopes using a combination of embedded stone, natural fabrics and aggressive native streamside and riparian revetment. The average Bank Height Ratio has been decreased from 1.95 (deeply incised) to 1.00 (stable) in Year 5.
- Provided a re-connection between the restored stream channel and a nested floodplain (bankfull bench) connected to the bankfull channel elevation (Priority Level II restoration). The completed restoration changed the average entrenchment ratio to 3.37, and restored the pre-existing unstable, incised and entrenched G4/F4 stream channel to a stable C4 stream type (Rosgen, 1994).
- Created instream aquatic habitat features including deep pools, rootwad streamside fish cover and streambank stabilization, constructed riffles, rock cross vanes and J-Hook vanes with deep pools and native streamside revetment to enhance outer meander bend stability, shade the pools, provide fish cover and lower water temperature to transition the channel thalweg of the restored stream to meet the culvert invert elevations at the three – 7.5 ft x 10.8 ft oval corrugated metal pipes (CMP) on the south side of Propst Road.
- Revegetated the stream banks and riparian corridor with indigenous trees, shrubs, herbaceous ground cover and preserved the riparian corridors within a perpetual conservation easement.

Lower Bailey Fork:

- Reversed the effects of channelization using Priority Level II restoration techniques. The restoration has increased the median width/depth ratios from 7.8 to 12.3 after construction completion and 5 years of monitoring.
- Restored natural stream pattern, profile and dimension throughout the 1,170 l.f. stream reach, increasing channel sinuosity from 1.2 to 1.3, while creating a more stable relationship between the valley and bankfull slopes (again, the bankfull slope was greater than the valley slope under pre-existing conditions; the bankfull slope is now less than the valley slope).
- Stabilized eroding streambanks by constructing an appropriately sized channel with stable streambank slopes using a combination of embedded stone, natural fabrics and aggressive native streamside and riparian revetment. The average Bank Height Ratio has been decreased from 1.95 (deeply incised) to 1.00 (stable).
- Provided a re-connection between the restored stream channel and a nested floodplain (bankfull bench) connected to the bankfull channel elevation (Priority

Level II restoration). The completed restoration changed the average entrenchment ratio to 3.19, and restored the pre-existing unstable, incised and entrenched G4/F4 stream channel to a stable C4 stream type.

- Created instream aquatic habitat features including deep pools, rootwad streamside fish cover and streambank stabilization, constructed riffles, single arm log vanes, rock cross vanes and J-Hook vanes with deep scour pools and native streamside revetment to enhance outer meander bend stability, shade the pools, provide fish cover and lower water temperature.
- Revegetated the stream banks and riparian corridor with indigenous trees, shrubs, herbaceous ground cover and preserved the riparian corridors within a perpetual conservation easement.

Unnamed Tributary (UT1):

- Reversed the effects of channelization utilizing natural channel design restoration techniques. The average width/depth ratio of the restored stream channel was increased from 7.8 to 17.0 after construction completion and five years of monitoring.
- Restored natural stream pattern, profile and dimension throughout the 1,758 l.f. stream reach, increasing channel sinuosity from 1.3 to 1.4, and providing a more stable relationship between the valley and bankfull slopes (the bankfull and valley slopes were essentially parallel under pre-existing condition. The bankfull slope is now less than the valley slope).
- Stabilized eroding streambanks by providing an appropriately sized channel with stable streambank slopes. The average Bank Height Ratio has been changed from 2.10 (extremely incised) to 1.00 (stable).
- Raised the streambed elevation reconnecting the bankfull elevation to the existing floodplain elevation (Priority Level I restoration).
- The completed restoration changed the average entrenchment ratio to 4.26.
- Created instream aquatic habitat features including deep pools, rootwad streamside fish cover and streambank stabilization, constructed riffles, rock sills, step cross vanes and J-Hook vanes with deep scour pools and native streamside revetment to enhance outer meander bend stability, shade the pools, provide fish cover and lower water temperature.
- Revegetated the stream banks and riparian corridor with indigenous trees, shrubs, herbaceous ground cover and preserved the riparian corridors within a perpetual conservation easement.

Unnamed Tributary (UT2):

- Reversed the effects of channelization utilizing natural channel design restoration techniques. The average width/depth ratio of the restored stream channel was increased from 3.42 to 18.2 after construction completion and five years of monitoring.
- Restored natural stream pattern, profile and dimension throughout the 1,271 l.f. stream reach, increasing channel sinuosity from 1.1 to 1.5, and providing a more stable relationship between the valley and bankfull slopes (the bankfull slope was greater than the valley slope under pre-existing conditions; the bankfull slope is now less than the valley slope).

- Stabilized eroding streambanks by providing an appropriately sized channel with stable streambank slopes. The average Bank Height Ratio is 1.00 (stable) post-restoration and after 5 years of monitoring.
- Raised the streambed elevation reconnecting the bankfull elevation to the existing floodplain elevation (Priority Level I restoration).
- The completed restoration changed the average entrenchment ratio to 4.75.
- Created instream aquatic habitat features including deep pools, streambank stabilization, constructed riffles, rock sills, log sills, rock cross vanes and J-Hook vanes with deep scour pools and native streamside revetment to enhance outer meander bend stability, shade the pools, provide fish cover and lower water temperature.
- Revegetated the stream banks and riparian corridor with indigenous trees, shrubs, herbaceous ground cover and preserved the riparian corridors within a perpetual conservation easement.

Information on the project structure and objectives is included in Tables I and II.

| Table I. Project Structure Table | |
|---|----------------------------------|
| Bailey Fork Stream Restoration / EEP Project No. D04006-02 | |
| Project Segment/Reach ID | Linear Footage or Acreage |
| Upper | 1,543.0 lf |
| Lower | 1,170.4 lf |
| UT1 | 1,758.1 lf |
| UT2 | 1,271.0 lf |
| TOTAL | 5,742.5 lf |

| Table II. Project Mitigation Objectives Table | | | | |
|---|------------------------|-----------------|----------------------------------|---|
| Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | | |
| Project Segment/ Reach ID | Mitigation Type | Approach | Linear Footage or Acreage | Comment |
| Upper | Restoration | Priority 2 | 1,543.0 lf | Restore dimension, pattern, and profile |
| Lower | Restoration | Priority 2 | 1,170.4 lf | Restore dimension, pattern, and profile |
| UT1 | Restoration | Priority 1 | 1,758.1 lf | Restore dimension, pattern, and profile |
| UT2 | Restoration | Priority 1 | 1,271.0 lf | Restore dimension, pattern, and profile |
| TOTAL | | | 5,742.5 lf | |

C. Project History and Background

Project activity and reporting history are provided in Table III. The project contact information is provided in Table IV. The project background history is provided in Table V.

**Table III. Project Activity and Reporting History
Bailey Fork Stream Restoration / EEP Project No. D04006-02**

| Activity or Report | Scheduled Completion | Data Collection Complete | Actual Completion or Delivery |
|---|-----------------------------|---|--------------------------------------|
| Restoration plan | Jan 2005 | Oct 2004 | Mar 2005 |
| Final Design - 90% ¹ | N/A | N/A | N/A |
| Construction | Aug 2005 | N/A | Sep 2005 |
| Temporary S&E applied to entire project area ² | Feb 2005 | N/A | Feb 2005 |
| Permanent plantings | Mar 2006 | N/A | Mar 2006 |
| Mitigation plan/As-built | Dec 2005 | May 2006 | Aug 2006 |
| Year 1 monitoring | 2006 | Sep 2006 (vegetation) Apr 2007 (geomorphology) | May 2007 |
| Remedial Stream Maintenance* | Aug 2007 | N/A | Aug 2007 |
| Year 2 monitoring | 2007 | Sep 2007 (vegetation) Oct 2007 (geomorphology) | Jan 2008 |
| Year 3 monitoring | 2008 | Sep 2008 (vegetation) Oct 2008 (geomorphology) Spring 2008 (planting) | Nov 2008 |
| Year 4 monitoring | 2009 | Sep 2009 (vegetation) Sep 2009 (geomorphology) Spring 2009 (planting) | Dec 2009 |
| Year 5 monitoring | 2010 | Sep 2010 (vegetation) Sep 2010 (geomorphology) | Feb 2011 |

¹Full-delivery project; 90% submittal not provided.

²Erosion and sediment control applied incrementally throughout the course of the project.

N/A: Data collection is not an applicable task to these project activities.

*Remedial Maintenance involved efforts to repair the degraded reaches of the channel along Upper and Lower Bailey Fork, improving channel bank stability by creating a more stable bank slope, as shown on the August 2007 maintenance plan sheet.

**Table IV. Project Contact Table
Bailey Fork Stream Restoration / EEP Project No. D04006-02**

| | |
|--------------------------------|---|
| Designer | Natural Systems Engineering* 3719 Benson Drive , Raleigh, NC 27609 |
| Construction Contractor | Natural Systems Engineering* 3719 Benson Drive , Raleigh, NC 27609 |
| Monitoring Performers | EMH&T, Inc. 5500 New Albany Road, Columbus, OH 43054 |
| Stream Monitoring POC | Jud M. Hines, EMH&T |
| Vegetation Monitoring POC | Megan Wolf, EMH&T |
| *Contact: | Jim Halley at The John R. McAdams Company, Inc 2905 Meridian Parkway, Durham, NC 27713 |

* Jim Halley authored the restoration plan for this project.

| Table V. Project Background Table* | |
|---|---|
| Bailey Fork Stream Restoration / EEP Project No. D04006-02 | |
| Project County | Burke |
| Drainage Area-Upper | 4.9 sq mi |
| Drainage Area-Lower | 5.5 sq mi |
| Drainage Area-UT1 | 0.55 sq mi |
| Drainage Area-UT2 | 0.98 sq mi |
| Drainage Impervious Cover Estimate | 10% |
| Stream Order | 2nd |
| Physiographic Region | Inner Piedmont |
| Ecoregion | Northern Inner Piedmont |
| Rosgen Classification of As-built | E/C type |
| Dominant Soil Types | Colvard sandy loam |
| Reference Site ID | Sal's Branch, Whites Creek, S. Muddy Birchfield, S. Muddy Tributary 4 |
| USGS HUC for Project and Reference | 03050101 |
| NCDWQ Sub-basin for Project and Reference | 03-08-31 |
| NCDWQ Classification for Project and Reference | C |
| Any portion of any project segment 303d listed? | No |
| Any portion of any project segment upstream of a 303d listed segment? | No |
| Reason for 303d listing or stressor | N/A |
| % of project easement fenced | 20% |

*Data for Table V was derived from information from reports produced by Natural Systems Engineering.







D. Monitoring Plan View

The monitoring plan view is included as Figure 2. The information shown in Figure 2 is derived entirely from the As-Built stream plan provided with the approved Mitigation Plan report. In-stream structures shown on the plan view have been verified by the stream restoration designer/contractor based on field reconnaissance. The monitoring plan view also depicts the locations of each monumented cross-section, vegetation plot, crest gage and photo point that are part of the five year monitoring effort for this project.


BURKE COUNTY, NORTH CAROLINA
BAILEY FORK STREAM RESTORATION
 FIGURE 2A – INDEX MAP
 N.C. ECOSYSTEM ENHANCEMENT PROGRAM

Date: January, 2011
 Scale: 1" = 60'
 Job No: 2006-1626





LEGEND

-  Root Wad
-  Step-Cross Vane
-  "J" Hook
-  Rock Channel Sill
-  Log Channel Sill
-  Riffle

Base map and structure locations are shown per the as-built plan completed by Natural Systems Engineering in Nov. 2007.





LEGEND





-  Vegetation Plot
-  Photo Point
-  Cross Section
-  Crest Gauge

N/F
 DAVID STROUP & WF
 DB. 225 PG. 58



N/F
 CHARLES TALBERT
 DB. 1322 PG. 157
 PB. 4 PG. 29







LEGEND

-  Vegetation Plot
-  Photo Point
-  Cross Section
-  Crest Gauge



N/F
 JAYNES GLADYS
 PROPST
 DB. 225 PG. 59




LEGEND

-  Vegetation Plot
-  Photo Point
-  Cross Section
-  Crest Gauge

N/F
 CHARLIE DUVAL
 DB. 841 PG. 1650





N/F
 CRYSTAL & JIMMA
 SMITH
 DB. 592 PG. 164

III. PROJECT CONDITION AND MONITORING RESULTS

A. Vegetation Assessment

1. Soil Data

Soils present in the riparian area adjacent to Bailey Fork are characteristic of those found in alluvial landforms within the Northern Inner Piedmont ecoregion of North Carolina. Colvard sandy loam soils are mapped within the floodplain and immediately adjacent to the stream channels on the project site. Colvard soils are formed in loamy alluvial deposits, and are nearly level, very deep, and well-drained or moderately well-drained.

Other soils within the project's vicinity include Fairview sandy clay loam and Unison fine sandy loam, which are mapped on adjacent slopes and terraces. No hydric soils were mapped within the project corridor.

Data on the soils series found within and near the project site is summarized in Table VI.

| Table VI. Preliminary Soil Data* Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | | | |
|--|-------------------------|--------------------------|----------------------|----------------------|-------------------------|
| Series | Max. Depth (in.) | % Clay on Surface | K¹ | T² | % Organic Matter |
| Colvard sandy loam | 60+ | 8-18 | 0.24 | 5 | 1-2 |
| Fairview sandy clay loam | 60+ | 20-35 | 0.24 | 5 | 0.5-1 |
| Unison fine sandy loam | 60+ | 12-20 | 0.24 | 5 | 0.5-1 |

*Data for Table VI was derived from information from reports produced by Natural Systems Engineering.

¹Erosion Factor K indicates the susceptibility of a soil to sheet and rill erosion, ranging from 0.05 to 0.69.

²Erosion Factor T is an estimate of the maximum average annual rate of soil erosion by wind or water that can occur without affecting crop productivity, measured in tons per acre per year.

2. Vegetative Problem Areas

Vegetative Problem Areas are defined as areas either lacking vegetation or containing populations of exotic vegetation. Each problem area identified during each year of monitoring is summarized in Table VII. Since no vegetation problem areas of concern were noted in during Year 5 vegetation monitoring, vegetation problem area photos have not been included in Appendix A.

| Table VII. Vegetative Problem Areas Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | |
|---|-------------------|----------------|---------|
| Feature/Issue | Station # / Range | Probable Cause | Photo # |
| NA | NA | NA | NA |

The oldest vegetative problem on this project is the spread of the non-native species *Sericea lespedeza*. This species is a common component of pasture mixes and as this project is adjacent to pasture lands, it likely spread into the project area from the surrounding landscape. This species is present throughout the project corridor. Management for this species in 2010 included the continuation of herbicide treatments, begun in the fall of 2008. Spraying has enhanced the survival of planted woody species throughout the project reaches. Since this species has been actively managed by herbicide treatment for three years, and all plot counts are meeting performance standards, *Sericea lespedeza* has been taken off of the stream problem area table (Table VII).

A very minor population of kudzu (*Pueraria montana*) was identified near Vegetation Plot #5 in 2009. At the time of the Year 5 vegetation monitoring, the population of this species remained too small to have an impact on the desired vegetation. In 2009 and 2010, the population was treated with herbicide to control the spread of this invasive species. Because of the factors listed above, the population of kudzu is not included in the table of vegetation problem areas.

An additional, yet temporary, problem area noted in Year 4 included a section along UT2 with sparse vegetation along the stream banks. The vegetation along the left bank was damaged or destroyed by an unknown source. In Year 5, vegetation coverage and root density have significantly increased in this area and the banks are not denuded. This is therefore an area of no concern with no management necessary.

3. Vegetation Problem Area Plan View

Since no vegetation problem areas of concern were noted during Year 5 vegetation monitoring, the vegetation problem area plan view map is not included in Appendix A.

4. Stem Counts

A summary of the stem count data for each species arranged by plot is shown in Table VIII. Table VIIIa provides the survival information for planted species, while Table VIIIb provides the total stem count for the plots, including all planted and recruit stems. This data was compiled from the information collected on each plot using the *CVS-EEP Protocol for Recording Vegetation, Version 4.0*. Additional data tables generated using the CVS-EEP format are included in Appendix A. All vegetation plots are labeled as VP in Figure 2.

**Table VIIIa. Stem counts for each species arranged by plot - planted stems.
Bailey Fork Stream Restoration / EEP Project No. D04006-02**

| Species | Plots | | | | | | | | | | Year 1 Totals | Year 2 Totals | Year 3 Totals | Year 4 Totals | Year 5 Totals | Survival % |
|----------------------------------|-------|-----|-----|-----|-----|-----|-----|-----|-----|-----|------------------|------------------|------------------|------------------|------------------|---------------|
| | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | | | | | | |
| Shrubs | | | | | | | | | | | | | | | | |
| <i>Alnus serrulata</i> | | | 3 | | | | | | | | 1 | 1 | 1 | 3 | 3 | 300 |
| <i>Cephalanthus occidentalis</i> | | | | | | | | | | | 3 | 3 | 0 | 0 | 0 | 0 |
| <i>Cornus amomum</i> | 1 | 1 | | 6 | 2 | 4 | 1 | 3 | 5 | 2 | 9 | 9 | 16 | 17 | 25 | 278 |
| <i>Rosa palustris</i> | 2 | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 100 |
| <i>Salix exigua</i> | | | | | | 1 | | | | | 2 | 2 | 2 | 2 | 1 | 50 |
| Trees | | | | | | | | | | | | | | | | |
| <i>Betula nigra</i> | | | 4 | | | | | | | | 0 | 0 | 0 | 4 | 4 | NA |
| <i>Fraxinus pennsylvanica</i> | 3 | | | | 5 | 1 | | | 2 | | 0 | 0 | 1 | 5 | 11 | NA |
| <i>Liriodendron tulipifera</i> | 1 | | | 2 | | 4 | 3 | | | | 15 | 4 | 8 | 10 | 10 | 67 |
| <i>Malus</i> sp. | 1 | | | | | | | | | | 0 | 0 | 1 | 1 | 1 | NA |
| <i>Nyssa sylvatica</i> | 1 | | | | | | | | | | 0 | 0 | 1 | 1 | 1 | NA |
| <i>Platanus occidentalis</i> | 4 | 1 | 8 | 4 | | | 4 | | | 10 | 35 | 30 | 31 | 32 | 31 | 89 |
| <i>Quercus alba</i> | | | | 2 | | | | | | | 0 | 0 | 0 | 2 | 2 | NA |
| <i>Quercus michauxii</i> | | | | | | 1 | | | 2 | | 0 | 0 | 0 | 3 | 3 | NA |
| <i>Quercus pagoda</i> | 1 | 8 | | | 1 | | 3 | 8 | 4 | 1 | 31 | 28 | 23 | 26 | 26 | 84 |
| <i>Quercus phellos</i> | | 4 | 4 | 4 | | | 1 | 2 | | 2 | 9 | 5 | 8 | 19 | 17 | 189 |
| <i>Salix nigra</i> | | | 1 | | | 2 | | 1 | | | 1 | 0 | 0 | 1 | 4 | 400 |
| <i>Sambucus canadensis</i> | | 1 | | | 2 | 2 | | 1 | 2 | | 0 | 0 | 0 | 0 | 8 | NA |
| Totals | 14 | 14 | 20 | 18 | 8 | 13 | 12 | 14 | 13 | 15 | 106 | 84 | 94 | 126 | 141 | 133 |
| Live Stem Density | 567 | 567 | 810 | 729 | 324 | 527 | 486 | 567 | 527 | 608 | | | | | | |
| Average Live Stem Density | 571 | | | | | | | | | | | | | | | |

**Table VIIIa. Stem counts for each species arranged by plot - all stems.
Bailey Fork Stream Restoration / EEP Project No. D04006-02**

| Species | Plots | | | | | | | | | | Year 1 Totals | Year 2 Totals | Year 3 Totals | Year 4 Totals | Year 5 Totals | Survival % |
|----------------------------------|-------|-----|------|-----|-----|-----|------|-----|-----|-----|------------------|------------------|------------------|------------------|------------------|------------|
| | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | | | | | | |
| Shrubs | | | | | | | | | | | | | | | | |
| <i>Alnus serrulata</i> | | | 3 | | | | | | | | 1 | 1 | 1 | 3 | 3 | 300 |
| <i>Cephalanthus occidentalis</i> | | | | | | | | | | | 3 | 3 | 0 | 0 | 0 | 0 |
| <i>Cornus amomum</i> | 1 | 1 | | 6 | 4 | 4 | 3 | 6 | 5 | 2 | 9 | 9 | 16 | 17 | 32 | 356 |
| <i>Rosa palustris</i> | 2 | | | | | | | | | | 2 | 2 | 2 | 2 | 2 | 100 |
| <i>Salix exigua</i> | | | | | | 1 | | | | | 2 | 2 | 2 | 2 | 1 | 50 |
| Trees | | | | | | | | | | | | | | | | |
| <i>Acer negundo</i> | | | | | | | 7 | | | 2 | 0 | 0 | 0 | 0 | 9 | NA |
| <i>Acer rubrum</i> | | 1 | 33 | | | | 4 | | | 2 | 0 | 0 | 0 | 0 | 40 | NA |
| <i>Betula nigra</i> | | | 12 | | | | | | | | 0 | 0 | 0 | 4 | 12 | NA |
| <i>Cercis canadensis</i> | | | | | | | | 1 | | | 0 | 0 | 0 | 0 | 1 | NA |
| <i>Fraxinus pennsylvanica</i> | 3 | | | | 5 | 1 | | | 2 | | 0 | 0 | 1 | 5 | 11 | NA |
| <i>Liriodendron tulipifera</i> | 2 | | 15 | 2 | | 4 | 3 | | | | 15 | 4 | 8 | 10 | 26 | 173 |
| <i>Malussp.</i> | 1 | | | | | | | | | | 0 | 0 | 1 | 1 | 1 | NA |
| <i>Nyssa sylvatica</i> | 1 | | | | | | | | | | 0 | 0 | 1 | 1 | 1 | NA |
| <i>Platanus occidentalis</i> | 6 | 1 | 8 | 4 | | | 4 | | | 11 | 35 | 30 | 31 | 32 | 34 | 97 |
| <i>Taxodium distichum</i> | | | | | | | 2 | | | | 0 | 0 | 0 | 0 | 2 | NA |
| <i>Quercus alba</i> | | | | 2 | | | | | | | 0 | 0 | 0 | 2 | 2 | NA |
| <i>Quercus michauxii</i> | | | | | | 1 | | | 2 | | 0 | 0 | 0 | 3 | 3 | NA |
| <i>Quercus pagoda</i> | 1 | 8 | | | 1 | | 3 | 8 | 4 | 1 | 31 | 28 | 23 | 26 | 26 | 84 |
| <i>Quercus phellos</i> | | 4 | 4 | 4 | | | 1 | 3 | | 3 | 9 | 5 | 8 | 19 | 19 | 211 |
| <i>Salix nigra</i> | | | 1 | | | 2 | | 1 | | | 1 | 0 | 0 | 1 | 4 | 400 |
| <i>Sambucus canadensis</i> | | 1 | | | 2 | 2 | 1 | 1 | 2 | | 0 | 0 | 0 | 0 | 9 | NA |
| Totals | 17 | 15 | 76 | 18 | 10 | 13 | 27 | 19 | 13 | 21 | 106 | 84 | 94 | 126 | 229 | 216 |
| Live Stem Density | 689 | 608 | 3078 | 729 | 405 | 527 | 1094 | 770 | 527 | 851 | | | | | | |
| Average Live Stem Density | 927 | | | | | | | | | | | | | | | |

At 571 stems/acre, average stem density of planted species for the site in 2010 exceeds the 5 year minimum criteria of 260 stems per acre. No plot has a stem density below the minimum. In addition, a substantial number of recruit stems have been found in all plots. The recruit stems increase the total stem density across the site by 62%.

Remedial tree plantings have been conducted throughout the monitoring period. These were intended to bring deficient areas of the site back into compliance with the 320 stems per acre minimum. In the spring of 2009, the following species were planted across the project site:

| <u>Scientific name</u> | <u>Common Name</u> |
|--------------------------------|--------------------|
| <i>Aronia arbutifolia</i> | Red chokeberry |
| <i>Alnus incana</i> | Speckled alder |
| <i>Ilex verticillata</i> | Winterberry |
| <i>Cornus amomum</i> | Silky dogwood |
| <i>Platanus occidentalis</i> | Sycamore |
| <i>Liriodendron tulipifera</i> | Tulip poplar |
| <i>Quercus bicolor</i> | Swamp white oak |
| <i>Quercus velutina</i> | Black oak |

The remedial plantings have resulted in a net gain of woody stems for the entire site; as exhibited in the yearly total presented in Table VIIIa, and the achievement of the minimum performance standard.

5. Vegetation Plot Photos

Vegetation plot photos are provided in Appendix A.

B. Stream Assessment

1. Hydrologic Criteria

A network of four crest-stage stream gages was installed on the project site, one on each of the stream reaches. The locations of the crest-stage stream gages are shown on the monitoring plan view (Figure 2). One bankfull event was documented for the site, prior to the beginning of the 5-year monitoring period, as reported in the Mitigation As-Built Report. Additional events were recorded in monitoring Years 2-5, and listed in Table IX. Photographs of the crest gages are shown in Appendix B.


| Date of Data Collection | Date of Occurrence | Method | Photo # |
|--------------------------------|---------------------------|--|--------------------|
| 10/31/05 | 10/7/05-10/8/05 | Photographs; Stream Gage Data | In Mitigation Plan |
| 7/19/07 | Unknown | Crest Gage 1 on UT1 | BF 1 |
| 10/17/07 | 9/14/07-9/15/07* | Crest Gage 4 on Lower Bailey | BF 2 |
| 9/21/09 | 8/27/08* | Crest Gage 1 on UT1 Crest Gage 2 on Upper Bailey Crest Gage 3 on UT2 Crest Gage 4 on Lower Bailey | BF 3,4,5,6 |
| 9/28/10 | 1/25/10* | Crest Gage 4 on Lower Bailey | BF 7 |

*Date is approximate; based on a review of recorded rainfall and crest gage data


In September 2010, the crest gage on Lower Bailey Fork registered a bankfull event at a level of 3'6" above the bottom of the crest gage. The crest gages on the unnamed tributaries to Bailey Fork and Upper Bailey Fork could have also had bankfull flows during Lower Bailey Fork's

bankfull event. However, cork at these crest gages did not adhere to the wooden laths. During the summer reading, fire ants were observed to be carrying the cork away from the gages. Because of this, no bankfull events were recorded on these crest gages in 2010. All crest gages are set at or above the bankfull elevation of each stream channel.

The probable date for the most recently documented bankfull event was after the precipitation event that occurred on January 25, 2010. As this was the largest precipitation event of significance since the previous documentation in September 2009, this is likely the bankfull event recorded by the series of crest gages. This corresponds to a high discharge event on January 25 as recorded at USGS Gage 02140991 along the Johns River at Arneys Store in Morganton, NC, which lies approximately 15 miles north of the project site. Other large precipitation events occurred on December 25 through December 26, 2009 and March 22, 2010. The discharge and gage height recorded at the Arneys Store station are shown on the hydrographs below.



USGS Surface-Water Daily Data for North Carolina
<http://waterdata.usgs.gov/nc/nwis/dv?>



USGS Surface-Water Daily Data for North Carolina
<http://waterdata.usgs.gov/nc/nwis/dv?>

The documentation provided by the onsite crest gage network in Year 4 provided the second monitoring year with a bankfull discharge event. No additional bankfull events were required to be documented for this project for the remainder of the monitoring period. The observance of the Year 5 bankfull event was included for documentation purposes.

2. Stream Problem Areas

A summary of the areas of concern identified during the visual assessment of the stream for each year of monitoring is included in Tables Xa through Xe.

| Table Xa. Stream Problem Areas – Year 1 Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | |
|---|--|---|--------------------------|
| Feature Issue | Station Numbers | Suspected Cause | Photo Number |
| Aggradation | 4+00 - 4+25 Upper | Lateral bar; bank material moving | SPA 1 (Year 1 Report) |
| | 1+50 - 2+00 Upper | Lateral bar; bank material moving | |
| Bank failure | 9+00 Lower | Rootwad causing reverse circulation leading to downstream bank scour and undercutting | SPA 2 (Year 1 Report) |
| | 8+00 Lower | Large boulder fell out of bank; bank undercutting | |
| | 11+50 Upper | Bank armor has fallen, undercutting | |
| Bank scour | 11+80 - 12+50 Upper | Coir matting has fallen, bank erosion; deposition downstream | SPA 3 (Year 1 Report) |
| | 10+25 Upper | Rootwad causing reverse circulation leading to downstream bank scour and undercutting | |
| | 3+50 Upper | Channel is over widened, bank is slumping | |
| Stressed/failing structure | 5+60 UT2 | Embedded rock sill; channel is stable | SPA 4 (Year 1 Report) |
| | 2+50 UT2 | Embedded cross-vane; channel is stable | |
| | 1+25 UT2 | Embedded J-hook; channel is stable | |
| | 14+75 Upper | Partially embedded J-hook; channel is stable | |
| | 13+00 Upper | Embedded J-hook; channel is stable | |
| | 10+60 UT1 | Embedded rock sill ; channel is stable | |
| | 3+25 UT1 | Partially embedded J-hook; channel is stable | |
| | 0+50 UT1 | Embedded J-hook; channel is stable | |
| 0+25 UT1 | Embedded rock sill ; channel is stable | | |
| Other | 7+00 UT1 | Sinkhole adjacent to channel; piping water | SPA 5 (Year 1 Report) |

| Table Xb. Stream Problem Areas – Year 2 Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | |
|---|------------------------------------|---|---------------------------------|
| Feature Issue | Station Numbers | Suspected Cause | Photo Number |
| Aggradation | 1+50 - 2+00 Upper | Point bar; vegetated and stable | SPA 1, SPA 2 (Year 2 Report) |
| | 1+75 Lower | Mid-channel bar | |
| Bank scour | 3+50 Upper | Channel overwidened, left bank is slumping, W/D too high resulting in aggradation. | SPA 3, SPA 4 (Year 2 Report) |
| Stressed/failing structure | 5+60 UT2 | Embedded rock sill; channel is stable | SPA 5, SPA 6 (Year 2 Report) |
| | 2+50 UT2 | Embedded cross-vane; channel is stable | |
| | 1+25 UT2 | Embedded J-hook; channel is stable | |
| | 14+75 Upper | Partially embedded J-hook; channel is stable | |
| | 13+00 Upper | Embedded J-hook; channel is stable | |
| | 2+50 Upper | Embedded J-hook; channel is stable | |
| | 12+00 UT1 | Embedded rock sill; channel is stable | |
| | 10+60 UT1 | Embedded rock sill ; channel is stable | |
| | 3+25 UT1 | Partially embedded J-hook; channel is stable | |
| | 2+00 UT1 | Embedded J-hook; channel is stable | |
| 0+50 UT1 | Embedded J-hook; channel is stable | | |
| Other | 7+00 UT1 | Sinkhole adjacent to channel; has improved since the previous year due to floodplain deposition | |

| Table Xc. Stream Problem Areas – Year 3 Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | |
|---|------------------------|---|--------------------------------|
| Feature Issue | Station Numbers | Suspected Cause | Photo Number |
| Aggradation | 1+50 - 2+00 Upper | Point bar; vegetated and stable | SPA 1, 2 (Year 3 Report) |
| | 1+75 Lower | Mid-channel bar; vegetated and stable | |
| | 6+30 UT1 | Embedded rock sill; channel is stable | |
| | 8+00 UT1 | Embedded J-hook; channel is stable | |
| Bank scour | 3+50 Upper | Slumping on left bank; heavily vegetated, channel is stable | SPA 3, 4, 5 (Year 3 Report) |

| Table Xd. Stream Problem Areas – Year 4 Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | |
|---|------------------------|--|--------------------------------|
| Feature Issue | Station Numbers | Suspected Cause | Photo Number |
| Aggradation | 2+00 Lower | Bar forming along left bank; likely the remnants of the mid-channel bar formerly at station 1+75; vegetated and stable | SPA 1, 2, 3 (Year 4 report) |
| | 1+80 UT1 | Embedded rock sill; channel is stable | |
| | 2+95 UT1 | Embedded rock sill; channel is stable | |
| | 4+15 UT1 | Embedded rock sill; channel is stable | |
| | 8+00 UT1 | Embedded J-hook; channel is stable | |
| | 13+80 UT1 | Bar forming along right bank; vegetated and stable | |
| Bank scour | 5+50 Upper | Scour on right bank upstream of J-hook on left bank | SPA 4, 5 (Year 4 report) |
| | 8+80 – 9+00 Lower | Slumping on right bank underneath erosion matting | |

| Table Xd. Stream Problem Areas – Year 5 Bailey Fork Stream Restoration / EEP Project No. D04006-02 | | | |
|---|------------------------|--|---------------------|
| Feature Issue | Station Numbers | Suspected Cause | Photo Number |
| Bank scour | 8+00 Lower | Scour on left bank upstream of J-hook on left bank | SPA 1 |

In Year 5, several features have been removed from the stream problem areas tables of previous monitoring years. The majority of these areas were structures that have been embedded throughout the monitoring period or they are areas of bank scour that were repaired in the summer of 2009. It is important to note that the stream channels remain stable in these areas in 2010. Once the channel has remained stable throughout two consecutive years of monitoring, the structures are no longer considered problem areas and are removed from the table.

The only feature that had remained on the Year 4 table from previous monitoring years was the J-hook at station 8+00 on UT1. When Year 5 observations are considered, the channel has remained stable in this area for three consecutive years. Therefore, it has been removed from **Table Xd.** in 2010.

The other category of potential problem areas that remained in Year 4 was limited to two isolated areas of minimal bank scour (one scour area on Lower Bailey Fork and the other on Upper Bailey Fork). These scour areas were removed from Table Xd. in Year 5 because they have since been repaired, are densely vegetated and remain stable. Only one new scour area was observed on Lower Bailey Fork in 2010. The scour hole is located at station 8+00 on Lower Bailey Fork. The scour hole although tall, remains localized to a small area along the left bank of Lower Bailey Fork. The left bank near this station is heavily vegetated and appears stable and is located immediately upstream of a grade control feature. It is therefore predicted that this minimal scour area will not become more than a localized issue and will re-stabilize, over time. Accordingly, maintenance work is not warranted and the scour area is mapped in Appendix B as a stream problem area of low concern.

3. Stream Problem Areas Plan View

The location of each structural problem area is shown on the stream problem area plan view included in Appendix B. Each problem area is color coded with yellow for areas of low concern (areas to be watched) or red for high concern (areas where maintenance is warranted).

4. Stream Problem Areas Photos

Photographs of the stream problem areas noted in Table Xd are included in Appendix B.

5. Fixed Station Photos

Photographs were taken at each established photograph station on September 18, 2010. These photographs are provided in Appendix B.

6. Stability Assessment Table

The visual stream assessment was performed to determine the percentage of stream features remaining in a state of stability after the first year of monitoring. A summary of the visual assessment for each reach is included in Table XIa through Table XIId. This summary was compiled from the more comprehensive Table B1, included in Appendix B. Each of the structures shown on the as-built plans were assessed during monitoring and reported in the tables.

| Table XIa. Categorical Stream Feature Visual Stability Assessment Bailey Fork Stream Restoration / EEP Project No. D04006-02 Segment/Reach: Upper | | | | | | |
|--|----------------|--------------|--------------|--------------|--------------|--------------|
| Feature | Initial | MY-01 | MY-02 | MY-03 | MY-04 | MY-05 |
| A. Riffles¹ | 100% | 87% | 87% | 87% | 87% | 87% |
| B. Pools² | 100% | 88% | 88% | 84% | 100% | 100% |
| C. Thalweg | 100% | 100% | 100% | 100% | 100% | 100% |
| D. Meanders | 100% | 91% | 98% | 98% | 100% | 100% |
| E. Bed General | 100% | 98% | 98% | 98% | 100% | 98% |
| F. Vanes / J Hooks etc.³ | 100% | 97% | 96% | 96% | 96% | 97% |
| G. Wads and Boulders⁴ | N/A | N/A | N/A | N/A | N/A | N/A |

| Table XIb. Categorical Stream Feature Visual Stability Assessment Bailey Fork Stream Restoration / EEP Project No. D04006-02 Segment/Reach: Lower | | | | | | |
|--|----------------|--------------|--------------|--------------|--------------|--------------|
| Feature | Initial | MY-01 | MY-02 | MY-03 | MY-04 | MY-05 |
| A. Riffles¹ | 100% | 100% | 100% | 100% | 98% | 98% |
| B. Pools² | 100% | 100% | 100% | 100% | 100% | 100% |
| C. Thalweg | 100% | 100% | 100% | 100% | 100% | 100% |
| D. Meanders | 100% | 91% | 100% | 100% | 96% | 100% |
| E. Bed General | 100% | 100% | 99% | 99% | 98% | 97% |
| F. Vanes / J Hooks etc.³ | 100% | 100% | 100% | 100% | 100% | 100% |
| G. Wads and Boulders⁴ | N/A | N/A | N/A | N/A | N/A | N/A |

| Table XIc. Categorical Stream Feature Visual Stability Assessment Bailey Fork Stream Restoration / EEP Project No. D04006-02 Segment/Reach: UT1 | | | | | | |
|--|----------------|--------------|--------------|--------------|--------------|--------------|
| Feature | Initial | MY-01 | MY-02 | MY-03 | MY-04 | MY-05 |
| A. Riffles¹ | 100% | 93% | 92% | 92% | 90% | 90% |
| B. Pools² | 100% | 89% | 87% | 86% | 86% | 86% |
| C. Thalweg | 100% | 100% | 100% | 100% | 100% | 100% |
| D. Meanders | 100% | 100% | 100% | 100% | 100% | 100% |
| E. Bed General | 100% | 100% | 100% | 98% | 99% | 98% |
| F. Vanes / J Hooks etc.³ | 100% | 97% | 97% | 95% | 94% | 94% |
| G. Wads and Boulders³ | 100% | 100% | 100% | 100% | 100% | 100% |

**Table XId. Categorical Stream Feature Visual Stability Assessment
Bailey Fork Stream Restoration / EEP Project No. D04006-02
Segment/Reach: UT2**

| Feature | Initial | MY-01 | MY-02 | MY-03 | MY-04 | MY-05 |
|--|----------------|--------------|--------------|--------------|--------------|--------------|
| A. Riffles¹ | 100% | 100% | 89% | 100% | 100% | 100% |
| B. Pools² | 100% | 96% | 86% | 93% | 90% | 90% |
| C. Thalweg | 100% | 100% | 100% | 100% | 100% | 100% |
| D. Meanders | 100% | 100% | 100% | 100% | 98% | 100% |
| E. Bed General | 100% | 100% | 100% | 100% | 100% | 100% |
| F. Vanes / J Hooks etc.³ | 100% | 95% | 95% | 95% | 95% | 95% |
| G. Wads and Boulders⁴ | N/A | N/A | N/A | N/A | N/A | N/A |

¹Riffles are assessed using the longitudinal profile. A riffle is determined to be stable based on a comparison of location and elevation with respect to the as-built profile.

²Pools are assessed using the longitudinal profile. A pool is determined to be stable based on a comparison of location and elevation with respect to the as-built profile and a consideration of appropriate depth.

³Physical structures such as vanes, J-hooks, and root wads are assessed using the as-built plan sheets to define the location of such features. A structure is considered stable if the feature remains functional in the same location as shown in the as-built plan.

⁴Those features not included in the stream restoration were labeled N/A. This includes structures such as rootwads and boulders.

The visual stream stability assessment revealed that the majority of in-stream structures are functioning as designed and built on the project reaches. The structures identified as problematic on Upper Bailey Fork and Tributaries UT1 and UT2 were vanes/J-hooks, each of which has become embedded in sand size sediment. However, the channel is stable at each location where aggradation has covered a structure. The percentage of embedded features has remained relatively similar throughout the monitoring years. Meanders along the stream were found to have better stability in Year 5. A few point bars have also formed within Upper and Lower Bailey Fork, resulting in the percentages for the Bed General category in the preceding tables.

As a result of the streambank maintenance that occurred along upper and lower Bailey Fork in Year 2 during August 2007 and in Year 4 during the summer of 2009, each meander that was in an unstable state during Year 1 and Year 4 monitoring was repaired and has remained stable in Year 5.

All of the stream reaches were noted to have either pools or riffles that were not performing as intended based on the as-built conditions. On both the Upper and Lower reaches of Upper Bailey Fork, pool depths appear to have increased over the Year 4 conditions; all of these are now considered stable and of adequate depth. Although the stability percentage for riffle features on Upper Bailey Fork is comparatively low, the stream channel is both stable and functional, with no apparent detrimental effect.

A limited number of pools and riffles along reaches UT1 and UT2 have been impacted by aggradation along these reaches. As on Upper Bailey Fork, some of the riffles along UT1 have become slightly embedded. Several pools along this reach have also become filled with fine sediments, resulting in shallower pools. As mentioned previously, sand is a dominant substrate in the watershed. As such, a high sediment supply is readily available for the project reaches, and

the depositional trends seen in the project reaches is anticipated as a natural component of the system, rather than a concern with the physical structure of the project. It should be noted, however, that generalized channel aggradation along UT1 and UT2 has decreased, overall, since Year 4. Comparison of the monumented cross sections and the longitudinal profiles of UT1 and UT2 demonstrate this observation. Furthermore, the consistency demonstrated in Tables XIb. and XIc. implies that the stream channels have achieved a state of equilibrium in Year 5.

7. Quantitative Measures

Graphic interpretations of cross-sections, profiles and pebble counts are provided in Appendix B. A summary of the baseline morphology for the site is included in Table XII for comparison with the monitoring data shown in the tables in the appendices. Geomorphic data in Table XII, except for Year 1 through Year 5 monitoring data, was provided by Natural Systems Engineering. Year 0 data presented in cross-sections and profiles, contained in Appendix B, were also provided by Natural Systems Engineering.

Data provided for Table XIII. *Morphology and Hydraulic Monitoring Summary*, reflects all years of stream monitoring. The table depicts basic morphological and dimensional measurements for each monumented cross section of the project. Table XIII makes it easy to compare these dimensional values from year to year, thus illuminating trends in channel evolution.

The stream pattern data provided for Year 1 through Year 5 is the same as the data provided from the As-Built survey, as pattern has not changed based on the yearly stream surveys and visual field assessments.

Bedform features continue to evolve along the restored reaches as shown on the long-term longitudinal profiles. Dimensional measurements of the monumented cross-sections remain stable when compared to as-built conditions. The comparison of the As-Built through Year 4, and the Year 5 long-term stream monitoring profile data show stability with minor changes from as-built conditions. Riffle lengths and slopes are generally stable, although a few have decreased slightly due to aggradation. Pool lengths are also generally stable, except for a slight decrease on UT1, which is also suspected to be due to aggradation. Pool to pool spacings are representative of reference reach conditions and were generally stable except for minor increases due to slight shifts in the locations of the maximum pools depths or the loss of a pool due to aggradation.

The constructed riffles remain stable, with a median particle size ranging from fine gravel to very coarse gravel. The pools substrate remained stable, with median particle sizes within the medium sand category, based on Year 5 substrate analysis.

Table XII. Baseline Geomorphic and Hydraulic Summary

Bailey Fork Stream Restoration / EEP Project No. D04006-02

Station/Reach: Upper {Long-Term Monitoring Profile Station 0+00 to 8+00 (800 feet)}

| Parameter | Regional Curve Data | | | Reference Reach | | | Pre-Existing Condition | | | Design | | | As-Built XSs 5 & 8 | | | Year 1 Sta. 0+00 - 8+00 | | | Year 2 Sta. 0+00 - 8+00 | | | Year 3 Sta. 0+00 - 8+00 | | | Year 4 Sta. 0+00 - 8+00 | | | Year 5 Sta. 0+00 - 8+00 | | | | | |
|--|---------------------|-----|-------|-----------------|--------|--------|------------------------|--------|--------|--------|--------|--------|--------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------|--------|--------|
| | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | | | |
| Drainage Area (mi ²) | | | 4.90 | 0.14 | 1.70 | 0.92 | | | 4.90 | | | 4.90 | | | 4.90 | | | 4.90 | | | 4.90 | | | 4.90 | | | 4.90 | | | 4.90 | | | |
| BF Width (ft) | | | 25.10 | 7.35 | 10.80 | 9.08 | 19.90 | 26.47 | 23.19 | | | 28.00 | 28.20 | 37.70 | 32.95 | 29.07 | 30.94 | 30.01 | 28.89 | 36.63 | 32.76 | 28.77 | 36.74 | 32.76 | 28.96 | 38.50 | 33.73 | 27.84 | 34.67 | 31.26 | | | |
| Floodprone Width (ft) | | | | 43.00 | 150.00 | 96.50 | 180.00 | 180.00 | 180.00 | | | 280.00 | 100.00 | 109.00 | 104.50 | 99.20 | 109.50 | 104.35 | 99.84 | 109.52 | 104.68 | 99.72 | 109.00 | 104.36 | 100.50 | 110.50 | 105.50 | 99.71 | 109.38 | 104.55 | | | |
| BF Cross Sectional Area (ft ²) | | | 63.62 | 9.10 | 20.70 | 14.90 | 67.37 | 71.69 | 69.53 | | | 65.00 | 71.70 | 81.80 | 76.75 | 77.68 | 102.22 | 89.95 | 77.14 | 89.37 | 83.26 | 76.82 | 90.98 | 83.90 | 75.00 | 97.40 | 86.20 | 79.47 | 88.19 | 83.83 | | | |
| BF Mean Depth (ft) | | | 2.53 | 1.30 | 2.10 | 1.70 | 2.71 | 3.38 | 3.05 | | | 2.30 | 2.30 | 2.30 | 2.30 | 2.67 | 3.30 | 2.99 | 2.44 | 2.67 | 2.56 | 2.48 | 2.67 | 2.58 | 2.53 | 2.59 | 2.56 | 2.54 | 2.85 | 2.70 | | | |
| BF Max Depth (ft) | | | | 1.80 | 2.80 | 2.30 | 4.55 | 4.96 | 4.76 | | | 4.20 | 4.10 | 5.20 | 4.65 | 4.14 | 5.39 | 4.77 | 4.25 | 4.63 | 4.44 | 4.22 | 4.68 | 4.45 | 4.26 | 4.79 | 4.53 | 4.69 | 5.12 | 4.91 | | | |
| Width/Depth (ft) | | | 9.92 | 5.65 | 5.14 | 5.40 | 7.34 | 7.83 | 7.59 | | | 12.20 | 12.26 | 16.39 | 14.33 | 9.38 | 10.89 | 10.14 | 10.82 | 15.01 | 12.92 | 10.78 | 14.81 | 12.80 | 11.18 | 15.22 | 13.20 | 9.77 | 13.65 | 11.71 | | | |
| Entrenchment Ratio | | | | 5.85 | 13.89 | 9.87 | 9.05 | 9.04 | 9.04 | | | 10.00 | 3.55 | 2.89 | 3.22 | 3.41 | 3.54 | 3.48 | 2.99 | 3.46 | 3.23 | 2.97 | 3.47 | 3.22 | 2.87 | 3.47 | 3.17 | 3.16 | 3.58 | 3.37 | | | |
| Bank Height Ratio | | | | 0.70 | 1.00 | 0.85 | 1.80 | 2.10 | 1.95 | | | 1.00 | 1.00 | 1.10 | 1.05 | 1.00 | 1.10 | 1.05 | 1.10 | 1.15 | 1.13 | 1.05 | 1.12 | 1.09 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | | | |
| Wetted Perimeter (ft) | | | 30.16 | 9.95 | 15.00 | 12.48 | 25.32 | 33.23 | 29.28 | | | 32.60 | 32.80 | 42.30 | 37.55 | 30.60 | 34.41 | 32.51 | 30.42 | 37.94 | 34.18 | 30.29 | 38.07 | 34.18 | 30.60 | 39.85 | 35.23 | 30.07 | 36.53 | 33.30 | | | |
| Hydraulic Radius (ft) | | | 2.11 | 0.91 | 1.38 | 1.15 | 2.66 | 2.16 | 2.41 | | | 1.99 | 1.93 | 2.19 | 2.06 | 2.54 | 2.97 | 2.76 | 2.36 | 2.54 | 2.45 | 2.39 | 2.54 | 2.47 | 2.44 | 2.45 | 2.45 | 2.41 | 2.64 | 2.53 | | | |
| Pattern | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| *Channel Beltwidth (ft) | | | | 20.00 | 50.00 | 35.00 | 75.00 | 105.00 | 90.00 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 | 70.00 | 153.00 | 111.50 |
| *Radius of Curvature (ft) | | | | 10.00 | 21.00 | 15.50 | 18.00 | 30.00 | 24.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 | 42.00 | 84.00 | 63.00 |
| *Meander Wavelength (ft) | | | | 35.00 | 50.00 | 42.50 | 60.00 | 96.00 | 78.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 | 70.00 | 154.00 | 112.00 |
| *Meander Width Ratio | | | | 2.00 | 21.80 | 11.90 | 3.20 | 3.60 | 3.40 | 2.50 | 5.50 | 4.00 | 2.50 | 5.50 | 4.00 | 2.41 | 4.95 | 3.72 | 2.42 | 4.18 | 3.40 | 2.43 | 4.16 | 3.40 | 2.42 | 3.97 | 3.31 | 2.51 | 4.41 | 3.57 | | | |
| Profile | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Riffle Length (ft) | | | | 3.00 | 26.40 | 14.70 | 15.00 | 67.80 | 41.40 | 23.80 | 68.00 | 45.90 | 23.80 | 68.00 | 45.90 | 5.60 | 24.00 | 12.70 | 13.40 | 23.75 | 17.77 | 10.67 | 43.75 | 20.36 | 9.34 | 38.38 | 19.71 | 12.34 | 31.32 | 21.95 | | | |
| Riffle Slope (ft/ft) | | | | 0.0068 | 0.0700 | 0.0384 | 0.0086 | 0.0860 | 0.0473 | 0.0020 | 0.0035 | 0.0028 | 0.0020 | 0.0035 | 0.0028 | 0.0120 | 0.0456 | 0.0238 | 0.0045 | 0.0260 | 0.0173 | 0.0066 | 0.0247 | 0.0134 | 0.0023 | 0.0242 | 0.0078 | 0.0088 | 0.0402 | 0.0256 | | | |
| Pool Length (ft) | | | | 5.50 | 41.30 | 23.40 | 80.00 | 100.00 | 90.00 | 45.00 | 96.00 | 70.50 | 45.00 | 96.00 | 70.50 | 27.90 | 72.20 | 51.20 | 28.23 | 80.25 | 53.58 | 24.12 | 71.34 | 44.25 | 26.97 | 67.43 | 42.82 | 24.68 | 75.93 | 47.88 | | | |
| Pool Spacing (ft) | | | | 16.00 | 70.00 | 43.00 | 81.00 | 211.00 | 146.00 | 95.00 | 224.00 | 159.50 | 95.00 | 224.00 | 159.50 | 56.00 | 167.00 | 98.20 | 49.12 | 109.70 | 75.59 | 34.26 | 101.86 | 68.19 | 30.08 | 89.22 | 58.94 | 31.32 | 102.51 | 66.28 | | | |
| Additional Reach Parameters | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| **d50 (mm) | | | | 20.0 | 29.0 | 24.5 | 6.0 | 24.0 | 15.0 | | | | 6.9 | 19.6 | 13.3 | | | 113.4 | | | 87.4 | | | 32.0 | | | 64.0 | | | 11.9 | | | |
| **d84 (mm) | | | | 38.0 | 76.0 | 57.0 | 7.0 | 50.0 | 28.5 | | | 55.0 | 121.0 | 154.0 | 137.5 | | | 178.3 | | | 115.0 | | | 139.3 | | | 119.8 | | | 95.1 | | | |
| Additional Reach Parameters | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Valley Length (ft) | | | | 209 | 295 | 252.00 | | | 1108 | | | 1108 | | | 1108 | | | 1108 | | | 1108 | | | 1108 | | | 1108 | | | 1108 | | | |
| Channel Length (ft) | | | | 406 | 479 | 442.50 | | | 1383.0 | | | 1410.4 | | | 1543.0 | | | 1543.0 | | | 1543.0 | | | 1543.0 | | | 1543.0 | | | 1543.0 | | | |
| Sinuosity | | | | 1.9 | 1.6 | 1.8 | | | 1.1 | | | 1.3 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 | | | |
| Water Surface Slope (ft/ft) | | | | 0.0044 | 0.0219 | 0.0132 | | | 0.0024 | | | 0.0025 | | | 0.0027 | | | 0.0019 | | | 0.0019 | | | 0.0020 | | | 0.0029 | | | 0.0029 | | | |
| BF Slope (ft/ft) | | | | 0.0044 | 0.0219 | 0.0132 | | | 0.0035 | | | 0.0033 | | | 0.0020 | | | 0.0017 | | | 0.0024 | | | 0.0020 | | | 0.0014 | | | 0.0031 | | | |
| Rosgen Classification | | | E | E4 | E4 | E4 | | | E-F-G | | | E4/C4 | | | C4 | | | E4 | | | C4 | | | C4 | | | C4 | | | C4 | | | |
| *Habitat Index | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| *Macrobenthos | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

* Inclusion will be project specific and determined primarily by As-built monitoring plan/success criteria

Note: Blank fields = Historic project documentation necessary to provide these data were unavailable at the time of this report submission.

**Year 3 D50 and D84 are composite values from XS-5 & XS-7. This distribution best represents reach substrate composition. Riffle XS-5 D50 and D84 substrate composition (i.e., 110 mm & 164 mm) uncharacteristically classifies UBF as a large cobble, C3 stream type.

Note: Where only one measurement was taken, that value is posted in the "Med" column.

Table XII. Baseline Geomorphic and Hydraulic Summary
Bailey Fork Stream Restoration / EEP Project No. D04006-02
Station/Reach: UT1 {Long-Term Monitoring Profile Station 0+00 to 8+00 (800 feet)}

| Parameter | Regional Curve Data | | | Reference Reach | | | Pre-Existing Condition | | | Design | | | As-Built XSs 1 & 3 | | | Year 1 Sta. 0+00 - 8+00 | | | Year 2 Sta. 0+00 - 8+00 | | | Year 3 Sta. 0+00 - 8+00 | | | Year 4 Sta. 0+00 - 8+00 | | | Year 5 Sta. 0+00 - 8+00 | | |
|--|---------------------|-----|-------|-----------------|--------|--------|------------------------|--------|--------|--------|--------|--------|--------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|-------------------------|--------|--------|
| | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med | Min | Max | Med |
| Drainage Area (mi ²) | | | 0.54 | 0.14 | 1.70 | 0.92 | | | 0.54 | | | 0.54 | | | 0.54 | | | 0.54 | | | 0.54 | | | 0.54 | | | 0.54 | | | 0.54 |
| BF Width (ft) | | | 10.93 | 7.35 | 10.80 | 9.08 | 19.90 | 26.47 | 23.19 | | | 14.00 | 16.60 | 27.40 | 22.00 | 14.43 | 17.76 | 16.10 | 14.69 | 16.26 | 15.48 | 15.32 | 15.75 | 15.54 | 14.97 | 16.45 | 15.71 | 15.40 | 17.35 | 16.38 |
| Floodprone Width (ft) | | | | 43.00 | 150.00 | 96.50 | 180.00 | 180.00 | 180.00 | 65.00 | 120.00 | 92.50 | 64.40 | 74.00 | 69.20 | 63.78 | 72.92 | 68.35 | 58.45 | 74.45 | 66.45 | 64.00 | 74.45 | 69.23 | 64.14 | 74.50 | 69.32 | 63.87 | 74.54 | 69.21 |
| BF Cross Sectional Area (ft ²) | | | 14.30 | 9.10 | 20.70 | 14.90 | 67.37 | 71.69 | 69.53 | | | 17.50 | 15.40 | 27.40 | 21.40 | 12.60 | 15.45 | 14.03 | 13.03 | 16.08 | 14.56 | 12.99 | 15.15 | 14.07 | 10.88 | 16.42 | 13.65 | 14.97 | 16.72 | 15.85 |
| BF Mean Depth (ft) | | | 1.30 | 1.30 | 2.10 | 1.70 | 2.71 | 3.38 | 3.05 | | | 1.30 | 0.56 | 1.73 | 1.15 | 0.87 | 0.87 | 0.87 | 0.89 | 0.99 | 0.94 | 0.85 | 0.96 | 0.91 | 0.73 | 1.00 | 0.87 | 0.96 | 0.97 | |
| BF Max Depth (ft) | | | | 1.80 | 2.80 | 2.30 | 4.55 | 4.96 | 4.76 | | | 1.80 | 1.80 | 3.00 | 2.40 | 1.66 | 1.98 | 1.82 | 1.66 | 2.03 | 1.85 | 1.70 | 1.98 | 1.84 | 1.64 | 2.08 | 1.86 | 1.91 | 2.26 | 2.09 |
| Width/Depth (ft) | | | 8.41 | 5.65 | 5.14 | 5.40 | 5.88 | 9.77 | 7.83 | | | 10.77 | 15.84 | 29.64 | 22.74 | 16.59 | 20.41 | 18.50 | 16.42 | 16.51 | 16.47 | 16.41 | 18.02 | 17.08 | 16.45 | 20.51 | 18.48 | 15.88 | 18.07 | 16.98 |
| Entrenchment Ratio | | | | 5.85 | 13.89 | 9.87 | 6.80 | 9.04 | 7.92 | | | 6.61 | 2.70 | 3.88 | 3.29 | 3.59 | 5.05 | 4.32 | 3.59 | 5.07 | 4.33 | 4.06 | 4.86 | 4.46 | 4.06 | 4.98 | 4.52 | 3.68 | 4.84 | 4.26 |
| Bank Height Ratio | | | | 0.70 | 1.00 | 0.85 | 2.05 | 2.15 | 2.10 | | | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | 1.05 | 1.03 | 1.00 | 1.02 | 1.01 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 | 1.00 |
| Wetted Perimeter (ft) | | | 13.53 | 9.95 | 15.00 | 12.48 | 25.32 | 33.23 | 29.28 | | | 16.60 | 17.72 | 30.86 | 24.29 | 15.20 | 19.06 | 17.13 | 15.45 | 17.34 | 16.40 | 15.97 | 16.67 | 16.32 | 15.70 | 17.01 | 16.36 | 16.60 | 18.37 | 17.49 |
| Hydraulic Radius (ft) | | | 1.06 | 0.91 | 1.38 | 1.15 | 2.66 | 2.16 | 2.41 | | | 1.05 | 0.87 | 0.89 | 0.88 | 0.81 | 0.83 | 0.82 | 0.84 | 0.93 | 0.89 | 0.81 | 0.91 | 0.86 | 0.69 | 0.97 | 0.83 | 0.90 | 0.91 | 0.91 |
| Pattern | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| *Channel Beltwidth (ft) | | | | 20.00 | 50.00 | 35.00 | 30.00 | 40.00 | 35.00 | 30.00 | 80.00 | 55.00 | 30.00 | 80.00 | 55.00 | 30.00 | 80.00 | 55.00 | 30.00 | 80.00 | 55.00 | 30.00 | 80.00 | 55.00 | 30.00 | 80.00 | 55.00 | 30.00 | 80.00 | 55.00 |
| *Radius of Curvature (ft) | | | | 10.00 | 21.00 | 15.50 | 9.00 | 18.00 | 13.50 | 15.00 | 35.00 | 25.00 | 15.00 | 35.00 | 25.00 | 15.00 | 35.00 | 25.00 | 15.00 | 35.00 | 25.00 | 15.00 | 35.00 | 25.00 | 15.00 | 35.00 | 25.00 | 15.00 | 35.00 | 25.00 |
| *Meander Wavelength (ft) | | | | 35.00 | 50.00 | 42.50 | 48.00 | 60.00 | 54.00 | 55.00 | 100.00 | 77.50 | 55.00 | 100.00 | 77.50 | 55.00 | 100.00 | 77.50 | 55.00 | 100.00 | 77.50 | 55.00 | 100.00 | 77.50 | 55.00 | 100.00 | 77.50 | 55.00 | 100.00 | 77.50 |
| *Meander Width Ratio | | | | 2.00 | 21.80 | 11.90 | 2.80 | 3.70 | 3.25 | 2.10 | 5.70 | 3.90 | 2.10 | 5.70 | 3.90 | 2.08 | 4.50 | 3.42 | 2.04 | 4.92 | 3.55 | 1.96 | 5.08 | 3.54 | 2.00 | 4.86 | 3.50 | 1.95 | 4.61 | 3.36 |
| Profile | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Riffle Length (ft) | | | | 3.00 | 26.40 | 14.70 | 34.80 | 69.50 | 52.15 | 14.00 | 40.00 | 27.00 | 4.00 | 37.00 | 14.22 | 4.70 | 28.60 | 15.70 | 5.02 | 26.34 | 14.17 | 9.28 | 25.32 | 18.00 | 6.61 | 19.84 | 9.89 | 4.80 | 33.10 | 14.20 |
| Riffle Slope (ft/ft) | | | | 0.0068 | 0.0700 | 0.0384 | 0.0070 | 0.0235 | 0.0153 | 0.0025 | 0.0070 | 0.0048 | 0.0010 | 0.1830 | 0.0020 | 0.0046 | 0.0645 | 0.0254 | 0.0097 | 0.0559 | 0.0259 | 0.0151 | 0.0646 | 0.0376 | 0.0030 | 0.0790 | 0.0199 | 0.0035 | 0.0402 | 0.0210 |
| Pool Length (ft) | | | | 5.50 | 41.30 | 23.40 | 27.20 | 60.00 | 43.60 | 20.00 | 45.00 | 32.50 | 3.00 | 37.00 | 20.00 | 8.40 | 56.90 | 30.80 | 7.44 | 54.86 | 27.36 | 10.67 | 44.74 | 23.21 | 8.03 | 30.13 | 15.94 | 7.40 | 60.70 | 24.70 |
| Pool Spacing (ft) | | | | 16.00 | 70.00 | 43.00 | 110.00 | 110.00 | 110.00 | 50.00 | 85.00 | 67.50 | 22.00 | 88.00 | 50.00 | 39.77 | 120.50 | 64.00 | 27.83 | 81.86 | 55.23 | 17.11 | 106.45 | 55.93 | 12.49 | 100.87 | 34.63 | 15.70 | 124.30 | 47.30 |
| Substrate | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| **d50 (mm) | | | | 20.0 | 29.0 | 24.5 | 6.0 | 24.0 | 15.0 | | | | 16.7 | 22.4 | 19.6 | | | | | | | | | | | | | | | |
| **d84 (mm) | | | | 38.0 | 76.0 | 57.0 | 7.0 | 50.0 | 28.5 | | | 65.0 | 31.0 | 50.0 | 40.5 | | | | | | | | | | | | | | | |
| Additional Reach Parameters | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Valley Length (ft) | | | | 209 | 295 | 252.00 | | | 1225 | | | 1225 | | | 1225 | | | 1225 | | | 1225 | | | 1225 | | | 1225 | | | 1225 |
| Channel Length (ft) | | | | 406 | 479 | 442.50 | | | 1648.1 | | | 1707.3 | | | 1758.1 | | | 1758.1 | | | 1758.1 | | | 1758.1 | | | 1758.1 | | | 1758.1 |
| Sinuosity | | | | 1.9 | 1.6 | 1.8 | | | 1.3 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 | | | 1.4 |
| Water Surface Slope (ft/ft) | | | | 0.0044 | 0.0219 | 0.0132 | | | 0.0024 | | | 0.0025 | | | 0.0071 | | | 0.0047 | | | 0.0050 | | | 0.0069 | | | 0.0075 | | | 0.0074 |
| BF Slope (ft/ft) | | | | 0.0044 | 0.0219 | 0.0132 | | | 0.0035 | | | 0.0033 | | | 0.0064 | | | 0.0046 | | | 0.0049 | | | 0.0069 | | | 0.0070 | | | 0.0075 |
| Rosgen Classification | | | E | E4 | E4 | E4 | | | G4/F4 | | | E4/C4 | | | C4 | | | C4 | | | C4 | | | C4 | | | C4 | | | C4 |
| *Habitat Index | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| *Macrobenthos | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

* Inclusion will be project specific and determined primarily by As-built monitoring plan/success criteria

Note: Blank fields = Historic project documentation necessary to provide these data were unavailable at the time of this report submission.

**Years 1 through 4 data were derived using three riffle cross-sections out of the six total cross-sections where pebble count data are collected per the site mitigation plan.. No data is reported, as only substrate samples at pool cross-sections were collected.

Note: Where only one measurement was taken, that value is posted in the "Med" column.

| Table XIII: Morphology and Hydraulic Monitoring Summary | | | | | | | | | | | | | | | | | | | | | | | | |
|--|--------------------------|-------|-------|-------|-------|-------|------------------------|-------|-------|-------|-------|-------|--------------------------|-------|-------|-------|-------|-------|------------------------|-------|-------|-------|-------|-------|
| Bailey Fork and Unnamed Tributaries Stream Restoration / EEP Project No. D04006-02 | | | | | | | | | | | | | | | | | | | | | | | | |
| Reach: Bailey Fork UT-1 | | | | | | | | | | | | | | | | | | | | | | | | |
| Parameter | Cross Section (Riffle 1) | | | | | | Cross Section (Pool 2) | | | | | | Cross Section (Riffle 3) | | | | | | Cross Section (Pool 4) | | | | | |
| Dimension | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 |
| BF Width (ft) | 35.37 | 14.43 | 14.69 | 15.32 | 14.97 | 15.4 | 19.7 | 14.81 | 24.25 | 25.01 | 23.92 | 20.98 | 25.38 | 17.76 | 16.26 | 15.75 | 16.45 | 17.35 | 15.5 | 11.54 | 13.07 | 24.73 | 21.51 | 23.42 |
| Floodprone Width (ft) | 74 | 72.92 | 74.45 | 74.45 | 74.5 | 74.54 | 68 | 67.71 | 53.33 | 68 | 56.83 | 54.05 | 64.4 | 63.78 | 58.45 | 64 | 64.14 | 63.87 | 78 | 78.42 | 78 | 78 | 77.92 | 78.46 |
| BF Cross Sectional Area (ft ²) | 19.98 | 12.6 | 13.03 | 12.99 | 10.88 | 14.97 | 18.18 | 10.35 | 18.62 | 19.23 | 16.92 | 16.45 | 29.11 | 15.45 | 16.08 | 15.15 | 16.42 | 16.72 | 20.18 | 9.13 | 9.17 | 13.96 | 11.01 | 11.64 |
| BF Mean Depth (ft) | 0.56 | 0.87 | 0.89 | 0.85 | 0.73 | 0.97 | 0.92 | 0.7 | 0.77 | 0.77 | 0.71 | 0.78 | 1.15 | 0.87 | 0.99 | 0.96 | 1 | 0.96 | 1.3 | 0.79 | 0.7 | 0.56 | 0.51 | 0.50 |
| BF Max Depth (ft) | 1.91 | 1.66 | 1.66 | 1.7 | 1.64 | 1.91 | 2.31 | 1.95 | 1.92 | 2.47 | 1.55 | 2.12 | 3.67 | 1.98 | 2.03 | 1.98 | 2.08 | 2.26 | 2.65 | 1.73 | 1.64 | 1.97 | 1.53 | 2.12 |
| Width/Depth Ratio | 63.16 | 16.59 | 16.51 | 18.02 | 20.51 | 15.88 | 21.41 | 21.16 | 31.49 | 32.48 | 33.69 | 26.9 | 22.07 | 20.41 | 16.42 | 16.41 | 16.45 | 18.07 | 11.92 | 14.61 | 18.67 | 44.16 | 42.18 | 46.84 |
| Entrenchment Ratio | 2.09 | 5.05 | 5.07 | 4.86 | 4.98 | 4.84 | 3.45 | 4.57 | 2.2 | 2.72 | 2.38 | 2.58 | 2.54 | 3.59 | 3.59 | 4.06 | 3.9 | 3.68 | 5.03 | 6.8 | 5.97 | 3.15 | 3.62 | 3.35 |
| Bank Height Ratio | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| Wetted Perimeter (ft) | 35.99 | 15.2 | 15.45 | 15.97 | 15.7 | 16.6 | 20.56 | 15.58 | 24.75 | 25.96 | 24.25 | 21.88 | 28.85 | 19.06 | 17.34 | 16.66 | 17.01 | 18.37 | 17.12 | 12.26 | 13.68 | 25.41 | 21.9 | 21.90 |
| Hydraulic Radius (ft) | 0.55 | 0.83 | 0.84 | 0.81 | 0.69 | 0.9 | 0.88 | 0.66 | 0.75 | 0.74 | 0.7 | 0.75 | 1.01 | 0.81 | 0.93 | 0.91 | 0.97 | 0.91 | 1.18 | 0.74 | 0.67 | 0.55 | 0.5 | 0.50 |
| Substrate | | | | | | | | | | | | | | | | | | | | | | | | |
| D50 (mm) | * | * | * | * | * | * | 0.63 | 0.22 | 0.21 | 0.24 | 0.33 | 0.36 | * | * | * | * | * | * | * | * | * | * | * | * |
| D84 (mm) | ** | ** | ** | ** | ** | ** | 1 | 0.45 | 0.45 | 1 | 0.52 | 0.81 | ** | ** | ** | ** | ** | ** | ** | ** | ** | ** | ** | ** |

| Table XIII: Morphology and Hydraulic Monitoring Summary | | | | | | | | | | | | | | | | | | | | | | | | |
|---|--------------------------|--------|--------|--------|--------|-------|------------------------|--------|--------|--------|--------|--------|------------------------|-------|-------|-------|-------|--------|--------------------------|--------|-------|-------|-------|--------|
| Bailey Fork and Unnamed Tributaries Stream Restoration/ EEP Project No. D04006-02 | | | | | | | | | | | | | | | | | | | | | | | | |
| Reach: Bailey Fork Mainstem (Upper) | | | | | | | | | | | | | | | | | | | | | | | | |
| Parameter | Cross Section (Riffle 5) | | | | | | Cross Section (Pool 6) | | | | | | Cross Section (Pool 7) | | | | | | Cross Section (Riffle 8) | | | | | |
| Dimension | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 |
| BF Width (ft) | 28.81 | 29.07 | 28.89 | 28.77 | 28.96 | 27.84 | 42.67 | 45.53 | 46.78 | 47 | 44.99 | 43.28 | 23.62 | 19.67 | 19.61 | 19.63 | 19.81 | 19.35 | 37.45 | 30.94 | 36.63 | 36.74 | 38.5 | 34.67 |
| Floodprone Width (ft) | 100 | 99.2 | 99.84 | 99.72 | 100.5 | 99.71 | 124 | 124.05 | 123.79 | 124.03 | 124.29 | 124.07 | 100 | 100.1 | 100 | 100 | 100 | 100.40 | 109 | 109 | 109 | 109 | 110.5 | 109.38 |
| BF Cross Sectional Area (ft ²) | 72.81 | 77.68 | 77.14 | 76.82 | 75 | 79.47 | 112.06 | 107.45 | 104.83 | 99.89 | 92.13 | 86.01 | 49.26 | 47.85 | 46.71 | 47.56 | 40.24 | 40.75 | 86.65 | 102.22 | 89.37 | 90.98 | 97.4 | 88.19 |
| BF Mean Depth (ft) | 2.53 | 2.67 | 2.67 | 2.67 | 2.59 | 2.85 | 2.63 | 2.36 | 2.24 | 2.13 | 2.05 | 1.99 | 2.09 | 2.43 | 2.38 | 2.42 | 2.03 | 2.11 | 2.31 | 3.3 | 2.44 | 2.48 | 2.53 | 2.54 |
| BF Max Depth (ft) | 4.06 | 4.14 | 4.25 | 4.22 | 4.26 | 4.69 | 5.37 | 5.83 | 4.18 | 4.44 | 5.19 | 4.81 | 3.87 | 3.61 | 3.64 | 3.69 | 3.74 | 3.72 | 5.19 | 5.39 | 4.63 | 4.68 | 4.79 | 5.12 |
| Width/Depth Ratio | 11.36 | 10.89 | 10.82 | 10.78 | 11.18 | 9.77 | 16.22 | 19.29 | 20.88 | 22.07 | 21.95 | 21.75 | 11.3 | 8.09 | 8.24 | 8.11 | 9.76 | 9.17 | 16.21 | 9.38 | 15.01 | 14.81 | 15.22 | 13.65 |
| Entrenchment Ratio | 3.47 | 3.41 | 3.46 | 3.47 | 3.47 | 3.58 | 2.91 | 2.72 | 2.65 | 2.64 | 2.76 | 2.87 | 4.23 | 5.09 | 5.1 | 5.09 | 5.05 | 5.17 | 2.91 | 3.52 | 2.98 | 2.97 | 2.87 | 3.16 |
| Bank Height Ratio | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| Wetted Perimeter (ft) | 30.27 | 30.6 | 30.42 | 30.29 | 30.6 | 30.07 | 45.21 | 49.13 | 47.71 | 48.02 | 46.43 | 44.68 | 26.24 | 21.64 | 21.8 | 21.84 | 21.36 | 21.48 | 40.31 | 34.41 | 37.94 | 38.07 | 39.85 | 36.53 |
| Hydraulic Radius (ft) | 2.41 | 2.54 | 2.54 | 2.54 | 2.45 | 2.64 | 2.48 | 2.19 | 2.2 | 2.08 | 1.98 | 1.93 | 1.88 | 2.21 | 2.14 | 2.18 | 1.88 | 1.90 | 2.15 | 2.97 | 2.36 | 2.39 | 2.44 | 2.41 |
| Substrate | | | | | | | | | | | | | | | | | | | | | | | | |
| D50 (mm) | 20.18 | 113.38 | 87.4 | 110.12 | 64 | 11.9 | 0.88 | * | * | * | * | * | 0.28 | 0.38 | 0.58 | 0.54 | 0.23 | 0.45 | 6.85 | * | * | * | * | * |
| D84 (mm) | 122.31 | 178.27 | 114.97 | 163.8 | 119.77 | 95.1 | 3.1 | ** | ** | ** | ** | ** | 1.15 | 6.54 | 0.87 | 0.94 | 0.53 | 0.95 | 156.52 | ** | ** | ** | ** | ** |

| Table XIII: Morphology and Hydraulic Monitoring Summary | | | | | | | | | | | | | | | | | | | | | | | | |
|--|-------------------------------|-------|-------|-------|-------|-------|----------------------------------|-------|--------|-------|-------|-------|---------------------------------|-------|-------|--------|-------|--------|-----------------------------------|--------|-------|--------|-------|--------|
| Bailey Fork and Unnamed Tributaries Stream Restoration / EEP Project No. D04006-02 | | | | | | | | | | | | | | | | | | | | | | | | |
| Reach: Bailey Fork UT-2 and Mainstem (Lower) | | | | | | | | | | | | | | | | | | | | | | | | |
| Parameter | UT 2 - Cross Section (Pool 9) | | | | | | UT 2 - Cross Section (Riffle 10) | | | | | | Lower - Cross Section (Pool 11) | | | | | | Lower - Cross Section (Riffle 12) | | | | | |
| Dimension | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 | MY 0 | MY 1 | MY 2 | MY 3 | MY 4 | MY 5 |
| BF Width (ft) | 21.19 | 12.6 | 11.71 | 11.95 | 7.1 | 7.65 | 18.75 | 16.97 | 13.36 | 12.25 | 13.07 | 14 | 33.39 | 33.78 | 32.84 | 51.94 | 35.91 | 36.33 | 32.12 | 32.36 | 32.71 | 32.89 | 31.76 | 32.92 |
| Floodprone Width (ft) | 74 | 74.23 | 74.01 | 74.18 | 31.82 | 72.75 | 67 | 67 | 67.15 | 58.18 | 66.5 | 66.54 | 110 | 109.9 | 101.2 | 120 | 93.89 | 109.49 | 106 | 104.21 | 106 | 104.22 | 105 | 105 |
| BF Cross Sectional Area (ft ²) | 21.06 | 12.23 | 10.05 | 9.75 | 3.15 | 7.95 | 19.16 | 15.43 | 10.63 | 8.88 | 9.49 | 10.8 | 84.5 | 92.87 | 84.76 | 108.26 | 88.89 | 93.91 | 82.05 | 81.41 | 83.19 | 85 | 75.58 | 88.19 |
| BF Mean Depth (ft) | 0.99 | 0.97 | 0.86 | 0.82 | 0.44 | 1.04 | 1.02 | 0.91 | 0.8 | 0.73 | 0.73 | 0.77 | 2.53 | 2.75 | 2.58 | 2.08 | 2.48 | 2.58 | 2.55 | 2.52 | 2.54 | 2.58 | 2.38 | 2.68 |
| BF Max Depth (ft) | 1.79 | 1.81 | 1.56 | 1.48 | 0.79 | 1.56 | 1.94 | 1.55 | 1.28 | 1.2 | 1.39 | 1.59 | 4.7 | 5.86 | 5.3 | 5.6 | 4.53 | 5.15 | 4.32 | 4.35 | 4.28 | 4.31 | 4.07 | 4.69 |
| Width/Depth Ratio | 21.4 | 12.99 | 13.62 | 14.57 | 16.14 | 7.36 | 18.38 | 18.65 | 16.7 | 16.78 | 17.9 | 18.18 | 13.2 | 12.28 | 12.73 | 24.97 | 14.48 | 14.08 | 12.6 | 12.84 | 12.88 | 12.75 | 13.34 | 12.28 |
| Entrenchment Ratio | 3.49 | 5.89 | 6.32 | 6.21 | 4.48 | 9.51 | 3.57 | 3.95 | 5.03 | 4.75 | 5.09 | 4.75 | 3.29 | 3.25 | 3.08 | 2.31 | 2.61 | 3.01 | 3.3 | 3.22 | 3.24 | 3.17 | 3.3 | 3.19 |
| Bank Height Ratio | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| Wetted Perimeter (ft) | 21.78 | 13.41 | 12.38 | 12.38 | 7.29 | 8.69 | 19.41 | 17.41 | 13.98 | 12.68 | 13.38 | 14.6 | 35.78 | 37.27 | 36.22 | 55.56 | 39.05 | 39.36 | 33.84 | 34.27 | 34.44 | 34.65 | 33.2 | 35.8 |
| Hydraulic Radius (ft) | 0.97 | 0.91 | 0.81 | 0.79 | 0.43 | 0.91 | 0.99 | 0.89 | 0.76 | 0.7 | 0.71 | 0.74 | 2.36 | 2.49 | 2.34 | 1.95 | 2.28 | 2.39 | 2.42 | 2.38 | 2.42 | 2.45 | 2.28 | 2.46 |
| Substrate | | | | | | | | | | | | | | | | | | | | | | | | |
| D50 (mm) | 0.41 | * | * | * | * | * | 2.33 | 45 | 38.5 | 4.85 | 4.43 | 5.7 | 0.3 | 0.31 | 0.3 | 1.42 | 0.42 | 0.41 | 22.6 | 46.09 | 41.75 | 58.57 | 58.16 | 50.7 |
| D84 (mm) | 0.76 | ** | ** | ** | ** | ** | 62.36 | 173.5 | 107.71 | 50.89 | 70.06 | 71.01 | 1.8 | 0.49 | 0.47 | 3.08 | 1.26 | 1.15 | 118.22 | 97.6 | 86.53 | 153.41 | 128.6 | 160.02 |

* D50 pebble information was not calculated ** D84 pebble information was not calculated

IV. METHODOLOGY

Year 1 vegetation monitoring was conducted in September 2006 using the *CVS-EEP Protocol for Recording Vegetation, Version 4.0* (Lee, M.T., Peet, R.K., Roberts, S.R., Wentworth, T.R. 2006). Year 5 vegetation monitoring was conducted in September 2010 using the same protocol as used in Years 1 through 4. Year 1 stream monitoring was conducted in April 2007 to provide adequate time between the as-built survey (completed in August 2006) and the Year 1 monitoring survey. Stream monitoring for Year 2 occurred in the fall of 2007, to provide six months between the Year 1 and Year 2 surveys. Year 3, 4, and 5 monitoring occurred in the fall of 2008, 2009, and 2010 respectively, to provide a full year between surveys.

APPENDIX A

Vegetation Raw Data

1. Vegetation Monitoring Plot Photos
2. Vegetation Data Tables



Vegetation Plot 1

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 2

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)
Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 3

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 4

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 5

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 6

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 7

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 8

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 9

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)
Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)



Vegetation Plot 10

Top Photo – Monitoring Year 1 (EMH&T, Inc. 9/20/06)

Bottom Photo - Monitoring Year 5 (EMH&T, Inc. 9/18/10)

Table 1. Vegetation Metadata

| | |
|---|---|
| Date Prepared | 1/22/2011 11:27 |
| Prepared by | Megan Wolf |
| database name | cv5-eep-entrytool-v2.2.6_Backup.mdb |
| database location | Q:\ENVIRONMENTAL\Monitoring\EEP_Vegetation_Database |
| computer name | JT7PV31 |
| file size | 53219328 |
| DESCRIPTION OF WORKSHEETS IN THIS DOCUMENT ----- | |
| Metadata | Description of database file, the report worksheets, and a summary of project(s) and project data. |
| Proj. planted | Each project is listed with its PLANTED stems per acre, for each year. This excludes live stakes. |
| Proj. total stems | Each project is listed with its TOTAL stems per acre, for each year. This includes live stakes, all planted stems, and all natural/volunteer stems. |
| Plots | List of plots surveyed with location and summary data (live stems, dead stems, missing, etc.). |
| Vigor | Frequency distribution of vigor classes for stems for all plots. |
| Vigor by Spp | Frequency distribution of vigor classes listed by species. |
| Damage | List of most frequent damage classes with number of occurrences and percent of total stems impacted by each. |
| Damage by Spp | Damage values tallied by type for each species. |
| Damage by Plot | Damage values tallied by type for each plot. |
| ALL Stems by Plot and spp | A matrix of the count of total living stems of each species (planted and natural volunteers combined) for each plot; dead and missing stems are excluded. |
| PROJECT SUMMARY ----- | |
| Project Code | D040062 |
| Project Name | Bailey Fork |
| Description | Restoration of Bailey Fork and unnamed tributaries |
| River Basin | |
| length(ft) | |
| stream-to-edge width (ft) | |
| area (sq m) | |
| Required Plots (calculated) | |
| Sampled Plots | 10 |

Table 2. Vegetation Vigor by Species

| | Species | 4 | 3 | 2 | 1 | 0 | Missing | Unknown |
|-------------|-------------------------|-----------|-----------|-----------|----------|----------|----------------|----------------|
| | Alnus serrulata | 2 | 1 | | | | 1 | |
| | Betula nigra | 3 | | 1 | | | | |
| | Cornus amomum | 13 | 8 | 2 | 2 | | | |
| | Cornus kousa | | 1 | | | | | |
| | Fraxinus pennsylvanica | 4 | 3 | 4 | | | 1 | |
| | Nyssa sylvatica | 1 | | | | | | |
| | Quercus alba | 2 | | | | | | |
| | Quercus michauxii | 3 | | | | | | |
| | Quercus pagoda | 18 | 6 | 2 | | | 1 | |
| | Quercus phellos | 11 | 2 | 3 | 1 | | 2 | |
| | Rosa palustris | 2 | | | | | | |
| | Salix nigra | 2 | 2 | | | | | |
| | Sambucus canadensis | | | 5 | 3 | | | |
| | Liriodendron tulipifera | 9 | 1 | | | | | |
| | Platanus occidentalis | 21 | 10 | | | | 3 | |
| | Malus | 1 | | | | | | |
| | Salix | | 2 | | | | | |
| | Salix exigua | | 1 | | | | | |
| TOT: | 18 | 92 | 37 | 17 | 6 | | 8 | |

Table 3. Vegetation Damage by Species

| | Species | All Damage Categories | (no damage) | Insects | Site Too Dry | Unknown | (other damage) |
|-------------|-------------------------|-----------------------|-------------|----------|--------------|-----------|----------------|
| | Alnus serrulata | 4 | 4 | | | | |
| | Betula nigra | 4 | 4 | | | | |
| | Cornus amomum | 25 | 21 | 1 | | 3 | |
| | Cornus kousa | 1 | 1 | | | | |
| | Fraxinus pennsylvanica | 12 | 10 | | | 2 | |
| | Liriodendron tulipifera | 10 | 10 | | | | |
| | Malus | 1 | 1 | | | | |
| | Nyssa sylvatica | 1 | 1 | | | | |
| | Platanus occidentalis | 34 | 34 | | | | |
| | Quercus alba | 2 | 2 | | | | |
| | Quercus michauxii | 3 | 3 | | | | |
| | Quercus pagoda | 28 | 27 | | | | 1 |
| | Quercus phellos | 19 | 14 | | 1 | 2 | 2 |
| | Rosa palustris | 2 | 2 | | | | |
| | Salix | 2 | 2 | | | | |
| | Salix exigua | 1 | 1 | | | | |
| | Salix nigra | 4 | 4 | | | | |
| | Sambucus canadensis | 8 | 2 | | | 6 | |
| TOT: | 18 | 161 | 143 | 1 | 1 | 13 | 3 |

Table 4. Vegetation Damage by Plot

| | plot | All Damage Categories (no damage) | Insects | Site Too Dry | Unknown | (other damage) | |
|-------------|------------------------|--------------------------------------|------------|--------------|----------|----------------|----------|
| | D040062-01-0001-year:5 | 15 | 15 | | | | |
| | D040062-01-0002-year:5 | 16 | 13 | | 3 | | |
| | D040062-01-0003-year:5 | 21 | 19 | 1 | | 1 | |
| | D040062-01-0004-year:5 | 19 | 17 | 1 | 1 | | |
| | D040062-01-0005-year:5 | 12 | 6 | | 6 | | |
| | D040062-01-0006-year:5 | 18 | 18 | | | | |
| | D040062-01-0007-year:5 | 14 | 13 | | | 1 | |
| | D040062-01-0008-year:5 | 16 | 15 | | 1 | | |
| | D040062-01-0009-year:5 | 15 | 12 | | 2 | 1 | |
| | D040062-01-0010-year:5 | 15 | 15 | | | | |
| TOT: | 10 | 161 | 143 | 1 | 1 | 13 | 3 |

Table 5. Stem Count by Plot and Species - Planted Stems

| Species | Total Planted Stems | # plots | avg# stems | plot D040062-01-0001-year:5 | plot D040062-01-0002-year:5 | plot D040062-01-0003-year:5 | plot D040062-01-0004-year:5 | plot D040062-01-0005-year:5 | plot D040062-01-0006-year:5 | plot D040062-01-0007-year:5 | plot D040062-01-0008-year:5 | plot D040062-01-0009-year:5 | plot D040062-01-0010-year:5 |
|-------------------------|---------------------|-----------|------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|
| Alnus serrulata | 3 | 1 | 3 | | | 3 | | | | | | | |
| Betula nigra | 4 | 1 | 4 | | | 4 | | | | | | | |
| Cornus amomum | 25 | 9 | 2.78 | 1 | 1 | | 6 | 2 | 4 | 1 | 3 | 5 | 2 |
| Cornus kousa | 1 | 1 | 1 | | | | | 1 | | | | | |
| Fraxinus pennsylvanica | 11 | 4 | 2.75 | 3 | | | | 5 | 1 | | | 2 | |
| Liriodendron tulipifera | 10 | 4 | 2.5 | 1 | | | 2 | | 4 | 3 | | | |
| Malus | 1 | 1 | 1 | 1 | | | | | | | | | |
| Nyssa sylvatica | 1 | 1 | 1 | 1 | | | | | | | | | |
| Platanus occidentalis | 31 | 6 | 5.17 | 4 | 1 | 8 | 4 | | | 4 | | | 10 |
| Quercus alba | 2 | 1 | 2 | | | | 2 | | | | | | |
| Quercus michauxii | 3 | 2 | 1.5 | | | | | | 1 | | | 2 | |
| Quercus pagoda | 26 | 7 | 3.71 | 1 | 8 | | | 1 | | 3 | 8 | 4 | 1 |
| Quercus phellos | 17 | 6 | 2.83 | | 4 | 4 | 4 | | | 1 | 2 | | 2 |
| Rosa palustris | 2 | 1 | 2 | 2 | | | | | | | | | |
| Salix | 2 | 1 | 2 | | | | | | 2 | | | | |
| Salix exigua | 1 | 1 | 1 | | | | | | 1 | | | | |
| Salix nigra | 4 | 3 | 1.33 | | | 1 | | | 2 | | 1 | | |
| Sambucus canadensis | 8 | 5 | 1.6 | | 1 | | | 2 | 2 | | 1 | 2 | |
| TOT: 18 | 152 | 18 | | 14 | 15 | 20 | 18 | 11 | 17 | 12 | 15 | 15 | 15 |

Table 6. Stem Count by Plot and Species - All Stems

| | Species | Total Stems | # plots | avg# stems | D040062-01-0001-year:5 | D040062-01-0002-year:5 | D040062-01-0003-year:5 | D040062-01-0004-year:5 | D040062-01-0005-year:5 | D040062-01-0006-year:5 | D040062-01-0007-year:5 | D040062-01-0008-year:5 | D040062-01-0009-year:5 | D040062-01-0010-year:5 |
|-------------|--------------------------------|-------------|-----------|------------|------------------------|------------------------|------------------------|------------------------|------------------------|------------------------|------------------------|------------------------|------------------------|------------------------|
| | <i>Alnus serrulata</i> | 3 | 1 | 3 | | | 3 | | | | | | | |
| | <i>Betula nigra</i> | 12 | 1 | 12 | | | 12 | | | | | | | |
| | <i>Cornus amomum</i> | 32 | 9 | 3.56 | 1 | 1 | | 6 | 4 | 4 | 3 | 6 | 5 | 2 |
| | <i>Cornus kousa</i> | 1 | 1 | 1 | | | | | 1 | | | | | |
| | <i>Fraxinus pennsylvanica</i> | 11 | 4 | 2.75 | 3 | | | | 5 | 1 | | | 2 | |
| | <i>Liquidambar styraciflua</i> | 3 | 2 | 1.5 | | | 1 | | | | 2 | | | |
| | <i>Nyssa sylvatica</i> | 1 | 1 | 1 | 1 | | | | | | | | | |
| | <i>Quercus alba</i> | 2 | 1 | 2 | | | | 2 | | | | | | |
| | <i>Quercus michauxii</i> | 3 | 2 | 1.5 | | | | | | 1 | | | 2 | |
| | <i>Quercus pagoda</i> | 26 | 7 | 3.71 | 1 | 8 | | | 1 | | 3 | 8 | 4 | 1 |
| | <i>Quercus phellos</i> | 19 | 6 | 3.17 | | 4 | 4 | 4 | | | 1 | 3 | | 3 |
| | <i>Rosa palustris</i> | 2 | 1 | 2 | 2 | | | | | | | | | |
| | <i>Salix nigra</i> | 4 | 3 | 1.33 | | | 1 | | | 2 | | 1 | | |
| | <i>Sambucus canadensis</i> | 9 | 6 | 1.5 | | 1 | | | 2 | 2 | 1 | 1 | 2 | |
| | <i>Cercis canadensis</i> | 1 | 1 | 1 | | | | | | | | 1 | | |
| | <i>Liriodendron tulipifera</i> | 26 | 5 | 5.2 | 2 | | 15 | 2 | | 4 | 3 | | | |
| | <i>Taxodium distichum</i> | 2 | 1 | 2 | | | | | | | 2 | | | |
| | <i>Platanus occidentalis</i> | 34 | 6 | 5.67 | 6 | 1 | 8 | 4 | | | 4 | | | 11 |
| | <i>Malus</i> | 1 | 1 | 1 | 1 | | | | | | | | | |
| | <i>Salix</i> | 2 | 1 | 2 | | | | | | 2 | | | | |
| | <i>Salix exigua</i> | 1 | 1 | 1 | | | | | | 1 | | | | |
| | <i>Acer negundo</i> | 9 | 2 | 4.5 | | | | | | | 7 | | | 2 |
| | <i>Acer rubrum</i> | 40 | 4 | 10 | | 1 | 33 | | | | 4 | | | 2 |
| TOT: | 23 | 244 | 23 | | 17 | 16 | 77 | 18 | 13 | 17 | 30 | 20 | 15 | 21 |

APPENDIX B

Geomorphologic Raw Data

1. Fixed Station Photos
2. Table B1. Qualitative Visual Stability Assessment
3. Cross Section Plots
4. Longitudinal Plots
5. Pebble Count Plots
6. Bankfull Event Photos
7. Stream Problem Areas Plan View
8. Stream Problem Area Photos



Fixed Station 1 (Photo Point 13)

Overview of the valley at the confluence of Lower Bailey Fork and UT2, near the downstream terminus of the project, facing upstream along the mainstem.

Year 5 – top photo (EMH&T, Inc. 9/18/10)

Year 2 – bottom photo (EMH&T, Inc. 10/22/07)



Fixed Station 2 (Photo Point 14)

Overview of valley at confluence of Upper Bailey Fork and UT1, facing upstream.

Year 5 – top photo (EMH&T, Inc. 9/18/10)

Year 2 – bottom photo (EMH&T, Inc. 10/22/07)



Fixed Station 3 (Photo Point 15)

Overview of valley along UT1 near the upstream terminus of the project, facing downstream.

Year 5 – top photo (EMH&T, Inc. 9/18/10)

Year 2 – bottom photo (EMH&T, Inc. 10/22/07)

Table B1. Visual Morphological Stability Assessment
Bailey Fork Stream Restoration / EEP Project No. D04006-02

Segment/Reach: Upper

| Feature Category | Metric (per As-built and reference baselines) | (# Stable) Number Performing as Intended | Total number per As-built | Total Number / feet in unstable state | % Perform in Stable Condition | Feature Perform. Mean or Total |
|-------------------|--|--|---------------------------|---------------------------------------|-------------------------------|--------------------------------|
| A. Riffles | 1. Present? | 13 | 15 | 2 | 87 | |
| | 2. Armor stable (e.g. no displacement)? | 13 | 15 | 2 | 87 | |
| | 3. Facet grade appears stable? | 13 | 15 | 2 | 87 | |
| | 4. Minimal evidence of embedding/fining? | 13 | 15 | 2 | 87 | |
| | 5. Length appropriate? | 13 | 15 | 2 | 87 | 87% |
| B. Pools | 1. Present? (e.g. not subject to severe aggrad. or migrat.?) | 16 | 16 | 0 | 100 | |
| | 2. Sufficiently deep (Max Pool D:Mean Bkf>1.6?) | 16 | 16 | 0 | 100 | |
| | 3. Length appropriate? | 16 | 16 | 0 | 100 | 100% |
| C. Thalgweg | 1. Upstream of meander bend (run/inflection) centering? | 11 | 11 | 0 | 100 | |
| | 2. Downstream of meander (glide/inflection) centering? | 11 | 11 | 0 | 100 | 100% |
| D. Meanders | 1. Outer bend in state of limited/controlled erosion? | 11 | 11 | 0 | 100 | |
| | 2. Of those eroding, # w/concomitant point bar formation? | 11 | 11 | 0 | 100 | |
| | 3. Apparent Rc within spec? | 11 | 11 | 0 | 100 | |
| | 4. Sufficient floodplain access and relief? | 11 | 11 | 0 | 100 | 100% |
| E. Bed General | 1. General channel bed aggradation areas (bar formation) | N/A | N/A | 1/20 feet | 95 | |
| | 2. Channel bed degradation - areas of increasing downcutting or headcutting? | N/A | N/A | 0/0 feet | 100 | 98% |
| F. Vanes | 1. Free of back or arm scour? | 16 | 16 | 0 | 100 | |
| | 2. Height appropriate? | 16 | 16 | 0 | 100 | |
| | 3. Angle and geometry appear appropriate? | 16 | 16 | 0 | 100 | |
| | 4. Free of piping or other structural failures? | 16 | 16 | 0 | 100 | |
| | 5. Structure buried under aggraded material? | 14 | 16 | 2 | 87 | 97% |
| G. Wads/ Boulders | 1. Free of scour? | N/A | 0 | N/A | N/A | N/A |
| | 2. Footing stable? | N/A | 0 | N/A | N/A | N/A |

Table B1. Visual Morphological Stability Assessment
Bailey Fork Stream Restoration / EEP Project No. D004006-02
Segment/Reach: Lower

| Feature Category | Metric (per As-built and reference baselines) | (# Stable) Number Performing as Intended | Total number per As-built | Total Number / feet in unstable state | % Perform in Stable Condition | Feature Perform. Mean or Total |
|-------------------|--|--|---------------------------|---------------------------------------|-------------------------------|--------------------------------|
| A. Riffles | 1. Present? | 9 | 9 | 0 | 100 | |
| | 2. Armor stable (e.g. no displacement)? | 8 | 9 | 1 | 89 | |
| | 3. Facet grade appears stable? | 9 | 9 | 0 | 100 | |
| | 4. Minimal evidence of embedding/fining? | 9 | 9 | 0 | 100 | |
| | 5. Length appropriate? | 9 | 9 | 0 | 100 | 98% |
| B. Pools | 1. Present? (e.g. not subject to severe aggrad. or migrat.?) | 10 | 10 | 0 | 100 | |
| | 2. Sufficiently deep (Max Pool D:Mean Bkf>1.6?) | 10 | 10 | 0 | 100 | |
| | 3. Length appropriate? | 10 | 10 | 0 | 100 | 100% |
| C. Thalweg | 1. Upstream of meander bend (run/inflection) centering? | 6 | 6 | 0 | 100 | |
| | 2. Downstream of meander (glide/inflection) centering? | 6 | 6 | 0 | 100 | 100% |
| D. Meanders | 1. Outer bend in state of limited/controlled erosion? | 6 | 6 | 0 | 100 | |
| | 2. Of those eroding, # w/concomitant point bar formation? | 6 | 6 | 0 | 100 | |
| | 3. Apparent Rc within spec? | 6 | 6 | 0 | 100 | |
| | 4. Sufficient floodplain access and relief? | 6 | 6 | 0 | 100 | 100% |
| E. Bed General | 1. General channel bed aggradation areas (bar formation) | N/A | N/A | 2/ 50 feet | 96 | |
| | 2. Channel bed degradation - areas of increasing downcutting or headcutting? | N/A | N/A | 0/ 0 feet | 100 | 97% |
| F. Vanes | 1. Free of back or arm scour? | 9 | 9 | 0 | 100 | |
| | 2. Height appropriate? | 9 | 9 | 0 | 100 | |
| | 3. Angle and geometry appear appropriate? | 9 | 9 | 0 | 100 | |
| | 4. Free of piping or other structural failures? | 9 | 9 | 0 | 100 | |
| | 5. Structure buried under aggraded material? | 9 | 9 | 0 | 100 | 100% |
| G. Wads/ Boulders | 1. Free of scour? | N/A | 0 | N/A | N/A | N/A |
| | 2. Footing stable? | N/A | 0 | N/A | N/A | N/A |

| Table B1. Visual Morphological Stability Assessment Bailey Fork Stream Restoration / EEP Project No. D04006-02 Segment/Reach: UT1 | | | | | | |
|---|--|--|---------------------------|---------------------------------------|-------------------------------|--------------------------------|
| Feature Category | Metric (per As-built and reference baselines) | (# Stable) Number Performing as Intended | Total number per As-built | Total Number / feet in unstable state | % Perform in Stable Condition | Feature Perform. Mean or Total |
| A. Riffles | 1. Present? | 33 | 35 | 2 | 94 | |
| | 2. Armor stable (e.g. no displacement)? | 33 | 35 | 2 | 94 | |
| | 3. Facet grade appears stable? | 33 | 35 | 2 | 94 | |
| | 4. Minimal evidence of embedding/fining? | 26 | 35 | 9 | 72 | |
| | 5. Length appropriate? | 33 | 35 | 2 | 94 | 90% |
| B. Pools | 1. Present? (e.g. not subject to severe aggrad. or migrat.?) | 33 | 35 | 2 | 94 | |
| | 2. Sufficiently deep (Max Pool D:Mean Bkt>1.6?) | 25 | 35 | 10 | 71 | |
| | 3. Length appropriate? | 33 | 35 | 2 | 94 | 86% |
| C. Thalweg | 1. Upstream of meander bend (run/inflection) centering? | 28 | 28 | 0 | 100 | |
| | 2. Downstream of meander (glide/inflection) centering? | 28 | 28 | 0 | 100 | 100% |
| D. Meanders | 1. Outer bend in state of limited/controlled erosion? | 28 | 28 | 0 | 100 | |
| | 2. Of those eroding. # w/concomitant point bar formation? | 28 | 28 | 0 | 100 | |
| | 3. Apparent Rc within spec? | 28 | 28 | 0 | 100 | |
| | 4. Sufficient floodplain access and relief? | 28 | 28 | 0 | 100 | 100% |
| E. Bed General | 1. General channel bed aggradation areas (bar formation) | N/A | N/A | 1/20 feet | 95 | |
| | 2. Channel bed degradation - areas of increasing downcutting or headcutting? | N/A | N/A | 0/0 feet | 100 | 98% |
| F. Vanes | 1. Free of back or arm scour? | 31 | 31 | 0 | 100 | |
| | 2. Height appropriate? | 31 | 31 | 0 | 100 | |
| | 3. Angle and geometry appear appropriate? | 31 | 31 | 0 | 100 | |
| | 4. Free of piping or other structural failures? | 31 | 31 | 0 | 100 | |
| | 5. Structure buried under aggraded material? | 22 | 31 | 9 | 71 | 94% |
| G. Wads/ Boulders | 1. Free of scour? | 12 | 12 | 0 | 100 | |
| | 2. Footing stable? | 12 | 12 | 0 | 100 | 100% |

| Table B1. Visual Morphological Stability Assessment Bailey Fork Stream Restoration / EEP Project No. D04006-02 Segment/Reach: UT2 | | | | | | |
|--|--|--|---------------------------|---------------------------------------|-------------------------------|--------------------------------|
| Feature Category | Metric (per As-built and reference baselines) | (# Stable) Number Performing as Intended | Total number per As-built | Total Number / feet in unstable state | % Perform in Stable Condition | Feature Perform. Mean or Total |
| A. Riffles | 1. Present? | 19 | 19 | 0 | 100 | |
| | 2. Armor stable (e.g. no displacement)? | 19 | 19 | 0 | 100 | |
| | 3. Facet grade appears stable? | 19 | 19 | 0 | 100 | |
| | 4. Minimal evidence of embedding/fining? | 19 | 19 | 0 | 100 | |
| | 5. Length appropriate? | 19 | 19 | 0 | 100 | 100% |
| B. Pools | 1. Present? (e.g. not subject to severe aggrad. or migrat.?) | 18 | 19 | 1 | 95 | |
| | 2. Sufficiently deep (Max Pool D:Mean Bkf>1.6?) | 15 | 19 | 4 | 79 | |
| | 3. Length appropriate? | 18 | 19 | 1 | 95 | 90% |
| C. Thalweg | 1. Upstream of meander bend (run/inflection) centering? | 15 | 15 | 0 | 100 | |
| | 2. Downstream of meander (gide/inflection) centering? | 15 | 15 | 0 | 100 | 100% |
| D. Meanders | 1. Outer bend in state of limited/controlled erosion? | 14 | 15 | 0 | 100 | |
| | 2. Of those eroding. # w/concomitant point bar formation? | 15 | 15 | 0 | 100 | |
| | 3. Apparent Rc within spec? | 15 | 15 | 0 | 100 | |
| | 4. Sufficient floodplain access and relief? | 15 | 15 | 0 | 100 | 100% |
| E. Bed General | 1. General channel bed aggradation areas (bar formation) | N/A | N/A | 0/ 0 feet | 100 | |
| | 2. Channel bed degradation - areas of increasing downcutting or headcutting? | N/A | N/A | 0/ 0 feet | 100 | 100% |
| F. Vanes | 1. Free of back or arm scour? | 11 | 11 | 0 | 100 | |
| | 2. Height appropriate? | 11 | 11 | 0 | 100 | |
| | 3. Angle and geometry appear appropriate? | 11 | 11 | 0 | 100 | |
| | 4. Free of piping or other structural failures? | 11 | 11 | 0 | 100 | |
| | 5. Structure buried under aggraded material? | 8 | 11 | 3 | 73 | 95% |
| G. Wads/ Boulders | 1. Free of scour? | N/A | 0 | N/A | N/A | N/A |
| | 2. Footing stable? | N/A | 0 | N/A | N/A | N/A |

Summary Data

Bankfull Area 14.97 ft²
 Bankfull Width 15.4 ft
 Mean Depth 0.97 ft
 Maximum Depth 1.91 ft
 Width/Depth Ratio 15.88
 Entrenchment Ratio 4.84
 Classification C

PROJECT

Bailey Fork
 D04006-2

5-YEAR

TASK Cross-Section

REACH UT1

DATE 9/28/10




CROSS SECTION: 1

FEATURE: Riffle



Cross-section photo – looking downstream



Summary Data

Bankfull Area 16.45 ft²
 Bankfull Width 20.98 ft
 Mean Depth 0.78 ft
 Maximum Depth 2.12 ft
 Width/Depth Ratio 26.9
 Entrenchment Ratio 2.58

PROJECT Bailey Fork
 D04006-2
 5-YEAR


TASK Cross-Section
REACH UT1
DATE 9/28/10



CROSS SECTION: 2
FEATURE: Pool



Cross-section photo – looking downstream



Summary Data

Bankfull Area 16.72 ft²
 Bankfull Width 17.35 ft
 Mean Depth 0.96 ft
 Maximum Depth 2.26 ft
 Width/Depth Ratio 18.07
 Entrenchment Ratio 3.68
 Classification C

PROJECT Bailey Fork

D04006-2
 5-YEAR

TASK Cross-Section

REACH UT1
DATE 9/28/10




CROSS SECTION: 3
FEATURE: Riffle



Cross-section photo – looking downstream
 Channel is obscured by vegetation.

XS 3



Summary Data

Bankfull Area 11.64 ft²
 Bankfull Width 23.42 ft
 Mean Depth 0.5 ft
 Maximum Depth 2.12 ft
 Width/Depth Ratio 46.84
 Entrenchment Ratio 3.35

PROJECT

Bailey Fork
 D04006-2
 5-YEAR

Cross-Section

UT1
 9/28/10




CROSS SECTION: 4
FEATURE: Pool



Cross-section photo – looking downstream

XS 4



Summary Data

Bankfull Area 79.47 ft²
 Bankfull Width 27.84 ft
 Mean Depth 2.85 ft
 Maximum Depth 4.69 ft
 Width/Depth Ratio 9.77
 Entrenchment Ratio 3.58
 Classification C

PROJECT Bailey Fork
 D04006-2
 5-YEAR


Cross-Section
 Upper
 9/28/10

CROSS SECTION: 5
FEATURE: Riffle

TASK
REACH
DATE



Cross-section photo – looking downstream



Summary Data

Bankfull Area 86.01 ft²
 Bankfull Width 43.28 ft
 Mean Depth 1.99 ft
 Maximum Depth 4.81 ft
 Width/Depth Ratio 21.75
 Entrenchment Ratio 2.87

PROJECT Bailey Fork
 D04006-2
 5-YEAR


TASK Cross-Section
REACH Upper
DATE 9/28/10



CROSS SECTION: 6
FEATURE: Pool



Cross-section photo – looking left to right bank



Summary Data

Bankfull Area 40.75 ft²
 Bankfull Width 19.35 ft
 Mean Depth 2.11 ft
 Maximum Depth 3.72 ft
 Width/Depth Ratio 9.17
 Entrenchment Ratio 5.17

PROJECT Bailey Fork

D04006-2
 5-YEAR

TASK

Cross-Section

REACH

Upper

DATE

9/28/10



CROSS SECTION: 7


FEATURE: Pool



Cross-section photo – looking downstream

XS 7

○ VRS Point XS
 ▲ Bankfull Indicators
 ▼ Water Surface Points
 △ XS7 Point Year 2
 ▲ XS7 Point Year 1
 ▼ XS7 Point Year 3
 □ XS7 Point Year 4
 DMF = 19.3
 DMF = 2.11
 DMF = 46.7



Summary Data

Bankfull Area 88.19 ft²
 Bankfull Width 34.67 ft
 Mean Depth 2.54 ft
 Maximum Depth 5.12 ft
 Width/Depth Ratio 13.65
 Entrenchment Ratio 3.16
 Classification C

PROJECT Bailey Fork
 D04006-2
 5-YEAR


TASK Cross-Section
REACH Upper
DATE 9/28/10



CROSS SECTION: 8
FEATURE: Riffle



Cross-section photo – looking downstream



Summary Data

Bankfull Area 7.95 ft²
 Bankfull Width 7.65 ft
 Mean Depth 1.04 ft
 Maximum Depth 1.56 ft
 Width/Depth Ratio 7.36
 Entrenchment Ratio 9.51

PROJECT Bailey Fork
 D04006-2
 5-YEAR


TASK Cross-Section
REACH UT2
DATE 9/28/10



CROSS SECTION: 9
FEATURE: Pool



Cross-section photo – looking downstream



Summary Data

Bankfull Area 10.8 ft²
 Bankfull Width 14.0 ft
 Mean Depth 0.77 ft
 Maximum Depth 1.59 ft
 Width/Depth Ratio 18.18
 Entrenchment Ratio 4.75
 Classification C

PROJECT Bailey Fork

D04006-2
 5-YEAR

TASK Cross-Section


REACH UT2
DATE 9/28/10



CROSS SECTION: 10
FEATURE: Riffle



Cross-section photo – looking downstream



Summary Data

Bankfull Area 93.91 ft²
 Bankfull Width 36.33 ft
 Mean Depth 2.58 ft
 Maximum Depth 5.15 ft
 Width/Depth Ratio 14.08
 Entrenchment Ratio 3.01

PROJECT

Bailey Fork
 D04006-2
 5-YEAR

TASK
REACH
DATE


Cross-Section
 Lower
 9/28/10



CROSS SECTION: 11
FEATURE: Pool



Cross-section photo – channel partially obscured by vegetation



Summary Data

Bankfull Area 88.19 ft²
 Bankfull Width 32.92 ft
 Mean Depth 2.68 ft
 Maximum Depth 4.69 ft
 Width/Depth Ratio 12.28
 Entrenchment Ratio 3.19
 Classification C

PROJECT Bailey Fork
 D04006-2
 5-YEAR


Cross-Section
 Lower
 9/28/10

CROSS SECTION: 12
FEATURE: Riffle


TASK
REACH
DATE




Cross-section photo – looking right to left bank




Upper Bailey - Year 5




Upper Bailey - Year 5




Lower Bailey Fork - Year 5




Lower Bailey Fork - Year 5




UT1- Year 5




UT1- Year 5




UT1- Year 5



UT2 - Year 5




UT2 - Year 5




| Pebble Count - Pool | | | | |
|---------------------|--------------------|-------|------------|--------------|
| Material | Particle Size (mm) | Count | % in Range | % Cumulative |
| Silt/Clay | <0.062 | 4 | 7 | 7 |
| Very Fine Sand | 0.062-0.125 | 5 | 8 | 15 |
| Fine Sand | 0.125-0.25 | 10 | 17 | 32 |
| Medium Sand | 0.25-0.5 | 24 | 40 | 72 |
| Coarse Sand | 0.5-1.0 | 12 | 20 | 92 |
| Very Coarse Sand | 1.0-2.0 | 5 | 8 | 100 |
| Very Fine Gravel | 2.0-4.0 | 0 | 0 | 100 |
| Fine Gravel | 4.0-5.7 | 0 | 0 | 100 |
| Fine Gravel | 5.7-8.0 | 0 | 0 | 100 |
| Medium Gravel | 8.0-11.3 | 0 | 0 | 100 |
| Medium Gravel | 11.3-16.0 | 0 | 0 | 100 |
| Coarse Gravel | 16.0-22.6 | 0 | 0 | 100 |
| Coarse Gravel | 22.6-32 | 0 | 0 | 100 |
| Very Coarse Gravel | 32-45 | 0 | 0 | 100 |
| Very Coarse Gravel | 45-64 | 0 | 0 | 100 |
| Small Cobble | 64-90 | 0 | 0 | 100 |
| Small Cobble | 90-128 | 0 | 0 | 100 |
| Large Cobble | 128-180 | 0 | 0 | 100 |
| Large Cobble | 180-256 | 0 | 0 | 100 |
| Small Boulder | 256-362 | 0 | 0 | 100 |
| Small Boulder | 362-512 | 0 | 0 | 100 |
| Medium Boulder | 512-1024 | 0 | 0 | 100 |
| Large Boulder | 1024-2048 | 0 | 0 | 100 |
| Bedrock | <2048 | 0 | 0 | 100 |
| Totals | | 60 | 100 | 100 |

| Bailey Fork Stream Restoration EEP Project No. D04006-02 | | | |
|--|-----------|---------|------|
| Reach | UT1 | X Sec | 2 |
| Date | 9/28/2010 | Sta No. | 4+50 |

Histogram




Particle Size Distribution




| Pebble Count - Riffle | | | | |
|-----------------------|--------------------|-------|------------|--------------|
| Material | Particle Size (mm) | Count | % in Range | % Cumulative |
| Silt/Clay | <0.062 | 0 | 0 | 0 |
| Very Fine Sand | 0.062-0.125 | 0 | 0 | 0 |
| Fine Sand | 0.125-0.25 | 1 | 2 | 2 |
| Medium Sand | 0.25-0.5 | 10 | 17 | 18 |
| Coarse Sand | 0.5-1.0 | 10 | 17 | 35 |
| Very Coarse Sand | 1.0-2.0 | 1 | 2 | 37 |
| Very Fine Gravel | 2.0-4.0 | 0 | 0 | 37 |
| Fine Gravel | 4.0-5.7 | 1 | 2 | 38 |
| Fine Gravel | 5.7-8.0 | 3 | 5 | 43 |
| Medium Gravel | 8.0-11.3 | 3 | 5 | 48 |
| Medium Gravel | 11.3-16.0 | 8 | 13 | 62 |
| Coarse Gravel | 16.0-22.6 | 7 | 12 | 73 |
| Coarse Gravel | 22.6-32 | 3 | 5 | 78 |
| Very Coarse Gravel | 32-45 | 1 | 2 | 80 |
| Very Coarse Gravel | 45-64 | 0 | 0 | 80 |
| Small Cobble | 64-90 | 2 | 3 | 83 |
| Small Cobble | 90-128 | 3 | 5 | 88 |
| Large Cobble | 128-180 | 2 | 3 | 92 |
| Large Cobble | 180-256 | 1 | 2 | 93 |
| Small Boulder | 256-362 | 2 | 3 | 97 |
| Small Boulder | 362-512 | 0 | 0 | 97 |
| Medium Boulder | 512-1024 | 0 | 0 | 97 |
| Large Boulder | 1024-2048 | 0 | 0 | 97 |
| Bedrock | <2048 | 2 | 3 | 100 |
| Totals | | 60 | 100 | |

| Bailey Fork Stream Restoration EEP Project No. D04006-02 | | | |
|--|-----------|---------|------|
| Reach | Upper | X Sec | 5 |
| Date | 9/28/2010 | Sta No. | 6+00 |

Histogram




Particle Size Distribution




| Pebble Count - Pool | | | | |
|---------------------|--------------------|-------|------------|--------------|
| Material | Particle Size (mm) | Count | % in Range | % Cumulative |
| Silt/Clay | <0.062 | 1 | 2 | 2 |
| Very Fine Sand | 0.062-0.125 | 1 | 2 | 3 |
| Fine Sand | 0.125-0.25 | 5 | 8 | 12 |
| Medium Sand | 0.25-0.5 | 29 | 48 | 60 |
| Coarse Sand | 0.5-1.0 | 16 | 27 | 87 |
| Very Coarse Sand | 1.0-2.0 | 6 | 10 | 97 |
| Very Fine Gravel | 2.0-4.0 | 0 | 0 | 97 |
| Fine Gravel | 4.0-5.7 | 0 | 0 | 97 |
| Fine Gravel | 5.7-8.0 | 0 | 0 | 97 |
| Medium Gravel | 8.0-11.3 | 1 | 2 | 98 |
| Medium Gravel | 11.3-16.0 | 1 | 2 | 100 |
| Coarse Gravel | 16.0-22.6 | 0 | 0 | 100 |
| Coarse Gravel | 22.6-32 | 0 | 0 | 100 |
| Very Coarse Gravel | 32-45 | 0 | 0 | 100 |
| Very Coarse Gravel | 45-64 | 0 | 0 | 100 |
| Small Cobble | 64-90 | 0 | 0 | 100 |
| Small Cobble | 90-128 | 0 | 0 | 100 |
| Large Cobble | 128-180 | 0 | 0 | 100 |
| Large Cobble | 180-256 | 0 | 0 | 100 |
| Small Boulder | 256-362 | 0 | 0 | 100 |
| Small Boulder | 362-512 | 0 | 0 | 100 |
| Medium Boulder | 512-1024 | 0 | 0 | 100 |
| Large Boulder | 1024-2048 | 0 | 0 | 100 |
| Bedrock | <2048 | 0 | 0 | 100 |
| Totals | | 60 | 100 | 100 |

| Bailey Fork Stream Restoration EEP Project No. D04006-02 | | | |
|--|-----------|---------|-------|
| Reach | Upper | X Sec | 7 |
| Date | 9/28/2010 | Sta No. | 11+00 |

Histogram




Particle Size Distribution




| Pebble Count - Riffle | | | | |
|-----------------------|--------------------|-------|------------|--------------|
| Material | Particle Size (mm) | Count | % in Range | % Cumulative |
| Silt/Clay | <0.062 | 0 | 0 | 0 |
| Very Fine Sand | 0.062-0.125 | 1 | 2 | 2 |
| Fine Sand | 0.125-0.25 | 1 | 2 | 3 |
| Medium Sand | 0.25-0.5 | 20 | 32 | 35 |
| Coarse Sand | 0.5-1.0 | 3 | 5 | 40 |
| Very Coarse Sand | 1.0-2.0 | 3 | 5 | 45 |
| Very Fine Gravel | 2.0-4.0 | 0 | 0 | 45 |
| Fine Gravel | 4.0-5.7 | 3 | 5 | 50 |
| Fine Gravel | 5.7-8.0 | 2 | 3 | 53 |
| Medium Gravel | 8.0-11.3 | 3 | 5 | 58 |
| Medium Gravel | 11.3-16.0 | 0 | 0 | 58 |
| Coarse Gravel | 16.0-22.6 | 0 | 0 | 58 |
| Coarse Gravel | 22.6-32 | 3 | 5 | 63 |
| Very Coarse Gravel | 32-45 | 4 | 6 | 69 |
| Very Coarse Gravel | 45-64 | 8 | 13 | 82 |
| Small Cobble | 64-90 | 4 | 6 | 89 |
| Small Cobble | 90-128 | 2 | 3 | 92 |
| Large Cobble | 128-180 | 0 | 0 | 92 |
| Large Cobble | 180-256 | 2 | 3 | 95 |
| Small Boulder | 256-362 | 3 | 5 | 100 |
| Small Boulder | 362-512 | 0 | 0 | 100 |
| Medium Boulder | 512-1024 | 0 | 0 | 100 |
| Large Boulder | 1024-2048 | 0 | 0 | 100 |
| Bedrock | <2048 | 0 | 0 | 100 |
| Totals | | 62 | 100 | |

| Bailey Fork Stream Restoration EEP Project No. D04006-02 | | | |
|--|-----------|---------|------|
| Reach | UT2 | X Sec | 10 |
| Date | 9/28/2010 | Sta No. | 6+50 |

Histogram





Particle Size Distribution



| Pebble Count - Pool | | | | |
|---------------------|--------------------|-------|------------|--------------|
| Material | Particle Size (mm) | Count | % in Range | % Cumulative |
| Silt/Clay | <0.062 | 6 | 9 | 9 |
| Very Fine Sand | 0.062-0.125 | 2 | 3 | 13 |
| Fine Sand | 0.125-0.25 | 6 | 9 | 22 |
| Medium Sand | 0.25-0.5 | 28 | 44 | 66 |
| Coarse Sand | 0.5-1.0 | 15 | 23 | 89 |
| Very Coarse Sand | 1.0-2.0 | 3 | 5 | 94 |
| Very Fine Gravel | 2.0-4.0 | 0 | 0 | 94 |
| Fine Gravel | 4.0-5.7 | 0 | 0 | 94 |
| Fine Gravel | 5.7-8.0 | 0 | 0 | 94 |
| Medium Gravel | 8.0-11.3 | 0 | 0 | 94 |
| Medium Gravel | 11.3-16.0 | 0 | 0 | 94 |
| Coarse Gravel | 16.0-22.6 | 0 | 0 | 94 |
| Coarse Gravel | 22.6-32 | 0 | 0 | 94 |
| Very Coarse Gravel | 32-45 | 0 | 0 | 94 |
| Very Coarse Gravel | 45-64 | 0 | 0 | 94 |
| Small Cobble | 64-90 | 0 | 0 | 94 |
| Small Cobble | 90-128 | 0 | 0 | 94 |
| Large Cobble | 128-180 | 0 | 0 | 94 |
| Large Cobble | 180-256 | 0 | 0 | 94 |
| Small Boulder | 256-362 | 2 | 3 | 97 |
| Small Boulder | 362-512 | 2 | 3 | 100 |
| Medium Boulder | 512-1024 | 0 | 0 | 100 |
| Large Boulder | 1024-2048 | 0 | 0 | 100 |
| Bedrock | <2048 | 0 | 0 | 100 |
| Totals | | 64 | 100 | |


| Bailey Fork Stream Restoration EEP Project No. D04006-02 | | | |
|--|-----------|---------|------|
| Reach | Lower | X Sec | 11 |
| Date | 9/28/2010 | Sta No. | 6+00 |




| Pebble Count - Riffle | | | | |
|-----------------------|--------------------|-------|------------|--------------|
| Material | Particle Size (mm) | Count | % in Range | % Cumulative |
| Silt/Clay | <0.062 | 0 | 0 | 0 |
| Very Fine Sand | 0.062-0.125 | 0 | 0 | 0 |
| Fine Sand | 0.125-0.25 | 0 | 0 | 0 |
| Medium Sand | 0.25-0.5 | 0 | 0 | 0 |
| Coarse Sand | 0.5-1.0 | 0 | 0 | 0 |
| Very Coarse Sand | 1.0-2.0 | 0 | 0 | 0 |
| Very Fine Gravel | 2.0-4.0 | 0 | 0 | 0 |
| Fine Gravel | 4.0-5.7 | 1 | 2 | 2 |
| Fine Gravel | 5.7-8.0 | 0 | 0 | 2 |
| Medium Gravel | 8.0-11.3 | 3 | 5 | 6 |
| Medium Gravel | 11.3-16.0 | 1 | 2 | 8 |
| Coarse Gravel | 16.0-22.6 | 4 | 6 | 14 |
| Coarse Gravel | 22.6-32 | 10 | 16 | 30 |
| Very Coarse Gravel | 32-45 | 10 | 16 | 45 |
| Very Coarse Gravel | 45-64 | 10 | 16 | 61 |
| Small Cobble | 64-90 | 10 | 16 | 77 |
| Small Cobble | 90-128 | 2 | 3 | 80 |
| Large Cobble | 128-180 | 5 | 8 | 88 |
| Large Cobble | 180-256 | 4 | 6 | 94 |
| Small Boulder | 256-362 | 1 | 2 | 95 |
| Small Boulder | 362-512 | 0 | 0 | 95 |
| Medium Boulder | 512-1024 | 1 | 2 | 97 |
| Large Boulder | 1024-2048 | 0 | 0 | 97 |
| Bedrock | <2048 | 2 | 3 | 100 |
| Totals | | 64 | 100 | |

| Bailey Fork Stream Restoration EEP Project No. D04006-02 | | | |
|--|-----------|---------|------|
| Reach | Lower | X Sec | 12 |
| Date | 9/28/2010 | Sta No. | 6+50 |

Histogram



Particle Size Distribution





BF 1
Crest Gage 1 on UT1.
(EMH&T, Inc. 7/19/07)



BF 2
Crest Gage 4 on Lower Bailey.
(EMH&T, Inc. 10/17/07)



BF 3
Crest Gage 1 on UT1.
(EMH&T, Inc. 9/21/09)



BF 4
Crest Gage 2 on Upper Bailey.
(EMH&T, Inc. 9/21/09)



BF 5
Crest Gage 3 on UT2.
(EMH&T, Inc. 9/21/09)



BF 6
Crest Gage 4 on Lower Bailey.
(EMH&T, Inc. 9/21/09)



BF 7
Crest Gage 4 on Lower Bailey.
(EMH&T, Inc. 09/28/10)



LEGEND

- High Concern
- Low Concern
- Bank Scour
- Aggradation

EMH&T
 Evans, Mechwart, Hambleton & Tilton, Inc.
 Engineers • Surveyors • Planners • Scientists
 5500 New Albany Road, Columbus, OH 43054
 Phone: 614.775.4500 Fax: 614.775.4800

BURKE COUNTY, NORTH CAROLINA
BAILEY FORK
 MONITORING
 APPENDIX B
 STREAM PROBLEM AREA PLAN VIEW – YEAR 4

Date: January, 2011
 Scale: 1" = 200'
 Job No: 2006-1626

\\OHDA1A01\Projects\20061626\20061626\Exhibits\Appendix A-B\Appendix B2 - No Krefs - 1.mxd - [C:\MSO10\src\MS\USGS\imgery\2009\1988_xx_NCDOT_Colorr\Burke\Burke.sld] - SavedBy: JRAMFR [1/13/2011 10:15:37 AM] - PlottedBy: JRAMFR [2/3/2011 8:58:53 AM]



SPA 1

**Scour hole on the right bank of Upper Bailey Fork near station 5+00.
(EMH&T, Inc. 9/18/10)**