

Monitoring Report MY04

**Sandy Bridge Restoration Site
DMS Contract 6400
DMS Project Number 96920**

**DWR #: 15-0414
USACE Action ID: 201500827
Rutherford County, North Carolina**



Prepared for:
NCDMS, 1652 Mail Service Center, Raleigh, NC 27699-1652

**Monitoring Data Collected: 2020
Date Submitted: December 2020**

Mitigation Project Name **Sandy Bridge Farm**
DMS ID **96920**
River Basin **Broad**
Cataloging Unit **03050105**
County **Rutherford**

USACE Action ID **2015-00827**
DWR Permit **2015-0414**
Date Project Instituted **4/10/2015**
Date Prepared **4/21/2020**
Stream/Wet. Service Area **Broad 03050105**

 9/21/2020

Signature & Date of Official Approving Credit Release

- 1 - For NCDMS, no credits are released during the first milestone
2 - For NCDMS projects, the initial credit release milestone occurs automatically when the as-built report (baseline monitoring report) has been made available to the IRT by posting it to the DMS portal, provided the following have been met:
1) Approved of Final Mitigation Plan
2) Recordation of the preservation mechanism, as well as a title opinion acceptable to the USACE covering the property.
3) Completion of all physical and biological improvements to the mitigation site pursuant to the mitigation plan.
4) Receipt of necessary DA permit authorization or written DA approval for projects where DA permit issuance is not required.
3 - A 10% reserve of credits is to be held back until the bankfull event performance standard has been met.

Credit Release Milestone	Cool Stream Credits						
	Scheduled Releases %	Proposed Releases %	Proposed Released #	Not Approved # Releases	Approved Credits	Anticipated Release Year	Actual Release Date
1 - Site Establishment	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2 - Year 0 / As-Built	30.00%	30.00%	487.800	0.000	487.800	2017	5/19/2017
3 - Year 1 Monitoring	10.00%	10.00%	162.600	0.000	162.600	2018	4/25/2018
4 - Year 2 Monitoring	10.00%	10.00%	162.600	0.000	162.600	2019	4/26/2019
5 - Year 3 Monitoring	10.00%	10.00%	162.600	0.000	162.600	2020	4/21/2020
6 - Year 4 Monitoring	5.00%					2021	
7 - Year 5 Monitoring	10.00%					2022	
8 - Year 6 Monitoring	5.00%					2023	
9 - Year 7 Monitoring	10.00%					2024	
Stream Bankfull Standard	10.00%	10.00%	162.600	0.000	162.600	2019	4/26/2019
			Totals		1,138.200		

Total Gross Credits	1,626.000
Total Unrealized Credits to Date	0.000
Total Released Credits to Date	1,138.200
Total Percentage Released	70.00%
Remaining Unreleased Credits	487.800

Credit Release Milestone	Riparian Credits						
	Scheduled Releases %	Proposed Releases %	Proposed Released #	Not Approved # Releases	Approved Credits	Anticipated Release Year	Actual Release Date
1 - Site Establishment	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2 - Year 0 / As-Built	30.00%	30.00%	1.996	0.000	1.996	2017	5/19/2017
3 - Year 1 Monitoring	10.00%	10.00%	0.665	0.000	0.665	2018	4/25/2018
4 - Year 2 Monitoring	10.00%	10.00%	0.665	0.000	0.665	2019	4/26/2019
5 - Year 3 Monitoring	15.00%	15.00%	0.998	0.000	0.998	2020	4/21/2020
6 - Year 4 Monitoring	5.00%					2021	
7 - Year 5 Monitoring	15.00%					2022	
8 - Year 6 Monitoring	5.00%					2023	
9 - Year 7 Monitoring	10.00%					2024	
Stream Bankfull Standard	N/A	N/A	N/A	N/A	N/A	N/A	N/A
			Totals		4.324		

Total Gross Credits	6.653
Total Unrealized Credits to Date	0.000
Total Released Credits to Date	4.324
Total Percentage Released	65.00%
Remaining Unreleased Credits	2.329

Mitigation Project Name Sandy Bridge Farm
 DMS ID 96920
 River Basin Broad
 Cataloging Unit 03050105
 County Rutherford

USACE Action ID 2015-00827
 DWR Permit 2015-0414
 Date Project Instituted 4/10/2015
 Date Prepared 4/21/2020
 Stream/Wet. Service Area Broad 03050105

Notes

Contingencies (if any)

Project Quantities

Mitigation Type	Restoration Type	Physical Quantity
Cool Stream	Restoration	1,626.000
Riparian	Restoration	6.850

Debits

Stream Restoration Credits	Riparian Restoration
----------------------------	----------------------

Beginning Balance (mitigation credits)							1,626.000	6.653
Released Credits							1,138.200	4.324
Unrealized Credits							0.000	0.000
Owning Program	Req. Id	TIP #	Project Name	USACE Permit #	DWR Permit #	DCM Permit #		
Statewide Stream & Wetland ILF Program	REQ-005154		Kings Mountain Quarry Expansion		2009-1301			1.996
Statewide Stream & Wetland ILF Program	REQ-005154		Kings Mountain Quarry Expansion		2009-1301			0.665
Statewide Stream & Wetland ILF Program	REQ-005154		Kings Mountain Quarry Expansion		2009-1301			0.665
Total Credits Debited							0.000	3.326
Remaining Available balance (Released credits)							1,138.200	0.998
Remaining balance (Unreleased credits)							487.800	2.329

Monitoring and Design Firm

Prepared by:



KCI Associates of North Carolina, PC
4505 Falls of Neuse Road
Suite 400
Raleigh, NC 27609
(919) 783-9214

Project Contact: Tim Morris
Email: tim.morris@kci.com

December 2020



February 2, 2021

Mr. Harry Tsomides
North Carolina Division of Mitigation Services
5 Ravenscroft Dr. #102
Asheville, NC 28801

Re: Response to Sandy Bridge Farm MY04 Report Comments

Dear Mr. Tsomides,

KCI has reviewed the comments prepared by the DMS for the Sandy Bridge Farm MY04 Report and has prepared the following responses:

1. Aggradation (attributed to beaver) is noted in the text as a site issue however the visual assessment table indicates 100% of the project performing as intended for the aggradation metric. Both pool cross sections (XS2 and XS4) are showing the pools with significant filling in. Please field-verify and quantify/update the visual assessment tables every year as appropriate.

KCI Response: The Visual Assessment Table and the CCPV have been updated to reflect the aggradation that is present on-site as a result of the beaver impoundments.

2. Please submit the features used to characterize the supplemental planting areas displayed in the CCPV.

Please submit photo point features attributed with unique ID's.

Please submit groundwater gauge features attributed with unique ID's.

Please submit vegetation plot features attributed with unique ID's.

KCI Response: These files have been added to the digital deliverables along with a shapefile characterizing the aggradation areas.

Please contact me if you have any questions or would like clarification concerning these responses.

Sincerely,

A handwritten signature in black ink, appearing to read 'Tim Morris'.

Tim Morris
Project Manager

TABLE OF CONTENTS

PROJECT SUMMARY	1
MONITORING RESULTS	2
REFERENCES	5
Figure 1. Project Site Vicinity Map	6
Figure 2. Site Asset Map.....	7

Appendix A – Background Tables

Table 1. Project Components and Mitigation Credits.....	9
Table 2. Project Activity and Reporting History	10
Table 3. Project Contacts	11
Table 4. Project Information	12

Appendix B – Visual Assessment Data

CCPV	15
Table 5. Visual Stream Morphology Stability Assessment	16
Table 6. Vegetation Condition Assessment	17
Photo Reference Points	18
Repair Area Photos	20

Appendix C – Stream Measurement and Geomorphology Data

Table 8. Baseline Stream Data Summary	22
Table 9. Cross-section Morphology Data Table	23
Cross-section Plots.....	24
Pebble Counts	28

Appendix D – Hydrologic Data

30-70 Percentile Graph	31
Table 10. Verification of Bankfull Events	32
Precipitation and Water Level Plots.....	35
Table 11. Wetland Hydrology Criteria Attainment.....	48

Appendix E – Additional Information

Replanting Species and Quantity	50
---------------------------------------	----

PROJECT SUMMARY

The Sandy Bridge Farm Restoration Site (SBFRS) was completed in March 2017 and restored a total of 6.85 acres of riparian wetland (1.29 acres of wetland rehabilitation and 5.56 acres of wetland reestablishment) and 1,626 linear feet of stream. The SBFRS is a riparian system located in the Broad River Basin (03050105 8-digit cataloging unit) in Rutherford County, North Carolina that had been substantially modified to maximize the use of the area for grazing. The completed project will restore impacted agricultural lands to a functioning stream and wetland ecosystem with enhanced water quality, restored hydrology, and improved fish and wildlife habitat.

The SBFRS is protected by a 9.5 acre permanent conservation easement, held by the State of North Carolina. The site is located off of Rock Road, approximately 3 miles north of Rutherfordton, North Carolina. The project site is bounded by interspersed pastureland and forested land to the east, agricultural land and Rock Road to the north-northwest, and Catheys Creek to the southwest.

The North Carolina Ecosystem Enhancement Program's (NCEEP) publication in 2009 identified HUC 03050105070020 (Catheys Creek) as a Targeted Local Watershed (TLW). The goals and priorities for SBRFS are based on the information presented in the Broad River Basin Restoration Priorities: to restore wetland and stream functions, to maintain and enhance water quality, to restore hydrology, and to improve fish and wildlife habitat (NCEEP 2009). The project goals, which reflect those from the approved Mitigation Plan, are in line with the following basin priorities:

- Reduce sources of sediment and nutrients by restoring riparian buffer vegetation, excluding livestock, and restoring natural geomorphology.
- Prioritize project implementation in the Catheys Creek local watershed planning area.

The goals for the project are to:

- Restore a channelized stream to a meandering C-type channel with a floodplain.
- Buffer and reduce sediment impacts to the project stream.
- Restore a Piedmont Alluvial Forest Community.
- Restore a wetland hydroperiod to drained and livestock-impacted land.

The project goals will be addressed through the following objectives:

- Relocate a channelized stream to its historic landscape position.
- Install an appropriately-sized channel cross-section.
- Install bedform diversity with pools, riffles, and habitat structures.
- Demarcate the project easement boundaries and fence out livestock.
- Plant the site with native trees and shrubs and an herbaceous seed mix that supports the development of a Piedmont Alluvial Forest.
- Fill field ditches and redevelop wetland microtopography to slow the flow of surface and subsurface drainage.

To restore the site, select ditches across the site were modified or filled and incoming surface inputs and seeps were integrated to create a stream/wetland complex. Additionally, Tributary 1 to Catheys Creek was improved with Priority 1 stream restoration to re-meander the stream and elevate the groundwater table. The entire site was planted as a Piedmont Alluvial Forest community (Schafale 2012). The site was constructed as designed with no modification from the design plan.

The majority of monitoring components were installed in March 2017. Nine groundwater monitoring gauges were installed to evaluate the attainment of jurisdictional wetland hydrology. A stream gauge was installed on Tributary 1 to Catheys Creek to record the occurrence of bankfull events. To determine the success of the planted mitigation areas, eight 10 m x 10 m permanent vegetation monitoring plots were established. The location of the planted stems relative to the origin within these plots, as well as the species, was recorded and planted stems were grouped into size categories (0-10 cm, 10-50 cm, 50-100 cm, >137 cm). Any volunteers found within the plots were also grouped into size categories by species, but separate from the planted stems. Six permanent photo reference points were established and will be taken annually. Four permanent cross-sections (two sets of coupled riffles and pools) were also established and a detailed longitudinal profile of the stream was taken. Wolman pebble counts were performed at both of the riffle cross-sections. The cross-section measurements will be repeated in future monitoring years, but the longitudinal profile will only be repeated if there are concerns about bed elevation adjustments. Reports will be submitted to DMS by the end of each monitoring year. During a site visit with the IRT on December 6, 2017, it was requested that KCI install three additional groundwater monitoring gauges and two additional vegetation plots. On March 30, 2018 the three additional groundwater monitoring gauges were installed along the area of the filled, pre-construction stream channel. On September 10, 2018, the two additional vegetation plots were installed near the southern end of the site. On March 27, 2020, a supplemental planting was completed on the site. 524 one-gallon size trees were planted in the wetland rehabilitation area and 1,875 bare root trees were planted in the central portion of the site and around the stream. The planting in the wetland rehabilitation area was done as a means of correcting a small area of low growth and vigor caused by heavy growth of herbaceous vegetation. The planting in the central portion of the site, however, was done simply as a preemptive attempt to mitigate damage done by the beavers. At this time KCI does not believe that the beavers represent a threat to the vegetative success of the site but is continuing to monitor their impact on the site.

Vegetative success criteria for the site is 320 woody stems/acre after three years, 260 woody stems/acre after five years, and 210 woody stems/acre after seven years. The baseline monitoring counted an average of 647 woody stems/acre. To meet the hydrologic success criteria, the upper 12 inches of the soil profile must have continuously saturated or inundated conditions for at least 10% of the growing season during normal weather conditions. The soil survey for Rutherford County estimates the growing season begins April 4 and ends November 6 (217 days), meaning the water table must be within 12 inches of the surface for at least 22 consecutive days during the growing season. A minimum of two bankfull events must also be recorded during the monitoring period. Bank height ratios should not exceed 1.2 and the entrenchment ratios should be 2.2 or greater. Visual assessments will also be used to identify problem areas.

MONITORING RESULTS

Vegetation monitoring did not take place during the fourth monitoring year, as stipulated in the mitigation plan. Overall the site is well vegetated despite the impact the beavers have had on the site. Many large, healthy trees (> 10 feet tall) are present throughout the site. Vegetation monitoring will resume in MY05.

Daily rainfall data were obtained from the NC State Climate Office for a local weather station in Rutherfordton, NC. In 2020 the months of January, February, April, May, July, August, September, October, and November experienced above average rainfall, while June experienced average rainfall. The month of March experienced below average rainfall for the site. Overall, the area experienced above average rainfall during the 2020 growing season. During the site's fourth growing season, ten of the twelve groundwater monitoring gauges had continuous saturation within 12 inches of the ground surface for 10% (22 days) or more of the 217 day growing season

(April 4 to November 6). Both of the two gauges that did not achieve the success criteria malfunctioned. One gauge continuously malfunctioned for the entire year, while the other only recorded a portion of the growing season. While these issues were thought to be fixed during the regular downloads this summer, they persisted and these gauges have been replaced so that we will have valid data in 2021. Even without the data from these two gauges, the fact that all of the other gauges met the hydrology criteria, we are confident that these parts of the site also met for 2020.

The stream gauge has recorded multiple bankfull events in each year since construction, including 6 bankfull events in 2020. This large number of bankfull events is the desired outcome for this project. A component of the stream design was to provide regular recharging of the riparian wetlands from overbank stream flows. In June 2018, several large beaver dams were discovered on site. Since then KCI has been continuously monitoring for further signs of beaver activity, trapping beavers on-site and removing dams when they are found. Dams were removed in August 2018, November 2018, June 2019, August 2019, October 2019, June 2020, and September 2020. In August 2020 KCI contracted with USDA APHIS-WS to provide ongoing beaver management. See Appendix B and Appendix D for more information.

Due to the presence of beavers on-site, there has been more aggradation in the stream channel than has been anticipated. KCI has been removing the beavers routinely, but when the dams are built sediment has deposited in the channel. Though not normally a part of monitoring year 4, the IRT requested that KCI conduct cross-section surveys in 2020 to monitor this situation. The fourth-year cross-section survey showed aggradation in the pool cross-sections (XS2 and 4) as well as aggradation on the banks of Cross-section 1. One of the beaver dams that was removed in June 2020 was located at the head of the riffle just below XS2. Another dam is located approximately 100 lf downstream from XS4. These dams had previously been removed in 2018 and 2019. During MY02, a mid-channel bar was recorded in the survey of XS2 as a result of backwater from the beaver dams. After the dams were removed, the sediment forming this bar washed through and it was no longer present during the MY03 survey. Due to the continued rebuilding of dams, the accumulated sediment did not have a chance to wash out of the channel in 2020. Over the next few years of monitoring we will continue to monitor this situation as we continue to remove beavers and beaver dams. It is believed that the sediment that has built up within the stream will wash out if given enough time after the removal of the beaver dams. It's important to note that even with the rebuilding of the dams, the stream flow has stayed within the restored channel and we have not seen any evidence of other channels forming in this system.


The monitored cross-section data have been calculated by adjusting the bankfull elevation to maintain the baseline bankfull area for each cross-section. A total cross-sectional metric has been added to the cross-section data to indicate the cross-sectional area below the baseline bankfull elevation. In instances where there has been some lateral aggradation and narrowing the data show the cross-section having a significantly higher bankfull width and higher width/depth ratio as compared to previous years. The comparison of cross-section plots between monitoring events illustrates that this change does not indicate a problematic change in cross-section condition. Future monitoring will show how the channel has adjusted to the varying backwater conditions and how the stream has processed the sediment from these events.


The right bank of the stream that flows along the easement's southern boundary had been experiencing significant erosion due to several areas of obstruction in the center of this channel that are diverting water into the banks. Although this stream is not part of the project, and is located outside of the easement bounds, the erosion on the right bank has encroached into the easement. In November 2019, KCI repaired and stabilize this area. This work involved removing

the mid-channel obstructions and sloping back the eroding bank. 150 live stakes were planted along this bank in March 2020. During this work, several farm gates that had become buried in the stream bank were removed and a small swale was dug to direct water into the site from fields adjacent to the eastern boundary of the site. This swale was designed to drain ponded conditions in these fields and dissipate the water throughout the wetlands on-site. See Appendix B for more information.

REFERENCES

- NCDENR, Ecosystem Enhancement Program. 2009. Broad River Basin Restoration Priorities 2009. Raleigh, NC. Last accessed 1/2016 at:
http://portal.ncdenr.org/c/document_library/get_file?uuid=705d1b58-cb91-451e-aa58-4ef128b1e5ab&groupId=60329
- NCDENR, Ecosystem Enhancement Program. 2014. NCDENR, Ecosystem Enhancement Program. 2014. Stream and Wetland Mitigation Monitoring Guidelines. Last accessed 1/2016 at:
http://portal.ncdenr.org/c/document_library/get_file?p_l_id=60409&folderId=18877169&name=DLFE-86604.pdf
- NCDENR, Ecosystem Enhancement Program. 2014. Stream and Wetland Mitigation Monitoring Guidelines. Last accessed 6/2015 at:
http://portal.ncdenr.org/c/document_library/get_file?p_l_id=60409&folderId=18877169&name=DLFE-86606.pdf
- NC Wetland Functional Assessment Team. 2010. NC Wetland Assessment Method (NC WAM)
User Manual, version 4.1. Last accessed 11/2012 at:
http://portal.ncdenr.org/c/document_library/get_file?uuid=76f3c58b-dab8-4960-ba43-45b7faf06f4c&groupId=38364
- Schafale, M.P. and A.S. Weakley. 2012. Guide to the Natural Communities of North Carolina:
Fourth Approximation. Natural Heritage Program, Division of Parks and Recreation, N.C. Department of Environment and Natural Resources. Raleigh, NC.





BMP

Catheys Creek

Tributary 2

-  Conservation Easement
-  Wetland Re-establishment (5.56 ac / 5.56 credits)
-  Wetland Rehabilitation-filled ditches (0.70 ac / 0.70 credits)
-  Wetland Rehabilitation (0.59 ac / 0.39 credits)
-  T1 - Priority 1 Restoration (1626 lf / 1,626 credits)
-  Other Streams

0 100 200
 Feet

SITE ASSET MAP
SANDY BRIDGE FARM RESTORATION SITE
RUTHERFORD COUNTY, NC



Source: NC Statewide
 Orthoimagery, 2015.

APPENDIX A

Background Tables

Table 1. Project Components and Mitigation Credits Sandy Bridge Farm Restoration Site, DMS Project #96920									
Mitigation Credits									
	Stream		Riparian Wetland		Non-riparian Wetland		Buffer	Nitrogen Nutrient Offset	Phosphorous Nutrient Offset
Type	R	RE	R	RE	R	RE			
Credits	1,626		6.65						
Project Components									
Project Component -or- Reach ID	Stationing/ Location	Existing Footage/ Acreage	Approach (PI, PII etc.)	Restoration -or- Restoration Equivalent	Restoration Footage/ Acreage	Mitigation Ratio	Credits		
Tributary 1	10+00 to 26+26	1,470 lf	PI	Restoration	1,626 lf	1:1	1,626		
Wetland Reestablishment				Restoration	5.56 ac	1:1	5.56		
Wetland Rehabilitation*		0.79 ac		Restoration	0.70 ac	1:1	0.70		
Wetland Rehabilitation		0.59 ac		Restoration	0.59 ac	1.5:1	0.39		
Component Summation									
Restoration Level	Stream (linear feet)	Riparian Wetlands (Acres)		Non-Riparian Wetlands (Acres)	Buffer (square feet)	Upland (Acres)			
		Riverine	Non-Riverine						
Restoration	1,626 lf								
Reestablishment		5.56 ac							
Rehabilitation		1.29 ac							
Enhancement									
Creation									
Preservation									
High Quality Preservation									

R= Restoration RE= Restoration Equivalent of Creation or Enhancement
 *=wetland rehabilitation associated with filled ditches

Table 2. Project Activity & Reporting History Sandy Bridge Farm Restoration Sites, DMS Project #96920		
Activity or Report	Data Collection Complete	Actual Completion or Delivery
Mitigation Plan		June 2016
Final Design - Construction Plans		June 2016
Construction Grading Completed		Aug 29, 2016
Planting Completed		March 11, 2017
Baseline Monitoring/Report	March 2017	April 2017
<i>Vegetation Monitoring</i>	<i>March 21, 2017</i>	
<i>Stream Survey</i>	<i>March 20, 2017</i>	
Year 1 Monitoring	November 2017	December 2017
<i>Vegetation Monitoring</i>	<i>October 26, 2017</i>	
<i>Stream Survey</i>	<i>November 6, 2017</i>	
Additional Groundwater Gauges Installed		March 30, 2018
Beaver Dam Removal		August 20, 2018
Additional Vegetation Plots Installed		September 10, 2018
Beaver Dam Removal		November 6, 2018
Year 2 Monitoring	November 2018	December 2018
<i>Vegetation Monitoring</i>	<i>September 10, 2018</i>	
<i>Stream Survey</i>	<i>XS1 and 2: June 28, 2018 XS3 and 4: September 11, 2018</i>	
Beaver Dam Removal		June 14, 2019
Beaver Dam Removal		August 8, 2019
Beaver Dam Removal		October 17, 2019
Non-project Reach Repair		November 21, 2019
Year 3 Monitoring	November 2019	December 2019
<i>Vegetation Monitoring</i>	<i>July 11, 2019</i>	
<i>Stream Survey</i>	<i>June 19, 2019</i>	
Supplemental Planting		March 27, 2020
Year 4 Monitoring	November 2020	December 2020
<i>Stream Survey</i>	<i>November 4, 2020</i>	
Beaver Dam Removal		June 12, 2020
Beaver Dam Removal		September 15, 2020


Table 3. Project Contacts Sandy Bridge Farm Restoration Sites, DMS Project #96920	
Design Firm	KCI Associates of North Carolina, PC 4505 Falls of Neuse Road Suite 400 Raleigh, NC 27609 Contact: Mr. Tim Morris Phone: (919) 278-2512 Fax: (919) 783-9266
Construction Contractor	KCI Environmental Technologies and Construction 4505 Falls of Neuse Road, Suite 400 Raleigh, NC 27609 Contact: Mr. Tim Morris Phone: (919) 278-2512
Planting Contractor	Conservation Services Inc. 1620 N. Delphine Ave. Waynesboro, VA 22980 Contact: Mr. David Coleman Phone: (540) 941-0067
Monitoring Performers	KCI Associates of North Carolina, PC 4505 Falls of Neuse Road Suite 400 Raleigh, NC 27609 Contact: Mr. Adam Spiller Phone: (919) 278-2514 Fax: (919) 783-9266

Table 4. Project Information Sandy Bridge Farm Restoration Site, DMS Project #96920			
Project Name	Sandy Bridge Farm Restoration Site		
County	Rutherford County		
Project Area (acres)	9.45 acres		
Project Coordinates (lat. and long.)	35.407997° N, -81.937000° W		
Project Watershed Summary Information			
Physiographic Province	Piedmont		
River Basin	Broad		
USGS Hydrologic Unit 8-digit	03050105	USGS Hydrologic Unit 14-digit	03050105070020
DWQ Sub-basin	9-41-13-(0.5)		
Project Drainage Area (acres)	837 acres		
Project Drainage Area Percentage of Impervious Area	8%		
CGIA Land Use Classification	Mixed Hardwoods/Conifers 42% (350.0 ac), Managed Herbaceous Cover 39% (329.3 ac), Mountain Conifers 12% (99.5 ac), Mixed Shrubland 5% (43.5 ac), Low Intensity Developed 1% (11.0 ac)		
Existing Reach Summary Information			
Parameters	T1		
Length of reach (linear feet)	1,470 lf		
Valley classification	Valley Type VIII		
Drainage area (acres)	837 acres		
NCDWQ Water Quality Classification	WS-V (Water Supply – upstream)		
Morphological Description (stream type)	Ditched channel		
Evolutionary trend	Channelized		
Mapped Soil Series	Wehadkee-Chewacla Association		
Drainage class	Poorly drained; Somewhat poorly drained		
Soil Hydric status	Drained hydric		
Slope	0-1%		
FEMA classification	Zone AE		
Existing vegetation community	N/A (Pasture)		
Percent composition of exotic invasive vegetation	5%		
Existing Wetland Summary Information			
Parameters			
Size of Wetland (acres)	0.59 acres (Wetland Rehabilitation Area)		
Wetland Type	Headwater Seep		
Mapped Soil Series	Wehadkee-Chewacla Association		
Drainage class	Poorly drained; Somewhat poorly drained		
Soil Hydric Status	Drained Hydric		
Source of Hydrology	Seepage/ Precipitation		
Hydrologic Impairment	Ditching and Grazing		
Existing vegetation community	Emergent Wetland		
Percent composition of exotic invasive vegetation	5%		

Regulatory Considerations			
Regulation	Applicable?	Resolved?	Supporting Documentation
Waters of the United States – Section 404	Yes	DWR# 15-0414 USACE Action ID# 201500827	Jurisdictional Determination
Waters of the United States – Section 401	Yes	DWR# 15-0414 USACE Action ID# 201500827	Jurisdictional Determination
Endangered Species Act	No	N/A	N/A
Historic Preservation Act	No	N/A	N/A
Coastal Zone Management Act (CZMA)/ Coastal Area Management Act (CAMA)	No	N/A	N/A
FEMA Floodplain Compliance	No	N/A	N/A
Essential Fisheries Habitat	No	N/A	N/A

APPENDIX B

Visual Assessment Data



LEGEND:

- VEG PLOT ACHIEVING DENSITY CRITERION - - - - -
- VEG PLOT BELOW DENSITY CRITERION - - - - -
- VEG PLOT TOTAL / PLANTED STEM DENSITY - - - - - 703/526
- WETLAND GAUGE ACHIEVING HYDRO. CRITERION - - - - - +
- WETLAND GAUGE BELOW HYDRO. CRITERION - - - - - +
- PHOTO POINT - - - - - ⊕
- CROSS-SECTION - - - - - —|—
- CONSERVATION EASEMENT - - - - -
- STREAM RESTORATION - - - - -
- REMOVED BEAVER DAMS - - - - -
- WETLAND REESTABLISHMENT - - - - -
- WETLAND REHABILITATION - - - - -
- STEP POOL - - - - -
- RIFFLE GRADE CONTROL - - - - -
- RIFFLE ENHANCEMENT - - - - -
- STREAM AGGRADATION - - - - -

*VEG DATA FROM MY03 (2019)
IMAGE SOURCE: GOOGLE EARTH 2017


NO.	DESCRIPTION	DATE

NCDEQ DIVISION OF
 MITIGATION SERVICES

KCI
ASSOCIATES OF NC
 ENGINEERS • PLANNERS • SCIENTISTS
4505 FALLS OF NEUSE RD, SUITE 400
 RALEIGH, NORTH CAROLINA 27609

SANDY BRIDGE FARM
 STREAM AND RIPARIAN WETLAND SITE
DMS PROJECT #98920
 RUTHERFORD COUNTY, NORTH CAROLINA

MONITORING YEAR 04



EROSION ALONG RIGHT BANK OF NON-CREDIT STREAM REPAIRED 2019-11-21

Table 5 Visual Stream Morphology Stability Assessment
 Sandy Bridge Farm Stream Restoration Site, DMS Project#96920
 Reach ID Reach 1
 Assessed Length 1626

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended
1. Bed	1. Vertical Stability (Riffle and Run units)	1. <u>Aggradation</u> - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			15	544	67%
		2. <u>Degradation</u> - Evidence of downcutting			0	0	100%
	2. Riffle Condition	1. <u>Texture/Substrate</u> - Riffle maintains coarser substrate	20	20			100%
		3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth \geq 1.6)	20	20		
	4. Thalweg Position	2. <u>Length</u> appropriate (>30% of centerline distance between tail of upstream riffle and head of downstream riffle)	20	20			100%
		1. Thalweg centering at upstream of meander bend (Run)	20	20			100%
		2. Thalweg centering at downstream of meander (Glide)	20	20			100%
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%
Totals					0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	8	8			100%
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	8	8			100%
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	5	5			100%
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	6	6			100%
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio \geq 1.6 Rootwads/logs providing some cover at base-flow.	5	5			100%

Table 6 **Vegetation Condition Assessment**
Sandy Bridge Farm Stream Restoration Site, DMS Project# 96920
Planted Acreage 9.5

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Planted Acreage
1. Bare Areas	Very limited cover of both woody and herbaceous material.	0.1 acres	Pattern and Color	0	0.00	0.0%
2. Low Stem Density Areas	Woody stem densities clearly below target levels based on MY3, 4, or 5 stem count criteria.	0.1 acres	Pattern and Color	0	0.00	0.0%
Total				0	0.00	0.0%
3. Areas of Poor Growth Rates or Vigor	Areas with woody stems of a size class that are obviously small given the monitoring year.	0.25 acres	Pattern and Color	0	0.00	0.0%
Cumulative Total				0	0.00	0.0%
Easement Acreage 9.5						
Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Easement Acreage
4. Invasive Areas of Concern	Areas or points (if too small to render as polygons at map scale).	1000 SF	Pattern and Color	0	0.00	0.0%
5. Easement Encroachment Areas	Areas or points (if too small to render as polygons at map scale).	none	Pattern and Color	0	0.00	0.0%

Photo Reference Photos



PP1 – MY-00 – 3/21/17



PP1 – MY-04 – 12/15/20



PP2 – MY-00 – 3/21/17



PP2 – MY-04 – 12/15/20



PP3 – MY-00 – 3/21/17



PP3 – MY-04 – 12/15/20



PP4 – MY-00 – 3/21/17



PP4 – MY-04 – 12/15/20



PP5– MY-00 – 3/21/17



PP5– MY-04 – 12/15/20



PP6– MY-00 – 3/21/17



PP6– MY-04 – 12/15/20

Repair Area Photos



8/28/18 – Before repair



3/30/18 – Before repair



11/21/19 – Immediately after repair



12/15/20 – One year after repair



12/15/20 – One year after repair

APPENDIX C

Stream Measurement and Geomorphology Data

Table 8. Baseline Stream Data Summary																
Sandy Bridge Farm Stream Restoration Site, DMS Project #96920																
Parameter	Pre-Existing Condition					Reference Reach(es) Data					Design	As-built				
Dimension - Riffle	Min	Mean	Med	Max	n	Min	Mean	Med	Max	n	Proposed	Min	Mean	Max	n	
Bankfull Width (ft)	31.5	32.9	330	34.0	4	14.8	16.7		18.6	2	15.0	15.4	17.2	18.9	2	
Floodprone Width (ft)	60.9	72.9	69.3	92.0	4	>40	>47		>55	2	>38	>60	>68	>70	2	
Bankfull Mean Depth (ft)	2.1	2.2	2.2	2.5	4	1.3	1.5		1.7	2	0.9	0.7	0.8	0.9	2	
Bankfull Max Depth (ft)	3.1	3.4	3.4	3.7	4	1.9	2.2		2.4	2	1.3	1.5	1.5	1.5	2	
Bankfull Cross-Sectional Area (ft ²)	66.6	73.2	71.2	84.0	4	25.0	25.1		25.1	2	12.7	13.2	13.5	13.8	2	
Width/Depth Ratio	13.5	14.8	14.9	16.0	4	8.8	11.3		13.8	2	17.7	17.3	22.1	27.0	2	
Entrenchment Ratio	1.9	2.2	2.2	2.7	4	>2.5	>2.5		>2.5	2	>2.5	3.8	4.0	4.1	2	
Bank Height Ratio	1.1	1.4	1.3	1.7	4	1.2	1.4		1.5	2	1.0	1.0	1.0	1.0	2	
Pattern																
Channel Beltwidth (ft)						60				1	35-60	35		60	2	
Radius of Curvature (ft)						16			87	1	30-50	30		50	2	
Rc:Bankfull width (ft/ft)						0.9			5.9	1	2.0-3.3	2.0		3.3	2	
Meander Wavelength (ft)						66			191	1	134-160	134		160	2	
Meander Width Ratio						4.1				1	8.9-10.7	8.9		10.7	2	
Riffle Length (ft)												23	40	56	20	
Riffle Slope (ft/ft)	0.000			0.010	2	0.013			0.035	2	0.002-0.008	0.000	0.006	0.014	20	
Pool Length (ft)	*					14			33	2	17-55	11	22	39	20	
Pool Spacing (ft)	*					50			105	2	55-90	25.9	78.3	102.2	19	
Substrate and Transport Parameters																
SC% / Sa% / G% / C% / B% / Be%	18%/39%/43%/1%/0%/0%										66%/2%/22%/10%/1%/0%					
d16 / d35 / d50 / d84 / d95 (mm)	0.076/1.2/3.3/5.2/9.4/18										0.062/0.5/17.5/25.5/40/90					
Channel length (ft)	1,470										1,626	1,626				
Drainage Area (SM)	1.31					1.49					1.31	1.31				
Rosgen Classification	E4-G4					C4					C4	C4				
Sinuosity	1.0					1.3					1.2	1.2				
Water Surface Slope (ft/ft)	0.0043					0.0050					0.0038	0.0027				

*No data shown due to channelization/lack of bed diversity

Table 9. Cross-Section Morphology Data Tables														
Sandy Bridge Farm Stream Restoration Site, DMS Project #96920														
Dimension and Substrate	Cross-Section 1 (Riffle) Station 14+75							Cross-Section 2 (Pool) Station 16+40						
	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Bankfull Elevation	866.7	866.9	867.3	867.4	867.9			866.7	866.7	867.5	867.7	868.2		
Bankfull Width (ft)	15.4	15.7	18.1	13.8	9.9			18.8	19.6	18.6	21.0	13.6		
Floodprone Width (ft)	>80	>80	>80	>80	>80			-	-	-	-	-		
Bankfull Mean Depth (ft)	0.9	0.9	0.8	1.0	1.4			1.4	1.4	1.4	1.3	2.0		
Bankfull Max Depth (ft)	1.5	1.7	2.0	2.1	2.2			2.7	2.7	2.2	2.7	2.4		
Bankfull Cross-Sectional Area (ft ²)	13.8	13.8	13.8	13.8	13.8			26.8	26.8	26.8	26.8	26.8		
Total Cross-Sectional Area (ft ²)	13.8	10.9	7.2	7.1	4.8			26.8	26.2	12.9	10.9	7.4		
Bankfull Width/Depth Ratio	17.3	17.9	23.6	13.4	7.1			-	-	-	-	-		
Bankfull Entrenchment Ratio	4.1	5.1	4.4	5.9	6.9			-	-	-	-	-		
Bankfull Bank Height Ratio	1.0	1.0	0.8	0.8	1.0			-	-	-	-	-		
d50 (mm)	35	26	0.7	0.6	4.4			-	-	-	-	-		
Dimension and Substrate	Cross-Section 3 (Riffle) Station 101+73							Cross-Section 4 (Pool) Station 105+67						
	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Bankfull Elevation	865.3	865.3	865.2	865.2	865.2			865.3	865.16	865.1	865.4	865.6		
Bankfull Width (ft)	15.7	17.3	15.4	16.7	16.2			18.7	18.1	17.1	20.4	35.1		
Floodprone Width (ft)	>70	>70	>70	>70	>70			-	-	-	-	-		
Bankfull Mean Depth (ft)	0.8	0.8	0.9	0.8	0.8			1.5	1.6	1.7	1.4	0.8		
Bankfull Max Depth (ft)	1.5	1.6	1.6	1.7	1.7			3.0	3.1	3.0	1.9	1.6		
Bankfull Cross-Sectional Area (ft ²)	13.1	13.1	13.1	13.1	13.1			28.8	28.8	28.8	28.8	28.8		
Total Cross-Sectional Area (ft ²)	13.1	12.4	15.1	15.1	14.4			28.8	30.7	32.1	20.7	17.8		
Bankfull Width/Depth Ratio	18.8	22.8	18.0	19.7	20.0			-	-	-	-	-		
Bankfull Entrenchment Ratio	4.6	4.2	4.7	4.5	4.5			-	-	-	-	-		
Bankfull Bank Height Ratio	1.0	1.0	1.0	0.9	1.0			-	-	-	-	-		
d50 (mm)	0.062	0.062	0.062	0.062	0.52			-	-	-	-	-		

Calculations are based on a fixed bankfull area established during the baseline survey, and the resulting bankfull elevation. Total Cross-Sectional Area represents the cross-sectional area measured from the baseline bankfull elevation.


Cross-Section Plots

River Basin:	Broad
Site:	Sandy Bridge
XS ID	XS1
Drainage Area:	837 acres
Date:	11/4/2020
Field Crew:	T. Seelinger, A. Gutierrez



Station	Elevation
0.0	868.59
0.3	868.31
1.5	868.33
4.5	868.55
9.5	868.53
14.3	868.46
18.5	868.61
19.4	868.59
22.2	868.09
25.5	868.02
28.5	867.69
33.5	867.98
35.4	867.87
36.7	867.85
37.5	867.46
38.3	867.04
38.6	866.51
39.7	866.27
40.5	865.89
41.1	865.87
42.2	865.69
43.2	865.70
44.4	866.17
45.0	866.19
45.3	867.02
45.8	867.57
46.8	867.93
48.1	868.06
50.1	868.07
52.0	867.91
53.29	867.79
55.10	868.23
57.67	867.67
59.35	868.20
61.17	868.25
63.98	868.39
66.81	868.31
69.95	868.17
73.36	868.16
76.43	867.97

SUMMARY DATA	
Current Bankfull Elevation:	867.87
Bankfull Cross-Sectional Area:	13.8
Total Cross-Sectional Area:	4.8
Bankfull Width:	9.9
Flood Prone Area Elevation:	870.0
Flood Prone Width:	67.9
Max Depth at Bankfull:	2.2
Mean Depth at Bankfull:	1.4
W / D Ratio:	7.1
Entrenchment Ratio:	6.9
Bank Height Ratio:	1.0




Cross-Section Plots

River Basin:	Broad
Site:	Sandy Bridge
XS ID	XS2
Drainage Area:	837 acres
Date:	11/4/2020
Field Crew:	T. Seelinger, A. Gutierrez



Station	Elevation	Station	Elevation	SUMMARY DATA	
0.0	868.47	70.8	868.01	Current Bankfull Elevation:	868.20
0.3	868.10	72.3	867.86	Bankfull Cross-Sectional Area:	26.8
3.5	868.02	75.8	867.62	Total Cross-Sectional Area:	7.4
8.2	868.08	77.8	867.90	Bankfull Width:	13.6
13.8	868.04	80.7	867.86	Flood Prone Area Elevation:	---
18.1	868.10	83.6	867.65	Flood Prone Width:	---
19.5	867.91	83.6	867.90	Max Depth at Bankfull:	2.4
21.8	867.41			Mean Depth at Bankfull:	2.0
24.2	867.24			W / D Ratio:	---
27.0	867.59			Entrenchment Ratio:	---
30.2	867.58			Bank Height Ratio:	---
31.8	867.68				
33.3	867.77				
33.9	867.75				
34.7	867.24				
35.0	866.33				
36.1	865.82				
37.4	865.88				
37.9	865.96				
39.8	865.84				
41.2	865.99				
42.1	866.04				
43.1	865.86				
44.1	866.10				
45.1	866.14				
45.9	866.39				
46.3	866.97				
47.0	867.28				
47.6	867.65				
48.3	867.65				
50.2	867.67				
52.3	867.96				
55.6	867.79				
58.9	867.65				
59.59	866.98				
60.86	866.91				
62.78	867.06				
64.45	867.56				
65.35	867.93				
66.76	868.45				
68.49	868.01				




Cross-Section Plots

River Basin:	Broad
Site:	Sandy Bridge
XS ID	XS3
Drainage Area:	837 acres
Date:	11/4/2020
Field Crew:	T. Seelinger, A. Gutierrez



Station	Elevation
0.0	866.34
0.2	865.89
1.1	865.34
2.8	865.58
4.6	865.59
9.0	865.44
12.1	865.37
17.0	865.34
19.8	865.34
22.0	865.12
25.4	865.03
28.3	865.03
28.8	865.28
30.1	865.27
32.0	864.99
33.9	864.77
34.9	864.60
35.7	864.05
37.0	863.72
37.7	863.71
38.3	863.84
39.0	863.88
40.0	863.53
40.8	863.59
41.8	863.91
42.7	864.50
43.2	865.00
44.87	864.81
46.68	865.11
48.83	865.27
52.60	865.48
54.78	865.23
57.60	865.63
62.30	865.37
68.01	865.32
72.47	865.22
72.39	865.58

SUMMARY DATA	
Current Bankfull Elevation:	865.22
Bankfull Cross-Sectional Area:	13.1
Total Cross-Sectional Area:	14.4
Bankfull Width:	16.2
Flood Prone Area Elevation:	866.9
Flood Prone Width:	72.4
Max Depth at Bankfull:	1.7
Mean Depth at Bankfull:	0.8
W / D Ratio:	20.0
Entrenchment Ratio:	4.5
Bank Height Ratio:	1.0




Cross-Section Plots

River Basin:	Broad
Site:	Sandy Bridge
XS ID	XS4
Drainage Area:	837 acres
Date:	11/4/2020
Field Crew:	T. Seelinger, A. Gutierrez




Station	Elevation
0.0	865.79
0.0	865.37
2.8	865.46
6.9	865.55
9.1	865.28
11.7	865.24
16.8	865.42
20.3	865.29
24.0	865.11
27.1	865.04
30.8	865.09
32.9	864.96
34.7	864.91
36.7	864.50
38.9	864.42
39.9	864.22
41.3	864.06
42.6	864.04
43.8	863.98
44.8	864.29
45.9	864.16
47.4	864.02
48.6	864.12
49.1	864.47
49.9	864.96
51.1	865.21
52.07	865.64
52.75	865.61
55.30	865.64
59.55	865.37
63.67	865.22
67.88	865.22
71.66	865.33

SUMMARY DATA	
Current Bankfull Elevation:	865.59
Bankfull Cross-Sectional Area:	28.8
Total Cross-Sectional Area:	17.8
Bankfull Width:	35.1
Flood Prone Area Elevation:	---
Flood Prone Width:	---
Max Depth at Bankfull:	1.6
Mean Depth at Bankfull:	0.8
W / D Ratio:	---
Entrenchment Ratio:	---
Bank Height Ratio:	---



Cross-Section 1 Riffle - MY-04			
Particle	Millimeter		Count
Silt/Clay	< 0.062	S/C	
Very Fine	.062 - .125	S	
Fine	.125 - .25	A	8
Medium	.25 - .50	N	12
Coarse	.50 - 1	D	10
Very Coarse	1 - 2	S	14
Very Fine	2 - 4		9
Fine	4 - 5.7	G	2
Fine	5.7 - 8	R	4
Medium	8 - 11.3	A	4
Medium	11.3 - 16	V	13
Coarse	16 - 22.6	E	14
Coarse	22.6 - 32	L	4
Very Coarse	32 - 45	S	4
Very Coarse	45 - 64		4
Small	64 - 90	C	1
Small	90 - 128	O	3
Large	128 - 180	B	1
Large	180 - 256	L	
Small	256 - 362	B	
Small	362 - 512	L	
Medium	512 - 1024	D	
Lrg- Very Lrg	1024 - 2048	R	
Bedrock	>2048	BDRK	
		Total	107
Note:			




Size (mm)	
D16	0.42
D35	1.4
D50	4.4
D65	13
D84	22
D95	62

Size Distribution	
mean	3.0
dispersion	7.7
skewness	-0.12

Type	
silt/clay	0%
sand	41%
gravel	54%
cobble	5%
boulder	0%
bedrock	0%
hardpan	0%
wood/det	0%
artificial	0%

Cross-Section 3 Riffle - MY-04			
Particle	Millimeter		Count
Silt/Clay	< 0.062	S/C	38
Very Fine	.062 - .125	S	
Fine	.125 - .25	A	2
Medium	.25 - .50	N	14
Coarse	.50 - 1	D	26
Very Coarse	1 - 2	S	25
Very Fine	2 - 4		6
Fine	4 - 5.7	G	
Fine	5.7 - 8	R	
Medium	8 - 11.3	A	
Medium	11.3 - 16	V	
Coarse	16 - 22.6	E	
Coarse	22.6 - 32	L	
Very Coarse	32 - 45	S	
Very Coarse	45 - 64		
Small	64 - 90	C	
Small	90 - 128	O	
Large	128 - 180	B	
Large	180 - 256	L	
Small	256 - 362	B	
Small	362 - 512	L	
Medium	512 - 1024	D	
Lrg- Very Lrg	1024 - 2048	R	
Bedrock	>2048	BDRK	
		Total	111
Note:			



Size (mm)	
D16	0.062
D35	0.17
D50	0.52
D65	0.81
D84	1.4
D95	2.1


Size Distribution	
mean	0.3
dispersion	5.5
skewness	-0.21

Type	
silt/clay	34%
sand	60%
gravel	5%
cobble	0%
boulder	0%
bedrock	0%
hardpan	0%
wood/det	0%
artificial	0%

APPENDIX D

Hydrologic Data

**Sandy Bridge Farm Restoration Site
30-70 Percentile Graph
WETS Station Name: Lake Lure 2, NC**



**Table 10. Verification of Bankfull Events
Sandy Bridge Farm Restoration Site, DMS Project #96920**

Date of Occurrence	Method	Photo Number
April 6, 2017	Onsite stream gauge	
April 24, 2017	Onsite stream gauge	
May 29, 2017	Onsite stream gauge	
August 3, 2017	Onsite stream gauge	
August 14, 2017	Onsite stream gauge	
August 15, 2017	Onsite stream gauge	
September 5, 2017	Onsite stream gauge	
October 23, 2017	Onsite stream gauge, photos taken on site	1
February 7, 2018	Onsite stream gauge, photos taken on site	2
February 11, 2018	Onsite stream gauge	
April 15, 2018	Onsite stream gauge	
April 24, 2018	Onsite stream gauge	
May 19, 2018	Onsite stream gauge	
May 30, 2018	Onsite stream gauge	
September 16, 2018	Onsite stream gauge	
October 11, 2018	Onsite stream gauge, photos taken on site	3
January 4, 2019	Onsite stream gauge	
January 20, 2019	Onsite stream gauge	
January 24, 2019	Onsite stream gauge	
February 18, 2019	Onsite stream gauge	
February 21, 2019	Onsite stream gauge	
February 22, 2019	Onsite stream gauge	
April 8, 2019	Onsite stream gauge	
May 11, 2019	Onsite stream gauge	
June 18, 2019	Onsite stream gauge	
October 31, 2019	Onsite stream gauge	
January 12, 2020	Onsite stream gauge	
January 24, 2020	Onsite stream gauge	
February 6, 2020	Onsite stream gauge	
February 13, 2020	Onsite stream gauge	
March 25, 2020	Onsite stream gauge	
April 13, 2020	Onsite stream gauge	




Photo 1. Sediment on plants and wrack lines above bankfull, 10/26/2017




Photo 2. Bankfull event on site, 2/7/2018




Photo 3. Wrack lines above bankfull, 11/7/2018


Sandy Bridge Farm Restoration Site Hydrograph Stream Gauge




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 1




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 2




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 3




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 4




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 5




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 6





Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 7




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 8




Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 9





Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 10



Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 11



Sandy Bridge Farm Restoration Site Hydrograph Wetland Gauge 12



**Table 11. Wetland Hydrology Criteria Attainment
Sandy Bridge Farm Restoration Site, DMS Project #96920**

	Greater than 10% Continuous Saturation/Max Consecutive Days During Growing Season (Percentage)						
Gauge #	MY-01 2017	MY-02 2018	MY-03 2019	MY-04 2020	MY-05 2021	MY-06 2022	MY-07 2023
Gauge 1	Yes/30 (13.8%)	Yes/40 (18.4%)	Yes/46 (21.2%)	Yes/215 (99.1%)			
Gauge 2	No/11 (5.1%)	Yes/35 (16.1%)	Yes/32 (14.7%)	Yes/126 (58.1%)			
Gauge 3	Yes/110 (50.7%)	Yes/78 (35.9%)	Yes/162 (74.7%)	Yes/158 (72.8%)			
Gauge 4	Yes/47 (21.7%)	Yes/105 (48.4%)	Yes/156 (71.9%)	Yes/158 (72.8%)			
Gauge 5	No/11 (5.1%)	Gauge malfunction	Yes/44 (20.3%)	Yes/158 (72.8%)			
Gauge 6	Yes/30 (13.8%)	Yes/63 (29.0%)	Yes/49 (22.6%)	Yes/209 (96.3%)			
Gauge 7	Yes/22 (10.1%)	Yes/105 (48.4%)	Yes/162 (74.7%)	Yes/214 (98.6%)			
Gauge 8	Yes/29 (13.4%)	Yes/43 (19.8%)	Yes/39 (18.0%)	Yes/209 (96.3%)			
Gauge 9	No/15 (6.9%)	Yes/87 (40.1%)	Yes/40 (18.4%)	Yes/197 (90.8%)			
Gauge 10*		No/8 (3.7%)	Yes/22 (10.1%)	Gauge malfunction			
Gauge 11*		No/8 (3.7%)	Yes/25 (11.5%)	Gauge malfunction			
Gauge 12*		Yes/38 (17.5%)	Yes/24 (11.1%)	Yes/217 (100%)			

*=Gauge installed March 30, 2018

APPENDIX E

Additional Information

Sandy Bridge Replant - Rutherfordton, NC

Near Veg Plots 7 & 8 (0.77 acres) 0.77 ac **524** trees

Gallon Trees 8' x 8' (681 trees/ac)

Very Wet

Bald Cypress	30%	157
Red Chokeberry	20%	105
Silky Dogwood	20%	105

Fringe

River Birch	10%	52
American Sycamore	10%	52
Cottonwood	<u>10%</u>	<u>52</u>
	100%	524

Central Site and along stream (4.3 acres) 4.3 ac **1875** trees

Bareroot Trees 10' x 10' (436 trees/ac)

Cottonwood	20%	375
American Sycamore	15%	281
River Birch	15%	281
Silky Dogwood	15%	281
Cherrybark Oak	10%	187
American Elm	10%	187
Swamp Chestnut Oak	10%	187
Sugarberry	<u>5%</u>	<u>94</u>
	100%	1875

150 Livestakes on repair area and adjacent bank **150**

Black Willow	33.3%	50
Silky Willow	33.3%	50
Silky Dogwood	<u>33.3%</u>	<u>50</u>
	100.0%	150