

**SUCK CREEK STREAM RESTORATION
(Project No. 0117950008)**

MONITORING YEAR 3 of 5 (2006)

Submitted

January 2007



Submitted to:

North Carolina Department of Environment and Natural Resources
Ecosystem Enhancement Program
Raleigh, North Carolina



TABLE OF CONTENTS

- I. Executive Summary..... 1
- II. Project Background 2
 - 1. Project Objectives 2
 - 2. Project Structure, Restoration Type, and Approach 2
 - 3. Location and Setting 3
 - 4. Project History and Background 5
 - 5. Monitoring Plan View 6
- III. Project Condition and Monitoring Results..... 10
 - A. Vegetation Assessment 10
 - 1. Vegetative Problem Areas..... 10
 - 2. Vegetative Problem Area Plan View 10
 - 3. Stem Counts 10
 - B. Stream Assessment..... 16
 - 1. Procedural Items..... 16
 - 2. Hydrologic Criteria 16
 - 3. Stream Problem Areas Plan View..... 16
 - 4. Stream Problem Areas Table 16
 - 5. Number Issue Photos Section 17
 - 6. Fixed Station Photos 17
 - 7. Stability Assessment 17
 - 8. Quantitative Measures Summary Tables 18
- IV. Methodology Section..... 22

Figures

- Figure 1: Site Vicinity Map 4
- Figure 2: Monitoring Plan 7 – 9

TABLE OF CONTENTS (continued)

Tables

Table I:	Project Mitigation Objectives Table.....	3
Table II.	Project Activity and Reporting History	5
Table III.	Project Contact Table	5
Table IV.	Project Background Table	6
Table V.	Stem Counts for Each Species Arranged by Plot and Location – Based on Data collected Using the EEP Stem Counting Protocol	15
Table VIa.	Categorical Stream Feature Visual Stability Assessment – Upper Reach.....	17
Table VIb.	Categorical Stream Feature Visual Stability Assessment – Lower Reach	17
Table VII.	Baseline Morphology and Hydraulic Summary	19
Table VIII.	Morphology and Hydraulic Monitoring Summary	20 - 21

Appendices

Appendix A

1. Vegetation Data Tables
2. Vegetation Problem Area Photos
3. Vegetation Monitoring Plot Photos

Appendix B

1. Stream Gauge Data
2. Problem Areas Plan View (Stream)
3. Table B.1 Stream Problem Areas
4. Representative Stream Problem Area Photos
5. Stream Photo-Station Photos
6. Table B.2. Qualitative Visual Stability Assessment
7. Cross Section Plots and Raw Data Tables
8. Longitudinal Plots and Raw Data Tables
9. Pebble Count Plots and Raw Data Tables

I. Executive Summary

The objective of the Suck Creek stream restoration project, implemented in 2003, was to restore an unstable, degraded stream corridor and adjacent riparian zones to a stable condition that supports high quality in-stream and riparian habitat. The design integrated design goals with site constraints, such as the need to maintain access to surrounding cattle pastures, and the requirements of local agencies, such as ensuring public safety. Design elements included: (1) constructing 3,260 feet of channel with a stable dimension, pattern and profile; (2) installing in-stream structures such as log vanes, J-hook vanes, cross vanes, root wads, and boulder clusters; (3) planting the stream banks and adjacent 7.8 acres of riparian buffer with native plant species; (4) installing fencing to exclude cattle from the restored area; and (5) creating stable road crossings to allow access to adjacent pasture lands. Construction was completed in April 2003, the as-built survey was completed June 2003, and the riparian buffer was planted in February 2004. Year 1 Monitoring was conducted in October 2004. Year 2 monitoring was conducted in September 2005. The Year 3 monitoring provided in this report was conducted in August 2006.

The stream restoration component of the project involved implementing a Priority I Restoration method to create a more stable C4 stream type. Based on the findings of the 2006 monitoring effort summarized in this report, the restored reaches are predominantly stable. Localized areas of bank erosion and bed aggradation in the form of mid-channel bars were observed within the restored channel. Cross vane structures are functioning properly or have reduced function but structure repairs are not recommended at this time. The majority of cross vane structures are functioning properly; maintenance is recommended for only two of the vanes. All of the log vane structures are functioning adequately. The mean particle size of mobile sediment in the upper reach has decreased (from $D_{50} = 7.3$ mm. to $D_{50} = 0.7$ mm). The mean particle size of mobile sediment in the lower reach has not significantly changed. An extensive mid-channel bar has continued to form just downstream of the boulder field in the upper reach.

Vegetation representing local riparian communities was planted to provide additional stability to the stream banks and establish a riparian buffer. The planted riparian vegetation onsite is well established on the stream banks and in the riparian corridor. Total cover by herbaceous plants is 99 percent. Predominant species are tall wormwood (*Artemisia caudata*) and whorled coreopsis (*Coreopsis verticillata*). Woody stem growth is most dense on the stream bank and becomes sparse in outlying riparian areas. Volunteer black willow and river birch root sucker stems account for the majority of woody stems. The woody stem density for the riparian buffer exceeds the success criteria of 260 stems/acre.

There is no wetland component to this mitigation site.

II. Project Background

1. Project Objectives

The goal of the project was to transform the pre-existing altered stream corridor to a more stable and biologically active form through the following objectives:

- Restore 3,260-linear feet of Suck Creek through geomorphic modification through dimension, pattern and profile adjustments, and cattle exclusion;
- Establish a riparian zone (7.8 acres) surrounding restored sections of Suck Creek;
- Improve the habitat within the channel and riparian zone;
- Provide cattle exclusion fencing and controlled crossings to protect restoration effort; and
- Provide perpetual protection of the riparian area and stream with a conservation easement.

2. Project Structure, Restoration Type, and Approach

The pre-restoration channel was incised with unstable banks. Using reference data from regional curves and appropriate reference reaches, the channel geometry was modified to produce a more stable C4 stream type, as defined by Rosgen (Rosgen 1994). In accordance with the Priority 1 Restoration method, the stream bed was elevated to reconnect it to its abandoned terrace, increasing available flood prone area to near pre-existing conditions. The result of the restoration effort is an increase in the width to depth ratio and reduced bank height ratios, thus improving channel stability. The sinuosity of the reach was also increased which resulted in a decreased mean slope. The decreased mean slope reduces the stream velocities of bankfull events that should also increase stream stability. In-stream structures including rock cross vanes, root wads and log vanes were incorporated into the channel. A vegetative buffer was planted along the stream corridor to further stabilize the stream banks, improve habitat conditions, and reduce ambient water temperature. Stream channel construction was completed in April of 2003 and the vegetated buffers were planted in February 2004. Stream and buffer restoration areas are surrounded by fencing and are protected by a conservation easement.

Suck Creek was restored through the North Carolina Ecosystem Enhancement Program (EEP) – formerly Wetlands Restoration Program (NCWRP). This is the Year 3 monitoring report for Suck Creek.

Table I provides information on the project structure and objectives.

Project Segment or Reach ID	Existing Feet/Acres	Type	Approach	Footage or Acreage	Mitigation Ratio	Mitigation Units	Stationing	Comment
Upper Reach	NA	R	P1	875 Lf	1.0	875	0+00 – 08+75	Restore dimension, pattern, and profile
Lower Reach	NA	R	P1	2,088 Lf	1.0	2,088	08+75 – 29+63	Restore dimension, pattern, and profile
Riparian Buffer Area	NA	R	SS	7.8 Ac.	1.0	7.8	NA	Restore riparian and wetland community
Mitigation Unit Summations								
Stream (lf)	Riparian Wetland (Ac)	Nonriparian Wetland (Ac)	Total Wetland (Ac)	Buffer (Ac)	Comment			
2,963	--	--	--	7.8				

R= Restoration

EII = Enhancement II

P1 = Priority I

P3 = Priority III

EI = Enhancement I

S = Stabilization


P2 = Priority II

SS = Stream Bank stabilization

3. Location and Setting



The Suck Creek Stream Restoration Project site lies within the Richardson Farm in Moore County, North Carolina. The stream drains a portion of the Deep River Subbasin (USGS Hydrologic Unit 03030003) and North Carolina Department of Water Quality (NCDWQ) Subbasin 03-06-10 of the Cape Fear River Basin. The project watershed consists of mainly of agricultural lands.

The Suck Creek site is located south of SR1261 and east of SR1210. Access to the site is provided via an access road on Richardson Farm. At the downstream terminus, the stream drains a 4.8 mile watershed that includes several impoundments. A vicinity map with directions to the site is provided in Figure 1.



The project is located west of Carthage in Moore County. From Raleigh, follow US-1 south to US-15/501 toward Carthage. When approaching Carthage, take NC-24/ Monroe Street into downtown. Follow through the downtown traffic circle to Dowd Road / SR 1240. Take Dowd Road west away from Carthage for approximately 1.5 miles. Take a right onto Beulah Hill Church Road / Mt. Carmel Road (SR 1210). After approximately 1.5 miles, turn right onto Richardson Farm Road (SR 1290) – a gravel road. Follow Richardson Farm Road to the primary residence and then turn left onto a gravel road. Follow the gravel road past the cattle nursery and chicken barns. The upper section of the project stream is located at the bottom of the hill. Please note that this is a private residence and permission is requested prior to entering the site.

Source: NCDOT USGS Topographic Quadrangle No. 105

 Ecosystem Enhancement Program	
FIGURE 1 PROJECT VICINITY MAP	
<i>Suck Creek Stream Restoration</i> <i>Project No. 011795008</i> <i>Monitoring Year 2 of 5</i> <i>Moore County, North Carolina</i>	
 THE LOUIS BERGER GROUP, INC 30A Vreeland Road Florham Park, NJ 07932	January 2007

4. Project History and Background

Project activity and reporting history are provided in Table II. The project contact information is provided in Table III. The project background history is provided in Table IV.

Table II. Project Activity and Reporting History Suck Creek Stream Restoration: Project No. 0117950008		
Activity or Report	Data Collection Complete	Actual Completion or Delivery
Restoration Plan	N/A	N/A
Final Design - 90%	N/A	2002
Construction	N/A	Apr-03
Temporary S&E mix applied to entire project area	N/A	N/A
Permanent seed mix applied to reach/segments 1 & 2	N/A	Apr-03
Containerized and B&B plantings for reach/segments 1 & 2	N/A	Feb-04
Mitigation Plan / As-built (Year 0 Monitoring - Baseline)	Mar-04	Jul-04
Year 1 Monitoring	Oct-04	Dec-04
Year 2 Monitoring	Sep-05	Dec-05

N/A: Historical project documents necessary to provide this data were unavailable.

Table III. Project Contact Table Suck Creek Stream Restoration: Project No. 0117950008	
Designer: Kimley-Horn and Associates, Inc.	P.O. Box 33068, Raleigh, NC, 27636 Mr. Will Wileham, Phone: (919) 677-2000
Construction Contractor: Shamrock Environmental Corporation	PO Box 14987, Greensboro NC 27415 Mr. Bill Wright
Planting Contractor: Shamrock Environmental Corporation	PO Box 14987, Greensboro NC 27415 Mr. Bill Wright
Seeding Contractor: Shamrock Environmental Corporation	PO Box 14987, Greensboro NC 27415 Mr. Bill Wright
Seedmix Sources: Ernst Crownvetch Farms	9006 Mercer Pike, Meadville, PA 16335 (814) 336-2404
Nursery Stock Suppliers: Hillis Nursery Company	92 Gardner Rd., McMinnville, TN 37110 (931) 668-9125
Monitoring Performers:	
Year 1 Monitoring (stream and vegetation): Kimley-Horn and Associates, Inc.	P.O. Box 33068, Raleigh, NC, 27636 Mr. Will Wileham, Phone: (919) 677-2000
Year 2 Monitoring (stream and vegetation): The Louis Berger Group, Inc.	1513 Walnut Street, Suite 250, Cary, NC, 27511 Mr. Ed Samanns, Phone: (973) 765-1800

Project County	Moore
Drainage Area of Upper Reach	4.7 sq. miles
Drainage Area of Lower Reach	4.8 sq. miles
Drainage Area Impervious Cover Estimate (%)	<2 percent
Stream Order	2
Physiographic Region	Piedmont
Ecoregion	Sand Hills
Rosgen Classification of As-built	C4
Cowardin Classification	Riverine Upper Perennial Stream Bed Sand Substrate (R3SB2) Lotic System
Dominant Soil Types	Chewacla silt loam, Tetotum silt loam
Reference Site ID	Upstream of project site and Richland Creek
USGS HUC for Project and Reference	3030003
NCDWQ Sub-Basin for Project and Reference	03-06-10
NCDWQ Classification for Project and Reference	C
NCDWQ Classification of Reach 1	C
NCDWQ Classification of Reach 2	C
Any portion of any project segment 303d listed?	No
Any portion of any project segment upstream of a 303d listed segment?	No
Reasons for 303d listing or stressor	--
% of project easement fenced	100%

5. Monitoring Plan View


The monitoring plan view is included as Figure 2.

MONITORING LEGEND

	VEGETATION PLOT
	O/S VEGETATION PLOT
	CROSS SECTION
	PHOTO POINT
	2000 GPS THALWEG

LEGEND

	BOULDER CLUSTER
	ROOT WAD
	BOULDER
	ROCK CROSS VANE
	J-HOOK VANE
	LOG VANE
	PROJECT FENCING/EASEMENT BOUNDARY
	EDGE OF WATER
	S of Suck Creek
	Wetland




Plot #	Plot Name	Plot Area (sq ft)	Plot Size (ft x ft)	Plot Orientation	Plot Location	Plot Notes
1	UPPER REACH POOL CROSS SECTION	100	10 x 10	N-S	UPPER REACH POOL	CROSS SECTION
2	CROSS SECTION 2	100	10 x 10	E-W	CROSS SECTION 2	CROSS SECTION
3	CROSS SECTION 3	100	10 x 10	E-W	CROSS SECTION 3	CROSS SECTION
4	VEGETATION PLOT A	100	10 x 10	N-S	VEGETATION PLOT A	VEGETATION PLOT
5	VEGETATION PLOT B	100	10 x 10	N-S	VEGETATION PLOT B	VEGETATION PLOT
6	VEGETATION PLOT C	100	10 x 10	N-S	VEGETATION PLOT C	VEGETATION PLOT
7	VEGETATION PLOT D	100	10 x 10	N-S	VEGETATION PLOT D	VEGETATION PLOT
8	UPPER RANCH RIFLE UPPER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
9	UPPER RANCH RIFLE LOWER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
10	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
11	UPPER RANCH RIFLE RIGHT SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
12	UPPER RANCH RIFLE LEFT SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
13	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
14	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
15	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
16	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
17	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
18	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
19	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
20	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
21	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
22	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
23	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
24	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
25	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
26	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
27	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
28	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
29	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
30	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
31	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
32	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
33	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
34	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
35	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
36	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
37	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
38	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
39	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
40	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
41	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
42	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
43	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
44	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
45	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
46	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
47	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
48	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
49	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION
50	UPPER RANCH RIFLE CENTER SECTION	100	10 x 10	N-S	UPPER RANCH RIFLE	CROSS SECTION


Ecosystem Enhancement Program

FIGURE 2A
MONITORING PLAN VIEW
SUCK CREEK STREAM RESTORATION
 Project No. 011795008
 Monitoring Year 3 of 5
 Moore County, North Carolina

THE LOUIS BERGER GROUP, INC
 50A Westland Road
 Flatbam Park, NJ 07932
 January 2007



MATCH SHEET 2
MATCH SHEET 3



Plot No.	Plot Area (sq ft)	Plot Description	GPS Point	Photo Point	Notes
0	1000	Vegetation Plot 0
1	1000	Vegetation Plot 1
2	1000	Vegetation Plot 2
3	1000	Vegetation Plot 3
4	1000	Vegetation Plot 4
5	1000	Vegetation Plot 5
6	1000	Vegetation Plot 6
7	1000	Vegetation Plot 7
8	1000	Vegetation Plot 8
9	1000	Vegetation Plot 9
10	1000	Vegetation Plot 10
11	1000	Vegetation Plot 11
12	1000	Vegetation Plot 12
13	1000	Vegetation Plot 13
14	1000	Vegetation Plot 14
15	1000	Vegetation Plot 15
16	1000	Vegetation Plot 16
17	1000	Vegetation Plot 17
18	1000	Vegetation Plot 18
19	1000	Vegetation Plot 19
20	1000	Vegetation Plot 20
21	1000	Vegetation Plot 21
22	1000	Vegetation Plot 22
23	1000	Vegetation Plot 23
24	1000	Vegetation Plot 24
25	1000	Vegetation Plot 25
26	1000	Vegetation Plot 26
27	1000	Vegetation Plot 27
28	1000	Vegetation Plot 28
29	1000	Vegetation Plot 29
30	1000	Vegetation Plot 30
31	1000	Vegetation Plot 31
32	1000	Vegetation Plot 32
33	1000	Vegetation Plot 33
34	1000	Vegetation Plot 34
35	1000	Vegetation Plot 35
36	1000	Vegetation Plot 36
37	1000	Vegetation Plot 37
38	1000	Vegetation Plot 38
39	1000	Vegetation Plot 39
40	1000	Vegetation Plot 40
41	1000	Vegetation Plot 41
42	1000	Vegetation Plot 42
43	1000	Vegetation Plot 43
44	1000	Vegetation Plot 44
45	1000	Vegetation Plot 45
46	1000	Vegetation Plot 46
47	1000	Vegetation Plot 47
48	1000	Vegetation Plot 48
49	1000	Vegetation Plot 49
50	1000	Vegetation Plot 50
51	1000	Vegetation Plot 51
52	1000	Vegetation Plot 52
53	1000	Vegetation Plot 53
54	1000	Vegetation Plot 54
55	1000	Vegetation Plot 55
56	1000	Vegetation Plot 56
57	1000	Vegetation Plot 57
58	1000	Vegetation Plot 58
59	1000	Vegetation Plot 59
60	1000	Vegetation Plot 60
61	1000	Vegetation Plot 61
62	1000	Vegetation Plot 62
63	1000	Vegetation Plot 63
64	1000	Vegetation Plot 64
65	1000	Vegetation Plot 65
66	1000	Vegetation Plot 66
67	1000	Vegetation Plot 67
68	1000	Vegetation Plot 68
69	1000	Vegetation Plot 69
70	1000	Vegetation Plot 70
71	1000	Vegetation Plot 71
72	1000	Vegetation Plot 72
73	1000	Vegetation Plot 73
74	1000	Vegetation Plot 74
75	1000	Vegetation Plot 75
76	1000	Vegetation Plot 76
77	1000	Vegetation Plot 77
78	1000	Vegetation Plot 78
79	1000	Vegetation Plot 79
80	1000	Vegetation Plot 80
81	1000	Vegetation Plot 81
82	1000	Vegetation Plot 82
83	1000	Vegetation Plot 83
84	1000	Vegetation Plot 84
85	1000	Vegetation Plot 85
86	1000	Vegetation Plot 86
87	1000	Vegetation Plot 87
88	1000	Vegetation Plot 88
89	1000	Vegetation Plot 89
90	1000	Vegetation Plot 90
91	1000	Vegetation Plot 91
92	1000	Vegetation Plot 92
93	1000	Vegetation Plot 93
94	1000	Vegetation Plot 94
95	1000	Vegetation Plot 95
96	1000	Vegetation Plot 96
97	1000	Vegetation Plot 97
98	1000	Vegetation Plot 98
99	1000	Vegetation Plot 99
100	1000	Vegetation Plot 100

MONITORING LEGEND

- VEGETATION PLOT
- GPS VEGETATION PLOT
- CROSS SECTION
- PHOTO POINT
- 2005 GPS THALWEG

LEGEND

- BOULDER CLUSTER
- ROOT MUD
- BOULDER
- ROCK CROSS VANE
- J-HOOK VANE
- LOG VANE
- PROJECT FENCING/EASEMENT BOUNDARY
- EDGE OF WATER
- Q of Suck Creek
- Wetland

Ecosystem Enhancement Program

FIGURE 2B

MONITORING PLAN VIEW

SUCK CREEK STREAM RESTORATION

Project No. 011795008

Monitoring Year 3 of 5

Moore County, North Carolina

THE LOUIS BERGER GROUP, INC.
 10000 Park Road
 Jannam Park, NJ 07832

January 2007



MATCH SHEET 2
MATCH SHEET 3


MONITORING LEGEND

- VEGETATION PLOT
- OVS VEGETATION PLOT
- CROSS SECTION
- PHOTO POINT
- 2005 GPS THALWEG

LEGEND

- BOULDER CLUSTER
- ROOT WAD
- BOULDER
- ROCK CROSS VANE
- J-HOOK VANE
- LOG VANE
- PROJECT FENCING/EASEMENT BOUNDARY
- EDGE OF WATER
- § of Suck Creek
- Wetland

Station	Point	Notes
1+00	1+00	Start of Suck Creek
1+10	1+10	...
1+20	1+20	...
1+30	1+30	...
1+40	1+40	...
1+50	1+50	...
1+60	1+60	...
1+70	1+70	...
1+80	1+80	...
1+90	1+90	...
2+00	2+00	...
2+10	2+10	...
2+20	2+20	...
2+30	2+30	...
2+40	2+40	...
2+50	2+50	...
2+60	2+60	...
2+70	2+70	...
2+80	2+80	...
2+90	2+90	...
3+00	3+00	...
3+10	3+10	...
3+20	3+20	...
3+30	3+30	...
3+40	3+40	...
3+50	3+50	...
3+60	3+60	...
3+70	3+70	...
3+80	3+80	...
3+90	3+90	...
4+00	4+00	...
4+10	4+10	...
4+20	4+20	...
4+30	4+30	...
4+40	4+40	...
4+50	4+50	...
4+60	4+60	...
4+70	4+70	...
4+80	4+80	...
4+90	4+90	...
5+00	5+00	...
5+10	5+10	...
5+20	5+20	...
5+30	5+30	...
5+40	5+40	...
5+50	5+50	...
5+60	5+60	...
5+70	5+70	...
5+80	5+80	...
5+90	5+90	...
6+00	6+00	...
6+10	6+10	...
6+20	6+20	...
6+30	6+30	...
6+40	6+40	...
6+50	6+50	...
6+60	6+60	...
6+70	6+70	...
6+80	6+80	...
6+90	6+90	...
7+00	7+00	...
7+10	7+10	...
7+20	7+20	...
7+30	7+30	...
7+40	7+40	...
7+50	7+50	...
7+60	7+60	...
7+70	7+70	...
7+80	7+80	...
7+90	7+90	...
8+00	8+00	...
8+10	8+10	...
8+20	8+20	...
8+30	8+30	...
8+40	8+40	...
8+50	8+50	...
8+60	8+60	...
8+70	8+70	...
8+80	8+80	...
8+90	8+90	...
9+00	9+00	...
9+10	9+10	...
9+20	9+20	...
9+30	9+30	...
9+40	9+40	...
9+50	9+50	...
9+60	9+60	...
9+70	9+70	...
9+80	9+80	...
9+90	9+90	...
10+00	10+00	...
10+10	10+10	...
10+20	10+20	...
10+30	10+30	...
10+40	10+40	...
10+50	10+50	...
10+60	10+60	...
10+70	10+70	...
10+80	10+80	...
10+90	10+90	...
11+00	11+00	...
11+10	11+10	...
11+20	11+20	...
11+30	11+30	...
11+40	11+40	...
11+50	11+50	...
11+60	11+60	...
11+70	11+70	...
11+80	11+80	...
11+90	11+90	...
12+00	12+00	...
12+10	12+10	...
12+20	12+20	...
12+30	12+30	...
12+40	12+40	...
12+50	12+50	...
12+60	12+60	...
12+70	12+70	...
12+80	12+80	...
12+90	12+90	...
13+00	13+00	...
13+10	13+10	...
13+20	13+20	...
13+30	13+30	...
13+40	13+40	...
13+50	13+50	...
13+60	13+60	...
13+70	13+70	...
13+80	13+80	...
13+90	13+90	...
14+00	14+00	...
14+10	14+10	...
14+20	14+20	...
14+30	14+30	...
14+40	14+40	...
14+50	14+50	...
14+60	14+60	...
14+70	14+70	...
14+80	14+80	...
14+90	14+90	...
15+00	15+00	...
15+10	15+10	...
15+20	15+20	...
15+30	15+30	...
15+40	15+40	...
15+50	15+50	...
15+60	15+60	...
15+70	15+70	...
15+80	15+80	...
15+90	15+90	...
16+00	16+00	...
16+10	16+10	...
16+20	16+20	...
16+30	16+30	...
16+40	16+40	...
16+50	16+50	...
16+60	16+60	...
16+70	16+70	...
16+80	16+80	...
16+90	16+90	...
17+00	17+00	...
17+10	17+10	...
17+20	17+20	...
17+30	17+30	...
17+40	17+40	...
17+50	17+50	...
17+60	17+60	...
17+70	17+70	...
17+80	17+80	...
17+90	17+90	...
18+00	18+00	...
18+10	18+10	...
18+20	18+20	...
18+30	18+30	...
18+40	18+40	...
18+50	18+50	...
18+60	18+60	...
18+70	18+70	...
18+80	18+80	...
18+90	18+90	...
19+00	19+00	...
19+10	19+10	...
19+20	19+20	...
19+30	19+30	...
19+40	19+40	...
19+50	19+50	...
19+60	19+60	...
19+70	19+70	...
19+80	19+80	...
19+90	19+90	...
20+00	20+00	...
20+10	20+10	...
20+20	20+20	...
20+30	20+30	...
20+40	20+40	...
20+50	20+50	...
20+60	20+60	...
20+70	20+70	...
20+80	20+80	...
20+90	20+90	...
21+00	21+00	...
21+10	21+10	...
21+20	21+20	...
21+30	21+30	...
21+40	21+40	...
21+50	21+50	...
21+60	21+60	...
21+70	21+70	...
21+80	21+80	...
21+90	21+90	...
22+00	22+00	...
22+10	22+10	...
22+20	22+20	...
22+30	22+30	...
22+40	22+40	...
22+50	22+50	...
22+60	22+60	...
22+70	22+70	...
22+80	22+80	...
22+90	22+90	...
23+00	23+00	...
23+10	23+10	...
23+20	23+20	...
23+30	23+30	...
23+40	23+40	...
23+50	23+50	...
23+60	23+60	...
23+70	23+70	...
23+80	23+80	...
23+90	23+90	...
24+00	24+00	...
24+10	24+10	...
24+20	24+20	...
24+30	24+30	...
24+40	24+40	...
24+50	24+50	...
24+60	24+60	...
24+70	24+70	...
24+80	24+80	...
24+90	24+90	...
25+00	25+00	...



Ecosystem Enhancement Program

FIGURE 2C

MONITORING PLAN VIEW

SUCK CREEK STREAM RESTORATION

Project No. 011795008

Monitoring Year 3 of 5

Moore County, North Carolina

THE LOUIS BERGER GROUP, INC

1704 Westland Road

Fountain, PA, 15082

January 2007

SCALE IN FEET

0 50

III. Project Condition and Monitoring Results

A. Vegetation Assessment

1. Vegetative Problem Areas

Vegetative Problem Areas are defined as either lacking vegetation or containing exotic vegetation. No problem areas were identified during Monitoring Year 3. Problem areas reported in previous years had become colonized with herbaceous vegetation.

2. Vegetative Problem Area Plan View

The location of each vegetative problem area is shown in Appendix A.

3. Stem Counts

Vegetation monitoring in Year 3 was conducted using two sampling methodologies: EEP Stem Counting Protocol and the CVS-EEP Protocol for Recording Vegetation (Levels 1 & 2). The EEP Stem Counting Protocol was used to collect data for comparison with Year 2 vegetation monitoring results since this methodology was used in Year 2. EEP Stem Count plot numbers and locations for this years monitoring were the same as the previous year. CVS-EEP vegetation plots (3,4) were located atop of the EEP Stem Count plots (3,4). Other CVS-EEP plots (1,2,5,6,7,8) were set across portions of the EEP Stem Count plots (1,2,5,10,11,12,13), and one CVS-EEP plot (9) was set outside of any previous vegetation monitoring plots. The data summary of woody stem density onsite described below was collected using EEP Stem Counting Protocol. The data summary generated using the CVS-EEP protocol is provided in Appendix A.

Based on the data collected using the EEP Stem Counting Protocol, all of the 13 plots had stem densities above the success criteria of 260 planted trees per acre. The average tree density for the entire site exceeded the success criteria at 1,042 trees per acre. Recruitment of volunteer species has significantly increased stem densities site-wide; with root suckering of river birch along the stream bank accounting for the majority of volunteer stems.

Within each plot, woody stem densities were higher along the stream banks because of regeneration from live stakes and root suckering of river birch. Stem density rapidly decreased with distance away from the stream banks. The most common woody plants recorded away from the stream banks included: sycamore (*Platanus occidentalis*), green ash (*Fraxinus pennsylvanica*) and sweet gum (*Liquidambar styraciflua*). These woody stem species are often taller than the herbaceous growth within this area. All of last year's red stem dogwood (*Cornus stolonifera*) were identified this year, correctly, as silky dogwood (*Cornus amomum*).

Thick herbaceous growth covers nearly all of the stream banks and riparian zone. The herbaceous growth is dominated by tall wormwood (*Artemisia caudata*) and whorled coreopsis (*Coreopsis verticillata*).

A summary of stem count data collected using the EEP Stem Counting Protocol is provided in Table V. The results of the vegetation monitoring conducted using the CVS-EEP Protocol is provided in Appendix A.

**Table V. Stem Counts for Each Species Arranged by Plot and Location – Based on Data collected Using the EEP Stem Counting Protocol
Suck Creek Stream Restoration: Project No. 0117950008**

Species	Plots													Year 3 Totals	Year 2 Totals	% Survival		
	1	2	3	4	5	6	7	8	9	10	11	12	13					
Shrubs																		
<i>Alnus serrulata</i> ¹							1		3	2		1				7	7	100
<i>Baccharis halimifolia</i>								1								2	0	
<i>Celtis laevigata</i> ¹										1						1	0	
<i>Cornus amomum</i>						3	6		1	2			3			15	0	
<i>Cornus stolonifera</i>						1										1	23	4
<i>Ligustrum vulgare</i>	1															1	0	
<i>Oxydendrum arboreum</i> ¹																0	3	0
Trees																		
<i>Acer rubrum</i> ¹		2	2													4	1	100
<i>Betula nigra</i>	7	1	2			7	6		8	19	36	84	25			195	150	100
<i>Diospyros virginiana</i>													1			1	0	
<i>Fraxinus pennsylvanica</i>			1		6							1				8	4	100
<i>Liquidambar styraciflua</i> ¹	2	1	1						4	2		5	2			17	24	71
<i>Liriodendron tulipifolia</i>																0	0	
<i>Nyssa sylvatica</i>	1	1										1				4	0	
<i>Pinus taeda</i>	1		3	4			2		1	2						13	2	100
<i>Platanus occidentalis</i>	2	1					1		2	5			18			29	36	80
<i>Prunus serotina</i>							1									1	0	
<i>Quercus phellos</i>																0	2	0
<i>Salix nigra</i>	2		5		1	3	6	8	8	2						36	50	72
Total Stems	17	8	17	8	12	20	30	17	36	45	49	104	63			335	302	
Stem Density	688	323	688	323	485	809	1,214	688	1,457	1,821	1,983	4,210	2,550					

¹Volunteer or sapling vegetation found within sampling plots.

B. Stream Assessment

1. Procedural Items

During the Year 2 (2005) field sampling effort at the lower pool cross section, the right bank stake could not be found. The field crew used a sub-meter accurate GPS unit to locate to the approximate coordinates of the previous year's location. When the stake location could not be located, a new end point was created. Conduit was driven into the ground to mark the location, GPS coordinates were established at the location of the installed conduit, the elevation of the top of conduit was established using a laser level and rod (tied into the permanent benchmark located on-site) and the cross section was surveyed. This same cross section location was used during Year 3 monitoring.

2. Hydrologic Criteria

A stream gauge was installed the first week in August 2006. Since a full year of hydrologic data was not collected, this criteria was not evaluated for the full Year 3 monitoring period. During the period of available data (August – October 2006) no bankfull events were recorded. A graphic of the data collected is provided in Appendix B.

3. Stream Problem Areas Plan View

The position of each structural problem area is shown in Appendix B.

4. Stream Problem Areas Table

There were no new problem areas identified during Year 3 monitoring. All Year 2 problem areas were unchanged, had not degraded further, or herbaceous vegetation had established on the problem area. The root wad failure at Station 19+10 has stabilized and vegetated and is not considered a problem area. This area will be looked at in future monitoring to track its stability. A summary of the problem structures observed during Year 3 monitoring with notes about each structures status is provided in Appendix B.

Maintenance is recommended on the cross vanes at Stations 21+60 and 26+60 since scour between and around individual rocks in the arm is extensive and the arm of the structure is not creating a bar behind the structure of any kind. Sediment has deposited atop the vane arms and has become vegetated. Piping between vane rocks still continues.

The mid-channel bar downstream of the boulder field (Stations 4+00 to 4+60) has become vegetated with rice cutgrass (*Leersia oryzoides*). This feature likely occurs because of unfocused velocity, down stream of the boulder field, and too slight a water surface slope. Low water levels due to the late summer drought may have also created shallow water conditions conducive for the germination and establishment of rice-cut grass. No maintenance actions are recommended at this time.

The root wad failure at Station 19+10 that caused bank erosion last year has stabilized. The banks and fabric matting have formed a vegetated slumping bank.

5. Number Issue Photos Section

A photograph of each structural problem area is provided in Appendix B.

6. Fixed Station Photos

Photographs taken at each established photograph station are provided in Appendix B.

7. Stability Assessment

A semi-qualitative summary of results from the visual inspection is proved in Table VIa for the Upper Reach and Table VIb for the Lower Reach.

Table VIa. Categorical Stream Feature Visual Stability Assessment – Upper Reach						
Suck Creek Stream Restoration: Project No. 0117950008						
Segment/Reach: Upper Reach						
Feature	Initial	MY-01	MY-02	MY-03	MY-04	MY-05
A. Riffles	N/A	N/A	88	88		
B. Pools	N/A	N/A	88	88		
C. Thalweg	N/A	N/A	100	100		
D. Meanders	N/A	N/A	100	100		
E. Bed General	N/A	N/A	99	99		
F. Bank Condition	N/A	N/A	96	96		
G. Vanes / J Hooks etc.	N/A	N/A	100	100		
H. Wads and Boulders	N/A	N/A	100	100		

N/A: Historical project documents necessary to provide this data were unavailable at the time of this report submission.

Table VIb. Categorical Stream Feature Visual Stability Assessment – Lower Reach						
Suck Creek Stream Restoration: Project No. 0117950008						
Segment/Reach: Lower Reach						
Feature	Initial	MY-01	MY-02	MY-03	MY-04	MY-05
A. Riffles	N/A	N/A	93.5	93.5		
B. Pools	N/A	N/A	100	100		
C. Thalweg	N/A	N/A	100	100		
D. Meanders	N/A	N/A	99	99		
E. Bed General	N/A	N/A	100	100		
F. Bank Condition	N/A	N/A	100	100		
G. Vanes / J Hooks etc.	N/A	N/A	85	85		
H. Wads and Boulders	N/A	N/A	96	96		

N/A: Historical project documents necessary to provide this data were unavailable at the time of this report submission.

8. Quantitative Measures Summary Tables

Graphic interpretations of cross sections, profiles and sediment distributions are shown in Appendix B. A summary of geomorphic measurements is shown in Table VII and Table VIII.

Parameter	USGS Gage Data			Regional Curve Interval			Pre-Existing Condition			Project Reference Stream			Design			As-built			
	Min	Max	Med	Min	Max	Med	Min	Max	Med	Min	Max	Med	Min	Max	Med	Min	Max	Med	
Dimension																			
BF Width (ft)													18	36	N/A	N/A	N/A	18.1	
Floodprone Width (ft)													1.2	1.8	N/A	N/A	N/A	1.3	
BF Cross Sectional Area (ft ²)													1.8	2.9	N/A	N/A	N/A	2.2	
BF Mean Depth (ft)													12.5	11.1	N/A	N/A	N/A	16.3	
BF Max Depth (ft)													N/A	N/A	N/A	N/A	N/A	N/A	
Width/Depth Ratio													N/A	N/A	N/A	N/A	N/A	N/A	
Entrenchment Ratio													N/A	N/A	N/A	N/A	N/A	N/A	
Bank Height Ratio													N/A	N/A	N/A	N/A	N/A	N/A	
Wetted Perimeter (ft)													N/A	N/A	N/A	N/A	N/A	N/A	
Hydraulic Radius (ft)													N/A	N/A	N/A	N/A	N/A	N/A	
Pattern																			
Channel Belwidth (ft)													21	99	N/A	N/A	20	104	N/A
Radius of Curvature (ft)													32	69	N/A	N/A	35	55	N/A
Meander Wavelength (ft)													130	265	N/A	N/A	120	265	N/A
Meander Width ratio																			
Profile																			
Riffle length (ft)													N/A	N/A	N/A	N/A	10	42	N/A
Riffle slope (ft/ft)													.45	1.0	N/A	N/A	0.5	1.0	N/A
Pool length (ft)													N/A	N/A	N/A	N/A	20	128	N/A
Pool spacing (ft)													60	140	N/A	N/A	54	171	N/A
Substrate																			
d50 (mm)													N/A	N/A	N/A	N/A	0.8	20	N/A
d84 (mm)													N/A	N/A	N/A	N/A	10	34	N/A
Additional Reach Parameters																			
Valley Length (ft)																			
Channel Length (ft)																			
Sinuosity																			
Water Surface Slope (ft/ft)																			
BF slope (ft)																			
Rosgen Classification																			
*Habitat Index																			
*Macrobenthos																			

* Inclusion will be project specific and determined primarily by As-built monitoring plan/success criteria
N/A: Historical project documents necessary to provide this data were unavailable.

Table VIII. Morphology and Hydraulic Monitoring Summary – Continued
Suck Creek Stream Restoration: Project No. 0117950008

Additional Reach Parameters	Segment/Reach:					
	MY-01 (2004)	MY-02 (2005) Lower/Upper	MY-03 (2006) Lower/Upper	MY-04 (XXXX)	MY-05 (XXXX)	MY+ (XXXX)
Valley length (ft)	N/A	411/386	411/386			
Channel length (ft)	N/A	515/408	515/408			
Stimosity	N/A	1.25/1.05	1.25/1.05			
Water surface slope (ft/ft)	N/A	0.0022/0.0017	0.0020/0.0021			
Bankfull slope (ft)	N/A	0.0023/0.0029	0.0054/0.0035			
Rosgen Classification	C5	C5	C5			
*Habitat Index	N/A	N/A	N/A			
*Macrobenthos	N/A	N/A	N/A			

* Inclusion will be project specific and determined primarily by As-built monitoring plan/success criteria
N/A: Historical project documents necessary to provide this data were unavailable at the time of this report submission.

IV. Methodology Section

No unavoidable deviations from established protocols occurred during Year 3 monitoring.

Appendix A
(Click here)

APPENDIX A

1. VEGETATION DATA TABLES

1. Vegetation Data Tables

Table 1. Vegetation Metadata	
Report Prepared By	Michael Lee
Date Prepared	11/17/2006 11:49
database name	CVS_EEP_DataEntry_v202.mdb
database location	C:\work\CVS-EEP
DESCRIPTION OF WORKSHEETS IN THIS DOCUMENT-----	
Metadata	This worksheet, which is a summary of the project and the project data.
Plots	List of plots surveyed.
Vigor	Frequency distribution of vigor classes.
Vigor by Spp	Frequency distribution of vigor classes listed by species.
Damage	List of most frequent damage classes with number of occurrences and percent of total stems impacted by each.
Damage by Spp	Damage values tallied by type for each species.
Damage by Plot	Damage values tallied by type for each plot.
Stem Count by Plot and Spp	Count of living stems of each species for each plot; dead and missing stems are excluded.
PROJECT SUMMARY-----	
Project Code	Suck Creek
project Name	Suck Creek
Description	Stream Restoration
length (ft)	
stream-to-edge width (ft)	
area (sq m)	
Required Plots (calculated)	
Sampled Plots	9

	Species	4	3	2	1	0	Missing
	<i>Alnus serrulata</i>	4					
	<i>Betula nigra</i>	63	3				
	<i>Celtis occidentalis</i>	2					
	<i>Cornus amomum</i>		1				
	<i>Diospyros virginiana</i>	1					
	<i>Fraxinus nigra</i>		1				
	<i>Fraxinus pennsylvanica</i>	8	1				
	<i>Liquidambar styraciflua</i>	1					
	<i>Pinus taeda</i>	7					
	<i>Quercus phellos</i>	2					
	<i>Salix nigra</i>	12	8	2			
	<i>Platanus occidentalis</i>	9	1				
	<i>Acer rubrum</i>	1	3				
TOT:	13	110	18	2			

	Species	All Damage Categories	(no damage)	Deer	Drought	Insects	Site Too Dry	Unknown	(other damage)
	<i>Acer rubrum</i>	4	1	1					2
	<i>Alnus serrulata</i>	4	2	2					
	<i>Betula nigra</i>	66	50	14		1		1	
	<i>Celtis occidentalis</i>	2	2						
	<i>Cornus amomum</i>	1		1					
	<i>Diospyros virginiana</i>	1	1						
	<i>Fraxinus nigra</i>	1		1					
	<i>Fraxinus pennsylvanica</i>	9	5	4					
	<i>Liquidambar styraciflua</i>	1	1						
	<i>Pinus taeda</i>	7	7						
	<i>Platanus occidentalis</i>	10	9						1
	<i>Quercus phellos</i>	2	2						
	<i>Salix nigra</i>	22	14		1	1	3	2	1
TOT:	13	130	94	23	1	2	3	3	4

Table 4. Vegetation Damage by Plot

	plot	All Damage Categories	(no damage)	Deer	Drought	Insects	Site Too Dry	Unknown	(other damage)
	79-1-1T-1/1	6	5					1	
	79-1-2	15	9	3			1		2
	79-1-3	13	9				2	2	
	79-1-4	9	6	1					2
	79-1-5	7	5	2					
	79-1-6	33	21	9	1	2			
	79-1-7	18	14	4					
	79-1-8	28	25	3					
	79-1-9	1		1					
TOT:	9	130	94	23	1	2	3	3	4

Table 5. Stem Count by Plot and Species

	Species	Total Stems	# plots	avg# stems	plot 79-1-1T-1/1	plot 79-1-2	plot 79-1-3	plot 79-1-4	plot 79-1-5	plot 79-1-6	plot 79-1-7	plot 79-1-8	plot 79-1-9
	<i>Acer rubrum</i>	4	2	2				3		1			
	<i>Alnus serrulata</i>	4	3	1.33				1		2		1	
	<i>Betula nigra</i>	66	6	11	1	9	1			16	13	26	
	<i>Celtis occidentalis</i>	2	2	1						1	1		
	<i>Cornus amomum</i>	1	1	1						1			
	<i>Diospyros virginiana</i>	1	1	1					1				
	<i>Fraxinus nigra</i>	1	1	1		1							
	<i>Fraxinus pennsylvanica</i>	9	5	1.8			1		4		2	1	1
	<i>Liquidambar styraciflua</i>	1	1	1				1					
	<i>Pinus taeda</i>	7	4	1.75	1		3	2		1			
	<i>Platanus occidentalis</i>	10	4	2.5	2	2		1		5			
	<i>Quercus phellos</i>	2	2	1			1	1					
	<i>Salix nigra</i>	22	6	3.67	2	3	7		2	6	2		
TOT:	13	130	13	30.05	6	15	13	9	7	33	18	28	1

APPENDIX A

2. VEGETATION PROBLEM AREA PHOTOS

2. Vegetation Problem Area Photos

No vegetation problem areas were observed during the Year 3 monitoring.

APPENDIX A

3. VEGETATION MONITORING PLOT PHOTOS

3. Vegetation Monitoring Plot Photos

A representative photo of each vegetation plot, taken on the day of sampling, is shown.



CVS Vegetation Plot 1



CVS Vegetation Plot 2



CVS Vegetation Plot 3



CVS Vegetation Plot 4



CVS Vegetation Plot 5



CVS Vegetation Plot 6



CVS Vegetation Plot 7



CVS Vegetation Plot 8




CVS Vegetation Plot 9

Appendix B
(Click here)

APPENDIX B

1. STREAM GAUGE DATA

Suck Creek Mitigation Site
Stream Gauge SC5G-1 (Serial No. N4497E95)



APPENDIX B

2. PROBLEM AREAS PLAN VIEW




STREAM PROBLEM AREA LEGEND

- PHOTO STATION
- 2005 PHOTO STATION
- STRESSED
- FALLING

LEGEND

- BOULDER CLUSTER
- ROOT WAD
- BOULDER
- ROCK CROSS VANE
- J-HOOK VANE
- LOG VANE
- PROJECT FENCING/EASEMENT BOUNDARY
- EDGE OF WATER
- ☉ of Suck Creek
- Wetland



Ecosystem Enhancement Program

Exhibit B-1a

STREAM PROBLEM AREA PLAN VIEW

SUCK CREEK STREAM RESTORATION

Project No. 011795008


Monitoring Year 3 of 5

Moore County, North Carolina

THE LOUIS BERGER GROUP, INC
 1000 West 10th Street
 Florence, SC 29502
 Phone: 803.792.1100
 Fax: 803.792.1101
 Email: info@louisberger.com

January 2007





STREAM PROBLEM AREA LEGEND

- PHOTO STATION
- 2005 PHOTO STATION
- STRESSED
- FALLING


LEGEND

- Boulder Cluster
- Root Wad
- Boulder
- Rock Cross Vane
- J-Hook Vane
- Log Vane
- Project Fencing/Assessment Boundary
- Edge of Water
- Edge of Suck Creek
- Wetland

Ecosystem Enhancement Program
 Exhibit B-1b
 STREAM PROBLEM AREA PLAN VIEW
 SUCK CREEK STREAM RESTORATION
 Project No. 011795008
 Monitoring Year 3 of 5
 Moore County, North Carolina

THE LOUIS BERGER GROUP, INC
 304 Vreeland Road
 Durham, NC 27632

January 2007




MATCH SHEET 2
 MATCH SHEET 3

STREAM PROBLEM AREA LEGEND

- PHOTO STATION
- 2005 PHOTO STATION
- STRESSED
- FALLING
- BOULDER CLUSTER
- ROOT WAD
- BOULDER
- ROCK CROSS VANE
- J-HOOK VANE
- LOG VANE
- PROJECT FENCING/EASEMENT BOUNDARY
- EDGE OF WATER
- § of Sick Creek
- Wetland

LEGEND



Ecosystem Enhancement Program

Exhibit B-1c

STREAM PROBLEM AREA PLAN VIEW

SUCK CREEK STREAM RESTORATION

Project No. 011795008

Monitoring Year 3 of 5

Moore County, North Carolina

THE LOUIS BERGER GROUP, INC

304 Vreeland Road

Warham Park, NC 27932

January 2007



APPENDIX B

3. TABLE B.2. STREAM PROBLEM AREAS

**Table B.1. Stream Problem Areas
Suck Creek Stream Restoration: Project No. 0117950008**

Feature Issue	Station Numbers	Suspected Cause	Photo Number / ID
Mid channel bar	4+00 to 4+60	Slope too slight to move sediment. More sediment has deposited and vegetation has established.	Station 4+00
Cross Vane, arm scour	18+00	Large voids between rocks in vane. No change from prior year.	Station 18+00
Root wad failure	19+10	Improper installation. Vegetation has established.	Station 19+10
Cross Vane, arm scour	21+60	Large voids between rocks in vane. No change from prior year.	Station 21+60
Cross Vane, arm scour	25+70	Large voids between rocks in vane. No change from prior year.	Station 25+70
Cross Vane, arm scour	26+60	Large voids between rocks in vane. No change from prior year.	

APPENDIX B


4. STREAM PROBLEM AREA PHOTOS

4. Representative Stream Problem Area Photos

A photo of each structural problem area is shown with corresponding stationing.



Station 4+00



Station 18+00



Station 19+10



Station 21+60



Station 25+70

APPENDIX B

5. STREAM PHOTO-STATION PHOTOS

5. Stream Photo-Station Photos



Photo Station 1



Photo Station 2



Photo Station 3



Photo Station 4



Photo Station 5




Photo Station 6

APPENDIX B

6. TABLE B.2. QUALITATIVE VISUAL STABILITY ASSESSMENT

6. Table B.2. Qualitative Visual Stability Assessment

Table B.2.a. Visual Morphological Stability Assessment Suck Creek Stream Restoration - Upper Reach: 2,088 feet						
Feature Category	Metric (per As-Built and reference baseline)	(# Stable) Number Performing as Intended	Total Number per As-built	Total Number / feet in unstable state	% Perform in Stable Condition	Feature Perform. Mean or Total
A. Riffles	1. Present?	7	8		88	
	2. Armor Stable?		0			
	3. Facet grade appears stable?	7	8		88	
	4. Minimal evidence of embedding / fining?	7	8		88	
	5. Length appropriate?	7	8		88	88
B. Pools	1. Present?	7	8		88	
	2. Sufficient depth?	7	8		88	
	3. Length appropriate?	7	8		88	88
C. Thalweg	1. Upstream of meander bend centering?	8	8		100	
	2. Downstream of meander bend centering?	8	8		100	100
D. Meanders	1. Outer bend in state of limited / controlled erosion	7	7		100	
	2. Of those eroding, # w/concomitant point bar formation?					
	3. Apparent Rc within spec?	7	7		100	
	4. Sufficient Floodplain Access and Relief?	7	7		100	100
E. Bed General	1. General channel bed aggradation areas?			60/850	93	
	2. Channel bed degradation?			0/850	100	96
F. Vanes	1. Free of back or arm scour?	7	7		100	
	2. Height appropriate?	7	7		100	
	3. Angle and geometry appear appropriate?	7	7		100	
	4. Free of piping or other structural failures?	7	7		100	100
G. Wads / Boulders	1. Free of Scour?	7	7		100	
	2. Footing Stable?	7	7		100	100

Table B.2.b. Visual Morphological Stability Assessment Suck Creek Stream Restoration - Lower Reach: 875 feet

Feature Category	Metric (per As-Built and reference baselines)	(# Stable) Number Performing as Intended	Total Number per As-built	Total Number / feet in unstable state	% Perform in Stable Condition	Feature Perform. Mean or Total
A. Riffles	1. Present?	23	23		100	
	2. Armor Stable?		0			
	3. Facet grade appears stable?	20	23		87	
	4. Minimal evidence of embedding / fining?	20	23		87	
	5. Length appropriate?	23	23		100	93.5
B. Pools	1. Present?	24	24		100	
	2. Sufficient depth?	24	24		100	
	3. Length appropriate?	24	24		100	100
C. Thalweg	1. Upstream of meander bend centering?	21	21		100	
	2. Downstream of meander bend centering?	21	21		100	100
D. Meanders	1. Outer bend in state of limited / controlled erosion	20	21		95	
	2. Of those eroding, # w/concomitant point bar formation?	21	21		100	
	3. Apparent Rc within spec?	21	21		100	
	4. Sufficient Floodplain Access and Relief?	21	21		100	99
E. Bed General	1. General channel bed aggradation areas?		0/2000		100	
	2. Channel bed degradation?		0/2000		100	100
F. Vanes	1. Free of back or arm scour?	15	19		79	
	2. Height appropriate?	17	19		90	
	3. Angle and geometry appear appropriate?	19	19		100	
	4. Free of piping or other structural failures?	14	19		73	85
G. Wads / Boulders	1. Free of Scour?	25	26		96	
	2. Footing Stable?	25	26		96	96


APPENDIX B

7. CROSS SECTION PLOTS AND RAW DATA TABLES

Survey Data

2004		9/22/2005		10/10/2006		Notes
Station	Foreshot	Station	Foreshot	Station	Foreshot	
0	5.63	0	4.67	0	11.21	Gr. L.Pin
5	5.89	10	5.42	5	11.52	
15	6.76	15	5.94	10	11.87	
18	7.35	20	6.91	15	12.26	
21	7.84	25	7.79	20	13.14	
23	8.37	30	8.28	21	13.46	
25	8.81	31	8.28	22	13.65	
26	9.07	32	8.28	23	13.85	
30	9.09	33	8.36	24	14.11	
35	8.95	34	8.39	25	14.19	
39	9.15	35	8.23	26	14.3	
41	9.35	36	8.04	27	14.58	
42.8	9.93	37	8.14	28	14.61	
45	10.49	38	8.21	29	14.71	
47	10.83	39	8.65	30	14.73	BKF
49	11.17	39.1	9.65	31	14.76	LNW
50	11.37	40	10.17	32	14.62	SH
52	11.57	41	10.17	33	14.54	SH
53	11.58	42	10.16	34	14.44	SH
54	11.58	43	10.03	35	14.51	SH
54.3	11.43	44	9.92	36	14.56	SH
54.6	10.30	45	9.91	37	14.45	SH
55	10	46	10.09	38	14.46	SH
55.5	9.04	47	10.21	39	14.59	CL
57	8.2	48	9.86	40	16.49	SH
61	7.74	49	8.25	41	16.48	SH
68	7.17	50	7.68	42	16.45	WS
75	6.44	51	7.27	43	16.33	
90	5.68	52	6.75	44	16.12	
105.6	5.48	53	6.50	45	16.11	
		54	5.87	46	16.23	
		63	5.86	47	16.42	
		67.2	5.93	48	16.58	
				49	16.43	
				50	14.93	
				51	14.22	
				52	13.53	
				53	13.13	
				54	12.71	
				55	12.64	
				60	12.24	
				65	12.24	
				67.9	12.29	Gr. Rl. Pin

Summary Data			
	2004	2005	2006
Bankfull Cross Sectional Area (ft ²)	33.0	13.4	11.4
Bankfull Width (ft)	31.0	9.9	10.5
Bankfull Mean Depth (ft)	1.1	1.4	1.1
Bankfull Max Depth (ft)	2.8	1.6	1.4
Width/Depth Ratio	29.2	7.3	9.7
Entrenchment Ratio	2.5	N/A	N/A
Classification	-	-	-




Title		Project		Project #	
Lower Section - Pool Cross Section		Suck Creek Stream Restoration Project		011795208	
Location		Survey Date		Field Team	
Moore County, NC		October 10, 2006		Tisha Johnson, Mike O'Rourke	
Survey Weather		Location		Figure	
Sunny, 30° F		Lower Reach			

Survey Data

Station	Foreshot	Station	Foreshot	Notes	Station	Foreshot	Notes
0	3/24/2004	0	9/20/2005	1.B	0	8/22/2006	On I.P.m
6	5.98	10	11.51		2	13.65	
14	6.32	15	12.23		4	13.84	
17	7.13	20	12.71		6	14.01	
21	7.50	21	13.55		8	14.1	
23	8.20	22	13.74		10	14.31	
26.4	8.73	22	14.00		12	14.5	
27.2	9.92	23	14.24		13	14.71	
31	10.05	24	14.43		19.5	15.65	
33	10.64	25	14.59	SB	22	16.1	
35	10.70	26	14.60	SB	23	16.42	
37	10.93	27	15.55	SB	24	16.54	BKF
38	10.85	28	16.07	LEW	25	16.74	
39.7	10.15	29	16.18	SB	26	16.9	
40	9.44	30	15.87	SB	27	17.69	
41	8.84	31	16.01	SB	28	18.28	WS
50	7.76	32	15.90	SB	29	18.58	
55	7.21	33	15.84	SB	30	18.34	
66	7.10	34	15.98	SB	31	18.16	
		35	15.91	CI	32	17.97	
		36	16.41	SB	33	17.94	
		37	16.48	SB	34	17.84	
		38	16.47	SB	35	18.03	
		39	15.87	SB	36	18.31	
		40	15.18	SB	37	18.38	
		41	14.52	BKF	38	18.41	
		42	14.20		38.5	18.22	
		43	14.05		40	17.47	
		44	13.93		41	16.76	
		45	13.79		42	16.26	
		46	13.28		44	16.06	
		60	12.56		45	15.9	
		65.6	12.67	RB	46	15.74	
					47	15.6	
					48	15.47	
					49	15.46	
					50	15.38	
					54	14.96	
					58	14.79	
					62	14.79	
					66	14.75	Gr R/P.m


Summary Data			
	2004	2005	2006
Bankfull Cross Sectional Area (ft ²)	27.4	20.9	20.5
Bankfull Width (ft)	20.7	16.6	16.6
Bankfull Mean Depth (ft)	1.3	1.2	1.2
Bankfull Max Depth (ft)	2.2	2.0	1.9
Width/Depth Ratio	15.6	13.2	13.4
Enrichment Ratio	3.2	N/A	N/A
Classification			

Title Lower Section - Riffle Cross Section
Project Suck Creek Stream Restoration Project
 Moore County, NC
Survey Date August 22, 2006
Survey Weather Sunny, 30° F
Field Team Richard Bolton, Tisha Johnson, Mike O'Rourke
Project # 011795008
Location Lower Reach



Survey Data

Cross Section - Upper Riffle
Cross Section Plot - Looking Downstream



Cross Section Photo - Looking Downstream



Station	Foreshot	Station	Foreshot	Notes	Station	Foreshot	Notes
0	5.82	0	5.69	LB	0	5.68	Gr LPin
7	6.18	5	5.92		4	5.81	
15	6.85	10	6.25		8	6	
19	7.45	15	6.74		12	6.28	
22	8.28	20	7.61		15	6.63	
24	9.03	23	8.73		18	7.08	
25	9.39	24	9.02		20	7.65	
28	9.56	25	9.26		22	8.17	
29.7	10.44	26	9.35	BKF	23	8.66	
32	10.84	27	9.37	SB	24	8.97	
34	11.00	28	9.41	SB	25	9.18	
36	11.00	29	9.74	SB	26	9.22	
38	10.90	30	10.42	LEW	27	9.23	
39.5	10.50	31	10.50	SB	28	9.23	
41	10.00	32	10.60	SB	29	9.65	
43	9.72	33	10.69	SB	30	10.37	
45.5	9.55	34	10.86	CL	30.3	10.33	WSF
48	9.01	35	10.95	SB	32	10.6	
50	8.35	36	10.69	SB	33	10.51	
52	7.94	37	10.64	SB	34	10.7	
56	7.82	38	10.64	SB	35	10.87	
59.5	7.78	39	10.43	SB	36	10.65	
		40	10.17	SB	37	10.4	
		41	9.66	SB	38	10.54	
		42	9.60	SB	39	10.32	
		43	9.58	SB	40	10.1	
		44	9.52	SB	41	9.79	
		45	9.42	SB	42	9.51	
		46	9.03		44	9.44	
		47	9.07		46	9.02	BKF
		48	8.86		50	8.08	
		49	8.63		54	7.65	
		50	8.15		58	7.63	
		51	7.85		61	7.78	Gr RPin
		52	7.68				
		53	7.68				
		54	7.68				
		55	7.67				
		59.9	7.88	RB			

Summary Data


	2004	2005	2006
Bankfull Cross Sectional Area (ft ²)	18.1	15.2	15.7
Bankfull Width (ft)	21.2	19.2	17
Bankfull Mean Depth (ft)	0.9	0.8	0.9
Bankfull Max Depth (ft)	1.6	1.6	1.6
Width/Depth Ratio	25.0	24.2	18.5
Entrainment Ratio	2.8	N/A	N/A

Title	Upper Section - Riffle Cross Section	Project #	011795008
Project	Suck Creek Stream Restoration Project	Field Team	Richard Bolton, Tisha Johnson, Mike O'Rourke
Location	Moore County, NC	Survey Weather	Sunny, 90° F
Survey Date	August 22, 2006	Location	Upper Reach



Survey Data

Cross Section - Upper Pool
Cross Section P10r - Looking Downstream



Cross Section Photo - Looking Downstream



Station	Forefoot	Station	Forefoot	Notes	Station	Forefoot	Notes
0	6.02	0	5.92	LB	0	5.71	Gr LPin
5	6.42	5	6.24		1	5.71	
10	7.07	10	6.92		2	5.83	
14	7.74	15	7.80		3	5.97	
16	8.25	16	8.14		4	6.07	
18	8.85	17	8.22		5	6.09	
20	9.45	18	8.52		6	6.2	
20.8	10.05	19	8.89		7	6.47	
22	10.82	20	9.21		8	6.53	
24	11.30	21	9.76		9	6.63	
25	11.48	22	10.85	LEW	10	6.67	
26	11.42	23	11.03	SB	11	6.86	
28	11.05	24	11.31	SB	12	7.09	
30	10.52	25	11.43	CL	13	7.28	
32	10.05	26	11.37	SB	14	7.41	
35	9.48	27	11.28	SB	15	7.57	
40	9.42	28	11.09	SB	16	7.73	
41	9.02	29	10.88	SB	17	7.98	
44.8	8.71	30	10.88	SB	18	8.3	
47	8.15	30.6	10.42	REW	19	8.49	
50	8.19	31	10.26	SB	20	8.94	
57	8.05	32	10.04	SB	21	9.28	
		33	9.63	SB	21.7	10.11	LEW
		34	9.52	SB	22	10.51	
		35	9.29	SB	23	10.79	
		36	9.35	SB	24	10.94	
		37	9.27	SB	25	11.15	
		38	9.32	SB	26	11.33	
		39	9.35	SB	27	11.17	
		40	9.39	SB	28	10.92	
		41	9.11	SB	29	10.67	
		42	8.86	BKF	30	10.39	
		43	8.86		31	10.06	REW
		44	8.86		32	9.88	
		45	8.63		33	9.62	
		50	8.04		34	9.35	
		55	8.08		35	9.09	
		57.7	7.99	RB	36	9.09	
					37	9.09	
					38	9.11	
					39	9.11	
					40	9.19	
					41	9.01	
					42	8.67	
					43	8.66	BKF
					44	8.63	
					45	8.47	
					46	8.23	
					47	7.91	
					48	7.86	
					50	7.86	
					55	7.98	
					58.4	7.66	Gr RPIn

Summary Data	
Bankfull Cross Sectional Area (ft ²)	2/004 34.3
Bankfull Width (ft)	2/005 32.5
Bankfull Mean Depth (ft)	2/006 28.8
Bankfull Max Depth (ft)	2/004 27.3
Width/Depth Ratio	2/004 1.8
Excess/Depth Ratio	2/004 2.8
Excess/Depth Ratio	2/005 2.7
Excess/Depth Ratio	2/006 2.1
Classification	N/A

Title: Upper Section - Pool Cross Section
Project: Stick Creek Stream Restoration Project
Location: Moore County, NC


Survey Date: August 22, 2006
Survey Weather: Sunny, 90° F
Field Team: Richard Bolton, Tisha Johnson, Mike O'Rourke
Project # Figure: 011795008
Location: Upper Reach




APPENDIX B

8. LONGITUDINAL PLOTS AND RAW DATA TABLES

Upper Longitudinal Profile							
Feature	Station	Feature Length	Thalweg Elevation	Water Elevation	Bankfull Elevation	Water Surface Slope	Depth at Bankfull
	ft.	ft.	ft.	ft.	ft.	ft./ft.	ft.
Cross Vane - Top	0		346.64	346.75	348.00		1.36
Pool	2	14	345.35	346.75	348.00	0.00	2.65
Pool	7.2	7	345.04	346.75	348.00	0.00	2.96
Glide	14	7	345.84	346.75	348.00	0.00	2.16
Riffle	21	13	346.42	346.75	348.24	0.04	1.82
Run	34	19	346.04	346.79	348.13	-0.11	2.09
Pool	53	86	345.64	346.68	348.13	0.04	2.49
Pool	63		344.68	346.68	347.91		3.23
Glide	139	10	346.25	346.72	348.11	0.03	1.86
Riffle	149	3	346.33	346.75	348.11	-0.16	1.78
Pool	152	56	345.10	346.59	347.57	0.00	2.47
Pool	157		344.84	346.59	347.57		2.73
Glide	208	7	346.09	346.59	348.04	-0.05	1.95
Riffle	215	1	346.54	346.54	347.90	-0.12	1.36
Pool	216	29	345.50	346.42	347.90	-0.03	2.4
Pool	224		345.20	346.42	347.90		2.7
Glide	245	10	345.75	346.39	347.33	0.00	1.58
Riffle	255	26	346.03	346.39	347.23	0.02	1.2
Pool	281	65	345.64	346.41	347.37	-0.09	1.73
Pool	300		344.76	346.40	347.37		2.61
Riffle	346	9	345.99	346.32	347.19	-0.19	1.2
Pool	355	12	345.63	346.13	347.19	0.02	1.56
Pool	361		345.18	346.13	347.19		2.01
Glide	367	14	345.69	346.15	347.57	0.01	1.88
Riffle	381	13	345.87	346.16	347.54	-0.01	1.67
Run	394	15	345.80	346.15	347.24	-0.24	1.44
Pool	409		346.05	345.91	346.55		0.5



8. Longitudinal Profiles
Longitudinal Profile - Upper Reach



Suck Creek - Lower Reach Long Profile

Feature	Station	Feature Length	Thalweg Elevation	Water Elevation	Bankfull Elevation	Water Surface Slope	Depth at Bankfull
Cross Vane - Top	0		339.88	339.89	342.74	0.00	2.86
Pool	6	40	336.52	339.89	342.74	0.00	6.22
Glide	40	22	339.09	339.89	343.14	0.00	4.05
Riffle	62	26	339.77	339.89	342.31	-0.40	2.54
Run	88	14	339.18	339.49	340.84	0.00	1.66
Pool	102	42	338.38	339.49	340.84	0.00	2.46
Pool	115		337.81	339.49	340.84		3.03
Glide	144	14	338.90	339.49	340.79	-0.03	1.89
Run	158	14	339.40	339.46	340.79	-0.08	1.39
Pool	172	45	337.99	339.38	340.56	-0.01	2.57
Pool	197		337.82	339.37	341.70		3.88
Glide	217	26	338.41	339.37	340.47	0.03	2.06
Riffle	243	27	339.14	339.40	340.47	-0.24	1.33
Run	270	21	338.79	339.16	341.43	0.00	2.64
Pool	291	77	337.60	339.16	341.87	0.00	4.27
Pool	298		337.17	339.16	341.87		4.7
Pool	350		339.01	339.16	341.87		2.86
Pool	358		337.65	339.16	341.89		4.24
Glide	368	7	338.47	339.16	341.89	0.10	3.42
Riffle	375	8	339.03	339.26	341.04	-0.11	2.01
Pool	383	24	338.47	339.15	341.04	0.00	2.57
Pool	390		338.25	339.15	341.04		2.79
Glide	407	11	338.51	339.15	341.04	-0.01	2.53
Riffle	418	21	338.94	339.14	340.61	-0.35	1.67
Run	439	20	338.50	338.79	340.37	-0.04	1.87
Pool	459	47	338.29	338.75	340.37	-0.05	2.08
Pool	476		337.23	338.75	340.37		3.14
Glide	506	15	337.74	338.70	339.98	0.08	2.24
Riffle	521		338.68	338.78	340.25		1.57


Longitudinal Profile - Lower Reach

APPENDIX B

9. PEBBLE COUNT PLOTS AND RAW DATA TABLES

9. Sediment Distribution

Upper Riffle Cross Section



Lower Riffle
Cross Section

