

CRC-VR-15-08

A rehearing on remand of CRC-VR-06-33

Attachment G:

Stipulated Exhibit No. 7
Powerpoint Presentation

The Riggings HOA Variance Request

November 17, 2015



Department of Environmental Quality



map.



Department of Environmental Quality




Department of Environmental Quality

View of Site Facing East
Google Earth Photography



Department of Environmental Quality

View of Site Facing West
DCM Aerial Photography
September 13, 1994



Department of Environmental Quality

View of Site Facing West
DCM Aerial Photography
September 13, 1994



Department of Environmental Quality

View of Existing Sandbags
DCM Photography Facing South
September 13, 1994



Department of Environmental Quality

View of Existing Sandbags
DCM Photography Facing North
September 13, 1994



Department of Environmental Quality



View of Existing Sandbags
DCM Photography Facing West
September 13, 1994



View of Existing Sandbags
DCM Photography Facing South
September 13, 1994

Department of Environmental Quality



View of Existing Sandbags
DCM Photography Facing North
September 13, 1994

Department of Environmental Quality

View of Site Facing West
DCM Aerial Photography
January 5, 1995



Department of Environmental Quality

View of Site Facing West
DCM Aerial Photography
January 5, 1995



Department of Environmental Quality



Department of Environmental Quality



View of Existing Sandbags
Facing North
DCM Photography
November 1999

Department of Environmental Quality

View of Existing Sandbags
Facing South
DCM Photography
November 1999



Department of Environmental Quality

View of Existing Sandbags Facing North
DCM Photography
November 1999



Department of Environmental Quality

View of Site Facing West
DCM Aerial Photography
February 2000




Department of Environmental Quality



View of Site Facing South
DCM Aerial Photography
February 2000

Department of Environmental Quality

View of Site Facing Southwest
DCM Aerial Photography
February 2000



Department of Environmental Quality

View of Existing Sandbags Facing South
DCM Photography
April 21, 2003



Department of Environmental Quality

View of Existing Sandbags Facing North
DCM Photography
April 21, 2003




Department of Environmental Quality

View of Existing Sandbags Facing South
DCM Photography
March 10, 2005



Department of Environmental Quality

View of Existing Sandbags Facing North
DCM Photography
March 10, 2005



Department of Environmental Quality

View of Existing Sandbags Facing South
DCM Photography
October 8, 2006



Department of Environmental Quality

View of Existing Sandbags Facing North
DCM Photography
November 9, 2006



Department of Environmental Quality

View of Existing Sandbags Facing South
DCM Photography
November 9, 2006



Department of Environmental Quality

View of Existing Sandbags Facing South
DCM Photography
January 4, 2007



Department of Environmental Quality

View of Site Facing Southwest
DCM Aerial Photography
April 20, 2007



View of Existing Sandbags Facing South
DCM Photography
December 11, 2007



Department of Environmental Quality

View of Existing Sandbags Facing North
DCM Photography
December 11, 2007



Department of Environmental Quality



View of Existing Sandbags Facing North
DCM Photography
April 2012

View of Site Facing West
DCM Aerial Photography
September 28, 2012



Department of Environmental Quality

View of Existing Sandbags Facing South
DCM Photography
October 13, 2015



Department of Environmental Quality

View of Existing Sandbags Facing West
DCM Photography
October 13, 2015



Department of Environmental Quality

View of Existing Sandbags Facing North
DCM Photography
October 13, 2015



Department of Environmental Quality

View of Existing Coquina Rock
Facing South
DCM Photography
October 13, 2015



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

February 14, 2013
Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality

January 2, 2013
Photography Provided by Petitioner



Department of Environmental Quality