

MY0 FINAL MONITORING REPORT

BRAHMA SITE

Alamance County, North Carolina
Cape Fear River Basin
Cataloging Unit 03030002

DMS Project No. 100092
Full Delivery Contract No. 7743
DMS RFP No. 16-007571
USACE Action ID No. SAW-2019-00126
DWR Project No. 20190158

Data Collection: December 2020-January 2021
Submission: April 2021



Prepared for:

NORTH CAROLINA DEPARTMENT OF ENVIRONMENTAL QUALITY
DIVISION OF MITIGATION SERVICES
1652 MAIL SERVICE CENTER
RALEIGH, NORTH CAROLINA 27699-1652



MY0 FINAL MONITORING REPORT

BRAHMA SITE

Alamance County, North Carolina
Cape Fear River Basin
Cataloging Unit 03030002

DMS Project No. 100092
Full Delivery Contract No. 7743
DMS RFP No. 16-007571
USACE Action ID No. SAW-2019-00126
DWR Project No. 20190158

Data Collection: December 2020-January 2021
Submission: April 2021

Prepared for:

NORTH CAROLINA DEPARTMENT OF ENVIRONMENTAL QUALITY
DIVISION OF MITIGATION SERVICES
1652 MAIL SERVICE CENTER
RALEIGH, NORTH CAROLINA 27699-1652



Prepared by:



Restoration Systems, LLC
1101 Haynes Street, Suite 211
Raleigh, North Carolina 27604
Contact: Worth Creech
919-755-9490 (phone)
919-755-9492 (fax)

And



Axiom Environmental, Inc.
218 Snow Avenue
Raleigh, North Carolina 27603
Contact: Grant Lewis
919-215-1693 (phone)



April 9, 2021

Ms. Lindsay Crocker
NC DEQ – Division of Mitigation Services
1652 Mail Service Center
Raleigh, North Carolina
27699-1652

Subject: Brahma Stream and Wetland Mitigation Site: As-Built Comment Responses
NC DMS Contract # 7743 RFP # 16-007571 DMS Project No. 100092

Dear Ms. Crocker,

Restoration Systems is pleased to provide you with the Final As-Built Baseline Monitoring Report (MY0) for the Brahma Stream and Wetland Mitigation Site. We have addressed your comments as follows.

1. Table 1. Check UT2A and UT2. It appears that the lengths may have been swapped/typo.
[This typo was corrected for this submittal.](#)
2. CCPV shows a gray line for 'no credit' stream. Clarify if there are any areas of "no stream credit" on this project.
["No stream credit" areas include crossings at easement breaks.](#)
3. Soil boring logs. Double check log for gauge 11. May be a typo (gauge 10 listed two times).
[This typo was corrected for this submittal.](#)
4. There appear to be additional tree species planted. The selected species are desirable diversity, but please confirm that they meet the target community as described in Mitigation Plan. Add a sentence in the baseline report to describe these changes.
[A sentence was added in the discussion of deviations from the construction plans explaining that the additional species are typical for the target community type.](#)
5. Include information on permanent and/or temporary seed mix and any soil amendments if utilized.
[Permanent/temporary seed mix and soil amendment info was added to the report.](#)
6. Provide a map or show on CCPV location of benthic sampling. The Mitigation Plan states that location of benthics will be established at the time of pre-construction benthic monitoring.
[Benthic sampling locations were added to the CCPV.](#)
7. There was proposed fencing plan in the construction drawings. Was fencing installed as constructed? If there were changes, please show them in the drawings or add that page into the as-built.
["Figure F-1. Asbuilt Fencing" was added into Appendix F.](#)

8. In the field, there were discussions that this site has had numerous large storm events since construction. It may be beneficial to describe those in the report text relation to stream stability.
[A brief discussion of the numerous rain events was added to Section 1.1.](#)
9. Include any pictures and/or videos to assist IRT in visualizing.
[A link to a drone video of the site is provided at the end of the "Project Summary" section.](#)

Electronic comments:

1. The feature for UT-2 has a length of 1359.76 ft vs the 1392 ft reported in Table 1. Please review and revise either the feature or Table 1.
[The as-built length of UT-2 was revised in Table 1 to match the length of the feature in the surveyed as-built centerline.](#)
2. Please attribute the stream gauge features with the unique ID's that will be used to associate these points with stream gauge figures.
[The features in the stream gauges shapefile were attributed properly.](#)
3. Submit existing stream and wetland features or confirm if these were transmitted during 401/401 process.
[The preconstruction stream and wetland shapefiles have been included in the digital submittal.](#)

Requests:

4. Submit a dwg file that includes the layers used in the as-built drawings.
[We do not use AutoCAD and therefore do not have .dwg files for as-built drawings.](#)
5. Submit a shapefile containing stream structures as point features.
[A stream structures point file is included in the digital submittal.](#)
6. Submit transect features as polygons.
[A transect polygon file is included in the digital submittal.](#)
7. Remove elevation tables from behind profile figures (pages 44-49) for future submittals.
[Elevation tables will be removed from profile figures for future submittals.](#)

Sincerely,



Worth Creech
Restoration Systems, LLC

TABLE OF CONTENTS

1.0 PROJECT SUMMARY	1
1.1 PROJECT BACKGROUND, COMPONENTS, AND STRUCTURE	1
1.2 PROJECT GOALS AND OBJECTIVES	5
1.3 SUCCESS CRITERIA	7
2.0 METHODS	7
2.1 MONITORING.....	7
3.0 REFERENCES	10

APPENDICES

Appendix A. Visual Assessment Data	
Figure 1. Current Conditions Plan View	
Table 4A-G. Visual Stream Morphology Stability Assessment Table	
Table 5. Vegetation Condition Assessment Table	
Vegetation Plot Photographs	
Cross-Section Photographs	
Appendix B. Vegetation Plot Data	
Table 6A. Planted Bare-Root Woody Vegetation	
Table 6B. Permanent Seed Mix	
Table 7. Vegetation Plot Counts and Densities	
Table 8. Vegetation Plot Data Table from Vegetation Data Entry Tool	
Appendix C. Stream Geomorphology Data	
Cross-Sections with Annual Overlays	
Longitudinal Profile	
Table 9A-D. Baseline Stream Data Summary Tables	
Table 10A-B. Cross-Section Morphology Monitoring Summary	
Appendix D. Hydrologic Data	
Groundwater Gauge Soil Profiles	
Appendix E. Project Timeline and Contact Info	
Table 11. Project Timeline	
Table 12. Project Contacts	
Appendix F. Other Data	
Preconstruction Benthic Results	
Preconstruction Benthic Habitat Assessment Data Forms	
Figure F-1. Asbuilt Fencing	

1.0 PROJECT SUMMARY

Restoration Systems, LLC has established the North Carolina Division of Mitigation Services (NCDMS) Brahma Site (Site).

1.1 Project Background, Components, and Structure

The Brahma Site (hereafter referred to as the “Site”) encompasses 22.7 acres of disturbed forest and livestock pasture along unnamed tributaries to Reedy Branch (warm water streams in the Jordan Lake watershed). The Site is located approximately 2 miles south of Snow Camp, NC, 5 miles northeast of Silk Hope, NC, and southwest of Clark Road (SR 2352) in southern Alamance County.

Prior to construction, land use at the Site is characterized by disturbed forest and livestock pasture. Riparian zones are primarily composed of herbaceous vegetation that is sparse and disturbed due to livestock grazing, bush hogging, and regular land-management activities.

During mitigation plan preparation, two Pilgrim’s Pride chicken houses were being constructed on the property adjacent to the southeast portion of UT 1. The chicken houses were constructed on pads that have a groundwater drainage network leading to two pipes that discharge adjacent to the easement. The pipes do not drain effluent from the chicken houses and discharge clean water. Most drainage from the chicken house facilities drains through a draw that is treated at the easement boundary and then discharged in wetlands prior to entering Site tributaries.

Chicken waste management is being managed through a Joint Responsibility – Producer/Third-Party Applicator agreement in a manner consistent with requirements set forth by the State of North Carolina in 15A NCAC 02T Section 1400 (Manure Hauler Regulations) and NRCS standard 633 (Waste Utilization). Documentation of the agreement is available upon request. Under the agreement the producer maintains the responsibility for keeping records on the amount of waste generated by the operation and providing the responsible third party with waste analysis records. The third-party applicator is responsible for applying materials at agronomic rates, soil testing, field evaluation, etc.

At present, no waste is to be discharged onto the property adjacent to the Site easement. If waste management changes at the property, there are minimum setbacks for waste management that include 100 feet from perennial waters.

Since construction was completed, the Site has endured multiple large storm events and well above average rainfall. All Site stream reaches have remained remarkably stable with no significant change from as-built conditions.

Proposed Site restoration activities generated 3881.066 Stream Mitigation Units (SMUs) and 6.655 Riparian Wetland Mitigation Units (WMUs) as described in Table 1.

Additional activities that occurred at the Site included the following.

- Planting 17.7 acres of the Site with 20,200 stems (planted species are included in Table 6 [Appendix B]).
- Treating fescue with mowing and glyphosate prior to planting.

- Applying a Site-wide temporary cover of winter rye (*Secale cereale*) as well as a temporary soil health seed mix consisting of white clover (*Trifolium repens*), red clover (*Trifolium pratense*), crimson clover (*Trifolium incarnatum*), berseem clover (*Trifolium alexandrinum*), chicory (*Cichorium intybus*), and purple top turnips (*Brassica rapa*) at a rate of 13 lbs per acre in areas of cut or high compaction.
- Applying a permanent seed mix at 2 lbs per acre across the Site. A species list is included in Table 6B (Appendix B).
- Fencing the entire conservation easement.

Deviations from the construction plans are summarized in the following table.

Location	Deviation	Explanation
UT-1 sta. 2+65	Vane arm not constructed	Limits of disturbance
UT-1 sta. 3+05	Vane arm not constructed	Field conditions
UT-1 sta. 6+70	(2) 18-inch pipes not constructed	Existing floodplain elevation same as proposed pipe invert
UT-1 sta. 9+20	Log vane structure not constructed	Existing mature tree
UT-1 sta. 10+60	Log vane structure relocated	Bedrock contact
UT-1 sta. 13+90	Log cross vane replaced with boulder sill	Mature tree with root mass
UT-1 sta. 15+15	Log vane structure replaced with log sill	
UT-1 sta. 15+35	Log vane structure replaced with boulder toe	Bedrock contact
UT-1 sta. 16+10	Log vane structure not constructed	Mature tree with root mass
UT-1 sta. 18+00	Log cross vane replaced by stone cross vane	Existing mature trees
UT-1 sta. 18+50	Log cross vane replaced by stone cross vane	
UT-1 sta. 19+20	Log cross vane structure replaced with (2) log sills	Bedrock contact
UT-1 sta. 27+90	(2) 18-inch pipes not constructed	Floodplain elevations the same as proposed pipe inverts
UT-1 sta. 29+05	Log cross vane structure replaced with stone boulder sill	Mature tree with root mass
UT-1 sta. 29+35 to 29+80	Alignment change	Bedrock
UT-1 sta. 31+05	Log cross vane structure replaced with boulder sill	Mature tree with root mass
UT-1 sta. 31+90	Log cross vane structure replaced with boulder cross vane	Bedrock contact
UT-1 sta. 33+50	Log sill added	To maintain grade above crossing
UT-1 sta. 33+95	Log vane structure replaced with log sill	Bedrock contact
UT-1 sta. 34+05	Log cross vane structure replaced with log sill	
UT-2 sta. 12+20	Log cross vane structure replaced with log sill	Floodplain elevations causing arms to sit on top of existing grade
UT-2 sta. 12+50	Log cross vane structure replaced with log sill	
UT-2 sta. 13+00	(2) 18-inch pipes not constructed	Floodplain elevations the same as proposed pipe inverts
UT-6 sta. 2+25	Log cross vane structure not constructed	Mature tree with root mass
UT-6 sta. 3+00	Log cross vane structure replaced with stone cross vane	Mature trees, roots, and bedrock
UT-6 sta. 3+85	Log cross vane structure replaced with stone cross vane	
UT-6 sta. 4+00	Log cross vane structure replaced with stone cross vane	
UT-6 sta. 4+30	Log cross vane structure replaced with stone cross vane	Bedrock contact

Additionally, several species were added to the Site planting list that were not included in the mitigation plan planting list (Table 6, Appendix B); however, these are typical species for a piedmont alluvial forest, the target natural community type, and they are expected to thrive.

No other deviations of significance occurred between construction plans and the as-built condition. In addition, no issues have arisen since construction occurred.

A reach-by-reach drone video of the Site can be viewed at the following link:
<https://youtu.be/OeoAZUN09ww>

Table 1. Brahma (ID-100092) Project Mitigation Quantities and Credits

Project Segment	Original Mitigation Plan Ft/Ac	As-Built Ft/Ac	Original Mitigation Category	Original Restoration Level	Original Mitigation Ratio (X:1)	Credits	Comments
Stream							
UT-1A	3034	3121	Warm	EI	1.50000	2,022.667	
UT-1B	192	191	Warm	EII	2.50000	76.800	
UT-1C	911	911	Warm	P	10.00000	91.100	
UT-2	1354	1360	Warm	EII	2.50000	541.600	
UT-2A	30	30	Warm	EII	2.50000	12.000	
UT-3	239	245	Warm	R	1.00000	239.000	
UT-4	129	135	Warm	EII	2.50000	51.600	
UT-5	626	631	Warm	EII	2.50000	250.400	
UT-6	501	511	Warm	R	1.00000	501.000	
UT-7	47	48	Warm	EII	2.50000	18.800	
					Total:	3,804.967	
Wetland							
Wetland Reestablish	4.740	4.736	R	REE	1.00000	4.740	
Wetland Enhancement	3.709	3.708	R	E	2.00000	1.855	
Wetland Preservation	0.601	0.601	R	P	10.00000	0.060	
					Total:	6.655	

Project Credits

Restoration Level	Stream			Riparian	Non-Rip	Coastal
	Warm	Cool	Cold	Wetland	Wetland	Marsh
Restoration	740.000			0.000	0.000	0.000
Re-establishment	0.000			4.740	0.000	0.000
Rehabilitation	0.000			0.000	0.000	0.000
Enhancement	0.000			1.855	0.000	0.000
Enhancement I	2,022.667	0.000	0.000			
Enhancement II	951.200	0.000	0.000			
Creation				0.000	0.000	0.000
Preservation	91.100	0.000	0.000	0.060	0.000	
Benthics 2%	76.099	0.000	0.000	0.000	0.000	
Totals	3,881.066	0.000	0.000	6.655	0.000	0.000

Total Stream Credit 3,881.066

Total Wetland Credit 6.655

Site design was completed in August 2020. Construction started on September 15, 2020 and ended within a final walkthrough on December 9, 2020. The Site was planted on January 12, 2021. Completed project activities, reporting history, completion dates, and project contacts are summarized in Tables 11-12 (Appendix E).

1.2 Project Goals and Objectives

Project goals are based on the *Cape Fear River Basin Restoration Priorities* (RBRP) report (NCEEP 2009) and on-site data collection of channel morphology and function observed during field investigations. The Site is located within **Targeted Local Watershed (TLW) 03030002050050**. The RBRP report documents benthic ratings vary between “Fair” and “Good-Fair” possibly due to cattle, dairy, and poultry operations. The project is not located in a Regional or Local Watershed Planning Area; however, RBRP goals are addressed by project activities as follows with Site specific information following the RBRP goals in parenthesis.

1. Reduce and control sediment inputs – reduction of 8.0 tons/year after mitigation is complete);
2. Reduce and manage nutrient inputs - livestock removed from streams resulting in a direct reduction of 1020.8 pounds of nitrogen, 84.6 pounds of phosphorus per year, and 11.2×10^{11} colonies of fecal coliform; fertilizer application has been eliminated; and marsh treatment areas were installed);
3. Protect and augment designated natural heritage areas (NA).

Site specific mitigation goals and objectives were developed through the use of North Carolina Stream Assessment Method (NC SAM) and North Carolina Wetland Assessment Method (NC WAM) analyses of preconstruction and reference stream systems at the Site (NC SFAT 2015 and NC WFAT 2010) (see table below).

Table 2. Summary: Goals, Performance, and Results

Targeted Functions	Goals	Objectives	Compatibility with Success Criteria
(1) HYDROLOGY			
(2) Flood Flow	<ul style="list-style-type: none"> Attenuate flood flow across the Site. Minimize downstream flooding to the maximum extent possible. Connect streams to functioning wetland systems. 	<ul style="list-style-type: none"> Construct new channel at historic floodplain elevation to restore overbank flows and restore jurisdictional wetlands Plant woody riparian buffer Remove livestock Deep rip floodplain soils to reduce compaction and increase soil surface roughness Protect riparian buffers with a perpetual conservation easement 	<ul style="list-style-type: none"> BHR not to exceed 1.2 Document four overbank events in separate monitoring years Livestock excluded from the easement Attain Wetland Hydrology Success Criteria Attain Vegetation Success Criteria Conservation Easement recorded
(4) Wooded Riparian Buffer			
(4) Microtopography			
(3) Stream Stability	<ul style="list-style-type: none"> Increase stream stability within the Site so that channels are neither aggrading nor degrading. 	<ul style="list-style-type: none"> Construct channels with proper pattern, dimension, and longitudinal profile Remove livestock Construct stable channels with appropriate substrate Plant woody riparian buffer Stabilize stream banks 	<ul style="list-style-type: none"> Cross-section measurements indicate a stable channel with appropriate substrate Visual documentation of stable channels and structures BHR not to exceed 1.2 ER of 2.2 or greater < 10% change in BHR and ER in any given year Livestock excluded from the easement Attain Vegetation Success Criteria
(4) Sediment Transport			
(4) Stream Geomorphology			
(1) WATER QUALITY			
(2) Streamside Area Vegetation	<ul style="list-style-type: none"> Remove direct nutrient and pollutant inputs from the Site and reduce contributions to downstream waters. 	<ul style="list-style-type: none"> Remove livestock and reduce agricultural land/inputs Install marsh treatment areas Plant woody riparian buffer Restore/enhance jurisdictional wetlands adjacent to Site streams Provide surface roughness and reduce compaction through deep ripping/plowing. Restore overbank flooding by constructing channels at historic floodplain elevation. 	<ul style="list-style-type: none"> Livestock excluded from the easement Attain Wetland Hydrology Success Criteria Attain Vegetation Success Criteria
(3) Upland Pollutant Filtration			
(2) Indicators of Stressors			
(2) Aquatic Life Tolerance			
Wetland Particulate Change			
Wetland Physical Change			
(1) HABITAT			
(2) In-stream Habitat	<ul style="list-style-type: none"> Improve instream and stream-side habitat. 	<ul style="list-style-type: none"> Construct stable channels with appropriate substrate Plant woody riparian buffer to provide organic matter and shade Construct new channel at historic floodplain elevation to restore overbank flows Plant woody riparian buffer Protect riparian buffers with a perpetual conservation easement Restore/enhance jurisdictional wetlands adjacent to Site streams Stabilize stream banks Install in-stream structures 	<ul style="list-style-type: none"> Cross-section measurement indicate a stable channel with appropriate substrate Visual documentation of stable channels and in-stream structures. Attain Wetland Hydrology Success Criteria Attain Vegetation Success Criteria Conservation Easement recorded
(3) Substrate			
(3) In-Stream Habitat			
(2) Stream-side Habitat			
(3) Stream-side Habitat			
(3) Thermoregulation			
Wetland Physical Structure			
Wetland Landscape Patch Structure			

1.3 Success Criteria

Monitoring and success criteria for stream restoration should relate to project goals and objectives identified from on-site NC SAM data collection. From a mitigation perspective, several of the goals and objectives are assumed to be functionally elevated by restoration activities without direct measurement. Other goals and objectives will be considered successful upon achieving success criteria. The following summarizes Site success criteria.

Success Criteria

Streams
<ul style="list-style-type: none"> All streams must maintain an Ordinary High-Water Mark (OHWM), per RGL 05-05. Continuous surface flow must be documented each year for at least 30 consecutive days. Bank height ratio (BHR) cannot exceed 1.2 at any measured cross-section. Entrenchment ratio (ER) must be no less than 2.2 at any measured riffle cross-section. BHR and ER at any measure riffle cross-section should not change by more than 10% from baseline condition during any given monitoring period. The stream project shall remain stable and all other performance standards shall be met through four separate bankfull events, occurring in separate years, during the monitoring years 1-7.
Wetland Hydrology
<ul style="list-style-type: none"> Saturation or inundation within the upper 12 inches of the soil surface for, at a minimum, 12 percent of the growing season, during average climatic conditions.
Vegetation
<ul style="list-style-type: none"> Within planted portions of the site, a minimum of 320 stems per acre must be present at year 3; a minimum of 260 stems per acre must be present at year 5; and a minimum of 210 stems per acre must be present at year 7. Trees must average 7 feet in height at year 5, and 10 feet in height at year 7 in each plot. Planted and volunteer stems are counted, provided they are included in the approved planting list for the site; natural recruits not on the planting list may be considered by the IRT on a case-by-case basis.

2.0 METHODS

Monitoring will be conducted by Axiom Environmental, Inc. Annual monitoring reports of the data collected will be submitted to the NCDMS by Restoration Systems no later than December 1st of each monitoring year data is collected. The monitoring schedule is summarized in the following table.

Monitoring Schedule

Resource	Year 1	Year 2	Year 3	Year 4	Year 5	Year 6	Year 7
Streams							
Wetlands							
Vegetation							
Macroinvertebrates							
Visual Assessment							
Report Submittal							

2.1 Monitoring

The monitoring parameters are summarized in the following table.

Monitoring Summary

Stream Parameters				
Parameter	Method	Schedule/Frequency	Number/Extent	Data Collected/Reported
Stream Profile	Full longitudinal survey	As-built (unless otherwise required)	All restored stream channels	Graphic and tabular data.
Stream Dimension	Cross-sections	Years 1, 2, 3, 5, and 7	Total of 12 cross-sections on restored channels	Graphic and tabular data.
Channel Stability	Visual Assessments	Yearly	All restored stream channels	Areas of concern will be depicted on a plan view figure with a written assessment and photograph of the area included in the report.
	Additional Cross-sections	Yearly	Only if instability is documented during monitoring	Graphic and tabular data.
Stream Hydrology	Continuous monitoring surface water gauges and/or trail camera	Continuous recording through monitoring period	3 surface water gauges on UT 3, 5, and 6	Surface water data for each monitoring period
Bankfull Events	Continuous monitoring surface water gauges and/or trail camera	Continuous recording through monitoring period	3 surface water gauges on UT 3, 5, and 6	Surface water data for each monitoring period
	Visual/Physical Evidence	Continuous through monitoring period	1 crest gauge on UT 1	Visual evidence, photo documentation, and/or rain data.
Benthic Macroinvertebrates	“Qual 4” method described in <i>Standard Operating Procedures for Collection and Analysis of Benthic Macroinvertebrates, Version 5.0</i> (NCDWR 2016)	Pre-construction, Years 3, 5, and 7 during the “index period” referenced in <i>Small Streams Biocriteria Development</i> (NCDWQ 2009)	2 stations (on UT 1 upstream and UT 1 downstream); however, the exact locations will be determined at the time pre-construction benthics are collected	Results* will be presented on a site-by-site basis and will include a list of taxa collected, an enumeration of <i>Ephemeroptera</i> , <i>Plecoptera</i> , and <i>Tricopetera</i> taxa as well as Biotic Index values.
Wetland Parameters				
Parameter	Method	Schedule/Frequency	Number/Extent	Data Collected/Reported
Wetland Restoration	Groundwater gauges	Years 1, 2, 3, 4, 5, 6, and 7 throughout the year with the growing season defined as March 1-October 22	10 gauges spread throughout restored wetlands	Soil temperature at the beginning of each monitoring period to verify the start of the growing season, groundwater and rain data for each monitoring period
Vegetation Parameters				
Parameter	Method	Schedule/Frequency	Number/Extent	Data Collected/Reported
Vegetation establishment and vigor	Permanent vegetation plots 0.0247 acre (100 square meters) in size; <i>CVS-EEP Protocol for Recording Vegetation, Version 4.2</i> (Lee et al. 2008)	As-built, Years 1, 2, 3, 5, and 7	19 plots spread across the Site	Species, height, planted vs. volunteer, stems/acre
	Annual random vegetation plots, 0.0247 acre (100 square meters) in size	As-built, Years 1, 2, 3, 5, and 7	4 plots randomly selected each year	Species and height

*Benthic Macroinvertebrate sampling data will not be tied to success criteria; however, the data may be used as a tool to observe positive gains to in-stream habitat

Table 3. Project Attribute Table								
Project Name	Brahma Site							
County	Alamance County, North Carolina							
Project Area (acres)	22.7							
Project Coordinates (latitude and longitude decimal degrees)	35.8540°N, 79.4106°W							
Project Watershed Summary Information								
Physiographic Province	Piedmont							
River Basin	Cape Fear							
USGS Hydrologic Unit 8-digit	3030002050050							
DWR Sub-basin	03-06-04							
Project Drainage Area (acres)	231							
Project Drainage Area Percentage of Impervious Area	<2%							
Land Use Classification	Managed Herbaceous Cover & Hardwood Swamps							
Reach Summary Information								
Parameters	UT 1 (upstream of confluence with UT2)	UT 1 (downstream of confluence with UT2)	UT 2	UT 3	UT4	UT5	UT6	UT7
Pre-project length (feet)	1071	3227	1384	239	129	657	501	47
Post-project (feet)	1072	3312	1390	245	135	662	511	48
Valley confinement (Confined, moderately confined, unconfined)	Alluvial, confined - moderately confined							
Drainage area (acres)	149.3	230.8	57.3	14.6	1.6	26.2	12.3	2.9
Perennial, Intermittent, Ephemeral	Per	Per	Int/Per	Int	Int	Int/Per	Int	Int
NCDWR Water Quality Classification	C, NSW							
Dominant Stream Classification (existing)	G5	Cg 4/5	G4/5	G5	F6	G/F4/5	F5	G5
Dominant Stream Classification (proposed)	C/E 4	C/E 4	G4/5	C/E 4	F6	C/F4/5	C/E 4	G5
Dominant Evolutionary class (Simon) if applicable	III/IV	III/IV	III	III	V	IV	III/IV	IV
Wetland Summary Information								
Parameters	Wetlands							
Pre-project (acres)	5.157 acres drained & 4.427 acres degraded							
Post-project (acres)	4.736 acres restored & 4.309 acres enhanced/preserved							
Wetland Type (non-riparian, riparian)	Riparian riverine							
Mapped Soil Series	Wehadkee							
Soil Hydric Status	Hydric							
Regulatory Considerations								
Parameters	Applicable?	Resolved?	Supporting Docs?					
Water of the United States - Section 404	Yes	Yes	401 Permit					
Water of the United States - Section 401	Yes	Yes	404 Certification					
Endangered Species Act	Yes	Yes	CE Document					
Historic Preservation Act	Yes	Yes	CE Document					
Coastal Zone Management Act (CZMA or CAMA)	NA	NA	NA					
Essential Fisheries Habitat	NA	NA	NA					

3.0 REFERENCES

- Griffith, G.E., J.M. Omernik, J.A. Comstock, M.P. Schafale, W.H. McNab, D.R. Lenat, T.F. MacPherson, J.B. Glover, and V.B. Shelbourne. 2002. Ecoregions of North Carolina and South Carolina. U.S. Geological Survey, Reston, Virginia.
- Lee, M.T., R.K. Peet, S.D. Roberts, and T.R. Wentworth. 2008. CVS-EEP Protocol for Recording Vegetation. Version 4.2. North Carolina Department of Environment and Natural Resources, Ecosystem Enhancement Program. Raleigh, North Carolina.
- North Carolina Division of Mitigation Services (NCDMS). 2014. Stream and Wetland Mitigation Monitoring Guidelines. North Carolina Department of Environmental Quality, Raleigh, North Carolina.
- North Carolina Division of Water Resources (NCDWR). 2016. Standard Operating Procedures for Collection and Analysis of Benthic Macroinvertebrates (Version 5.0). (online). Available:
https://files.nc.gov/ncdeq/Water%20Quality/Environmental%20Sciences/BAU/NCDWR/Macroinvertebrate-SOP-February%202016_final.pdf
- North Carolina Division of Water Quality (NCDWQ). 2009. Small Streams Biocriteria Development. Available:
http://portal.ncdenr.org/c/document_library/get_file?uuid=2d54ad23-0345-4d6e-82fd-04005f48eaa7&groupId=38364
- North Carolina Ecosystem Enhancement Program (NCEEP). 2008. Lumber River Basin Restoration Priorities (online). Available:
https://files.nc.gov/ncdeq/Mitigation%20Services/Watershed_Planning/Lumber_River_Basin/Lumber_RBRP_2008_FINAL.pdf (January 9, 2018).
- North Carolina Stream Functional Assessment Team. (NC SFAT 2015). N.C. Stream Assessment Method (NC SAM) User Manual. Version 2.1.
- North Carolina Wetland Functional Assessment Team. (NC WFAT 2010). N.C. Wetland Assessment Method (NC WAM) User Manual. Version 4.1.
- Schafale, M.P. and A.S. Weakley. 1990. Classification of the Natural Communities of North Carolina: Third Approximation. North Carolina Natural Heritage Program, Division of Parks and Recreation, North Carolina Department of Environment, Health, and Natural Resources. Raleigh, North Carolina.
- Simon A, Hupp CR. 1986. Geomorphic and Vegetative Recovery Processes Along Modified Tennessee Streams: An Interdisciplinary Approach to Disturbed Fluvial Systems. Forest Hydrology and Watershed Management. IAHS-AISH Publ.167.


United States Department of Agriculture (USDA). 1990. Soil Survey of Alamance County, North Carolina. Soil Conservation Service.

United States Department of Agriculture (USDA). 2017. Web Soil Survey (online). Available: <https://websoilsurvey.sc.egov.usda.gov/App/HomePage.htm> [May 7, 2018]. United States Department of Agriculture.

Appendix A

Visual Assessment Data

Figure 1. Current Conditions Plan View
Tables 4A-G. Stream Visual Stability Assessment
Table 5. Visual Vegetation Assessment
Vegetation Plot Photographs



Prepared for:



Project:

BRAHMA SITE

Alamance County, NC

Title:

CURRENT CONDITIONS PLAN VIEW

Drawn by:

KRJ

Date:

APR 2021


Scale:

1:3100

Project No.:

19-006

- Legend**
- Brahma Easement = 22.7 ac
 - Stream Restoration
 - Stream Enhancement (Level I)
 - Stream Enhancement (Level II)
 - Stream Preservation
 - Stream Generating No Credit
 - Wetland Reestablishment
 - Wetland Enhancement
 - Wetland Preservation
 - Permanent Vegetation Plots
 - ★ Vegetation Plot Origins
 - Temporary Vegetation Transects
 - Cross-Sections
 - Groundwater Gauges
 - ▲ Stream Flow/Crest Gauges
 - ★ Rain Gauge/Soil Temperature Logger
 - ★ Benthic Sampling Stations



FIGURE

1

Table 4A. Visual Stream Stability Assessment

Reach UT 1
 Assessed Stream Length 3312
 Assessed Bank Length 6624

Major Channel Category		Metric	Number Stable, Performing as Intended	Total Number in As-built	Amount of Unstable Footage	% Stable, Performing as Intended
Bank	Surface Scour/Bare Bank	Bank lacking vegetative cover resulting simply from poor growth and/or surface scour			0	100%
	Toe Erosion	Bank toe eroding to the extent that bank failure appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	100%
	Bank Failure	Fluvial and geotechnical - rotational, slumping, calving, or collapse			0	100%
Totals					0	100%
Structure	Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	33	33		100%
	Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in DMS monitoring guidance document)	33	33		100%

Table 4B. Visual Stream Stability Assessment

Reach UT 2
 Assessed Stream Length 1390
 Assessed Bank Length 2780

Major Channel Category		Metric	Number Stable, Performing as Intended	Total Number in As-built	Amount of Unstable Footage	% Stable, Performing as Intended
Bank	Surface Scour/Bare Bank	Bank lacking vegetative cover resulting simply from poor growth and/or surface scour			0	100%
	Toe Erosion	Bank toe eroding to the extent that bank failure appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	100%
	Bank Failure	Fluvial and geotechnical - rotational, slumping, calving, or collapse			0	100%
Totals					0	100%
Structure	Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	8	8		100%
	Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in DMS monitoring guidance document)	8	8		100%

Table 4C. Visual Stream Stability Assessment

Reach UT 3
 Assessed Stream Length 245
 Assessed Bank Length 490

Major Channel Category		Metric	Number Stable, Performing as Intended	Total Number in As-built	Amount of Unstable Footage	% Stable, Performing as Intended
Bank	Surface Scour/Bare Bank	Bank lacking vegetative cover resulting simply from poor growth and/or surface scour			0	100%
	Toe Erosion	Bank toe eroding to the extent that bank failure appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	100%
	Bank Failure	Fluvial and geotechnical - rotational, slumping, calving, or collapse			0	100%
Totals					0	100%
Structure	Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	6	6		100%
	Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in DMS monitoring guidance document)	6	6		100%

Table 4D. Visual Stream Stability Assessment

Reach UT 4
 Assessed Stream Length 135
 Assessed Bank Length 270

Major Channel Category		Metric	Number Stable, Performing as Intended	Total Number in As-built	Amount of Unstable Footage	% Stable, Performing as Intended
Bank	Surface Scour/Bare Bank	Bank lacking vegetative cover resulting simply from poor growth and/or surface scour			0	100%
	Toe Erosion	Bank toe eroding to the extent that bank failure appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	100%
	Bank Failure	Fluvial and geotechnical - rotational, slumping, calving, or collapse			0	100%
Totals					0	100%
Structure	Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	0	0		100%
	Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in DMS monitoring guidance document)	0	0		100%

Table 4E. Visual Stream Stability Assessment

Reach UT 5
 Assessed Stream Length 662
 Assessed Bank Length 1324

Major Channel Category		Metric	Number Stable, Performing as Intended	Total Number in As-built	Amount of Unstable Footage	% Stable, Performing as Intended
Bank	Surface Scour/Bare Bank	Bank lacking vegetative cover resulting simply from poor growth and/or surface scour			0	100%
	Toe Erosion	Bank toe eroding to the extent that bank failure appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	100%
	Bank Failure	Fluvial and geotechnical - rotational, slumping, calving, or collapse			0	100%
Totals					0	100%
Structure	Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	0	0		100%
	Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in DMS monitoring guidance document)	0	0		100%

Table 4F. Visual Stream Stability Assessment

Reach UT 6
 Assessed Stream Length 511
 Assessed Bank Length 1022

Major Channel Category		Metric	Number Stable, Performing as Intended	Total Number in As-built	Amount of Unstable Footage	% Stable, Performing as Intended
Bank	Surface Scour/Bare Bank	Bank lacking vegetative cover resulting simply from poor growth and/or surface scour			0	100%
	Toe Erosion	Bank toe eroding to the extent that bank failure appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	100%
	Bank Failure	Fluvial and geotechnical - rotational, slumping, calving, or collapse			0	100%
Totals					0	100%
Structure	Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	19	19		100%
	Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in DMS monitoring guidance document)	19	19		100%

Table 5. Visual Vegetation Assessment

Planted acreage

17.7



Vegetation Category	Definitions	Mapping Threshold	Combined Acreage	% of Planted Acreage
Bare Areas	Very limited cover of both woody and herbaceous material.	0.10 acres	0.00	0.0%
Low Stem Density Areas	Woody stem densities clearly below target levels based on current MY stem count criteria.	0.10acres	0.00	0.0%
Total			0.00	0.0%
Areas of Poor Growth Rates	Planted areas where average height is not meeting current MY Performance Standard.	0.10 acres	0.00	0.0%
Cumulative Total			0.00	0.0%

Easement Acreage




22.7

Vegetation Category	Definitions	Mapping Threshold	Combined Acreage	% of Easement Acreage
Invasive Areas of Concern	Invasives may occur outside of planted areas and within the easement and will therefore be calculated against the total easement acreage- Include species with the potential to directly outcompete native, young, woody stems in the short-term or community structure for existing communities. Species included in summation above should be identified in report summary.	0.10 acres	0.00	0.0%
Easement Encroachment Areas	Encroachment may be point, line, or polygon. Encroachment to be mapped consists of any violation of restrictions specified in the conservation easement. Common encroachments are mowing, cattle access, vehicular access. Encroachment has no threshold value as will need to be addressed regardless of impact area.	none	# Encroachments noted	

Brahma Site
MYO (2021) Vegetation Monitoring Photographs (taken January 14-15, 2021)



Brahma Site
MYO (2021) Vegetation Monitoring Photographs (taken January 14-15, 2021)



Brahma Site
MYO (2021) Vegetation Monitoring Photographs (taken January 14-15, 2021)



Appendix B Vegetation Data

- Table 6A. Planted Bare-Root Woody Vegetation
Table 6B. Permanent Seed Mix
Table 7. Vegetation Plot Counts and Densities
Table 8. Vegetation Plot Data Table from Vegetation Data Entry Tool

**Table 6A. Planted Bare Root Woody Vegetation
Brahma Site**

Species	Total
Acres	17.7
<i>Asimina triloba</i>	200
<i>Betula nigra</i>	1500
<i>Celtis occidentalis</i>	500
<i>Cephalanthus occidentalis</i>	600
<i>Cornus amomum</i>	2700
<i>Diospyros virginiana</i>	500
<i>Fraxinus pennsylvanica</i>	900
<i>Liriodendron tulipifera</i>	1000
<i>Morus rubra</i>	600
<i>Nyssa sylvatica</i>	1000
<i>Platanus occidentalis</i>	2700
<i>Quercus alba</i>	1000
<i>Quercus lyrata</i>	500
<i>Quercus nigra</i>	2000
<i>Quercus pagoda</i>	1000
<i>Quercus phellos</i>	2000
<i>Quercus shumardii</i>	1000
<i>Ulmus americana</i>	500
TOTALS	20,200
Average Stems/Acre	1141

**Table 6B. Permanent Seed Mix
Brahma Site**

Species*	Percentage	Species*	Percentage
<i>Achillea millefolium</i>	0.8	<i>Eupatorium coelestinum</i>	0.5
<i>Agrostis gigantea</i>	15	<i>Eupatorium perfoliatum</i>	0.5
<i>Agrostis hyemalis</i>	5	<i>Gaillardia perennial</i>	2
<i>Agrostis perennans</i>	5	<i>Helianthus angustifolius</i>	1
<i>Agrostis stolonifera</i>	2	<i>Heliopsis helianthoides</i>	1
<i>Baptisia australis</i>	2	<i>Hibiscus moscheutos</i>	0.5
<i>Carex vulpinoidea</i>	1	<i>Juncus tenuis</i>	0.5
<i>Chamaecrista fasciculata</i>	1	<i>Lespedeza capitata</i>	0.5
<i>Chamaecrista nictitans</i>	1	<i>Liatris spicata</i>	0.5
<i>Chrysanthemum leucanthemum</i>	4.5	<i>Monarda fistulosa</i>	0.5
<i>Chrysanthemum x superbum</i>	3	<i>Panicum anceps</i>	0.5
<i>Coreopsis lanceolata</i>	4	<i>Panicum clandestinum</i>	5
<i>Coreopsis tinctoria</i>	4	<i>Penstemon digitalis</i>	1
<i>Cosmos bipinnatus</i>	1	<i>Rudbeckia amplexicaulis</i>	1
<i>Consolida ajacis</i>	2	<i>Rudbeckia hirta</i>	3
<i>Desmodium canadense</i>	1	<i>Senna hebecarpa</i>	0.5
<i>Echinacea purpurea</i>	5	<i>Tridens flavus</i>	18
<i>Elymus virginicus</i>	5	<i>Verbena hastata</i>	1
		Total	100

* This seed mix was applied at 2 lbs per acre sitewide; however, in streamside areas, an additional 5 lbs each *Carex vulpinoidea* and *Juncus effusus* were added to the mix.

**Table 7. Planted Vegetation Totals
Brahma Site**

Plot #	Planted Stems/Acre	Success Criteria Met?
1	931	Yes
2	769	Yes
3	648	Yes
4	607	Yes
5	607	Yes
6	729	Yes
7	688	Yes
8	567	Yes
9	607	Yes
10	688	Yes
11	729	Yes
12	688	Yes
13	931	Yes
14	729	Yes
15	810	Yes
16	648	Yes
17	850	Yes
18	607	Yes
19	729	Yes
R-20	810	Yes
R-21	769	Yes
R-22	729	Yes
R-23	648	Yes
Average Planted Stems/Acre	718	Yes

Table 8. Vegetation Plot Data Table from Vegetation Data Entry Tool

Planted Acreage	17.7
Date of Initial Plant	2021-01-12
Date(s) of Supplemental Plant(s)	#N/A
Date(s) Mowing	#N/A
Date of Current Survey	2021-01-15
Plot size (ACRES)	0.0247

	Scientific Name	Common Name	Tree/ Shrub	Indicator Status	Veg Plot 1 F		Veg Plot 2 F		Veg Plot 3 F		Veg Plot 4 F		Veg Plot 5 F		Veg Plot 6 F		Veg Plot 7 F		Veg Plot 8 F		Veg Plot 9 F		Veg Plot 10 F		Veg Plot 11 F		
					Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted
Species Included in Approved Mitigation Plan	<i>Asimina triloba</i>	pawpaw	Tree	FAC														2	2			4	4	3	3		
	<i>Betula nigra</i>	river birch	Tree	FACW			5	5	4	4														1	1		
	<i>Celtis occidentalis</i>	common hackberry	Tree	FACU												4	4										
	<i>Cornus amomum</i>	silky dogwood	Shrub	FACW	7	7																					
	<i>Diospyros virginiana</i>	common persimmon	Tree	FAC			7	7	1	1					2	2					1	1					
	<i>Fraxinus pennsylvanica</i>	green ash	Tree	FACW			3	3																			
	<i>Liriodendron tulipifera</i>	tuliptree	Tree	FACU	5	5					3	3															
	<i>Morus rubra</i>	red mulberry	Tree	FACU	1	1																					
	<i>Nyssa sylvatica</i>	blackgum	Tree	FAC					2	2														2	2		
	other								1	1											2	2		3	3		
	<i>Platanus occidentalis</i>	American sycamore	Tree	FACW	3	3	1	1	2	2	1	1	2	2	1	1			1	1	6	6	4	4			
	<i>Quercus alba</i>	white oak	Tree	FACU	1	1			1	1			1	1					1	1				1	1		
	<i>Quercus lyrata</i>	overcup oak	Tree	OBL									1	1			2	2			1	1					
	<i>Quercus nigra</i>	water oak	Tree	FAC											1	1					2	2	1	1			
	<i>Quercus pagoda</i>	cherrybark oak	Tree	FACW	2	2					4	4	2	2	1	1	1	1	3	3							
<i>Quercus phellos</i>	willow oak	Tree	FAC									3	3			1	1										
<i>Quercus shumardii</i>	Shumard's oak	Tree	FAC											1	1												
<i>Quercus sp.</i>						4	4	2	2	5	5	3	3	6	6	11	11	6	6	7	7	3	3	8	8	8	8
<i>Ulmus americana</i>	American elm	Tree	FACW			1	1			4	4			1	1	3	3										
Sum	Performance Standard				23	23	19	19	16	16	15	15	15	15	18	18	17	17	14	14	15	15	17	17	18	18	
Mitigation Plan Performance Standard	Current Year Stem Count				23		19		16		15		15		18		17		14		15		17		18		
	Stems/Acre				931		769		648		607		607		729		688		567		607		688		729		
	Species Count				7		6		7		5		6		7		6		5		6		4		6		
	Dominant Species Composition (%)				30		37		31		27		40		61		35		50		40		47		44		
	Average Plot Height				2		2		2		2		2		2		2		1		2		1		2		
% Invasives				0		0		0		0		0		0		0		0		0		0		0			
Post Mitigation Plan Performance Standard	Current Year Stem Count				23		19		16		15		15		18		17		14		15		17		18		
	Stems/Acre				931		769		648		607		607		729		688		567		607		688		729		
	Species Count				7		6		7		5		6		7		6		5		6		4		6		
	Dominant Species Composition (%)				30		37		31		27		40		61		35		50		40		47		44		
	Average Plot Height				2		2		2		2		2		2		2		1		2		1		2		
% Invasives				0		0		0		0		0		0		0		0		0		0		0			

- 1). Bolded species are proposed for the current monitoring year, italicized species are not approved, and a regular font indicates that the species has been approved.
- 2). The "Species Included in Approved Mitigation Plan" section contains only those species that were included in the original approved mitigation plan. The "Post Mitigation Plan Species" section includes species that are being proposed through a mitigation plan addendum for the current monitoring year (bolded), species that have been approved in prior monitoring years through a mitigation plan addendum (regular font), and species that are not approved (italicized).
- 3). The "Mitigation Plan Performance Standard" section is derived only from stems included in the original mitigation plan, whereas the "Post Mitigation Plan Performance Standard" includes data from mitigation plan approved, post mitigation plan approved, and proposed stems.

Table 8. Vegetation Plot Data Table from Vegetation Data Entry Tool (continued)

Planted Acreage	17.7
Date of Initial Plant	2021-01-12
Date(s) of Supplemental Plant(s)	#N/A
Date(s) Mowing	#N/A
Date of Current Survey	2021-01-15
Plot size (ACRES)	0.0247

	Scientific Name	Common Name	Tree/ Shrub	Indicator Status	Veg Plot 12 F		Veg Plot 13 F		Veg Plot 14 F		Veg Plot 15 F		Veg Plot 16 F		Veg Plot 17 F		Veg Plot 18 F		Veg Plot 19 F		Veg Plot 20	Veg Plot 21	Veg Plot 22	Veg Plot 23	
					Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	Planted	Total	R	R	R
Species Included in Approved Mitigation Plan	<i>Asimina triloba</i>	pawpaw	Tree	FAC					1	1			1	1			3	3	1	1					
	<i>Betula nigra</i>	river birch	Tree	FACW																					
	<i>Celtis occidentalis</i>	common hackberry	Tree	FACU	3	3	1	1	1	1												9			
	<i>Cornus amomum</i>	silky dogwood	Shrub	FACW															1	1					
	<i>Diospyros virginiana</i>	common persimmon	Tree	FAC	2	2			1	1	1	1	2	2					1	1			2	1	
	<i>Fraxinus pennsylvanica</i>	green ash	Tree	FACW							3	3			2	2	1	1	1	1	12				
	<i>Liriodendron tulipifera</i>	tuliptree	Tree	FACU									2	2	3	3	3	3	4	4				2	
	<i>Morus rubra</i>	red mulberry	Tree	FACU			4	4	3	3			1	1	3	3	1	1						1	
	<i>Nyssa sylvatica</i>	blackgum	Tree	FAC											1	1							2	2	
	other					1	1	5	5	1	1	3	3												
	<i>Platanus occidentalis</i>	American sycamore	Tree	FACW			2	2	1	1			9	9	3	3	3	3						3	
	<i>Quercus alba</i>	white oak	Tree	FACU																					3
	<i>Quercus lyrata</i>	overcup oak	Tree	OBL													1	1			1	1	1	1	
	<i>Quercus nigra</i>	water oak	Tree	FAC	1	1														2	2				
	<i>Quercus pagoda</i>	cherrybark oak	Tree	FACW			2	2	1	1											3	1	3	2	
<i>Quercus phellos</i>	willow oak	Tree	FAC	6	6			2	2					4	4			5	5	1	2	3	6		
<i>Quercus shumardii</i>	Shumard's oak	Tree	FAC																					1	
<i>Quercus sp.</i>					4	4	9	9	7	7	13	13	3	3	6	6	3	3	3	3	1		2	4	
<i>Ulmus americana</i>	American elm	Tree	FACW																		2	2			
Sum	Performance Standard				17	17	23	23	18	18	20	20	16	16	21	21	15	15	18	18	20	19	18	16	
Mitigation Plan Performance Standard	Current Year Stem Count				17		23		18		20		16		21		15		18		20	19	18	16	
	Stems/Acre				688		931		729		810		648		850		607		729		810	769	729	648	
	Species Count				6		6		9		4		5		7		7		8		6	7	9	5	
	Dominant Species Composition (%)				35		39		39		65		56		29		20		28		60	47	17	38	
	Average Plot Height				2		2		2		1		2		2		2		2		1	2	2	2	
% Invasives				0		0		0		0		0		0		0		0		0	0	0	0		
Post Mitigation Plan Performance Standard	Current Year Stem Count				17		23		18		20		16		21		15		18		20	19	18	16	
	Stems/Acre				688		931		729		810		648		850		607		729		810	769	729	648	
	Species Count				6		6		9		4		5		7		7		8		6	7	9	5	
	Dominant Species Composition (%)				35		39		39		65		56		29		20		28		60	47	17	38	
	Average Plot Height				2		2		2		1		2		2		2		2		1	2	2	2	
% Invasives				0		0		0		0		0		0		0		0		0	0	0	0		

- 1). Bolded species are proposed for the current monitoring year, italicized species are not approved, and a regular font indicates that the species has been approved.
- 2). The "Species Included in Approved Mitigation Plan" section contains only those species that were included in the original approved mitigation plan. The "Post Mitigation Plan Species" section includes species that are being proposed through a mitigation plan addendum for the current monitoring year (bolded), species that have been approved in prior monitoring years through a mitigation plan addendum (regular font), and species that are not approved (italicized).
- 3). The "Mitigation Plan Performance Standard" section is derived only from stems included in the original mitigation plan, whereas the "Post Mitigation Plan Performance Standard" includes data from mitigation plan approved, post mitigation plan approved, and proposed stems.

Appendix C

Stream Geomorphology Data

Cross-Sections with Annual Overlays
Longitudinal Profile

Table 9A-D. Baseline Stream Data Summary Tables

Table 10A-B. Cross-Section Morphology Monitoring Summary


Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS -1, Pool
Feature	Pool
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	597.2
1.6	597.2
3.1	597.1
4.5	596.8
5.1	596.4
5.8	596.1
6.4	595.8
7.0	595.5
7.8	595.5
8.4	595.6
9.2	595.7
10.1	595.8
10.7	596.2
11.3	596.5
11.7	596.8
12.3	597.0
12.9	597.2
14.0	597.5
14.5	597.6
15.5	597.8
16.0	597.90
16.6	597.8
17.4	597.7

SUMMARY DATA	
Bankfull Elevation:	597.1
Bank Height Ratio:	1.0
Thalweg Elevation:	595.5
LTOB Elevation:	597.1
LTOB Max Depth:	1.6
LTOB Cross Sectional Area:	8.7



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS -2, Riffle
Feature	Pool
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	597.6
2.0	597.5
3.9	597.4
4.6	597.3
5.1	597.0
5.5	596.9
6.2	596.8
6.8	596.7
7.2	596.7
8.0	596.3
8.4	596.6
9.2	596.6
10.1	596.4
10.5	596.4
10.9	596.6
11.2	596.8
11.9	596.7
12.2	596.9
12.7	597.1
13.2	597.2
14.0	597.61
14.5	597.9
15.2	598.0
15.6	598.2
17.0	598.1
18.2	598.3
19.9	598.2

SUMMARY DATA	
Bankfull Elevation:	597.4
Bank Height Ratio:	1.0
Thalweg Elevation:	596.4
LTOB Elevation:	597.4
LTOB Max Depth:	1.0
LTOB Cross Sectional Area:	6.0



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS -3, Riffle
Feature	Riffle
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	599.8
0.1	599.8
1.7	599.8
2.3	599.6
3.2	599.3
4.1	599.1
4.8	598.8
5.7	598.4
6.6	598.4
7.4	598.2
8.2	598.0
9.1	597.9
10.1	597.8
10.8	598.0
11.6	598.0
12.4	598.2
13.1	598.3
13.8	598.8
14.6	598.8
15.6	599.0
16.4	599.28
17.0	599.3
17.9	599.3
19.2	599.2
20.5	599.3

SUMMARY DATA	
Bankfull Elevation:	599.2
Bank Height Ratio:	1.0
Thalweg Elevation:	597.8
LTOB Elevation:	599.2
LTOB Max Depth:	1.4
LTOB Cross Sectional Area:	10.5



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS -4, Pool
Feature	Pool
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	600.9
1.4	600.7
3.9	600.7
4.5	600.5
5.2	599.5
5.9	599.5
6.7	598.7
7.3	598.2
8.1	598.3
8.9	598.0
9.7	598.2
10.7	598.4
11.2	598.7
11.7	598.9
12.3	599.9
12.8	600.1
13.9	600.4
14.9	600.7
16.3	600.6
17.8	600.7
18.8	600.80
19.8	600.8

SUMMARY DATA	
Bankfull Elevation:	600.5
Bank Height Ratio:	1.0
Thalweg Elevation:	598.0
LTOB Elevation:	600.5
LTOB Max Depth:	2.5
LTOB Cross Sectional Area:	14.6



Stream Type	E/C 5
--------------------	-------




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS - 5, Riffle
Feature	Riffle
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	606.8
1.6	606.7
2.9	606.6
3.8	606.5
4.5	606.2
5.4	605.5
6.3	605.3
7.2	605.2
7.9	605.0
8.8	605.0
9.8	604.9
10.8	605.0
11.7	605.3
11.8	605.2
12.3	605.8
13.4	606.2
14.1	606.4
15.2	606.6
16.0	606.6

SUMMARY DATA	
Bankfull Elevation:	606.5
Bank Hieght Ratio:	1.0
Thalweg Elevation:	604.9
LTOB Elevation:	606.5
LTOB Max Depth:	1.6
LTOB Cross Sectional Area:	10.7



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS - 6, Pool
Feature	Pool
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	606.8
3.2	606.6
5.0	606.1
6.1	605.6
6.7	605.4
7.9	605.4
8.5	605.0
9.3	604.3
10.1	604.1
10.4	603.1
11.3	603.1
12.5	602.9
12.8	604.4
13.3	606.1
14.3	606.4
14.9	606.6
16.0	606.6
18.0	606.7

SUMMARY DATA	
Bankfull Elevation:	606.6
Bank Height Ratio:	1.0
Thalweg Elevation:	602.9
LTOB Elevation:	606.6
LTOB Max Depth:	3.7
LTOB Cross Sectional Area:	18.0



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS - 7, Riffle
Feature	Riffle
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	611.8
1.5	612.0
3.1	611.9
3.8	611.5
4.4	611.1
5.1	611.0
5.4	610.9
5.8	610.5
6.3	610.5
6.8	610.3
7.3	610.2
8.0	610.2
8.9	610.1
9.9	610.1
10.9	610.2
11.8	610.1
12.2	611.2
12.6	611.5
13.1	611.7
14.0	611.9
15.3	611.98
16.7	612.0

SUMMARY DATA	
Bankfull Elevation:	611.7
Bank Height Ratio:	1.0
Thalweg Elevation:	610.1
LTOB Elevation:	611.7
LTOB Max Depth:	1.6
LTOB Cross Sectional Area:	11.0



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT1, XS - 8, Riffle
Feature	Riffle
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	612.1
1.7	611.9
3.0	611.8
3.7	611.6
4.3	611.5
5.1	611.2
5.7	611.1
6.5	610.1
7.0	609.8
7.7	609.5
8.4	609.3
9.1	609.3
9.8	609.0
10.7	609.4
11.3	609.6
11.8	609.8
12.1	610.8
12.6	611.6
13.3	611.7
14.3	611.9
15.8	612.00
17.7	612.2

SUMMARY DATA	
Bankfull Elevation:	611.6
Bank Height Ratio:	1.0
Thalweg Elevation:	609.0
LTOB Elevation:	611.6
LTOB Max Depth:	2.6
LTOB Cross Sectional Area:	13.3



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT3, XS - 9, Riffle
Feature	Riffle
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	602.1
1.1	602.3
2.3	602.2
2.9	602.2
3.6	601.9
4.3	601.7
4.8	601.5
5.3	601.5
5.8	601.4
6.4	601.5
6.8	601.7
7.3	601.8
7.8	602.0
8.2	602.0
9.0	602.1
10.1	602.2
11.1	602.2

SUMMARY DATA	
Bankfull Elevation:	602.0
Bank Height Ratio:	1.0
Thalweg Elevation:	601.4
LTOB Elevation:	602.0
LTOB Max Depth:	0.6
LTOB Cross Sectional Area:	1.7



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT3, XS - 10, Pool
Feature	Pool
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	602.5
0.0	602.5
1.4	602.5
2.2	602.6
2.9	602.8
3.7	602.6
4.4	602.4
5.1	601.8
5.5	601.7
5.8	601.8
6.3	601.9
6.6	602.2
7.3	602.5
8.0	602.7
8.5	602.9
9.3	602.6
10.3	602.7
11.3	602.7
12.6	602.8

SUMMARY DATA	
Bankfull Elevation:	602.6
Bank Hieght Ratio:	1.0
Thalweg Elevation:	601.7
LTOB Elevation:	602.6
LTOB Max Depth:	0.8
LTOB Cross Sectional Area:	1.6



Stream Type	E/C 5
--------------------	-------




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT6, XS - 11, Pool
Feature	Pool
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	605.9
1.0	606.0
2.4	605.9
3.4	605.8
4.1	605.6
4.6	605.1
5.0	604.7
5.5	604.7
6.0	604.9
6.4	604.8
6.7	604.7
6.9	604.7
7.2	605.0
7.6	605.2
7.9	605.5
8.6	605.7
8.9	605.8
9.7	605.8
10.7	605.9
11.6	605.9
12.6	605.69

SUMMARY DATA	
Bankfull Elevation:	605.8
Bank Hieght Ratio:	1.0
Thalweg Elevation:	604.7
LTOB Elevation:	605.8
LTOB Max Depth:	1.1
LTOB Cross Sectional Area:	3.4



Stream Type E/C 5




Site	Brahma Site
Watershed:	Cape Fear River Basin, 03030002
XS ID	UT6, XS - 12, Riffle
Feature	Riffle
Date:	1/15/2021
Field Crew:	Perkinson, D. Lewis

Station	Elevation
0.0	606.5
1.0	606.4
1.8	606.1
2.7	606.0
3.4	605.9
3.9	605.9
4.3	605.6
5.0	605.2
5.6	605.3
6.1	605.3
6.7	605.3
7.0	605.6
7.5	605.7
8.1	605.9
8.8	605.9
9.3	606.2
10.8	606.0
12.0	606.1

SUMMARY DATA	
Bankfull Elevation:	605.9
Bank Height Ratio:	1.0
Thalweg Elevation:	605.3
LTOB Elevation:	605.9
LTOB Max Depth:	0.6
LTOB Cross Sectional Area:	1.6




Stream Type E/C 5



Project Name	Brahma - Baseline (2021) Profile		
Reach	UT 1 (Sta 00+00 to 10+00)		
Feature	Profile		
Date	1/15/21		
Crew	Perkinson		

2021 Baseline Survey				As needed				As needed				As needed			
Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB
0.0	600.89	601.04	602.17												
12.4	600.93	601.00													
19.4	599.58	601.11	602.33												
24.0	600.05	601.12													
61.1	600.44	601.05													
72.8	600.61	601.62													
77.0	600.64	601.58													
82.7	600.46	601.62													
84.2	601.42	601.60	602.77												
102.5	601.32	601.77													
106.5	600.30	601.79													
109.5	599.55	601.77													
119.4	600.12	601.79	602.96												
127.2	600.50	601.80													
131.8	601.87	602.01													
152.0	601.84	602.24	603.34												
155.4	600.70	602.25													
162.7	600.39	602.25													
167.3	602.00	602.24													
181.5	602.02		603.71												
183.8	601.47	602.47													
192.2	602.02	602.48													
193.6	602.49	602.57	603.53												
208.3	602.45	602.74													
224.7	602.76	602.91	603.55												
227.4	601.75	602.92													
230.2	601.86	602.92													




520.6 604.39 604.64

Project Name	Brahma - Baseline (2021) Profile		
Reach	UT 1 (Sta 10+00 to 20+00)		
Feature	Profile		
Date	1/15/21		
Crew	Perkinson		

2021 Baseline Survey				As needed				As needed				As needed			
Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB
986.9	606.89	607.19													
1011.0	607.01	607.33													
1016.1	606.23	607.34													
1027.9	605.89	607.33													
1035.1	605.82	607.34													
1042.0	607.21	607.35													
1057.4	607.24	607.44													
1061.2	605.83	607.46	608.40												
1071.1	606.05	607.48													
1086.7	606.34	607.45													
1090.5	607.63	607.71													
1098.0	607.31	607.79													
1107.9	607.30	607.79													
1112.0	606.35	607.76													
1117.6	606.65	607.78													
1123.4	606.55	607.77													
1127.1	607.26	607.78													
1141.6	607.35	607.82													
1155.6	607.40	607.82	609.63												
1160.9	606.24	607.84													
1166.9	605.98	607.79													
1176.0	606.34	607.84													
1180.8	607.71	607.95													
1189.8	607.80	608.09													
1199.6	607.92	608.28													
1202.9	606.64	608.28	609.29												
1211.1	607.06	608.27													

Brahma, UT 1 (Sta 10+00 to 20+00)
Baseline Profile 2021




1528.2 609.54 610.58

Project Name Brahma - Baseline (2021) Profile
Reach UT 1 (Sta 20+00 to 30+00)
Feature Profile
Date 1/15/21
Crew Perkinson

2021 Baseline Survey				As needed				As needed				As needed			
Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB
1995.7	612.32	613.64													
2001.0	613.19	613.69													
2012.6	613.34	613.86	614.45												
2013.9	613.05	613.88													
2015.7	612.89	613.84													
2017.9	613.32	613.84													
2021.4	612.58	613.85													
2026.4	612.67	613.84													
2029.9	613.22	613.85													
2042.6	613.31	613.86													
2047.3	612.38	613.80													
2053.3	612.85	613.85													
2056.4	613.51	613.86													
2081.8	612.42	614.19													
2088.0	612.00	614.12													
2096.8	612.79	614.20													
2100.7	614.20	614.48													
2117.5	613.92	614.49													
2131.4	614.29	614.47													
2133.5	613.16	614.50													
2138.0	612.58	614.49													
2142.8	613.11	614.48													
2148.3	614.15	614.56													
2167.7	614.41	614.87													
2170.7	614.03	614.87													
2174.2	613.95	614.87													
2178.8	613.34	614.85													

Brahma, UT 1 (Sta 20+00 to 30+00)
Baseline Profile 2021




2429.0 615.60 617.01

Project Name	Brahma - Baseline (2021) Profile		
Reach	UT 1 (Sta 30+00 to 35+00)		
Feature	Profile		
Date	1/15/21		
Crew	Perkinson		

2021 Baseline Survey				As needed				As needed				As needed			
Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB
2995.8	620.53	620.89													
3006.8	620.72	621.09													
3018.0	620.81	621.24	621.69												
3020.1	620.37	621.23													
3023.5	620.41	621.26													
3024.6	621.11	621.23													
3033.5	620.78	621.27													
3040.4	621.01	621.28													
3044.0	619.94	621.27													
3050.3	620.07	621.28													
3054.5	620.74	621.30													
3061.4	621.12	621.46													
3076.0	621.22	621.70													
3079.2	620.44	621.65													
3083.3	619.86	621.70													
3087.4	620.16	621.61													
3090.3	621.16	621.69													
3094.9	621.45	621.71	622.31												
3096.8	620.21	621.71													
3101.1	620.27	621.61													
3105.2	620.54	621.70													
3108.1	621.52	621.71													
3115.4	621.69	621.88	622.38												
3117.6	620.72	621.86													
3123.8	620.52	621.87													
3126.8	621.36	621.86													
3141.5	621.81	621.97													


Brahma, UT 1 (Sta 30+00 to 35+00)
Baseline Profile 2021



Project Name	Brahma - Baseline (2021) Profile		
Reach	UT 3 (Sta 00+00 to 05+00)		
Feature	Profile		
Date	1/15/21		
Crew	Perkinson		

2021 Baseline Survey				As needed				As needed				As needed			
Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB
0.0	608.10	608.14													
11.2	608.64	608.76													
14.1	608.17	608.75													
17.1	608.23	608.76													
20.1	608.14	608.75													
21.3	608.77	608.78													
35.2	608.52	609.05													
37.3	607.88	609.07													
40.1	608.01	609.05													
43.6	608.08	609.05													
44.7	609.07	609.09	609.58												
56.0	608.87	609.23													
56.9	608.56	609.23													
62.3	608.83	609.22													
67.5	608.51	609.24													
68.6	609.54	609.60													
76.4	609.30	609.61													
77.3	608.92	609.64													
81.0	609.07	609.64													
83.5	609.36	609.75													
92.2	609.63	609.83													
93.7	609.34	609.86													
95.8	609.16	609.87													
98.0	609.33	609.87													
100.5	609.63	609.91													
108.8	609.71	610.06													
110.4	609.36	610.03													


Brahma, UT 3 (Sta 00+00 to 05+00)
Baseline Profile 2021



Project Name Brahma - Baseline (2021) Profile
Reach UT 6 (Sta 00+00 to 06+00)
Feature Profile
Date 1/15/21
Crew Perkinson

2021 Baseline Survey				As needed				As needed				As needed			
Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB	Station	Bed Elevation	Water Elevation	TOB
0.0	606.92	607.40	608.55												
7.6	608.02	608.09													
16.3	608.40	608.66													
16.9	608.34	608.60													
18.1	608.07	608.65													
19.4	608.84	609.03													
30.8	609.60	609.64													
41.4	609.87	610.00	610.52												
43.6	609.20	610.01													
47.9	609.13	610.01													
50.7	609.67	610.02													
59.3	609.86	610.17													
61.1	609.60	610.17													
63.6	609.55	610.18													
66.4	610.29	610.30													
77.5	610.74	610.82													
84.6	610.81	611.10													
85.5	610.46	611.11													
88.8	610.55	611.11													
90.6	611.00	611.17													
99.5	611.10	611.39	611.96												
100.7	610.69	611.39													
102.5	610.90	611.39													
106.3	610.92	611.38													
110.2	611.37	611.56													
118.5	611.88	612.10													
119.7	611.40	612.10													

Brahma, UT 6 (Sta 00+00 to 06+00)
Baseline Profile 2021



288.7 616.75 616.79

**Table 9A. Baseline Stream Data Summary
Brahma - UT 1 (Upstream)**

Parameter	Pre-Existing Condition (applicable)					Design		Monitoring Baseline (MY0)		
	Min	Mean	Med	Max	n	Min	Max	Min	Max	n
Riffle Only										
Bankfull Width (ft)	5.8	8		16		9.4	10.8	9.8	12.9	3
Floodprone Width (ft)	6	8		14		40	100	100	100	3
Bankfull Mean Depth (ft)	0.5	0.9		1.3		0.7	0.8	0.6	1.0	3
Bankfull Max Depth (ft)	1	1.5		1.8		0.9	1.2	1.1	1.6	3
Bankfull Cross Sectional Area (ft ²)	7.3	7.3		7.3		7.3	7.3	6.2	10.7	3
Width/Depth Ratio	4.5	9.1		32		12	16	11.3	15.8	3
Entrenchment Ratio	0.9	1		1		4.3	9.3	7.8	10.2	3
Bank Height Ratio	1.1	1.5		1.9		1	1.3	1.0	1.0	3
Max part size (mm) mobilized at bankfull										
Rosgen Classification	G5					E/C 4		E/C 4		
Bankfull Discharge (cfs)	28.2					28.2		28.2		
Sinuosity (ft)	1.1					1.12		1.12		
Water Surface Slope (Channel) (ft/ft)	0.0076					0.0075		0.0073		
Other										

**Table 9B. Baseline Stream Data Summary
Brahma - UT 1 (Downstream)**

Parameter	Pre-Existing Condition (applicable)					Design		Monitoring Baseline (MY0)		
	Min	Mean	Med	Max	n	Min	Max	Min	Max	n
Riffle Only										
Bankfull Width (ft)	5.4	8.2		16.9		10.2	11.8	9.6	9.6	1
Floodprone Width (ft)	14	19		100		50	150	75.0	75.0	1
Bankfull Mean Depth (ft)	0.5	1.1		1.6		0.7	0.9	1.1	1.1	1
Bankfull Max Depth (ft)	0.8	1.6		2.7		0.9	1.3	1.6	1.6	1
Bankfull Cross Sectional Area (ft ²)	8.7	8.7		8.7		8.7	8.7	11.0	11.0	1
Width/Depth Ratio	3.4	7.8		33.8		12	16	8.4	8.4	1
Entrenchment Ratio	1.3	2.4		13.3		4.9	12.7	7.8	7.8	1
Bank Height Ratio	1.2	2.1		2.9		1	1.3	1.0	1.0	1
Max part size (mm) mobilized at bankfull										
Rosgen Classification	Gg 4/5					E/C 4		E 4		
Bankfull Discharge (cfs)	34.4					34.4		34.4		
Sinuosity (ft)	1.33					1.33		1.33		
Water Surface Slope (Channel) (ft/ft)	0.0052					0.0052		0.0064		
Other										

**Table 9C. Baseline Stream Data Summary
Brahma - UT 3**

Parameter	Pre-Existing Condition (applicable)					Design		Monitoring Baseline (MY0)		
	Min	Mean	Med	Max	n	Min	Max	Min	Max	n
Riffle Only										
Bankfull Width (ft)	3.1	3.8		5.9		4.1	4.7	4.9	4.9	1
Floodprone Width (ft)	3	5		8		25	75	50.0	50.0	1
Bankfull Mean Depth (ft)	0.3	0.4		0.5		0.3	0.4	0.3	0.3	1
Bankfull Max Depth (ft)	0.4	0.6		0.7		0.4	0.5	0.6	0.6	1
Bankfull Cross Sectional Area (ft ²)	1.5	1.5		1.5		1.5	1.5	1.7	1.7	1
Width/Depth Ratio	6.2	9.5		19.7		12	16	14.3	14.3	1
Entrenchment Ratio	0.8	1.4		1.6		6.1	15.8	10.2	10.2	1
Bank Height Ratio	2.3	3.2		4		1	1.3	1.0	1.0	1
Max part size (mm) mobilized at bankfull										
Rosgen Classification	G 5					E/C 4		E/C 4		
Bankfull Discharge (cfs)	5.4					5.4		5.4		
Sinuosity (ft)	1.08					1.12		1.12		
Water Surface Slope (Channel) (ft/ft)	0.017					0.0173		0.0195		
Other										

**Table 9D. Baseline Stream Data Summary
Brahma - UT 6**

Parameter	Pre-Existing Condition (applicable)					Design		Monitoring Baseline (MY0)		
	Min	Mean	Med	Max	n	Min	Max	Min	Max	n
Riffle Only										
Bankfull Width (ft)	3.3	6.5		16.3		4.1	4.7	4.1	4.1	1
Floodprone Width (ft)	5	13		23		25	75	50.0	50.0	1
Bankfull Mean Depth (ft)	0.1	0.2		0.4		0.3	0.4	0.4	0.4	1
Bankfull Max Depth (ft)	0.2	0.4		0.7		0.4	0.5	0.7	0.7	1
Bankfull Cross Sectional Area (ft ²)	1.4	1.4		1.4		1.4	1.4	1.8	1.8	1
Width/Depth Ratio	3.6	32.5		163		12	16	9.6	9.6	1
Entrenchment Ratio	1.2	1.5		2.7		6.1	15.8	12.1	12.1	1
Bank Height Ratio	1	3.1		5		1	1.3	1.0	1.0	1
Max part size (mm) mobilized at bankfull										
Rosgen Classification	F 5					E/C 4		E 4		
Bankfull Discharge (cfs)	4.8					4.8		4.8		
Sinuosity (ft)	1.02					1.12		1.12		
Water Surface Slope (Channel) (ft/ft)	0.0203					0.0173		0.0297		
Other										

Table 10A. Monitoring Data - Cross Section Morphology Monitoring Summary
(Brahma/ DMS:100092) UT 1

	UT 1 - Cross Section 1 (Pool)							UT 1 - Cross Section 2 (Riffle)							UT 1 - Cross Section 3 (Riffle)							UT 1 - Cross Section 4 (Pool)							UT 1 - Cross Section 5 (Riffle)							
	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	
Bankfull Elevation (ft) - Based on AB-Bankfull Area	597.11							597.43							599.24								600.54							606.49						
Bank Height Ratio_Based on AB Bankfull Area	1.00							1.00							1.00								1.00							1.00						
Thalweg Elevation	595.50							596.4							597.83								598.02							604.89						
LTOB ² Elevation	597.11							597.4							599.24								600.54							606.49						
LTOB ² Max Depth (ft)	1.61							1.04							1.41								2.52							1.60						
LTOB ² Cross Sectional Area (ft ²)	8.7							6.0							10.5								14.6							10.7						
	UT 1 - Cross Section 6 (Pool)							UT 1 - Cross Section 7 (Riffle)							UT 1 - Cross Section 8 (Riffle)																					
Bankfull Elevation (ft) - Based on AB-Bankfull Area	606.58							611.70							611.59																					
Bank Height Ratio_Based on AB Bankfull Area	1.00							1.00							1.00																					
Thalweg Elevation	602.89							610.1							609.02																					
LTOB ² Elevation	606.58							611.7							611.59																					
LTOB ² Max Depth (ft)	3.69							1.61							2.57																					
LTOB ² Cross Sectional Area (ft ²)	18.0							11.0							13.3																					
Bankfull Elevation (ft) - Based on AB-Bankfull Area																																				
Bank Height Ratio_Based on AB Bankfull Area																																				
Thalweg Elevation																																				
LTOB ² Elevation																																				
LTOB ² Max Depth (ft)																																				
LTOB ² Cross Sectional Area (ft ²)																																				

The above morphology parameters reflect the 2018 guidance that arose from the mitigation technical workgroup consisting of DMS, the IRT and industry mitigation providers/practitioners. The outcome resulted in the focus on three primary morphological parameters of interest for the purposes of tracking channel change moving forward. They are the bank height ratio using a constant As-built bankfull area and the cross sectional area and max depth based on each years low top of bank. These are calculated as follows:
 1 - **Bank Height Ratio (BHR)** takes the As-built bankfull area as the basis for adjusting each subsequent years bankfull elevation. For example if the As-built bankfull area was 10 ft2, then the MY1 bankfull elevation would be adjusted until the calculated bankfull area within the MY1 cross section survey = 10 ft2. The BHR would then be calculated with the difference between the low top of bank (LTOB) elevation for MY1 and the thalweg elevation for MY1 in the numerator with the difference between the MY1 bankfull elevation and the MY1 thalweg elevation in the denominator. This same process is then carried out in each successive year.
 2 - **LTOB Area and Max depth** - These are based on the LTOB elevation for each years survey (The same elevation used for the LTOB in the BHR calculation). Area below the LTOB elevation will be used and tracked for each year as above. The difference between the LTOB elevation and the thalweg elevation (same as in the BHR calculation) will be recorded and tracked above as LTOB max depth.

Note: The smaller the channel the closer the survey measurements are to their limit of reliable detection, therefore inter-annual variation in morphological measurement (as a percentage) is by default magnified as channel size decreases. Some of the variability above is the result of this factor and some is due to the large amount of depositional sediments observed.

Table 10B. Monitoring Data - Cross Section Morphology Monitoring Summary
(Brahma/ DMS:100092) UT 3 and UT 6

	UT 3 - Cross Section 9 (Riffle)							UT 3 - Cross Section 10 (Pool)							UT 6 - Cross Section 11 (Pool)							UT 6 - Cross Section 12 (Riffle)														
	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	MY0	MY1	MY2	MY3	MY5	MY7	MY+	
Bankfull Elevation (ft) - Based on AB-Bankfull Area	602.04							602.55							605.79								605.90													
Bank Height Ratio_Based on AB Bankfull Area	1.00							1.00							1.00								1.00													
Thalweg Elevation	601.40							601.7							604.69								605.26													
LTOB ² Elevation	602.04							602.6							605.79								605.90													
LTOB ² Max Depth (ft)	0.64							0.83							1.10								0.64													
LTOB ² Cross Sectional Area (ft ²)	1.7							1.6							3.4								1.6													
Bankfull Elevation (ft) - Based on AB-Bankfull Area																																				
Bank Height Ratio_Based on AB Bankfull Area																																				
Thalweg Elevation																																				
LTOB ² Elevation																																				
LTOB ² Max Depth (ft)																																				
LTOB ² Cross Sectional Area (ft ²)																																				

The above morphology parameters reflect the 2018 guidance that arose from the mitigation technical workgroup consisting of DMS, the IRT and industry mitigation providers/practitioners. The outcome resulted in the focus on three primary morphological parameters of interest for the purposes of tracking channel change moving forward. They are the bank height ratio using a constant As-built bankfull area and the cross sectional area and max depth based on each years low top of bank. These are calculated as follows:
 1 - **Bank Height Ratio (BHR)** takes the As-built bankfull area as the basis for adjusting each subsequent years bankfull elevation. For example if the As-built bankfull area was 10 ft2, then the MY1 bankfull elevation would be adjusted until the calculated bankfull area within the MY1 cross section survey = 10 ft2. The BHR would then be calculated with the difference between the low top of bank (LTOB) elevation for MY1 and the thalweg elevation for MY1 in the numerator with the difference between the MY1 bankfull elevation and the MY1 thalweg elevation in the denominator. This same process is then carried out in each successive year.
 2 - **LTOB Area and Max depth** - These are based on the LTOB elevation for each years survey (The same elevation used for the LTOB in the BHR calculation). Area below the LTOB elevation will be used and tracked for each year as above. The difference between the LTOB elevation and the thalweg elevation (same as in the BHR calculation) will be recorded and tracked above as LTOB max depth.

Note: The smaller the channel the closer the survey measurements are to their limit of reliable detection, therefore inter-annual variation in morphological measurement (as a percentage) is by default magnified as channel size decreases. Some of the variability above is the result of this factor and some is due to the large amount of depositional sediments observed.


Appendix D

Hydrologic Data

Groundwater Gauge Soil Profiles

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW1 / 35.85676, -79.411422

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-4	10YR 5/2	100	-	-	Loam
4-12	10YR 7/2	95	10 YR 6/1	3	Fine Sandy Loam
			10 YR 6/4	2	
12+	10YR 7/2	50	10 YR 5/6	4	Sandy Clay
	10YR 6/6	46			

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW2 / 35.856591, -79.411864

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-3	10YR 5/2	98	10 YR 4/4	2	Loam
3-8	10YR 7/2	97	10 YR 4/6	2	Fine Sandy Loam
			10 YR 3/1	1	
8+	10YR 7/4	98	10 YR 6/2	2	Fine Sandy Loam

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW3 / 35.856085, -79.411777

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-2	10YR 5/3	95	10YR 3/4	5	Loam
2-6	10YR 6/2	97	10YR 4/6	2	Fine Sandy Loam
			10YR 3/1	1	
6+	10YR 6/2	80	10YR 6/6	20	Fine Sandy Loam

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW4 / 35.855802, -79.411305

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-2	10YR 6/2	95	10YR 4/4	5	Sandy Loam
2-9	10YR 7/1	85	10YR 6/1	10	Fine Sandy Loam
			10YR 5/6	5	
9+	10YR 7/1	97	10YR 6/6	3	Fine Sandy Loam

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW5 / 35.855268, -79.411734

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-2	10YR 6/2	95	10YR 5/6	5	Sandy Loam
2-11	10YR 7/2	75	2.5Y 7/4	20	Fine Sandy Loam
			10YR 6/6	5	
11+	10YR 6/6	80	10YR 7/2	20	Sandy Clay Loam

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW6 / 35.855112, -79.411422

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-4	10YR 4/1	97	10YR 4/4	3	Fine Sandy Loam
4-9	10YR 6/2	95	10YR 4/4	5	Fine Sandy Loam
9+	10YR 7/1	70	10YR 6/6	30	Fine Sandy Loam

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW7 / 35.854738, -79.411192

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-1	10YR 5/2	97	10yr 5/6	3	Fine Sandy Loam
1-10	10YR 6/2	95	10yr 5/6	2	Fine Sandy Loam
			10YR 6/4	3	
10+	10YR 6/2	80	10YR 6/6	20	Clay Loam

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW8 / 35.853817, -79.410806

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-3	10YR 4/3	100	-	-	Loam
3-12	10YR 6/3	50	10YR 5/6	5	Sandy Clay Loam
	10YR 6/1	45			
12+	10YR 6/1	90	10YR 6/2	7	Sandy Clay Loam
			10YR 5/6	3	

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW9 / 35.853378, -79.410372

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-2	10YR 6/2	95	10YR 4/4	5	Loam
2-9	10YR 6/2	60	10YR 6/1	35	Clay Loam
			10YR 5/6	5	
9+	10YR 6/2	40	10YR 5/6	20	Silt Loam
	10YR 7/1	40			

North Carolina Licensed Soil Scientist


Number: 1233

Signature: W Grant Lewis

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW10 / 35.852992, -79.409984

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-2	10YR 4/2	80	10YR 5/1	15	Loamy Clay
			10YR 4/6	5	
2-10	10YR 6/2	95	10YR 5/6	5	Sandy Clay Loam
10+	10YR 6/1	85	10YR 5/6	10	Fine Sandy Loam
			10YR 5/8	5	

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW11 / 35.852792, -79.409045

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-3	10YR 5/2	40	10YR 4/6	10	Loam
	10YR 5/1	40	10YR 5/6	10	
3-11	10YR 6/2	95	10YR 6/6	5	Fine Sandy Loam
11+	10YR 6/2	60	10YR 6/8	37	Fine Sandy Loam
			10YR 5/8	3	

North Carolina Licensed Soil Scientist


Number: 1233

Signature: *W Grant Lewis*

Name/Print: W. Grant Lewis

AXIOM ENVIRONMENTAL, INC

218 Snow Avenue
 Raleigh, North Carolina 27603
 919-215-1693



Axiom Environmental, Inc.

SOIL BORING LOG

Project/Site: Brahma Site

County, State: Alamance, NC

Sampling Point/
 Coordinates: GW12 / 35.852387, -79.410655

Investigator: Lewis

Notes:

Depth (inches)	Matrix		Mottling		Texture
	Color	%	Color	%	
0-2	10YR 3/3	90	10YR 6/1	10	Loam
2-13	10YR 6/2	95	10YR 4/6	5	Sandy Clay Loam
13+	10YR 6/1	80	10YR 5/3	15	Fine Sandy Loam
			10YR 4/6	5	

North Carolina Licensed Soil Scientist

Number: 1233

Signature: W Grant Lewis

Name/Print: W. Grant Lewis

Appendix E

Project Timeline and Contact Info

Table 11. Project Timeline

Table 12. Project Contacts

Table 11. Project Timeline

Activity or Deliverable	Data Collection Complete	Task Completion or Deliverable Submission
Project Instituted	NA	Dec-18
Mitigation Plan Approved	NA	8-Jul-20
Construction (Grading) Completed	NA	9-Dec-21
Planting Completed	NA	12-Jan-21
As-built Survey Completed	NA	Feb-21
MY-0 Baseline Report	Jan-21	Apr-21
MY1+ Monitoring Reports		

Table 12. Project Contacts

Brahma Site/100092	
Provider	Restoration Systems, LLC 1101 Haynes Street, Suite 211 Raleigh, NC 27604
Mitigation Provider POC	Worth Creech 919-755-9490
Designer	Axiom Environmental, Inc. 218 Snow Ave Raleigh, NC 27603
Primary project design POC	Grant Lewis 919-215-1693
Construction Contractor	Land Mechanics Designs, Inc. 126 Circle G Lane Willow Spring, NC 27592 Charles Hill 919-639-6132

Appendix F Other Data

Preconstruction Benthic Results
Preconstruction Benthic Habitat Assessment Data Forms
Figure F-1. Asbuilt Fencing

PAI ID NO			52714	52715
STATION			UT-1-US	UT-1-DS
DATE			7/1/2019	7/1/2019
SPECIES	T.V.	F.F.G.		
MOLLUSCA				
Gastropoda				
Basommatophora				
Physidae				
<i>Physella sp.</i>	8.7	CG	2	1
ANNELIDA				
Clitellata				
Hirudinea		P		
Rhynchobdellida				
<i>Batrachobdella phalera</i>		P	2	
<i>Helobdella triserialis</i>	9.3	P		1
ARTHROPODA				
Crustacea				
Isopoda				
Asellidae		SH		
<i>Lirceus sp.</i>	7.4	CG	1	
Insecta				
Odonata				
Aeshnidae		P		
<i>Aeshna sp.</i>		P		1
Coenagrionidae		P		
<i>Ischnura sp.</i>	9.5		1	3
Hemiptera				
Corixidae		PI	1	
Megaloptera				
Corydalidae		P		
<i>Chauliodes pectinicornis</i>			2	
Coleoptera				
Scirtidae		SC		
<i>Scirtes sp.</i>			8	
Diptera				
Chironomidae				
<i>Psectrotanypus dyari</i>	10	P	3	1
Culicidae		FC		
<i>Anopheles sp.</i>	8.6	FC		1
<i>Culex sp.</i>		FC	1	
TOTAL NO. OF ORGANISMS			21	8
TOTAL NO. OF TAXA			9	6
EPT TAXA			0	0
BIOTIC INDEX ASSIGNED VALUES			9.27	9.30

Habitat Assessment Field Data Sheet
Mountain/ Piedmont Streams

53

Brahma Utl US

Biological Assessment Unit, DWQ

TOTAL SCORE

Directions for use: The observer is to survey a minimum of 100 meters with 200 meters preferred of stream, preferably in an upstream direction starting above the bridge pool and the road right-of-way. The segment which is assessed should represent average stream conditions. To perform a proper habitat evaluation the observer needs to get into the stream. To complete the form, select the description which best fits the observed habitats and then circle the score. If the observed habitat falls in between two descriptions, select an intermediate score. A final habitat score is determined by adding the results from the different metrics.

Stream Brahma Utl US Location/road: Shaw Camp NC (Road Name Clark) County Alamance

Date 190701 CC# 03030002 Basin Cape Fear Subbasin 03-06-04

Observer(s) P.P.D.C. Type of Study: Fish Benthos Basinwide Special Study (Describe) _____

Latitude 35.852042 Longitude 79.408454 Ecoregion: MT P Slate Belt Triassic Basin

Water Quality: Temperature _____ °C DO _____ mg/l Conductivity (corr.) _____ µS/cm pH _____

Physical Characterization: Visible land use refers to immediate area that you can see from sampling location - include what you estimate driving thru the watershed in watershed land use.

Visible Land Use: 20 %Forest _____ %Residential 80 %Active Pasture _____ % Active Crops
_____ %Fallow Fields _____ % Commercial _____ %Industrial _____ %Other - Describe: _____

Watershed land use : Forest Agriculture Urban Animal operations upstream

Width: (meters) Stream 1.5 Channel (at top of bank) _____ Stream Depth: (m) Avg .1 Max _____
 Width variable Large river >25m wide

Bank Height (from deepest part of riffle to top of bank-first flat surface you stand on): (m) _____

Bank Angle: 90 ° or NA (Vertical is 90°, horizontal is 0°. Angles > 90° indicate slope is towards mid-channel, < 90° indicate slope is away from channel. NA if bank is too low for bank angle to matter.)

- Channelized Ditch
- Deeply incised-steep, straight banks Both banks undercut at bend Channel filled in with sediment
- Recent overbank deposits Bar development Buried structures Exposed bedrock
- Excessive periphyton growth Heavy filamentous algae growth Green tinge Sewage smell
- Manmade Stabilization: N Y: Rip-rap, cement, gabions Sediment/grade-control structure Berm/levee

Flow conditions : High Normal Low
Turbidity: Clear Slightly Turbid Turbid Tannic Milky Colored (from dyes)

Good potential for Wetlands Restoration Project?? YES NO Details _____

Channel Flow Status

Useful especially under abnormal or low flow conditions.

- A. Water reaches base of both lower banks, minimal channel substrate exposed
- B. Water fills >75% of available channel, or <25% of channel substrate is exposed.....
- C. Water fills 25-75% of available channel, many logs/snags exposed.....
- D. Root mats out of water.....
- E. Very little water in channel, mostly present as standing pools.....

Weather Conditions: not dry Photos: N Y Digital 35mm

Remarks: Proposed stream and wetland mitigation sale. Livestock has unrestricted access to entire stream

I. Channel Modification

- A. channel natural, frequent bends..... 5
- B. channel natural, infrequent bends (channelization could be old)..... 4
- C. some channelization present..... 3
- D. more extensive channelization, >40% of stream disrupted..... 2
- E. no bends, completely channelized or rip rapped or gabioned, etc..... 0

Evidence of dredging Evidence of desnagging=no large woody debris in stream Banks of uniform shape/height

Remarks _____ Subtotal 3

II. Instream Habitat: Consider the percentage of the reach that is favorable for benthos colonization or fish cover. If >70% of the reach is rocks, 1 type is present, circle the score of 17. Definition: leafpacks consist of older leaves that are packed together and have begun to decay (not piles of leaves in pool areas). Mark as Rare, Common, or Abundant.

 Rocks Macrophytes X Sticks and leafpacks Snags and logs Undercut banks or root mats

AMOUNT OF REACH FAVORABLE FOR COLONIZATION OR COVER

	>70%	40-70%	20-40%	<20%
	Score	Score	Score	Score
4 or 5 types present.....	20	16	12	8
3 types present.....	19	15	11	7
2 types present.....	18	14	10	6
1 type present.....	17	13	<u>9</u>	5
No types present.....	0			

No woody vegetation in riparian zone Remarks _____ Subtotal 9

III. Bottom Substrate (silt, sand, detritus, gravel, cobble, boulder) Look at entire reach for substrate scoring, but only look at riffle for embeddedness, and use rocks from all parts of riffle-look for "mud line" or difficulty extracting rocks.

- A. substrate with good mix of gravel, cobble and boulders**
 - 1. embeddedness <20% (very little sand, usually only behind large boulders)..... 15
 - 2. embeddedness 20-40%..... 12
 - 3. embeddedness 40-80%..... 8
 - 4. embeddedness >80%..... 3
- B. substrate gravel and cobble**
 - 1. embeddedness <20%..... 14
 - 2. embeddedness 20-40%..... 11
 - 3. embeddedness 40-80% 6
 - 4. embeddedness >80%..... 2
- C. substrate mostly gravel**
 - 1. embeddedness <50%..... 8
 - 2. embeddedness >50%..... 4
- D. substrate homogeneous**
 - 1. substrate nearly all bedrock..... 3
 - 2. substrate nearly all sand 3
 - 3. substrate nearly all detritus..... 2
 - 4. substrate nearly all silt/ clay..... 1

Remarks Riffles are sand/gravel Subtotal 4

IV. Pool Variety Pools are areas of deeper than average maximum depths with little or no surface turbulence. Water velocities associated with pools are always slow. Pools may take the form of "pocket water", small pools behind boulders or obstructions, in large high gradient streams, or side eddies.

- A. Pools present**
 - 1. Pools Frequent (>30% of 200m area surveyed)
 - a. variety of pool sizes..... 10
 - b. pools about the same size (indicates pools filling in)..... 8
 - 2. Pools Infrequent (<30% of the 200m area surveyed)
 - a. variety of pool sizes..... 6
 - b. pools about the same size..... 4
- B. Pools absent..... 0**

Subtotal 8

Pool bottom boulder-cobble=hard Bottom sandy-sink as you walk Silt bottom Some pools over wader depth

Remarks _____

Brahma-47-1-45

V. Riffle Habitats

Definition: Riffle is area of reaceration-can be debris dam, or narrow channel area.

	Riffles Frequent Score	Riffles Infrequent Score
A. well defined riffle and run, riffle as wide as stream and extends 2X width of stream....	16	12
B. riffle as wide as stream but riffle length is not 2X stream width	14	7
C. riffle not as wide as stream and riffle length is not 2X stream width	10	3
D. riffles absent.....	0	

Channel Slope: Typical for area Steep=fast flow Low=like a coastal stream

Subtotal 3

VI. Bank Stability and Vegetation

FACE UPSTREAM

Left Bank
Score Rt. Bank
Score

A. Banks stable

1. little evidence of erosion or bank failure(except outside of bends), little potential for erosion.. 7 7

B. Erosion areas present

1. diverse trees, shrubs, grass; plants healthy with good root systems..... 6 6

2. few trees or small trees and shrubs; vegetation appears generally healthy..... 5 5

3. sparse mixed vegetation; plant types and conditions suggest poorer soil binding..... 3 3

4. mostly grasses, few if any trees and shrubs, high erosion and failure potential at high flow.. 2 2

5. little or no bank vegetation, mass erosion and bank failure evident..... 0 0

Total 10

Remarks _____

VII. Light Penetration Canopy is defined as tree or vegetative cover directly above the stream's surface. Canopy would block out sunlight when the sun is directly overhead. Note shading from mountains, but not use to score this metric.

	Score
A. Stream with good canopy with some breaks for light penetration	10
B. Stream with full canopy - breaks for light penetration absent.....	8
C. Stream with partial canopy - sunlight and shading are essentially equal.....	<u>7</u>
D. Stream with minimal canopy - full sun in all but a few areas.....	2
E. No canopy and no shading.....	0

Remarks _____

Subtotal 7

VIII. Riparian Vegetative Zone Width

Definition: Riparian zone for this form is area of natural vegetation adjacent to stream (can go beyond floodplain). Definition: A break in the riparian zone is any place on the stream banks which allows sediment or pollutants to directly enter the stream, such as paths down to stream, storm drains, uprooted trees, otter slides, etc.

FACE UPSTREAM

Dominant vegetation: Trees Shrubs Grasses Weeds/old field Exotics (kudzu, etc)

Lft. Bank Rt. Bank
Score Score

A. Riparian zone intact (no breaks)

1. width > 18 meters..... 5 5

2. width 12-18 meters..... 4 4

3. width 6-12 meters..... 3 3

4. width < 6 meters..... 2 2

B. Riparian zone not intact (breaks)

1. breaks rare

a. width > 18 meters..... 4 4

b. width 12-18 meters..... 3 3

c. width 6-12 meters..... 2 2

d. width < 6 meters..... 1 1

2. breaks common

a. width > 18 meters..... 3 3

b. width 12-18 meters..... 2 2

c. width 6-12 meters..... 1 1

d. width < 6 meters..... 0 0

Remarks Mixed subdeciduous forest, minimal woody species

Total 8

Page Total 28

Disclaimer-form filled out, but score doesn't match subjective opinion-atypical stream.

TOTAL SCORE 53

Moham UT-DS

Habitat Assessment Field Data Sheet
Mountain/ Piedmont Streams

TOTAL SCORE

Biological Assessment Unit, DWQ

Directions for use: The observer is to survey a minimum of 100 meters with 200 meters preferred of stream, preferably in an upstream direction starting above the bridge pool and the road right-of-way. The segment which is assessed should represent average stream conditions. To perform a proper habitat evaluation the observer needs to get into the stream. To complete the form, select the description which best fits the observed habitats and then circle the score. If the observed habitat falls in between two descriptions, select an intermediate score. A final habitat score is determined by adding the results from the different metrics.

Stream Brahma UT-DS Location/road: Snow Camp NC (Road Name Clark) County Alamogordo

Date 1/9/70 CC# 03030002 Basin Cane Fear Subbasin 03-06-04

Observer(s) R.P.D.C Type of Study: Fish Benthos Basinwide Special Study (Describe) _____

Latitude 35.85721 Longitude -79.411824 Ecoregion: MT P Slate Belt Triassic Basin

Water Quality: Temperature _____ °C DO _____ mg/l Conductivity (corr.) _____ µS/cm pH _____

Physical Characterization: Visible land use refers to immediate area that you can see from sampling location - include what you estimate driving thru the watershed in watershed land use.

Visible Land Use: 20 %Forest _____ %Residential 80 %Active Pasture _____ % Active Crops
_____ %Fallow Fields _____ % Commercial _____ %Industrial _____ %Other - Describe: _____

Watershed land use : Forest Agriculture Urban Animal operations upstream

Width: (meters) Stream 2 Channel (at top of bank) 2 Stream Depth: (m) Avg .1 Max .3
 Width variable Large river >25m wide

Bank Height (from deepest part of riffle to top of bank-first flat surface you stand on): (m) 1.5

Bank Angle: 90 ° or NA (Vertical is 90°, horizontal is 0°. Angles > 90° indicate slope is towards mid-channel, < 90° indicate slope is away from channel. NA if bank is too low for bank angle to matter.)

Channelized Ditch
 Deeply incised-steep, straight banks Both banks undercut at bend Channel filled in with sediment
 Recent overbank deposits Bar development Buried structures Exposed bedrock
 Excessive periphyton growth Heavy filamentous algae growth Green tinge Sewage smell
Manmade Stabilization: N Y: Rip-rap, cement, gabions Sediment/grade-control structure Berm/levee

Flow conditions : High Normal Low
Turbidity: Clear Slightly Turbid Turbid Tannic Milky Colored (from dyes)

Good potential for Wetlands Restoration Project?? YES NO Details _____

Channel Flow Status
Useful especially under abnormal or low flow conditions.
A. Water reaches base of both lower banks, minimal channel substrate exposed
B. Water fills >75% of available channel, or <25% of channel substrate is exposed.....
C. Water fills 25-75% of available channel, many logs/snags exposed.....
D. Root mats out of water.....
E. Very little water in channel, mostly present as standing pools.....

Weather Conditions: dry Photos: N Y Digital 35mm

Remarks: Livestock have unrestricted access to entire stream

I. Channel Modification

- A. channel natural, frequent bends..... (5)
- B. channel natural, infrequent bends (channelization could be old)..... 4
- C. some channelization present..... 3
- D. more extensive channelization, >40% of stream disrupted..... 2
- E. no bends, completely channelized or rip rapped or gabioned, etc..... 0

Evidence of dredging Evidence of desnagging = no large woody debris in stream Banks of uniform shape/height

Remarks good size mostly, but 1 used Subtotal 5

II. Instream Habitat: Consider the percentage of the reach that is favorable for benthos colonization or fish cover. If >70% of the reach is rocks, 1 type is present, circle the score of 17. Definition: leafpacks consist of older leaves that are packed together and have begun to decay (not piles of leaves in pool areas). Mark as Rare, Common, or Abundant.

Rocks Macrophytes Sticks and leafpacks Snags and logs Undercut banks or root mats

AMOUNT OF REACH FAVORABLE FOR COLONIZATION OR COVER

	>70%	40-70%	20-40%	<20%
	Score	Score	Score	Score
4 or 5 types present.....	20	16	12	8
3 types present.....	19	15	11	7
2 types present.....	18	14	(10)	6
1 type present.....	17	13	9	5
No types present.....	0			

No woody vegetation in riparian zone Remarks _____ Subtotal 10

III. Bottom Substrate (silt, sand, detritus, gravel, cobble, boulder) Look at entire reach for substrate scoring, but only look at riffle for embeddedness, and use rocks from all parts of riffle-look for "mud line" or difficulty extracting rocks.

- A. substrate with good mix of gravel, cobble and boulders
 - 1. embeddedness <20% (very little sand, usually only behind large boulders)..... 15
 - 2. embeddedness 20-40%..... 12
 - 3. embeddedness 40-80%..... 8
 - 4. embeddedness >80%..... 3
- B. substrate gravel and cobble
 - 1. embeddedness <20%..... 14
 - 2. embeddedness 20-40%..... (11)
 - 3. embeddedness 40-80%..... 6
 - 4. embeddedness >80%..... 2
- C. substrate mostly gravel
 - 1. embeddedness <50%..... 8
 - 2. embeddedness >50%..... 4
- D. substrate homogeneous
 - 1. substrate nearly all bedrock..... 3
 - 2. substrate nearly all sand..... 3
 - 3. substrate nearly all detritus..... 2
 - 4. substrate nearly all silt/ clay..... 1

Remarks _____ Subtotal 11

IV. Pool Variety Pools are areas of deeper than average maximum depths with little or no surface turbulence. Water velocities associated with pools are always slow. Pools may take the form of "pocket water", small pools behind boulders or obstructions, in large high gradient streams, or side eddies.

- A. Pools present
 - 1. Pools Frequent (>30% of 200m area surveyed)
 - a. variety of pool sizes..... 10
 - b. pools about the same size (indicates pools filling in)..... (8)
 - 2. Pools Infrequent (<30% of the 200m area surveyed)
 - a. variety of pool sizes..... 6
 - b. pools about the same size..... 4
- B. Pools absent..... 0

Subtotal 6

Pool bottom boulder-cobble=hard Bottom sandy-sink as you walk Silt bottom Some pools over wader depth

Remarks _____

V. Riffle Habitats

Definition: Riffle is area of recretion-can be debris dam, or narrow channel area.

Riffles Frequent

Riffles Infrequent

	<u>Score</u>	<u>Score</u>
A. well defined riffle and run, riffle as wide as stream and extends 2X width of stream....	16	12
B. riffle as wide as stream but riffle length is not 2X stream width	14	7
C. riffle not as wide as stream and riffle length is not 2X stream width	10	3
D. riffles absent.....	0	

Subtotal 16

Channel Slope: Typical for area Steep=fast flow Low=like a coastal stream

VI. Bank Stability and Vegetation

FACE UPSTREAM

Left Bank Score Rt. Bank Score

A. Banks stable

1. little evidence of erosion or bank failure(except outside of bends), little potential for erosion.. 7 7

B. Erosion areas present

1. diverse trees, shrubs, grass; plants healthy with good root systems..... 6 6

2. few trees or small trees and shrubs; vegetation appears generally healthy..... 5 5

3. sparse mixed vegetation; plant types and conditions suggest poorer soil binding..... 3 3

4. mostly grasses, few if any trees and shrubs, high erosion and failure potential at high flow.. 2 2

5. little or no bank vegetation, mass erosion and bank failure evident..... 0 0

Total 10

Remarks _____

VII. Light Penetration Canopy is defined as tree or vegetative cover directly above the stream's surface. Canopy would block out sunlight when the sun is directly overhead. Note shading from mountains, but not use to score this metric.

	<u>Score</u>
A. Stream with good canopy with some breaks for light penetration	10
B. Stream with full canopy - breaks for light penetration absent.....	8
C. Stream with partial canopy - sunlight and shading are essentially equal.....	7
D. Stream with minimal canopy - full sun in all but a few areas.....	2
E. No canopy and no shading.....	0

Subtotal 8

Remarks _____

VIII. Riparian Vegetative Zone Width

Definition: Riparian zone for this form is area of natural vegetation adjacent to stream (can go beyond floodplain). Definition: A break in the riparian zone is any place on the stream banks which allows sediment or pollutants to directly enter the stream, such as paths down to stream, storm drains, uprooted trees, otter slides, etc.

FACE UPSTREAM

Lft. Bank Score Rt. Bank Score

Dominant vegetation: Trees Shrubs Grasses Weeds/old field Exotics (kudzu, etc)

A. Riparian zone intact (no breaks)

1. width > 18 meters..... 5 5

2. width 12-18 meters..... 4 4

3. width 6-12 meters..... 3 3

4. width < 6 meters..... 2 2

B. Riparian zone not intact (breaks)

1. breaks rare

a. width > 18 meters..... 4 4

b. width 12-18 meters..... 3 3

c. width 6-12 meters..... 2 2

d. width < 6 meters..... 1 1

2. breaks common

a. width > 18 meters..... 3 3

b. width 12-18 meters..... 2 2

c. width 6-12 meters..... 1 1

d. width < 6 meters..... 0 0


Total 8

Remarks _____

Page Total 42

Disclaimer-form filled out, but score doesn't match subjective opinion-atypical stream.

TOTAL SCORE 74



Prepared for:



Project:

**BRAHMA
MITIGATION SITE**

Alamance County, NC

Title:

**ASBUILT
FENCING**

Drawn by:

KRJ

Date:

APR 2021

Scale:


1:3000

Project No.:

19-006

Legend

- ▭ Brahma Easement Boundary
- + Fence
- Gate




FIGURE

F-1

05/08/99

NC DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF MITIGATION SERVICES AS-BUILT PLANS BRAHMA SITE

STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
N.C.	BRAHMA SITE	1	



VICINITY MAP
Not to Scale


LOCATION: ALAMANCE COUNTY, NORTH CAROLINA

TYPE OF WORK: STREAM RESTORATION AND ENHANCEMENT (CLEARING, GRUBBING, GRADING, EROSION CONTROL AND PLANTING)

INDEX OF SHEETS

SHEET NUMBER	SHEET
01	Title Sheet
02	Symbology
03	Easement
04A THRU 04P	As-Built Structures
04Q	As-Built Planting Table

RECORD DRAWING



Brahma Site
Site #100058
Cape Fear 03030002;
Alamance County
Contract #0007525
Latitude: 35.8540
Longitude: -79.4106 (WGS84)

SURVEYORS CERTIFICATION(S)

Surveyor's disclaimer: No attempt was made to locate any cemeteries, wetlands, hazardous material sites, underground utilities or any other features above, or below ground other than those shown. However, no visible evidence of cemeteries or utilities, aboveground or otherwise, was observed by the undersigned (other than those shown).

I certify that the survey is of an existing parcel or parcels of land or one or more existing easements and does not create a new street or change an existing street.


I, **JOHN A. RUDOLPH**, certify that this plat was prepared under my supervision from an actual field survey made under my supervision, of as-built conditions.

That the boundaries not surveyed are clearly indicated as such and were plotted from information as referenced herein; That the ratio of precision as calculated was 1:7,500+ and that the global navigational satellite system (GNSS) was used to perform this survey and the following information was used:

Class of Survey: CLASS B (HORIZONTAL) CLASS B (VERTICAL)
 Positional Accuracy: 0.12 feet (HORIZONTAL)
 Type of GPS field procedure: RTK
 Dates of survey: February and March 2021
 Datum/Epoch: NAD 1983(2011)
 Published/Fixed Control Use: OPUS
 Geoid Model: 2012B CONUS
 Combined Grid Factor: 0.99995565 GROUND TO GRID
 Units: US SURVEY FEET

That this plat meets the requirements of the standards of practice for land surveying in North Carolina. Witness my hand and seal this 3rd day of March, 2021.

SEAL OR STAMP




3/24/2021

L-4194
Professional Land Surveyor License Number

CONTRACT: BRAHMA SITE

GRAPHIC SCALES



PROPOSED LENGTH OF -UT 1- = 4298	PROPOSED LENGTH OF -UT 4- = 129		
PROPOSED LENGTH OF -UT 2- = 1385	PROPOSED LENGTH OF -UT 5- = 657		
PROPOSED LENGTH OF -UT 2A- = 30	PROPOSED LENGTH OF -UT 6- = 501		
PROPOSED LENGTH OF -UT 3- = 239	PROPOSED LENGTH OF -UT 7- = 47		
TOTAL STREAM LENGTHS (LF) = 7286			
RESTORATION LEVEL	STREAM (linear footage)	RIPARIAN WETLAND (acreage)	NONRIPARIAN WETLAND (acreage)
RESTORATION	740	4.740	0.000
ENHANCEMENT I	3034	3.709	0.000
ENHANCEMENT II	2378	0.000	0.000
PRESERVATION	911	0.601	0.000
TOTALS	7063	9.050	0.000
MITIGATION UNITS	3881.066 SMUs	6.655 RIPARIAN WMUs	NONRIPARIAN WMUs

Axiom Environmental
 218 Snow Ave
 Raleigh, NC 27603

GRANT LEWIS
 PROJECT DESIGNER


Restoration Systems
 1101 Haynes St.
 Suite 211
 Raleigh, NC 27604

WORTH CREECH
 SITE CONSTRUCTION MANAGER

Prepared In the Office of:
SUNGATE DESIGN GROUP, P.A.

905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890

JOSHUA G. DALTON, P.E.
 PROJECT ENGINEER



3/24/2021

DATE:

3/24/2021
Brahma_Rdy_PSH_AB_0.dgn
jnarvey



RECORD DRAWING

CONVENTIONAL PLAN SHEET SYMBOLS

Note: Not to Scale

*S.U.E. = Subsurface Utility Engineering

SHEET NAME		SHEET NUMBER
SYMBOLOLOGY		2
PROJECT NAME: BRAHMA SITE		
COUNTY: ALAMANCE	DATE: 2021	

905 JONES FRANKLIN ROAD
RALEIGH, NORTH CAROLINA 27606
TEL. (919) 859-2243
ENG FIRM LICENSE NO. C-890

BOUNDARIES AND PROPERTY:

State Line	-----
County Line	-----
Township Line	-----
City Line	-----
Reservation Line	-----
Property Line	-----
Existing Iron Pin	○ EIP
Computed Property Corner	✕
Property Monument	◻ EGM
Parcel/Sequence Number	①23
Existing Fence Line	-x-x-x-
Proposed Fence Gate	◻
Proposed Barbed Wire Fence	◊
Existing Wetland Boundary	----- WLB
Proposed Wetland Boundary	----- WLB
Existing Endangered Animal Boundary	----- EAB
Existing Endangered Plant Boundary	----- EPB
Existing Historic Property Boundary	----- HPB

BUILDINGS AND OTHER CULTURE:

Gas Pump Vent or U/G Tank Cap	○
Sign	○ S
Well	○ W
Small Mine	✕
Foundation	◻
Area Outline	◻
Cemetery	⊕
Building	◻
School	⊕
Church	⊕
Dam	⊕

HYDROLOGY:

Stream or Body of Water	-----
Hydro, Pool or Reservoir	-----
Jurisdictional Stream	----- JS
Buffer Zone 1	----- BZ 1
Buffer Zone 2	----- BZ 2
Flow Arrow	←
Disappearing Stream	-----
Spring	○
Wetland	-----
Proposed Lateral, Tail, Head Ditch	-----

RIGHT OF WAY & PROJECT CONTROL:

Secondary Horiz and Vert Control Point	◆
Primary Horiz Control Point	○
Primary Horiz and Vert Control Point	●

Exist Permanent Easement Pin and Cap	◇
New Permanent Easement Pin and Cap	◇
Vertical Benchmark	⊠
Existing Right of Way Marker	△
Existing Right of Way Line	-----
New Right of Way Line	-----
New Right of Way Line with Pin and Cap	△
New Right of Way Line with Concrete or Granite RW Marker	△
New Control of Access Line with Concrete C/A Marker	△
Existing Control of Access	△
New Control of Access	△
Existing Easement Line	----- E
New Conservation Easement	----- E
New Temporary Drainage Easement	----- TDE
New Permanent Drainage Easement	----- PDE
New Permanent Drainage / Utility Easement	----- DUE
New Permanent Utility Easement	----- PUE
New Temporary Utility Easement	----- TUE
New Aerial Utility Easement	----- AUE

ROADS AND RELATED FEATURES:

Existing Edge of Pavement	-----
Existing Curb	-----
Proposed Slope Stakes Cut	----- C
Proposed Slope Stakes Fill	----- F
Proposed Curb Ramp	----- CR
Existing Metal Guardrail	-----
Proposed Guardrail	-----
Existing Cable Guiderail	-----
Proposed Cable Guiderail	-----
Equality Symbol	⊕
Pavement Removal	-----

VEGETATION:

Single Tree	⊕
Single Shrub	⊕
Hedge	-----
Woods Line	-----
Orchard	-----
Vineyard	-----

EXISTING STRUCTURES:

MAJOR:	
Bridge, Tunnel or Box Culvert	----- CONC
Bridge Wing Wall, Head Wall and End Wall	----- CONC WW
MINOR:	
Head and End Wall	----- CONC HW

Pipe Culvert	-----
Footbridge	-----
Drainage Box: Catch Basin, DI or JB	◻ CB
Paved Ditch Gutter	-----
Storm Sewer Manhole	⊕
Storm Sewer	----- S

UTILITIES:

POWER:	
Existing Power Pole	●
Proposed Power Pole	○
Existing Joint Use Pole	●
Proposed Joint Use Pole	○
Power Manhole	⊕
Power Line Tower	⊠
Power Transformer	⊠
U/G Power Cable Hand Hole	●
H-Frame Pole	●
U/G Power Line LOS B (S.U.E.*)	----- P
U/G Power Line LOS C (S.U.E.*)	----- P
U/G Power Line LOS D (S.U.E.*)	----- P

TELEPHONE:

Existing Telephone Pole	●
-------------------------	---

WATER:

Water Manhole	⊕
Water Meter	○
Water Valve	⊗
Water Hydrant	⊕
U/G Water Line LOS B (S.U.E.*)	----- W
U/G Water Line LOS C (S.U.E.*)	----- W
U/G Water Line LOS D (S.U.E.*)	----- W
Above Ground Water Line	----- A/G Water

GAS:

Gas Valve	◇
Gas Meter	◇
U/G Gas Line LOS B (S.U.E.*)	----- G
U/G Gas Line LOS C (S.U.E.*)	----- G
U/G Gas Line LOS D (S.U.E.*)	----- G
Above Ground Gas Line	----- A/G Gas

SANITARY SEWER:

Sanitary Sewer Manhole	⊕
Sanitary Sewer Cleanout	⊕
U/G Sanitary Sewer Line	----- SS
Above Ground Sanitary Sewer	----- A/G Sanitary Sewer
SS Forced Main Line LOS B (S.U.E.*)	----- FSS
SS Forced Main Line LOS C (S.U.E.*)	----- FSS

SS Forced Main Line LOS D (S.U.E.*) ----- FSS

MISCELLANEOUS:

Utility Pole	●
Utility Pole with Base	◻
Utility Located Object	○
Utility Traffic Signal Box	⊠
Utility Unknown U/G Line LOS B (S.U.E.*)	----- TUL
U/G Tank; Water, Gas, Oil	◻
Underground Storage Tank, Approx. Loc.	◻ UST
A/G Tank; Water, Gas, Oil	◻
Geoenvironmental Boring	⊕
U/G Test Hole LOS A (S.U.E.*)	⊕
Abandoned According to Utility Records	⊕ AATUR
End of Information	⊕ E.O.I.

Riffle Rip Rap -----

Log Vane -----

Log Cross Vane -----

Step Pool Structure -----

Stream Plug -----

Floodplain Interceptor -----

Proposed Fence -----

Limits of Disturbance ----- LOD

AS-BUILT:

Stream Centerline -----

Stream Top of Bank -----

Stream Gauge -----

Groundwater Gauge ----- #

Benthic & Water Quality Station ----- 1

Origin Point on CVS Plots -----


CVS Plots ----- #

Cross Section ----- XS-10R

Adjusted Stream Structure -----

Not Constructed -----

RECORD DRAWING




SURVEY INFORMATION PROPERTY/
EASEMENT PROVIDED BY:
K2 DESIGN GROUP, P.A.
5688 U.S. HIGHWAY 70 EAST
GOLDSBORO, NC 27534



SHEET NAME		SHEET NUMBER	
EASEMENT		3	
PROJECT NAME: BRAHMA SITE			
COUNTY: ALAMANCE		DATE: 2021	



SUNGATE DESIGN GROUP, P.A.
905 JONES FRANKLIN ROAD
RALEIGH, NORTH CAROLINA 27606
TEL: (919) 859-2243
ENG FIRM LICENSE NO. C-890



3/24/2021
P:\Projects\2021\PSH_AB_03.dgn
jbarney



SHEET NAME		SHEET NUMBER	
AS-BUILT STRUCTURES		4A	
PROJECT NAME: BRAHMA SITE			
COUNTY: ALAMANCE	DATE: 2021		


SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.

**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**

DocuSigned by:
Joshua G. Dalton
 1089AD8514994C3...
 PROFESSIONAL SEAL
 26971
 ENGINEER
 JOSHUA G. DALTON
 DATE: 3/24/2021


RECORD DRAWING



RIFFLE BED MATERIAL IS REQUIRED
IN ALL RESTORATION AND
ENHANCEMENT (LEVEL I) REACHES

WETLAND ENHANCEMENT AREAS DERIVED FROM
APPROVED PRELIMINARY JURISDICTIONAL DELINEATION

-UT1- STRUCTURE LOCATIONS				
STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	765,125.13	1,879,060.30	622.25	624.54
CROSS VANE	765,146.24	1,879,028.05	621.91	624.11
CROSS VANE	765,186.00	1,879,010.22	621.56	623.69
CROSS VANE	765,291.17	1,878,959.69	620.68	620.90



3/24/2021
 P:\Projects\2021\Brahma\AB_04A.dgn
 jhervay


-UT1- STRUCTURE LOCATIONS				
STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	765,434.95	1,878,901.31	619.68	619.87
CROSS VANE	765,520.25	1,878,800.61	618.77	618.94
CROSS VANE	765,525.86	1,878,768.87	618.47	618.70
LOG VANE	765,558.80	1,878,661.02	617.62	
LOG VANE	765,544.83	1,878,622.48	617.37	617.52

RECORD DRAWING

SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4B
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890


CAROLINE A HINSHAW
 PIN: 8776769067
 DEED BOOK: 3705
 PAGE: 0067



**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**


DocuSigned by:
 Joshua G Dalton
 1089A89C14994C3...
 SEAL
 26971
 ENGINEER
 JOSHUA G. DALTON

3/24/2021
 DATE:



RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES

WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION




3/24/2021
 P:\Projects\2021\Brahma\UT1\AB_04B.dgn
 jh-vay

SHEET NAME		SHEET NUMBER
AS-BUILT STRUCTURES		4C
PROJECT NAME: BRAHMA SITE		
COUNTY: ALAMANCE	DATE: 2021	

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.



DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DocuSigned by:
 Joshua G. Dalton
 1089A08C14994C3...

PROFESSIONAL SEAL
 26971
 ENGINEER
 JOSHUA G. DALTON


3/24/2021
 DATE:

-UT1- STRUCTURE LOCATIONS

STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	765,562.36	1,878,560.27	616.99	617.14
CROSS VANE	765,572.21	1,878,537.31	616.50	616.82
CROSS VANE	765,611.54	1,878,467.91	615.99	616.11
CROSS VANE	765,640.94	1,878,430.75	615.62	615.77
LOG VANE	765,659.10	1,878,375.67	615.03	615.13
CROSS VANE	765,695.61	1,878,356.54	614.65	614.73
BOULDER SILL	765,753.72	1,878,304.49	613.97	614.28
LOG SILL	765,840.94	1,878,278.34	613.40	613.48

-UT2- STRUCTURE LOCATIONS

STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
LOG SILL	765,550.00	1,878,326.67	616.93	617.06
LOG SILL	765,571.78	1,878,340.86	616.64	616.84
LOG VANE	765,665.81	1,878,336.61	615.94	616.10
STEP POOL STRUCTURE	765,680.50	1,878,336.52	615.81	615.94
STEP POOL STRUCTURE	765,699.63	1,878,348.14	614.45	615.25



Permanent Pipe Crossings

Centerline Station	Pipe Size	Pipe Length (feet)	Pipe Invert In (feet)	Pipe Invert Out (feet)	Bury Depth (feet)
12+98-UT2-	1 at 66"x51" CSPA	39	615.3	615.1	1.0

3/24/2021
 P:\Projects\2021\Brahma\Drawings\AS-Built\04C.dgn
 jdalton

-UT1- STRUCTURE LOCATIONS				
STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
LOG SILL	765,874.84	1,878,294.90	613.20	613.40
CROSS VANE	765,993.42	1,878,293.50	612.64	
DOUBLE LOG VANE	765,984.44	1,878,183.88	612.21	612.34
LOG VANE	766,025.11	1,878,191.51	611.81	612.03
CROSS VANE	766,064.97	1,878,190.82	611.49	611.51
CROSS VANE	766,104.78	1,878,203.19	611.16	611.09
CROSS VANE	766,124.29	1,878,207.68	610.86	610.78
CROSS VANE	766,171.21	1,878,180.66	610.30	
LOG SILL	766,183.72	1,878,176.23		610.43
LOG SILL	766,190.94	1,878,172.45		610.02
CROSS VANE	766,196.43	1,878,167.93	610.02	610.01
CROSS VANE	766,214.01	1,878,145.05	609.69	609.90

RECORD DRAWING

SHEET NAME: AS-BUILT STRUCTURES
 SHEET NUMBER: 4D
 PROJECT NAME: BRAHMA SITE
 COUNTY: ALAMANCE
 DATE: 2021

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890



Axiom Environmental, Inc.

SCALE: 1" = 50'

DATE: 3/24/2021

WETLAND ENHANCEMENT AREAS DERIVED FROM APPROVED PRELIMINARY JURISDICTIONAL DELINEATION

RIFFLE BED MATERIAL IS REQUIRED IN ALL RESTORATION AND ENHANCEMENT (LEVEL I) REACHES



DocuSigned by:
 Joshua G. Dalton
 1089AD8014994C3...
 PROFESSIONAL SEAL
 26971
 ENGINEER
 JOSHUA G. DALTON
 DATE: 3/24/2021



3/24/2021
 P:\Projects\2021\Brahma\UT1\UT1-AB.dgn

RECORD DRAWING

SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4E
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.



**DOCUMENT NOT CONSIDERED FINAL
 UNLESS ALL SIGNATURES COMPLETED**

DocuSigned by
 Joshua G Dalton
 1089ADE614994C3...

**PROFESSIONAL
 SEAL**
 26971
 ENGINEER
 JOSHUA G. DALTON


3/24/2021
 DATE:

-UT1- STRUCTURE LOCATIONS


STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	766,283.20	1,878,082.41	608.98	609.33
CROSS VANE	766,298.32	1,878,032.26	608.67	608.76
CROSS VANE	766,372.99	1,878,009.84	608.20	608.25
CROSS VANE	766,481.28	1,878,044.68	607.48	607.57
LOG VANE	766,517.64	1,878,063.19	607.17	606.90
CROSS VANE	766,597.24	1,878,047.71	606.76	606.66

-UT3- STRUCTURE LOCATIONS

STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	766,465.95	1,878,104.62	609.20	609.47
CROSS VANE	766,468.51	1,878,082.92	608.81	609.00
CROSS VANE	766,486.64	1,878,059.38	608.34	608.69



RECORD DRAWING



SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4F
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021


SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.

**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**

DocuSigned by:
Joshua G. Dalton
 1089AD8C14994C3...

3/24/2021
 DATE:



(2) 18" PIPES NOT CONSTRUCTED DUE TO FLOODPLAIN ELEVATIONS THE SAME AS PROPOSED PIPE INVERTS

LOG CROSS VANE STRUCTURE REPLACED WITH BOULDER SILL DUE TO MATURE TREE WITH ROOT MASS

ALIGNMENT CHANGE DUE TO BEDROCK


RIFFLE BED MATERIAL IS REQUIRED IN ALL RESTORATION AND ENHANCEMENT (LEVEL I) REACHES

-UT1- STRUCTURE LOCATIONS

STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	766,693.96	1,878,064.03	606.00	608.30
CROSS VANE	766,767.07	1,878,054.30	605.53	605.77
CROSS VANE	766,932.52	1,878,022.04	604.57	604.72
BOULDER SILL	766,957.00	1,877,999.19	604.31	604.40

Permanent Pipe Crossings

Centerline Station	Pipe Size	Pipe Length (feet)	Pipe Invert In (feet)	Pipe Invert Out (feet)	Bury Depth (feet)
27+85 -UT1-	1 at 81"x59" CSPA	42	604.1	603.9	1.0



3/24/2021
 P:\Projects\2021\Brahma\AS-Built\AS-Built.dgn
 jg

RIFFLE BED MATERIAL IS REQUIRED
IN ALL RESTORATION AND
ENHANCEMENT (LEVEL I) REACHES



RECORD DRAWING

SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4G
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021

SUNGATE DESIGN GROUP, P.A.
905 JONES FRANKLIN ROAD
RALEIGH, NORTH CAROLINA 27606
TEL: (919) 859-2243
ENG FIRM LICENSE NO. C-890


Axiom Environmental, Inc.

WETLAND ENHANCEMENT AREAS DERIVED FROM
APPROVED PRELIMINARY JURISDICTIONAL DELINEATION





**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**

DocuSigned by:
Joshua G. Dalton
1089AP8C14994C3...
26971
ENGINEER
JOSHUA G. DALTON
3/24/2021
DATE:



STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
BOULDER SILL	767,145.52	1,877,999.38	603.36	602.49
BOULDER CROSS VANE	767,184.57	1,877,950.80	602.83	602.82
CROSS VANE	767,200.70	1,877,916.10	602.40	602.45
CROSS VANE	767,188.59	1,877,858.56	601.78	601.86
CROSS VANE	767,206.36	1,877,820.32	601.40	601.41
LOG SILL	767,262.89	1,877,822.30	600.84	600.93
LOG SILL	767,287.08	1,877,815.34	600.62	600.87
STEP POOL STRUCTURE	767,291.13	1,877,812.86	600.42	600.55
STEP POOL STRUCTURE	767,319.65	1,877,790.33	599.81	600.54

Centerline Station	Pipe Size	Pipe Length (feet)	Pipe Invert In (feet)	Pipe Invert Out (feet)	Bury Depth (feet)
33+66 -UT1-	1 at 81"x59" CSPA	42	600.2	599.8	1.0





3/24/2021
P:\Projects\2021\psh_AB_04G.dgn
jhr.vay

RECORD DRAWING

SHEET NAME		SHEET NUMBER
AS-BUILT STRUCTURES		4H
PROJECT NAME: BRAHMA SITE		
COUNTY: ALAMANCE	DATE: 2021	

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.



**RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES**

**WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION**



**DOCUMENT NOT CONSIDERED FINAL
 UNLESS ALL SIGNATURES COMPLETED**

DocuSigned by:
 Joshua G. Dalton
 1089AD8C14994C3...

**PROFESSIONAL
 SEAL
 26971
 ENGINEER
 JOSHUA G. DALTON**


3/24/2021

DATE:



3/24/2021
 8:28:12 AM
 R:\Projects\2021\Brahma\Drawings\AS-Built\4H.dgn
 jhd

RECORD DRAWING




SHEET NAME		SHEET NUMBER	
AS-BUILT STRUCTURES		4I	
PROJECT NAME: BRAHMA SITE			
COUNTY: ALAMANCE	DATE: 2021		




SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890

**DOCUMENT NOT CONSIDERED FINAL
 UNLESS ALL SIGNATURES COMPLETED**



3/24/2021
DATE:




MATCHLINE STA 40+00 - UT1-
 SEE SHEET 4H

END PRESERVATION
 STA 45+54 - UT1-


**RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES**

**WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION**



3/24/2021
 P:\Projects\Brahma\psh_AB_041.dgn
 jhr.vay

RECORD DRAWINGS



SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4J
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021


SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.

**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**

DocuSigned by:
 Joshua G. Dalton
 4089AD8C14994C3
 SEAL
 26971
 ENGINEER
 JOSHUA G. DALTON


3/24/2021
 DATE:





CAROLINE A HINSHAW
 PIN: 8776769067
 DEED BOOK: 3705
 PAGE: 0067

RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES

WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION



3/24/2021
 P:\Projects\2021\Brahma\Drawings\AS-Built\AB_04J.dgn
 jhervay



SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4K
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890


Axiom Environmental, Inc.

**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**

RECORD DRAWINGS

DocuSigned by:
 Joshua G. Dalton
 1089AD8C14994C3...

DATE: 3/24/2021




STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	765,018.52	1,877,992.78	622.82	623.15
CROSS VANE	765,097.82	1,877,998.75	621.85	621.93
LOG SILL	765,139.58	1,878,017.91	621.23	

CAROLINE A HINSHAW
 PIN: 8776769067
 DEED BOOK: 3705
 PAGE: 0067


RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES

WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION





3/24/2021
 C:\hms\rdj\psh_AB_04K.dgn
 rdj

CAROLINE A HINSHAW
 PIN: 8776769067
 DEED BOOK: 3705
 PAGE: 0067




RECORD DRAWINGS

SHEET NAME		SHEET NUMBER	
AS-BUILT STRUCTURES		4L	
PROJECT NAME: BRAHMA SITE			
COUNTY: ALAMANCE			DATE: 2021

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890

**DOCUMENT NOT CONSIDERED FINAL
 UNLESS ALL SIGNATURES COMPLETED**





3/24/2021

DATE:

**RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES**


**WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION**




3/24/2021
 Pr...
 ...

RECORD DRAWINGS


SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4M
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021



SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890




**DOCUMENT NOT CONSIDERED FINAL
 UNLESS ALL SIGNATURES COMPLETED**





3/24/2021

DATE:



WETLAND ENHANCEMENT AREAS DERIVED FROM APPROVED PRELIMINARY JURISDICTIONAL DELINEATION

3/24/2021
 P:\Projects\Brahma\Drawings\AS-Built\AB_04M.dgn
 jharvey




SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4N
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021




RECORD DRAWING

**DOCUMENT NOT CONSIDERED FINAL
UNLESS ALL SIGNATURES COMPLETED**



3/24/2021
DATE:




CAROLINE A HINSHAW
PIN: 8776769067
DEED BOOK: 3705
PAGE: 0067

**RIFFLE BED MATERIAL IS REQUIRED
IN ALL RESTORATION AND
ENHANCEMENT (LEVEL I) REACHES**

**WETLAND ENHANCEMENT AREAS DERIVED FROM
APPROVED PRELIMINARY JURISDICTIONAL DELINEATION**



-UT3- STRUCTURE LOCATIONS

STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	766,412.52	1,878,247.26	611.34	611.60
CROSS VANE	766,414.63	1,878,208.85	610.64	610.79
CROSS VANE	766,425.85	1,878,184.62	610.19	610.58



3/24/2021
P:\Projects\Brahma\AS-Built\AS-Built.dgn

-UT6- STRUCTURE LOCATIONS				
STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
STONE CROSS VANE	767,226.16	1,878,256.47	610.76	610.69
STEP POOL STRUCTURE	767,211.32	1,878,196.28	609.17	608.11
STEP POOL STRUCTURE	767,214.52	1,878,177.81	606.71	607.01



SHEET NAME	PLAN AND PROFILE	SHEET NUMBER	40
PROJECT NAME:	BRAHMA SITE		
COUNTY:	ALAMANCE	DATE:	2020

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.



RIFFLE BED MATERIAL IS REQUIRED
 IN ALL RESTORATION AND
 ENHANCEMENT (LEVEL I) REACHES

WETLAND ENHANCEMENT AREAS DERIVED FROM
 APPROVED PRELIMINARY JURISDICTIONAL DELINEATION

RECORD DRAWING




DOCUMENT NOT CONSIDERED FINAL
 UNLESS ALL SIGNATURES COMPLETED

DocuSigned by:
 Joshua G. Dalton
 10882D8C14994C3...
 26971
 ENGINEER
 JOSHUA G. DALTON
 3/24/2021
 DATE:



Permanent Pipe Crossings					
Centerline Station	Pipe Size	Pipe Length (feet)	Pipe Invert In (feet)	Pipe Invert Out (feet)	Bury Depth (feet)
5+34 -UT5-	1 at 42" CSP	36	603.5	603.3	0.7

3/24/2021
 P:\Projects\2020\Brahma\Drawings\AB_040.dgn
 jgd



SHEET NAME	SHEET NUMBER
AS-BUILT STRUCTURES	4P
PROJECT NAME:	BRAHMA SITE
COUNTY:	ALAMANCE
DATE:	2021

SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL: (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.

RECORD DRAWING

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DocuSigned by:
 Joshua G. Dalton
 1089AD8C14994C3...

ENGINEER
 JOSHUA G. DALTON

3/24/2021
 DATE:

-UT6- STRUCTURE LOCATIONS				
STR. TYPE	NORTHING	EASTING	Prop Elevation	AB Survey Elevation
CROSS VANE	767,174.58	1,878,624.76	621.90	621.76
CROSS VANE	767,184.61	1,878,611.75	621.41	621.34
CROSS VANE	767,200.41	1,878,605.30	620.95	620.88
CROSS VANE	767,210.24	1,878,589.25	620.48	620.53
CROSS VANE	767,224.38	1,878,577.54	619.96	620.14
CROSS VANE	767,230.86	1,878,556.18	619.37	619.36
CROSS VANE	767,239.65	1,878,539.53	618.78	618.85
CROSS VANE	767,238.75	1,878,520.34	618.24	618.40
CROSS VANE	767,249.22	1,878,499.62	617.60	618.10
CROSS VANE	767,249.58	1,878,448.52	616.13	
CROSS VANE	767,246.33	1,878,414.57	615.11	615.28
CROSS VANE	767,248.68	1,878,397.88	614.71	614.68
STONE CROSS VANE	767,246.05	1,878,383.56	614.35	614.31
CROSS VANE	767,246.46	1,878,369.40	613.99	614.11
CROSS VANE	767,242.71	1,878,335.38	613.12	613.12
STONE CROSS VANE	767,234.16	1,878,301.06	612.11	612.10
STONE CROSS VANE	767,225.97	1,878,287.00	611.57	611.36

RIFFLE BED MATERIAL IS REQUIRED IN ALL RESTORATION AND ENHANCEMENT (LEVEL I) REACHES


WETLAND ENHANCEMENT AREAS DERIVED FROM APPROVED PRELIMINARY JURISDICTIONAL DELINEATION



3/24/2021
 P:\Projects\2021\Brahma\Drawings\AB_04P.dgn
 jhd

RECORD DRAWING

SHEET NAME		SHEET NUMBER
AS-BUILT PLANTING		4Q
PROJECT NAME: BRAHMA SITE		
COUNTY: ALAMANCE	DATE: 2021	



SUNGATE DESIGN GROUP, P.A.
 905 JONES FRANKLIN ROAD
 RALEIGH, NORTH CAROLINA 27606
 TEL (919) 859-2243
 ENG FIRM LICENSE NO. C-890

Axiom Environmental, Inc.

Vegetation Association	Piedmont/Low Mountain Alluvial Forest*		Stream-side Assemblage**		TOTAL
	Area (acres)				
Area (acres)	13.7		4.2		17.9
Species	# planted*	% of total	# planted**	% of total	# planted
Tag alder (<i>Alnus serrulata</i>)	--	--	571	5	571
River birch (<i>Betula nigra</i>)	932	10	571	5	1503
Silky dogwood (<i>Cornus amomum</i>)	932	10	2285	20	3216
Green ash (<i>Fraxinus pennsylvanica</i>)	932	10	2285	20	3216
Tulip poplar (<i>Liriodendron tulipifera</i>)	932	10	--	--	932
Sycamore (<i>Platanus occidentalis</i>)	1863	20	2285	20	4148
Black gum (<i>Nyssa sylvatica</i>)	932	10	--	--	932
Water oak (<i>Quercus nigra</i>)	1397	15	1142	10	2540
Willow oak (<i>Quercus phellos</i>)	1397	15	1142	10	2540
Black willow (<i>Salix nigra</i>)	--	--	1142	10	1142
TOTAL	9316	100	11424	100	20740

* Planted at a density of 680 stems/acre.

** Planted at a density of 2720 stems/acre.

Area (acres)	17.7
Species	Total
Tag alder (<i>Alnus serrulata</i>)	571
River birch (<i>Betula nigra</i>)	1503
Silky dogwood (<i>Cornus amomum</i>)	2700
Green ash (<i>Fraxinus pennsylvanica</i>)	900
Tulip poplar (<i>Liriodendron tulipifera</i>)	1000
Sycamore (<i>Platanus occidentalis</i>)	2700
Black gum (<i>Nyssa sylvatica</i>)	1000
Water oak (<i>Quercus nigra</i>)	2000
Willow oak (<i>Quercus phellos</i>)	2000
Black willow (<i>Salix nigra</i>)	1142
Pawpaw (<i>Asimina triloba</i>)	200
Hackberry (<i>Celtis occidentalis</i>)	500
Buttonbush (<i>Cephalanthus occidentalis</i>)	600
Common Persimmon (<i>Diospyros virginiana</i>)	500
Red Mulberry (<i>Morus rubra</i>)	600
White oak (<i>Quercus alba</i>)	1000
Overcup oak (<i>Quercus lyrata</i>)	500
Cherry bark oak (<i>Quercus pagoda</i>)	1000
Shumard oak (<i>Quercus shumardii</i>)	1000
American elm (<i>Ulmus americana</i>)	500
TOTAL	20200
Average Stems/Acre	1141