FINAL MONITORING REPORT (MY3)

WARREN WILSON COLLEGE STREAM MITIGATION SITE

Buncombe County, North Carolina

NCDMS Project ID No. 100019 Full Delivery Contract No. 7188 USACE Action ID No. SAW-2017-01557 NCDWR No. 20171158 RFP No. 16-006991 (Issued: 9/16/16)

French Broad River Basin Cataloging Unit 06010105

Data Collection: January - October 2022 Submission: February 2023



Prepared for:

NORTH CAROLINA DEPARTMENT OF ENVIRONMENTAL QUALITY
DIVISION OF MITIGATION SERVICES

1652 MAIL SERVICE CENTER

RALEIGH, NORTH CAROLINA 27699-1652

Restoration Systems, LLC 1101 Haynes St. Suite 211 Raleigh, North Carolina Ph: (919) 755-9490 Fx: (919) 755-9492



Response to Monitoring Year 3 (2022) DMS Comments

Warren Wilson College Stream Restoration Site French Broad River Basin – CU# 06010105– Buncombe County DMS Project ID No. 100019 Contract # 7188

Comments Received (Black Text) & Responses (Blue Text)

General:

1. DMS notes from the April 20, 2022 IRT credit release meeting are as follows:

The IRT noted that four vegetation plots did not meet the vegetation success criteria. The IRT noted that vegetation plot 25 showed some higher-than-normal tree mortality. Restoration Systems (RS) reported that vegetation plot 11 likely failed as it is located in a wet area. The IRT recommended adding some wet tolerant species if supplemental planting is completed on the site. The IRT also asked that RS look at vegetation diversity and address it accordingly if a supplemental planting effort is planned for the site in the future.

Response: Understood – RS requests a site visit with the IRT in early 2023 to discuss this area and several other topics noted in the 2022 IRT credit release meeting notes; wetland monitoring, vegetation development, and invasive species treatments.

Invasives on the site were discussed. The IRT asked about the Parrot Feather reported on the site. The Parrot Feather was located on UT3 near VP 8 and will be treated through project closeout. Erin Davis (DWR) recommended that Parrot Feather be called out in the CCPV maps in future monitoring reports.

Response: Parrot feather and other areas of invasives species concern are depicted on this year's CCPV.

Kim Isenhour (USACE) noted that the growing season should remain consistent per the IRT approved mitigation

Response: The MY3 2022 growing season is consistent with the approved mitigation plan, and is based on the NRCS growing season of April 2 to November 1.

RS requested that wetland gauge monitoring stop on the site as the wetland wells have been successful with no wetland credits being generated as part of the project. The IRT asked for additional wetland gauge monitoring in MY3(2022) and then a request from RS that wetland gauge monitoring stop at the 2023 credit release meeting. Response: To be discussed during the credit release meeting — PLEASE SEE PRE-CONSTRUCTION WETLAND GAUGE DATA VS POST-CONSTRUCTION GAUGE DATA ANALYSIS (TABLE 19, APPENDIX F).

The IRT asked about fescue treatment during construction and requested potential fescue ring sprays on the site. RS noted that they utilized sod mats during construction that included fescue. RS does not believe these areas of fescue are an issue on the site.

Response: Though present, RS still does not believe fescue is a concern currently or moving forward.

Kim Isenhour (USACE) asked that a note be added in future monitoring reports noting that all failed equipment has been repaired on the site.

Response: Understood.

Kim Isenhour (USACE) asked about River Cane on the site. RS noted that the River Cane is doing well and is successful on the tributaries that flow into the Swannanoa river. The IRT asked for drone footage in the River Cane area/s (if possible) with the MY3(2022) submittal. The IRT indicated that they would like to see the site later in 2022 (if possible) but noted that credit could be released as proposed for MY2 (2021).

Response: We apologize that photos of River Cane did not make it into the MY3 Photo Log – RS will acquire photos before the credit release meeting and will be prepared to show them at that time.

Please review the notes and confirm that all the requests, IRT questions and full delivery provider commitments from the 2022 credit release meeting have been addressed and included in the final MY3 (2022) report.

Response: RS has responded and updated the report as necessary.

2. Please ensure that project monitoring equipment is checked prior to the start of the growing season and at least quarterly thereafter to confirm that it is functioning properly and collecting data through the full growing season/monitoring year.

Response: All monitoring equipment will be checked for functionality before the growing season and periodically throughout the growing season.

Report

3. Section 1.2 Project Background: "The Warren Wilson College Stream Mitigation Site (hereafter referred to as the "Site") encompasses a 25.3-acre easement (pending easement modification) along cold-water, unnamed tributaries (UTs) to the Swannanoa River." The easement modification was completed and recorded in 2021. Please review, QA/QC and update the report text accordingly.

Response: The document was updated to remove all mention of the "pending easement modification."

- 4. Section 1.2 Project Background: "Results of preconstruction gauge data, included in Table 12 (Appendix F)". This should be updated to Table 18. Please review, QA/QC and update the report text accordingly.

 Response: The reference to preconstruction gauge data was updated to Table 18 (Appendix F).
- 5. Section 1.3 Project Components and Structure: "The log sill was constructed as designed and is holding grade. These changes are depicted on the Asbuilt Plan Sheets (Appendix E)." Asbuilt Plan Sheets are not available in Appendix E in the MY3 (2022) report. Additionally, it is not necessary to discuss construction deviations in MY3. The MY3 report can reference the project's final MY0/ Record Drawing report which is available on the DMS website. Please review, QA/QC and update the report accordingly.

 Response: The discussion of construction deviations was removed from Section 1.3.
- 6. Section 1.4 Success Criteria & Section 2.1 Monitoring: Please also reference the project's final IRT approved mitigation plan as it is the document that established the project's final success criteria. Please confirm that the success criteria reported in the MY3 (2022) report is the same as the IRT approved mitigation plan.

 Response: References to the IRT-approved detailed mitigation plan were added to sections 1.4 and 2.1. The success criteria detailed in the MY3 (2022) are the same as those established in the mitigation plan.
- 7. Section 2.1 Monitoring: In the report text, please discuss any project maintenance activities (invasive treatment, supplemental planting, beaver removal, etc.) that took place in MY3 (2022). As an example, CCPV Sheet 21 indicates; Parrot feather observed along reach. Spot treatment occurred throughout the year and will continue as needed. This and additional invasive treatment and maintenance activities should be discussed in the report text.
 - Response: A discussion of the 2022 invasive treatments was added to the "Vegetation Summary" in Section 2.1. These were the only site maintenance activities that took place during MY3 (2022).
- 8. Section 2.1 Monitoring Wetland Summary: Per IRT comments during the 2022 IRT Credit Release meeting, DMS recommends using the Buncombe County soil survey start/end dates for the remainder of wetland monitoring conducted on the site. DMS understands that RS will request termination of the groundwater well monitoring at the 2023 IRT credit release meeting.
 - Response: Noted. If wetland hydrology monitoring continues through the 2023 growing season, the Buncombe County soil survey start/end dates will be used to determine growing season.
- 9. Section 2.1 Monitoring Vegetation Summary: Please also discuss the five (5) random vegetation plots installed on the site and summarize the results in the report text.
 - Response: A discussion of the five vegetation transects was added to the "Vegetation Summary" in Section 2.1.

10. Section 2.1 Monitoring – Vegetation Summary: Based on the MY3 (2022) fixed and random plot results, is any supplemental planting warranted or planned in MY4 (2023). Please discuss and update the report text accordingly. In the report text, please also discuss the MY3 status of the rivercane planted/transplanted as part of project implementation.

Response: Currently, RS is not planning additional planting. Vegetation plots 1, 5, 11, and did not meet success criteria in 2022. However, plots 1 and 5 easily meet success criteria when taking natural recruits into consideration. A temporary transect was done adjacent to plot 11 and met success criteria with 445 stems/acre.

Plot 11 is in a wetland area adjacent to Gauge 8 that was meeting wetland success for 101 consecutive days, which likely caused the mortality of several less wet-tolerant species. However, RS does not believe this to be a negative, and believe the habitat within the area of plot 11 is appropriate. This is an area RS wishes to discuss with the IRT in the field.

Both plots 11 and 25 had no mortality between year 2 (2021) and year 3 (2022).

- 11. Table 1 Mitigation Assets and Components: The project credits in the summary portion of the table are in the "Riparian Wetland" column. Please review, QA/QC and update the table accordingly.
 Response: The cold water column was moved under the "Stream" section of the table.
- 12. Table 2 Project Activity and Reporting History: Please include all project maintenance activities (invasive treatment, supplemental planting, beaver removal, etc.) in the table.
 Response: Table 2 was updated to include all project maintenance activities.
- 13. Table 5 Visual Stream Morphology Stability Assessment: Please confirm that the project streams, banks and engineered structures are 100% stable and 100% preforming as intended as reported in the Table 5.

 Response: No areas of concern were observed during MY3 monitoring, and all streams, banks, and engineered structures are 100% stable and performing as intended.
- 14. Table 7. Planted Bare Root Woody Vegetation: Please include the species common name and the wetland indicator status for the species in the planted species list.
 Response: Common names and indicator statuses were added to Table 7.
- 15. Cross Section (Warren Wilson, UT 1, XS 7, Pool): Please review and include highlighted survey & points for MY3 (2022).

Response: The MY3 cross section data line and points were added to the UT 1 XS-7 plot.

- 16. Table 16. Verification of Bankfull Events: Please include an additional column noting the monitoring year associated with the reported bankfull event.
 Response: A column was added to table 16 indicating the monitoring year during which each bankfull event occurred.
- 17. Appendix G Site Photo Log: In the photo captions, please provide dates that the photos were taken. DMS recommends including the photo locations on the CCPV map or a separate map in Appendix G.

 Response: The crossing photos are the only permanent photo points other than cross-section and vegetation plot photos. A shapefile was created to show their locations on the CCPV. The 4 additional photos in the photo log were meant to provide a general overview of site vegetation and easement boundary conditions. The quantity and location of additional photos will likely change from year to year, and therefore, their locations were not added to the CCPV. Additionally, dates have been added to all photo captions in the photo log.

Digital Support File Comments:

18. No photo points were indicated on the CCPV map and no photos were submitted in the digital support files. Please verify that no photo points are required per the IRT approved mitigation plan.

Response: The only photo points required by the IRT approved mitigation plan are at cross-sections and vegetation plots, which were included in the digital submittal. However, the IRT recently requested that photos

be taken upstream and downstream of each piped/bridged crossing as part of annual monitoring. Those photo points have been included in the digital submittal as well.

- 19. The digital data submission is missing the following components:
 - a. Asset Table There was no asset table in the digital submission. Please include it in the final digital submittal

Response: An excel file containing Tables 1-4 was added to the digital submittal.

b. Project Activity Table - There was no project activity table in the digital submission. Please include it in the final digital submittal.

Response: An excel file containing Tables 1-4 was added to the digital submittal.

c. Two polygons were indicated as invasive problem areas in the CCPV and in the visual vegetation assessment table; no vegetation problem area polygons were submitted. Please submit the polygons in the final digital submittal.

Response: A shapefile for the MY3 invasive species polygons was added to the digital submittal.

WWC Year 3, 2022 Monitoring Summary

General Notes

- No encroachment was identified in Year 3.
- No evidence of nuisance animal activity (i.e., beaver, heavy deer browsing, etc.) was observed.

Streams

- Stream monitoring show that all stream channels and structures are stable.
- Stream Monitoring gauges malfunctioned in 2022. These gauges will be replaced and, in a manner, consistent with the standard stream gauge installation typically provided by DMS and the USACE to Restoration Systems See Exhibit A, Methods 1 3 for installation of a pressure transducers for stream restoration below immediately following this monitoring summary.

Wetlands

- Wetland hydrology has improved from preconstruction and year 1 (2020) conditions. All gauges were saturated/inundated for greater than 10 percent of the year 3 (2022) growing season, with gauges 2-7 and 9 being inundated for approximately 90% of the growing season (Table 17A-B, Appendix E). No wetland mitigation credit is being generated.
- At the April 2022 DMS/IRT monitoring review meeting, it was discussed that upon favorable MY3
 (2022) monitoring data, wetland monitoring associated with UT-3 may be ended. RS will continue
 to plan for monitoring wetlands in 2023 but is requesting termination of this monitoring effort.

Vegetation


- Measurements of the 25 permanent vegetation plots resulted in an average of 539 stems/acre excluding livestakes. All plots met success criteria except plots 1, 5, 11, and 25 (Tables 8-10, Appendix C). Vegetation plots 1, 5, 11, and did not meet success criteria in 2022. However, plots 1 and 5 easily meet success criteria when taking natural recruits into consideration. A temporary transect was done adjacent to plot 11 and met success criteria with 445 stems/acre.
- Plot 11 is in a wetland area adjacent to Gauge 8 that was meeting wetland success for 101 consecutive days, which likely caused the mortality of several less wet-tolerant species. However, RS does not believe this to be a negative, and believe the habitat within the area of plot 11 is appropriate. This is an area RS wishes to discuss with the IRT in the field.
- Both plots 11 and 25 had no mortality between year 2 (2021) and year 3 (2022).
- Year 3 (2022) vegetation measurements also included 5 random sampling transects.
 Measurements of all 30 plots resulted in a sitewide average of 525 planted stems/acre excluding livestakes.

Site Maintenance Report (2022)


Invasive Species Work	Maintenance work
06/27/2022 – 06/28-2022 Parrot Feather, Multiflora rose, Privet, Chinese Bittersweet, Cattail, Johnson Grass, Air Potato, Japanese Knotweed	N/A
09/15/2022 Chinese Bittersweet, Air Potato, Multiflora rose, Parrot feather, Privet, Cattail	


Site Permitting/Monitoring Activity and Reporting History

Activity or Deliverable	Data Collection Complete	Completion or Delivery
RFP No. 16-006991 Issuance Date		September 16, 2016
RFP No. 16-006991 Opening Date		February 15, 2017
Institution Date (NCDMS Contract No. 100014)		May 22, 2017
Mitigation Plan	March 2018	November 2018
Construction Plans		January 10, 2020
404 Permit		May 13, 2019
Site Construction		March 4, 2020
Planting		March 16, 2020
As-built Baseline Monitoring (MY0)	January-March 2020	August 2020
Treatment of Kudzu, Rose, Privet, Honeysuckle, English Ivy		July 27, 2020
Treatment of Kudzu, Princess Tree, Privet, Rose, Japanese Bittersweet, Honeysuckle	-	October 8, 2020
Annual Monitoring (MY1)	November 2020	January 2021
Treatment of Japanese Bittersweet, Parrot Feather, Privet, Multiflora Rose, Cattail, Air Potato, Honeysuckle, Japanese Knotweed, English Ivy		May 24-27, 2022 & September 29 to October 1, 2022
Annual Monitoring (MY2)	October 2021	December 2021
Treatment of Parrot Feather, Multiflora rose, Privet, Chinese Bittersweet, Cattail, Johnson Grass, Air Potato, Japanese Knotweed		June 27-28, 2022
Treatment of Chinese Bittersweet, Air Potato, Multiflora rose, Parrot feather, Privet, Cattail		September 15, 2022
Annual Monitoring (MY3)	October 2022	February 2023



METHOD 1





FINAL MONITORING REPORT (MY3)

WARREN WILSON COLLEGE STREAM MITIGATION SITE

Buncombe County, North Carolina

NCDMS Project ID No. 100019 Full Delivery Contract No. 7188 USACE Action ID No. SAW-2017-01557 NCDWR No. 20171158 RFP No. 16-006991 (Issued: 9/16/16)

French Broad River Basin Cataloging Unit 06010105

Data Collection: January - October 2022 Submission: February 2023

Prepared for:

NORTH CAROLINA DEPARTMENT OF ENVIRONMENTAL QUALITY
DIVISION OF MITIGATION SERVICES
1652 MAIL SERVICE CENTER
RALEIGH, NORTH CAROLINA 27699-1652



Prepared by:



Restoration Systems, LLC 1101 Haynes Street, Suite 211 Raleigh, North Carolina 27604 Contact: Worth Creech 919-755-9490 (phone)

919-755-9492 (fax)

Axiom Environmental, Inc. 218 Snow Avenue Raleigh, North Carolina 27603 Contact: Grant Lewis 919-215-1693 (phone)

TABLE OF CONTENTS								
1.0 PROJEC	T SUMMARY		2					
1.1 Proje	ect Goals & Objectives		2					
1.2 Proje	ect Background		4					
1.3 Project Components and Structure								
1.4 Succe	ess Criteria		5					
	DS							
	toring							
3.0 REFERE	NCES		10					
	APPE	NDICES						
Appendix A	A. Background Map and Tables	Appendix D. St	ream Geomorphology Data					
Figure 1.	Project Location	Tables 11A-I.	Baseline Stream Data Summary					
Table 1.	Project Components and Mitigation	Tables 12A-I.	Baseline Stream Data Summary					
	Units		(Substrate, Bed, Bank, and					
	Project Activity and Reporting History		Hydrologic Containment					
Table 3.	Project Contacts Table		Parameter Distributions)					
Table 4.	Project Attributes Table	Tables 13A-I.	Monitoring Data-Dimensional					
			Morphology Summary					
	B. Visual Assessment Data		(Dimensional Parameters-Cross-					
Figures 2	& 2A-2E. Current Conditions Plan		sections)					

View

Tables 5A-5G. Visual Stream Morphology **Stability Assessment**

Table 6. Vegetation Condition Assessment **Vegetation Plot Photographs**

Appendix C. Vegetation Data

Table 7. Planted Bare Root Woody Vegetation Table 8. Total Stems by Plot and Species

Table 9. Temporary Vegetation Plot Data

Table 10. Planted Vegetation Totals

Tables 14A-I. Monitoring Data-Stream Reach **Data Summary**

Cross-section Plots

Appendix E. Hydrology Data

Tables 15A-C. Channel Evidence Table 16. Verification of Bankfull Events Table 17A-B. Groundwater Hydrology Data **Groundwater Gauge Graphs** Figure E-1. Year 3 (2022) Soil Temperature Data

Appendix F. Preconstruction Wetland Hydrology Data

Figure 3. Preconstruction Gauge Locations Table 18. Preconstruction Groundwater Gauge Data Summary Table 19. Preconstruction vs Postconstruction **Gauge Analysis**

Appendix G. Site Photo Log

1.0 PROJECT SUMMARY

Restoration Systems, LLC (RS) has established the North Carolina Division of Mitigation Services (NCDMS) Warren Wilson College Stream Restoration Site (Site).

1.1 Project Goals & Objectives

Stressors documented in the *French Broad River Basin Restoration Priorities* (RBRP) report (NCEEP 2009) include habitat degradation, poor riparian buffers, nutrient enrichment, channelization, sedimentation, and toxicity primarily attributed to urban and residential runoff and development.

Within the Site, stressors prior to construction could further be attributed to soil instability, increased runoff, and water quality impairments in the receiving watersheds. The project is not located in a Regional or Local Watershed Planning Area; however, the RBRP goals outlined below are addressed by project activities as follows (Site-specific information follows each RBRP goal in parentheses).

- 1. Reduce sediment inputs (based on the sediment model, Site construction eliminates approximately 228 tons per year [tons/year] of sediment that resulted from streambank erosion, excessive fines from channel straightening, channel incision, lack of cobble substrate in disturbed reaches, and a narrow or absent riparian buffer)
- 2. Reduce nutrient inputs (based on the nutrient model, Site construction eliminates 657.4 pounds per year [lbs/yr] of nitrogen and 54.5 lbs/yr of phosphorus due to the installation of marsh treatment areas, removal of preconstruction land uses and livestock, and elimination of fertilizer application)
- 3. Restore riparian buffers (removal of preconstruction land uses and livestock, control of invasive species, and approximately 19.6 acres of woody riparian buffers were planted adjacent to streams)
- 4. Stabilize streambanks (restored stable channels at the historic floodplain elevation, and enhanced oversized and incised channels by raising the stream invert and using grade control/habitat structures)
- 5. Restore and/or protect aquatic habitat (restored aquatic habitat in restoration and enhancement [Level I] reaches by installing grade control/habitat structures, coarsening channel bed materials, removing nutrient inputs, and planting woody riparian buffers to provide shade and organic matter to streams)
- 6. Reduce fecal coliform inputs (based on the nutrient model, Site construction eliminates 31.2 x 10^{11} colonies [col] of fecal coliform per day by removing preconstruction land uses and livestock and treating agricultural runoff with marsh treatment areas)
- 7. Implement agricultural best management practices (BMPs) (the easement is fenced to eliminated livestock from accessing the easement and marsh treatment areas were installed).

Site specific mitigation goals and objectives were developed through the use of North Carolina Stream Assessment Method (NC SAM) analyses of preconstruction and reference stream systems at the Site (NC SFAT 2015) (see Table 1).

Stream/Wetland Targeted Functions, Goals, and Objectives

Stream, Wetlan	la raigeteu runction	s, Goals, and Objectives	
Targeted Functions	Goals	Objectives	Compatibility of Success Criteria
(1) HYDROLOGY			
(2) Flood Flow(Floodplain Access)(3) Streamside AreaAttenuation(4) Floodplain Access(4) Wooded RiparianBuffer	 Attenuate flood flow across the Site. Minimize downstream flooding to the maximum 	 Construct new channel at historic floodplain elevation to restore overbank flows and enhance existing jurisdictional wetlands Plant woody riparian buffer Remove livestock and cease agricultural practices within areas 	 BHR not to exceed 1.2 Document four overbank events in separate monitoring years Livestock excluded from the easement
(4) Microtopography	extent possible. Connect streams to functioning wetland systems.	 protected by the conservation easement. Deep rip floodplain soils to reduce compaction and increase soil surface roughness Protect riparian buffers with a perpetual conservation easement 	 Attain Wetland Hydrology Success Criteria Attain Vegetation Success Criteria Conservation Easement recorded
(3) Stream Stability		Construct channels with proper pattern,	Cross-section measurements
(4) Channel Stability		dimension, longitudinal profile, and	and visual assessments
(4) Sediment	Increase stream stability within	substrate	indicate stable channels and
Transport	stability within the Site so that	Remove livestock and cease agricultural	structuresBHR not to exceed 1.2
(4) Thermoregulation (4) Stream Geomorphology	channels are neither aggrading nor degrading.	practices within areas protected by the conservation easement. Construct stable channels with gravel substrate Stabilize streambanks Plant woody riparian buffer	 ER of 1.4 or greater < 10% change in BHR and ER Livestock excluded from the easement Attain Vegetation Success Criteria
(1) WATER QUALITY			
(2) Streamside Area Vegetation (3) Upland Pollutant Filtration (2) Indicators of Stressors	Remove direct nutrient and pollutant inputs from the Site and reduce contributions to downstream waters.	 Remove livestock and reduce agricultural land/inputs Install marsh treatment areas Plant woody riparian buffer Enhance jurisdictional wetlands adjacent to Site streams Provide surface roughness and reduce compaction through deep ripping/plowing Restore overbank flooding by constructing channels at historic floodplain elevation 	 Livestock excluded from the easement Attain Vegetation Success Criteria

Stream/Wetland Targeted Functions, Goals, and Objectives (Continued)

(2) In-stream Habitat (3) Substrate (3) Stream Stability (3) In-Stream Habitat (2) Stream-side Habitat (3) Stream-side Habitat (3) Stream-side Habitat • Construct stable channels with gravel substrate • Plant woody riparian buffer to provide organic matter and shade • Construct new channel at historic floodplain elevation to restore overbank flows • Improve instream and structures. • Protect riparian buffers with a perpetual conservation easement • Construct stable channels with gravel substrate • Cross-section measurements indicate stable channels and structures. • Attain Vegetation Success Criteria	(1) HABITAT			
to Site streams Remove invasive plant species Add large woody debris to Site channels	(2) In-stream Habitat (3) Substrate (3) Stream Stability (3) In-Stream Habitat (2) Stream-side Habitat (3) Stream-side Habitat	instream and stream-side	 substrate Plant woody riparian buffer to provide organic matter and shade Construct new channel at historic floodplain elevation to restore overbank flows Protect riparian buffers with a perpetual conservation easement Enhance jurisdictional wetlands adjacent to Site streams Remove invasive plant species 	 and visual assessments indicate stable channels and structures. Attain Vegetation Success Criteria Conservation Easement

1.2 Project Background

The Warren Wilson College Stream Mitigation Site (hereafter referred to as the "Site") encompasses a 25.3-acre easement along cold-water, unnamed tributaries (UTs) to the Swannanoa River. Warren Wilson College occupies approximately 1200 acres, and the Site is part of an actively managed farm and forest system on the Warren Wilson College property that includes livestock management areas, pastureland, agricultural row crops, and a sustainably managed forest. The Site is located approximately 2 miles west of Swannanoa and 5 miles east of Asheville in Buncombe County, North Carolina (Figure 1, Appendix A).

Prior to construction, the Site consisted of agricultural and managed forest land accessible to livestock. Site streams were part of an actively managed farm and forest system that included livestock, pastureland, agricultural row crops, and sustainable forest management. Streams were eroded vertically and laterally, received extensive sediment and nutrient inputs, and were dredged and straightened and/or rerouted to the floodplain edge. Preconstruction Site conditions resulted in degraded water quality, a loss of aquatic habitat, reduced nutrient and sediment retention, and unstable channel characteristics (loss of horizontal flow vectors that maintain pools and an increase in erosive forces to channel bed and banks). Site restoration activities restored riffle-pool morphology, aided in energy dissipation, increased aquatic habitat, stabilized channel banks, and greatly reduced sediment loss from channel banks.

Preconstruction Groundwater Gauges:

Preconstruction groundwater gauges were installed along UT-3 upper (Clingman's) upon the request of IRT members to model pre-construction wetland characteristics. Data was collected for 2018 and the beginning of 2019 within gauges nested in transects perpendicular to the existing channel. In addition, a crest gauge along the existing incised reach was installed to measure overbank events.

Results of preconstruction gauge data, included in Table 18 (Appendix F), indicate that gauges near the incised stream showed reduced hydroperiod as compared to those further from the channel. 2018 exhibited normal rainfall patterns, and one gauge appeared to meet jurisdictional criteria based on groundwater level being within 12 inches of the surface for 12.5% of the growing season (26 days, based

on the NRCS growing season of April 2 to November 1). 2019 exhibited wetter than average rainfall patterns, and six gauges appeared to meet the same jurisdictional criteria. In addition, the crest gauge installed on UT-3 showed no overbank events during 2018 and one during 2019 after a 4.56-inch rainfall.

1.3 Project Components and Structure

Proposed Site restoration activities generated 10,050.933 Stream Mitigation Units (SMUs) as the result of the following.

- Restored 9220 linear feet of perennial stream channel by constructing stable streams in the historic floodplain location and elevation.
- Enhanced (Level I) 62 linear feet of stream by installing in-stream structures, providing proper channel dimension and appropriate floodplain width, reducing shear on eroding banks, controlling invasive species within the riparian area, and planting with native riparian vegetation.
- Enhanced (Level II) 1974 linear feet of stream channel by removing current land use practices, controlling invasive species within the riparian area, and planting native vegetation.

Additional activities that occurred at the Site included the following.

- Installation of four marsh treatment areas to treat stormwater runoff before it enters Site streams.
- Established a minimum 30-foot-wide woody riparian buffer adjacent to Site streams,
- Fenced the conservation easement boundaries in areas used for livestock management.
- Protected the Site in perpetuity with a conservation easement.

During the initial DMS as-built review, it was discovered that several culvert pipes extend into the recorded conservation easement. Once the encroachments were located and documented via GPS, easement modifications were initiated to remove any crossing materials from the conservation easement. Creditable stream removed from the easement were also removed from mitigation assets. A mitigation plan addendum for the reduction in project credit was submitted to the IRT as part of the MYO/ As-Built Baseline Monitoring Report review and was approved by the IRT via email on October 5, 2020.

Site design was completed on January 10, 2020. Construction started on September 1, 2019 and ended within a final walkthrough on March 4, 2020. Site planting was completed on March 16, 2020. Completed project activities, reporting history, completion dates, project contacts, and background information are summarized in Tables 1-4 (Appendix A).

1.4 Success Criteria

Project success criteria were established in the IRT-approved detailed mitigation plan and in accordance with the October 24, 2016 NC Interagency Review Team *Wilmington District Stream and Wetland Compensatory Mitigation Update*. Monitoring and success criteria relate to project goals and objectives. From a mitigation perspective, several of the goals and objectives are assumed to be functionally elevated by restoration activities without direct measurement. Other goals and objectives will be considered successful upon achieving success criteria. The following table summarizes Site success criteria.

Success Criteria

Streams

- All streams must maintain an Ordinary High-Water Mark (OHWM), per RGL 05-05.
- Continuous surface flow must be documented each year for at least 30 consecutive days.
- Bank height ratio (BHR) cannot exceed 1.2 at any measured cross-section.
- Entrenchment ratio (ER) must be no less than 2.2 for E- and C-type channels at any measured riffle cross-section.
- BHR and ER at any measure riffle cross-section should not change by more than 10% from baseline condition during any given monitoring period.
- The stream project shall remain stable and all other performance standards shall be met through four separate bankfull events, occurring in separate years, during the monitoring years 1-7.

Wetland Hydrology

- Groundwater gauge data will be used to observe fluctuations in groundwater hydrology pre- and
 postconstruction as the result of overbank events; however, no wetland mitigation credit is being
 acquired and there are no wetland hydrology success criteria proposed at this time.
- Jurisdictional wetland adjacent to UT-3 will demonstrate a 10 to 20% increase in wetland hydrology as compared to pre-construction hydrology, under similar climactic conditions.

Vegetation

- Within planted portions of the site, a minimum of 320 stems per acre must be present at year 3; a minimum of 260 stems per acre must be present at year 5; and a minimum of 210 stems per acre must be present at year 7.
- Areas of dense river cane (canebrakes) are a natural niche habitat within the Swannanoa River floodplain that contribute native habitat for endangered species. River cane may outcompete woody seedlings during the initial establishment of vegetation. Within the Swannanoa floodplain (UT-6, UT-7, and UT-8), the presence of canebrakes may supersede the vegetative success criteria for planted stems per acre.
- Trees must average 6 feet in height at year 5, and 8 feet in height at year 7 in each plot.
- Planted and volunteer stems are counted, provided they are included in the approved planting list
 for the site; natural recruits not on the planting list may be considered by the IRT on a case-by-case
 basis.

2.0 METHODS

Monitoring requirements and success criteria outlined in this plan follow the October 24, 2016 NC Interagency Review Team *Wilmington District Stream and Wetland Compensatory Mitigation Update*. Monitoring will be conducted by Axiom Environmental, Inc. Annual monitoring reports of the data collected will be submitted to the NCDMS by Restoration Systems no later than December 1 of each monitoring year data is collected. The monitoring schedule is summarized in the following table.

Monitoring Schedule

Resource	Year 1	Year 2	Year 3	Year 4	Year 5	Year 6	Year 7
Streams	Х	Х	Х		Х		Х
Wetlands	Х	Х	Х	Х	Х	Х	Х
Vegetation	Х	Х	Х		Х		Х
Visual Assessment	Х	Х	Х	Х	Х	Х	Х
Report Submittal	Х	Х	Х	Х	Х	Х	Х

2.1 Monitoring

The monitoring parameters were established in the IRT-approved detailed mitigation plan and are summarized in the following table.

Monitoring Summary

Stream Parameters								
Parameter	Method	Schedule/Frequency	Number/Extent	Data Collected/Reported				
Stream Profile	Full longitudinal survey	As-built (unless otherwise required)	All restored stream channels	Graphic and tabular data.				
Stream Dimension	Cross-sections	Years 1, 2, 3, 5, and 7	Total of 50 cross-sections on restored channels	Graphic and tabular data.				
Channel Stability	Visual Assessments	ual Assessments Yearly All restored stream channels		Areas of concern to be depicted on a plan view figure with a written assessment and photograph of the area included in the report.				
Additional Cross- Sections Yearly		Only if instability is documented during monitoring	Graphic and tabular data.					
Stream Hydrology	Continuous monitoring surface water gauges and trail cameras	Continuous recording through monitoring period	Total of 3 surface water gauges (UT3, UT6, & UT8)	Surface water data for each monitoring period				
Bankfull Events	Continuous monitoring surface water gauges and Continuous recording through monitoring period Total of 3 surface gauges (UT3, UT6,		Total of 3 surface water gauges (UT3, UT6, & UT8)	Surface water data for each monitoring period				
Visual/Physical Continuous through monitoring period		All restored stream channels	Visual evidence, photo documentation, and/or rain data.					
	Wetland Parameters							
Parameter	Method	Schedule/Frequency	Number/Extent	Data Collected/Reported				
Wetland Rehabilitation	Groundwater gauges	Preconstruction, Asbuilt, Years 1-7	10 gauges in wetlands adjacent to UT1+, UT3*+, & UT6+	Graphic and tabular data.				

Monitoring Summary (Continued)

Vegetation Parameters								
Parameter	Method	Schedule/ Frequency	Number/Extent	Data Collected/Reported				
Vegetation establishment and vigor	Permanent vegetation plots 0.0247 acre (100 square meters) in size; CVS-EEP Protocol for Recording Vegetation, Version 4.2 (Lee et al. 2008)	As-built, Years 1, 2, 3, 5, and 7	25 plots spread across the Site	Species, height, planted vs. volunteer, stems/acre				
and vigor	Annual random vegetation plots, 0.0247 acre (100 square meters) in size	As-built, Years 1, 2, 3, 5, and 7	Number of randomly selected plots to be determined each year. as needed	Species				

^{*} Seven groundwater monitoring gauges were installed in jurisdictional wetland areas adjacent to UT-3 to take measurements before and after hydrological modifications were performed at the Site. The preconstruction condition of the upper reach of UT-3 was an incised Eg-type channel with bank-height-ratios ranging from 1.8-2.4. The majority of UT-3 upper has been restored (priority I) with construction of channels at the historic floodplain elevation to restore overbank flows to adjacent wetlands. A stream flow gauge and trail camera were installed on UT-3 upper to verify overbank events. Groundwater gauge data will be used to observe fluctuations in groundwater hydrology pre- and post-construction as the result of overbank events; however, no wetland mitigation credit is being acquired and there are no wetland hydrology success criteria proposed at this time.

Stream Summary

All streams are functioning as designed, and no stream areas of concern were observed during year 3 (2022) monitoring. Stream morphology data is available in Appendix D.

All three flow gauges failed during the 2022 season, and data was not able to be recovered. The flow gauges were replaced with Onset U-20 gauges on December 2, 2022, and no additional malfunctions are expected. Visual inspection shows strong evidence of channel formation and water flow was observed in all Site streams during year 3 (2022) (Tables 15A-C, Appendix E).

[†] Three groundwater gauges were installed, one adjacent to UT-1, one adjacent to UT-3 lower, and one adjacent to UT-6, in order to show no net loss in function, due to project activities, in existing wetlands along these tributaries. In order to monitor an area of potential wetland creation associated with stream channel restoration, two additional gauges (gauges 4 and 5) were installed along the right bank of UT-3 upper. This area was previously determined non-jurisdictional.

Wetland Summary

Summary of Monitoring Period/Hydrology Success Criteria by Year

Year	Soil Temperatures/Date Bud Burst Documented	Monitoring Period Used for Determining Success	10 Percent of Monitoring Period
2020 (Year 1)	March 16, 2020*	March 16-November 1 (231 days)	23 days
2021 (Year 2)	April 6, 2021**	April 6-November 12 (221 days)	22 days
2022 (Year 3)	April 2, 2022^	April 2-November 1 (215 days)	22 days

^{*}Based on observed/documented bud burst and data collected from a soil temperature data logger located on the Site.

** During year 1, the growing season was determined based the Soil Survey of Buncombe County (April 2 – November 1) and onsite bud burst documentation. However, based on a 2021 discussion with the IRT, concern arose that the Soil Survey growing season does not accurately represent the current growing season end date. As a result, the growing season methodology was changed to use the most current WETS (USDA 2021) data to determine the growing season end date. After year 2 review, the IRT requested that providers use the growing season methodology from the approved mitigation plan.

^Soil temperature of 44.27°F was documented on March 1 and remained above 41°F thereafter (Appendix E). However, to be consistent with the approved mitigation plan, the Buncombe County soil survey start/end dates are used for year 3 (2022).

Overall, based on groundwater gauge data, wetland hydrology has improved from preconstruction and year 1 (2020) conditions. All gauges were saturated/inundated for greater than 10 percent of the year 3 (2022) growing season, with gauges 2-7 and 9 were inundated for approximately 90% of the growing season (Table 17A-B, Appendix E).

Vegetation Summary

During quantitative vegetation sampling, 25 sample plots (10-meter by 10-meter) were installed within the Site as per guidelines established in *CVS-EEP Protocol for Recording Vegetation, Version 4.2* (Lee et al. 2008). Year 3 (2022) vegetation measurements occurred in July 2022 and included 5 additional random sample plots (one 25-meter by 4-meter and four 50-meter by 2-meter). Measurements of all 30 plots resulted in an average of 525 planted stems/acre excluding livestakes. Additionally, all individual plots met success criteria except plots 1, 5, 11, 25, and random plot 4 (Tables 8-10, Appendix C). Vegetation plots 1, 5, 11, and did not meet success criteria in 2022. However, plots 1 and 5 easily meet success criteria when taking natural recruits into consideration. A temporary transect was done adjacent to plot 11 and met success criteria with 445 stems/acre. Plot 11 is in a wetland area adjacent to Gauge 8 that was meeting wetland success for 101 consecutive days, which likely caused the mortality of several less wettolerant species. However, RS does not believe this to be a negative, and believe the habitat within the area of plot 11 is appropriate. This is an area RS wishes to discuss with the IRT in the field. Both plots 11 and 25 had no mortality between year 2 (2021) and year 3 (2022).

During year (2022) monitoring, parrot feather (*Myriophyllum aquaticum*) was observed spread throughout the upper reach of UT-3 (Figure 2A, Appendix B). Additionally, multiflora rose (*Rosa multiflora*), Chinese privet (*Ligustrum sinense*), Chinese bittersweet (*Celastrus orbiculatus*), cattail (*Typha spp.*), Johnson grass (*Sorghum halepense*), air potato (*Dioscorea bulbifera*), and Japanese knotweed (*Reynoutria japonica*) were observed elsewhere throughout the Site but were especially dense along UT-8 (Figure 2D, Appendix B). All invasives were treated on June 27-28 and September 15, 2022, and will continue to be treated as necessary.

3.0 REFERENCES

- Griffith, G.E., J.M. Omernik, J.A. Comstock, M.P. Schafale, W.H. McNab, D.R. Lenat, T.F. MacPherson, J.B. Glover, and V.B. Shelbourne. 2002. Ecoregions of North Carolina and South Carolina. U.S. Geological Survey, Reston, Virginia.
- Lee, M.T., R.K. Peet, S.D. Roberts, and T.R. Wentworth. 2008. CVS-EEP Protocol for Recording Vegetation. Version 4.2. North Carolina Department of Environment and Natural Resources, Ecosystem Enhancement Program. Raleigh, North Carolina.
- North Carolina Division of Mitigation Services (NCDMS). 2014. Stream and Wetland Mitigation Monitoring Guidelines. North Carolina Department of Environmental Quality, Raleigh, North Carolina.
- North Carolina Ecosystem Enhancement Program (NCEEP), 2009. French Broad River Basin Restoration Priorities 2009 (online). Available at:

 https://ncdenr.s3.amazonaws.com/s3fspublic/PublicFolder/Work%20With/Watershed%20Planners/French_Broad_RBRP_15july09.pdf [June 1, 2016]. North Carolina Department of Environment and Natural Resources, Raleigh.
- North Carolina Stream Functional Assessment Team. (NC SFAT 2015). N.C. Stream Assessment Method (NC SAM) User Manual. Version 2.1.
- Schafale, M.P. and A.S. Weakley. 1990. Classification of the Natural Communities of North Carolina: Third Approximation. North Carolina Natural Heritage Program, Division of Parks and Recreation, North Carolina Department of Environment, Health, and Natural Resources. Raleigh, North Carolina.
- Simon A, Hupp CR. 1986. Geomorphic and Vegetative Recovery Processes Along Modified Tennessee Streams: An Interdisciplinary Approach to Disturbed Fluvial Systems. Forest Hydrology and Watershed Management. IAHS-AISH Publ.167.
- United States Department of Agriculture (USDA). 2016. Web Soil Survey (online). Available: http://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx [August 2016].
- United States Department of Agriculture (USDA), 2009. Soil Survey for Buncombe County North Carolina.

 US Department of Agriculture. Available at:

 http://www.nrcs.usda.gov/Internet/FSE_MANUSCRIPTS/north_carolina/buncombeNC2009/Buncombe NC.pdf [June 7, 2016].
- United States Department of Agriculture (USDA). 2021. Natural Resources Conservation Service National Weather and Climate Center. AgACIS Climate Data. Asheville WETS Station (online). Available: http://agacis.rcc-acis.org

Appendix A – Background Map and Tables

Figure 1. Project Location

Table 1. Mitigation Assets and Components

Table 2. Project Activity and Reporting History

Table 3. Project Contacts Table

Table 4. Project Attributes Table




Table 1. Mitigation Assets and Components Warren Wilson College Stream Mitigation Site

Project Segment	Stream Stationing/ Wetland Type	Existing Footage/ Acreage	Mitigation Plan Footage/ Acreage	Restoration Level	Mitigation Ratio	Restoration Footage/ Acreage^	Calculated Credit^	Comment
UT 1A	0+09-4+92	189	483	Restoration (Priority I)	1:1	483	483.000	
UT 1B	1+09-1+22	13	13	Enhancement (Level II)	2.5:1	12	4.800	
UT 1C	1+22-7+06	554	584- 20=564*	Restoration (Priority I)	1:1	584-42=542*	542.000	42 If is outside of the easement and therefore is non-credit-generating.
UT 3A	0+05-0+50	45	45	Enhancement (Level II)	2.5:1	50	20.000	
UT 3B	0+50-21+66	1901	2116-20- 5=2091*	Restoration (Priority I/II)	1:1	2116-52- 5=2059*	2059.000	52 If is outside of the easement and 5 If is located at a foot crossing within the easement; therefore, are non-credit-generating.
UT 3C	21+66-22+28	62	62	Enhancement (Level I)	1.5:1	62	41.333	
UT 3D	0+00-5+00	428	500	Restoration (Priority I)	1:1	500	500.000	
UT 3E	5+00-8+34	334	334	Enhancement (Level II)	2.5:1	334	133.600	
UT 3F	8+34-9+60	91	126	Restoration (Priority I)	1:1	126	126.000	
UT 3G	9+60-16+81	721	721- 21=700*	Enhancement (Level II)	2.5:1	721-21=700*	280.000	21 If is outside of the easement and therefore is non-credit-generating.
UT 4A	0+00-2+33	70	233	Restoration (Priority I)	1:1	187	187.000	
UT 4B	2+33-4+75	242	242- 20=222*	Enhancement (Level II)	2.5:1	288-107=181*	72.400	107 If is outside of the easement and therefore is non-credit-generating.
UT 5A	0+00-0+48	48	48	Enhancement (Level II)	2.5:1	47	18.800	
UT 5B	0+48-11+58	719	1110- 31=1079*	Restoration (Priority I)	1:1	1117- 38=1079*	1079.000	38 If is outside of the easement and therefore is non-credit-generating.
UT 6A	0+08-1+63	155	155	Enhancement (Level II)	2.5:1	155	62.000	
UT 6B	2+16-16+48	713	1432- 20=1412*	Restoration (Priority I/II)	1:1	1432- 44=1388*	1388.000	44 If is outside of the easement and therefore is non-credit-generating.
UT 6C	16+48-21+43	495	495	Enhancement (Level II)	2.5:1	495	198.000	
UT 7A	0+00-19+85	2426	1985-36-20- 45=1884*	Restoration (Priority I)	1:1	1940-39- 54=1847*	1847.000	93 If is outside of the easement and therefore is non-credit-generating.
UT 8A	0+18-10+65	957	1047- 38=1009*	Restoration (Priority I/II)	1:1	1047- 38=1009*	1009.000	38 If is outside of the easement and therefore is non-credit-generating.

^{*}Areas located outside of the easement or at a foot path crossing within the easement and therefore are non-credit generating.

^Several credited stream segments were reduced in length during as-built due to a modification to remove all crossing materials from the easement.

Table 1 (continued). Project Credits
Warren Wilson College Stream Mitigation Site

Dostovation Lovel	Stream		Riparian Wetland Non-Rip		Coastal		
Restoration Level	Warm	Cool	Cold	Riverine	Non-Riverine	Wetland	Marsh
Restoration			9220.000				
Re-establishment							
Rehabilitation							
Enhancement							
Enhancement I			41.333				
Enhancement II			789.600				
Creation							
Preservation							
TOTALS			10,050.933				

Table 2. Project Activity and Reporting History Warren Wilson College Stream Mitigation Site

Activity or Deliverable	Data Collection Complete	Completion or Delivery
Institution Date (NCDMS Contract No. 100014)		May 22, 2017
Mitigation Plan	March 2018	November 2018
Construction Plans		January 10, 2020
404 Permit		May 13, 2019
Site Construction		March 4, 2020
Planting		March 16, 2020
As-built Baseline Monitoring (MY0)	January-March 2020	August 2020
Treatment of Kudzu, Rose, Privet, Honeysuckle, English Ivy		July 27, 2020
Treatment of Kudzu, Princess Tree, Privet, Rose, Japanese Bittersweet, Honeysuckle		October 8, 2020
Annual Monitoring (MY1)	November 2020	January 2021
Treatment of Japanese Bittersweet, Parrot Feather,		May 24-27, 2022 &
Privet, Multiflora Rose, Cattail, Air Potato, Honeysuckle,		September 29 to October 1,
Japanese Knotweed, English Ivy		2022
Annual Monitoring (MY2)	October 2021	December 2021
Treatment of Parrot Feather, Multiflora rose, Privet, Chinese Bittersweet, Cattail, Johnson Grass, Air Potato, Japanese Knotweed		June 27-28, 2022
Treatment of Chinese Bittersweet, Air Potato, Multiflora rose, Parrot feather, Privet, Cattail		September 15, 2022
Annual Monitoring (MY3)	October 2022	February 2023

Table 3. Project Contacts Table

Warren Wilson College Stream Mitigation Site


Full Delivery Provider	As-built Monitoring Provider
Restoration Systems	Axiom Environmental, Inc.
1101 Haynes Street, Suite 211	218 Snow Avenue
Raleigh, North Carolina 27604	Raleigh, NC 27603
Worth Creech	Grant Lewis
919-755-9490	919-215-1693
Designer	
Anchor QEA of North Carolina, PLLC	
231 Haywood Street	
Asheville, NC 28801	
Sara Stavinoha	
828-771-0279	


Table 4. Project Attribute Table Warren Wilson Stream Mitigation Site


		Project Inf	ormation							
Project Name			Warren Wil	son Stream Mitiga	ation Site					
Project County			Buncomb	e County, North C	Carolina					
Project Area (acres)	25.3									
Project Coordinates (latitude & latitude)	35.609817ºN, 82.443540ºW									
Planted Area (acres) 19.64										
	Proj	ect Watershed Su	ummary Informat	ion						
Physiographic Province				Blue Ridge						
Project River Basin				French Broad						
USGS HUC for Project (14-digit)			0	6010105070030						
NCDWR Sub-basin for Project				04-03-02						
Project Drainage Area			49.9 to 822.3 ac	res (0.08 to 1.28	square miles)					
% of Project Drainage Area that is Impervious				<5%						
CGIA Land Use Classification	Cultivated, Manage	ed Herbaceous Ve	egetation, Unman	aged Herbaceous	Vegetation, Hard	wood Swamp, Oa	k/Gum/Cypress			
		Reach Summai	y Information							
Parameters	UT1	UT 3	UT4	UT 5	UT6	UT 7	UT 8			
Length of reach (linear feet)	756	3582	312	769	1363	2425	957			
Valley Classification & Confinement		Mo	derately confined	to somewhat un	confined (UT-3 &	UT-5)				
Drainage Area (acres and square miles)	171.3 ac.	822.3 ac.	153.9 ac.	98.3 ac.	49.9 ac.	141.0 ac.	64.4 ac.			
,	(0.27 sq. mi.)	(1.28 sq. mi.)	(0.24 sq. mi.)	(0.15 sq. mi.)	(0.08 sq. mi.)	(0.22 sq. mi.)	(0.10 sq. mi.)			
Perennial, Intermittent, Ephemeral	Perennial	Perennial	Perennial	Perennial	Intermittent/ Perennial	Perennial	Perennial			
NCDWR Water Quality Classification				С						
Existing Morphological Description (Rosgen 1996)	Cg4	Eg4	G4	G3	G3	Gb4	Eg4			
Proposed Stream Classification (Rosgen 1996)	Cb4	Ce4	C4	Ce4	Ce4	Gb4	C4			
Existing Evolutionary Stage (Simon and Hupp 1986)		11/111	Channelized/Deg	raded)					
FEMA Classification	NA	Zone AE	NA	NA	NA	NA	NA			
Thermal Regime				Cold						

Appendix B – Visual Assessment Data

Figures 2 & 2A-2E. Current Conditions Plan View Tables 5A-5G. Visual Stream Morphology Stability Assessment Table 6. Vegetation Condition Assessment Vegetation Plot Photographs














Table 5A <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-1

Assessed Length 756
Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	<u>Aggradation</u> - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		2. <u>Degradation</u> - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	21	21			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	21	21			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	21	21			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	21	21			100%			
		2. Thalweg centering at downstream of meander (Glide)	21	21			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does NOT include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	22	22			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	22	22			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	22	22			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	22	22			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio <u>></u> 1.6 Rootwads/logs providing some cover at base-flow.	22	22			100%			

Table 5B <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-3

Assessed Length 3582 Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Stabilizing Woody	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	Aggradation - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		Degradation - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	44	44			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	45	45			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	45	45			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	45	45			100%			
		2. Thalweg centering at downstream of meander (Glide)	45	45			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	46	46			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	46	46			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	46	46			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	46	46			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio ≥ 1.6 Rootwads/logs providing some cover at base-flow.	46	46			100%			

Table 5C <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-4

Assessed Length 312 Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Stabilizing Woody	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	<u>Aggradation</u> - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		2. <u>Degradation</u> - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	6	6			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	6	6			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	6	6			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	6	6			100%			
		2. Thalweg centering at downstream of meander (Glide)	6	6			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does NOT include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	7	7			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	7	7			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	7	7			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	7	7			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio ≥ 1.6 Rootwads/logs providing some cover at base-flow.	7	7			100%			

Table 5D <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-5

Assessed Length 769
Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Number with Stabilizing Woody Vegetation	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	Aggradation - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		Degradation - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	27	27			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	27	27			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	27	27			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	27	27			100%			
		2. Thalweg centering at downstream of meander (Glide)	27	27			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	27	27			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	27	27			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	27	27			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	27	27			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio ≥ 1.6 Rootwads/logs providing some cover at base-flow.	27	27			100%			

Table 5E <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-6

Assessed Length 1363 Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Stabilizing Woody	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	Aggradation - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		Degradation - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	46	46			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	46	46			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	46	46			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	46	46			100%			
		2. Thalweg centering at downstream of meander (Glide)	46	46			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	47	47			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	47	47			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	47	47			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	47	47			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio ≥ 1.6 Rootwads/logs providing some cover at base-flow.	47	47			100%			

Table 5F <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-7

Assessed Length 2425 Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Stabilizing Woody	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	Aggradation - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		Degradation - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	42	42			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	43	43			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	43	43			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	43	43			100%			
		2. Thalweg centering at downstream of meander (Glide)	43	43			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	45	45			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	45	45			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	45	45			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	45	45			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio ≥ 1.6 Rootwads/logs providing some cover at base-flow.	45	45			100%			

Table 5G <u>Visual Stream Morphology Stability Assessment</u>

Reach ID Warren Wilson College UT-8

Assessed Length 957
Assessment Date 20-Oct-22

Major Channel Category	Channel Sub-Category	Metric	Number Stable, Performing as Intended	Total Number in As-built	Number of Unstable Segments	Amount of Unstable Footage	% Stable, Performing as Intended	Stabilizing Woody	Footage with Stabilizing Woody Vegetation	Adjusted % for Stabilizing Woody Vegetation
1. Bed	Vertical Stability (Riffle and Run units)	<u>Aggradation</u> - Bar formation/growth sufficient to significantly deflect flow laterally (not to include point bars)			0	0	100%			
		Degradation - Evidence of downcutting			0	0	100%			
	2. Riffle Condition	Texture/Substrate - Riffle maintains coarser substrate	30	30			100%			
	3. Meander Pool Condition	1. <u>Depth</u> Sufficient (Max Pool Depth : Mean Bankfull Depth ≥ 1.6)	30	30			100%			
		Length appropriate (>30% of centerline distance between tail of upstream riffle and head of downstrem riffle)	30	30			100%			
	4.Thalweg Position	Thalweg centering at upstream of meander bend (Run)	30	30			100%			
		2. Thalweg centering at downstream of meander (Glide)	30	30			100%			
2. Bank	1. Scoured/Eroding	Bank lacking vegetative cover resulting simply from poor growth and/or scour and erosion			0	0	100%			100%
	2. Undercut	Banks undercut/overhanging to the extent that mass wasting appears likely. Does <u>NOT</u> include undercuts that are modest, appear sustainable and are providing habitat.			0	0	100%			100%
	3. Mass Wasting	Bank slumping, calving, or collapse			0	0	100%			100%
				Totals	0	0	100%	0	0	100%
3. Engineered Structures	1. Overall Integrity	Structures physically intact with no dislodged boulders or logs.	31	31			100%			
	2. Grade Control	Grade control structures exhibiting maintenance of grade across the sill.	31	31			100%			
	2a. Piping	Structures lacking any substantial flow underneath sills or arms.	31	31			100%			
	3. Bank Protection	Bank erosion within the structures extent of influence does <u>not</u> exceed 15%. (See guidance for this table in EEP monitoring guidance document)	31	31			100%			
	4. Habitat	Pool forming structures maintaining ~ Max Pool Depth : Mean Bankfull Depth ratio ≥ 1.6 Rootwads/logs providing some cover at base-flow.	31	31			100%			

Table 6

Vegetation Condition Assessment

Warren Wilson College

Assessment Date Planted Acreage¹

20-Oct-22 19 64

	10.0 1					
Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Planted Acreage
1. Bare Areas	None	0.1 acres	none	0	0.00	0.0%
2. Low Stem Density Areas	None	0.1 acres	none	0	0.00	0.0%
2B. Low Planted Stem Density Areas	None	0.1 acres	none	0	0.00	0.0%
			Total	0	0.00	0.0%
3. Areas of Poor Growth Rates or Vigor	None	0.25 acres	none	0	0.00	0.0%
		Cur	nulative Total	0	0.00	0.0%


Easement Acreage²

25.3

Vegetation Category	Definitions	Mapping Threshold	CCPV Depiction	Number of Polygons	Combined Acreage	% of Easement Acreage
4. Invasive Areas of Concern ⁴	None	1000 SF	yellow hatching	2	5.01	19.8%
5. Easement Encroachment Areas ³	None	none	none	0	0.00	0.0%

- 1 = Enter the planted acreage within the easement. This number is calculated as the easement acreage minus any existing mature tree stands that were not subject to supplemental planting of the understory, the channel acreage, crossings or any other elements not directly planted as part of the project effort.
- 2 = The acreage within the easement boundaries.
- 3 = Encroachment may occur within or outside of planted areas and will therefore be calculated against the overall easement acreage. In the event a polygon is cataloged into items 1, 2 or 3 in the table and is the result of encroachment, the associated acreage should be tallied in the relevant item (i.e., item 1,2 or 3) as well as a parallel tally in item 5.
- 4 = Invasives may occur in or out of planted areas, but still within the easement and will therefore be calculated against the overall easement acreage. Invasives of concern/interest are listed below. The list of high concern species are those with the potential to directly outcompete native, young, woody stems in the short-term (e.g. monitoring period or shortly thereafter) or affect the community structure for existing, more established tree/shrub stands over timeframes that are slightly longer (e.g. 1-2 decades). The low/moderate concern group are those species that generally do not have this capacity over the timeframes discussed and therefore are not expected to be mapped with regularity, but can be mapped, if in the judgement of the observer their coverage, density or distribution is suppressing the viability, density, or growth of planted woody stems. Decisions as to whether remediation will be needed are based on the integration of risk factors by DMS such as species present, their coverage, distribution relative to native biomass, and the practicality of treatment. For example, even modest amounts of Kudzu or Japanese Knotweed early in the projects history will warrant control, but potentially large coverages of Microstegium in the herb layer will not likley trigger control because of the limited capacities to impact tree/shrub layers with the timeframes discussed and the potential impacts of treating extensive amounts of ground cover. Those species with the "watch list" designator in gray shade are of interest as well, but have yet to be observed across the state with any frequency. Those in *red italics* are of particular interest given their extreme risk/threat level for mapping as points where <u>isolated</u> specimens are found, particularly ealry in a projects monitoring history. However, areas of discreet, dense patches will of course be mapped as polygons. The symbology scheme below was one that was found to be helpful for symbolzing invasives polygons, particulalry for situations where the conditio

Warren Wilson College Site MY3 (2022) Vegetation Monitoring Photographs (taken June 2022)



Alliance Headwaters Site MY3 (2022) Vegetation Monitoring Photographs (taken June 2022)



Warren Wilson College Site MY3 (2022) Vegetation Monitoring Photographs (taken June 2022 except Plot 24, taken November 2022)



Warren Wilson College Site MY3 (2022) Vegetation Monitoring Photographs (taken June 2022)



Appendix C – Vegetation Data

Table 7. Planted Bare Root Woody Vegetation

Table 8. Total Stems by Plot and Species

Table 9. Temporary Vegetation Plot Data

Table 10. Planted Vegetation Totals

Table 7. Planted Bare Root Woody Vegetation Warren Wilson College Stream Mitigation Site

Species – Scientific Name	Species – Common Name	Wetland Indicator Status	Total*
		Acres	19.64
Cephalanthus occidentalis	Buttonbush	OBL	50
Diospyros virginiana	Common persimmon	FAC	500
Liriodendron tulipifera	Tulip poplar	FACU	900
Betula nigra	River birch	FACW	2800
Fraxinus pennsylvanica	Green ash	FACW	3800
Cornus amomum	Silky dogwood	FACW	3900
Quercus alba	White oak	FACU	4200
Quercus nigra	Water oak	FAC	4200
Platanus occidentalis	American Sycamore	FACW	5600
		TOTALS	25,950*

^{**}Approximately 5000 live stakes of willow (*Salix* spp.), elderberry (*Sambucus canadensis*), silky dogwood (*Cornus amomum*), and ninebark (*Physocarpus opulifolius*) were planted, but are not included in this table.

Table 8. Total Stems by Plot and Species Project Code 20004. Project Name: WWC

															(Current	Plot D	ata (MY	3 2022)												
			20	004-01-0	0001	200	04-01-	0002	200	04-01-0	003	200	04-01-0	0004	200	04-01-0	0005	200	04-01-0	006	200	04-01-	0007	200	04-01-	8000	200	004-01-0	0009	2000	04-01-00	010
Scientific Name	Common Name	Species Type	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	T
Acer rubrum	red maple	Tree			5																											
Betula nigra	river birch	Tree	1	1	1				11	11	11	12	12	12				2	2	2	5	5	5				2	2	<u>'</u> 2	. 2	2	- 2
Carya	hickory	Tree																														
Celtis occidentalis	common hackberry	Tree				1	1	. 1	1																							
Cephalanthus occidentalis	common buttonbush	Shrub																														
Cornus amomum	silky dogwood	Shrub				7	7	' 8	12	12	13				3	3	5				6	6	6	1	1	1 1	. 3	3	3	, 3	3	3,
Diospyros virginiana	common persimmon	Tree				1	1	. 1	L												3	3	3				2	2 2	<u>.</u> 2	. 1	1	1
Fraxinus pennsylvanica	green ash	Tree																														
Liriodendron tulipifera	tuliptree	Tree									15				3	3	3			4												
Platanus occidentalis	American sycamore	Tree			7	3	3	3	3	3	24	3	3	24			2	1	1	1	5	5	55	9	ç	9 9	j			3	3	5,
Prunus serotina	black cherry	Tree			1																											
Quercus	oak	Tree	2	2 2	2	. 1	1	. 1	L									1	1	1							1	. 1	. 1			
Quercus alba	white oak	Tree	2	2 2	2	2			2	2	2	2	2	2	1	1	1	10	10	10	4	4	4				1	. 1	. 1	. 2	2	2
Quercus nigra	water oak	Tree										2	2	2							2	2	2									
Quercus rubra	northern red oak	Tree																														
Robinia	locust																															
Salix nigra	black willow	Tree			4	l I																										
Jnknown		Shrub or Tree																														
Wisteria frutescens	American wisteria	Vine																														
Wisteria sinensis	Chinese wisteria	Exotic																											1			
		Stem count		5 5	22	13	13	14	28	28	65	19	19	40	7	7	11	14	14	18	25	25	75	10	10	10	9 ر	9	9	11	11	11
		size (ares)		1			1			1			1			1			1			1			1			1			1	
	9						0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02	
		Species count	3	3	7	5	5	5 5	4	4	5	4	4	4	3	3	4	4	4	5	6	6	6	2	2	2 2	. 5	, 5	5	5	5	ŗ
		Stems per ACRE	202.3	202.3	890.3	526.1	526.1	566.6	1133	1133	2630	768.9	768.9	1619	283.3	283.3	445.2	566.6	566.6	728.4	1012	1012	3035	404.7	404.7	7 404.7	364.2	364.2	364.2	445.2	445.2	445.2

Color for Density

Exceeds requirements by 10%

Exceeds requirements, but by less than 10%

Fails to meet requirements, by less than 10%

Fails to meet requirements by more than 10%

PnoLS = Planted excluding livestakes P-all = Planting including livestakes

T = All planted and natural recruits including livestakes

T includes natural recruits

Table 8. Total Stems by Plot and Species (continued)
Project Code 20004. Project Name: WWC

																Current	Plot D	ata (MY	3 2022)											,		-
			200	04-01-0	0011	200	04-01-0	0012	200	04-01-0	0013	200	04-01-0	014	200	04-01-0	015	200	04-01-0	016	200	04-01-0	017	200	04-01-	0018	200	04-01-0	019	200	04-01-0	020
Scientific Name	Common Name	Species Type	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т
Acer rubrum	red maple	Tree																											1			· ·
Betula nigra	river birch	Tree	4	. 4	4	3	3	3	1	1	1							3	3	3	6	6	6	3	3	3	3	3	3	2	. 2	2
Carya	hickory	Tree																											<u>'</u>			
Celtis occidentalis	common hackberry	Tree																											, ,			[
Cephalanthus occidentalis	common buttonbush	Shrub																											i			[
Cornus amomum	silky dogwood	Shrub				2	2	2				2	2	2	3	3	3	3	3	3	5	5	5	1	. 1	. 1			,	2	. 2	2
Diospyros virginiana	common persimmon	Tree							1	1	1																3	3	3			[
Fraxinus pennsylvanica	green ash	Tree																											,			[
Liriodendron tulipifera	tuliptree	Tree							3	3	3				1	1	1												i			[
Platanus occidentalis	American sycamore	Tree				3	3	3	3	3	4	15	15	15	13	13	13	7	7	21	2	2	2	1	. 1	. 1	11	11	11	. 8	8	8
Prunus serotina	black cherry	Tree																											i			[
Quercus	oak	Tree													1	1	1	4	4	4	1	1	1	1	. 1	. 1				1	. 1	1
Quercus alba	white oak	Tree				1	1	1							1	1	1	2	2	2	1	1	1						,	1	. 1	1
Quercus nigra	water oak	Tree				5	5	5							1	1	1				1	1	1	2	. 2	. 2			i			[
Quercus rubra	northern red oak	Tree																			2	2	2						i			[
Robinia	locust																															
Salix nigra	black willow	Tree																											i			[
Unknown		Shrub or Tree																											i			[
Wisteria frutescens	American wisteria	Vine																											<u>'</u>			
Wisteria sinensis	Chinese wisteria	Exotic																														
		Stem count	4	4	4	14	14	14	8	8	9	17	17	17	20	20	20	19	19	33	18	18	18	8	8	8	17	17	17	14	14	14
		size (ares)		1			1			1			1			1			1			1			1			1			1	
		size (ACRES)		0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02			0.02	
	Species of				1	. 5	5	5	4	4	4	2	2	2	6	6	6	5	5	5	7	7	7	5	5	5	3	3	3	5	5	5
	Stems pe			161.9	161.9	566.6	566.6	566.6	323.7	323.7	364.2	688	688	688	809.4	809.4	809.4	768.9	768.9	1335	728.4	728.4	728.4	323.7	323.7	323.7	688	688	688	566.6	566.6	566.6

Color for Density

Exceeds requirements by 10%

Exceeds requirements, but by less than 10%

Fails to meet requirements, by less than 10%

Fails to meet requirements by more than 10%

PnoLS = Planted excluding livestakes

P-all = Planting including livestakes

T = All planted and natural recruits including livestakes

T includes natural recruits

Table 8. Total Stems by Plot and Species (continued)
Project Code 20004. Project Name: WWC

								Cur	rent Pl	ot Data	(MY3 2	2022)											Annual	Means	;				
			200	04-01-	0021	200	04-01-	0022	20	004-01-	0023	200	004-01-	0024	200	004-01-	0025	M	Y3 (202	2)	N	1Y2 (202	21)	M	Y1 (202	20)	M	Y0 (2020	0)
Scientific Name	Common Name	Species Type	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	T	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	Т	PnoLS	P-all	T	PnoLS	P-all	T	PnoLS I	P-all	T
Acer rubrum	red maple	Tree																		5			4						
Betula nigra	river birch	Tree	5	į	5 5	1	1	1	. 3	3 3	3 3	3 1	1 1	. 1	. 2	. 2	. 2	72	72	72	71	. 71	71	75	75	75	77	77	77
Carya	hickory	Tree																					2						
Celtis occidentalis	common hackberry	Tree																1	1	1	1	. 1	1						
Cephalanthus occidentalis	common buttonbush	Shrub																						1	1	1	1	1	1
Cornus amomum	silky dogwood	Shrub				5	5	5	1	L 1	1	. 6	5 6	6	5 1	. 1	. 1	66	66	70	64	64	64	70	70	70	75	75	75
Diospyros virginiana	common persimmon	Tree										2	2 2	. 2	2			13	13	13	15	15	15	16	16	16	22	22	22
Fraxinus pennsylvanica	green ash	Tree	1	:	1 1													1	1	1	1	. 1	1	1	1	1	1	1	1
Liriodendron tulipifera	tuliptree	Tree							1	L 1	1 1							8	8	27	8	8	14	16	16	16	18	18	18
Platanus occidentalis	American sycamore	Tree	5	Ξ,	5 5	5	5	5	3	3 3	3	3			1	. 1	. 1	104	104	220	103	103	436	116	116	134	115	115	115
Prunus serotina	black cherry	Tree																		1			1						
Quercus	oak	Tree										1	L 1	. 1				14	14	14	25	25	25	64	64	64	93	93	93
Quercus alba	white oak	Tree	3	:	3 3	2	2	2	1	L 1	1				2	. 2	. 2	38	38	38	33	33	33	37	37	37	35	35	35
Quercus nigra	water oak	Tree										1	L 1	. 1				14	14	14	12	12	12	25	25	25	29	29	29
Quercus rubra	northern red oak	Tree																2	2	2	2	. 2	3	2	2	2			
Robinia	locust																						3						
Salix nigra	black willow	Tree																		4			4						
Unknown		Shrub or Tree																									5	5	5
Wisteria frutescens	American wisteria	Vine																						1	1	1			
Wisteria sinensis	Chinese wisteria	Exotic																						3	3	3			
		Stem count	14	14	1 14	13	13	13	9	9 9	9 9	11	11	. 11	. 6	6	6	333	333	482	335	335	689	427	427	445	471	471	471
		size (ares)		1			1			1			1			1			25			25			25			25	
		size (ACRES)		0.02	0.02 0.02					0.02			0.02			0.02			0.62			0.62			0.62			0.62	
		Species count	4	4	1 4	4	4	4		5 5	5 5	5	5 5	5	5	4	4	11	11	14	11	. 11	16	13	13	13		11	11
		Stems per ACRE	566.6	566.0	566.6	526.1	526.1	526.1	364.2	364.2	364.2	445.2	445.2	445.2	242.8	242.8	242.8	539	539	780.2	542.3	542.3	1115	691.2	691.2	720.3	762.4	762.4	762.4

Color for Density

Exceeds requirements by 10%

Exceeds requirements, but by less than 10%

Fails to most requirements, by less than 10%

Fails to meet requirements, by less than 10% Fails to meet requirements by more than 10%

PnoLS = Planted excluding livestakes

P-all = Planting including livestakes

T = All planted and natural recruits including livestakes

T includes natural recruits

Table 9. MY3 Temporary Vegetation Plot Data Warren Wilson College Restoration Site

Species	Common Name	T-1 (82°)	T-2 (240°)	T-3 (82°)	T-4 (284°)	T-5 (167°)
Betula nigra	River birch					3
Liriodendron tulipifera	Tulip poplar		4			
Nyssa sylvatica	Black gum					
Diospyros virginiana	Common persimmon		6			
Quercus alba	White oak	2		3		1
Platanus occidentalis	American sycamore	8	3	4	5	
Quercus phellos	Willow oak					2
Fraxinus pennsylvanica	Green Ash			1		
Cornus amomum	Silky dogwood	1	3	4	1	5
Total Number of Stems	Stem Count	11	16	12	6	11
	Size (Ares)	1	1	1	1	1
	Size (Acres)	0.02	0.02	0.02	0.02	0.02
	Species count	6	5	6	6	6
Stems/Acre	Stems per acre	445	647	486	243	445

Table 10. Planted Vegetation Totals
Warren Wilson College Stream Mitigation Site

Warren Wilson College Stream Mitig Plot #	Planted Stems/Acre	Success Criteria Met?
1	202	No
2	526	Yes
3	1133	Yes
4	769	Yes
5	283	No
6	567	Yes
7	1012	Yes
8	405	Yes
9	364	Yes
10	445	Yes
11	162	No
12	567	Yes
13	324	Yes
14	688	Yes
15	809	Yes
16	769	Yes
17	728	Yes
18	324	Yes
19	688	Yes
20	567	Yes
21	567	Yes
22	526	Yes
23	364	Yes
24	445	Yes
25	243	No
T-1	445	Yes
T-2	647	Yes
T-3	486	Yes
T-4	243	No
T-5	445	Yes
Average Planted Stems/Acre Across Permanent & Temporary Plots	525	Yes

Appendix D – Stream Geomorphology Data

- Tables 11A-I. Baseline Stream Data Summary
- Tables 12A-I. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions)
- Tables 13A-I. Monitoring Data-Dimensional Morphology Summary (Dimensional Parameters-Cross-sections)
- Tables 14A-I. Monitoring Data-Stream Reach Data Summary

Cross-section Plots

							D	! 4 NI .	/N I						n Data			T 4 1	/53	(O. f t)											
Parameter	Gauge ²	D	ional C		I	D			ame/Nur	nber ((vvarre			019) ence Da		ent/Rea					D-4-	_	Ī	D '		I		B.	D!!		
raidilletei	Gauge	Reg	ionai C	urve		Pre-	Existinç	Cona	ition			UI	4 Refer	ence D	ata			Cnemti	ronics i	Referen	ce Data			Design				Monitorin	ig Baseiii	ne	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD ⁵	n	Min	Mean	Med	Max	SD⁵	n	Min	Mean	Med	Max	SD ⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD⁵	n
Bankfull Width (ft))				2.6	10.9		19.3			5.1	6.8		9.4			11.3	14.0		15.8			9.2	10.0	10.7	10.6	11.2	11.2	11.9		2.0
Floodprone Width (ft)					27.0	55.0		75.0			15.0	20.0		28.0			16.5	19.0		25.0			25.0	55.0	75.0	100.0	100.0	100.0	100.0		2.0
Bankfull Mean Depth (ft)					0.4	0.6		1.2			0.8	0.9		1.0			0.4	0.6		1.2			0.7	0.7	0.8	0.9	1.0	1.0	1.1		2.0
¹ Bankfull Max Depth (ft))				0.6	1.7		1.7			1.3	1.4		1.5			1.7	1.8		2.0			0.9	1.1	1.3	1.7	1.9	1.9	2.1		2.0
Bankfull Cross Sectional Area (ft²)					3.2	6.8		7.1			6.2	6.2		6.2			16.7	16.7	<u> </u>	16.7			7.1	7.1	7.1	9.4	11.1	11.1	12.8		2.0
Width/Depth Ratio					2.1	17.0		53.2			5.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	11.1	11.5	11.5	11.9		2.0
Entrenchment Ratio					1.4	6.9		21.2			2.7	2.9		3.0			16.5	19.0		22.0			1.3	2.9	3.0	8.4	8.9	8.9	9.5		2.0
¹ Bank Height Ratio					1.0	1.8		5.7			1.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0		2.0
Profile																															
Riffle Length (ft)																										1.9	14.9	8.9	55.2	14.8	20.0
Riffle Slope (ft/ft)					No died		.4141		.: 		0.0090	0.0400		0.0754			0.0156	0.0228		0.0468			0.0286	0.0457	0.0857	0.0055	0.0201	0.0192	0.0387	0.0095	20.0
Pool Length (ft)					ino disi		staighte		riffles and p tivities	ooois																2.4	10.7	11.2	19.4	4.8	20.0
Pool Max depth (ft)								9			2.0	2.3		2.6			1.9	2.1		2.3			1.0	1.4	1.4						
Pool Spacing (ft)											27.3	37.1		45.8			28.8	50.7		70.7			29.9	39.9	69.8	6.9	30.6	28.0	66.9	16.2	19.0
Pattern																															
Channel Beltwidth (ft)										15.4	19.0		25.2			13.4	14.7		16.6			15.0	29.9	39.9	15.0		29.9	39.9			
Radius of Curvature (ft)					1						8.7	15.8		29.4			0.8	2.2		3.3			19.9	29.9	39.9	15.0		29.9	39.9		
Rc:Bankfull width (ft/ft)					No dist		stitive par staighte		riffles and p	oools																					
Meander Wavelength (ft)						uuo to	otalgine	mig do			56.5	63.8		76.0			59.8	96.3		117.2			59.8	84.7	119.6	59.8		84.7	119.6		
Meander Width Ratio											2.3	2.8		3.7			1.0	1.1		1.2			1.5	3.0	4.0	1.5		3.0	4.0		
Transport parameters																															
Reach Shear Stress (competency) lb/f²	2						7.6	63																0.78							
Max part size (mm) mobilized at bankfull																															
Stream Power (transport capacity) W/m²	2						50.	82																49.43							
Additional Reach Parameters																															
Rosgen Classification							Cg	j 4					Ek	4					В	3 4				Cb 4				C	b 4		
Bankfull Velocity (fps)							0.	6																							
Bankfull Discharge (cfs)							27	.7																							
Valley length (ft)							567	7.0																							
Channel Thalweg length (ft)							578	3.0																610.0				60	01.0		
Sinuosity (ft)								.0					.2						.0				1.1					1.1			
Water Surface Slope (Channel) (ft/ft)							0.02	294				0.0	226					0.0	167				0.0286				0.0	0163			
BF slope (ft/ft)																															
³ Bankfull Floodplain Area (acres)																															
⁴ % of Reach with Eroding Banks																															
Channel Stability or Habitat Metric																															
Biological or Other	-																														

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

4 = Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data;

5. Of value/needed only if the n exceeds 3

							Pro	ject N	ame/Num						m Data Segm			T 1 Up	per (43	6 feet)											
Parameter	Gauge ²	Reg	ional C	urve		Pre	Existing	g Cond	lition	\perp		UT	4 Refer	ence D	ata			Chemt	tronics F	Referen	ce Data	a		Desig	n			Monitorii	ng Baseli	ne	
Dimension and Substrate - Riffle Only	П	LL	UL	Eq.	Min	Mean	Med	Max	SD ⁵	n Mi	in	Mean	Med	Max	SD ⁵	n	Min	Mean	Med	Max	SD⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD⁵	n
Bankfull Width (ft)					2.6	10.9		19.3		5.		6.8		9.4			11.3	14.0		15.8			9.2	10.0	10.7	8.5	9.1	9.1	9.6		2.0
Floodprone Width (ft)					27.0	55.0		75.0		15		20.0		28.0			16.5	19.0		25.0			25.0	55.0	75.0	100.0	100.0	100.0	100.0		2.0
Bankfull Mean Depth (ft)					0.4	0.6		1.2		0.	.8	0.9		1.0			0.4	0.6		1.2			0.7	0.7	0.8	0.5	0.6	0.6	0.7		2.0
¹ Bankfull Max Depth (ft)					0.6	1.7		1.7		1.	.3	1.4		1.5			1.7	1.8		2.0			0.9	1.1	1.3	8.0	1.1	1.1	1.4		2.0
Bankfull Cross Sectional Area (ft²)					3.2	6.8		7.1		6.	.2	6.2		6.2			16.7	16.7		16.7			7.1	7.1	7.1	4.3	5.4	5.4	6.6		2.0
Width/Depth Ratio					2.1	17.0		53.2		5.	.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	14.0	15.5	15.5	16.9		2.0
Entrenchment Ratio					1.4	6.9		21.2		2.	.7	2.9		3.0			16.5	19.0		22.0			1.3	2.9	3.0	10.4	11.1	11.1	11.8		2.0
¹ Bank Height Ratio					1.0	1.8		5.7		1.	.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0		1.0
Profile																															
Riffle Length (ft)																										1.9	14.9	8.9	55.2	14.8	20.0
Riffle Slope (ft/ft)					No dis	tinct ren	etitive na	ttern of	riffles and po	0.00	090	0.0400		0.0754			0.0156	0.0228	5	0.0468			0.0286	0.0457	0.0857	0.0055	0.0201	0.0192	0.0387	0.0095	20.0
Pool Length (ft)					, No dis		o staighte																	L.,	<u> </u>	2.4	10.7	11.2	19.4	4.8	20.0
Pool Max depth (ft)					ı		3	3		2.		2.3		2.6			1.9	2.1		2.3			1.0	1.4	1.4		00.0	00.0	00.0	40.0	40.0
Pool Spacing (ft)										27	.3	37.1		45.8			28.8	50.7		70.7			29.9	39.9	69.8	6.9	30.6	28.0	66.9	16.2	19.0
Pattern Clark Co. 18 (6)			1	_						15	: 4 T	10.0	ı	25.2	т .	ī	12.4	14.7	T	166	_	_	15.0	20.0	20.0	15.0	т .	29.9	39.9		1
Channel Beltwidth (ft) Radius of Curvature (ft)					Į.					15 8.		19.0 15.8		29.4	<u> </u>		13.4 0.8	2.2	1	16.6 3.3	-	1	15.0 19.9	29.9 29.9	39.9 39.9	15.0 15.0	-	29.9	39.9		
Radius of Curvature (it) Rc:Bankfull width (ft/ft)					No dis	tinct rep	etitive pa	ttern of	riffles and po	ols O.	' +	10.0		23.4	1		0.0	2.2		3.5		1	13.3	20.0	00.0	10.0	-	20.0	33.3		-
Meander Wavelength (ft)				-	ł	due t	o staighte	ening ac	tivities	56	5.5	63.8	-	76.0	-		59.8	96.3		117.2	-	+	59.8	84.7	119.6	59.8	+	84.7	119.6		
Meander Wavelength (it)					ı					2.		2.8		3.7	1		1.0	1.1		1.2		1	1.5	3.0	4.0	1.5	 	3.0	4.0		
Wearder Width Natio										_				411										0.0				***			
Transport parameters																															
Reach Shear Stress (competency) lb/f ²							7.	.6																0.8		T					
Max part size (mm) mobilized at bankfull																										1					
Stream Power (transport capacity) W/m ²							50	0.8																49.4							
Additional Reach Parameters	!I							-															_								
Rosgen Classification							Cg	1 4					Ek	o 4					В	4			$\overline{}$	Cb 4		$\overline{}$		(Cb 4		
Bankfull Velocity (fps)							0.																								
Bankfull Discharge (cfs)							27	7.7																							
Valley length (ft)							189																								
Channel Thalweg length (ft)							19:																	478.0					58.0		
Sinuosity (ft)							1.							.2					1					1.1					1.1		
Water Surface Slope (Channel) (ft/ft)							0.0	294					0.0	226	-				0.0	167				0.0286	;			0.	0372		
BF slope (ft/ft)																															
³ Bankfull Floodplain Area (acres)																															
⁴ % of Reach with Eroding Banks																															
Channel Stability or Habitat Metric																															
Biological or Other																															

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

						Ta Project Name/Number (V							e Streai 0019)				T 3 Lo	wer (87	3 feet)											
Parameter	Gauge ²	Reg	jional C	urve		Pre-	Existin	g Cond	lition	\perp	U	T4 Ref	erence D	ata			Chemt	ronics F	Referen	ce Data	a		Design	1			Monitori	ng Baselii	ne	
Dimension and Substrate - Riffle Only		LL	UL	I Ea.	Min	Mean	Med	Max	SD ⁵ n	Min	Mean	Med	Max	SD ⁵	l n	Min	Mean	Med	Max	SD ⁵	l n	Min	Med	Max	Min	Mean	Med	Max	SD ⁵	n
Bankfull Width (ft)			<u> </u>	-4.	11.5	12.1		14.1	1	5.1	6.8	1	9.4	+	- 	11.3			15.8		- 	14.8	16.0	17.1	10.6	17.0	17.0	23.5		2.0
Floodprone Width (ft)					19.0	29.0		100.0		15.0	20.0	1	28.0			16.5	19.0		25.0			80.0	100.0	120.0	100.0	100.0	100.0	100.0		2.0
Bankfull Mean Depth (ft)					1.3	1.5		1.6		0.8	0.9		1.0			0.4	0.6		1.2			1.1	1.1	1.2	0.9	1.0	1.0	1.2		2.0
¹ Bankfull Max Depth (ft)					1.6	2.0		2.2		1.3	1.4		1.5			1.7	1.8		2.0			1.4	1.7	2.1	1.7	1.9	1.9	2.1		2.0
Bankfull Cross Sectional Area (ft²)					18.2	18.2		18.2		6.2	6.2	1	6.2			16.7	16.7		16.7			18.2	18.2	18.2	9.4	18.3	18.3	27.2		2.0
Width/Depth Ratio					7.3	8.0		10.9		5.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	11.9	16.1	16.1	20.2		2.0
Entrenchment Ratio					1.3	2.5		8.3		2.7	2.9	1	3.0			16.5	19.0		22.0			5.4	6.3	7.0	4.3	6.9	6.9	9.5		2.0
¹ Bank Height Ratio					1.8	2.0		2.4		1.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0		2.0
Profile		-		•									•	•	•		•	•		•	•			•		•		•		
Riffle Length (ft)																									16.7	35.3	33.0	65.0	13.7	15.0
Riffle Slope (ft/ft)					No dis	tinct ren	atitiva na	ttern of i	riffles and pool	0.009	0.040	0	0.0754			0.0156	0.0228		0.0468			0.0141	0.0225	0.0423		0.0183	0.0194	0.0276	0.0055	15.0
Pool Length (ft)					I No dis		staighte																		11.3	20.4	20.3	29.2	6.5	15.0
Pool Max depth (ft)						440	- o.a.g	g ac		2.0			2.6			1.9	2.1		2.3			1.6	2.2	2.3	~~~	010	F7.0	1010	10.0	45.0
Pool Spacing (ft)										27.3	37.1		45.8			28.8	50.7		70.7			47.9	63.8	111.7	32.2	64.0	57.0	104.0	18.9	15.0
Pattern				_						15.4	1 10 0	_	1 25 2			12.4	1 117		16.6			22.0	17.0	62.0	22.0		47.0	62.0		
Channel Beltwidth (ft)					1					15.4 8.7	19.0 15.8		25.2 29.4	-		13.4 0.8	14.7		16.6 3.3			23.9 31.9	47.9. 47.9	63.8 63.8	23.9 31.9		47.9 47.9	63.8 47.9		
Radius of Curvature (ft) Rc:Bankfull width (ft/ft)					No dis				riffles and pool	5 -0.7	13.0	+	29.4			0.0	2.2		3.3			31.9	47.5	03.0	31.9		47.5	47.5		
Meander Wavelength (ft)					ł	due to	o staighte	ening ac	tivities	56.5	63.8	+	76.0	 	-	59.8	96.3	<u> </u>	117.2	-	 	95.8	135.7	191.5	95.8		165.7	191.5		
Meander Wavelength (tr)					ł					2.3		+	3.7	<u> </u>		1.0	1.1		1.2			1.5	3.0	4.0	1.5		3.0	4.0		
Wearder Width Natio													4									- 110	-				-			
Transport parameters																														
Reach Shear Stress (competency) lb/f ²					$\overline{}$		3	.0															0.9		$\overline{}$					
Max part size (mm) mobilized at bankfull					_																	-			_					
Stream Power (transport capacity) W/m ²					_		69	9.1															66.7		1					
Additional Reach Parameters							3.									-														
Rosgen Classification					$\overline{}$		Εç	₃ 4		$\overline{}$			Eb 4					В	4				Ce 4		$\overline{}$		(Ce 4		
Bankfull Velocity (fps)								.5															4.2				9	60.0		
Bankfull Discharge (cfs)							75	5.8																						
Valley length (ft)							168																							
Channel Thalweg length (ft)							358	32.0															971.0				9	60.0		
Sinuosity (ft)							1			\perp			1.2					1					1.1					1.1		
Water Surface Slope (Channel) (ft/ft)					Ь—		0.0	146				0	.0226					0.0	167				0.0155		<u> </u>		0.	0129		
BF slope (ft/ft)					<u> </u>					—						ļ									ــــــ					
³ Bankfull Floodplain Area (acres)										Д																				
⁴ % of Reach with Eroding Banks																														
Channel Stability or Habitat Metric																														
Biological or Other																														

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

							Proj	ect Na	nme/Number	Table 1 (Warre	11d. B n Wils	aseline on/100	e Streai 019)	m Data Segme	Summ nt/Rea	nary nch: UT	⁻ 3 Upp	oer (199	95 feet)										
Parameter	Gauge ²	Reg	ional C	urve		Pre-	Existing	g Cond	lition		U	T4 Refe	rence D	ata			Chemt	ronics F	Referen	ce Data	a		Desigr	1			Monitori	ng Baselii	ne	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD ⁵ n	Min	Mean	Med	Max	SD ⁵	n	Min	Mean	Med	Max	SD⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD ⁵	n
Bankfull Width (ft)					11.5	12.1		14.1		5.1	6.8		9.4			11.3	14.0		15.8			14.8	16.0	17.1	14.2	16.1	15.7	18.7	2.1	4.0
Floodprone Width (ft)					19.0	29.0		100.0		15.0	20.0		28.0			16.5	19.0		25.0			80.0	100.0	120.0		100.0	100.0	100.0	0.0	4.0
Bankfull Mean Depth (ft)					1.3	1.5		1.6		0.8	0.9		1.0			0.4	0.6		1.2			1.1	1.1	1.2	1.0	1.0	1.0	1.1	0.1	4.0
¹ Bankfull Max Depth (ft)					1.6	2.0		2.2		1.3	1.4		1.5			1.7	1.8		2.0			1.4	1.7	2.1	1.6	1.8	1.8	1.9	0.1	4.0
Bankfull Cross Sectional Area (ft²)					18.2	18.2		18.2		6.2	6.2		6.2			16.7	16.7		16.7			18.2	18.2	18.2	13.6	16.8	16.2	21.4	3.3	4.0
Width/Depth Ratio					7.3	8.0		10.9		5.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	13.3	15.5	15.6	17.4	1.7	4.0
Entrenchment Ratio					1.3	2.5		8.3		2.7	2.9		3.0			16.5	19.0		22.0			5.4	6.3	7.0	5.4	6.3	6.4	7.0	0.8	4.0
¹ Bank Height Ratio					1.8	2.0		2.4		1.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0	0.0	4.0
Profile																														
Riffle Length (ft)										<u> </u>														<u> </u>	8.7	33.7	29.5	79.6	18.6	34.0
Riffle Slope (ft/ft)					No dis	tinct ren	etitive nat	tern of i	riffles and pools	0.0090	0.0400)	0.0754			0.0156	0.0228		0.0468			0.0141	0.0225	0.0423		0.0183	0.0176	0.0338	0.0059	34.0
Pool Length (ft)					110 0.0	due to	staighte	ning ac	tivities								0.1		0.0						10.1	19.3	17.4	42.7	6.6	34.0
Pool Max depth (ft)					l		3	3		2.0	2.3		2.6			1.9	2.1		2.3			1.6	2.2	2.3	22.0	CF 4		100.0	47.0	22.0
Pool Spacing (ft)										27.3	37.1		45.8			28.8	50.7		70.7			47.9	03.8	111.7	33.6	65.4	61.3	108.0	17.8	33.0
Pattern Channel Baltari III. (ft)										15.4	19.0		25.2	_		13.4	14.7		16.6		_	23.9	47.9.	63.8	23.9	т —	47.9	63.8		
Channel Beltwidth (ft) Radius of Curvature (ft)										8.7	15.8		29.4			0.8	2.2		3.3			31.9	47.9	63.8	31.9	 	47.9	63.8		
Radius of Curvature (it) Rc:Bankfull width (ft/ft)				-	No dis				riffles and pools	0.7	10.0	+	20.4		-		2.2		0.0			01.0	47.0	00.0	01.5	 	77.0	00.0		
Meander Wavelength (ft)					ł	due to	staighte	ning ac	tivities	56.5	63.8	+	76.0			59.8	96.3		117.2			95.8	135.7	191.5	95.8	 	165.7	191.5		
Meander Wavelength (tr)					i					2.3	2.8	+	3.7	1	-	1.0	1.1		1.2			1.5	3.0	4.0	1.5	 	3.0	4.0		
Wedner Watti Rate																														
Transport parameters																														
Reach Shear Stress (competency) lb/f ²							3.	0															0.9		T					
Max part size (mm) mobilized at bankfull																						_			1					
Stream Power (transport capacity) W/m ²							69	.1															66.7		$\overline{}$					
Additional Reach Parameters										-																				
Rosgen Classification							Eg	4				Е	b 4					В	4				Ce 4				(Ce 4		
Bankfull Velocity (fps)							1.																4.2							
Bankfull Discharge (cfs)							75	.8																						
Valley length (ft)							222																							
Channel Thalweg length (ft)							358																2116.0					195.0		
Sinuosity (ft)							1.						1.2					1.					1.1					1.1		
Water Surface Slope (Channel) (ft/ft)							0.01	146				0.0	0226					0.0	167		-		0.0155				0.	0139		
BF slope (ft/ft)																														
³ Bankfull Floodplain Area (acres)																														
⁴ % of Reach with Eroding Banks																														
Channel Stability or Habitat Metric																														
Biological or Other																														

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

								Projec	t Name/Nu	Table	: 11e. Narre	Bas	seline (Strean	n Data	Summ	nary /Reach	· I IT 4	(278 fe	et)											
Parameter	Gauge ²	Reg	jional C	urve		Pre-	Existing			TIDEL (V	vario		Refere			ginen			tronics F		ce Data	1		Design	l			Monitori	ng Baseliı	ne	
			I	T =		1			L 0D5 L	-	1,,				0.05	1	1	Ι.,	1		0.05					1 14:	1 14	1	1 14	0.05	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD⁵ n	Min 5.1		ean 5.8	Med	Max 9.4	SD⁵	n	Min 11.3	Mean 14.0	Med	Max 15.8	SD⁵	n	Min 8.6	Med 9.3	Max 10.0	Min 14.0	Mean 14.0	Med 14.0	Max 14.0	SD⁵	n 1.0
Bankfull Width (ft) Floodprone Width (ft)										15.0		0.0		28.0			16.5		1	25.0		<u> </u>	20.0	70.0	120.0		100.0	100.0	100.0		1.0
Bankfull Mean Depth (ft)										0.8		0.0	-	1.0			0.4	0.6	+	1.2		<u> </u>	0.6	0.7	0.7	1.0	1.0	1.0	1.0		1.0
¹ Bankfull Max Depth (ft)							\vdash			1.3	_	.4		1.5			1.7	1.8		2.0			0.8	1.0	1.2	1.6	1.6	1.6	1.6		1.0
Bankfull Cross Sectional Area (ft²)				1	-				 	6.2		6.2		6.2			16.7	16.7	+	16.7		 	6.2	6.2	6.2	13.3	13.3	13.3	13.3		1.0
Width/Depth Ratio							\vdash			5.1		7.6		11.8	-		8.1	12.0	+	14.8			12.0	14.0	16.0	14.7	14.7	14.7	14.7		1.0
Entrenchment Ratio										2.7		2.9		3.0			16.5	19.0	+	22.0		-	2.3	7.5	12.0	7.2	7.2	7.2	7.2		1.0
¹ Bank Height Ratio							\vdash			1.0		.0		1.0			1.0	1.0	 	1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0		1.0
Profile									<u> </u>		_							1										1			
Riffle Length (ft)			I	П						T	$\overline{}$	\neg	Т		Г	П		Т	Т	ı		Т	T T	I	Г	10.4	25.1	19.3	63.9	19.9	6.0
Riffle Slope (ft/ft)					1					0.009	90 0.0	400		0.0754			0.0156	0.0228	1	0.0468			0.0194	0.0311	0.0583	0.0095	0.0338	0.0380	0.0619	0.0189	6.0
Pool Length (ft)					No dis		etitive pat o staighte		riffles and pool	s	\top	\neg														12.8	15.0	14.8	19.2	2.3	6.0
Pool Max depth (ft)					1	due id	staignte	ming ac	uviues	2.0		2.3		2.6			1.9	2.1	1	2.3			0.9	1.3	1.3						
Pool Spacing (ft)										27.3	3	7.1		45.8			28.8	50.7		70.7			27.9	37.3	65.2	28.3	38.0	42.0	45.3	8.2	6.0
Pattern																															
Channel Beltwidth (ft)										15.4		9.0		25.2			13.4			16.6			14.0	27.9	37.3	27.9		27.9	37.3		
Radius of Curvature (ft)					No dis	tinct rene	etitive nat	tern of r	riffles and poo	8.7	1:	5.8		29.4			0.8	2.2		3.3			18.6	27.9	37.3	18.6		27.9	37.3		
Rc:Bankfull width (ft/ft)					, ito alo		staighte							70.0			50.0	000		117.0			55.0	70.0	1110			70.0	1110		
Meander Wavelength (ft)					l		J	Ü		56.5		3.8		76.0				96.3		117.2			55.9		111.8	55.9		79.2	111.8		
Meander Width Ratio										2.3		2.8		3.7			1.0	1.1		1.2			1.5	3.0	4.0	1.5		3.0	4.0		
Transport parameters																															
										_														0.7		T					
Reach Shear Stress (competency) lb/f ² Max part size (mm) mobilized at bankfull										_													_	0.7							
																							_	28.9		 					
Stream Power (transport capacity) W/m ² Additional Reach Parameters					<u></u>												<u> </u>							20.9		<u> </u>					
Rosgen Classification					r		G	4					Eb	4					B	4			_	C4		т —			C 4		
Bankfull Velocity (fps)			П				1.							_						_			_	3.9							
Bankfull Discharge (cfs)							29																	0.0							
Valley length (ft)							312			-																					
Channel Thalweg length (ft)							362	2.0																233.0				2	92.0		
Sinuosity (ft)							1.						1.2	2					1	.0				1.1					1.1		
Water Surface Slope (Channel) (ft/ft)							0.02	226					0.02	26					0.0	167				0.0194				0.	0235		
BF slope (ft/ft)																															
³ Bankfull Floodplain Area (acres)																															
⁴ % of Reach with Eroding Banks										T																					
Channel Stability or Habitat Metric																															
Biological or Other							\top																								

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

							F	Project	t Name/Num	Table ber (Wa							UT 5	(1024 f	eet)											
Parameter	Gauge ²	Reg	ional C	urve		Pre-	Existing	g Cond	lition		U	T4 Refe	rence D	ata			Chemt	ronics F	Referen	ce Data	a		Design	1			Monitorii	ng Baselii	ne	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD⁵ n	Min	Mean	Med	Max	SD ⁵	n	Min	Mean	Med	Max	SD ⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD ⁵	n
Bankfull Width (ft)					5.6	6.1		7.6		5.1	6.8		9.4			11.3	14.0		15.8			7.6	8.2	8.8	7.3	10.5	9.9	14.4		3.0
Floodprone Width (ft)					8.0	9.0		9.0		15.0	20.0		28.0			16.5	19.0		25.0			80.0	100.0	120.0	100.0	100.0	100.0	100.0		3.0
Bankfull Mean Depth (ft)					0.6	0.8		0.9		0.8	0.9		1.0			0.4	0.6		1.2			0.5	0.6	0.6	0.6	0.7	0.7	8.0		3.0
¹ Bankfull Max Depth (ft))				0.8	1.2		1.3		1.3	1.4		1.5			1.7	1.8		2.0			0.7	0.9	1.1	1.0	1.3	1.5	1.5		3.0
Bankfull Cross Sectional Area (ft ²)					4.8	4.8		4.8		6.2	6.2		6.2			16.7	16.7		16.7			4.8	4.8	4.8	4.5	7.6	7.9	10.4		3.0
Width/Depth Ratio					6.5	7.8		12.0		5.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	11.9	14.7	12.5	19.8		3.0
Entrenchment Ratio					1.2	1.4		1.5		2.7	2.9		3.0			16.5	19.0		22.0			10.5	12.2	13.7	7.0	10.3	10.1	13.7		3.0
¹ Bank Height Ratio					2.4	4.8		5.8		1.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0		3.0
Profile											•	•	•	•			•			•	•			•	-		•	•		
Riffle Length (ft)																									9.2	17.7	15.2	36.5	7.6	31.0
Riffle Slope (ft/ft)					No die	tinct ren	atitiva na	ttern of	riffles and pools	0.0090	0.0400)	0.0754			0.0156	0.0228		0.0468			0.0134	0.0214	0.0401	0.0111	0.0268	0.0248	0.0631	0.0105	31.0
Pool Length (ft)					INO dis		o staighte																		5.5	12.1	12.5	18.2	3.0	30.0
Pool Max depth (ft)						uuo k	o otaligi ita	Jilling Go		2.0	2.3		2.6			1.9	2.1		2.3			0.8	1.1	1.2						
Pool Spacing (ft)										27.3	37.1		45.8			28.8	50.7		70.7			24.6	32.8	57.4	24.0	34.6	32.5	50.2	6.8	30.0
Pattern										45.4	1 40 0		1 05 0	•		40.4	1 44 7	•	40.0			40.0	040	1 00 0	40.0	,	1 040			
Channel Beltwidth (ft)					l					15.4		1	25.2			13.4	14.7		16.6			12.3	24.6	32.8	12.3		24.6	32.8		
Radius of Curvature (ft)					No dis	tinct repe	etitive pa	ttern of i	riffles and pools	8.7	15.8		29.4			0.8	2.2		3.3			16.4	24.6	32.8	16.4		32.8	47.9		
Rc:Bankfull width (ft/ft)						due to	staighte	ening ac	tivities	56.5	63.8		76.0			59.8	06.2		117.0			40.2	60.7	98.4	49.2		60.7	98.4		
Meander Wavelength (ft)					ł					2.3	2.8	+	76.0 3.7			1.0	96.3 1.1	-	117.2	-	1	49.2 1.5	69.7 3.0	4.0	1.5		69.7 3.0	4.0		
Meander Width Ratio										2.5	2.0		5.7			1.0	1.1		1.2			1.0	3.0	4.0	1.5		5.0	4.0		
Transport parameters																														
Reach Shear Stress (competency) lb/f ²	2						7.	.6															0.4							
Max part size (mm) mobilized at bankfull							-	-																						
Stream Power (transport capacity) W/m ²							15	5.8															15.1							
Additional Reach Parameters																														
Rosgen Classification							G	3		T		E	b 4					В	4			Т	Ce 4					Ce 4		
Bankfull Velocity (fps)			I				0.	.3															3.8							
Bankfull Discharge (cfs)							18																							
Valley length (ft)							115																							
Channel Thalweg length (ft)							76	9.0															1076.0				10	76.0		
Sinuosity (ft)							1.					1	.2					1.					1.1					1.1		
Water Surface Slope (Channel) (ft/ft)							0.0	14				0.0)226					0.0	167				0.0134				0.	0221		
BF slope (ft/ft)																														
³ Bankfull Floodplain Area (acres)																														
⁴ % of Reach with Eroding Banks																														
Channel Stability or Habitat Metric																														
Biological or Other																														

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

								Project	t Name/Nu	Table mber (V	e 11g Varr	g. Ba en W	seline ilson/1	Strear 00019	n Data) Seເ	Sumn gment/	nary Reach:	UT 6	(1265 f	eet)											
Parameter	Gauge ²	Regi	ional C	urve		Pre	Existin	g Cond	lition	\perp		UT	4 Refer	ence D	ata			Chemt	ronics F	Referen	ce Data	a		Desig	1			Monitorir	ıg Baseliı	ne	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD ⁵ r	n Mir	n N	/lean	Med	Max	SD ⁵	n	Min	Mean	Med	Max	SD ⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD ⁵	n
Bankfull Width (ft)					4.2	5.5		6.4		5.1		6.8		9.4			11.3	14.0		15.8			6.1	6.6	7.0	9.5	10.4	10.1	11.7	1.0	4.0
Floodprone Width (ft)					8.0	9.0		9.0		15.		20.0		28.0			16.5	19.0		25.0			25.0	50.0	75.0	100.0	100.0	100.0	100.0	0.0	4.0
Bankfull Mean Depth (ft)					0.5	0.6		0.7		3.0	_	0.9		1.0			0.4	0.6		1.2			0.4	0.5	0.5	0.5	0.7	0.7	0.9	0.2	4.0
¹ Bankfull Max Depth (ft)					0.6	1.0		1.3		1.3	3	1.4		1.5			1.7	1.8		2.0			0.6	0.7	0.9	0.9	1.1	1.1	1.3	0.2	4.0
Bankfull Cross Sectional Area (ft²)					3.1	3.1		3.1		6.2	2	6.2		6.2			16.7	16.7		16.7			3.1	3.1	3.1	5.6	7.0	7.1	8.1	1.3	4.0
Width/Depth Ratio					5.7	9.8		13.2		5.1		7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	11.1	16.0	15.5	22.0	5.1	4.0
Entrenchment Ratio					1.4	1.5		2.1		2.7	7	2.9		3.0			16.5	19.0		22.0			4.1	7.6	10.6	8.5	9.7	9.9	10.5	0.9	4.0
¹ Bank Height Ratio					2.8	3.9		5.0		1.0	о <u>Г</u>	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0	0.0	4.0
Profile																															
Riffle Length (ft)																										4.8	16.1	13.5	45.8	8.4	47.0
Riffle Slope (ft/ft)					No dis	tinct ren	etitive na	ttern of i	riffles and poo	0.00	90 0	.0400		0.0754			0.0156	0.0228		0.0468			0.0042	0.0067	0.0125		0.0085	0.0066	0.0510	0.0087	36.0
Pool Length (ft)					. No dis		o staighte																			2.0	10.3	10.9	15.7	3.5	46.0
Pool Max depth (ft)							3	3		2.0		2.3		2.6			1.9	2.1		2.3			0.7	0.9	0.9	147	00.0	00.5	00.5	0.0	40.0
Pool Spacing (ft)										27.	3	37.1		45.8			28.8	50.7		70.7			19.8	26.4	46.1	14.5	30.9	29.5	60.5	8.8	46.0
Pattern Clark Control (6)				1						15	4 1	19.0	-	25.2		ı	13.4	14.7		16.6		_	9.9	19.8	26.4	0.0	1	19.8	26.4	ı	1
Channel Beltwidth (ft) Radius of Curvature (ft)				-						15. 8.7		15.8		29.4	-		0.8	2.2		3.3	-	-	13.2	19.8	26.4	9.9 13.2		19.8	26.4		
Radius of Curvature (it) Rc:Bankfull width (ft/ft)					No dis	tinct rep	etitive pa	ttern of i	riffles and poo	ols	-	10.0		23.4		-	0.0	2.2		0.0		1	10.2	13.0	20.4	10.2		13.0	20.4		-
Meander Wavelength (ft)				1	1	due t	o staighte	ening ac	tivities	56.	5	63.8	_	76.0		\vdash	59.8	96.3	-	117.2	-	+	39.5	56.0	79.1	39.5	-	56.0	79.1		-
Meander Wavelength (it)					1					2.3		2.8		3.7			1.0	1.1		1.2		1	1.5	3.0	4.0	1.5		3.0	4.0		
Wearider Width Natio																								0.0				-			
Transport parameters																															
Reach Shear Stress (competency) lb/f ²							1	.1																0.1		T T					
Max part size (mm) mobilized at bankfull					_																										
Stream Power (transport capacity) W/m ²							2	.8																3.0							
Additional Reach Parameters																	-														
Rosgen Classification							G	3					Eb	4					В	4			T	Ce 4				C	e 4		
Bankfull Velocity (fps)							0	.4																3.7							
Bankfull Discharge (cfs)							11																								
Valley length (ft)							213																								
Channel Thalweg length (ft)							136																	1455.0					455		
Sinuosity (ft)							1						1.						1.					1.2					1.2		
Water Surface Slope (Channel) (ft/ft)					<u> </u>		0.0	039					0.02	226					0.0	167				0.0042				0.0	0051		
BF slope (ft/ft)					Ь—																		↓								
³ Bankfull Floodplain Area (acres)																															
⁴ % of Reach with Eroding Banks																															
Channel Stability or Habitat Metric																															
Biological or Other								-						-				-		-											

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

					Project Name/					Table 1 ber (Wa	11h. B arren V	aseline Vilson/1	Strear 100019	m Data)) Seເ	Summ ment/l	nary Reach:	: UT 7	(1844 f	eet)											
Parameter	Gauge ²	Regi	ional C	urve		Pre-	Existing	g Cond	lition		U'	T4 Refe	rence D	ata			Chemt	ronics F	Referen	ce Data	a		Design	1			Monitorii	ng Baselii	пе	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD⁵ n	Min	Mean	Med	Max	SD ⁵	n	Min	Mean	Med	Max	SD ⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD ⁵	n
Bankfull Width (ft)					7.0	7.4		9.7		5.1	6.8		9.4			11.3	14.0		15.8			8.6	9.3	10.0	10.1	11.9	12.2	13.2	1.4	4.0
Floodprone Width (ft)					10.0	13.0		17.0		15.0	20.0		28.0			16.5	19.0		25.0			20.0	70.0	120.0	100.0	100.0	100.0	100.0	0.0	4.0
Bankfull Mean Depth (ft)					0.6	0.8		0.9		0.8	0.9		1.0			0.4	0.6		1.2			0.6	0.7	0.7	0.5	0.7	0.7	0.8	0.1	4.0
¹ Bankfull Max Depth (ft)					0.9	1.1		1.3		1.3	1.4		1.5			1.7	1.8		2.0			8.0	1.0	1.2	8.0	1.1	1.2	1.3	0.2	4.0
Bankfull Cross Sectional Area (ft²)					6.2	6.2		6.2		6.2	6.2		6.2			16.7	16.7		16.7			6.2	6.2	6.2	5.2	8.3	8.6	10.7	2.5	4.0
Width/Depth Ratio					7.9	8.8		15.2		5.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	15.5	17.8	18.0	19.6	1.7	4.0
Entrenchment Ratio					1.4	1.5		2.4		2.7	2.9		3.0			16.5	19.0		22.0			2.3	7.5	12.0	7.6	8.5	8.2	9.9	1.1	4.0
¹ Bank Height Ratio					1.4	1.9		2.6		1.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0	0.0	4.0
Profile																									-					
Riffle Length (ft)																									7.7	27.4	24.3	91.3	15.5	44.0
Riffle Slope (ft/ft)					No die	tinct ren	atitiva na	ttern of i	riffles and pools	0.0090	0.0400		0.0754			0.0156	0.0228		0.0468			0.0194	0.0311	0.0583		0.0126	0.0097	0.0396	0.0113	44.0
Pool Length (ft)					NO UIS	due to	staighte	ening ac	rinies and poors tivities																4.0	11.3	11.7	15.8	2.7	44.0
Pool Max depth (ft)						uuo t	otalgilla	ining ao	aviaoo	2.0	2.3		2.6			1.9	2.1		2.3			0.9	1.3	1.3						
Pool Spacing (ft)										27.3	37.1		45.8			28.8	50.7		70.7			27.9	37.3	65.2	22.3	44.2	40.1	107.9	16.3	43.0
Pattern										1 45 4	1 40 0	,	1 05 0			40.4	1 44 7	•	40.0			110	07.0	1 07 0	07.0		07.0	1 070		
Channel Beltwidth (ft)										15.4			25.2			13.4	14.7		16.6			14.0	27.9	37.3	27.9		27.9	37.3		
Radius of Curvature (ft)					No dis	tinct rep	etitive pa	ttern of i	riffles and pools	8.7	15.8		29.4			0.8	2.2		3.3			18.6	27.9	37.3	18.6		27.9	37.3		
Rc:Bankfull width (ft/ft)						due to	staighte	ening ac	tivities	56.5	63.8	1	76.0			59.8	06.2		117.0			55.0	70.2	111 0	55.9		70.2	111 0		
Meander Wavelength (ft)										2.3	2.8	1	76.0 3.7	<u> </u>		1.0	96.3 1.1		117.2	-	-	55.9 1.5	3.0	111.8 4.0	1.5		79.2 3.0	111.8 4.0		
Meander Width Ratio										2.5	2.0		5.7			1.0	1.1		1.2			1.5	3.0	4.0	1.5		5.0	4.0		
Transport parameters																														
Reach Shear Stress (competency) lb/f ²							2.	.1															0.7		T					
Max part size (mm) mobilized at bankfull																														
Stream Power (transport capacity) W/m ²							30).1															28.9		1					
Additional Reach Parameters																														
Rosgen Classification							Gb	4		T		Е	b 4					В	4			T	Eb 4		T		E	b 4		
Bankfull Velocity (fps)							1.	6															3.9							
Bankfull Discharge (cfs)							23	.9																						
Valley length (ft)							198																							
Channel Thalweg length (ft)							242	6.0															1973.0				1	973		
Sinuosity (ft)							1.						.2					1					1.1					1.1		
Water Surface Slope (Channel) (ft/ft)							0.02	202				0.0)226					0.0	167				0.0194				0.	0103		
BF slope (ft/ft)																														
³ Bankfull Floodplain Area (acres)																														
⁴ % of Reach with Eroding Banks																														
Channel Stability or Habitat Metric										1																				
Biological or Other																														

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

								Projec	ct Name/Nun	Table ber (W	11i. E arren	Baselir Wilso	e Strear n/10001	n Data 9) Se	Summ gment	ary /Reach	ı: UT 8	(760 fe	eet)											
Parameter	Gauge ²	Reg	ional C	urve		Pre-	Existing	g Cond	lition		ı	JT4 Re	ference D	ata			Chemt	tronics F	Referen	ce Data	a		Design	1			Monitori	ng Baseli	ne	
Dimension and Substrate - Riffle Only		LL	UL	Eq.	Min	Mean	Med	Max	SD ⁵ n	Min	Mea	n Me	d Max	SD ⁵	n	Min	Mean	Med	Max	SD⁵	n	Min	Med	Max	Min	Mean	Med	Max	SD ⁵	n
Bankfull Width (ft)					5.6	6.8		9.4		5.1	6.8		9.4			11.3	14.0		15.8			6.6	7.1	7.6	10.3	12.0	12.1	13.7		3.0
Floodprone Width (ft)					11.0	12.0		19.0		15.0			28.0			16.5	19.0		25.0			25.0	50.0	75.0	100.0	100.0	100.0	100.0		3.0
Bankfull Mean Depth (ft)					0.4	0.5		0.6		0.8	0.9		1.0			0.4	0.6		1.2			0.5	0.5	0.5	0.6	0.7	0.7	0.7		3.0
¹ Bankfull Max Depth (ft)					0.6	0.8		0.9		1.3	1.4		1.5			1.7	1.8		2.0			0.6	8.0	0.9	1.2	1.4	1.4	1.7		3.0
Bankfull Cross Sectional Area (ft²)					3.6	3.6		3.6		6.2	6.2		6.2			16.7	16.7		16.7			3.6	3.6	3.6	6.4	8.3	8.3	10.2		3.0
Width/Depth Ratio					8.7	12.8		24.5		5.1	7.6		11.8			8.1	12.0		14.8			12.0	14.0	16.0	16.6	17.5	17.7	18.3		3.0
Entrenchment Ratio					1.8	2.0		2.0		2.7	2.9		3.0			16.5			22.0			3.8	7.0	9.9	7.3	8.4	8.2	9.7		3.0
¹ Bank Height Ratio					2.3	2.7		3.8		1.0	1.0		1.0			1.0	1.0		1.0			1.0	1.0	1.3	1.0	1.0	1.0	1.0		3.0
Profile																														
Riffle Length (ft)										L															7.8	15.9	13.8	32.4	7.2	27.0
Riffle Slope (ft/ft)					No dis	tinct rep	etitive pa	ttern of i	riffles and pools	0.0090	0.040	0	0.0754	•		0.0156	0.0228	3	0.0468			0.0144	0.0231	0.0433		0.0098	0.0101	0.0231	0.0056	27.0
Pool Length (ft)							staighte			- 20	1	4				4.0	1 24		2.2			0.7	4.0	10	6.8	12.2	12.4	19.9	2.6	27.0
Pool Max depth (ft)					ı		Ū	Ü		2.0	2.3 37.1		2.6 45.8			1.9			2.3			0.7	1.0	1.0	24.4	20.0	20.6	40.0	6.0	26.0
Pool Spacing (ft)										21.3	37.1		45.6			28.8	50.7		70.7			21.3	28.4	49.7	24.1	32.2	30.6	48.2	6.9	20.0
Pattern Channel Beltwidth (ft)				_						15.4	19.0		25.2	т —		13.4	14.7	т —	16.6		т —	10.6	21.3	28.4	10.6	1	21.3	28.4		
Radius of Curvature (ft)					ŀ					8.7	15.8		29.4		-	0.8	2.2	+	3.3			14.2		28.4	14.2	 	21.3	28.4		
Radius of Curvature (it) Rc:Bankfull width (ft/ft)				+	No dis				riffles and pools	0.7	10.0	+	20.4	1	-	0.0		+	0.0		<u> </u>	17.2	21.0	20.4	17.2	 	21.0	20.4		
Meander Wavelength (ft)					ł	due to	o staighte	ning ac	tivities	56.5	63.8		76.0	1		59.8	96.3	+	117.2			42.6	63.9	85.2	42.6	 	64.0	85.2		
Meander Wavelength (tr)				1	i					2.3	2.8		3.7		 	1.0	1.1	+	1.2		 	1.5	3.0	4.0	1.5	 	3.0	4.0		
Woulder Width Land																														
Transport parameters																														
Reach Shear Stress (competency) lb/f ²							1.	1															0.4							
Max part size (mm) mobilized at bankfull																														
Stream Power (transport capacity) W/m ²							3.	9															12.3							
Additional Reach Parameters																														
Rosgen Classification							Eg	4					Eb 4					В	4				C 4					C 4		
Bankfull Velocity (fps)							0.																3.8							
Bankfull Discharge (cfs)							13																							
Valley length (ft)							104																							
Channel Thalweg length (ft)							957			—												<u> </u>	874.0		<u> </u>			374.0		
Sinuosity (ft)							1.						1.2						.0				1.2		—			1.2		
Water Surface Slope (Channel) (ft/ft)	<u> </u>				<u> </u>		0.00	J46		╀		(0.0226					0.0	167				0.0144		—		0	.0063		
BF slope (ft/ft)					—					+-															⊢—					
³ Bankfull Floodplain Area (acres)					Ь—					╀															—					
⁴ % of Reach with Eroding Banks										╀																				
Channel Stability or Habitat Metric					Ь—																									
Biological or Other																														

^{1 =} The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile. 2 = For projects with a proximal USGS gauge in-line with the project reach (added bankfull verification - rare).

^{3.} Utilizing XS measurement data produce an estimate of the bankfull floodplain area in acres, which should be the area from the top of bank to the toe of the terrace riser/slope.

^{4 =} Proportion of reach exhibiting banks that are eroding based on the visual survey for comparison to monitoring data; 5. Of value/needed only if the n exceeds 3

Table 12a. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions)
Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 1 Lower (572 feet)

Parameter	Pre-Existing Condition	Reference Reach(es) Data	Reference Reach(es) Data	Design	As-built/Baseline
¹ Ri% / Ru% / P% / G% / S%	6				49 5 39 10
¹ SC% / Sa% / G% / C% / B% / Be%	6				
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)					
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10					
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0					

Table 12b. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 1 Upper (436 feet)

Parameter	Pre-Ex	isting Condition	Referen	ce Reach(es) Data	Referenc	e Reach(es) Data	Design	As-k	uilt/Baseline	
¹ Ri% / Ru% / P% / G% / S%								58 5 2	6 7	
¹ SC% / Sa% / G% / C% / B% / Be%										
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)										
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10										
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0										

Table 12c. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 3 Lower (873 feet)

Parameter	Pr	re-Exi	isting C	Conditio	on		Refe	rence l	Reach	(es) Data		Refe	rence	Reac	h(es) Da	а		D	esign			As-	built/B	aseline	9	
¹ Ri% / Ru% / P% / G% / S%																					55	3	32 1	0		
¹ SC% / Sa% / G% / C% / B% / Be%																										
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)																										
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10																										
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0																										

Shaded cells indicate that these will typically not be filled in.

- 1 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave
- 2 = Entrenchment Class Assign/bin the reach footage into the classes indicated and provide the percentage of the total reach footage in each class in the table. This will result from the measured cross-sections as well as visual estimates
- 3 = Assign/bin the reach footage into the classes indicated and provide the percentage of the total reach footage in each class in the table. This will result from the measured cross-sections as well as the longitudinal profile

Footnotes 2,3 - These classes are loosley built around the Rosgen classification and hazard ranking breaks, but were adjusted slightly to make for easier assignment to somewhat coarser bins based on visual estimates in the field such that measurement of every segment for ER would not be necessary.

The intent here is to provide the reader/consumer of design and monitoring information with a good general sense of the extent of hydrologic containment in the pre-existing and the rehabilitated states as well as comparisons to the reference distributions.

ER and BHR have been addressed in prior submissions as a subsample (cross-sections as part of the design measurements), however, these subsamples have often focused entirely on facilitating design without providing a thorough pre-constrution distribution of these parameters, leaving the reader/consumer with a sample that is weighted heavily on the stable sections of the reach. This means that the distributions for these parameters should include data from both the cross-section measurements and the longitudinal profile and in the case of ER, visual estimates. For example, the typical longitudinal profile permits sampling of the BHR at riffles beyond those subject to cross-sections and therefore can be readily integrated and provide a more complete sample distribution for these parameters, thereby providing the distribution/coverage necessary to provide meaningful comparisons.

Table 12d. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions)
Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 3 Upper (1995 feet)

Parameter	Pre-Existing Condition	Reference Reach(es) Data	Reference Reach(es) Data	Design	As-built/Baseline
¹ Ri% / Ru% / P% / G% / S%	6				52 6 30 12
¹ SC% / Sa% / G% / C% / B% / Be%	6				
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)					
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10	0				
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0	0				

Table 12e. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 4 (278 feet)

Parameter	Pre-Existing Condition	Reference Reach(es) Data	Reference Reach(es) Data	Design	As-built/Baseline
¹ Ri% / Ru% / P% / G% / S%					52 3 31 9
¹ SC% / Sa% / G% / C% / B% / Be%					
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)					
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10					
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0					

Table 12f. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 5 (1024 feet)

Parameter	Pre-Existing Condition	Reference Reach(es) Data	Reference Reach(es) Data	Design	As-built/Baseline
¹ Ri% / Ru% / P% / G% / S%					51 4 34 11
¹ SC% / Sa% / G% / C% / B% / Be%					
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)					
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10					
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0					

Shaded cells indicate that these will typically not be filled in.

- 1 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave
- 2 = Entrenchment Class Assign/bin the reach footage into the classes indicated and provide the percentage of the total reach footage in each class in the table. This will result from the measured cross-sections as well as visual estimates
- 3 = Assign/bin the reach footage into the classes indicated and provide the percentage of the total reach footage in each class in the table. This will result from the measured cross-sections as well as the longitudinal profile

Footnotes 2,3 - These classes are loosley built around the Rosgen classification and hazard ranking breaks, but were adjusted slightly to make for easier assignment to somewhat coarser bins based on visual estimates in the field such that measurement of every segment for ER would not be necessary.

The intent here is to provide the reader/consumer of design and monitoring information with a good general sense of the extent of hydrologic containment in the pre-existing and the rehabilitated states as well as comparisons to the reference distributions.

ER and BHR have been addressed in prior submissions as a subsample (cross-sections as part of the design measurements), however, these subsamples have often focused entirely on facilitating design without providing a thorough pre-constrution distribution of these parameters, leaving the reader/consumer with a sample that is weighted heavily on the stable sections of the reach. This means that the distributions for these parameters should include data from both the cross-section measurements and the longitudinal profile and in the case of ER, visual estimates. For example, the typical longitudinal profile permits sampling of the BHR at riffles beyond those subject to cross-sections and therefore can be readily integrated and provide a more complete sample distribution for these parameters, thereby providing the distribution/coverage necessary to provide meaningful comparisons.

Table 12g. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 6 (1265 feet)

Parameter	Pre-Existing Co	ndition	Refere	nce Reach	es) Data	Refe	erence	Reach((es) Dat	а	Des	ign				As-bui	ilt/Basel	line	
¹ Ri% / Ru% / P% / G% / S%														50	6	31	10		
¹ SC% / Sa% / G% / C% / B% / Be%																			
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)																			
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10																			
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0																			

Table 12h. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 7 (1844 feet)

Parameter	Pre-Existing (Condition	Refere	nce Reach	(es) Data		Referen	ce Rea	ch(es) [Data		Desig	n			As-bu	ilt/Base	eline	
¹ Ri% / Ru% / P% / G% / S%														61	5	25	7		
¹ SC% / Sa% / G% / C% / B% / Be%																			
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)																			
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10																			
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0																			

Table 12i. Baseline Stream Data Summary (Substrate, Bed, Bank, and Hydrologic Containment Parameter Distributions) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 8 (760 feet)

Parameter	Pre-Existing Condition	Reference Reach(es) Data	Reference Reach(es) Data	Design	As-built/Baseline
¹ Ri% / Ru% / P% / G% / S%					49 5 38 9
¹ SC% / Sa% / G% / C% / B% / Be%					
¹ d16 / d35 / d50 / d84 / d95 / di ^p / di ^{sp} (mm)					
² Entrenchment Class <1.5 / 1.5-1.99 / 2.0-4.9 / 5.0-9.9 / >10					
³ Incision Class <1.2 / 1.2-1.49 / 1.5-1.99 / >2.0					

Shaded cells indicate that these will typically not be filled in.

- 1 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave
- 2 = Entrenchment Class Assign/bin the reach footage into the classes indicated and provide the percentage of the total reach footage in each class in the table. This will result from the measured cross-sections as well as visual estimates
- 3 = Assign/bin the reach footage into the classes indicated and provide the percentage of the total reach footage in each class in the table. This will result from the measured cross-sections as well as the longitudinal profile

Footnotes 2,3 - These classes are loosley built around the Rosgen classification and hazard ranking breaks, but were adjusted slightly to make for easier assignment to somewhat coarser bins based on visual estimates in the field such that measurement of every segment for ER would not be necessary.

The intent here is to provide the reader/consumer of design and monitoring information with a good general sense of the extent of hydrologic containment in the pre-existing and the rehabilitated states as well as comparisons to the reference distributions.

ER and BHR have been addressed in prior submissions as a subsample (cross-sections as part of the design measurements), however, these subsamples have often focused entirely on facilitating design without providing a thorough pre-constrution distribution of these parameters, leaving the reader/consumer with a sample that is weighted heavily on the stable sections of the reach. This means that the distributions for these parameters should include data from both the cross-section measurements and the longitudinal profile and in the case of ER, visual estimates. For example, the typical longitudinal profile permits sampling of the BHR at riffles beyond those subject to cross-sections and therefore can be readily integrated and provide a more complete sample distribution for these parameters, thereby providing the distribution/coverage necessary to provide meaningful comparisons.

				Ta	able 1																			tions)							
	Indiatum used																															
Based on fixed baseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+				
Record elevation (datum) used																																\Box
Bankfull Width (ft)	11.9	13.4	12.2	12.6				8.2	8.2	7.9	7.6				9.2	9.3	10.0	10.7				10.6	11.8	11.7	14.4							
Floodprone Width (ft)	100.0	100.0	100.0	100.0				NA	NA	NA	NA				NA	NA	NA	NA				100.0	100.0	100.0	100.0							
Bankfull Mean Depth (ft)	1.1	1.0	1.0	1.0				1.0	1.0	1.0	1.1				0.8	0.8	0.7	0.7				0.9	0.8	8.0	0.7							
Bankfull Max Depth (ft)	2.1	1.9	2.0	2.0				1.9	1.9	2.0	1.9				1.4	1.5	1.6	1.7				1.7	1.7	1.7	1.6							
								1.9	1.9	1.9	1.9				1.4	1.5	1.7	1.6				1.7	2.0	1.8	1.3							
Bankfull Cross Sectional Area (ft ²)	12.8	12.8	12.8	12.8				8.3	8.3	8.3	8.3				7.4	7.4	7.4	7.4				9.4	9.4	9.4	9.4							
Bankfull Width/Depth Ratio	11.1	14.0	11.7	12.5				NA	NA	NA	NA				NA	NA	NA	NA				11.9	14.8	14.7	21.9							
Bankfull Entrenchment Ratio	8.4	7.5	8.2	7.9				NA	NA	NA	NA				NA	NA	NA	NA				9.5	8.5	8.5	7.0							
Bankfull Bank Height Ratio	1.0	1.0	0.9	1.0				1.0	1.0	1.0	1.0				1.0	1.0	1.1	1.0				1.0	1.2	1.0	0.8							
Cross Sectional Area between end pins (ft ²)	46.9	42.4	43.2	44.2				22.5	22.5	21.7	21.6				23.2	23.4	23.3	22.7				15.8	15.6	15.2	15.6							
d50 (mm)																																

				Ta	able 1	3b. N	lonito	ring	Data -	- Dim	ensio	nal Mo	orpho	ology	Sum	mary	(Dim	ensio	nal P	aram	eters	– Cro	ss Se	ctions)							
						Р	roject	t Nam	e/Nur	nber	(Warr	en Wi	lson/	10001	9) :	Segm	ent/F	Reach	: UT	1 Up	per (4:	6 fee	t)									- 1
	Midth (ff) 8.5 9.0 9.2 9.6 6.2 9.0 7.2 6.6 10.0 11.8 13.9 13.4 9.6 10.0 8.9 10.6 Midth (ff) 100.0 100.																															
Based on fixed baseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	4 MY	75 MY	- Base	MY1	MY2	MY3	MY4	MY5	MY+				
Record elevation (datum) used	i																															
Bankfull Width (ft)	8.5	9.0	9.2	9.6				6.2	9.0	7.2	6.6				10.0	11.8	13.9	13.4				9.6	10.0	8.9	10.6							
Floodprone Width (ft)	100.0	100.0	100.0	100.0				NA	NA	NA	NA				NA	NA	NA	NA				100.	100.0	100.0	100.0							
Bankfull Mean Depth (ft)	0.5	0.5	0.5	0.4				0.6	0.4	0.5	0.6				0.9	0.8	0.6	0.7				0.7	0.7	0.7	0.6							
Bankfull Max Depth (ft)	0.8	1.0	1.0	1.1				1.3	1.1	1.2	1.4				2.3	1.8	1.8	1.7				1.4	1.4	1.5	1.3							
Low Bank Height (ft)	0.8	1.0	1.0	1.2				1.3	1.1	1.2	1.3				2.3	1.8	1.7	1.3				1.4	1.4	1.5	1.3							
Bankfull Cross Sectional Area (ft ²)	4.3	4.3	4.3	4.3				3.8	3.8	3.8	3.8				9.0	9.0	9.0	9.0				6.6	6.6	6.6	6.6							
Bankfull Width/Depth Ratio	16.9	18.8	19.4	21.5				NA	NA	NA	NA				NA	NA	NA	NA				14.0	15.2	12.1	17.2							
Bankfull Entrenchment Ratio	11.8	11.1	10.9	10.4				NA	NA	NA	NA				NA	NA	NA	NA				10.4	10.0	11.2	9.4							
Bankfull Bank Height Ratio				1.1				1.0	1.0		0.9				1.0	_	_					1.0		1.0	1.0							
Cross Sectional Area between end pins (ft ²)	11.6	13.5	14.1	12.6				14.1	18.1	18.3	17.4				17.1	13.6	15.6	15.0				10.3	9.6	12.5	12.5							
d50 (mm))																															

^{1 =} Widths and depths for annual measurements will be based on the baseline bankfull datum regardless of dimensional/depositional development. Input the elevation used as the datum, which should be consistent and based on the baseline datum established. If the performer has inherited the project and cannot acquire the datum used for prior years this must be discussed with EEP. If this cannot be resolved in time for a given years report submission a footnote in this should be included that states: "It is uncertain if the monitoring datum has been consistent over the monitoring history, which may influence calculated values. Additional data from a prior performer is being acquired to provide confirmation. Values will be recalculated in a future submission based on a consistent datum if determined to be necessary."

				Ta	able 1															ramet				tions)									
	Project Name/Number (Warren Wilson/10019) Segment/Reach: UT 3 Lower (873 feet) Segment/Rea															_																		
Based on fixed baseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+						
Record elevation (datum) used																																		
Bankfull Width (ft)	23.5	31.6	31.9	32.0				13.8	11.1	10.4	9.4				14.5	21.0	21.6	17.2				17.6	23.8	18.2	26.6									
Floodprone Width (ft)	100.0	100.0	100.0	100.0				NA	NA	NA	NA				NA	NA	NA	NA				100.0	100.0	100.0	100.0									
Bankfull Mean Depth (ft)	1.2	0.9	0.9	0.8				1.0	1.5	1.6	1.8				0.8	1.0	1.0	1.2				0.9	0.7	0.9	0.6									
		2.0	2.0	2.1				2.5	2.7	2.7	2.4				2.6	2.3	2.4	2.4				1.4	1.4	1.4	1.5									
Low Bank Height (ft)	2.1	2.0	2.0	2.0				2.5	2.6	2.8	2.5				2.6	2.3	2.3	2.3				1.4	1.4	1.4	1.5									
Bankfull Cross Sectional Area (ft ²)	27.2	27.2	27.2	27.2				16.7	16.7	16.7	16.7				21.3	21.3	21.3	21.3				17.0	17.0	17.0	17.0									
Bankfull Width/Depth Ratio	20.2	36.7	37.4	37.7				NA	NA	NA	NA				NA	NA	NA	NA				18.1	33.3	19.4	41.5									
Bankfull Entrenchment Ratio	4.3	3.2	3.1	3.1				NA	NA	NA	NA				NA	NA	NA	NA				5.7	4.2	5.5	3.8									
Bankfull Bank Height Ratio				1.0				1.0	1.0	1.0	1.0				1.0	1.0	1.0	1.0				1.0	1.0	1.0	1.0									
Cross Sectional Area between end pins (ft ²)	45.6	46.3	37.5	31.5				31.1	31.9	43.5	42.4				43.1	39.4	39.6	35.9				39.2	38.1	35.3	38.7									
d50 (mm)																																		
		C	Cross S	ection	6 (Riffl	e)			-	Cross (Section	7 (Poo	ıl)			(Cross S	ection	8 (Riffl	le)			(cross S	ection	9 (Riff	le)		(Cross S	ection	10 (Po	ol)	

				Ta	ble 1																ers –			tions)										\neg
						Pr	oject	Name	/Num	nber (Warre	n Wil	son/1	00019	9) S	egme	nt/Re	ach: I	UT 3 (Uppei	r (199	5 feet)												
		(Cross S	Section	5 (Poo	ol)			C	ross S	ection	6 (Riffle	e)			(ross S	ection	7 (Riffle	e)			(ross S	Section	8 (Poc	ol)			С	ross S	ection	9 (Riffle	e)	
Based on fixed baseline bankfull elevation ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used																																		\Box	
Bankfull Width (ft)	14.3	13.9	12.8	13.5				18.7	19.7	20.1	21.6				14.2	24.8	21.1	17.9				16.0	14.9	14.5	14.0				16.9	27.7	24.4	29.3			
Floodprone Width (ft)	NA	NA	NA	NA				100.0	100.0	100.0	100.0				100.0	100.0	100.0	100.0				NA	NA	NA	NA				100.0	100.0	100.0	100.0			
Bankfull Mean Depth (ft)	1.3	1.4	1.5	1.4				1.1	1.1	1.1	1.0				1.0	0.5	0.6	0.8				1.3	1.4	1.4	1.5				1.0	0.6	0.7	0.6			
Bankfull Max Depth (ft)	2.2	2.4	2.7	2.6				1.9	1.9	1.9	2.0				1.8	1.4	1.7	1.8				2.9	2.7	2.8	2.8				1.6	1.5	1.6	1.6			
5 (7		2.3	2.8	2.4				1.9	1.9	2.0	1.8				1.8	1.4	1.7	1.8				2.9	2.7	3.1	2.5				1.6	1.5	1.6	1.6			
Bankfull Cross Sectional Area (ft ²)	19.1	19.1	19.1	19.1				21.4	21.4	21.4	21.4				13.6	13.6	13.6	13.6				20.8	20.8	20.8	20.8				16.4	16.4	16.4	16.4		ш	
Bankfull Width/Depth Ratio	NA	NA	NA	NA				16.3	18.1	19.0	21.9				15.0	45.2	32.8	23.5				NA	NA	NA	NA				17.4	46.8	36.3	52.1			
Bankfull Entrenchment Ratio	NA	NA	NA	NA				5.4	5.1	5.0	4.6				7.0	4.0	4.7	5.6				NA	NA	NA	NA				5.9	3.6	4.1	3.4			
Bankfull Bank Height Ratio		1.0	1.0	0.9				1.0	1.0	1.0	0.9				1.0	1.0	1.0	1.0				1.0	1.0	1.1	0.9				1.0	1.0	1.0	1.0			
Cross Sectional Area between end pins (ft ²)	61.5	66.1	66.6	61.0				31.0	29.9	29.9	31.7				29.5	23.1	21.4	22.4				28.5	30.5	38.0	37.1				28.5	22.9	21.0	23.6		\Box	
d50 (mm)																																			
				ection							ection '							ection 1		-,															
Based on fixed baseline bankfull elevation ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+														
Record elevation (datum) used																																			
Bankfull Width (ft)	16.4	15.8	13.4	13.6				20.7	22.9	24.7	26.4				14.6	13.4	14.1	16.3																	
Floodprone Width (ft)	NA	NA	NA	NA				NA	NA	NA	NA				100.0	100.0	100.0	100.0																	
Bankfull Mean Depth (ft)	1.0	1.1	1.2	1.2				1.4	1.3	1.2	1.1				1.1	1.2	1.1	1.0																	
Bankfull Max Depth (ft)	2.5	2.7	3.0	3.0				3.3	3.0	2.8	2.9				1.9	2.5	2.2	2.2																	
Low Bank Height (ft)	2.5	2.7	3.0	2.9				3.3	2.9	2.7	2.7				1.9	2.5	2.3	2.2																	
Bankfull Cross Sectional Area (ft²)	16.7	16.7	16.7	16.7				28.8	28.8	28.8	28.8				16.0	16.0	16.0	16.0																	
Bankfull Width/Depth Ratio	NA	NA	NA	NA				NA	NA	NA	NA				13.3	11.2	12.5	16.6															\Box	\Box	
Bankfull Entrenchment Ratio	NA	NA	NA	NA				NA	NA	NA	NA				6.8	7.5	7.1	6.1																	
Bankfull Bank Height Ratio		1.0	1.0	1.0				1.0	1.0	1.0	0.9				1.0	1.0	1.0	1.0																	
Cross Sectional Area between end pins (ft²)	29.3	25.4	30.2	27.8				52.7	50.2	49.0	43.6				36.8	37.4	40.8	36.5																	
d50 (mm)																																		\Box	

^{1 =} Widths and depths for annual measurements will be based on the baseline bankfull datum regardless of dimensional/depositional development. Input the elevation used as the datum, which should be consistent and based on the baseline datum established. If the performer has inherited the project and cannot acquire the datum used for prior years this must be discussed with EEP. If this cannot be resolved in time for a given years report submission a footnote in this should be included that states: "It is uncertain if the monitoring datum has been consistent over the monitoring history, which may influence calculated values. Additional data from a prior performer is being acquired to provide confirmation. Values will be recalculated in a future submission based on a consistent datum if determined to be necessary."

				Ta	able 1	3e. N					ensio ber (V								Cross	Sec	tions)	1					
		-	Cross S	Section	1 (Poo	ol)			(Cross	Section	2 (Riff	e)			_											
Based on fixed baseline bankfull elevation		MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+													
Record elevation (datum) used																											
Bankfull Width (ft)	12.0	11.0	11.0	11.4				14.0	20.5	16.1	15.0																
Floodprone Width (ft)	NA	NA	NA	NA				100.0	100.0	100.0	100.0																
Bankfull Mean Depth (ft)	1.0	1.1	1.1	1.0				1.0	0.6	0.8	0.9																
Bankfull Max Depth (ft)				2.1				1.6	1.6	1.8	1.7																
Low Bank Height (ft)	1.9	1.9	2.1	2.1				1.6	1.6	1.8	1.8																
Bankfull Cross Sectional Area (ft²)	11.8	11.8	11.8	11.8				13.3	13.3	13.3	13.3																
Bankfull Width/Depth Ratio	NA	NA	NA	NA				14.7	31.6	19.6	16.8																
Bankfull Entrenchment Ratio	NA	NA	NA	NA				7.2	4.9	6.2	6.7																
Bankfull Bank Height Ratio	1.0	1.0	1.1	1.0				1.0	1.0	1.0	1.1																
Cross Sectional Area between end pins (ft ²)	21.1	21.6	22.9	22.3				18.6	18.5	19.2	15.9																
d50 (mm)																											

				Ta	able 1	13f. N															ters –		s Sec	tions)										
							Proj	ect N	ame/l	Numb	er (W	arren	Wilso	n/100	019)	Seç	gment	t/Read	ch: U	T 5 (1	024 fe	et)													
			Cross S	Section	1 (Poc	ol)			(Cross S	ection	2 (Riffle	e)				Cross S	Section	3 (Po	ol)				Cross S	ection	4 (Riff	le)			-	Cross S	Section	5 (Poo	ıl)	
Based on fixed baseline bankfull elevation ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used																																			
Bankfull Width (ft)	11.1	11.7	11.1	12.1				9.9	10.5	10.0	9.3				8.6	9.0	9.0	12.3				21.1	21.0	21.2	21.1				7.8	8.4	7.4	5.6			
Floodprone Width (ft)		NA	NA	NA				100.0	100.0						NA	NA	NA	NA				100.0	100.0	100.0					NA	NA	NA	NA			
Bankfull Mean Depth (ft)		1.3	1.4	1.3				8.0	0.8	0.8	0.8				0.9	0.8	0.8	0.6				0.3	0.3	0.3	0.3				1.1	1.0	1.2	1.6	<u> </u>	ш	
Bankfull Max Depth (ft)		2.6	2.5	2.6				1.5	1.3	1.5	1.7				1.5	1.6	1.6	1.7				1.2	1.4	1.5	1.4				1.8	1.9	1.9	2.1	Ш'	ш	
Low Bank Height (ft)	_	2.6	2.6	2.5				1.5	1.3	1.5	1.8				1.5	1.5	1.6	1.6				1.2	1.4	1.3	1.3				1.8	2.0	2.1	2.1	└	\sqcup	
Bankfull Cross Sectional Area (ft²)				15.3				7.9	7.9	7.9	7.9				7.4	7.4	7.4	7.4				7.3	7.3	7.3	7.3				8.7	8.7	8.7	8.7	₩	\sqcup	
Bankfull Width/Depth Ratio	_	NA	NA	NA		—		12.5	14.0	_	_	\vdash		╙	NA	NA	NA	NA		_		61.0		61.2		_	_		NA	NA	NA	NA	—'	oxdot	
Bankfull Entrenchment Ratio	_	NA	NA	NA		—		10.1	9.5	_	10.7	\vdash		╙	NA	NA	NA	NA	_	_		4.7	4.8	4.7	4.7	<u> </u>			NA	NA	NA	NA	—'	igwdown	—
Bankfull Bank Height Ratio		1.0		1.0	_	-		1.0	1.0		1.1	\vdash		╙	1.0	0.9	1.0	1.0	_	_		1.0	1.0	0.9	0.9			_	1.0	1.1	1.1	1.0	—′	$\vdash \vdash$	—
Cross Sectional Area between end pins (ft²)	22.2	23.7	23.7	24.4		_		13.4	13.8	12.2	12.4				10.7	11.2	9.4	8.0	_			6.2	7.3	7.3	6.3				19.7	20.9	22.2	17.6	₩	\vdash	
d50 (mm)		يسا		Ц.,	0 /5:55	<u> </u>		-				l		L							<u> </u>	┡							—						\dashv
	_				6 (Riffl		T				_					_	_	_	_	_				_		_			₩			_			\longrightarrow
Based on fixed baseline bankfull elevation ¹ Record elevation (datum) used		MY1	MY2	MY3	MY4	MY5	MY+	-	_	├	-	<u> </u>				-	-	-	-	-		_					-		₩-		₩		₩	-	—
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				.	-	-				-	_	_		_		_	_	-		-	_	_			_		_	-		—	$ldsymbol{\sqcup}$		ሥ	\vdash	-
Bankfull Width (ft)				23.0	-	-	_	-		-		_				_		-		+	-	_			_		-	-	ऻ	-	₩		$ldsymbol{\sqcup}$	\vdash	-
Floodprone Width (ft) Bankfull Mean Depth (ft)				_	-	-		├		-		-				-		-		+	-	_					-	-	—	⊢	-	_	⊢─	\vdash	-
Bankfull Mean Depth (ft) Bankfull Max Depth (ft)		0.6 1.4	0.5 1.3	0.5 1.5	├	-	 	├	-	-	-	-		\vdash		├	-	-	-	+	-			-	-	-	-	-		⊢	-	-	$ldsymbol{}$	\vdash	-
Low Bank Height (ft)	_	1.4	1.3	1.5	├	-	\vdash	├─	-	-		-		\vdash	_	\vdash		\vdash		+-	₩	_	-	_	_		\vdash	-	┈	-	\vdash	_	屵	\vdash	-
Bankfull Cross Sectional Area (ft²)	_	10.4		10.4	\vdash	\vdash		\vdash		\vdash				\vdash		\vdash		\vdash	\vdash	+-		_					\vdash	\vdash	一	\vdash	Н		\vdash	Н	-
Bankfull Width/Depth Ratio			_	51.1	t	t		T		t				\vdash				t		1	†						<u> </u>	t	\vdash	\vdash	Н		Н	\vdash	-
Bankfull Entrenchment Ratio	7.0	5.5	4.9	4.3						\vdash				\vdash						1									\vdash	$\overline{}$	\Box		-	ш	\neg
Bankfull Bank Height Ratio	1.0	0.9	0.9	1.0																											\Box		$\overline{}$		\neg
Cross Sectional Area between end pins (ft²)	20.0	18.2	17.6	14.04																															
d50 (mm)				1	г —	T				т —		т —				т —	т —	1			T								$\overline{}$	$\overline{}$	$\overline{}$		$\overline{}$		-

^{1 =} Widths and depths for annual measurements will be based on the baseline bankfull datum regardless of dimensional/depositional development. Input the elevation used as the datum, which should be consistent and based on the baseline datum established. If the performer has inherited the project and cannot acquire the datum used for prior years this must be discussed with EEP. If this cannot be resolved in time for a given years report submission a footnote in this should be included that states: "It is uncertain if the monitoring datum has been consistent over the monitoring history, which may influence calculated values. Additional data from a prior performer is being acquired to provide confirmation. Values will be recalculated in a future submission based on a consistent datum if determined to be necessary."

				Ta	ble 1	3g. N														ramet			s Sec	tions)										
			Cross S	Section	1 (Poo	ol)			C	ross S	ection	2 (Riffle)			-	Cross S	ection	3 (Poc	ol)			C	ross S	ection	4 (Riffl	e)			-	ross S	ection	5 (Riffle))	
Based on fixed baseline bankfull elevation ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used																																			_
Bankfull Width (ft)	9.0	11.2	13.5	12.9				10.2	10.6	11.2	11.2				11.5	13.9	13.5	14.5				10.1	13.6	13.3	15.2				9.5	12.7	10.1	10.7			
Floodprone Width (ft)	NA	NA	NA	NA				100.0	100.0	100.0	100.0				NA	NA	NA	NA				100.0	100.0	100.0	100.0				100.0	100.0	100.0	100.0			
Bankfull Mean Depth (ft)	0.9	0.7	0.6	0.6				0.6	0.5	0.5	0.5				0.9	0.7	0.7	0.7				0.8	0.6	0.6	0.5				0.9	0.6	0.8	8.0			
Bankfull Max Depth (ft)	1.7	1.6	1.3	1.3				0.9	0.9	0.9	1.0				1.7	1.3	1.4	1.6				1.1	1.1	1.1	1.1				1.3	1.3	1.4	1.4			
Low Bank Height (ft)	1.7	1.6	1.2	1.1				0.9	0.9	1.0	0.9				1.7	1.2	1.6	1.6				1.1	1.1	1.1	1.0				1.3	1.3	1.4	1.4			
Bankfull Cross Sectional Area (ft ²)	8.3	8.3	8.3	8.3				5.6	5.6	5.6	5.6				9.8	9.8	9.8	9.8				8.0	8.0	8.0	8.0				8.1	8.1	8.1	8.1			
Bankfull Width/Depth Ratio	NA	NA	NA	NA				18.3	20.1	22.1	22.6				NA	NA	NA	NA				12.6	23.1	22.1	29.0				11.1	19.9	12.4	14.3			
Bankfull Entrenchment Ratio	NA	NA	NA	NA				9.8	9.4	9.0	8.9				NA	NA	NA	NA				9.9	7.4	7.5	6.6				10.5	7.9	9.9	9.3			
Bankfull Bank Height Ratio	1.0	1.0	0.9	8.0				1.0	1.0	1.1	0.9				1.0	0.9	1.1	1.0				1.0	1.0	0.9	0.9				1.0	1.0	1.0	1.0			
Cross Sectional Area between end pins (ft2)	19.4	17.5	18.8	22.6				14.3	15.1	15.8	14.5				25.8	25.3	25.6	24.2				16.6	17.5	18.5	16.6				12.8	12.9	12.5	12.0			
d50 (mm)																																			
		(Cross S	Section	6 (Poo	ol)			(Cross S	Section	7 (Poo)			(Cross S	ection	8 (Riffl	le)															
Based on fixed baseline bankfull elevation ¹	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+						1								
Record elevation (datum) used																																			
Bankfull Width (ft)	9.6	13.1	11.4	12.8				13.2	13.2	16.6	16.4				11.7	13.2	15.1	14.4																	
Floodprone Width (ft)	NA	NA	NA	NA				NA	NA	NA	NA				100.0	100.0	100.0	100.0																	
Bankfull Mean Depth (ft)	0.9	0.6	0.7	0.7				0.8	0.8	0.7	0.7				0.5	0.5	0.4	0.4																	
Bankfull Max Depth (ft)	1.5	1.4	1.5	1.5				1.8	1.7	1.7	1.7				1.0	1.0	0.9	1.1																	
Low Bank Height (ft)	1.5	1.3	1.6	1.5				1.8	1.6	1.7	1.7				1.0	1.1	0.9	1.0																	
Bankfull Cross Sectional Area (ft²)	8.4	8.4	8.4	8.4				11.1	11.1	11.1	11.1				6.3	6.3	6.3	6.3																	
Bankfull Width/Depth Ratio	NA	NA	NA	NA				NA	NA	NA	NA				22.0	27.7	36.2	32.7																	
Bankfull Entrenchment Ratio	NA	NA	NA	NA				NA	NA	NA	NA				8.5	7.6	6.6	7.0																$\neg \neg$	
Bankfull Bank Height Ratio	1.0	0.9	1.1	1.0		1		1.0	0.9	1.0	1.0				1.0	1.1	1.0	0.9																一	
Cross Sectional Area between end pins (ft2)	18.5	16.9	17.9	18.3				26.5	26.5	26.7	29.6				17.4	15.5	21.2	17.6																	
d50 (mm)																																		\neg	

^{1 =} Widths and depths for annual measurements will be based on the baseline bankfull datum regardless of dimensional/depositional development. Input the elevation used as the datum, which should be consistent and based on the baseline datum established. If the performer has inherited the project and cannot acquire the datum used for prior years this must be discussed with EEP. If this cannot be resolved in time for a given years report submission a footnote in this should be included that states: "It is uncertain if the monitoring datum has been consistent over the monitoring history, which may influence calculated values. Additional data from a prior performer is being acquired to provide confirmation. Values will be recalculated in a future submission based on a consistent datum if determined to be necessary."

	Table 13h. Monitoring Data - Dimensional Morphology Summary (Dimensional Parameters - Cross Sections) Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 7 (1844 feet) Cross Section 1 (Riffle) Cross Section 2 (Pool) Cross Section 3 (Riffle) Cross Section 4 (Pool) Cross Section 5 (Riffle)																																		
		-	Cross S	Section	1 (Riff	le)	FIU	ect N			_			11/100	10 19)					_)44 IE	ei)		Cross S	ection	4 (Poo	J)			_	ross S	ection	5 (Riffle	2)	
Based on fixed baseline bankfull elevation	Base				_		MY+	Base				_		MY+	Base				_	MY5	MY+	Base						MY+	Base					,	MY+
Record elevation (datum) used																																			
Bankfull Width (ft)	12.9	15.1	14.3	13.7				14.2	18.4	18.5	18.6				13.2	14.7	14.6	13.2				11.4	12.6	11.9	12.5				11.6	12.2	12.1	11.1			
Floodprone Width (ft)	100.0	100.0	100.0	100.0				NA	NA	NA	NA				100.0	100.0	100.0	100.0				NA	NA	NA	NA				100.0	100.0	100.0	100.0			
Bankfull Mean Depth (ft)	0.8	0.7	0.8	0.8				1.3	1.0	1.0	1.0				0.8	0.7	0.7	0.8				1.1	1.0	1.1	1.0				0.6	0.6	0.6	0.6			
Bankfull Max Depth (ft)	1.3	1.3	1.3	1.4				2.1	2.2	1.9	2.0				1.3	1.2	1.2	1.2				1.8	1.8	1.8	1.8				1.1	1.1	1.3	1.2			
Low Bank Height (ft)	1.3	1.3	1.4	1.3				2.1	2.2	1.8	1.9				1.3	1.2	1.1	1.2				1.8	1.9	1.9	1.8				1.1	1.2	1.3	1.3			
Bankfull Cross Sectional Area (ft²)		10.7	10.7	10.7				18.2	18.2	18.2	18.2				9.9	9.9	9.9	9.9				13.0	12.6	13.0	13.0				7.2	7.2	7.2	7.2			
Bankfull Width/Depth Ratio	15.5	21.3	19.0	17.6				NA	NA	NA	NA				17.5	21.8	21.5	17.5				NA	NA	NA	NA				18.5	20.7	20.2	17.2			
Bankfull Entrenchment Ratio		6.6	7.0	7.3				NA	NA	NA	NA				7.6	6.8	6.9	7.6				NA	NA	NA	NA				8.6	8.2	8.3	9.0			
Bankfull Bank Height Ratio		1.0		0.9				1.0	1.0	0.9	0.9				1.0	1.0	0.9	1.0				1.0	1.1	1.0	1.0				1.0	1.1	1.1	1.0			
Cross Sectional Area between end pins (ft²)	18.6	18.6	19.5	18.3				34.1	28.0	28.4	26.5				20.9	18.6	19.6	19.6				23.6	25.9	24.5	25.3				20.3	19.9	19.8	21.0			
d50 (mm)																																			
			Cross S									7 (Poo						ection																	
Based on fixed baseline bankfull elevation ¹		MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used																																			
Bankfull Width (ft)	8.8	10.6	10.6	11.5				9.1	11.4	10.0	10.2				10.1	10.1	10.5																		
Floodprone Width (ft)	NA	NA	NA	NA				NA	NA	NA	NA				100.0		100.0	100.0																	
Bankfull Mean Depth (ft)	1.2	1.0	1.0	0.9				1.3	1.0	1.2	1.1				0.5	0.5	0.5	0.5																	
Bankfull Max Depth (ft)	1.9	1.9	2.0	2.1				2.0	1.9	2.0	2.3				0.8	1.0	0.9	1.0																	
Low Bank Height (ft)	_	1.8	1.9	_				2.0	1.8	2.1	2.3				0.8	1.2	1.0	0.9																	
Bankfull Cross Sectional Area (ft ²)	10.7	10.7	10.7	10.7				11.6	11.6	11.6	11.6				5.2	5.2	5.2	5.2																	
Bankfull Width/Depth Ratio	NA	NA	NA	NA				NA	NA	NA	NA				19.6	19.6	21.2	17.6																	
Bankfull Entrenchment Ratio		NA	NA	NA				NA	NA	NA	NA				9.9	9.9	9.5																		
Bankfull Bank Height Ratio		0.9	1.0	1.0				1.0	0.9	1.1	1.0				1.0	1.2	1.1	0.9																	
Cross Sectional Area between end pins (ft²)	17.1	16.7	15.4	15.6		<u> </u>		21.0	18.5	20.5	20.3				11.2	15.2	13.2	14.0				Ь													
d50 (mm)																																			

^{1 =} Widths and depths for annual measurements will be based on the baseline bankfull datum regardless of dimensional/depositional development. Input the elevation used as the datum, which should be consistent and based on the baseline datum established. If the performer has inherited the project and cannot acquire the datum used for prior years this must be discussed with EEP. If this cannot be resolved in time for a given years report submission a footnote in this should be included that states: "It is uncertain if the monitoring datum has been consistent over the monitoring history, which may influence calculated values. Additional data from a prior performer is being acquired to provide confirmation. Values will be recalculated in a future submission based on a consistent datum if determined to be necessary."

				Ta	able 1	13i. N	lonito	ring [Data -	Dime	nsion	nal Mo	rpho	logy \$	Sumn	nary (Dime	nsion	al Pa	ramet	ers –	Cros	s Sec	tions)										\neg
							Pro	ject N	lame/	Numb	er (W	/arren	Wils	on/10	0019) Se	gmen	t/Rea	ch: U	JT 8 (7	760 fe	et)													!
		(Cross S	ection	1 (Riff	le)			(Cross S	Section	2 (Poo	l)			(Cross S	Section	3 (Riff	le)		Ī	(Cross S	Section	4 (Pod	ol)			(cross S	ection	5 (Riffle	<u>)</u>	
Based on fixed baseline bankfull elevation	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+	Base	MY1	MY2	MY3	MY4	MY5	MY+
Record elevation (datum) used														İ		İ				i –														\neg	
Bankfull Width (ft)	13.7	15.2	12.2	14.0				11.4	13.4	14.0	15.1				12.1	12.9	10.4	12.3				10.2	11.0	11.5	13.5				10.3	10.3	11.2	11.3		\Box	
Floodprone Width (ft)	100.0	100.0	100.0	100.0				NA	NA	NA	NA				100.0	100.0	100.0	100.0				NA	NA	NA	NA				100.0	100.0	100.0	100.0		\Box	
Bankfull Mean Depth (ft)	0.7	0.7	1.0	0.7				1.2	1.0	1.0	0.9				0.7	0.6	0.8	0.7				0.9	0.8	0.8	0.7				0.6	0.6	0.6	0.6			
Bankfull Max Depth (ft)	1.7	1.3	2.0	1.5				2.0	1.9	1.9	1.8				1.4	1.4	1.5	1.4				1.7	1.6	1.7	1.7				1.2	1.2	1.0	1.1			
Low Bank Height (ft)	1.7	1.5	1.9	1.5				2.0	1.9	1.7	1.7				1.4	1.5	1.5	1.3				1.7	1.6	1.7	1.7				1.2	1.3	1.0	1.2			
Bankfull Cross Sectional Area (ft²)	_	_	_	10.2				13.9	13.9	13.9	13.9				8.3	8.3	8.3	8.3				9.1	9.1	9.1	9.1				6.4	6.4	6.4	6.4		$oldsymbol{ol}}}}}}}}}}}}}}}$	
Bankfull Width/Depth Ratio	18.3	22.7	11.7	19.1				NA	NA	NA	NA				17.7	20.0	13.0	18.4				NA	NA	NA	NA				16.6	16.6	19.4	19.9			
Bankfull Entrenchment Ratio		6.6	_	7.2				NA	NA	NA	NA			$ldsymbol{ldsymbol{ldsymbol{ldsymbol{eta}}}$	8.2		9.6	_	<u> </u>			NA	NA	NA	NA				9.7	9.7	8.9	8.8		\longrightarrow	
Bankfull Bank Height Ratio		1.2		1.0				1.0	1.0	0.9	1.0			Ь_	1.0	1.1	1.0		<u> </u>			1.0	1.0	1.0	1.0				1.0	1.1	1.1	1.1		\longrightarrow	
Cross Sectional Area between end pins (ft²)	31.1	30.5	29.6	30.8				38.2	32.0	35.3	36.1				18.8	19.6	18.9	19.7				19.8	20.6	19.2	19.3				13.5	12.2	12.6	14.2			
d50 (mm)																													↓						
			Cross S																	_															
Based on fixed baseline bankfull elevation ¹		MY1	MY2	MY3	MY4	MY5	MY+																												
Record elevation (datum) used																																			
Bankfull Width (ft)	_	14.4		14.0										$ldsymbol{ldsymbol{ldsymbol{eta}}}$																				\longrightarrow	
Floodprone Width (ft)		NA	NA	NA										$ldsymbol{ld}}}}}}$					<u> </u>																
Bankfull Mean Depth (ft)		0.9	0.9	0.9																														—	
Bankfull Max Depth (ft)		1.8	_	1.9	_	ــــــ	L			Ь—				Ь—		Ь—									<u> </u>		\vdash		Ь—		igspace			ightharpoonup	
Low Bank Height (ft)		1.8	_	1.8	┝	—	\vdash		<u> </u>	├	<u> </u>		<u> </u>	╙		\vdash	Ь—	_	Ь—		₩			<u> </u>	├	_	\vdash	-	—	<u> </u>	ш			\longrightarrow	
Bankfull Cross Sectional Area (ft²)		13.1	_	13.1	_	—				Ь—	<u> </u>	\vdash	<u> </u>	\vdash		╙	Ь—		Ь—					<u> </u>	<u> </u>	_	\vdash	_	-		ш			\longrightarrow	
Bankfull Width/Depth Ratio	_	NA	NA	NA	<u> </u>	-	<u> </u>	_		┡	<u> </u>	_		\vdash		⊢	<u> </u>	_	├	1	<u> </u>	_	_	<u> </u>	_	<u> </u>	₩	₩	Ь—		Ш			\longrightarrow	
Bankfull Entrenchment Ratio	_	NA	_	NA	├	₩	⊢	⊢		⊢	⊢	_	<u> </u>	⊢	<u> </u>	\vdash	<u> </u>	⊢	├	-	!	_	—	<u> </u>	<u> </u>	├	-	₩	⊢		\vdash			\longrightarrow	
Bankfull Bank Height Ratio		1.0		0.9	├	-	—	_		⊢—	-		<u> </u>	⊢	<u> </u>	\vdash	├	-	₩	-	-			<u> </u>	├	-	\vdash	-						\longrightarrow	
Cross Sectional Area between end pins (ft²)	25.0	24.6	26.6	25.8	-	╄	├	├		_	├	_			<u> </u>	├	-	-	├	+	╄		-	_		-	\vdash	\vdash	-						
d50 (mm)						l						l .																							

^{1 =} Widths and depths for annual measurements will be based on the baseline bankfull datum regardless of dimensional/depositional development. Input the elevation used as the datum, which should be consistent and based on the baseline datum established. If the performer has inherited the project and cannot acquire the datum used for prior years this must be discussed with EEP. If this cannot be resolved in time for a given years report submission a footnote in this should be included that states: "It is uncertain if the monitoring datum has been consistent over the monitoring history, which may influence calculated values. Additional data from a prior performer is being acquired to provide confirmation. Values will be recalculated in a future submission based on a consistent datum if determined to be necessary."

		Table 14a. Monitoring Data - Stream Reach Data Summary Project Name/Number (Warren Wilson/100019) Segment/Reach: UT 1 Lower (572 feet) Baseline MY-1 MY-2 MY-3 MY-4																																		
Parameter			Bas	eline					M.		TOJOC	, ivan	lo/Ita	111001			1113011	11000	<u> </u>	ocgii					01 (07	2 100		Y- 4			T		MY	- 5		一
		Т	•				_					ı			_		Ι ,			ī	•	•	4			T			1 4	Т		_	•			=
Dimension and Substrate - Riffle only		Mean	Med	Max	SD ⁴	n	Min	Mean	Med	Max	SD ⁴	n		Mean		Max	SD⁴	n		Mean	Med	Max	SD ⁴	n	Min	Mean	Med	Max	SD ⁴	n	Min	Mean	Med	Max	SD ⁴	n
Bankfull Width (ft)		11.22				2	11.8	11.1		12.8						12.24	<u> </u>	2	12.6		13.5	14.4		2				-	₩	╄	_	-			\longrightarrow	—
Floodprone Width (ft)	100		100	100		2	100	100	100	100		2	100	100	100			2	100		100	100		2				_	₩	₩	_	1			\longrightarrow	—
Bankfull Mean Depth (ft)						2	0.8	0.9	0.9	1		2	0.8			1.048		2	0.7	0.85	0.85	1		2				-	+	<u> </u>	_				\longrightarrow	
¹ Bankfull Max Depth (ft)		1.895				2	1.7	1.8	1.8	1.9		2	1.741	1.893		2.044		2	1.6	1.8	1.8	2		2					+	_					\longrightarrow	-
		11.07		_		2	9.4		11.1	12.8		2	9.4	11.1		12.8		2	9.4		11.1	12.8		2				-	+	┼	_	_			\longrightarrow	-
Width/Depth Ratio						2	14	-		14.8						14.65		2	12.5	17.2		21.9		2				-	+	╄	_	_			\longrightarrow	-
Entrenchment Ratio			8.944			2	7.5	8	8	8.5		_				8.525		2	7	7.45	7.45	7.9		2				-	+	_	_				\longrightarrow	
¹ Bank Height Ratio	_1_	1	1	1		2	1	1.1	1.1	1.2		2	0.9	0.977	0.977	1.0		2	0.8	0.9	0.9	1		2											\rightarrow	_
Profile																																			_	
Riffle Length (ft)																																			_	
Riffle Slope (ft/ft)																																				
Pool Length (ft)	2.416	10.68	11.19	19.43	4.772	20																														
Pool Max depth (ft)																																			_	
Pool Spacing (ft)	6.911	30.62	28.03	66.88	16.18	19																													_	
Pattern																																				
Channel Beltwidth (ft)	15		29.9																																	
Radius of Curvature (ft)	15		29.9	39.9												Patter	n data w	ill not tv	pically b	e collect	ted unles	ss visual	data. di	mensior	nal data	or profil	e data i	ndicate								
Rc:Bankfull width (ft/ft)																			,,				m baseli													
Meander Wavelength (ft)				119.6																																
Meander Width Ratio	1.5		3	4																																
Additional Reach Parameters																																				
Rosgen Classification			CI	b 4																																
Channel Thalweg length (ft)				01																											1					
Sinuosity (ft)				05																											1					\neg
Water Surface Slope (Channel) (ft/ft)				163																											\top					\dashv
BF slope (ft/ft)																																				一
³ Ri% / Ru% / P% / G% / S%					l									<u> </u>			1									1		1	1							
³ SC% / Sa% / G% / C% / B% / Be%															t				1	t								t	t		\top	 			\dashv	-
³ d16 / d35 / d50 / d84 / d95 /																												t	t			1			\dashv	
² % of Reach with Eroding Banks				0																								1	1		_					
Channel Stability or Habitat Metric				_																											\top					-
Biological or Other																																				\neg

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

		Project Name/													4b. N	lonit	oring	Data	ı - S	trear	n Rea	ach D	ata S	umm	ary												\neg
										ı	Projec	t Nan														er (4	36 fee	t)									
Parameter			Bas	eline					M`	Y-1					N	IY-2						MY	′- 3					M	Y- 4					M)	/- 5		
Dimension and Substrate - Riffle only	Min	Mean	Med	Max	SD⁴	n		Mean			SD⁴	n					x SD					Med		SD⁴	n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)						2			9.5				8.924									10.1				_				_	4	_					└
Floodprone Width (ft)		100				2	100 0.5		100 0.6	100 0.7			100 0.472					2								_	-			+	+	₩					-
Bankfull Mean Depth (ft)	0.503	0.593	0.593	4.004	-	2	0.5	0.6 1.2												0.4	1.2	0.5				-	-	+	+	+	+		-				-
¹ Bankfull Max Depth (ft)	0.831	1.111	1.111	1.391	-	2	1			1.4			0.966					2				1.2	1.3			_		-	+	+-	_		_				1
Bankfull Cross Sectional Area (ft²)	4.276	5.421	5.421	6.566		2	4.3	5.5		6.6		2			5.45			2								_				4							1
Width/Depth Ratio	14.05	15.47	15.47	16.9		2	15.2			18.8			12.13					—				19.35					_		+	+	_						ـــــا
Entrenchment Ratio				11.76		2	2.8	6.4		10			10.92				_	2	_	9.4		9.9				_		-	+	_		-					1
¹ Bank Height Ratio	_1_	1	1	1		2	1	1	1	1		2	1.0	1.0	1.0	1.1	_	2		1	1.05	1.05	1.1			_	\perp		\perp	\perp	\perp	_					$ldsymbol{\sqcup}$
Profile	40.00	21 00 4 4	100.55	1 40 00	10.040	1 40													_	_						┡			_	_	_						
Riffle Length (ft)	12.63	3 22.14	20.55	43.08	8.919	12									_			_		_						_		1	1	_		_					
Riffle Slope (ft/ft)	6.021	0.040	0.039	0.000	0.014	12										_		_	_	_						-		-	_	+		1					
Pool Length (ft)	0.900	9.924	0.009	10.40	3.365	12												_	-	_						-				+		-					\vdash
Pool Max depth (ft) Pool Spacing (ft)	26./	4 37.44	3/1 8/1	52.16	8 468	11		-							+	+	_	+	+	-						-		+	+	+	+	+					\vdash
Poor Spacing (it)	20.5	1 07.44	104.04	J 32. 10	0.400	1 ''									-			+		-								1	+	+		-					
Channel Beltwidth (ft)	15	1	29.9	39.9	T	ī		1	1	ı	1		-		+		_	+	-	-						_	1	1	+	+	+	1					
Radius of Curvature (ft)	15	1		39.9		1		1							+	1															_	1					
Rc:Bankfull width (ft/ft)		1	1					1							1	Patte	ern data	will no	t typic	ally be	collecte	ed unles	ss visua	l data, d	imensio	nal data	a or prof	ile data	indicate			1					
Meander Wavelength (ft)	59.82	2	84.7	119.6																	sigr	nificant s	shifts fro	m base	line												
Meander Width Ratio			3	4																																	
Additional Reach Parameters																																					
Rosgen Classification			С	b 4																																	
Channel Thalweg length (ft)				58																																	
Sinuosity (ft)				.05																																	
Water Surface Slope (Channel) (ft/ft)			0.0)372																																	
BF slope (ft/ft)																																				_	
³ Ri% / Ru% / P% / G% / S%																																					
³ SC% / Sa% / G% / C% / B% / Be%																				T																	
³ d16 / d35 / d50 / d84 / d95 /																																					
² % of Reach with Eroding Banks				0										•	•	-												-	•	-				•	-	-	
Channel Stability or Habitat Metric																																					
Biological or Other																																					

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

													Tal	ble 1	4c. N	lonito	oring	Data	- Stı	ream	Rea	ich D	ata S	umma	ary												\neg
										F	Project	t Nan	ne/Nu	mbe	r (Wa	rren \	Wilso	n/100	019) Se	egm	ent/R	each	: UT 3	Low	er (87	73 fee	t)									
Parameter			Bas	eline					M)	Y-1					· M	Y-2			T	•		MY	'- 3					M	Y- 4					M`	/- 5		\neg
Dimension and Substrate - Riffle only		Mean							Med			n					SD⁴	n					Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)									23.7						25.03			2				29.3			2				_	_	4						igspace
Floodprone Width (ft)		100				2	0.7	100		100 1.2					100 1 0.894			2		00 7		100 0.7			2		_		-	+			_	-			\vdash
Bankfull Mean Depth (ft)						2		0.9 1.8							2 1.712					1.5					2		-	-	+	+-	+	-	-				
¹ Bankfull Max Depth (ft)						2	1.4			2.1								2				1.8	2.1		2			_	-	+	_		_				
Bankfull Cross Sectional Area (ft²)		22.1				2	17		22.1	27.2		2	17		22.1			2				22.1			2				_	_							
Width/Depth Ratio	11.88	16.06	16.06	20.24		2			26.8						28.4			2		7.7		39.6			2				╀	+	_						igwdown
Entrenchment Ratio			_	9.472		2	4.2	4.2		4.3					4.32	_	_	2	_	_	_	3.45			2			_	+	+							
¹ Bank Height Ratio	_1_	1	1	<u> 1</u>		2	1	1	1	1	$oldsymbol{\sqcup}$	2	1.0	1.0	1.0	1.0	_	2	_	1	1	1	1		2					_	_	_					igspace
Profile	16.70	21 25 22	122.02	164.05	142.70	1 15										+		+	+	_	-								-	-							
Riffle Length (ft) Riffle Slope (ft/ft)																			+		_									+							
Riffle Slope (π/π) Pool Length (ft)	11 32	2 20 36	20.28	20.020	6.40	15									+	+	+	+	+	-	-							-	+	+	_	-					
Pool Lengtn (π) Pool Max depth (ft)	11.52	2 20.30	20.20	29.23	0.43	13									+				+		-									+		_					
Pool Spacing (ft)	32 17	7 64 03	56 97	104	18 91	15	_								+	+	+	+	+	-	\rightarrow								+	+	_	1					
Pattern	<u> </u>	. 1000	100.0.	1	10.0										1	+		+	+	_	_									+							
Channel Beltwidth (ft)	23.9	T	47.9	63.8	T	I			1						1		1		┰	_	\neg									1		1					
Radius of Curvature (ft)			47.9	47.9													_										•										
Rc:Bankfull width (ft/ft)																Patte	rn data	will not	typica	ılly be c	ollecte	ed unles	s visual	l data, d	mensio	nal data	or profi	le data	indicate								
Meander Wavelength (ft)	95.8		165.7	191.5																	sıgn	iificant s	shifts fro	m basel	ine												
Meander Width Ratio	1.5		3	4																																	
Additional Reach Parameters																																					
Rosgen Classification				e 4																																	
Channel Thalweg length (ft)				60															+																		
Sinuosity (ft)				1.1															4																		
Water Surface Slope (Channel) (ft/ft))129															+													-					
BF slope (ft/ft) ³ Ri% / Ru% / P% / G% / S%		1		 T	1			1	1	1				1	1		1		-		Т			1			1	1	1	1		_	1	1	1	1	
3SC% / Sa% / G% / C% / B% / Be%											\vdash				+	1	+		+		-+							1	+	+		-			-		
³ d16 / d35 / d50 / d84 / d95 /											\vdash			\vdash	+	+	+		+	+	\dashv			-			+	+-	+	+-			1	 	-		
² % of Reach with Eroding Banks				0							ш								+								1	1	_			1			<u> </u>		
Channel Stability or Habitat Metric																			+													1					
Biological or Other																			+																		

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

													Tal	ole 14	4d. M	onito	ring [ata -	Strea	ım Re	ach D	ata S	umma	ary												\neg
										Р	roject	t Nam	ie/Nui	mber	(War	ren W	/ilson	1000°	19)	Segm	ent/R	each:	UT 3	Uppe	r (19	95 fe	et)									,
Parameter			Bas	eline					M)	Y-1					M	Y-2					M	′- 3					М	Y- 4					MY	- 5		
Dimension and Substrate - Riffle only	Min	Mean	Med	Max	SD⁴	n	Min	Mean				n			Med			n		Mean				n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)								11.7									4.3	4		21.28				4						_						
Floodprone Width (ft) Bankfull Mean Depth (ft)		100				4	0.5	100 0.6			0.35	4			100		0.26	4		100 0.85			0.19	4		-	+	+	+	+						
Banktuli Mean Deptin (π) ¹ Bankfull Max Depth (ft)						4	1	1.5		2.5	0.55	4					0.26	4	1.6	1.9	1.9		0.19	4			1	+	+	+						
								16.2				<u> </u>			1.023			4		16.85				4			-	-	+							
Bankfull Cross Sectional Area (ft²) Width/Depth Ratio	13.55	16.84	15.63	21.4 17.20	3.291	4		16.2			18.33	4					11.26	4		28.53									+							
Width/Depth Ratio Entrenchment Ratio							2.8		5.5		1.75	4			4.846			4		4.93						-	_	+	+-	+						
		1	_	1	_	4	1	1		1	0	4	1.0	1		1.0		4		0.975			0.05				1		+	1						
¹ Bank Height Ratio	<u>'</u>	<u> </u>	' '	<u> </u>	_ <u> </u>	4		'	'	'		4	1.0	_ '	1.0	1.0	0.0	4	0.9	0.975	<u> </u>	'	0.05	-												
Profile Riffle Length (ft)	8 655	51.33.73	1 29 5	1 79 65	118.55	34		Г					_		+		+			+	-							+	+	-						
Riffle Slope (ft/ft)	0.008	3 0.018	0.018	0.034	0.006	34									1						 								+							
Pool Length (ft)	10.08	19.26	17.43	42.65	6.576	34									1													+	+							
Pool Max depth (ft)		1			1																								1							
Pool Spacing (ft)	33.58	65.36	61.27	108	17.84	33																														
Pattern				•		•			•	•																										
Channel Beltwidth (ft)				63.8																																
Radius of Curvature (ft)	31.9		47.9	63.8																																
Rc:Bankfull width (ft/ft)			l													Patter	rn data w	ill not ty	pically b	e collec sid	ted unle: nificant :	ss visual	l data, d m hasel	imensio ine	nal data	or profi	le data	indicate								
Meander Wavelength (ft)				191.5	<u> </u>															319	, illiodite	3111113 110	JIII DUSCI													
Meander Width Ratio	1.5		3	4																																
Additional Reach Parameters																																				
Rosgen Classification			C	e 4			_																													
Channel Thalweg length (ft)				195			_																													
Sinuosity (ft)				1.1																																
Water Surface Slope (Channel) (ft/ft)			0.0)139																																
BF slope (ft/ft)																																				
³ Ri% / Ru% / P% / G% / S%																																				
³ SC% / Sa% / G% / C% / B% / Be%																																				
³ d16 / d35 / d50 / d84 / d95 /																i i													1							
² % of Reach with Eroding Banks				0											-	-	-			!	-		!				-	-								
Channel Stability or Habitat Metric				-																																
Biological or Other																																				

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

																	oring																				\neg
											Pro	oject	Name	/Nun			en Wi	lson/	1000	19)	Seg			ich: L	JT 4 (278 f	eet)										
Parameter			Bas	eline					M)	Y-1					M	IY-2						MY-	- 3					M	Y- 4					M)	/- 5		
					, ,																									•							
Dimension and Substrate - Riffle only		Mean				n		Mean				n					⟨ SD⁴	n		n Me				SD⁴	n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)						1		20.5				1			16.13			1	_	98 14.					1					_	_						↓
Floodprone Width (ft)		100				1	100		100			1			100			1		0 10					1			-	+	+							\longleftarrow
Bankfull Mean Depth (ft)						1	0.6	0.6		0.6		1			0.824			1		91 0.8					1	-	-	-	+	+		-					1
¹ Bankfull Max Depth (ft)						1	1.6	1.6		1.6		1			1.77			1		38 1.6					1												
Bankfull Cross Sectional Area (ft²)		13.3				1	13.3			13.3		1			13.3			1		34 13.					1												1
Width/Depth Ratio						1		31.6				1			19.59			1		33 16.					1												
Entrenchment Ratio	7.158	7.158	7.158	7.158		1	4.9	4.9	4.9	4.9		1			6.198			1	_	73 6.6		_			1												
¹ Bank Height Ratio	1	1	1	1		1	1	1	1	1		1	1.0	1.0	1.0	1.0		1	1.1	1 1.	1 '	1.1	1.1		1												1
Profile																																					
Riffle Length (ft)																																					
Riffle Slope (ft/ft)	0.009	9 0.034	0.038	0.062	0.019	6																															
Pool Length (ft)	12.84	14.96	14.76	19.24	2.287	6																															
Pool Max depth (ft)																																					
Pool Spacing (ft)	28.34	4 38	42.04	45.35	8.199	6																															
Pattern																																					
Channel Beltwidth (ft)				37.3																																	
Radius of Curvature (ft)	18.6		27.9	37.3																							_										
Rc:Bankfull width (ft/ft)																Patte	ern data v	will not	typically	y be col	lected	l unless	s visual	data, di m baseli	mensio	nal data	or prof	ile data	indicate								
Meander Wavelength (ft)				111.8																	sigriili	icanii Si	IIILS IIOI	III baseii	IIIE												
Meander Width Ratio	1.5		3	4																																	
Additional Reach Parameters																																					
Rosgen Classification				2 4																																	
Channel Thalweg length (ft)				92																																	
Sinuosity (ft)				.05																																	
Water Surface Slope (Channel) (ft/ft)			0.0)235															4																		
BF slope (ft/ft)					,										_	_	_		_																		
³ Ri% / Ru% / P% / G% / S%																	\perp																				
³ SC% / Sa% / G% / C% / B% / Be%																																					1
³ d16 / d35 / d50 / d84 / d95 /																																					
² % of Reach with Eroding Banks		•		0							•			•	-	-	-	-		-	-		-				-	•	-				-	•	-	-	
Channel Stability or Habitat Metric																																					
Biological or Other																										T											

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

																	oring																				
											Pro	ject N	lame/	Num	ber (\	Warr	en Wi	lson/	1000	019)	Seg	gmen	t/Rea	ıch: U	T 5 (1024	feet)										,
Parameter			Bas	eline					M)	Y-1					N	IY-2						MY	'- 3					M	Y- 4					M)	/- 5		
					. ,																			. ,													
Dimension and Substrate - Riffle only		Mean				n		Mean			SD⁴	n					x SD						Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)								18.3					10.03					3	_			21.1			3					_							1
Floodprone Width (ft)		100				3	100		100			3			100			3		00		100			3		_	_	+	+	_						igwdown
Bankfull Mean Depth (ft)	0.614	0.711	0.725	0.796		3	0.3	0.6		0.8			0.346					3	_	0.3		0.5			3			1	+	+-	_		_				1
¹ Bankfull Max Depth (ft)						3	1.3	1.4		1.4			1.293					3			1.53	1.5	1.7		3												
Bankfull Cross Sectional Area (ft²)		7.9		10.4		3	7.3	7.9		10.4		3		8.53		10.4		3	7	7.3		7.9	10.4		3												
Width/Depth Ratio	11.87	14.72	12.47	19.81		3	14		32.2				12.79					3				51.1			3												
Entrenchment Ratio	6.966	10.26	10.08	13.72		3	1.9	2.2	2.2	3.8		3	4.721					3	4	4.3	6.57	4.7	10.7		3												
¹ Bank Height Ratio	1	1	1	1		3	1	0.9	0.9	1		3	0.9	0.93	0.9	1.0)	3	0	0.9	1	1	1.1		3												
Profile																																					
Riffle Length (ft)	9.158	17.7	15.15	36.54	7.615	31																															
Riffle Slope (ft/ft)	0.011	1 0.027	0.025	0.063	0.010	31																															
Pool Length (ft)	5.509	9 12.12	12.54	18.16	3.017	30																															
Pool Max depth (ft)																																					
Pool Spacing (ft)	24.01	1 34.63	32.47	50.16	6.837	30																															
Pattern																																					
Channel Beltwidth (ft)				32.8																																	
Radius of Curvature (ft)	16.4		32.8	47.9												.																					
Rc:Bankfull width (ft/ft)																Patte	ern data	will not	typica	ally be o	collecte	ed unles ificant s	s visual	i data, d m basel	imensic	nal data	a or prof	ile data	indicate								
Meander Wavelength (ft)				98.37																	31911	illiodi it c	7111113 110	iii basci													
Meander Width Ratio	1.5		3	4																																	
Additional Reach Parameters				e 4																																	
Rosgen Classification				e 4 076															4-							!						-					
Channel Thalweg length (ft)				.05															-							_											
Sinuosity (ft) Water Surface Slope (Channel) (ft/ft)			0.0																+							1											
																			-							_											
BF slope (ft/ft) 3Ri% / Ru% / P% / G% / S%		Т		 T	Г				Ι	ı	1		<u> </u>	ı	1	1	_		_	- 1	1			1		\vdash	1	1	1	Т		-	1	ī	ı	I	
3SC% / Sa% / G% / C% / B% / Be%													<u> </u>	-	+	+	+		-	+	\dashv			-		—	1	1	+	+		\vdash	\vdash	\vdash			
³ d16 / d35 / d50 / d84 / d95 /													┢		+	+	+			\dashv	\dashv						+	+	†	+							
² % of Reach with Eroding Banks				0															-							1						-	-				
Channel Stability or Habitat Metric																			\top							1						1					
Biological or Other																			_													1					

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

																	ring [
											Pro	ject N	Name	/Num	ber (V	Varre	n Wils	son/1	00019) Se	gmen	ıt/Rea	ich: U	T 6 (265	feet)										
Parameter			Bas	eline					M)	/-1					M	Y-2					MY	′- 3					M	Y- 4					MY	'- 5		
Dimension and Substrate - Riffle only		Mean				n			Med			n			Med			n		Mean				n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)											1.34						2.22	4		12.88				4				_	—							
Floodprone Width (ft)		100				4			100			4			100			4		100				4			-	-	+-	_						
Bankfull Mean Depth (ft)	0.533	0.000	0.076	0.007	0.100	4	0.5	0.6			0.06						0.17	4	0.4	0.55	_		0.17	_		1	+	+	+	+						
¹ Bankfull Max Depth (ft)	0.865	1.074	1.056	1.319	0.198	4	0.9	1.1	1.1	1.3	0.17	4					0.24	4	1	1.15	1.1		0.17	4			-		+	_						
Bankfull Cross Sectional Area (ft²)	5.639	7.015	7.145	8.131	1.26	4	5.6		7.2	8.1	1.25	4	5.6	7	7.15		1.25	4	5.6		7.15		1.25													
Width/Depth Ratio	11.06	16.01	15.47	22.04	5.078	 			21.6			4					9.8	4		24.65						<u> </u>			↓							
Entrenchment Ratio			-	-	_	4	2	7.5			0.91	_		_			1.48	4		7.95								_								
¹ Bank Height Ratio	1	1	1	1	0	4	1	1	1	1	0.05	4	0.9	1	1.0	1.1	0.1	4	0.9	0.925	0.9	1	0.05	4												
Profile																																				
Riffle Length (ft)		1 16.05				47																														
Riffle Slope (ft/ft)																																				
Pool Length (ft)	1.97	7 10.27	10.89	15.65	3.499	46																														
Pool Max depth (ft)	44.55	100.05	00.50	00.40	0.000	40										_	1									1	_	_	_							
Pool Spacing (ft)	14.55	30.95	29.52	60.46	8.806	46							_															_								
Pattern	0.0		1100	1 26 4									-		-	-				-						1	-	-	+							
Channel Beltwidth (ft)		1		26.4		<u> </u>							-	-	-	┦——														-						
Radius of Curvature (ft) Rc:Bankfull width (ft/ft)	10.2	1	13.0	20.4	-	<u> </u>							-		-	Patte	rn data v	ill not tv	nically b	e collect	ted unles	ss visual	l data d	imensio	nal data	or prof	ile data	indicate								
Meander Wavelength (ft)	39.5		56	79.1	+	1							-		-				p.ou, 2	sig	nificant s	shifts fro	m basel	ine	iai date	. о. р.о										
Meander Wavelength (it)			3	4	+-	-							-		+																					
Wearider Width Natio	1.0		U	ı ·																																
Additional Reach Parameters																																				
Rosgen Classification			С	e 4			$\overline{}$						-																							
Channel Thalweg length (ft)			14	455																																
Sinuosity (ft)			1.	.15																																
Water Surface Slope (Channel) (ft/ft)			0.0	0051																																
BF slope (ft/ft)																																				
³ Ri% / Ru% / P% / G% / S%																																				
³ SC% / Sa% / G% / C% / B% / Be%																																				
³ d16 / d35 / d50 / d84 / d95 /																	1										1	1								
² % of Reach with Eroding Banks				0											-											•	•	•	-							
Channel Stability or Habitat Metric													1																							
Biological or Other																																				

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

																	ring [\Box
											Pro	ject N	Name/	Num	ber (V	Narre	n Wils	son/1	00019) Se	gmen	ıt/Rea	ich: U	T 7 (1844	feet)										ļ
Parameter			Bas	eline					M`	Y-1					М	Y-2					MY	′- 3					М	Y- 4					MY	'- 5		
Dimension and Substrate - Riffle only			Med			n		Mean				n			Med			n			Med			n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)																	1.936	4			12.15			4				_	4							
Floodprone Width (ft)			100			4		100				4			100			4			100			4				╀	+	_						lacksquare
Bankfull Mean Depth (ft)							0.5	0.6			0.096	_					0.129		0.5		0.7					_	-	-	+			<u> </u>				
¹ Bankfull Max Depth (ft)			1.163				1	1.2			0.129	4					0.189		1	1.2	1.2		0.163													
Bankfull Cross Sectional Area (ft²)	5.196	8.26	8.583	10.68	2.517	4	5.2		8.6		2.525	4					2.525				8.55															1
Width/Depth Ratio	15.52	17.76	17.95	19.61	1.734	4		21		21.8		4					1.13	4			17.55			4												
Entrenchment Ratio	7.602	8.481	8.207	9.908	1.056	4	0.7	1.5	1.5	2	1.53	4					1.2	4		8.6			1.47	4												
¹ Bank Height Ratio	1	1	1	1	0	4	1	1	1	1.2	0.096	4	0.9	1.025	1.0	1.1	0.096	4	0.9	0.95	0.95	1	0.058	4												
Profile																																				
Riffle Length (ft)	7.735	27.4	24.34	91.32	15.53	44																														
Riffle Slope (ft/ft)	0.000	0.013	0.010	0.040	0.011	44																														
Pool Length (ft)	4.044	11.28	11.73	15.84	2.729	44																														
Pool Max depth (ft)																																				
Pool Spacing (ft)	22.31	1 44.19	40.07	107.9	16.31	43																														
Pattern																																				
Channel Beltwidth (ft)				37.3																																
Radius of Curvature (ft)	18.6		27.9	37.3																																
Rc:Bankfull width (ft/ft)			<u> </u>	l												Patte	rn data v	ill not ty	pically b	e collect	ted unles nificant s	ss visual shifts fro	l data, d m hasel	imensio ine	nal data	or profi	ile data	indicate								
Meander Wavelength (ft)				111.8												Ļ				3.9	riiioant s	3111113 110	JIII DUSCI													
Meander Width Ratio	1.5		3	4																																
Additional Reach Parameters				b 4			_																													
Rosgen Classification				973			-												-												.					
Channel Thalweg length (ft)				.07																																
Sinuosity (ft)				0103			 												I												-					
Water Surface Slope (Channel) (ft/ft)																																				
BF slope (ft/ft) 3Ri% / Ru% / P% / G% / S%		1	, 	 T	1		\vdash	ı	T		1				1	1	T		-	1		1				1	1	1	т —		⊢—	T	ı			
³ SC% / Sa% / G% / C% / B% / Be%													⊢	<u> </u>	\vdash	+	+									-	+	+	+		_	\vdash				
³ d16 / d35 / d50 / d84 / d95 /		-	-								_		<u> </u>	\vdash	\vdash	+	+			-		<u> </u>				₩	+	+	+		_	-				
													<u> </u>			1	1									<u> </u>	1	1			₩					
² % of Reach with Eroding Banks				0															1																	
Channel Stability or Habitat Metric							Ь—																													
Biological or Other	I												I																							

Biological or Other

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3

											Pro	ject l					_						umma ach: L	-	760 f	eet)										
Parameter			Base	eline					M)	/ -1		-			М	Y-2					MY	′- 3					M	Y- 4					MY	- 5		\neg
Dimension and Substrate - Riffle only		Mean			SD⁴	n	Min	Mean			SD⁴	n				Max		n		Mean		Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n	Min	Mean	Med	Max	SD⁴	n
Bankfull Width (ft)						3		12.9				3	10.38					3			12.3			3												
Floodprone Width (ft)		100				3	100		100			3				100		3			100			3												
Bankfull Mean Depth (ft)	0.624	0.684	0.684	0.745		3	0.6		0.6	0.7			0.576		_			3	0.6	0.667	_			3												
¹ Bankfull Max Depth (ft)	1.197	1.433	1.426	1.677		3	1.2	1.3	1.3	1.4		3	1.206	1.5	1.457	1.625	5	3	1.1	1.33	1.4	1.5		3												
Bankfull Cross Sectional Area (ft²)	6.446	8.305	8.293	10.18		3	6.4	8.3	8.3	10.2		3	6.4	8.3		10.2		3	6.4	8.3	8.3	10.2		3												
Width/Depth Ratio	16.57	17.55	17.74	18.34		3	16.6	20		22.7			12.99					3	18.4	19.13	19.1	19.9		3												
Entrenchment Ratio	7.32	8.413	8.244	9.676		3	1.6	1.9	1.9	2.2		3	6.883	8.9	8.943	9.638	3	3	7.2	8.033	8.1	8.8		3												
¹ Bank Height Ratio	1	1	1	1		3	1.1	1.1	1.1	1.2		3	0.9	1	1.0	1.0		3	0.9	1	1	1.1		3												
Profile																																				
Riffle Length (ft)	7.812	15.86	13.77	32.44	7.157	27																														
Riffle Slope (ft/ft)																																				
Pool Length (ft)	6.84	12.15	12.42	19.87	2.569	27																														
Pool Max depth (ft)																																				
Pool Spacing (ft)	24.07	32.15	30.62	48.15	6.855	26																														
Pattern																																				
Channel Beltwidth (ft)			21.3													_																				
Radius of Curvature (ft)	14.2		21.3	28.4												.																				
Rc:Bankfull width (ft/ft)																Patter	n data v	ill not ty	pically b	e collec	ted unles	ss visual shifts fro	l data, di om baseli	mensio	nai data	or profi	ile data i	ndicate								
Meander Wavelength (ft)			64	85.2																316	, illiodite s	3111113 110	nn basci													
Meander Width Ratio	1.5		3	4																																
Additional Reach Parameters																																				
Rosgen Classification			С	4																					-						-					-
Channel Thalweg length (ft)			87	74																																
Sinuosity (ft)			1.	15																																
Water Surface Slope (Channel) (ft/ft)			0.0	063																																
BF slope (ft/ft)																																				
³ Ri% / Ru% / P% / G% / S%																																				
³ SC% / Sa% / G% / C% / B% / Be%																	1				t															
³ d16 / d35 / d50 / d84 / d95 /																																				
² % of Reach with Eroding Banks				0																																
Channel Stability or Habitat Metric																																				
Biological or Other																																				-

Shaded cells indicate that these will typically not be filled in.

1 = The distributions for these parameters can include information from both the cross-section measurements and the longitudinal profile.

2 = Proportion of reach exhibiting banks that are eroding based on the visual survey from visual assessment table

3 = Riffle, Run, Pool, Glide, Step; Silt/Clay, Sand, Gravel, Cobble, Boulder, Bedrock; dip = max pave, disp = max subpave

4. = Of value/needed only if the n exceeds 3


Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS -1, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2571.6
3.7	2570.9
6.3	2569.9
7.3	2569.3
7.9	2568.8
8.8	2568.1
10.0	2567.9
10.5	2567.9
11.0	2568.0
11.3	2568.0
11.8	2568.6
12.9	2568.8
14.9	2568.9
18.2	2569.8
22.3	2570.2

SUMMARY DATA	
Bankfull Elevation:	2569.9
Bankfull Cross-Sectional Area:	12.8
Bankfull Width:	12.6
Flood Prone Area Elevation:	2571.8
Flood Prone Width:	100.0
Max Depth at Bankfull:	2.0
Low Bank Height:	1.9
Mean Depth at Bankfull:	1.0
W / D Ratio:	12.5
Entrenchment Ratio:	7.9
Bank Height Ratio:	1.0



Stream	Type	Cb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS - 2, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.1	2571.0
3.5	2570.6
5.7	2570.4
6.2	2570.3
7.2	2569.9
7.7	2568.4
9.0	2568.2
9.7	2568.3
10.5	2568.4
11.5	2568.8
12.0	2568.9
12.6	2569.8
14.1	2570.0
17.1	2570.5
19.9	2570.4

SUMMARY DATA	
Bankfull Elevation:	2570.1
Bankfull Cross-Sectional Area:	8.3
Bankfull Width:	7.6
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.0
Low Bank Height:	1.9
Mean Depth at Bankfull:	1.1
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS - 3, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2575.9
4.6	2575.6
6.9	2575.3
8.2	2574.9
8.3	2574.7
8.8	2574.2
9.1	2574.2
9.3	2574.1
9.9	2574.0
10.7	2574.1
11.4	2574.2
12.1	2575.2
14.0	2575.5
17.2	2576.2
19.2	2576.6

SUMMARY DATA	
Bankfull Elevation:	2575.7
Bankfull Cross-Sectional Area:	7.4
Bankfull Width:	10.7
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.7
Low Bank Height:	1.6
Mean Depth at Bankfull:	0.7
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream	Type	Cb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS -4, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2576.2
4.1	2575.8
5.2	2575.5
6.1	2575.2
6.7	2575.2
7.5	2574.7
8.0	2574.6
8.5	2574.5
9.0	2574.7
9.5	2574.8
10.6	2575.2
12.6	2575.6
17.1	2576.5

SUMMARY DATA	
Bankfull Elevation:	2576.1
Bankfull Cross-Sectional Area:	9.4
Bankfull Width:	14.4
Flood Prone Area Elevation:	2577.7
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.6
Low Bank Height:	1.7
Mean Depth at Bankfull:	0.7
W / D Ratio:	21.9
Entrenchment Ratio:	7.0
Bank Height Ratio:	1.0






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS - 5, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2599.1
3.0	2598.8
4.8	2598.2
5.4	2598.2
6.3	2598.0
6.7	2597.8
7.2	2597.7
7.9	2597.3
8.3	2597.5
9.1	2597.8
9.4	2597.6
9.7	2598.0
10.6	2598.1
12.2	2598.3
14.2	2598.5
16.3	2598.6

SUMMARY DATA	
Bankfull Elevation:	2598.5
Bankfull Cross-Sectional Area:	4.3
Bankfull Width:	9.6
Flood Prone Area Elevation:	2599.6
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.1
Low Bank Height:	1.2
Mean Depth at Bankfull:	0.4
W / D Ratio:	21.5
Entrenchment Ratio:	10.4
Bank Height Ratio:	1.1



Stream	Type	Cb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS - 6, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.1	2599.5
2.7	2598.9
4.8	2598.7
5.8	2598.4
6.6	2597.9
7.4	2597.5
7.9	2597.2
8.3	2597.2
8.8	2597.1
9.2	2597.3
9.6	2597.7
10.1	2598.4
12.6	2598.5
15.9	2598.6

-	
SUMMARY DATA	
Bankfull Elevation:	2598.5
Bankfull Cross-Sectional Area:	3.8
Bankfull Width:	6.6
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.4
Low Bank Height:	1.4
Mean Depth at Bankfull:	0.6
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type	Cb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS - 7, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2605.2
4.0	2604.8
6.3	2604.5
7.3	2604.1
8.0	2603.6
8.4	2603.4
8.7	2603.2
9.2	2603.2
9.2	2603.2
10.0	2603.2
10.7	2603.3
11.4	2603.5
11.8	2603.8
12.4	2604.3
14.7	2604.6
17.8	2605.0
20.4	2605.2

SUMMARY DATA	
Bankfull Elevation:	2604.9
Bankfull Cross-Sectional Area:	9.0
Bankfull Width:	13.4
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.7
Low Bank Height:	1.6
Mean Depth at Bankfull:	0.7
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.9



Stream Type Cb 4	Stream Type	Cb 4
------------------	-------------	------




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 1, XS - 8, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2606.1
4.3	2605.7
6.0	2605.2
6.2	2605.0
6.8	2604.8
7.6	2604.5
7.9	2604.5
8.5	2604.6
8.7	2604.5
9.2	2604.6
9.8	2605.2
11.3	2605.2
13.5	2605.8
16.4	2606.0
18.1	2606.2
18.1	2606.2

SUMMARY DATA	•
Bankfull Elevation:	2605.8
Bankfull Cross-Sectional Area:	6.6
Bankfull Width:	10.6
Flood Prone Area Elevation:	2607.1
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.3
Low Bank Height:	1.3
Mean Depth at Bankfull:	0.6
W / D Ratio:	17.2
Entrenchment Ratio:	9.4
Bank Height Ratio:	1.0



Stream	Type	Cb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 1, Riffle
Feature	Riffle
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2550.1
3.1	2550.1
6.1	2550.0
8.3	2549.5
10.4	2549.2
12.0	2548.9
13.1	2548.5
14.4	2548.0
15.3	2548.1
16.5	2547.8
17.8	2547.9
18.9	2548.0
19.7	2548.2
21.2	2548.5
22.5	2548.7
24.6	2549.1
26.9	2549.5
30.0	2549.8
34.4	2549.8
38.4	2549.9

SUMMARY DATA	
Bankfull Elevation:	2549.9
Bankfull Cross-Sectional Area:	27.2
Bankfull Width:	32.0
Flood Prone Area Elevation:	2552.0
Flood Prone Width:	100.0
Max Depth at Bankfull:	2.1
Low Bank Height:	2.0
Mean Depth at Bankfull:	0.8
W / D Ratio:	37.7
Entrenchment Ratio:	3.1
Bank Height Ratio:	1.0






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 2, Pool
Feature	Pool
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.3	2550.3
5.0	2550.2
7.1	2550.0
9.3	2549.7
11.3	2549.4
12.1	2548.4
13.9	2547.5
15.5	2547.0
16.8	2546.9
17.8	2547.0
18.4	2547.3
19.8	2547.4
20.1	2547.4
20.8	2549.6
21.4	2550.0
23.6	2550.4
26.9	2550.8
32.8	2550.8

SUMMARY DATA	
Bankfull Elevation:	2549.3
Bankfull Cross-Sectional Area:	16.7
Bankfull Width:	9.4
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.4
Low Bank Height:	2.5
Mean Depth at Bankfull:	1.8
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT3, XS - 3, Pool
Feature	Pool
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2558.6
3.0	2558.5
5.1	2557.9
6.2	2557.3
7.1	2556.6
7.7	2556.1
8.9	2555.8
10.0	2555.5
11.4	2555.6
12.1	2555.7
13.2	2556.1
14.1	2556.3
15.1	2556.5
16.0	2556.8
16.4	2557.0
17.2	2557.1
18.7	2557.3
21.2	2557.8
23.5	2558.04
26.6	2557.81

SUMMARY DATA	
Bankfull Elevation:	2557.9
Bankfull Cross-Sectional Area:	21.3
Bankfull Width:	17.2
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.4
Low Bank Height:	2.3
Mean Depth at Bankfull:	1.2
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 4, Riffle
Feature	Riffle
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2558.9
2.8	2558.4
4.1	2558.0
6.6	2558.0
8.8	2557.7
10.7	2557.4
11.8	2556.9
12.7	2556.9
13.5	2556.7
15.6	2556.6
17.0	2556.8
18.2	2556.7
19.1	2556.8
19.8	2557.2
20.5	2557.3
21.7	2557.6
23.0	2557.6
24.5	2558.0
27.3	2558.1
30.2	2558.1

SUMMARY DATA	
Bankfull Elevation:	2558.1
Bankfull Cross-Sectional Area:	17.0
Bankfull Width:	26.6
Flood Prone Area Elevation:	2559.7
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.5
Low Bank Height:	1.5
Mean Depth at Bankfull:	0.6
W / D Ratio:	41.5
Entrenchment Ratio:	3.8
Bank Height Ratio:	1.0



Stream Type	Co 1
or cam Type	




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 5, Pool
Feature	Pool
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.4	2602.8
7.1	2602.4
10.4	2601.8
13.3	2601.1
14.6	2600.6
15.6	2599.0
16.5	2598.8
18.2	2598.9
19.7	2598.8
21.1	2599.4
21.8	2599.9
22.9	2600.5
25.1	2601.1
27.3	2601.7
29.6	2601.9
34.8	2601.7
40.5	2601.8

SUMMARY DATA	
Bankfull Elevation:	2601.3
Bankfull Cross-Sectional Area:	19.1
Bankfull Width:	13.5
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.6
Low Bank Height:	2.4
Mean Depth at Bankfull:	1.4
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.9



Stream	Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 6, Riffle
Feature	Riffle
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.1	2603.0
6.1	2603.0
9.9	2602.7
11.8	2602.3
13.7	2601.9
15.4	2601.6
17.4	2601.0
18.5	2600.8
19.6	2600.8
20.6	2600.8
21.4	2601.1
22.6	2601.4
23.6	2601.5
25.2	2602.0
27.9	2602.6
33.1	2603.3
36.4	2603.2
38.1	2603.2

SUMMARY DATA	
Bankfull Elevation:	2602.8
Bankfull Cross-Sectional Area:	21.4
Bankfull Width:	21.6
Flood Prone Area Elevation:	2604.8
Flood Prone Width:	100.0
Max Depth at Bankfull:	2.0
Low Bank Height:	1.8
Mean Depth at Bankfull:	1.0
W / D Ratio:	21.9
Entrenchment Ratio:	4.6
Bank Height Ratio:	0.9






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 7, Riffle
Feature	Riffle
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.2	2610.0
3.8	2610.0
7.4	2609.7
10.8	2609.2
12.3	2608.7
12.9	2608.4
13.6	2608.0
14.9	2607.9
16.0	2607.9
17.1	2607.9
18.5	2608.6
19.8	2608.9
21.4	2609.3
24.0	2609.8
28.9	2609.7
32.0	2609.5

SUMMARY DATA	
Bankfull Elevation:	2609.6
Bankfull Cross-Sectional Area:	13.6
Bankfull Width:	17.9
Flood Prone Area Elevation:	2611.4
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.8
Low Bank Height:	1.8
Mean Depth at Bankfull:	0.8
W / D Ratio:	23.5
Entrenchment Ratio:	5.6
Bank Height Ratio:	1.0



Stream Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 8, Pool
Feature	Pool
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2611.9
7.4	2611.9
12.3	2611.5
14.8	2610.7
15.7	2608.7
17.1	2608.4
18.5	2608.4
20.3	2608.6
21.3	2608.7
21.8	2608.9
22.6	2610.3
23.2	2610.5
24.4	2610.8
31.3	2611.7
35.8	2611.7
40.0	2611.7

SUMMARY DATA	
Bankfull Elevation:	2611.2
Bankfull Cross-Sectional Area:	20.8
Bankfull Width:	14.0
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.8
Low Bank Height:	2.5
Mean Depth at Bankfull:	1.5
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.9



Stream	Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 9, Riffle
Feature	Riffle
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.1	2617.1
5.7	2617.0
12.2	2616.3
15.2	2615.7
16.0	2615.4
16.9	2615.4
17.7	2615.2
18.6	2615.2
19.3	2615.5
20.0	2615.8
21.3	2615.6
22.4	2616.0
24.3	2616.2
26.4	2616.8
29.8	2616.8
33.3	2616.7
36.1	2616.6

SUMMARY DATA	
Bankfull Elevation:	2616.8
Bankfull Cross-Sectional Area:	16.4
Bankfull Width:	29.3
Flood Prone Area Elevation:	2618.5
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.6
Low Bank Height:	1.6
Mean Depth at Bankfull:	0.6
W / D Ratio:	52.1
Entrenchment Ratio:	3.4
Bank Height Ratio:	1.0



Stream Type	Co 1
or cam Type	




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 10, Pool
Feature	Pool
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2617.7
3.8	2617.5
8.2	2617.2
10.2	2616.7
11.8	2616.3
13.0	2614.5
14.4	2614.4
15.2	2614.3
16.2	2614.5
16.7	2614.6
17.5	2616.7
18.7	2617.0
21.7	2617.4
27.7	2617.8

SUMMARY DATA	
Bankfull Elevation:	2617.3
Bankfull Cross-Sectional Area:	16.7
Bankfull Width:	13.6
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	3.0
Low Bank Height:	2.9
Mean Depth at Bankfull:	1.2
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream	Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 11, Pool
Feature	Pool
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
1.0	2623.9
6.9	2623.2
10.6	2622.4
11.9	2622.1
13.3	2620.5
13.9	2620.5
14.8	2620.7
15.8	2620.9
16.6	2621.0
17.8	2621.5
19.1	2621.9
22.1	2622.4
26.8	2623.2
34.3	2623.7

SUMMARY DATA	
Bankfull Elevation:	2623.5
Bankfull Cross-Sectional Area:	28.8
Bankfull Width:	26.4
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.9
Low Bank Height:	2.7
Mean Depth at Bankfull:	1.1
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.9






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 3, XS - 12, Riffle
Feature	Riffle
Date:	11/6/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.5	2623.6
5.6	2623.1
9.1	2622.9
9.9	2622.5
10.7	2621.9
11.5	2621.4
12.6	2621.2
13.7	2621.0
15.2	2621.0
15.8	2621.3
16.5	2621.0
17.1	2622.3
18.7	2622.8
20.4	2622.9
21.4	2623.3
25.1	2623.4
28.9	2624.0

SUMMARY DATA	
Bankfull Elevation:	2623.2
Bankfull Cross-Sectional Area:	16.0
Bankfull Width:	16.3
Flood Prone Area Elevation:	2625.4
Flood Prone Width:	100.0
Max Depth at Bankfull:	2.2
Low Bank Height:	2.2
Mean Depth at Bankfull:	1.0
W / D Ratio:	16.6
Entrenchment Ratio:	6.1
Bank Height Ratio:	1.0



Stream Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 4, XS - 1, Pool
Feature	Pool
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.1	2586.0
5.5	2585.8
7.3	2585.7
9.3	2585.4
11.7	2585.0
12.9	2584.5
14.0	2583.8
14.5	2583.8
15.5	2583.4
16.7	2583.3
17.3	2583.3
18.7	2584.5
20.1	2585.3
23.5	2585.8
26.4	2585.7
28.7	2585.6

SUMMARY DATA	
Bankfull Elevation:	2585.4
Bankfull Cross-Sectional Area:	11.8
Bankfull Width:	11.4
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.1
Low Bank Height:	2.1
Mean Depth at Bankfull:	1.0
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type	C 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 4, XS - 2, Riffle
Feature	Riffle
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	2586.9
5.0	2587.0
7.3	2586.9
10.2	2586.1
11.6	2585.7
12.9	2585.7
13.6	2585.2
14.6	2585.2
15.5	2585.0
16.5	2585.0
16.9	2585.2
17.8	2585.4
18.9	2585.7
20.0	2586.1
21.7	2586.5
24.0	2586.8
29.0	2586.5

SUMMARY DATA	
Bankfull Elevation:	2586.7
Bankfull Cross-Sectional Area:	13.3
Bankfull Width:	15.0
Flood Prone Area Elevation:	2588.4
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.7
Low Bank Height:	1.8
Mean Depth at Bankfull:	0.9
W / D Ratio:	16.8
Entrenchment Ratio:	6.7
Bank Height Ratio:	1.1



Stream	Type	C 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 5, XS - 1, Pool
Feature	Pool
Date:	10/11/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.2	514.5
2.5	514.2
5.2	514.2
7.0	513.8
8.1	513.5
9.4	511.9
10.7	511.7
11.8	511.5
12.9	511.8
14.0	511.8
14.4	513.0
15.5	513.4
16.7	514.0
17.7	514.0
18.6	514.1
20.5	514.3
23.2	514.5

SUMMARY DATA	
Bankfull Elevation:	514.0
Bankfull Cross-Sectional Area:	15.3
Bankfull Width:	12.1
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.6
Low Bank Height:	2.5
Mean Depth at Bankfull:	1.3
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 5, XS - 2, Riffle
Feature	Riffle
Date:	10/11/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	514.6
3.4	514.7
5.5	514.4
7.0	513.9
8.1	513.4
8.8	513.3
9.8	512.6
10.3	512.8
10.7	512.8
11.2	513.2
12.0	513.1
12.9	513.4
14.2	514.0
15.8	514.5
18.1	514.6
20.1	514.7

SUMMARY DATA	
Bankfull Elevation:	514.3
Bankfull Cross-Sectional Area:	7.9
Bankfull Width:	9.3
Flood Prone Area Elevation:	516.0
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.7
Low Bank Height:	1.8
Mean Depth at Bankfull:	0.8
W / D Ratio:	11.0
Entrenchment Ratio:	10.7
Bank Height Ratio:	1.1






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 5, XS - 3, Pool
Feature	Pool
Date:	10/11/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.3	520.6
1.9	520.7
5.6	520.6
6.9	520.4
7.9	520.0
8.4	519.1
9.1	519.1
10.3	519.0
10.8	518.9
11.6	519.2
12.2	520.0
12.9	520.2
14.6	520.6
17.1	520.6
20.4	520.6

SUMMARY DATA	
Bankfull Elevation:	520.6
Bankfull Cross-Sectional Area:	7.4
Bankfull Width:	12.3
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.7
Low Bank Height:	1.6
Mean Depth at Bankfull:	0.6
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Ty	pe	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 5, XS - 4, Riffle
Feature	Riffle
Date:	10/11/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.2	521.3
3.2	521.3
6.8	521.4
8.4	521.0
9.3	520.8
10.1	520.0
11.1	520.2
12.1	520.4
13.1	520.9
15.7	521.3
20.9	521.4

SUMMARY DATA	
Bankfull Elevation:	521.3
Bankfull Cross-Sectional Area:	7.3
Bankfull Width:	21.1
Flood Prone Area Elevation:	522.7
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.4
Low Bank Height:	1.3
Mean Depth at Bankfull:	0.3
W / D Ratio:	60.6
Entrenchment Ratio:	4.7
Bank Height Ratio:	0.9






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 5, XS - 5, Pool
Feature	Pool
Date:	10/11/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.1	531.0
3.7	530.8
6.6	530.6
8.1	530.8
9.0	530.4
10.1	528.4
11.3	528.5
12.2	528.6
13.0	528.7
13.6	528.9
14.1	530.5
14.6	530.8
16.0	530.5
18.2	530.6
20.6	530.8
22.8	531.1

SUMMARY DATA	
Bankfull Elevation:	530.6
Bankfull Cross-Sectional Area:	8.7
Bankfull Width:	6.7
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.1
Low Bank Height:	2.1
Mean Depth at Bankfull:	1.3
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream	Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 5, XS -6, Riffle
Feature	Riffle
Date:	10/11/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.2	531.4
5.9	531.0
9.4	530.6
11.5	530.5
12.4	529.8
13.0	529.8
13.3	529.9
14.0	530.5
15.9	530.6
19.9	530.9
25.7	531.2

SUMMARY DATA		
Bankfull Elevation:	531.2	
Bankfull Cross-Sectional Area:	10.4	
Bankfull Width:	23.0	
Flood Prone Area Elevation:	532.7	
Flood Prone Width:	100.0	
Max Depth at Bankfull:	1.5	
Low Bank Height:	1.5	
Mean Depth at Bankfull:	0.5	
W / D Ratio:	51.1	
Entrenchment Ratio:	4.3	
Bank Height Ratio:	1.0	






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS - 1, Pool
Feature	Pool
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-4.2	21.6
-1.1	21.0
0.8	20.9
2.3	20.5
3.6	20.2
4.8	20.0
5.7	19.9
7.5	20.3
8.6	20.8
10.1	21.0
11.4	21.4
13.0	21.5
14.8	21.7
17.1	22.0

SUMMARY DATA	
Bankfull Elevation:	21.2
Bankfull Cross-Sectional Area:	8.3
Bankfull Width:	12.9
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.3
Low Bank Height:	1.1
Mean Depth at Bankfull:	0.6
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.8






Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS -2, Riffle
Feature	Riffle
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	21.9
4.0	21.8
6.5	21.4
8.2	21.2
9.2	21.1
9.9	20.7
10.5	20.8
11.3	20.6
12.1	20.8
12.9	20.9
14.3	21.1
15.6	21.5
17.4	21.8
19.4	22.0
20.6	22.1
21.6	22.2

SUMMARY DATA	
Bankfull Elevation:	21.6
Bankfull Cross-Sectional Area:	5.6
Bankfull Width:	11.2
Flood Prone Area Elevation:	22.6
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.0
Low Bank Height:	0.9
Mean Depth at Bankfull:	0.5
W / D Ratio:	22.6
Entrenchment Ratio:	8.9
Bank Height Ratio:	0.9



Stream Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS - 3, Pool
Feature	Pool
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.3	24.1
2.4	23.7
5.3	23.5
7.3	23.3
8.9	22.9
10.0	22.4
10.7	22.4
11.5	22.3
12.3	22.2
12.9	22.4
13.5	22.6
14.7	23.0
16.1	23.5
17.0	23.8
18.8	24.1
21.0	24.2
22.7	24.5

SUMMARY DATA	
Bankfull Elevation:	23.7
Bankfull Cross-Sectional Area:	9.8
Bankfull Width:	14.5
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.6
Low Bank Height:	1.6
Mean Depth at Bankfull:	0.7
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS -4, Riffle
Feature	Riffle
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.1	24.1
3.1	23.8
6.2	23.7
7.3	23.2
8.2	22.9
9.1	22.9
10.7	22.8
12.0	22.8
13.4	23.0
14.6	23.3
15.4	23.6
16.7	23.7
18.8	24.0
20.5	24.1
21.7	24.3

SUMMARY DATA	
Bankfull Elevation:	23.9
Bankfull Cross-Sectional Area:	8.0
Bankfull Width:	15.2
Flood Prone Area Elevation:	24.9
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.1
Low Bank Height:	1.0
Mean Depth at Bankfull:	0.5
W / D Ratio:	29.0
Entrenchment Ratio:	6.6
Bank Height Ratio:	0.9



Stream	Type	Ce 4



Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS -5, Riffle
Feature	Riffle
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	26.3
1.5	26.5
3.3	26.5
4.8	26.4
5.9	26.3
6.9	26.0
7.6	25.7
8.1	25.5
8.6	25.1
9.2	24.9
10.0	25.0
11.0	25.2
12.1	25.5
13.8	25.5
15.9	26.3
18.0	26.5
20.2	26.6

SUMMARY DATA	
Bankfull Elevation:	26.4
Bankfull Cross-Sectional Area:	8.1
Bankfull Width:	10.7
Flood Prone Area Elevation:	27.8
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.4
Low Bank Height:	1.4
Mean Depth at Bankfull:	0.8
W / D Ratio:	14.3
Entrenchment Ratio:	9.3
Bank Height Ratio:	1.0



Stream Type Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS - 6, Pool
Feature	Pool
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.1	27.0
2.3	26.7
4.7	26.7
6.1	26.5
7.6	26.0
8.6	25.6
9.2	25.5
10.0	25.2
10.8	25.0
12.0	25.3
12.8	25.6
13.9	25.8
16.7	26.4
20.0	26.6
23.7	26.7

SUMMARY DATA	
Bankfull Elevation:	26.5
Bankfull Cross-Sectional Area:	8.4
Bankfull Width:	12.8
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.5
Low Bank Height:	1.5
Mean Depth at Bankfull:	0.7
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream	Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS - 7, Pool
Feature	Pool
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.3	28.1
3.6	27.9
6.9	27.9
8.6	27.5
9.8	27.0
10.9	26.5
12.0	26.1
12.7	25.4
13.5	25.5
14.5	25.6
16.0	26.0
17.4	26.5
18.5	26.7
20.2	26.6
23.2	27.1
25.7	27.1
27.8	27.4

SUMMARY DATA	
Bankfull Elevation:	27.2
Bankfull Cross-Sectional Area:	11.1
Bankfull Width:	16.4
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.7
Low Bank Height:	1.7
Mean Depth at Bankfull:	0.7
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type	Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 6, XS -8, Riffle
Feature	Riffle
Date:	11/5/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	27.5
2.0	27.2
4.9	27.1
8.6	26.9
10.6	26.7
12.1	26.6
13.2	26.2
14.1	25.9
15.3	26.2
16.0	26.2
17.1	26.4
18.3	26.5
20.2	26.9
22.1	27.2
24.2	27.1
26.3	27.3
29.4	27.3

SUMMARY DATA	
Bankfull Elevation:	27.0
Bankfull Cross-Sectional Area:	6.3
Bankfull Width:	14.4
Flood Prone Area Elevation:	28.1
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.1
Low Bank Height:	1.0
Mean Depth at Bankfull:	0.4
W / D Ratio:	32.7
Entrenchment Ratio:	7.0
Bank Height Ratio:	0.9



Stream Type Ce 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS -1, Riffle
Feature	Riffle
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	25.6
4.7	25.8
6.6	25.5
7.8	25.1
9.5	24.6
11.1	24.4
12.2	24.4
13.1	24.3
14.2	24.6
15.3	24.8
16.4	25.1
18.2	25.6
20.8	26.0
23.3	26.1
24.9	26.2

SUMMARY DATA	
Bankfull Elevation:	25.7
Bankfull Cross-Sectional Area:	10.7
Bankfull Width:	13.7
Flood Prone Area Elevation:	27.1
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.4
Low Bank Height:	1.3
Mean Depth at Bankfull:	0.8
W / D Ratio:	17.6
Entrenchment Ratio:	7.3
Bank Height Ratio:	0.9



Stream Type Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS - 2, Pool
Feature	Pool
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
1.1	25.3
3.9	25.5
6.0	25.2
7.6	24.4
8.0	24.3
9.1	24.1
9.9	23.9
11.1	23.8
12.0	23.8
13.2	23.8
13.4	23.6
14.0	23.8
14.7	23.9
15.2	23.9
15.5	24.6
16.2	24.8
18.2	25.3
20.9	25.9
23.1	26.0
24.9	26.1

SUMMARY DATA	
Bankfull Elevation:	25.6
Bankfull Cross-Sectional Area:	18.2
Bankfull Width:	18.6
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.0
Low Bank Height:	1.9
Mean Depth at Bankfull:	1.0
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.9



Stream Type	Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS -3, Riffle
Feature	Riffle
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.9	25.7
3.2	25.6
4.6	25.2
5.8	24.5
7.3	24.4
8.6	24.6
10.1	24.4
11.3	24.4
13.1	25.0
14.8	25.3
16.7	25.7
18.7	26.0
21.6	26.2

SUMMARY DATA	
Bankfull Elevation:	25.6
Bankfull Cross-Sectional Area:	9.9
Bankfull Width:	13.2
Flood Prone Area Elevation:	26.8
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.2
Low Bank Height:	1.2
Mean Depth at Bankfull:	0.8
W / D Ratio:	17.5
Entrenchment Ratio:	7.6
Bank Height Ratio:	1.0



Stream Type Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS - 4, Pool
Feature	Pool
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.2	25.6
2.5	25.7
4.4	25.7
6.1	25.3
7.3	24.8
8.5	24.3
9.5	23.9
10.7	23.9
12.0	23.7
13.0	23.6
14.4	23.9
15.2	24.3
15.8	25.1
17.3	25.4
20.6	25.8
22.9	26.1

SUMMARY DATA	
Bankfull Elevation:	25.4
Bankfull Cross-Sectional Area:	13.0
Bankfull Width:	12.5
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.8
Low Bank Height:	1.8
Mean Depth at Bankfull:	1.0
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS -5, Riffle
Feature	Riffle
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	30.9
4.0	30.4
6.6	29.9
7.9	29.7
8.7	29.4
9.1	29.1
9.9	29.2
10.1	29.1
10.8	29.0
10.8	29.0
11.3	29.2
12.4	29.1
12.7	29.4
16.2	30.3
20.8	30.3
23.7	30.5

SUMMARY DATA	
Bankfull Elevation:	30.2
Bankfull Cross-Sectional Area:	7.2
Bankfull Width:	11.1
Flood Prone Area Elevation:	31.4
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.2
Low Bank Height:	1.3
Mean Depth at Bankfull:	0.6
W / D Ratio:	17.2
Entrenchment Ratio:	9.0
Bank Height Ratio:	1.0



Stream Type	Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS - 6, Pool
Feature	Pool
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	31.3
3.5	31.0
5.6	30.5
6.9	30.1
7.9	29.5
8.2	29.2
8.7	29.2
9.5	28.9
10.0	29.1
10.7	29.2
11.1	29.4
12.4	30.6
15.9	31.2
17.7	31.4

SUMMARY DATA	
Bankfull Elevation:	31.0
Bankfull Cross-Sectional Area:	10.7
Bankfull Width:	11.5
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.1
Low Bank Height:	2.1
Mean Depth at Bankfull:	0.9
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS - 7, Pool
Feature	Pool
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	37.8
4.5	37.5
6.4	37.1
7.2	36.9
7.6	36.3
8.1	35.6
8.5	35.4
9.1	35.4
9.2	35.3
9.6	35.3
10.3	35.3
10.9	35.1
11.6	35.5
12.1	35.9
13.0	37.0
14.7	37.5
16.8	37.8
19.8	38.0

SUMMARY DATA	
Bankfull Elevation:	37.5
Bankfull Cross-Sectional Area:	11.6
Bankfull Width:	10.2
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	2.3
Low Bank Height:	2.3
Mean Depth at Bankfull:	1.1
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0



Stream Type	Eb 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 7, XS -8, Riffle
Feature	Riffle
Date:	6/22/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.5	39.3
3.4	38.8
5.3	38.6
7.2	38.1
7.7	37.9
8.1	37.7
8.8	37.7
9.2	37.7
9.7	37.7
10.1	37.7
10.8	38.0
11.4	37.9
11.8	37.9
12.3	38.3
13.5	38.6
15.3	38.9
18.1	38.9

SUMMARY DATA	
Bankfull Elevation:	38.7
Bankfull Cross-Sectional Area:	5.2
Bankfull Width:	9.5
Flood Prone Area Elevation:	39.7
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.0
Low Bank Height:	0.9
Mean Depth at Bankfull:	0.5
W / D Ratio:	17.6
Entrenchment Ratio:	10.5
Bank Height Ratio:	0.9



Stream Type	Eb 4
-------------	------




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 8, XS -1, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-0.5	515.5
1.9	515.1
4.1	514.9
6.1	514.6
8.4	514.1
9.9	513.8
10.6	513.5
11.1	513.4
12.0	513.5
12.8	513.6
14.6	514.2
16.4	514.7
18.9	515.2
20.8	515.4
21.9	515.6
24.5	515.9

SUMMARY DATA	
Bankfull Elevation:	514.9
Bankfull Cross-Sectional Area:	10.2
Bankfull Width:	14.0
Flood Prone Area Elevation:	516.4
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.5
Low Bank Height:	1.5
Mean Depth at Bankfull:	0.7
W / D Ratio:	19.1
Entrenchment Ratio:	7.2
Bank Height Ratio:	1.0



Stream Type	C 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 8, XS - 2, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.2	515.4
2.5	515.2
6.0	515.0
7.7	514.6
9.5	514.0
10.4	513.6
11.7	513.2
12.9	513.3
14.4	513.4
15.4	513.3
15.6	513.8
16.6	514.1
18.1	514.8
20.4	515.2
23.6	515.4
26.3	516.0

SUMMARY DATA	
Bankfull Elevation:	515.0
Bankfull Cross-Sectional Area:	13.9
Bankfull Width:	15.1
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.8
Low Bank Height:	1.7
Mean Depth at Bankfull:	0.9
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0








Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 8, XS - 3, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
-1.5	517.5
2.6	517.0
5.0	516.8
6.0	516.5
6.6	516.4
7.3	516.2
8.0	516.2
8.5	515.9
9.2	515.5
10.0	515.5
10.4	515.6
10.5	515.6
11.5	515.7
12.7	516.1
15.3	516.8
18.8	517.2
20.1	517.4

SUMMARY DATA	
Bankfull Elevation:	516.9
Bankfull Cross-Sectional Area:	8.3
Bankfull Width:	12.3
Flood Prone Area Elevation:	518.3
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.4
Low Bank Height:	1.3
Mean Depth at Bankfull:	0.7
W / D Ratio:	18.4
Entrenchment Ratio:	8.1
Bank Height Ratio:	0.9



Stream Type	C 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 8, XS - 4, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	517.5
2.3	517.0
5.4	516.9
7.3	516.4
9.2	516.1
10.1	515.5
10.4	515.3
10.9	515.3
11.1	515.3
11.9	515.4
12.2	515.6
13.1	516.0
14.5	516.5
15.6	516.8
17.9	517.1
21.2	517.6

SUMMARY DATA	
Bankfull Elevation:	517.0
Bankfull Cross-Sectional Area:	9.1
Bankfull Width:	13.5
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.7
Low Bank Height:	1.7
Mean Depth at Bankfull:	0.7
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	1.0







Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 8, XS -5, Riffle
Feature	Riffle
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	519.1
3.2	518.8
4.5	518.8
6.5	518.4
8.7	517.8
9.3	517.7
10.3	517.7
10.8	517.7
11.2	517.6
11.8	517.8
11.9	517.8
12.2	517.9
13.0	518.1
14.2	518.4
16.6	518.8
21.4	519.2

SUMMARY DATA	
Bankfull Elevation:	518.7
Bankfull Cross-Sectional Area:	6.4
Bankfull Width:	11.3
Flood Prone Area Elevation:	519.8
Flood Prone Width:	100.0
Max Depth at Bankfull:	1.1
Low Bank Height:	1.2
Mean Depth at Bankfull:	0.6
W / D Ratio:	19.9
Entrenchment Ratio:	8.8
Bank Height Ratio:	1.1



Stream Type	C 4




Site	Warren Wilson
Watershed:	French Broad, 06010105
XS ID	UT 8, XS - 6, Pool
Feature	Pool
Date:	6/21/2022
Field Crew:	Perkinson, Adams, D. Lewis

Station	Elevation
0.0	519.4
3.8	519.1
6.0	518.7
7.2	518.2
8.3	518.1
9.5	517.9
10.1	517.5
11.3	517.3
12.1	517.1
12.7	517.0
14.0	517.2
14.5	517.4
15.7	517.6
16.9	518.3
18.4	518.7
21.0	519.1
25.3	519.5

SUMMARY DATA	
Bankfull Elevation:	518.8
Bankfull Cross-Sectional Area:	13.1
Bankfull Width:	14.0
Flood Prone Area Elevation:	NA
Flood Prone Width:	NA
Max Depth at Bankfull:	1.9
Low Bank Height:	1.8
Mean Depth at Bankfull:	0.9
W / D Ratio:	NA
Entrenchment Ratio:	NA
Bank Height Ratio:	0.9



Stream Type	C 4



Appendix E – Hydrology Data

Tables 15A-C Channel Evidence
Table 16. Verification of Bankfull Events
Table 17A-B. Groundwater Hydrology Data
Groundwater Gauge Graphs
Figure E-1. Year 3 (2022) Soil Temperature Data

Table 15A. UT3 Channel Evidence

UT3 Channel Evidence	Year 1 (2020)	Year 2 (2021)	Year 3 (2022)	Year 4 (2023)	Year 5 (2024)	Year 6 (2025)	Year 7 (2026)
Max consecutive days channel flow	159	173	N/A**				
Presence of litter and debris (wracking)	Yes	Yes	Yes				
Leaf litter disturbed or washed away	Yes	Yes	Yes				
Matted, bent, or absence of vegetation (herbaceous or otherwise)	Yes	Yes	Yes				
Sediment deposition and/or scour indicating sediment transport	Yes	Yes	Yes				
Water staining due to continual presence of water	Yes	Yes	Yes				
Formation of channel bed and banks	Yes	Yes	Yes				
Sediment sorting within the primary path of flow	Yes	Yes	Yes				
Sediment shelving or a natural line impressed on the banks	Yes	Yes	Yes				
Change in plant community (absence or destruction of terrestrial vegetation and/or transition to species adapted for flow or inundation for a long duration, including hydrophytes)	Yes	Yes	Yes				
Development of channel pattern (meander bends and/or channel braiding) at natural topographic breaks, woody debris piles, or plant root systems	Yes	Yes	Yes				
Exposure of woody plant roots within the primary path of flow	No	No	No				
Other:							

^{**} All three flow gauges failed during the 2022 season, and data was not able to be recovered from them. These flow gauges will be replaced prior to year 4 (2023).

Table 15B. UT6 Channel Evidence

UT6 Channel Evidence	Year 1 (2020)	Year 2 (2021)	Year 3 (2022)	Year 4 (2023)	Year 5 (2024)	Year 6 (2025)	Year 7 (2026)
Max consecutive days channel flow	33*	198	N/A**				
Presence of litter and debris (wracking)	Yes	Yes	Yes				
Leaf litter disturbed or washed away	Yes	Yes	Yes				
Matted, bent, or absence of vegetation (herbaceous or otherwise)	Yes	Yes	Yes				
Sediment deposition and/or scour indicating sediment transport	Yes	Yes	Yes				
Water staining due to continual presence of water	Yes	Yes	Yes				
Formation of channel bed and banks	Yes	Yes	Yes				
Sediment sorting within the primary path of flow	Yes	Yes	Yes				
Sediment shelving or a natural line impressed on the banks	Yes	Yes	Yes				
Change in plant community (absence or destruction of terrestrial vegetation and/or transition to species adapted for flow or inundation for a long duration, including hydrophytes)	Yes	Yes	Yes				
Development of channel pattern (meander bends and/or channel braiding) at natural topographic breaks, woody debris piles, or plant root systems	Yes	Yes	Yes				
Exposure of woody plant roots within the primary path of flow	No	No	No				
Other:							

^{*}The gauge was installed August 1, 2020. Based on precipitation data, adjacent groundwater gauge data (Gauge 9), and other Site stream gauge data, it is expected to have flowed consecutively for much of the year 1 (2020) monitoring period.

^{**} All three flow gauges failed during the 2022 season, and data was not able to be recovered from them. These flow gauges will be replaced prior to year 4 (2023).

Table 15C. UT8 Channel Evidence

UT8 Channel Evidence	Year 1 (2020)	Year 2 (2021)	Year 3 (2022)	Year 4 (2023)	Year 5 (2024)	Year 6 (2025)	Year 7 (2026)
Max consecutive days channel flow	241	161	N/A**				
Presence of litter and debris (wracking)	Yes	Yes	Yes				
Leaf litter disturbed or washed away	Yes	Yes	Yes				
Matted, bent, or absence of vegetation (herbaceous or otherwise)	Yes	Yes	Yes				
Sediment deposition and/or scour indicating sediment transport	Yes	Yes	Yes				
Water staining due to continual presence of water	Yes	Yes	Yes				
Formation of channel bed and banks	Yes	Yes	Yes				
Sediment sorting within the primary path of flow	Yes	Yes	Yes				
Sediment shelving or a natural line impressed on the banks	Yes	Yes	Yes				
Change in plant community (absence or destruction of terrestrial vegetation and/or transition to species adapted for flow or inundation for a long duration, including hydrophytes)	Yes	Yes	Yes				
Development of channel pattern (meander bends and/or channel braiding) at natural topographic breaks, woody debris piles, or plant root systems	Yes	Yes	Yes				
Exposure of woody plant roots within the primary path of flow	No	No	No				
Other:							

^{**} All three flow gauges failed during the 2022 season, and data was not able to be recovered from them. These flow gauges will be replaced prior to year 4 (2023).

Table 16. Verification of Bankfull Events

Date of Data Collection	Date of Occurrence	Method	Photo (if available)	Monitoring Year
May 20, 2020	May 20, 2020	Stream gauges and trail cameras captured a bankfull event at UT8 after 4.47 inches of rain was documented between May 19 and 20, 2020 at a nearby weather station.	1	MY1
November 4, 2020	October 27, 2020	Wrack and laid-back vegetation were observed outside the TOB of UT3 after 4.7 inches of rain was documented between October 27 and 28, 2020 at a nearby weather station.	2	MY1
January 26, 2021	January 26, 2021	Wrack and laid-back vegetation were observed outside the TOB of UT6 after 0.5 inches of rain was documented January 26, 2021 at an onsite rain gauge.	3	MY2
April 6, 2021	March 31, 2021	Wrack and laid-back vegetation were observed outside the TOB of UT7 after 1.09 inches of rain was documented March 31, 2021 at an onsite rain gauge.	4	MY2
October 13, 2022	September 6, 2022	Wrack and laid-back vegetation were observed along the TOB of UT3, UT5, and UT8 after 2.22 inches of rain was documented September 5-6, 2022 at an onsite rain gauge.	5, 6, 7	MY3
















Table 17A. Groundwater Hydrology Data: Mitigation Success (UT-3B, Little Berea/Clingman's)


	Typical Su	uccess Criteria Ad	chieved/Max Co	nsecutive Day	s During Growi	ng Season (Perc	entage)
Gauge	Year 1 (2020)	Year 2 (2021)	Year 3 (2022)	Year 4 (2023)	Year 5 (2024)	Year 6 (2025)	Year 7 (2026)
3	Yes/127 days (55.0%)	Yes/198 days (89.6%)	Yes/193 days (89.8%)				
4	Yes/32 days (13.9%)	Yes/198 days (89.6%)	Yes/193 days (89.8%)				
5	Yes/174 days (75.3%)	Yes/198 days (89.6%)	Yes/193 days (89.8%)				
6	Yes/93 days (40.3%)	Yes/198 days (89.6%)	Yes/193 days (89.8%)				
7	Yes/72 days (31.2%)	Yes/198 days (89.6%)	Yes/193 days (89.8%)				
8	Yes/231 days (100%)	Yes/198 days (89.6%)	Yes/101 days (47.0%)				


Table 17B. Groundwater Hydrology Data: Potential Wetland Loss Monitoring Areas


6	Typical S	uccess Criteria A	chieved/Max Co	nsecutive Da	ys During Growi	centage)	
Gauge	Year 1 (2020)	Year 2 (2021)	Year 3 (2022)	Year 4 (2023)	Year 5 (2024)	Year 6 (2025)	Year 7 (2026)
1	Yes/37 days (16.0%)	Yes/198 days (89.6%)	Yes/46 days (21.4%)				
2	Yes/61 days (26.4%)	Yes/198 days (89.6%)	Yes/194 days (90.2%)				
9	Yes/175 days (75.8%)	Yes/198 days (89.6%)	Yes/193 days (89.8%)				
10	No*/9 days (3.9%)	Yes/61 days (27.6%)	Yes/26 days (12.1%)				


^{*}Gauge was not installed until August 1, 2020. It is expected to have exceeded typical wetland success criteria had it been installed earlier in the growing season.





























Appendix F – Preconstruction Wetland Hydrology Data

Figure 3. Preconstruction Gauge Locations

Table 18. Preconstruction Groundwater Gauge Data Summary

Table 19. Preconstruction vs Postconstruction Gauge Analysis




Table 18. Preconstruction Groundwater Gauge Data Summary

	l reconstruction Groundwa					
Gauge	Success Criteria Achieved/ Max Consecutive Days During Growing Season (Percentage)					
dauge	2018 Data	2019 Data				
1A	No/21 days (9.8 percent)	Yes/57 days (27 percent)				
1B	No/9 days (4.2 percent)	Yes/50 days (23 percent)				
1C	No/3 days (1.4 percent)	No/3 days (1.4 percent) Yes/48 days (22 percent)				
2A	NA*					
2В	No/20 days (9.3 percent)	No/0 days (0 percent)				
2C	No/12 days (5.6 percent)	Yes/50 days (23 percent)				
3A	No/24 days (11.2 percent)	Yes/124 days (58 percent)				
3B	Yes/117 days (54.7 percent)	Yes/140 days (65 percent)				
3C	No/4 days (1.9 percent)	No/3 days (1.4 percent)				

^{*}Gauge 2A was damaged during 2018 and data was not recoverable. It was replaced in 2019.

Table 19.

WWC - Pre-construction Wetland Gauge Data vs Post-construction Gauge Data

Criteria

3B

3C

54.7%

1.9%

65.0%

1.4%

59.9%

1.7%

7

6

31.2%

40.3%

89.6%

89.6%

89.8%

89.8%

70.2%

73.2%

10.4%

71.6%

Jurisdictional wetland adjacent to UT-3 will demonstrate a 10 to 20% increase in wetland hydrology as compared to pre-construction hydrology, under similar climactic conditions.

Pre-	Construction -	Max Consectut	ive Days		Post-Construction - Max Consectutive Days			Percent		
Gauge	2018	2019	Avg.	Gauge	MY1 (2020)	MY2 (2021)	MY3 (2022)	Avg.	Improvement	Notes
1A	21	57	39							Develop in a series and in beautiful and Course 14
1B	9	50	29.5	2	61	198	194	151	287%	Percent improvement is based on Gauge 1/ average of 39 consecutive days
1C	3	3	3							
2A	NA	48	48	3	61	198	194	151	214%	Post-Construction gauges are location +/- 150' down stream from pre-construction gauges
2B	20	0	20	4	32	198	193	141	605%	
2C	12	50	31	5	174	198	193	188	506%	
3A	24	124	74	8	231	198	101	177	139%	Post-Construction gauges are location in approximately the same location as preconstruction gauges
3B	117	140	128.5	7	72	198	193	154	20%	
3C	4	3	3.5	6	93	198	193	161	4500%	
	Pre-Constructi	on - % Hydrope	riod		Post-Co	onstruction - % I	Hydroperiod		Improvement of	
Gauge	2018	2019	Avg.	Gauge	MY1 (2020)	MY2 (2021)	MY3 (2022)	Avg.	Hydroperiod %	Notes
1A	9.8%	27.0%	18.4%							
1B	4.2%	23.0%	13.6%	2	26.4%	89.6%	90.2%	68.7%	50.3%	Increase in % hydroperiod is based on Gauge 1A average of 18.4%
1C	1.4%	1.4%	1.4%							
2A	NA	22.0%	22.0%	3	55.0%	89.6%	89.8%	78.1%	56.1%	Post-Construction gauges are location +/-
2B	9.3%	0.0%	9.3%	4	13.9%	89.6%	89.8%	64.4%	55.1%	150' down stream from pre-construction gauges
2C	5.6%	23.0%	14.3%	5	75.3%	89.6%	89.8%	84.9%	70.6%	

approximately the same location as pre-

construction gauges

Appendix G – Site Photo Log



