

DIVISION OF AIR QUALITY
Ambient Monitoring Section
217 West Jones Street / 1641 Mail Service Center
Raleigh, NC 27699-1641

7/26/2022

QA BULLETIN NUMBER DAQ-17-011.2

TO:

Marshall Cannon, RRO Operator

DocuSigned by:

Marshall Cannon 7/19/2022

5A799BD9BE664DE...

Steve Helms, RRO Operator

DocuSigned by: 8/1/2022

Steve Helms

98C7F357AD974C5

Mark Yirka, ECB Electronics Technician

DocuSigned by:

Mark Yirka 8/1/2022

F8989D27AB17467...

THROUGH:

Patrick Bulter, AMS Chief

DocuSigned by: 7/18/2022

Patrick Bulter

4290A7E2D2A0429...

Joette Steger, PPB Supervisor

DocuSigned by:

Joette Steger 7/18/2022

Derrick House, ECB Supervisor

DocuSigned by:

Derrick House 8/1/2022

2BFD2E5865E148E...

Taylor Hartsfiend, RRO Air Quality Supervisor

DocuSigned by:

Taylor Hartsfield 7/18/2022

3193BD42A80246E...

Tim Skelding, RRO Monitoring Coordinator

DocuSigned by: 7/19/2022

Tim Skelding

B582CC3DF519469...

FROM:

Kay Roberts, PPB Chemist

DocuSigned by:

Kay Roberts 8/18/2022

BE4009EE242941D...

SUBJECT: Changes to Verification / Calibration Frequency

Revision to the Nitrogen Dioxide (NO₂) Verification/Calibration Frequency:

Upon receipt/adjustment/repair/ installation/ moving. Every 182 days and 2/ calendar year if manual zero/span performed biweekly.

The frequency change takes place immediately and will be added to the next SOP review and revision.

Replace and Discard Original	<input type="checkbox"/>
Add Material to Document	<input type="checkbox"/>
Retain this bulleting until further notice	<input checked="" type="checkbox"/>
Discard this bulleting after noting contents	<input type="checkbox"/>
This bulleting will be invalid after:	Click or tap to enter a date.
This bulletin will be incorporated into DAQ-###-##.2 (which will replace SOP-2.17.2 by	9/30/2022