

Civil Penalties Assessed During the Month of January 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Faye Earnheart 10304 Old Ardrey Kell Rd. Charlotte, NC Mecklenburg Co.	Earnheart's Service 10209 Providence Rd. W. Charlotte, NC Mecklenburg Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close three substandard UST systems.	\$5,854.52	1/23/07
William Timothy Rich 891 Wyburn Rd. McLeansville, NC Guilford Co.	Sprinkle Gas 1 2918 E. Market St. Greensboro, NC Guilford Co.	Violation of 15A NCAC 2N .0302 by failing to inspect the internal lining of six USTs within ten years of liner installation and every five years thereafter and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for six USTs.	\$6,672.18	1/29/07
Sheetz Inc. 5700 Sixth Ave. Altoona, PA Blair Co.	Sheetz Inc 385 2505 Somerset Center Dr. Winston Salem, NC Forsyth Co.	Violation of NCGS 143-215.94U by failing to hold an operating permit at a facility where petroleum products were caused to be placed.	\$1,428.36	1/22/07
CLI Transport, LP RR 1 Box 587 Claysburg, PA	Sheetz Inc 385 2505 Somerset Center Dr. Winston Salem, NC Forsyth Co.	Violation of NCGS 143-215.94U by placing petroleum product into USTs at a facility for which the owner or operator did not hold an operating permit.	\$1,433.00	1/19/07
Astley & Ethel Scarlett PO Box 404 Paw Creek, NC Mecklenburg Co.	Scarlett 66 Service Station 1030 Seigle Ave. Charlotte, NC Mecklenburg Co.	Violation of 15A NCAC 2N .0405 and .0803 by failing to assess a site at permanent closure and submit a UST closure report for six UST systems.	\$6,877.42	1/25/07
Judy Sigmon 5865 Springs Rd. Conover, NC Catawba Co.	Tommy Sigmon Facility 5865 Springs Rd. Conover, NC Catawba Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close two substandard UST systems.	\$3,890.94	1/30/07

Civil Penalties Assessed During the Month of February 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
C.R. Hassinger Grading Co., Inc. 709 Freedom Dr. Raleigh, NC  Wake Co.	C.R. Hassinger Grading Co., Inc. 709 Freedom Dr. Raleigh, NC  Wake Co.	Violation of 15A NCAC 2N .0402 by failing to have a qualified cathodic protection tester evaluate a cathodic protection systems for one UST and three steel piping systems at least once every three years, violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for three USTs and one suction piping system, violation of 15A NCAC 2N .0603 by failing to investigate a suspected release after environmental conditions indicate that a release may have occurred, and violation of NCGS 143-215.94U by failing to maintain a currently valid operating permit at a facility where petroleum product was caused to be placed.	\$15,108.32	2/26/07

Civil Penalties Assessed During the Month of March 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
TRS Properties, Inc. 4003 Gaston Ct. Greensboro, NC  Guilford Co.	TRS Mart 1418 W. Green Dr. High Point, NC  Guilford Co.	Violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for two USTs.	\$3,387.23	3/22/07
H. Richard & Elsie B. Callahan 874 E. Hwy. 74 Rockingham, NC  Richmond Co.	Callahan's Enterprises 874 E. Hwy. 74 Rockingham, NC  Richmond Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close five substandard UST systems.	\$7,836.86	3/26/07
James F. Keith II 13041 Falls of Neuse Rd. Wake Forest, NC  Wake Co.	Keith's Store 13041 Falls of Neuse Rd. Wake Forest, NC  Wake Co.	Violation of 15A NCAC 2N .0304 by failing to provide three USTs with secondary containment or enhanced leak detection and by failing to provide three steel piping systems with secondary containment.	\$8,270.90	3/21/07
Holding Oil Company, Inc. PO Box 648 Wake Forest, NC  Wake Co.	James Keith Grocery 13041 Falls of Neuse Rd. Wake Forest, NC  Wake Co.	Violation of 15A NCAC 2N .0304 by failing to provide two USTs with secondary containment or enhanced leak detection and by failing to provide steel or metal connected piping and ancillary equipment for two UST systems with secondary containment; violation of 15A NCAC 2N .0502 by failing to comply with leak detection requirements for two USTs and two suction piping systems; violation of 15A NCAC 2N .0603 by failing to investigate a suspected release after environmental conditions indicate a release may have occurred; and violation of NCGS 143-215.94U by failing maintain a currently valid operating permit at a facility where petroleum product is caused to be placed.	\$18,770.90	3/19/07

Civil Penalties Assessed During the Month of April 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Kurz Transfer Products, LP 3200 Woodpark Blvd. Charlotte, NC  Mecklenburg Co.	Kurz Transfer Products 939 N. NC Hwy 150 Lexington, NC  Davidson Co.	Violation of 15A NCAC 2N .0302 by failing to provide corrosion protection for two steel underground piping systems; and violation of 15A NCAC 2N .0503 by failing to provide secondary containment for two hazardous substance USTs and associated piping systems.	\$11,818.87	4/9/07
Ram Marketing, Inc. P.O. Box 842 Moravian Falls, NC  Wilkes Co.	U Filler Up 309 Carolina Ave. Maiden, NC  Catawba Co.	Violation of 15A NCAC 2N .0302 by failing to provide spill prevention for five UST systems; violation of 15A NCAC 2N .0402 by failing to operate and maintain a corrosion protection system for five UST systems, by failing to have a qualified corrosion protection tester evaluate a cathodic protection system at least once every three years, and by failing to inspect a cathodic protection system every sixty days; violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for five USTs, three pressurized piping systems, and two suction piping systems; and violation of 15A NCAC 2N .0505 by failing to conduct an annual test of the operation of three ALLDs associated with three pressurized piping systems.	\$16,279.20	4/9/07
Kyle's Friendly Service, Inc. 127 Blue Bell Rd. Greensboro, NC  Guilford Co.	Hwy 29 BP 4736 NC Hwy 29 N. Greensboro, NC  Guilford Co.	Violation of NCGS 143-215.94U by placing petroleum products into USTs at a facility for which it did not hold a valid operating permit.	\$4,691.12	4/18/07
Marshall Oil Group, LLC P.O. Box 128 Zebulon, NC  Wake Co.	Hopedale Market 384 810 Deep Creek Ch. Rd. Burlington, NC  Alamance Co.	Violation of 15A NCAC 2N .0801 by failing to secure and maintain five UST systems in temporary closure.	\$5,446.16	4/30/07
Douglas Allen Haneline 2107 Amity Hill Rd. Statesville, NC  Iredell Co.	Haneline Country Store 870 S. Main St. Troutman, NC  Iredell Co.	Violation of 15A NCAC 2N .0302 by failing to ensure the integrity of three UST systems prior to installing corrosion protection, violation of 15A NCAC 2N .0402 by failing to operate and maintain a corrosion protection system to continuously provide corrosion protection for three UST systems, violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for three USTs, and violation of 15A NCAC 2N .0801 by failing to secure and maintain three UST systems in temporary closure.	\$15,346.07	4/18/07
Quality Oil Company 203 W. Broad Ave. Rockingham, NC  Richmond Co.	Otuel's Food-N-Fuel 701 E. Broad St. Rockingham, NC  Richmond Co.	Violation of 15A NCAC 2N .0302 and .0402 by failing to comply with corrosion protection requirements for five UST systems, violation of 15A NCAC 2N .0302 by failing to comply with corrosion protection requirements for metal flexible connectors and ancillary equipment for five piping systems, violation of 15A NCAC 2N .0502 by failing to meet leak detection requirements for one suction piping system, and violation of 15A NCAC 2N .0601 and .0603 by failing to report and investigate a suspected release.	\$11,831.40	4/23/07

Civil Penalties Assessed During the Month of May 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
ATC Leasing Company, LLC 4316 39th Ave. Kenosha, WI Kenosha Co.	Auto Truck Transport Corp. 320 Bear Poplar Rd. Cleveland, NC Rowan Co.	Violation of 15A NCAC 2N .0301, .0402, and .0405 by failing to demonstrate compliance with corrosion protection requirements for two UST systems; violation of 15A NCAC 2N .0301 by failing to demonstrate compliance with overfill control requirements for two UST systems; violation of 15A NCAC 2N .0502 by failing to conduct leak detection for two pressurized piping systems; and violation of 15A NCAC 2N .0505 by failing to conduct an annual test of the operation of two automatic line leak detectors associated with pressurized piping systems.	\$10,923.64	5/2/07

Civil Penalties Assessed During the Month of June 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Mecklenburg Co. 600 E. 4th St. Charlotte, NC Mecklenburg Co.	Mecklenburg Co. Jail 801 E. 4th St. Charlotte, NC Mecklenburg Co.	Violation of 15A NCAC 2N .0301 by failing to demonstrate compliance with corrosion protection requirements for a UST piping system and violation of 15A NCAC 2N .0601 and .0603 by failing to report and investigate a suspected release after an unusual operating condition was observed within a containment sump.	\$4,573.52	6/29/0

Civil Penalties Assessed During the Month of July 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Ginger E. Cox 800 Fisher Ferry Rd. Thomasville, NC  Davidson Co.	Fisher Ferry 76 800 Fisher Ferry Rd. Thomasville, NC  Davidson Co.	Violation of 15A NCAC 2N .0302 by failing to inspect two UST internal liners and by failing to provide corrosion protection for flexible connectors associated with two piping systems and violation of 15A NCAC 2N .0801 by failing to secure and maintain two UST systems in temporary closure.	\$9,540.36	7/2/07
Kyle's Friendly Service, Inc. 127 Blue Bell Rd. Greensboro, NC  Guilford Co.	Kyle's Aycock St. Texaco 822 S. Aycock St. Unit A Greensboro, NC  Guilford Co.	Violation of 15A NCAC 2N .0301 by failing to demonstrate compliance with overfill control and corrosion protection requirements for two UST systems and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for two USTs.	\$10,778.88	7/2/07
JSK Group, Inc. 1339 Baxter St. Ste. 200 Charlotte, NC  Mecklenburg Co.	Gas N Go 13209 Carolwinds Blvd. Charlotte, NC  Mecklenburg Co.	Violation of 15A NCAC 2N .0302 by failing to comply with corrosion protection requirements for metal flexible connectors and piping and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for three USTs.	\$6,175.56	7/2/07

Civil Penalties Assessed During the Month of August 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Ronald G. Overcash 1150 Shelton Rd. Concord, NC  Cabarrus Co.	Overcash Gravel & Grading, Inc. 1150 Shelton Rd. Concord, NC  Cabarrus Co.	Violation of 15A NCAC 2L .0405 by failing to submit a Limited Site Assessment report.	\$9,301.66	8/10/07
Dawn I. Saeed 1269 N NC Hwy 109 Thomasville, NC  Davidson Co.	Big R Food Store 1269 N NC Hwy 109 Thomasville, NC  Davidson Co.	Violation of 15A NCAC 2N .0302 by failing to provide corrosion protection for three UST systems; violation of 15A NCAC 2N .0502 by failing to conduct a valid method of leak detection for three USTs and by failing to meet leak detection requirements for three suction piping systems; and violation of 15A NCAC 2N .0405, .0802, and .0803 by failing to properly permanently close a UST system and submit a UST closure report.	\$11,641.72	8/15/07
Leslie Hinshaw 414 Candlewood Rd. Liberty, NC  Randolph Co.	H&M Tire Service 232 N. Greensboro St. Liberty, NC  Randolph Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close six UST systems in temporary closure.	\$7,345.36	8/28/07
Robert Coleman 1005 Rowan Ter. Rockingham, NC  Richmond Co.	Robert Coleman Exxon (former) 508 Fayetteville Rd. Rockingham, NC  Richmond Co.	Violation of 15A NCAC 2L .0405 [formerly 2L .0115(c)(4)] by failing to submit a Limited Site Assessment report.	\$4,418.88	8/20/07
People's Gas & Oil Company, Inc. 209 N. Patterson St. Maxton, NC  Robeson Co.	Maxton Mobile (former) N. Patterson & Martin Luther King Dr. Maxton, NC  Robeson Co.	Violation of 15A NCAC 2L .0405 by failing to submit a Limited Site Assessment report.	\$8,497.36	8/30/07
Wellons Construction, Inc. 510 N. Powell Ave. Dunn, NC  Harnett Co.	Wellons Construction, Inc. 510 N. Powell Ave. Dunn, NC  Harnett Co.	Violation of 15A NCAC 2N .0405 and .0803 by failing to assess a site after the permanent closure of a UST system and submit a UST closure report.	\$5,139.94	8/28/07
Quality Oil Company (aka Swink Quality Oil Company) 203 W. Broad St.  Rockingham, NC  Richmond Co.	Callahan's Enterprises 874 E. Hwy 74 Rockingham, NC  Richmond Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close three substandard UST systems.	\$9,346.50	8/16/07

Civil Penalties Assessed During the Month of September 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
William C. Wade 1300 Patterson Ave. Winston Salem, NC  Forsyth Co.	Wade's Amoco Station 1300 Patterson Ave. Winston Salem, NC  Forsyth Co.	Violation of 15A NCAC 2N .0405 [formerly 2L .0115(c)(4)] by failing to submit a Limited Site Assessment report.	\$8,090.76	9/18/07
Chandrakant N. Patel P.O. Box 685 Holly Springs, NC  Wake Co.	Quality Food Mart 300 N. Main St. Holly Springs, NC  Wake Co.	Violation of 15A NCAC 2N .0402 by failing to operate and maintain a cathodic protection system to continuously provide corrosion protection for four UST systems and by failing to inspect an impressed current cathodic protection system every sixty days, and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for one suction piping system.	\$8,899.96	9/19/07
David Wayne Allen 2825 Elizabeth Ave. Shelby, NC  Cleveland Co.	Doug's Mini Mart 3321 Polkville Rd. Shelby, NC  Cleveland Co.	Violation of 15A NCAC 2N .0801 by failing to secure and maintain five UST systems in temporary closure.	\$5,360.10	9/4/07
Samah Z Al Shara 3900 Burlington Mills Rd. Wake Forest, NC  Wake Co.	Eddins Grocery 3900 Burlington Mills Rd. Wake Forest, NC  Wake Co.	Violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for two USTs and two suction piping systems.	\$8,341.00	9/4/07
Ushaben C. and Chhanal B. Patel 1155 Salisbury Rd. Statesville, NC  Iredell Co.	USA Mart 1155 Salisbury Rd. Statesville, NC  Iredell Co.	Violation of 15A NCAC 2N .0402 by failing to inspect an impressed current cathodic protection system every sixty days, and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for five USTs and two suction piping systems.	\$8,322.52	9/12/07
Kyle's Friendly Service, Inc. 127 Blue Bell Rd. Greensboro, NC  Guilford Co.	Kyle's N. Elm 3602 N. Elm St. Greensboro, NC  Guilford Co.	Violation of 15A NCAC 2N .0301 by failing to demonstrate compliance with corrosion protection requirements for metal ancillary piping associated with one UST system and by failing to demonstrate compliance with overflow control requirements for one UST system, and violation of 15A NCAC 2N .0603 by failing to investigate three suspected releases.	\$11,995.82	9/24/07

**Civil Penalties Assessed During the Month of October 2007**

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Carl Vick 84 Dickie Dr. Henderson, NC  Franklin Co.	Ingleside Grocery 3573 NC Hwy 39 N. Louisburg, NC  Franklin Co.	Violation of 15A NCAC 2N .0405 [formerly 2L .0115(c)(4)] by failing to submit a Limited Site Assessment report.	\$6,513.47	10/8/07
Rose Oil Company, Inc. PO Box 706 Henderson, NC  Vance Co.	Cokesbury Food Mart 1374 S. Cokesbury Rd. Henderson, NC  Vance Co.	Violation of NCGS 143-215.94U by placing petroleum product in a UST system at a facility for which the owner or operator did not hold a currently valid operating permit.	\$3,163.54	10/15/07
Monroe Snyder 823 W. Center St. Lexington, NC  Davidson Co.	Monroe Service Center Snyder's Phillips 66 823 W. Center St.  Lexington, NC Davidson Co.	Violation of 15A NCAC 2L .0405 by failing to submit a Limited Site Assessment report.	\$11,302.84	10/24/07
S&W Trading Post, Inc. 1196 Waughtown St. Winston Salem, NC  Forsyth Co.	Waughtown Auto Sales 1196 Waughtown St. Winston Salem, NC  Forsyth Co.	Violation of 15A NCAC 2L .0405 by failing to submit a Limited Site Assessment report.	\$4,266.68	10/8/07
Yoco, Inc. PO Box 78 White Plains, NC  Surry Co.	Neighbors Store 9 8400 Norcross Rd. Greensboro, NC  Guilford Co.	Violation of 15A NCAC 2N .0302 by having a single-walled UST system component (diesel piping at dispenser) located within 100 feet of a well serving a public water system; violation of 15A NCAC 2N .0304 by failing to provide secondary containment or enhanced leak detection for seven UST systems or UST system components located between 100 and 500 feet of a well serving a public water system and by failing to provide secondary containment for steel or metal connected piping and ancillary equipment associated with one UST system (kerosene UST) located between 100 and 500 feet of a well serving a public water system; violation of 15A NCAC 2N .0402 by failing to operate and maintain a corrosion protection system to continuously provide corrosion protection for one UST system (kerosene UST); and violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for two USTs (regular gasoline USTs).	\$19,996.23	10/15/07
Guilford Lakes Aviation LLC 150 Air Harbor Rd. Greensboro, NC  Guilford Co.	Air Harbor Airport 150 Air Harbor Rd. Greensboro, NC  Guilford Co.	Violation of 15A NCAC 2N .0303 by failing to update registration information for one UST system, violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for one UST, violation of 15A NCAC 2N .0801 by failing to maintain and secure a UST system in temporary closure, and violation of NCGS 143-215.94U by failing to maintain a currently valid operating permit at a facility where petroleum product was caused to be placed.	\$8,584.27	10/22/07
Jeffrey Karl Phipps 1211 N. Main St. Mocksville, NC  Davie Co.	Gunters II 981 N. Main St. Mocksville, NC  Davie Co.	Violation of 15A NCAC 2N .0801n by failing to permanently close four substandard UST systems.	\$5,342.64	10/30/07
Senia Parker 2917 Field St. Raleigh, NC  Wake Co.	Parker's Trading Post 1001 Pearces Rd. Zebulon, NC  Wake Co.	Violation of 15A NCAC 2N .0405 [formerly 2L .0115(c)(4)] by failing to submit a Limited Site Assessment report.	\$4,128.65	10/24/07

Civil Penalties Assessed During the Month of November 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Robert Lewis Gibbs, Sr. 415 S. Caldwell Ave. Newton, NC  Catawba Co.	Newton Mustang 601 East D. St. Newton, NC  Catawba Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close seven substandard UST systems.	\$7,394.68	11/30/07
Robert B. Wilson 409 Country Club Dr. Stoneville, NC  Rockingham Co.	Robert Wilson Service 2209 E. Bessemer Ave. Greensboro, NC  Guilford Co.	Violation of 15A NCAC 2N .0302 by failing to provide corrosion protection for a flexible connector on piping; violation of 15A NCAC 2N .0303 by failing to update registration information for four UST systems; violation of 15A NCAC 2N .0402 by failing to have a qualified cathodic protection tester evaluate a cathodic protection system every three years and by failing to inspect an impressed current cathodic protection system every sixty days; violation of 15A NCAC 2N .0601 and .0603 by failing to report and investigate two suspected releases; and violation of 15A NCAC 2N .0801 by failing to maintain and secure four UST systems in temporary closure.	\$17,179.28	11/30/07

Civil Penalty Assessments December 2007

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
James M. Logan 6095 Santa Maria Dr. Winston Salem, NC  Forsyth Co.	Joyner Wrecking & Grading Co. 4002 Indiana Ave. Winston Salem, NC  Forsyth Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close two substandard UST systems.	\$5,335.84	12/10/07
J.L. Carpenter, Jr. Sarah Carpenter 779 Hickory Hollow Rd.  Gaston, NC  Northampton Co.	Big John's 4210 Big John's Store Rd. Pleasant Hill, NC  Northampton Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close four substandard UST systems.	\$7,454.72	12/31/07
Diversified Investment and Growth, LLC 205 Lochside Dr. Cary, NC  Wake Co.	Petrol Mart 6 3900 New Bern Ave. Raleigh, NC  Wake Co.	Violation of 15A NCAC 2N .0402 by failing to operate and maintain a corrosion protection system to continuously provide corrosion protection for four UST systems, by failing to have a qualified cathodic protection tester evaluate an impressed current cathodic protection system at least every three years and to submit a UST-7 notification form, and by failing to inspect an impressed current cathodic protection system every sixty days; violation of 15A NCAC 2N .0502 and .0506 by failing to comply with leak detection requirements for four USTs and three pressurized piping systems; and violation of 15A NCAC 2N .0505 by failing to conduct an annual test of the operation of three automatic line leak detectors.	\$15,897.00	12/26/07
Bowers & Burrows, Inc. PO Box 137 Henderson, NC  Vance Co.	L&R Quick Stop 6809 Mitchell Mill Rd. Zebulon, NC  Wake Co.	Violation of 15A NCAC 2N .0801 by failing to secure and maintain four UST systems in temporary closure.	\$5,299.68	12/26/07
Hooker Oil Co., Inc. PO Box 640 Aurora, NC  Beaufort Co.	South Creek Marina 161 Muddy Creek Rd. Aurora, NC  Beaufort Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close one substandard UST system.	\$9,869.76	12/31/07
Joseph Steven King 66 Matthews Dr. Henderson, NC  Vance Co.	East End Amoco 531 E. Andrews Ave. Henderson, NC  Vance Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close four substandard UST systems.	\$8,023.14	12/31/07
George Tate, Jr. Ester W. Tate 342 W. Rosemary St.  Chapel Hill, NC  Durham Co.	Dal's Amoco 3101 Fayetteville St. Durham, NC  Durham Co.	Violation of 15A NCAC 2N .0801 by failing to permanently close three substandard UST systems.	\$7,979.28	12/31/07
Satyam Corporation 3301 High Point Rd. Greensboro, NC  Guilford Co.	Snack N Soda 3 1409 S. Elm-Eugene St. Greensboro, NC  Guilford Co.	Violation of 15A NCAC 2N .0301 by failing to meet spill prevention requirements for one UST system and by failing to demonstrate compliance with overflow control requirements for three UST systems, and violation of 15A NCAC 2N .0502 by failing to comply with leak detection requirements for three pressurized piping systems.	\$7,085.81	12/27/07