

DIVISION OF AIR QUALITY
Ambient Monitoring Section
217 West Jones Street / 1641 Mail Service Center
Raleigh, NC 27699-1641

2/21/2022

QA BULLETIN NUMBER DAQ-17-004

TO: Chaitali Bhaumik (LAB Chemist): DocuSigned by: Chaitali Bhaumik 3/2/2022
BE2629DB877140F...

Nathan Miller (LAB Chemistry Tech.): DocuSigned by: Nathan Miller 3/2/2022
A575C2DC109A4CA...

THROUGH: Patrick Butler (AMS Chief): DocuSigned by: Patrick Butler 2/21/2022
4290A7E2D2A0429...

Jim Bowyer (LAB Supervisor): DocuSigned by: Jim Bowyer 3/2/2022
C96894826C9B41D...

Joette Steger (PPB Supervisor): DocuSigned by: Joette Steger 2/21/2022
B278F8186CEC4DC...

FROM: Steven Walters (PPB Chemist): DocuSigned by: Steven Walters 2/21/2022
AE6DEE7D0265442...

SUBJECT: Urban Air Toxics (UAT) and Photochemical Assessment Monitoring Station (PAMS) Carbonyl Analysis Criteria Update

This Quality Assurance (QA) memo intends to clarify different quality control limits listed in the UAT and PAMS Carbonyl QA Summary Report (DAQ-03-016) and table 5.5.5 in Standard Operating Procedure (SOP)# DAQ-03-004.2. The QA summary report compares the correct quality control limit (reported method detection limit value) but the table in the SOP lists the incorrect quality control limit (method detection limit spike value). This change will be made to table 5.5.3 in SOP# DAQ-03-004.2 during the next SOP review.

Replace and Discard Original	<input type="checkbox"/>
Add Material to Document	<input type="checkbox"/>
Retain this bulleting until further notice	<input checked="" type="checkbox"/>
Discard this bulleting after noting contents	<input type="checkbox"/>
This bulleting will be invalid after:	Click or tap to enter a date.
This bulletin will be incorporated into SOP# DAQ-03-004.2 by	9/30/2022