ROY COOPER Governor ELIZABETH S. BISER Secretary S. DANIEL SMITH Director



November 4, 2021

Robyn L Gross, Americas Asset Director Management Badin Business Park LLC 201 Isabella St, Suite 500 Pittsburgh, PA 15212-5858

SUBJECT: NOTICE OF DEFICIENCY

Tracking Number: NOD-2021-LV-0201

Permit No. NC0004308 Badin Business Park Stanly County

Dear Ms. Gross:

A review of the September 2021 Discharge Monitoring Report (DMR) for the subject facility revealed the deficiency(s) indicated below:

## **Limit Exceedance Deficiency(s):**

Sample Location	Parameter	Date	Limit Value	Reported Value	Type of Deficiency
005 Effluent	Fluoride, Total (as F) (00951)	9/30/2021	1.8	1.93	Monthly Average Exceeded

Please be aware that non-compliance with your permit could result in enforcement action by the Division of Water Resources for these and any additional violations of State law. The Mooresville Regional Office encourages you to take all necessary actions to bring your facility into compliance.

If you should need any assistance or would like to discuss this non-compliance situation, please contact Roberto Scheller of the Mooresville Regional Office at 704-663-1699.

Sincerely,



W. Corey Basinger, Regional Supervisor Water Quality Regional Operations Section Mooresville Regional Office Division of Water Resources, NCDEQ

Cc: WQS Mooresville Regional Office - Enforcement File NPDES Compliance/Enforcement Unit - Enforcement File