Underground Storage Tanks (USTs) Public Record - Summary Information

General Information

Public Record Posted Date: 12/19/2023

Total Number Of Active UST Facilities: 7,187

Total Number Of USTs: 23,370

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 2,895

Inspection Period Dates: 10/1/2022 To: 10/1/2023

Percent Compliance (Combined Measure): 61%

Summary Information For Releases

Number Of Confirmed UST Releases: 158

Release Reporting Period Dates 10/1/2022 To: 10/1/2023

Summary Information For Release Sources And Causes

	Cause															
Source			Spill		Overfill		Corrosion		Phys/Mech Damage		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	73	46%	0	0%	0	0%	11	15%	20	27%	0	0%	2	3%	40	55%
Piping	23	15%	1	4%	0	0%	2	9%	17	74%	0	0%	0	0%	3	13%
Dispenser	21	13%	1	5%	0	0%	2	10%	8	38%	1	5%	2	10%	7	33%
STP**	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery Problem		40/	•	•	•			00/		00/	•	00/		001	•	20/
	1	1%	0	0%	-	0%	0			0%	0	0%	-	0%	0	0%
Other	19	12%	1	5%	1	5%	0	0%	7	37%	0	0%	6	32%	4	21%
Unknown	21	13%	0	0%	0	0%	1	5%	0	0%	0	0%	0	0%	20	95%
Totals	158	100%	3	2%	1	1%	16	10%	53	34%	1	1%	10	6%	74	47%

^{*}Additionally, there were 225 confirmed releases from non-regulated USTs, primarily heating oil tanks. There are also 274 confirmed releases from non-usts during the reporting period.

To obtain site-specific information on UST releases contact the Regional DEQ Office for the county in which the release occurred. To obtain UST compliance information contact the UST Section Central Office, Permits and Inspection Branch

^{**}STP - Submersible Turbine Pump