031 361	vice Prov	vider List (All) - Corrosion Pro		Simpariles Only	
Company		Listing Submitte	d 5/17/2021	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889				Mountains (West of I-77): Yes	
	W	ebsite <u>www.aes-nc.com</u>			
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	Yes
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 4/15/2021	Area of state conducts work	
American UST Compliance Testing		Phone (919) 777-8543		Coastal (East of I-95): Yes	
180 BPW Club Rd. A-1		Fax		Central (West of I-95 and East of I-77): Yes	
Carrboro, NC 27510				Mountains (West of I-77): Yes	
	W	ebsite		Mountains (west of 1-77): Tes	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
			Nie		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
	No No	Waste Disposal and Treatment: Other:	NO		

UST Serv	vice Prov	rider List (All) - Corrosion Prot	ection Co	ompanies Only	
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Bay Compliance and Testing LLC	P	Phone (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	We	bsite https://baycomplianceandtesting.com/			
Comp	oliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/10/2022	Area of state conducts work	
		U			
Bunnell-Lammons Engineering, Inc.	P	Phone (828) 277-0100		Coastal (East of I-95): Yes	
130 Oval Road	P	*		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
		Phone (828) 277-0100 Fax (828) 277-0110			
130 Oval Road Arden, NC 28704	We	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
130 Oval Road Arden, NC 28704	We bliance Testin	Phone (828) 277-0100 Fax (828) 277-0110 Phone (828) 277-0110 Phone (828) 277-0110 Phone (828) 277-0110 Phone (828) 277-0100 Phone (828) 277-0110 Phone (828) 277-010 Phone (828)		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing:	We Dliance Testin <u>Yes</u>	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	We bliance Testin Yes (Yes (Phone (828) 277-0100 Fax (828) 277-0110 bosite www.blecorp.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	We bliance Testin Yes (Yes (Yes (Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We bliance Testin Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
130 Oval Road Arden, NC 28704 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	We <u>Pliance Testin</u> <u>Yes</u> <u>Yes</u> <u>Yes</u> <u>Yes</u>	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
130 Oval Road Arden, NC 28704 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	We Diance Testin Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	We Diance Testin Yes Yes Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testin Yes Yes Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er	We pliance Testin Yes Yes Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 Phosite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	We Diance Testin Yes Yes Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	Yes Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	We pliance Testin Yes Yes Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
130 Oval Road Arden, NC 28704 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	We pliance Testin Yes Yes Yes Yes Yes Yes Yes Ves Ves Ves Ves Ves Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	We pliance Testin Yes Yes Yes Yes Yes Yes Yes Ves Ves Ves Ves Ves Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Serv	vice Pro	ovider List (All) - Corrosion Prot	ection Co	ompanies Only	
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc.		Phone (423) 895-1500		Coastal (East of I-95): Yes	6
916 Egypt Rd.		Fax		Central (West of I-95 and East of I-77): Yes	6
Bluff City, NC 37618				Mountains (West of I-77): Yes	6
	V	Vebsite			
Com	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/14/2021	Area of state conducts work	
Company Cobb Environmental & Technical Services, Inc	c.	Listing Submitted Phone (662) 841-0995	5/14/2021	Area of state conducts work Coastal (East of I-95): Yes	6
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802	.		5/14/2021		
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street		Phone (662) 841-0995 Fax (662) 841-0810	5/14/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	6
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802		Phone (662) 841-0995	5/14/2021	Coastal (East of I-95): Yes	6
Cobb Environmental & Technical Services, Ind P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804	v	Phone (662) 841-0995 Fax (662) 841-0810	5/14/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	8
Cobb Environmental & Technical Services, Ind P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804	v	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check:	5/14/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	8
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	V pliance Tes	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	5
Comparison Containment Sump Testing: Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts:	V <u>pliance Tes</u> <u>Yes</u>	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	3 3 <u>Yes</u>
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	V <mark>bliance Tes</mark> <u>Yes</u> <u>Yes</u>	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	S Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	V <mark>bliance Tes</mark> Yes No	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	S Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	V Diliance Tes Yes Yes No Yes Yes Yes	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	V Diance Tes Yes Yes No Yes Yes Yes Yes Yes	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	V Diliance Tes Yes Yes No Yes Yes Yes	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	V Diance Tes Yes Yes Yes Yes Yes No	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	V Diance Tes Yes Yes Yes Yes Yes No	Phone (662) 841-0995 Fax (662) 841-0810 Website www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	V Diance Tes Yes Yes Yes Yes Yes No No No No	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tall Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	V Diance Tes Yes Yes Yes Yes Yes No No No No	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes Yes
Cobb Environmental & Technical Services, Inc P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	V Diance Tes Yes Yes Yes Yes Yes No No No No	Phone (662) 841-0995 Fax (662) 841-0810 Vebsite www.cobbenv.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tall Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes No No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes Yes

UST Serv	vice Pro	vider List (All) - Corrosion Prot	ection Co	ompanies Only	
Company		Listing Submitted	11/21/2023	Area of state conducts work	
Conklin Corrosion Control LLC		Phone (704) 560-9154		Coastal (East of I-95): Yes	
118 Oak Point Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Stony Point, NC 28678				Mountains (West of I-77): Yes	
	W	ebsite <u>benconklincc@gmail.com</u>			
Com	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	10/11/2023	Area of state conducts work	
Company Conklin Corrosion Control LLC		Listing Submitted Phone (704) 560-9154	10/11/2023	Area of state conducts work Coastal (East of I-95): Yes	
Conklin Corrosion Control LLC 118 Oak Point Lane		· · · · · · · · · · · · · · · · · · ·	10/11/2023		
Conklin Corrosion Control LLC		Phone (704) 560-9154 Fax	10/11/2023	Coastal (East of I-95): Yes	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678	w	Phone (704) 560-9154 Fax ebsite <u>benconklincc@gmail.com</u>	10/11/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678	W Diance Test	Phone (704) 560-9154 Fax ebsite <u>benconklincc@gmail.com</u> ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Comp Automatic Line Leak Detector Testing:	W bliance Test No	Phone (704) 560-9154 Fax ebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing:	W Dliance Test No No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W Dliance Test No No No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W Dliance Test No No <u>Yes</u>	Phone (704) 560-9154 Fax benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	W Dliance Test No No Yes Yes	Phone (704) 560-9154 Fax ebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	W Dliance Test No No Yes Yes No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair:	No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	W Diiance Test No No Yes Yes No No	Phone (704) 560-9154 Fax ebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	W Dliance Test No No Yes Yes No No No	Phone (704) 560-9154 Fax ebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: E	W Diance Test No No Yes Yes No No No No	Phone (704) 560-9154 Fax ebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	W Diance Test No No Yes Yes No No No No No No No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	W Diance Test No No Yes Yes No No No No No No No No No No No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	W Dliance Test No No Yes Yes No No No No No No No No No No No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	W Diance Test No No Yes Yes No No No No No No No No No No No	Phone (704) 560-9154 Fax Pebsite benconklincc@gmail.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

UST Serv	vice Prov	ider List (All) - C	Corrosion Prote	ection Co	ompanies Only	
Company			Listing Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC	F	Phone (610) 278-7203			Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462	10/0		~		Mountains (West of I-77): Yes	
		bsite <u>www.crompco.con</u>	<u>II</u>			
Comp		ig and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment		<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Statistical Iventory Reconcilia		<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Te	esting:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Inte		No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:		UST Internal Lining Inspectior	ns:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants	i:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatme	nt:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	1/1/2022	Area of state conducts work	
Galloway	F	Phone (303) 770-8884			Coastal (East of I-95): Yes	
6162 South Willow Drive		Fax (303) 770-3636			Central (West of I-95 and East of I-77): Yes	
Suite 320		, , ,			Mountains (West of I-77): Yes	
Greenwood Village, CO 80111	We	bsite www.Gallowayus.	<u>com</u>		Mountains (West of 1-77). Tes	
Comp	oliance Testin	ig and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment	t Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconcilia	tion Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Te	esting:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Inte		No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspectior	ns:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	UST/AST System	Design	UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants	:	Yes		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatme	nt:	No		
Oil and Solvent Recycling:	No	Other:	UST/AST System	Design		

Company		Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group	Phone	(888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100	Fax			Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730	T dA				
	Website			Mountains (West of I-77): Yes	
Comp	liance Testing and	d Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes Overfil	I Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Statist	ical Iventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	Yes Spill P	revention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	Yes Tank T	Fightness Testing:	Yes	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	Yes UST Ir	nternal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes UST Ir	nternal Lining Inspections:	Yes	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes Other:			UST Piping/Sump Installation:	Yes
Line Tightness Testing:	Yes			UST System Removal:	No
Er	vironmental Servi	ice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST C	Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No UST E	quipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu		Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Other:				
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service	Phone	(704) 892-8600		Coastal (East of I-95): Yes	
737 Zimmer Road	Fax			Central (West of I-95 and East of I-77): Yes	
Fort Mill, SC 29707	I dA	(104) 032-0111			
	Website	www.precisiontankservice.com		Mountains (West of I-77): Yes	
Comp	liance Testing and	d Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes Overfil	I Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Statist	ical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill P	revention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank T	Fightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes UST Ir	nternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes UST Ir	nternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Er	vironmental Servi	ice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST C	Compliance Consultants:	Yes		
	No UST E	quipment Verification:	No		
Environmental Engineer/Geologist - Site Checks:					
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu		Disposal and Treatment:	No		
		Disposal and Treatment:	No		

		vider List (All) - Corrosion Prot			
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Superior Services		Phone (828) 698-6286		Coastal (East of I-95): Yes	
PO Box 982		Fax (828) 698-6294		Central (West of I-95 and East of I-77): Yes	
Hendersonville, NC				Mountains (West of I-77): Yes	
	W	ebsite <u>www.superiorservices.com</u>			
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Repair and lining, AST Inspections, Repairs and	d Lining	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	I No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/26/2022	Area of state conducts work	
UST Corrosion Management, Inc.		Phone (888) 822-2431		Coastal (East of I-95): Yes	
2764 Pleasant Rd #10714		Fax (803) 802-0561		Central (West of I-95 and East of I-77): Yes	
Fort Mill, SC 29708				Mountains (West of I-77): Yes	
	N	ebsite www.ustcorrosion.com			
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
	No	Other:		UST Piping/Sump Installation:	No
Leak Detection Monitoring Services:				UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No				
Line Tightness Testing:		al Service Firms		Other:	
Line Tightness Testing:	nvironmenta		No	Other:	
Line Tightness Testing: Emergency Cleanup - Spill/Release:		UST Compliance Consultants:	No No	Other:	
Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	nvironmenta No No	UST Compliance Consultants: UST Equipment Verification:		Other:	
Line Tightness Testing: Emergency Cleanup - Spill/Release:	nvironmenta No No	UST Compliance Consultants:	No	Other:	

UST Serv	ice Provide	r List (All) - Corrosion Prote	ection Co	ompanies Only	
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING	Phone	• (813) 671-9065		Coastal (East of I-95): Yes	s
451 APOLLO BEACH BOULEVARD	Fax(866) 328-9796WebsiteWWW.VALLEYTANK.COM			Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
APOLLO BEACH, FL 33572					
Comp	liance Testing an	d Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes Overfi	Il Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Statist	tical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill P	Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank	Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes UST I	nternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes UST I	nternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
En	vironmental Serv	ice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST C	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No UST E	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Waste	e Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Other:				
Soil and Water Testing Lab:	No				