UST Service Provider List (All) - Leak	Detection Testing Companies Univ
--	----------------------------------

Company			Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.		Phone	(252) 237-6047		Coastal (East of I-95): Yes	
PO Box 502			(252) 237-5507		Central (West of I-95 and East of I-77): Yes	
711 S. Goldsboro St.			(202) 20. 000.		Mountains (West of I-77): No	
Wilson, NC 27893	V	Vebsite	www.peswilson.com		mountains (west of 1-17). No	
Comp	oliance Tes	ting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No		Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>		al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No		evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tig	ghtness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Inte	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Inte	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironment	al Servic	e Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	impliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equ	uipment Verification:	No		
	No		Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	•			
Soil and Water Testing Lab:	No					
0						
Company			Listing Submitted	5/17/2021	Area of state conducts work	
AFS of Greenville LLC		Phone	Listing Submitted	5/17/2021	Area of state conducts work Coastal (Fast of I-95): Yes	
AES of Greenville LLC		Phone	(252) 758-3311	5/17/2021	Coastal (East of I-95): Yes	
				5/17/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
AES of Greenville LLC 141 S. Market Street	V		(252) 758-3311	5/17/2021	Coastal (East of I-95): Yes	
AES of Greenville LLC 141 S. Market Street Washington, NC 27889		Fax Website	(252) 758-3311 (252) 481-5814	5/17/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
AES of Greenville LLC 141 S. Market Street Washington, NC 27889		Fax Website ting and	(252) 758-3311 (252) 481-5814 www.aes-nc.com	5/17/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp	oliance Tes	Fax Website	(252) 758-3311 (252) 481-5814 www.aes-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Company Automatic Line Leak Detector Testing:	oliance Tes	Fax Website ting and Overfill F	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Tes Yes Yes	Fax Website ting and Overfill F Statistica Spill Pre	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services:	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Fax Website Iting and Overfill If Statistics Spill Pre Tank Tig	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No Yes	Fax Nebsite ting and Overfill F Statistic: Spill Pre Tank Tig UST Inte	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No Yes Yes	Fax Nebsite ting and Overfill F Statistic: Spill Pre Tank Tig UST Inte	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No Yes Yes Yes Yes Yes Yes	Fax Nebsite ting and Overfill F Statistica Spill Pre Tank Tig UST Inte	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes	Fax Nebsite ting and Overfill F Statistic: Spill Pre Tank Tig UST Inte UST Inte Other:	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes	Fax Nebsite ting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other:	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes Yes No Yes	Fax Website Iting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other:	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes Yes No No No	Fax Website Iting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other: Cal Servic UST Cou	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: ce Firms empliance Consultants: uipment Verification:	Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Your No No No	Fax Nebsite ting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other: tal Servic UST Col UST Equ Waste D	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
AES of Greenville LLC 141 S. Market Street Washington, NC 27889 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes Yes No No No	Fax Website Iting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other: Cal Servic UST Cou	(252) 758-3311 (252) 481-5814 www.aes-nc.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: ce Firms empliance Consultants: uipment Verification:	Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Service Provider List (All) - Leak	Detection Testing Companies Univ
--	----------------------------------

Company		Listing Submitted		Area of state conducts work	
American UST Compliance Testing		Phone (919) 777-8543		Coastal (East of I-95): Yes	
180 BPW Club Rd. A-1		Fax		Central (West of I-95 and East of I-77): Yes	
Carrboro, NC 27510				Mountains (West of I-77): Yes	
	We	ebsite		Mountains (West of 1-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Bay Compliance and Testing LLC		Phone (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	We	ebsite https://baycomplianceandtesting.com/		Modificants (West of 1-77). No	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
				LICT Cystem Installation Complete Cystems	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	
Leak Detection Monitoring Services:		UST Internal Lining Inspections: Other:	No	UST Piping/Sump Installation:	No
		- · · · · · · · · · · · · · · · · · · ·	No	UST Piping/Sump Installation: UST System Removal:	No No
Leak Detection Monitoring Services: Line Tightness Testing:	No <u>Yes</u>	- · · · · · · · · · · · · · · · · · · ·	No	UST Piping/Sump Installation:	
Leak Detection Monitoring Services: Line Tightness Testing:	No Yes nvironmenta	Other:	No No	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	No Yes nvironmenta No	Other: Service Firms		UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Yes nvironmenta No No	Other: Service Firms UST Compliance Consultants:	No	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes nvironmenta No No No	Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No	UST Piping/Sump Installation: UST System Removal:	

LIST Sanie	Dro	vider List (All) - Leak Detection	Tactina	Omnanias Only	
Company	JE FIO	Listing Submitted		Area of state conducts work	
Bunnell-Lammons Engineering, Inc.		Phone (828) 277-0100	171072022	Coastal (East of I-95): Yes	
130 Oval Road				Central (West of I-95 and East of I-77): Yes	
Arden, NC 28704		Fax (828) 277-0110			
		Website www.blecorp.com		Mountains (West of I-77): Yes	
Comp	liance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
En	vironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Trust Fund	Projects		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc		Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802 871 South Green Street		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
or i South Gleen Street					
Tupelo, MS 38804		Website www.cobbenv.com		Mountains (West of I-77): Yes	
Tupelo, MS 38804		, ,		Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Tupelo, MS 38804		Website www.cobbenv.com	Yes		<u>Yes</u>
Tupelo, MS 38804	liance Te	Website www.cobbenv.com sting and Monitoring	Yes No	UST Equipmment Service Contractors	
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing:	oliance Te Yes	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	liance Te Yes Yes	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes Yes No Yes	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No Yes Yes	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No Yes Yes Yes Yes Yes Yes	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes No	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes No	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	Yes Yes No Yes Yes Yes Yes Yes Yes No Yes Yes No No	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Tupelo, MS 38804 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Yes Yes Yes Yes Yes Yes Yes Yes No No No No	Website www.cobbenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No Yes No No No Yes	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes

Oil and Solvent Recycling:

Soil and Water Testing Lab:

Other:

No

No

|--|

Company		` '	isting Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC	P	Phone (610) 278-7203			Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462		(010) 210 1021			Mountains (West of I-77): Yes	
	We	bsite www.crompco.com			mountains (west of 1-77). Tes	
Comp	oliance Testin	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Ope		<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Statistical Iventory Reconciliation S		<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing	g:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company		L	isting Submitted	9/24/2021	Area of state conducts work	
C-Store Services, Inc.	P	Phone (919) 662-0798			Coastal (East of I-95): Yes	
7129 Hidden Valley Trail		Fax (919) 662-0711			Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529					Mountains (West of I-77): No	
	We	bsite			modificants (violation 177).	
Comp	oliance Testin	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Ope	erability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation S	Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	g:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other:	UST-27 monthly insp	pection	UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Monitoring Services.	No				LIOT Occident Democratic	<u>Yes</u>
Line Tightness Testing:	No No				UST System Removal:	
Line Tightness Testing:	No	Service Firms			Other:	<u></u>
Line Tightness Testing:	No nvironmental			No		<u></u>
Line Tightness Testing:	No nvironmental No	Service Firms		No No		
Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No nvironmental No No	Service Firms UST Compliance Consultants:				
Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironmental No No No No	Service Firms UST Compliance Consultants: UST Equipment Verification:		No		<u></u>

UST Service Provider List (All) - Leak Detection Testing Companies O	UST Service Pro	ovider List (All)	- Leak Detection	Testing C	Companies Onl
--	------------------------	-------------------	------------------	-----------	---------------

Company		Listing Submitte	ed 10/26/2021	Area of state conducts work	
Guardian Fueling Technologies	F	Phone (919) 729-6980		Coastal (East of I-95): Yes	
5116 Departure Drive		Fax (919) 769-2919		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616		(010) 700 2010			
	We	bsite <u>www.guardianfueltech.com</u>		Mountains (West of I-77): No	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other: SafeGuard UST Inspection	n Services	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	No
Ei	nvironmental	Service Firms		Other: FuelGuard fuel polishing / tank	cleaning
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 5/15/2023	Area of state conducts work	
JF Petroleum Group	F	Phone (919) 744-4391		Coastal (East of I-95): Yes	
-		(010) / 11 1001			
100 Perimeter Park Drive				Central (West of I-95 and East of I-77): Yes	
Suite H		Fax		Central (West of I-95 and East of I-77): Yes	
	We		talcompliance	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Suite H Morrisville, NC 27560		Fax	talcompliance		
Suite H Morrisville, NC 27560	oliance Testir	Fax bsite jfpetrogroup.com/services/environmen	talcompliance Yes	Mountains (West of I-77): Yes	
Suite H Morrisville, NC 27560 Comp	oliance Testir <u>Yes</u>	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring		Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing:	oliance Testir Yes Yes	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	<u>Yes</u>
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes Yes No	Fax bbsite ifpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Diance Testin Yes Yes No No	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	<u>Yes</u> No <u>Yes</u>	Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No No	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No No Yes	Fax Absite ifpetrogroup.com/services/environment and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No No No Yes	Fax besite ifpetrogroup.com/services/environment and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes	Fax besite ifpetrogroup.com/services/environment and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes Yes	Fax besite ifpetrogroup.com/services/environment ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	Yes No Yes Yes No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes You	Fax Absite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Yes Yes No No No Yes Yes Yes Yes Yes You	Fax bisite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	Yes No Yes Yes No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes No No No Yes Yes Yes Yes Yes No	Fax bisite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes

UST Service Provider List (All) - Leak Detection Testing Companies O	UST Service Pro	ovider List (All)	- Leak Detection	Testing C	Companies Onl
--	------------------------	-------------------	------------------	-----------	---------------

Company		Li	isting Submitted	1/5/2022	Area of state conducts work	
Johnson, Spellman & Associates, Inc.		Phone (770) 447-4555			Coastal (East of I-95): Yes	;
350 Research Ct.		Fax			Central (West of I-95 and East of I-77): Yes	
Suite 130	1 ax					
Peachtree Corners, GA 30092	V	Vebsite			Mountains (West of I-77): Yes	i
Comp	liance Tes	ting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation S	ervices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	r.	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Er	ngineering- Design Sei	rvices	UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironment	al Service Firms			Other: Engineering-Design	Services
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other: E	ngineering-Design Sei	rvices		
Soil and Water Testing Lab:	No					
Company		Li	isting Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581			Coastal (East of I-95): Yes	;
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300			Central (West of I-95 and East of I-77): Yes	;
Rancho Cucamonga, CA 91730		• •			Mountains (West of I-77): Yes	
	V	Vebsite			mountaine (reset et 111).	
Сотр	liance Tes	ting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation S	ervices:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing	:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity /	Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
LE : (0 1 10 10 10 10 10 10	NI-	Waste Disposal and Treatment:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	NO	waste Disposal and Treatment.				
Oil and Solvent Recycling:	No No	Other:				

UST Service Provider List (All) - Leak	Detection Testing Companies Univ
--	----------------------------------

Company	00 1 10 110		Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment and Service, Inc.	Р	hone	(704) 335-8801		Coastal (East of I-95): No	
4125 Sinclair Street		Fax			Central (West of I-95 and East of I-77): Yes	
PO Box 1949		· ux	(. 0 .) 0 12 10 12		Mountains (West of I-77): Yes	
Denver, NC 28037	Wel	bsite	www.petroleumequipment.net		Mountains (West of 1-77): Tes	
Comp	oliance Testin	g and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes S	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No T	Γank Τi	ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			ternal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	JST Int	ternal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironmental	Servic	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No L	JST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No L	JST Eq	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No V	Naste [Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No C	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	5/14/2021	Area of state conducts work	
Petroleum Solutions Inc.	P	hone	(919) 605-1979		Coastal (East of I-95): Yes	
3012 Whitehart Ln.		Fax	(919) 773-1704		Central (West of I-95 and East of I-77): Yes	
819 Purser Drive			(0.0)		Mountains (West of I-77): No	
Raleigh, NC 27606	Wel	bsite	www.petroleumsolutionsinc.net		Mountains (West of 1-77). NO	
Comp	oliance Testin	g and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No T	Γank Ti	ghtness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No L	JST Int	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No L	JST Int	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No C	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
		Servic	ce Firms		Other:	
Er	nvironmental					
Emergency Cleanup - Spill/Release:		JST Co	ompliance Consultants:	No		
	No L		ompliance Consultants: quipment Verification:			
Emergency Cleanup - Spill/Release:	No L	JST Eq		No <u>Yes</u> No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No L No L No V	JST Eq	quipment Verification:	<u>Yes</u>		

UST Service Provider List (All) - Leak	Detection Testing Companies Univ
--	----------------------------------

Company	00 1 10 110		Listing Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service	PI	hone	(704) 892-8600		Coastal (East of I-95): Yes	
737 Zimmer Road			(704) 892-8711		Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707		I dx	(10 7) 002-01 11			
	Web	osite	www.precisiontankservice.com		Mountains (West of I-77): Yes	
Comp	pliance Testing	g and l	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill P	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes S	Statistica	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:			vention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:			htness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	JST Inte	rnal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	JST Inte	rnal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental \$	Service	e Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	JST Cor	mpliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	JST Equ	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No V	Vaste D	isposal and Treatment:	No		
Oil and Solvent Recycling:	No C	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	12/30/2021	Area of state conducts work	
Superior Services	PI	hone	(828) 698-6286		Coastal (East of I-95): Yes	
PO Box 982		Fax	(828) 698-6294		Central (West of I-95 and East of I-77): Yes	
Hendersonville, NC					Mountains (West of I-77): Yes	
	Web	osite	www.superiorservices.com		mountains (Woot of 177).	
Comp	pliance Testing	g and l	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill P	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	Statistica	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u> S	Spill Prev	vention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		_	htness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:			rnal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:			rnal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No C	Other:	Repair and lining, AST Inspections, Repairs and	Lining	UST Piping/Sump Installation:	No
_					UST System Removal:	No
Line Tightness Testing:	<u>Yes</u>					
Line Tightness Testing:		Service	e Firms		Other:	
Line Tightness Testing:	<u>Yes</u> nvironmental \$		e Firms npliance Consultants:	No	Other:	
Line Tightness Testing:	Yes nvironmental S	JST Cor		No No	Other:	
Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes nvironmental S No U No U	JST Cor JST Equ	npliance Consultants:		Other:	
Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes nvironmental \$ No	JST Cor JST Equ	npliance Consultants: uipment Verification:	No	Other:	

UST Service Provider List (All) - Leak Detection Testing Compar	nies Only

Company		Listing Submitted	12/30/2021	Area of state conducts work	
Terraquest Environmental Consultants, P.C.	Pho	one (919) 563-9091		Coastal (East of I-95): Yes	
100 E. Ruffin Street	ı	Fax (919) 563-9095		Central (West of I-95 and East of I-77): Yes	
Mebane, NC 27302	107	•		Mountains (West of I-77): Yes	
	Webs	ite <u>www.terraquestpc.com</u>			
Comp	liance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Sta	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spi	Il Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		ner:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er		Other:			
Emergency Cleanup - Spill/Release:	Yes US	T Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		ste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Oth	ner:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING	Pho	one (813) 671-9065		Coastal (East of I-95): Yes	
451 APOLLO BEACH BOULEVARD	ı	Fax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	
APOLLO BEACH, FL 33572	Mala a	**- VAVAVAV VALLEVTANIK COM		Mountains (West of I-77): Yes	
	Webs	ite <u>WWW.VALLEYTANK.COM</u>			
Comp	UST Equipmment Service Contractors				
Automatic Line Leak Detector Testing:		erfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spi	Il Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		nk Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u> US	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes Oth	ner:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
En	nvironmental Se	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No US	T Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No US	T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu			No		
	No Wa	ste Disposal and Treatment:	INO		
Oil and Solvent Recycling:	No Wa	·	INO		
		·	NO		