Company				Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.	F	hone	(252) 237-6047			Coastal (East of I-95): Yes	
PO Box 502		Fax	(252) 237-5507			Central (West of I-95 and East of I-77): Yes	
711 S. Goldsboro St.						Mountains (West of I-77): No	
Wilson, NC 27893	We	ebsite	www.peswilson.com	1		mountaino (nost or 117). No	
Comp	oliance Testin	ng and	Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			Prevention Equipment (<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:			al Iventory Reconciliation		No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:			evention Equipment Tes	ting:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:			ghtness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			ernal Inspections (Integ		No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:			ernal Lining Inspections	:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:		Other:				UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
Er	nvironmental	Service	e Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	mpliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste [Disposal and Treatment	:	No		
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company				Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc.							
Advanced Environmental Services, inc.	F	Phone	(336) 282-3586			Coastal (East of I-95): Yes	
PO Box 38218	F	Phone Fax	(336) 282-3586 (336) 282-3587			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
·		Fax	(336) 282-3587			Central (West of I-95 and East of I-77): Yes	
PO Box 38218			` ,	nental.com			
PO Box 38218 Greensboro, NC 27438		Fax ebsite	(336) 282-3587 AdavancedEnvironr	nental.com		Central (West of I-95 and East of I-77): Yes	
PO Box 38218 Greensboro, NC 27438	We	Fax ebsite	(336) 282-3587 AdavancedEnvironr		No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
PO Box 38218 Greensboro, NC 27438	We bliance Testin	Fax bsite ng and Overfill	(336) 282-3587 AdavancedEnvironr Monitoring	Operability Check:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
PO Box 38218 Greensboro, NC 27438 Company Automatic Line Leak Detector Testing:	We pliance Testin No	Fax ebsite ng and Overfill Statistic	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment (Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
PO Box 38218 Greensboro, NC 27438 Comparing Line Leak Detector Testing: Containment Sump Testing:	We Diance Testin No No No No	Fax ebsite ng and Overfill Statistic Spill Pre	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Cal Iventory Reconciliation	Operability Check:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
PO Box 38218 Greensboro, NC 27438 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	We Diance Testin No No No No No No	Fax ebsite ng and Overfill Statistic Spill Pre Tank Tig	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Call Iventory Reconciliation exercision Equipment Tesservention Equipment Equipment Tesservention Equipment Equi	Operability Check: on Services: ting:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
PO Box 38218 Greensboro, NC 27438 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Webliance Testin	Fax ebsite ng and Overfill Statistic Spill Pre Tank Tig UST Int	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Coal Iventory Reconciliation Equipment Testings (Special Processor) Province of the Control of the Con	Operability Check: on Services: ting: rity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
PO Box 38218 Greensboro, NC 27438 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Webliance Testin	Fax ebsite ng and Overfill Statistic Spill Pre Tank Tig UST Int	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Cal Iventory Reconciliation Equipment Testing: evention Equipment Testing: ernal Inspections (Integral)	Operability Check: on Services: ting: rity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Webliance Testin	Fax bebsite ng and Overfill Statistic Spill Pre Tank Tig UST Int UST Int	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Cal Iventory Reconciliation Equipment Testing: evention Equipment Testing: ernal Inspections (Integral)	Operability Check: on Services: ting: rity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testin	Fax Pebsite Ing and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other:	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Cal Iventory Reconciliation Equipment Testing: Provention Equipment Testing: Provention Equipment Testing: Provention Inspections (Integernal Lining Inspections)	Operability Check: on Services: ting: rity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testin	Fax Pebsite Ing and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Service	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Cal Iventory Reconciliation Equipment Testing: Provention Equipment Testing: Provention Equipment Testing: Provention Inspections (Integernal Lining Inspections)	Operability Check: on Services: ting: rity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testin No	Fax ebsite ng and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Servic UST Co	(336) 282-3587 AdavancedEnviron Monitoring Prevention Equipment Call Iventory Reconciliation Equipment Testing: Exernal Inspections (Integrated Inspections) The Firms AdavancedEnviron Monitoring Prevention Equipment Call Iventory Reconciliation Equipment Testing: Exernal Lining Inspections The Firms	Operability Check: on Services: ting: rity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	We pliance Testin No	Fax Pebsite Ing and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Servic UST Co UST Eq	(336) 282-3587 AdavancedEnvironr Monitoring Prevention Equipment Call Iventory Reconciliation Equipment Testing: Evention Equipment Consultants:	Operability Check: on Services: ting: rity Assessments):	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
PO Box 38218 Greensboro, NC 27438 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Webliance Testin	Fax Pebsite Ing and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Servic UST Co UST Eq	AdavancedEnvironr Monitoring Prevention Equipment Call Iventory Reconciliations evention Equipment Testing: Evention Equipment Te	Operability Check: on Services: ting: rity Assessments):	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitted	1	Area of state conducts work	
AES of Greenville LLC	P	hone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889		(202) 101 0011		Mountains (West of I-77): Yes	
	Wek	osite <u>www.aes-nc.com</u>		Wouldains (West of 1-77): Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		JST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u> U	JST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u> C	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	JST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	JST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No V	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No C	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/15/2021	Area of state conducts work	
American UST Compliance Testing	P	hone (919) 777-8543		Coastal (East of I-95): Yes	
180 BPW Club Rd. A-1		Fax		Central (West of I-95 and East of I-77): Yes	
Carrboro, NC 27510				Mountains (West of I-77): Yes	
	Wek	osite		Mountains (West of 1-77). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	-				V
Contains out Comm. To ette so	<u>Yes</u> C	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u> No
Corrosion Protection Design Experts:	<u>Yes</u> S				
	Yes S No S No T	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S No S No T	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes S No S No T Yes U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes S No S No T Yes U Yes U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No <u>Yes</u>
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes S No S No T Yes U Yes U	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S No S No T Yes U Yes U No C	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S No S No T Yes U Yes U No C Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes S No S No T Yes U No C Yes U nvironmental \$	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No <u>Yes</u> <u>Yes</u> No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes S No S No T Yes U No C Yes U Yes U Yes U Yes U No C Yes U No C	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: Other: Service Firms JST Compliance Consultants:	No Yes Yes No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes S No S No T Yes U Yes U No Yes nvironmental S Yes U No U No W	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes No No Yes No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No

Company			Listing Submitted	5/17/2021	Area of state conducts work	
Apex Engineering, PC	F	hone (301	I) 417-0200		Coastal (East of I-95): Yes	
15850 Crabbs Branch Way		Fax (301	1) 975-0169		Central (West of I-95 and East of I-77): Yes	
Suite 200		(,		Mountains (West of I-77): Yes	
Rockville, Maryland 20855-	We	bsite <u>www</u>	v.apexcos.com		moditalits (West 61177). 163	
Comp	pliance Testir	g and Moni	itoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prever	ntion Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iver	ntory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention	on Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Γank Tightnes	ss Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	JST Internal I	Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	JST Internal L	Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
E	nvironmental	Service Firi	ms		Other:	
Emergency Cleanup - Spill/Release:	Yes	JST Compliar	nce Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:			ent Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu			sal and Treatment:	Yes		
Oil and Solvent Recycling:		Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	7/19/2022	Area of state conducts work	
Company B & M WEST CONSTRUCTION CO OF TEXAS	DRAD E	hone (863	Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS	DBA D. F	•	3) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
	DBA D. F	•		7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD		Fax (863	3) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860	We	Fax (863	3) 519-4441 3) 519-4407 SHOUPPE.COM	7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp	We pliance Testir	Fax (863 bsite DWS	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparing Line Leak Detector Testing:	We pliance Testin	Fax (863 bsite DWS g and Moni	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparing Line Leak Detector Testing: Containment Sump Testing:	Wepliance Testin	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison of the Compariso	We pliance Testin No No No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We pliance Testin No No No No No No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Fank Tightnes	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing: ss Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u>
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	We pliance Testin No No No No No No No No No	Fax (863 bsite DWS g and Moni Dverfill Prevertice Statistical Iver Spill Preventice Fank Tightnes UST Internal I	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Interpretable of Equipment Testing: Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u> No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Prevertice Statistical Iver Spill Preventice Fank Tightnes UST Internal I	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing: ss Testing:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison of the Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	We pliance Testin No	Fax (863 bsite DWS g and Moni Overfill Preverticatistical Iver Spill Preventication Trank Tightnes UST Internal In	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Interpretable of Equipment Testing: Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No No No
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testin No	Fax (863 bsite DWS g and Moni Overfill Prevention Fank Tightnes JST Internal I JST Internal L Other:	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: In Equipment Testing: Inspections (Integrity Assessments): Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testir No	Fax (863 bsite DWS g and Moni Overfill Prevertical Iver Spill Preventical Fank Tightnes JST Internal I JST Internal L Other: Service Fire	3) 519-4441 3) 519-4407 SHOUPPE.COM itoring ntion Equipment Operability Check: ntory Reconciliation Services: on Equipment Testing: ss Testing: Inspections (Integrity Assessments): Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 1209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	We pliance Testir No	Fax (863 bsite DWS g and Moni Overfill Prever Statistical Iver Spill Preventio Tank Tightnes JST Internal I JST Internal L Other: Service Fire JST Complian	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Tank Tightnes JST Internal I JST Internal L Dther: Service Fire JST Complian JST Equipme	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Reconciliation Services: In Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Integrity Assessments: Integr	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 1209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	We pliance Testir No	Fax (863 bsite DWS g and Moni Dverfill Prever Statistical Iver Spill Preventio Tank Tightnes JST Internal I JST Internal L Dther: Service Fire JST Complian JST Equipme	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS 209 E BADCOCK BLVD MULBERRY, FL 33860 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	We pliance Testir No	Fax (863 bsite DWS g and Moni Overfill Prevention Fank Tightnes JST Internal I JST Internal L Other: Service Fire JST Compliar JST Equipme Waste Dispos	B) 519-4441 B) 519-4407 SHOUPPE.COM itoring Intion Equipment Operability Check: Intory Reconciliation Services: Intory Reconciliation Services: In Equipment Testing: Inspections (Integrity Assessments): Lining Inspections: Integrity Assessments: Integr	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes

Company		Listing Submitted	12/30/2021	Area of state conducts work	
Bay Compliance and Testing LLC		Phone (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
		Website https://baycomplianceandtesting.com/		mountains (west of 177). No	
Comp	oliance 1	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironm	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/5/2023	Area of state conducts work	
CATLIN Engineers and Scientists		Phone (910) 452-5861	4/5/2023	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (910) 452-5861	4/5/2023	Coastal (East of I-95): Yes	
CATLIN Engineers and Scientists			d 4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road		Phone (910) 452-5861	d 4/5/2023	Coastal (East of I-95): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405	oliance 1	Phone (910) 452-5861 Fax	d 4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405	oliance 1	Phone (910) 452-5861 Fax Website www.CatlinUSA.com	4/5/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp		Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Compa	No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Festing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Festing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Festing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No No No No No No No Vo No Tvironm Yes Yes	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Tental Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No Vo Tvironm Yes Yes	Phone (910) 452-5861 Fax Website www.CatlinUSA.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Tental Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Company			, ,	Listing Submitted	5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc).	Phone	(662) 841-0995			Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax	(662) 841-0810			Central (West of I-95 and East of I-77): Yes	
871 South Green Street			(,			Mountains (West of I-77): Yes	
Tupelo, MS 38804	V	lebsite	www.cobbenv.com			moditalits (West 61177). Tes	
Comp	oliance Test	ing and	Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>		Prevention Equipment (<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>		al Iventory Reconciliation		No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No		evention Equipment Tes	sting:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>		ghtness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>		ernal Inspections (Integ		No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Inte	ernal Lining Inspections	3:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:				UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Servic	e Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	mpliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste D	Disposal and Treatment	:	No		
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Soli and Water Testing Lab.	140						
Company	110			Listing Submitted	1/20/2022	Area of state conducts work	
	110	Phone	(919) 233-8626	Listing Submitted	1/20/2022	Area of state conducts work Coastal (East of I-95): Yes	
Company COHESION, INC 5216 YATES MILL POND RD	110		(919) 233-8626	Listing Submitted	1/20/2022	Coastal (East of I-95): Yes	
Company COHESION, INC		Phone Fax	. ,		1/20/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
COMPANY COHESION, INC 5216 YATES MILL POND RD			(919) 233-8626 WWW.COHESION		1/20/2022	Coastal (East of I-95): Yes	
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606		Fax /ebsite	WWW.COHESION		1/20/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606	W	Fax /ebsite ing and	WWW.COHESION	-INC.COM	1/20/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp	W oliance Test	Fax /ebsite ing and Overfill	WWW.COHESION Monitoring	-INC.COM Operability Check:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Company Automatic Line Leak Detector Testing:	W Dliance Test	Fax /ebsite ing and Overfill Statistic	WWW.COHESION Monitoring Prevention Equipment (-INC.COM Operability Check: on Services:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	W Dliance Test No No	Fax /ebsite ing and Overfill Statistic Spill Pre	WWW.COHESION Monitoring Prevention Equipment (al Iventory Reconciliation	-INC.COM Operability Check: on Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Fax /ebsite cing and Overfill Statistic Spill Pre Tank Tig	WWW.COHESION Monitoring Prevention Equipment (all Iventory Reconciliation evention Equipment Test	-INC.COM Operability Check: on Services: sting:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No	Fax /ebsite cing and Overfill Statistic Spill Pre Tank Tig UST Inte	WWW.COHESION Monitoring Prevention Equipment of all Iventory Reconciliation evention Equipment Testing threes Testing:	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No	Fax /ebsite cing and Overfill Statistic Spill Pre Tank Tig UST Inte	WWW.COHESION Monitoring Prevention Equipment of all Iventory Reconciliation evention Equipment Testing: evention Equipment Testing: ernal Inspections (Integrated)	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Fax /ebsite ing and Overfill Statistic Spill Pre Tank Tig UST Inte	WWW.COHESION Monitoring Prevention Equipment of all Iventory Reconciliation evention Equipment Testing: evention Equipment Testing: ernal Inspections (Integrated)	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Fax /ebsite cing and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	WWW.COHESION Monitoring Prevention Equipment of all Iventory Reconciliative evention Equipment Testing: evention Equipment Testing: ernal Inspections (Integernal Lining Inspections)	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax /ebsite sing and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	WWW.COHESION Monitoring Prevention Equipment of all Iventory Reconciliative evention Equipment Testing: evention Equipment Testing: ernal Inspections (Integernal Lining Inspections)	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax /ebsite ing and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	WWW.COHESION Monitoring Prevention Equipment of all Iventory Reconciliation evention Equipment Test ghtness Testing: ernal Inspections (Integrenal Lining Inspections etc.)	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Fax /ebsite ing and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other: al Servic UST Co UST Eq	WWW.COHESION Monitoring Prevention Equipment (all Iventory Reconciliation evention Equipment Test ghtness Testing: ernal Inspections (Integreenal Lining Inspections ernal Lining Inspections ernal Epirms impliance Consultants:	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax /ebsite ing and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other: al Servic UST Co UST Eq	WWW.COHESION Monitoring Prevention Equipment Of all Iventory Reconciliation evention Equipment Test ghtness Testing: ernal Inspections (Integernal Lining Inspections ernal Lining Inspection ern	-INC.COM Operability Check: on Services: sting: rity Assessments):	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company			Listing Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC	Р	Phone (610) 278-7203			Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462		(010) 210 1021			Mountains (West of I-77): Yes	
	Wel	bsite <u>www.crompco.com</u>			mountains (west of 1-77). Tes	
Comp	oliance Testin	g and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Ope		<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Statistical Iventory Reconciliation		<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testin	ıg:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Гаnk Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		JST Internal Inspections (Integrity	/ Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	JST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No L	JST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No L	JST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No V	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No (Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	9/24/2021	Area of state conducts work	
C-Store Services, Inc.	P	hone (919) 662-0798			Coastal (East of I-95): Yes	
7129 Hidden Valley Trail		Fax (919) 662-0711			Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529		,			Mountains (West of I-77): No	
	Wel	bsite			modificants (1705) of 177). The	
Comp	oliance Testin	g and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Ope	erability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testin	ig:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No 7	Fank Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No L	JST Internal Inspections (Integrity	/ Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No L	JST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (Other:	UST-27 monthly insp	pection	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms			Other:	
		IOT Occupion Consideration		No		
Emergency Cleanup - Spill/Release:	No L	JST Compliance Consultants:				
		JST Compliance Consultants: JST Equipment Verification:		No		
Emergency Cleanup - Spill/Release:	No L					
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No U	JST Equipment Verification:		No		

Company		Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company	-	Phone (336) 214-9012		Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407				Mountains (West of I-77): Yes	
	We	ebsite <u>www.dhgriffin.com</u>		Mountains (West of 1-17). Tes	
Comp	oliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:		Other: Vacuum Truck			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/6/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969	4/0/2023	Coastal (East of I-95): Yes	
3815 Junction Boulevard		,		,	
Raleigh , NC 27603		Fax		Central (West of I-95 and East of I-77): Yes	
Tanada, Tanada	We	ebsite eastcoastenv.com		Mountains (West of I-77): No	
Comm				LICT Equipment Capias Contractors	
_		ng and Monitoring	No	UST Equipmment Service Contractors	Nia
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:		Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Spill Bucket Installation Repair: UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Repairs. Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes Yes
	INO	031 internal hispections (integrity Assessments).			<u>Yes</u> No
LLeak Detection Equipment Operability Check:	No	LIST Internal Lining Inspections:	No		110
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	
Leak Detection Monitoring Services:	No	UST Internal Lining Inspections: Other:	No	UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing:	No No	Other:	No	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	No No nvironmental	Other: Service Firms		UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No nvironmental No	Other: Service Firms UST Compliance Consultants:	Yes	UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No nvironmental No <u>Yes</u>	Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes	UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No nvironmental No Yes Yes	Other: Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	Yes	UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No nvironmental No Yes Yes	Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes	UST Piping/Sump Installation: UST System Removal:	<u>Yes</u>

Company		Listing Submittee		Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27603				Mountains (West of I-77): No	
	W	ebsite <u>eastcoastenv.com</u>		Mountains (West of 1-77). No	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submittee	d 1/4/2022	Area of state conducts work	
EnviroTrac Ltd.		Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Suite J		Tux			
Greensboro, NC 27410	W	ebsite envirotrac.com		Mountains (West of I-77): Yes	
Comp	olianco Tocti				
Automatic Line Leak Detector Testing:	mance resti	ng and Monitoring		UST Equipmment Service Contractors	
Automatio Eine Ecak Detector Testing.		ng and Monitoring Overfill Prevention Equipment Operability Check:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No		No No		No No
	No No	Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Containment Sump Testing:	No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No No Vo nvironmenta Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No No No No No No No voironmenta Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company	o i Tovido	Listing Sub		Area of state conducts work	
Evo Corporation	Pho	one (336) 725-5844		Coastal (East of I-95): Yes	3
1703 Vargrave Street		Fax		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27107	'			Mountains (West of I-77): Yes	
	Webs	site <u>www.evocorp.net</u>		Mountains (West of 1-11). Tes	•
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ov	erfill Prevention Equipment Operability Chec	ck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Sta	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		ill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		T Internal Inspections (Integrity Assessment	ts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Oth	ner:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental Se	ervice Firms		Other: Vacuum Truck	Services
Emergency Cleanup - Spill/Release:	<u>Yes</u> US	T Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No US	T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Wa	aste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes Oth	ner: Transpo	ortation Services		
Soil and Water Testing Lab:	No				
Company		Listing Sub	mitted 12/30/2021	Area of state conducts work	
Geo-Hydro Engineers, Inc.	Pho	one (704) 837-7174		Coastal (East of I-95): Yes	3
2748 Interstate Street		Fax		Central (West of I-95 and East of I-77): Yes	S
Suite A				Mountains (West of I-77): Yes	
Charlotte, NC 28208	Webs	site <u>www.geohydro.com</u>		wountains (west of 1-77). Tes	•
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:				COT Equipminont Cot vice Contractors	
_	No Ov	erfill Prevention Equipment Operability Chec	ck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		erfill Prevention Equipment Operability Checatistical Iventory Reconciliation Services:	k: No No		No No
	No Sta			Dispenser Meter Repair/Calibration:	
Containment Sump Testing:	No Sta	atistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Containment Sump Testing: Corrosion Protection Design Experts:	No Sta No Sp No Ta	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Sta No Sp No Ta No US	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Sta No Sp No Ta No US	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessment T Internal Lining Inspections:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Sta No Sp No Ta No US	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessment T Internal Lining Inspections:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Sta No Sp No Ta No US No Ott	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessment T Internal Lining Inspections: ner:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Sta No Sp No Ta No US No US No Oth No	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessment T Internal Lining Inspections: ner:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Sta No Sp No Ta No US No US No Ott No Ott No Ott No US	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: IT Internal Inspections (Integrity Assessment IT Internal Lining Inspections: ner:	No No No ts): No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Sta No Sp No Ta No US No Ott No Ott No Ta No US No Ott No Ott No US No Ott No US Yes US	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessment T Internal Lining Inspections: ner: ervice Firms T Compliance Consultants:	No No No ts): No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No State No Sp No Ta No US No Otf No Otf No US No US Yes US Yes Wa	atistical Iventory Reconciliation Services: ill Prevention Equipment Testing: nk Tightness Testing: IT Internal Inspections (Integrity Assessment IT Internal Lining Inspections: ner: ervice Firms IT Compliance Consultants: IT Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitte		Area of state conducts work	
Geological Resources, Inc.	Pł	none (704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28112		(101) 010 1012		Mountains (West of I-77): Yes	
	Web	site grienv.com		mountains (west of 1-77). Tes	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No O	ther:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u> U	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> U	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u> W	aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No O	ther:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 11/16/2023	Area of state conducts work	
Groundwater Management Associates, Inc.	Pł	none (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100				Mountains (West of I-77): Yes	
Greenville, NC 27834	Web	site <u>www.gma-nc.com</u>		Mountains (West of 1-77). 163	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
		pin i reventien Equipment reeting.	No		NI-
Corrosion Protection System Repairs:		ank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Ta	· · · · · · · · · · · · · · · · · · ·		UST Equipment Installation - Other: UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ta	ank Tightness Testing:	No	UST Equipment Repair: UST System Installation - Complete Systems:	
Corrosion Protection System Testing:	No Ta No U No U	ank Tightness Testing: ST Internal Inspections (Integrity Assessments):	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Ta No U No U	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ta No U No U No O	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No To No U No O No	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Ti No U No O No O No O vironmental S	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: Service Firms	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No To No U No O No No No No V Yes U	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: Service Firms ST Compliance Consultants:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No To No U No O No O No O V Yes U Yes W	ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: Service Firms ST Compliance Consultants: ST Equipment Verification:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No

Company	O I TOVIGO	Listing Submitted	10/26/2021	Area of state conducts work	
Guardian Fueling Technologies	Pho	ne (919) 729-6980		Coastal (East of I-95): Yes	
5116 Departure Drive Raleigh, NC 27616	F	ax (919) 769-2919		Central (West of I-95 and East of I-77): Yes	
	Webs	ite <u>www.guardianfueltech.com</u>		Mountains (West of I-77): No	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	erfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes Sta	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Spi	I Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Tar	k Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No US	Γ Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes US	Γ Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes Oth	er: SafeGuard UST Inspection Se	ervices	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental Se	rvice Firms		Other: FuelGuard fuel polishing / tank of	leaning
Emergency Cleanup - Spill/Release:	No US	Γ Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No US	Γ Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Wa	ste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Oth	er:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/25/2022	Area of state conducts work	
HARCO Services LLC	Pho	ne (770) 917-8846		Coastal (East of I-95): Yes	
PO Box 2347	F	ax (770) 917-0921		Central (West of I-95 and East of I-77): Yes	
Kennesaw, GA 30156				Mountains (West of I-77): Yes	
	Webs	ite <u>www.harcoservices.com</u>		modificants (West of 177).	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Sta	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spi	I Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tar	k Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No US	Γ Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
		(g,,,,,,,		110-0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u>Yes</u>
Leak Detection Equipment Operability Check:		Γ Internal Lining Inspections:	No	UST System Installation - Complete Systems:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:		Γ Internal Lining Inspections:	No	UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes
	No US	Γ Internal Lining Inspections:	No	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	No US' No Oth	Γ Internal Lining Inspections: er:	No	UST Piping/Sump Installation:	Yes
Leak Detection Monitoring Services: Line Tightness Testing:	No US No Oth No nvironmental Se	Γ Internal Lining Inspections: er:	No No	UST Piping/Sump Installation: UST System Removal:	Yes
Leak Detection Monitoring Services: Line Tightness Testing:	No US' No Oth No nvironmental Se No US'	Γ Internal Lining Inspections: er: rvice Firms		UST Piping/Sump Installation: UST System Removal:	Yes
Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No US' No Oth No nvironmental Se No US' No US'	T Internal Lining Inspections: er: rvice Firms Γ Compliance Consultants:	No	UST Piping/Sump Installation: UST System Removal:	Yes
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No US' No Oth No nvironmental Se No US' No US'	T Internal Lining Inspections: er: rvice Firms T Compliance Consultants: T Equipment Verification: ste Disposal and Treatment:	No No	UST Piping/Sump Installation: UST System Removal:	Yes

Company		` , ,	Submitted	4/11/2023	Area of state conducts work	
INENCO, Inc.	PI	none (704) 662-8192			Coastal (East of I-95): Yes	
132 W. Statesville Avenue		Fax (704) 662-8194			Central (West of I-95 and East of I-77): Yes	
Mooresville, NC 27115		(101) 012			Mountains (West of I-77): Yes	
	Web	site			mountains (West of 1-77). Tes	
Comp	oliance Testing	ı and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	verfill Prevention Equipment Operability	Check: N	10	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services	s: N	10	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	N	10	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Testing:	N	10	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		ST Internal Inspections (Integrity Assess	sments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	N	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No C	ther:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental \$	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:	<u>Y</u>	<u>′es</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> U	ST Equipment Verification:	N	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes W	aste Disposal and Treatment:	N	No		
Oil and Solvent Recycling:	No C	ther:				
Soil and Water Testing Lab:	No					
Company		Listing	Submitted	5/15/2023	Area of state conducts work	
JF Petroleum Group	PI	none (919) 744-4391			Coastal (East of I-95): Yes	
100 Perimeter Park Drive		Fax			Central (West of I-95 and East of I-77): Yes	
Suite H					Mountains (West of I-77): Yes	
Morrisville, NC 27560	Web	site jfpetrogroup.com/services/en	vironmentalcor	<u>mpliance</u>	Mountains (West of 1-77). Tes	
Comp	oliance Testing	and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes C	verfill Prevention Equipment Operability	Check: Y	<u>'es</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u> S	tatistical Iventory Reconciliation Services	s: N	10	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	<u>Y</u>	<u>′es</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No T	ank Tightness Testing:	<u>Y</u>	<u>′es</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assess	sments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:		CT Internal Lining Inconstitute		No	UST System Installation - Complete Systems:	<u>Yes</u>
	<u>Yes</u> ∪	ST Internal Lining Inspections:	ı,			<u>Yes</u>
Leak Detection Monitoring Services:		ther:	IN		UST Piping/Sump Installation:	100
Leak Detection Monitoring Services: Line Tightness Testing:			I.		UST System Removal:	Yes
Line Tightness Testing:	<u>Yes</u>	ther:				
Line Tightness Testing:	Yes Yes nvironmental	ther:			UST System Removal:	
Line Tightness Testing:	Yes Yes Tvironmental S	ther: Service Firms	Y	′es	UST System Removal:	
Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes Convironmental Section No UNO UNO UNO UNI NO UN	ST Compliance Consultants:	Ϋ́		UST System Removal:	
Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Convironmental Section No. U. No. U. No. W.	Service Firms ST Compliance Consultants: ST Equipment Verification:	Ϋ́	<u>(es</u> (es	UST System Removal:	

Company		Listing Submitted		Area of state conducts work	
Jones Covey Group	F	Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730		(000)		Mountains (West of I-77): Yes	
	We	ebsite		Mountains (West of 1-77). Tes	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No '	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
MGF Environmental, PLLC	F	Phone (904) 814-3680		Coastal (East of I-95): No	
288 Gap Creek Rd		Fax		Central (West of I-95 and East of I-77): Yes	
Fletcher, NC 28732				Mountains (West of I-77): Yes	
	We	ebsite mgfenvironmental.com		Mountains (West of 1-77): Tes	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:			110		
Controller Following Exports.		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No			Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
	No S	Spill Prevention Equipment Testing:	No		
Corrosion Protection System Repairs:	No No No	Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	UST Equipment Installation - Other:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Signal No	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No nvironmental	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No nvironmental	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No No No No No No No nvironmental No Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No rvironmental No Yes	Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No	UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No

Company			ting Submitted	2/28/2022	Area of state conducts work	
Parliament Petroleum Services LLC	Р	none (864) 871-8058			Coastal (East of I-95): No	
3277 Neely Ferry Rd		Fax			Central (West of I-95 and East of I-77): No	
Laurens, SC 29360					Mountains (West of I-77): Yes	
	Wel	osite Parliamentpetroleumserv	rices.com		mountains (West of 177). 163	
Comp	oliance Testin	g and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	verfill Prevention Equipment Operat	oility Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Ser	vices:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No T	ank Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No L	ST Internal Inspections (Integrity As	sessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No L	ST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No C	ther:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No L	ST Compliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	No L	ST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No V	/aste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No C	ther:				
Soil and Water Testing Lab:	No					
Company		List	ting Submitted	11/1/2023	Area of state conducts work	
Peak Hydrogeologic, PLLC	Р	none (828) 817-5209			Coastal (East of I-95): No	
470 Hogback Mtn Rd		Fee			Central (West of I-95 and East of I-77): Yes	
Tryon, NC 28782		Fax				
I.						
	Wel	psite https://peakhydrogeologic	c.com		Mountains (West of I-77): Yes	
Comp			c.com			
Comp Automatic Line Leak Detector Testing:	oliance Testin	osite https://peakhydrogeologic		No	Mountains (West of I-77): Yes	No
_	No (psite https://peakhydrogeologic	bility Check:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Automatic Line Leak Detector Testing:	No S	psite https://peakhydrogeologicg and Monitoring verfill Prevention Equipment Operation	oility Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No S	psite https://peakhydrogeologicg and Monitoring Everfill Prevention Equipment Operate tatistical Iventory Reconciliation Services	bility Check:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No S No S No S No T	psite https://peakhydrogeologicg and Monitoring Everfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing:	bility Check:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S No S No T No T	psite https://peakhydrogeologicg and Monitoring pverfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing: ank Tightness Testing:	bility Check: vices: sessments):	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S	psite https://peakhydrogeologic g and Monitoring everfill Prevention Equipment Operate tatistical Iventory Reconciliation Ser- pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity As	bility Check: vices: sessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S	psite https://peakhydrogeologicg and Monitoring Everfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity As ST Internal Lining Inspections:	bility Check: vices: sessments):	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	psite https://peakhydrogeologicg and Monitoring pverfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity As ST Internal Lining Inspections: other:	bility Check: vices: sessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	psite https://peakhydrogeologicg and Monitoring pverfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity As ST Internal Lining Inspections: other:	bility Check: vices: sessments):	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	psite https://peakhydrogeologicg and Monitoring Iverfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity As ST Internal Lining Inspections: other:	pility Check: vices: sessments):	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No S	posite https://peakhydrogeologicg and Monitoring Iverfill Prevention Equipment Operate tatistical Iventory Reconciliation Serpill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity As ST Internal Lining Inspections: Wither: Service Firms ST Compliance Consultants:	pility Check: vices: sessments):	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S	psite https://peakhydrogeologicg and Monitoring Diverfill Prevention Equipment Operate tatistical Iventory Reconciliation Service Firms ST Internal Inspections (Integrity As ST Internal Lining Inspections: Wither: Service Firms ST Compliance Consultants: ST Equipment Verification:	pility Check: vices: sessments):	No No No No No Vo	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company	o i iovidoi	Listing Submitted		Area of state conducts work	
Petroleum Equipment and Service, Inc.	Pho	one (704) 335-8801		Coastal (East of I-95): No	
4125 Sinclair Street		Fax (704) 342-1672		Central (West of I-95 and East of I-77): Yes	
PO Box 1949	-	(,		Mountains (West of I-77): Yes	
Denver, NC 28037	Websi	ite <u>www.petroleumequipment.net</u>		Modificants (West of 1-77). Tes	
Comp	oliance Testing a	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes Ove	erfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes Stat	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		Il Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		nk Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		T Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes US1	T Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes Oth	ner:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmental Se	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	T Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No UST	T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Was	ste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Oth	ner:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/14/2021	Area of state conducts work	
Petroleum Solutions Inc.	Pho	one (919) 605-1979		Coastal (East of I-95): Yes	
3012 Whitehart Ln.	F	Fax (919) 773-1704		Central (West of I-95 and East of I-77): Yes	
819 Purser Drive				Mountains (West of I-77): No	
Raleigh, NC 27606	Websi	ite <u>www.petroleumsolutionsinc.net</u>		Modificants (West of 1-77). No	
Comp	oliance Testing a	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	erfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Stat	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spil	Il Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Tan	nk Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No UST	T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No UST	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No Oth	ner:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental Se	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	T Compliance Consultants:	No		
Efficiency Cleanup - Spill/Release.					
Environmental Engineer/Geologist - Site Checks:	No UST	T Equipment Verification:	<u>Yes</u>		
		T Equipment Verification: uste Disposal and Treatment:	<u>Yes</u> No		
Environmental Engineer/Geologist - Site Checks:		ste Disposal and Treatment:			

Company		Listing Submitted	11/1/2023	Area of state conducts work	
Pilot Geological , PLLC	Pho	one (336) 870-3095		Coastal (East of I-95): Yes	
PO Box 128		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
743 Park Lawn Court		(600, 610 101		Mountains (West of I-77): Yes	
Kernersville, NC 27285	Webs	ite <u>www.pilotenviro.com</u>		Modificants (West Of 1-17). 165	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ov	erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Sta	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Sp	Il Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Oth	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmental Se	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u> US	T Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> US	T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u> Wa	ste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Oth	er:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
Practical Environmental Solutions	Pho	one (910) 790-8265		Coastal (East of I-95): Yes	
5634 Harvest Grove Lane		Fax Tax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28049	147.1	to a construction of the second		Mountains (West of I-77): No	
	Webs	ite <u>www.oil-tank.com</u>			
Comp		and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Il Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		T Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Oth	er:		UST Piping/Sump Installation:	No
				UST System Removal:	<u>Yes</u>
Line Tightness Testing:	No				
	No nvironmental Se	ervice Firms		Other: UST Abandonment In-place, State Com	npilance
Emergency Cleanup - Spill/Release:	nvironmental Se	ervice Firms T Compliance Consultants:	No	Other: UST Abandonment In-place, State Com	npilance
E	nvironmental Se		No No	Other: UST Abandonment In-place, State Com	npilance
Emergency Cleanup - Spill/Release:	No US Yes US	T Compliance Consultants:		Other: UST Abandonment In-place, State Com	npilance
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No US Yes US Yes Wa	T Compliance Consultants: T Equipment Verification:	No	Other: UST Abandonment In-place, State Com	npilance

Company		, ,	Listing Submitted	10/12/2022	Area of state conducts work	
Practical Environmental Solutions. PC	P	hone (910) 790-8265			Coastal (East of I-95): Yes	
5634 Harvest Grove Ln		Fax			Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28409					Mountains (West of I-77): No	
	Web	osite <u>www.oil-tank.com</u>			Mountains (West of 1-77). No	
Comp	oliance Testin	g and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	Overfill Prevention Equipment Op	erability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testir	ng:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	IST Internal Inspections (Integrity	y Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No L	IST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No C	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental \$	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No U	IST Compliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	IST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Vaste Disposal and Treatment:		No		
Oil and Solvent Recycling:		Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service	P	hone (704) 892-8600	<u> </u>		Coastal (East of I-95): Yes	
737 Zimmer Road		,			Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707		Fax (704) 892-8711				
	Wel	osite www.precisiontankse	rvice.com		Mountains (West of I-77): Yes	
Comp	oliance Testin	g and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Op	erability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	tatistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testir	ng:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	IST Internal Inspections (Integrity	y Assessments):	No	UST Equipment Repair:	<u>Yes</u>
1 1 5 1 2 5 5 1 1 1 1 1 1 1 1					LIOT Occident legislation of Commission Constants	No
Leak Detection Equipment Operability Check:		IST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	<u>Yes</u>	IST Internal Lining Inspections: Other:		No	UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
	<u>Yes</u>			No		No No
Leak Detection Monitoring Services: Line Tightness Testing:	Yes C	Other:		No	UST Piping/Sump Installation:	
Leak Detection Monitoring Services: Line Tightness Testing:	Yes C Yes Yes	Other:		Yes	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	Yes C Yes C Yes Provironmental S	Other: Service Firms			UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Yes Converse	Service Firms IST Compliance Consultants:		Yes	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Converse	Service Firms IST Compliance Consultants: IST Equipment Verification:		Yes No	UST Piping/Sump Installation: UST System Removal:	

Company			Listing Submitted	1/3/2022	Area of state conducts work	
Pyramid Environmental & Engineering, PC	Pho	ne (336) 335-3174			Coastal (East of I-95): Yes	
503 Industrial Avenue Greensboro, NC 27406	F	ax (336) 691-0648			Central (West of I-95 and East of I-77): Yes	
,	Websi	te <u>www.PyramidEnviro</u>	nmental.com		Mountains (West of I-77): Yes	
Comp	oliance Testing a	nd Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Ove	rfill Prevention Equipment C	perability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Stat	stical Iventory Reconciliatio	n Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Test	ing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tan	c Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST	Internal Inspections (Integr	ity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Othe	er:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental Se	vice Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes UST	Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:		Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes Was	te Disposal and Treatment:		<u>Yes</u>		
Oil and Solvent Recycling:	No Othe	er:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	6/29/2021	Area of state conducts work	
0000 5						
SR&R Environmental, Inc.	Pho	ne (910) 763-6274			Coastal (East of I-95): Yes	
4920 Highway 421 N.		ne (910) 763-6274 ax (910) 763-6132			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
	F	ax (910) 763-6132			Central (West of I-95 and East of I-77): Yes	
4920 Highway 421 N.		ax (910) 763-6132				
4920 Highway 421 N. Wilmington, NC 28401-	F	(910) 763-6132 te			Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	
4920 Highway 421 N. Wilmington, NC 28401-	Websi Dliance Testing a No Ove	te www.srrenviro.com Monitoring rfill Prevention Equipment C		No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
4920 Highway 421 N. Wilmington, NC 28401- Company Automatic Line Leak Detector Testing: Containment Sump Testing:	Websi Dliance Testing a No Ove No Stat	te www.srrenviro.com nd Monitoring rfill Prevention Equipment C stical Iventory Reconciliatio	n Services:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Websi Diance Testing at No Ove No Stat No Spill	te www.srrenviro.com Ind Monitoring If Il Prevention Equipment Constical Iventory Reconciliation Prevention Equipment Test	n Services:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
4920 Highway 421 N. Wilmington, NC 28401- Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Websi Dliance Testing a No Ove No Stat No Spill No Tanl	te www.srrenviro.com Ind Monitoring If Ill Prevention Equipment Constitution Prevention Equipment Test Tightness Testing:	n Services: ing:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Websi Dliance Testing a No Ove No Stat No Spill No Tani No UST	te www.srrenviro.com Ind Monitoring If Il Prevention Equipment Constitution Prevention Equipment Test In Tightness Testing: Internal Inspections (Integr	n Services: ing: ity Assessments):	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Websi Dliance Testing a No Ove No Stat No Spill No Tani No UST	te www.srrenviro.com Ind Monitoring If Ill Prevention Equipment Constitution Prevention Equipment Test Tightness Testing:	n Services: ing: ity Assessments):	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Websi Dliance Testing a No Ove No Stat No Spill No Tani No UST	te www.srrenviro.com Ind Monitoring Ind Moni	n Services: ing: ity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Websi Dliance Testing a No Ove No Stat No Spill No Tanl No UST No UST	te www.srrenviro.com Ind Monitoring Ind Moni	n Services: ing: ity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Websi Dliance Testing at No Ove No State No Spill No Tani No UST No UST No Other	te www.srrenviro.com Ind Monitoring If Ill Prevention Equipment Control Internal Inspections Internal Inspections Internal Lining Inspections	n Services: ing: ity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
4920 Highway 421 N. Wilmington, NC 28401- Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Websi Dliance Testing a No Ove No Stat No Spill No Tanl No UST No UST No Othe No	te www.srrenviro.com Ind Monitoring If Ill Prevention Equipment Control Internal Inspections Internal Inspections Internal Lining Inspections	n Services: ing: ity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
4920 Highway 421 N. Wilmington, NC 28401- Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Websi Dliance Testing a No Ove No Stat No Spill No Tani No UST No UST No Othe No nvironmental Ser	te www.srrenviro.com Ind Monitoring Ind Moni	n Services: ing: ity Assessments):	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
4920 Highway 421 N. Wilmington, NC 28401- Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Websi Dliance Testing at No Ove No State No Spill No Tani No UST No Other	te www.srrenviro.com Ind Monitoring Ind Monitoring Ind Monitoring Ind Prevention Equipment Costical Iventory Reconciliation Prevention Equipment Test Internal Inspections (Integral Internal Lining Inspections: Internal Lining Inspections: Internal Compliance Consultants:	n Services: ing: ity Assessments):	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
4920 Highway 421 N. Wilmington, NC 28401- Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Websi Dliance Testing at No Ove No State No Spill No Tani No UST No Other	te www.srrenviro.com Ind Monitoring If Il Prevention Equipment Control Equipment Control Equipment Test Internal Inspections (Integral Internal Lining Inspections: Internal Compliance Consultants: Equipment Verification: It Equipment Verification: It Disposal and Treatment:	n Services: ing: ity Assessments):	No No No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company		Listing Submitted	3/6/2024	Area of state conducts work	
Titan Environmental Group	F	Phone (984) 200-6825		Coastal (East of I-95): Yes	
2005 Citation Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529				Mountains (West of I-77): Yes	
	We	bsite <u>www.titanenvirogroup.com</u>		meantaine (treet et 177). Tee	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/31/2023	Area of state conducts work	
Valor Construction LLC	F	Phone (205) 577-1035		Coastal (East of I-95): Yes	
PO Box 680654		Fax		Central (West of I-95 and East of I-77): Yes	
Fort Payne, AL 35968				Mountains (West of I-77): Yes	
	We	bsite		would west of 1-77).	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
_		Service Firms		Other:	
Er	nvironmental	COLVIDE LITTLE			
Emergency Cleanup - Spill/Release:		UST Compliance Consultants:	No		
	No		No No		
Emergency Cleanup - Spill/Release:	No No	UST Compliance Consultants:			
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No	UST Compliance Consultants: UST Equipment Verification:	No		

Company		Listing Submitted	1	Area of state conducts work	
VITAL FUEL SYSTEMS INC.	Р	hone (919) 303-7374		Coastal (East of I-95): Yes	
1076 CLASSIC ROAD		Fax (919) 303-7399		Central (West of I-95 and East of I-77): Yes	
APEX, NC 27540		(6.0) 600		Mountains (West of I-77): Yes	
	Wel	bsite <u>WWW.VITALFUELSYSTEMS.COM</u>		mountains (west of 177). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No T	Fank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No L	JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No L	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No C	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No L	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No L	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No V	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No C	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Withers Ravenel, Inc.	Р	hone (919) 469-3340		Coastal (East of I-95): Yes	
115 MacKenan Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Cary, NC 27591				Mountains (West of I-77): Yes	
	Wel	bsite <u>www.withersravenel.com</u>		Wouldains (West of 1-77). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		gg		OST Equipininent Service Contractors	
		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No (No No		No No
Containment Sump Testing: Corrosion Protection Design Experts:	No C	Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
	No S No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No C No S No S No T	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No C No S No T No U	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Control No Solution No Control	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Control No Solution No Control	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Control	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Convironmental	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Convironmental Street	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No Ves No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No