

North Carolina Department of Transportation Roadside Environmental Unit Erosion & Sedimentation / Stormwater Report



Project Information

Inspection Date: 08/17/2022 **Evaluator:** Reid Whitehead
Project #: 36030.3.GV4 **TIP #:** I-4700 **Contract #:** C204266
Division #: 13 **County:** Buncombe
Project Type: Contract **Engineer:** Buncombe I-4700 I-26 Widening
Project Length: 7.49 **Disturbed Acres:** 10
River Basin: French Broad **HQW Zone:** NO **Trout Zone:** NO
Location Description: I-26 from NC-280 (Exit 40) to I-40

Project Evaluation

Report Type: Routine ICA ICA Ex 1st ICA Ex 2nd CICA - SWO
 PCN ECPAR

Length	Section	Installation of BMPs	Maintenance of BMPs	Effectiveness of BMPs	Plan Implementation	Overall Project Evaluation
0.01	Station 1090+50 Rt.	8	8	8	8	8

Grading Scale: 0 - 6 = Immediate Corrective Action Required, 7 = Fair, 8 = Good, 9 = Very Good, 10 = Excellent

Remarks and Recommendations:

The ICA is lifted.

Reinspection of the ICA site was done today 8/17/2022 with Luke Middleton - Resident Engineer and Rick Cunningham - Erosion Inspector.

Approximately L- station 1090+50 Rt.

The material lost into the JS has been cleaned up and removed.

Perimeter Silt Fence with Special Sediment Control Fence outlets has been reinstalled along the JS.

A Special Sediment Control Fence check has been installed across the fillslope above the work area.

Two earth berms have installed above the Special Sediment Control Fence check.