

City of High Point Sedimentation Inspection Report

Inspector Jan It Shephere ASV Date of Inspection 7/1/22
Permit Number EN-21-0226 Project Name Triangle Lake Re) Commercial Sike
Address 3124 Triangle Lake Rd High Poist NE 27260
Individual responsible for Erosion Control fre of usa, LLC
Mailing address for individual 7 west mount Court, Corcus bore Ne 27410
Contact made with Pany on Sik Soil/Weather Conditions Dry /cker
Site in COMPLIANCEwith approved plan or in NON-COMPLIANCEUnder NOV?
The following Violations that were discovered on your site are: Failere to Smoket,
Failure to install clauses, Failure to Follow Plan
The necessary actions to correct the above violations are: Install by thes in Sectional
basin on Site. Place Coverage in along basin when Com Pheted within
14 days of Completion, Convect Siversion ditch to basin and
ensure proper drainage into the basin.
Additional remarks by Inspector: FRP was sant Civil Penalty Assessment Letter
on 6/9/22. As of bodays date 7/1/22, Contractor has not Completed
the basin on Site, All devices on Site Must furtien properly, and
be installed Correctly before civil penalities will be Littled for
this Sile
Has off-site sedimentation occurred since last inspection? YESNO
Photographs YES NO
Describe and estimate amount of off-site sedimentation damage and area that it covers:
<u>none</u>