


# Compliance Inspection Overview

A photograph of water flowing through a concrete culvert. The water is clear and creates a white, frothy cascade as it falls. The concrete walls of the culvert are visible on either side, and the background shows a natural landscape with trees and a stream.

Tom Tharrington

Environmental Program Consultant

Wilmington Regional Office


910-796-7324/[tom.tharrington@ncdenr.gov](mailto:tom.tharrington@ncdenr.gov)



# Compliance Inspections

## Wilmington Regional Office

- System Inspections for
  - NPDES Wastewater Treatment
  - Non-Discharge Wastewater Treatment
  - Residual Solids Application
  - Sewer Collection Systems
  - Closed Loop Recycle Systems
  - Spills & Complaints






# Monitoring

## Self-Monitoring & Compliance Monitoring

# Sampling & Measurements

- Compliance History of Discharge Monitoring Reports
- Appropriate Sampling Protocol
- Proper Analytical Methods
- Certified Laboratory
- Complete Records
- Meter Calibrations Performed





# Operations & Maintenance

---



# Problems & Deficiencies

---