Underground Storage Tanks (USTs) Public Record - Summary Information

General Information

Public Record Posted Date: 12/20/2024

Total Number Of Active UST Facilities: 7,147

Total Number Of USTs: 23,315

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 2,756

Inspection Period Dates: 10/1/2023 To: 9/30/2024

Percent Compliance (Combined Measure): 55%

Summary Information For Releases

Number Of Confirmed UST Releases: 149

Release Reporting Period Dates 10/1/2024 To: 09/30/20204

Summary Information For Release Sources And Causes

1&8 2 3 4 5 6 7

				~~						-		•				
Source			Spill		Overfill		Corrosion		Phys/Mech Damage		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	84	56	1	1%	1	1%	14	17%	10	12%	0	0%	3	4%	55	65%
Piping	19	13	0	0%	0	0%	4	21%	10	53%	0	0%	1	5%	4	21%
Dispenser	15	10	2	13%	0	0%	0	0%	3	20%	0	0%	0	0%	10	67%
STP**	0	0	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery																
Problem	2	1	0	0%	2	100%	0	0%	0	0%	0	0%	0	0%	0	0%
Other	9	6	0	0%	1	11%	1	11%	2	22%	0	0%	0	0%	5	56%
Unknown	20	13	0	0%	0	0%	1	5%	0	0%	0	0%	1	5%	18	90%
Totals	149	100	3	2%	4	3%	20	13%	25	17%	0	0%	5	3%	92	62%
•		•														

^{*}Additionally, there were 213 confirmed releases from non-regulated USTs, primarily heating oil tanks. There are also 366 confirmed releases from non-usts during the reporting period.

To obtain site-specific information on UST releases contact the Regional DEQ Office for the county in which the release occurred. To obtain UST compliance information contact the UST Section Central Office, Permits and Inspection Branch

^{**}STP - Submersible Turbine Pump