

## UST Service Provider List (All) - Corrosion Protection Companies Only

| Company   | Listing Submitted   | 12/30/2021          | Area of state conducts work   |
|---|---|---------------------|---|
| <b>Bay Compliance and Testing LLC</b><br>P.O. Box 16628<br>Chesapeake, VA 23328   | <b>Phone</b> (757) 410-5974<br><br><b>Fax</b><br><br><b>Website</b> <a href="https://baycomplianceandtesting.com/">https://baycomplianceandtesting.com/</a>   |                     | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> No<br><b>Mountains (West of I-77):</b> No   |
| Compliance Testing and Monitoring   |   |                     | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: <b>Yes</b>                         | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                         |                     | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: <b>Yes</b><br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |                     |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |                     |   |
| Company   | Listing Submitted   | 1/10/2022           | Area of state conducts work   |
| <b>Bunnell-Lammons Engineering, Inc.</b><br>130 Oval Road<br>Arden, NC 28704  | <b>Phone</b> (828) 277-0100<br><br><b>Fax</b> (828) 277-0110<br><br><b>Website</b> <a href="http://www.blecorp.com">www.blecorp.com</a>   |                     | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |                     | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: <b>Yes</b><br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): <b>Yes</b><br>UST Internal Lining Inspections: <b>Yes</b><br>Other: |                     | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other:         |
| Environmental Service Firms   |   |                     |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: <b>Yes</b><br>Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b><br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: <b>Yes</b><br>UST Equipment Verification: <b>Yes</b><br>Waste Disposal and Treatment: <b>Yes</b><br>Other:  | Trust Fund Projects |   |

## UST Service Provider List (All) - Corrosion Protection Companies Only

| Company   | Listing Submitted   | 11/1/2023  | Area of state conducts work   |
|---|---|------------|---|
| <b>Catholic Protection Services, Inc.</b><br>916 Egypt Rd.<br>Bluff City, NC 37618  | <b>Phone</b> (423) 895-1500<br><br><b>Fax</b><br><br><b>Website</b>   |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |            | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |            | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |            |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |            |   |
| Company   | Listing Submitted   | 11/21/2023 | Area of state conducts work   |
| <b>Conklin Corrosion Control LLC</b><br>118 Oak Point Lane<br>Stony Point, NC 28678   | <b>Phone</b> (704) 560-9154<br><br><b>Fax</b><br><br><b>Website</b> <a href="mailto:benconklincc@gmail.com">benconklincc@gmail.com</a>  |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |            | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |            | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |            |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |            |   |

## UST Service Provider List (All) - Corrosion Protection Companies Only

| Company   | Listing Submitted | 12/30/2021  | Area of state conducts work   |
|---|-------------------|---|---|
| <b>Crompco, LLC</b><br>1815 Gallagher Road<br>Plymouth Meeting, PA 19462<br><br><b>Phone</b> (610) 278-7203<br><b>Fax</b> (610) 278-7621<br><br><b>Website</b> <a href="http://www.crompco.com">www.crompco.com</a>             |                   |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring   |                   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>        | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:   | <b>Yes</b>        | Statistical Inventory Reconciliation Services:    | <b>Yes</b>  |
| Corrosion Protection Design Experts:  | No                | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | No                | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:  | <b>Yes</b>        | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:   | <b>Yes</b>        | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:   | <b>Yes</b>        | Other:  |   |
| Line Tightness Testing:   | <b>Yes</b>        |   |   |
| Environmental Service Firms   |                   |   |   |
| Emergency Cleanup - Spill/Release:  | No                | UST Compliance Consultants:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:   | No                | UST Equipment Verification:                       | <b>Yes</b>  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No                | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:  | No                | Other:  |   |
| Soil and Water Testing Lab:   | No                |   |   |
| Company   | Listing Submitted | 5/14/2024   | Area of state conducts work   |
| <b>Environmental Petroleum Services</b><br>1234 Gordon Park Rd<br>Augusta, GA 30901<br><br><b>Phone</b> (877) 297-6763<br><b>Fax</b><br><br><b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a> |                   |   | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes  |
| Compliance Testing and Monitoring   |                   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>        | Overfill Prevention Equipment Operability Check:  | <b>Yes</b>  |
| Containment Sump Testing:   | <b>Yes</b>        | Statistical Inventory Reconciliation Services:    | No  |
| Corrosion Protection Design Experts:  | <b>Yes</b>        | Spill Prevention Equipment Testing:               | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | <b>Yes</b>        | Tank Tightness Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Testing:  | <b>Yes</b>        | UST Internal Inspections (Integrity Assessments): | No  |
| Leak Detection Equipment Operability Check:   | <b>Yes</b>        | UST Internal Lining Inspections:                  | No  |
| Leak Detection Monitoring Services:   | No                | Other:  |   |
| Line Tightness Testing:   | <b>Yes</b>        |   |   |
| Environmental Service Firms   |                   |   |   |
| Emergency Cleanup - Spill/Release:  | No                | UST Compliance Consultants:                       | No  |
| Environmental Engineer/Geologist - Site Checks:   | No                | UST Equipment Verification:                       | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No                | Waste Disposal and Treatment:                     | No  |
| Oil and Solvent Recycling:  | No                | Other:  |   |
| Soil and Water Testing Lab:   | No                |   |   |

## UST Service Provider List (All) - Corrosion Protection Companies Only

| Company  | Listing Submitted   | 1/1/2022  | Area of state conducts work   |
|--|---|---|---|
| <b>Galloway</b><br>6162 South Willow Drive<br>Suite 320<br>Greenwood Village, CO 80111 | <b>Phone</b> (303) 770-8884<br><b>Fax</b> (303) 770-3636<br><b>Website</b> <a href="http://www.Gallowayus.com">www.Gallowayus.com</a> |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring  |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | Dispenser Meter Repair/Calibration:   |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | Leak Detection Equipment Installation Servicing:  |
| Corrosion Protection Design Experts:   | <u>Yes</u>  | Spill Prevention Equipment Testing:               | Spill Bucket Installation Repair:   |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                           | UST Equipment Installation - Other:   |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair:   |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:                  | UST System Installation - Complete Systems:   |
| Leak Detection Monitoring Services:  | No  | Other: UST/AST System Design                      | UST Piping/Sump Installation:   |
| Line Tightness Testing:  | No  |   | UST System Removal:   |
|  |   |   | Other:  |
| Environmental Service Firms  |   |   |   |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       |   |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                       |   |
| Environmental Engineer/Geologist Soil and GW Cleanu                                    | No  | Waste Disposal and Treatment:                     |   |
| Oil and Solvent Recycling:   | No  | Other: UST/AST System Design                      |   |
| Soil and Water Testing Lab:  | No  |   |   |
| Company  | Listing Submitted   | 12/20/2022  | Area of state conducts work   |
| <b>Jones Covey Group</b><br>9595 Lucas Ranch Rd STE 100<br>Rancho Cucamonga, CA 91730  | <b>Phone</b> (888) 972-7581<br><b>Fax</b> (909) 484-0300<br><b>Website</b>  |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| Compliance Testing and Monitoring  |   |   | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing:  | <u>Yes</u>  | Overfill Prevention Equipment Operability Check:  | Dispenser Meter Repair/Calibration:   |
| Containment Sump Testing:  | <u>Yes</u>  | Statistical Inventory Reconciliation Services:    | Leak Detection Equipment Installation Servicing:  |
| Corrosion Protection Design Experts:   | <u>Yes</u>  | Spill Prevention Equipment Testing:               | Spill Bucket Installation Repair:   |
| Corrosion Protection System Repairs:   | <u>Yes</u>  | Tank Tightness Testing:                           | UST Equipment Installation - Other:   |
| Corrosion Protection System Testing:   | <u>Yes</u>  | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair:   |
| Leak Detection Equipment Operability Check:  | <u>Yes</u>  | UST Internal Lining Inspections:                  | UST System Installation - Complete Systems:   |
| Leak Detection Monitoring Services:  | <u>Yes</u>  | Other:  | UST Piping/Sump Installation:   |
| Line Tightness Testing:  | <u>Yes</u>  |   | UST System Removal:   |
|  |   |   | Other:  |
| Environmental Service Firms  |   |   |   |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       |   |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                       |   |
| Environmental Engineer/Geologist Soil and GW Cleanu                                    | No  | Waste Disposal and Treatment:                     |   |
| Oil and Solvent Recycling:   | No  | Other:  |   |
| Soil and Water Testing Lab:  | No  |   |   |

## UST Service Provider List (All) - Corrosion Protection Companies Only

| <b>Company</b>  | <b>Listing Submitted</b> | <b>12/30/2021</b>   | <b>Area of state conducts work</b>  |
|---|--------------------------|---|---|
| <b>Precision Tank Service</b><br>737 Zimmer Road<br>Fort Mill , SC 29707<br><br><b>Phone</b> (704) 892-8600<br><b>Fax</b> (704) 892-8711<br><br><b>Website</b> <a href="http://www.precisiontankservice.com">www.precisiontankservice.com</a> |                          |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:              | <b>Yes</b>  |
| Containment Sump Testing:   | <b>Yes</b>               | Statistical Inventory Reconciliation Services:                | No  |
| Corrosion Protection Design Experts:  | No                       | Spill Prevention Equipment Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | No                       | Tank Tightness Testing:                                       | <b>Yes</b>  |
| Corrosion Protection System Testing:  | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments):             | No  |
| Leak Detection Equipment Operability Check:   | <b>Yes</b>               | UST Internal Lining Inspections:                              | No  |
| Leak Detection Monitoring Services:   | <b>Yes</b>               | Other:  |   |
| Line Tightness Testing:   | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | No                       | UST Compliance Consultants:                                   | <b>Yes</b>  |
| Environmental Engineer/Geologist - Site Checks:   | No                       | UST Equipment Verification:                                   | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No                       | Waste Disposal and Treatment:                                 | No  |
| Oil and Solvent Recycling:  | No                       | Other:  |   |
| Soil and Water Testing Lab:   | No                       |   |   |
| <b>Superior Services</b><br>PO Box 982<br>Hendersonville, NC<br><br><b>Phone</b> (828) 698-6286<br><b>Fax</b> (828) 698-6294<br><br><b>Website</b> <a href="http://www.superiorservices.com">www.superiorservices.com</a>                     |                          |   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |
| <b>Compliance Testing and Monitoring</b>  |                          |   | <b>UST Equipment Service Contractors</b>  |
| Automatic Line Leak Detector Testing:   | <b>Yes</b>               | Overfill Prevention Equipment Operability Check:              | <b>Yes</b>  |
| Containment Sump Testing:   | <b>Yes</b>               | Statistical Inventory Reconciliation Services:                | No  |
| Corrosion Protection Design Experts:  | <b>Yes</b>               | Spill Prevention Equipment Testing:                           | <b>Yes</b>  |
| Corrosion Protection System Repairs:  | <b>Yes</b>               | Tank Tightness Testing:                                       | <b>Yes</b>  |
| Corrosion Protection System Testing:  | <b>Yes</b>               | UST Internal Inspections (Integrity Assessments):             | <b>Yes</b>  |
| Leak Detection Equipment Operability Check:   | <b>Yes</b>               | UST Internal Lining Inspections:                              | <b>Yes</b>  |
| Leak Detection Monitoring Services:   | No                       | Other: repair and lining, AST Inspections, Repairs and Lining |   |
| Line Tightness Testing:   | <b>Yes</b>               |   |   |
| <b>Environmental Service Firms</b>  |                          |   |   |
| Emergency Cleanup - Spill/Release:  | No                       | UST Compliance Consultants:                                   | No  |
| Environmental Engineer/Geologist - Site Checks:   | No                       | UST Equipment Verification:                                   | No  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No                       | Waste Disposal and Treatment:                                 | No  |
| Oil and Solvent Recycling:  | No                       | Other:  |   |
| Soil and Water Testing Lab:   | No                       |   |   |

## UST Service Provider List (All) - Corrosion Protection Companies Only

| Company   | Listing Submitted   | 1/26/2022 | Area of state conducts work   |
|---|---|-----------|---|
| <b>UST Corrosion Management, Inc.</b><br>2764 Pleasant Rd #10714<br>Fort Mill, SC 29708   | <b>Phone</b> (888) 822-2431<br><b>Fax</b> (803) 802-0561<br><b>Website</b> <a href="http://www.ustcorrosion.com">www.ustcorrosion.com</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: No<br>Containment Sump Testing: No<br>Corrosion Protection Design Experts: <b>Yes</b><br>Corrosion Protection System Repairs: <b>Yes</b><br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: No<br>Leak Detection Monitoring Services: No<br>Line Tightness Testing: No                         | Overfill Prevention Equipment Operability Check: No<br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: No<br>Tank Tightness Testing: No<br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other:                         |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |
| Company   | Listing Submitted   | 7/14/2022 | Area of state conducts work   |
| <b>VALLEY TANK TESTING</b><br>451 APOLLO BEACH BOULEVARD<br>APOLLO BEACH, FL 33572  | <b>Phone</b> (813) 671-9065<br><b>Fax</b> (866) 328-9796<br><b>Website</b> <a href="http://WWW.VALLEYTANK.COM">WWW.VALLEYTANK.COM</a>   |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes   |
| Compliance Testing and Monitoring   |   |           | UST Equipment Service Contractors   |
| Automatic Line Leak Detector Testing: <b>Yes</b><br>Containment Sump Testing: <b>Yes</b><br>Corrosion Protection Design Experts: No<br>Corrosion Protection System Repairs: No<br>Corrosion Protection System Testing: <b>Yes</b><br>Leak Detection Equipment Operability Check: <b>Yes</b><br>Leak Detection Monitoring Services: <b>Yes</b><br>Line Tightness Testing: <b>Yes</b> | Overfill Prevention Equipment Operability Check: <b>Yes</b><br>Statistical Inventory Reconciliation Services: No<br>Spill Prevention Equipment Testing: <b>Yes</b><br>Tank Tightness Testing: <b>Yes</b><br>UST Internal Inspections (Integrity Assessments): No<br>UST Internal Lining Inspections: No<br>Other: |           | Dispenser Meter Repair/Calibration: No<br>Leak Detection Equipment Installation Servicing: No<br>Spill Bucket Installation Repair: No<br>UST Equipment Installation - Other: No<br>UST Equipment Repair: No<br>UST System Installation - Complete Systems: No<br>UST Piping/Sump Installation: No<br>UST System Removal: No<br>Other: |
| Environmental Service Firms   |   |           |   |
| Emergency Cleanup - Spill/Release: No<br>Environmental Engineer/Geologist - Site Checks: No<br>Environmental Engineer/Geologist Soil and GW Cleanu: No<br>Oil and Solvent Recycling: No<br>Soil and Water Testing Lab: No   | UST Compliance Consultants: No<br>UST Equipment Verification: No<br>Waste Disposal and Treatment: No<br>Other:  |           |   |