Company		Listing Submitted	8/19/2024	Area of state conducts work	
A1 Environmental Services Inc		Phone (252) 531-1284		Coastal (East of I-95): Yes	
PO Box 59		Fax		Central (West of I-95 and East of I-77): No	
Greenville, NC 27835				Mountains (West of I-77): No	
	We	ebsite <u>www.aes-nc.com</u>		Wouldains (West of 1-77). No	
Comp	oliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Ei	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc.		Phone (336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax (336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438		(000) 202 0007			
	We	ebsite AdavancedEnvironmental.com		Mountains (West of I-77): Yes	
Comp	oliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		LIOT leteres liberes et les es d'este milite A es es es este le	NI.	UST Equipment Repair:	No
	No	UST Internal Inspections (Integrity Assessments):	No		
Leak Detection Equipment Operability Check:		UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST System Installation - Complete Systems:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No				No No
	No	UST Internal Lining Inspections:		UST System Installation - Complete Systems:	
Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmental	UST Internal Lining Inspections: Other:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmental Yes	UST Internal Lining Inspections: Other: Service Firms	No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No No nvironmental Yes Yes	UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmental Yes Yes Yes	UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No

Company		Listing Submitted	6/26/2024	Area of state conducts work	
BUCKEYE ELM CONTRACTING, LLC	F	Phone (336) 337-6001		Coastal (East of I-95): Yes	
PO Box 1026		Fax		Central (West of I-95 and East of I-77): Yes	
MOCKSVILLE, NC 27028				Mountains (West of I-77): Yes	
	We	bsite <u>www.buckeye-elm.com</u>		Modificants (West of 1-77). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Cape Fear Engineering, Inc.	F	Phone (910) 383-1044		Coastal (East of I-95): Yes	
151 Poole Road		Fax		Central (West of I-95 and East of I-77): No	
Suite 100				Mountains (West of I-77): No	
Leland, NC 28451	We	bsite www.capefearengineering.com		mountains (west of 177). No	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
				UST Piping/Sump Installation:	No
Leak Detection Monitoring Services:		Other:			
Leak Detection Monitoring Services: Line Tightness Testing:		Other:		UST System Removal:	No
Line Tightness Testing:	No No	Other: Service Firms			No
Line Tightness Testing:	No No nvironmental		Yes	UST System Removal:	No
Line Tightness Testing:	No No nvironmental	Service Firms	Yes No	UST System Removal:	No
Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No nvironmental No Yes	Service Firms UST Compliance Consultants:		UST System Removal:	No
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No nvironmental No Yes Yes	Service Firms UST Compliance Consultants: UST Equipment Verification:	No	UST System Removal:	No

Company		Listing Submitted	5/18/2022	Area of state conducts work	
Cape Fear Engineering, Inc.		Phone (910) 383-1044		Coastal (East of I-95): Yes	
151 Poole Road		Fax		Central (West of I-95 and East of I-77): No	
Suite 100		I ax			
Leland, NC 28451	We	ebsite <u>www.capefearengineering.com</u>		Mountains (West of I-77): No	
Comp	oliance Testin	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/5/2023	Area of state conducts work	
CATLIN Engineers and Scientists	ı	Phone (910) 452-5861		Coastal (East of I-95): Yes	
220 Old Dairy Road		Fax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28405				Mountains (West of I-77): No	
	We	ebsite www.CatlinUSA.com		Wouldains (West of 1-77). No	
Comp					
	oliance Testii	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
_	No	ng and Monitoring	No No		No No
Automatic Line Leak Detector Testing:	No No	ng and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No No No No No No No Vo nvironmental Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No Vo nvironmental Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

001 00	SI VICE F	Provider List (All) - Environment	ai Servici	e Films Only	
Company		Listing Submitted	4/5/2023	Area of state conducts work	
CDG, Inc.		Phone (704) 394-6913		Coastal (East of I-95): Yes	6
4301 Taggart Creek Road		Fax		Central (West of I-95 and East of I-77): Yes	3
Charlotte, NC 28208				Mountains (West of I-77): Yes	
	1	Website www.cdge.com		mountains (vost or 177). Too	,
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Eı	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company		Phone (336) 214-9012		Coastal (East of I-95): Yes	3
4716 Hilltop Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407				Mountains (West of I-77): Yes	
	1	Website <u>www.dhgriffin.com</u>		Mountains (West of 1-11). Too	,
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	tal Service Firms		Other:	
	V	LICT Compliance Consultants	No		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> No	UST Equipment Verification:	No		

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu No

Yes

Vacuum Truck Services

Waste Disposal and Treatment:

Other:

<u>Yes</u>

No

UST Service Provider List (A	II) - Environmental Service Firms Only
-------------------------------------	--

Company		Listing Submittee	d 4/5/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27603		T un		Mountains (West of I-77): No	
	1	Website <u>eastcoastenv.com</u>		Mountains (west of 1-77): No	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	d 1/6/2025	Area of state conducts work	
ECS Southeast, LLC		Phone (919) 861-9910		Coastal (East of I-95): Yes	
5260 Greens Dairy Road		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616		T un			
	1	Website ecslimited.com		Mountains (West of I-77): Yes	
Comp		TTEDOILE GOMENICO.COM			
		sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
-	oliance Tes	sting and Monitoring	No No		No No
Automatic Line Leak Detector Testing:	oliance Tes No	sting and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Ital Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company			Listing Submitted	7/2/2024	Area of state conducts work	
Environmental Hydrogeological Consultants, I	Inc. DB	Phone	(910) 843-4456		Coastal (East of I-95): Yes	
PO Box 902		Fax	(910) 843-5376		Central (West of I-95 and East of I-77): Yes	
Red Springs, NC 28377			(*,		Mountains (West of I-77): Yes	
	1	Nebsite	www.environmentalnc.com		mountains (West of 1-77). Tes	
Comp	pliance Tes	ting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Int	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Int	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Servic	ce Firms		Other: Liquid/Hydro Excavate Vac Truck S	Services
Emergency Cleanup - Spill/Release:	Yes		ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No		juipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu			Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:	OSRO Certified US Coast Guard Con			
Soil and Water Testing Lab:	Yes					
			Linting Culturitted	7/4.0/2024	Area of state conducts work	
Company			Listing Submitted	7/16/2024		
EnviroSouth, Inc.		Phone	(864) 236-9010		Coastal (East of I-95): No	
3440 Augusta Road Greenville, SC 29605		Fax			Central (West of I-95 and East of I-77): Yes	
Greenville, 3C 29003	,	Nebsite	www.envirosouth.com		Mountains (West of I-77): Yes	
Comp	pliance Tes		Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No		Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No		cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No		evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No		ghtness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:			ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
	No		, , , , , , , , , , , , , , , , , , , ,	110		
Leak Detection Equipment Operability Check:	No No	UST Int	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No No		, , , , , , , , , , , , , , , , , , , ,		UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
	No	UST Int	, , , , , , , , , , , , , , , , , , , ,		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	No No	UST Int Other:	ernal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Int Other:	ernal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmen	UST Int Other: tal Service UST Co	ernal Lining Inspections:	No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No No nvironment No Yes	UST Int Other: tal Service UST Co	ce Firms compliance Consultants:	No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmen No Yes	UST Int Other: tal Service UST Co	ce Firms compliance Consultants: quipment Verification:	No No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No

UST Se	ervice	e Provider List (All) - Environment	al Servic	e Firms Onlv	
Company		Listing Submitted	7/12/2023	Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800		Coastal (East of I-95): Yes	3
625 Huntsman Court		Fax (704) 853-3949		Central (West of I-95 and East of I-77): Yes	3
Gastonia, NC 28054		Website www.excelengr.com		Mountains (West of I-77): Yes	
Comp	oliance	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironr	mental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/3/2024	Area of state conducts work	
Groundwater Manage. Associates		Phone (252) 758-3310		Coastal (East of I-95): Yes	6
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	3
Suite 100 Greenville, NC 27834		Website www.gma-nc.com		Mountains (West of I-77): Yes	3
Comp	oliance	Testing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
		· .		· · · · · ·	

Soil and Water Testing Lab:

Leak Detection Monitoring Services:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

Line Tightness Testing:

No

No

No

<u>Yes</u>

No

No

Other:

Other:

UST Compliance Consultants:

Waste Disposal and Treatment:

UST Equipment Verification:

Environmental Service Firms

No

No

UST Piping/Sump Installation:

UST System Removal:

Other:

No

No

No

Company		Listing Submitted		Area of state conducts work	
Groundwater Management Associates, Inc.	Ph	one (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100				Mountains (West of I-77): Yes	
Greenville, NC 27834	Webs	site <u>www.gma-nc.com</u>		Wouldains (West of 1-77). Tes	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		rerfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Sp	ill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	nk Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Ot	her:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental S	ervice Firms	_	Other:	
Emergency Cleanup - Spill/Release:	No US	GT Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes US	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u> W	aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Ot	her:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
GTA Associates, In.c	Ph	one (704) 553-2300		Coastal (East of I-95): No	
701 Peninsula Lane, Suite B		Fax (704) 553-2400		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28226		• •		Mountains (West of I-77): No	
	Webs	site <u>www.gtaeng.com</u>		mountains (Wost of 177). He	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	rerfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No.				No
	No St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	
Corrosion Protection Design Experts:		atistical Iventory Reconciliation Services: ill Prevention Equipment Testing:	No No	Spill Bucket Installation Repair:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Sp No Ta	ill Prevention Equipment Testing: nk Tightness Testing:			No No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Sp No Ta	ill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Sp No Ta No US	ill Prevention Equipment Testing: nk Tightness Testing:	No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Sp No Ta No US No US	ill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessments):	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Sp No Ta No US No US	ill Prevention Equipment Testing: nk Tightness Testing: GT Internal Inspections (Integrity Assessments): GT Internal Lining Inspections:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Sp No Ta No US No Ot	ill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Sp No Ta No US No Ot No Ot	ill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Sp No Ta No US No US No Ot No Ot No Ot No Other Transport Section 1	ill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Sp No Ta No US No US No Ot No No Trivironmental S No US No US No US No US No US Yes US	ill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her: ervice Firms ST Compliance Consultants:	No No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Sp No Ta No US No Ot No Ot No vironmental S No US Yes US Yes W	ill Prevention Equipment Testing: nk Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: her: ervice Firms ST Compliance Consultants: ST Equipment Verification:	No No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No

UST Se	rvice F	Provider List (All) - Environment	tal Servic	e Firms Only	
Company		Listing Submitted		Area of state conducts work	
INENCO, Inc.		Phone (704) 662-8192		Coastal (East of I-95): Yes	
132 W. Statesville Avenue		Fax (704) 662-8194		Central (West of I-95 and East of I-77): Yes	
Mooresville, NC 27115		` '		Mountains (West of I-77): Yes	
	,	Website			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/15/2023	Area of state conducts work	
JF Petroleum Group		Phone (919) 744-4391		Coastal (East of I-95): Yes	
100 Perimeter Park Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Suite H				Mountains (West of I-77): Yes	
Morrisville, NC 27560	,	Website jfpetrogroup.com/services/environmental	<u>lcompliance</u>	mountaino (Prost of 177).	
		sting and Monitoring		UST Equipmment Service Contractors	
Comp	pliance Tes	sting and Monitoring			
Automatic Line Leak Detector Testing:	oliance Tes <u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	Yes
_			<u>Yes</u> No		Yes Yes
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	<u>Yes</u> <u>Yes</u>	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	<u>Yes</u> <u>Yes</u> No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes

Soil and Water Testing Lab:

No

No

Other:

Company		Listing Submitted		Area of state conducts work	
Jones Covey Group	P	hone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730		(000) 10 1 0000		Mountains (West of I-77): Yes	
	Wek	osite		woulder (west of 1-11). Tes	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	tatistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		pill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		ST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:		ST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental \$	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No V	Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No C	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
MGF Environmental, PLLC	P	hone (904) 814-3680		Coastal (East of I-95): No	
288 Gap Creek Rd		Fax		Central (West of I-95 and East of I-77): Yes	
Fletcher, NC 28732				Mountains (West of I-77): Yes	
	Web	osite mgfenvironmental.com		mountains (west of 177).	
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S			Leak Detection Equipment Installation Servicing:	No
	110	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment installation Servicing.	
Corrosion Protection Design Experts:		tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing:	No No	Spill Bucket Installation Repair:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S				No No
	No S No T	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No T No U	pill Prevention Equipment Testing: ank Tightness Testing:	No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S No T No U No U	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments):	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No T No U No U	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No C	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No C	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other:	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No T No U No O No O No O O O O O O O O O O O O O O O O O O O	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other: Service Firms	No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No S No T No U No C No No No C Invironmental S No U Yes U	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other: IST Compliance Consultants:	No No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S No T No U No C No No No C Vironmental S No U Yes U Yes W	pill Prevention Equipment Testing: ank Tightness Testing: IST Internal Inspections (Integrity Assessments): IST Internal Lining Inspections: Other: IST Compliance Consultants: IST Equipment Verification:	No No No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No

051 56	ervice	Provider List (All) - Environment	ai Service	e Firms Only	
Company		Listing Submitted	9/8/2022	Area of state conducts work	
Mid-Atlantic Associates, Inc.		Phone (919) 250-9918		Coastal (East of I-95): Yes	s
409 Rogers View Ct		Fax (919) 250-9950		Central (West of I-95 and East of I-77): Yes	S
Raleigh, NC 27610				Mountains (West of I-77): Yes	S
		Website www.maaonline.com		,	
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	i
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/2/2024	Area of state conducts work	
Paragon Environmental Consultants, Inc.		Phone (336) 669-6037		Coastal (East of I-95): No	
P.O. Box 157		Fax (336) 476-7708		Central (West of I-95 and East of I-77): Yes	s
Thomasville, NC 27361				Mountains (West of I-77): No	
		Website		· ,	
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	;
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Elife Tighthoss Tosting.					
	nvironmer	ntal Service Firms		Other:	
	nvironmer No	ntal Service Firms UST Compliance Consultants:	No	Other:	
Er			No No	Other:	

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

Waste Disposal and Treatment:

Other:

No

No

Company		Listing Sul	bmitted 11/1/2023	Area of state conducts work	
Peak Hydrogeologic, PLLC	Ph	one (828) 817-5209		Coastal (East of I-95):	No
470 Hogback Mtn Rd		Fax		Central (West of I-95 and East of I-77):	Yes
Tryon, NC 28782				Mountains (West of I-77):	
	Web	site https://peakhydrogeologic.com		mountains (west of 177).	103
Comp	liance Testing	and Monitoring		UST Equipmment Service Contract	ors
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Che	eck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Sp	oill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ink Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No US	ST Internal Inspections (Integrity Assessmer	nts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Ot	her:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental S	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes US	ST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	· · · · · · · · · · · · · · · · · · ·	ST Equipment Verification:	No No		
Environmental Engineer/Geologist Soil and GW Cleanu	· · · · · · · · · · · · · · · · · · ·	aste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:		her:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Sul	bmitted 3/31/2022	Area of state conducts work	
Petroleum Tec	Ph	one (980) 781-1000		Coastal (East of I-95):	Yes
5420 Powerhouse Ct		Fax		Central (West of I-95 and East of I-77):	
Concord, NC 28027				Mountains (West of I-77):	
	Web	site <u>www.petroleumtec.com</u>		meantaine (treet et t.t.).	
Comp	liance Testing	and Monitoring		UST Equipmment Service Contract	ors
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Che	eck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No St	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Sp	oill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ink Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No US	ST Internal Inspections (Integrity Assessmer	nts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Ot	her:	Tank Cleaning	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental S	ervice Firms		Other: T	ank Cleaning
Emergency Cleanup - Spill/Release:	Yes US	ST Compliance Consultants:	No		
	No US	ST Equipment Verification:	No		
Environmental Engineer/Geologist - Site Checks:					
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and Treatment:	<u>Yes</u>		
		aste Disposal and Treatment: her:	<u>Yes</u> Tank Cleaning		

UST Service Provider	List (All) - Envir	onmental	Service	Firms Only

Company		Listing Submitted	8/19/2024	Area of state conducts work	
Piedmont Geologic, P.C.		Phone (919) 954-9700		Coastal (East of I-95): Yes	
6003-145 Chapel Hill Road		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27607		I un		Mountains (West of I-77): Yes	
	W	ebsite <u>www.piedmontgeologic.com</u>		Mountains (West of 1-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Ei	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Pilot Geological , PLLC		Phone (336) 870-3095		Coastal (East of I-95): Yes	
PO Box 128		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
743 Park Lawn Court		(000) 010 1027			
Kernersville, NC 27285	W	ebsite <u>www.pilotenviro.com</u>		Mountains (West of I-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:				UST System Installation - Complete Systems:	No
Ecak Detection Equipment Operability Officer.	No	UST Internal Lining Inspections:	No	031 System installation - Complete Systems.	
Leak Detection Monitoring Services:	No No	UST Internal Lining Inspections: Other:	No	UST Piping/Sump Installation:	No
			No		No <u>Yes</u>
Leak Detection Monitoring Services: Line Tightness Testing:	No No		No	UST Piping/Sump Installation:	
Leak Detection Monitoring Services: Line Tightness Testing:	No No nvironmenta	Other:	No Yes	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	No No nvironmenta Yes	Other: I Service Firms		UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No nvironmenta Yes Yes	Other: I Service Firms UST Compliance Consultants:	Yes No	UST Piping/Sump Installation: UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No nvironmenta Yes Yes	Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	<u>Yes</u>	UST Piping/Sump Installation: UST System Removal:	

Company		· · · · · · · · · · · · · · · · · · ·	Listing Submitted	10/12/2022	Area of state conducts work	
Practical Environmental Solutions. PC		Phone (910) 790-8265			Coastal (East of I-95): Yes	
5634 Harvest Grove Ln		Fax			Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28409		Tux			Mountains (West of I-77): No	
	W	ebsite www.oil-tank.com	1		Mountains (West of 1-77). No	
Comp	oliance Testi	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipmer	nt Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconcilia	ation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment 7	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Int	egrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspection	ons:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmenta	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultant	s:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatme	ent:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	4/4/2023	Area of state conducts work	
Company Regional Environmental PLLC		Phone (704) 694-8359	Listing Submitted	4/4/2023	Area of state conducts work Coastal (East of I-95): Yes	
Regional Environmental PLLC 9016 Hazel Forest Drive		` ,	Listing Submitted	4/4/2023	Coastal (East of I-95): Yes	
Regional Environmental PLLC		Phone (704) 694-8359 Fax	Listing Submitted	4/4/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Regional Environmental PLLC 9016 Hazel Forest Drive		` ,	-	4/4/2023	Coastal (East of I-95): Yes	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526	W	Fax	-	4/4/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526	W	Fax bsite www.regionalenv	.com	4/4/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp	Wo	Fax bsite www.regionalenv ng and Monitoring	.com nt Operability Check:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Compa	Wo Dliance Testi No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmen	.com nt Operability Check: ation Services:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Webliance Testi No No No No	Fax besite www.regionalenv ng and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia	.com nt Operability Check: ation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Webliance Testi No No No No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment 1	nt Operability Check: ation Services: Festing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wo Dliance Testi No No No No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment T Tank Tightness Testing:	nt Operability Check: ation Services: Festing: egrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment Thank Tightness Testing: UST Internal Inspections (Internal Inspections)	nt Operability Check: ation Services: Festing: egrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (Intust UST Internal Lining Inspection)	nt Operability Check: ation Services: Festing: egrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (Intust UST Internal Lining Inspection)	nt Operability Check: ation Services: Festing: egrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipment Statistical Iventory Reconcilia Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (Int UST Internal Lining Inspection Other:	nt Operability Check: ation Services: Testing: egrity Assessments): ons:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Int UST Internal Lining Inspectio Other: Service Firms	nt Operability Check: ation Services: Testing: egrity Assessments): ons:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (Int UST Internal Lining Inspectio Other: Service Firms UST Compliance Consultant	nt Operability Check: ation Services: Festing: eegrity Assessments): ons:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Pebsite www.regionalenv Ing and Monitoring Overfill Prevention Equipmer Statistical Iventory Reconcilia Spill Prevention Equipment Tank Tightness Testing: UST Internal Inspections (Int UST Internal Lining Inspectio Other: Service Firms UST Compliance Consultant UST Equipment Verification:	nt Operability Check: ation Services: Festing: eegrity Assessments): ons:	No No No No No Ves No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Service P	rovid	ler List (All) - Environ	menta	al Service	e Firms Only	
		Listing Su	bmitted	7/30/2024	Area of state conducts work	
	Phone	(910) 763-6274			Coastal (East of I-95): Yes	
	Fax	(910) 763-6132			Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28401						
V	Vebsite	www.srrenviro.com			mountains (West of 177). 103	
mpliance Tes	ting and	l Monitoring			UST Equipmment Service Contractors	
No	Overfill	Prevention Equipment Operability Che	eck:	No	Dispenser Meter Repair/Calibration:	No
No	Statistic	cal Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:	No
No	Spill Pr	evention Equipment Testing:		No	Spill Bucket Installation Repair:	No
No	Tank T	ightness Testing:		No	UST Equipment Installation - Other:	No
No			nts):	No	UST Equipment Repair:	No
No	UST In	ternal Lining Inspections:		No	UST System Installation - Complete Systems:	No
No	Other:					No
No						<u>Yes</u>
Environment	al Servi	ce Firms			Other:	
<u>Yes</u>	UST Co	ompliance Consultants:		No		
No	UST E	quipment Verification:		No		
anu No	Waste	Disposal and Treatment:		<u>Yes</u>		
<u>Yes</u>	Other:		Fuel Po	lishing		
No						
		Listing Su	bmitted	8/15/2024	Area of state conducts work	
	Phone	(336) 854-8135			Coastal (East of I-95): Yes	
	Fax				Central (West of I-95 and East of I-77): Yes	
V	Vebsite	https://www.terracon.com/			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						
No	Overfill	Prevention Equipment Operability Che	eck:	No	Dispenser Meter Repair/Calibration:	No
No	Statistic	cal Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:	No
No	Spill Pr	revention Equipment Testing:		No	Spill Bucket Installation Repair:	No
No				No	UST Equipment Installation - Other:	No
No			nts):	No	UST Equipment Repair:	No
NI-	LIST In	ternal Lining Inspections:		No	UST System Installation - Complete Systems:	No
No	001 111	torria: Emmig mopostioner		-		
No No	Other:	tornar <u>-</u> mmig mopositorio			UST Piping/Sump Installation: UST System Removal:	No
	mpliance Test No	Phone Fax Website Impliance Testing and No Overfill No Statistic No Spill Pr No Tank T No UST In No Other: No Environmental Servit Yes UST Co No UST En	Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com Impliance Testing and Monitoring No Overfill Prevention Equipment Operability Chemical None Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessmen None UST Internal Lining Inspections: No Other: No UST Compliance Consultants: No UST Equipment Verification: Waste Disposal and Treatment: Yes Other: No Uster: No Uster: No Uster: No Uster of the None (336) 854-8135 Fax Website https://www.terracon.com/ Impliance Testing and Monitoring No Overfill Prevention Equipment Operability Chemical No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing:	Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com Impliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: No Environmental Service Firms Yes UST Compliance Consultants: No UST Equipment Verification: anu No Waste Disposal and Treatment: Yes Other: Fuel Po No Listing Submitted Phone (336) 854-8135 Fax Website https://www.terracon.com/ Impliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing:	Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com Impliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No No UST Internal Inspections (Integrity Assessments): No No UST Internal Lining Inspections: No No Other: No Environmental Service Firms Yes UST Compliance Consultants: No No UST Equipment Verification: No anu No Waste Disposal and Treatment: Yes No Listing Submitted 8/15/2024 Phone (336) 854-8135 Fax Website https://www.terracon.com/ Impliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No	Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com Website www.srrenviro.com Mountains (West of I-95): Yes Mountains (West of I-77): Yes M

Soil and Water Testing Lab:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

No

<u>Yes</u>

Other:

<u>Yes</u>

Yes

No

No

UST Compliance Consultants:

Waste Disposal and Treatment:

UST Equipment Verification:

Company		Listing Submit	tted 3/6/2024	Area of state conducts work	
Titan Environmental Group	P	Phone (984) 200-6825		Coastal (East of I-95): Yes	
2005 Citation Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529				Mountains (West of I-77): Yes	
	We	ebsite <u>www.titanenvirogroup.com</u>		mountains (West of 177). 103	
Comp	UST Equipmment Service Contractors				
Automatic Line Leak Detector Testing:	No (Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	No l	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	No l	UST Internal Lining Inspections:	UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	No (Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No l	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No \	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submit	tted 8/27/2024	Area of state conducts work	
UES Professional Solutions 29, Inc.	P	Phone (704) 504-1717		Coastal (East of I-95): Yes	
10121 Pineville Distribution Street		Fax (704) 504-1125		Central (West of I-95 and East of I-77): Yes	
Pineville, NC 28134			Mountains (West of I-77): Yes		
	We	ebsite <u>www.teamues.com</u>		,	
Comp	pliance Testin	and a second Billian at the action of			
Automatic Line Leak Detector Testing:		ng and Monitoring		UST Equipmment Service Contractors	
	No (Overfill Prevention Equipment Operability Check:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Corrosion Protection Design Experts:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:		Dispenser Meter Repair/Calibration:	
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No S No S No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No S No S No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No S No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No S No S No No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No S No S No No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S No S No No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No S	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

UST Service Provider List (All) - Environmental Service Firms Only

Company		Listing Submitted	11/1/2023	Area of state conducts work	
Withers Ravenel, Inc.	Pho	one (919) 469-3340		Coastal (East of I-95): Yes	3
115 MacKenan Drive	1	Fax Tax		Central (West of I-95 and East of I-77): Yes	3
Cary, NC 27591	Webs	ite <u>www.withersravenel.com</u>		Mountains (West of I-77): Yes	3
Comp	UST Equipmment Service Contractors				
Automatic Line Leak Detector Testing:	No Ov	erfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Sta	tistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spi	Il Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tai	Tank Tightness Testing: No		UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No US	UST Internal Inspections (Integrity Assessments):		UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No US	T Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Oth	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	vironmental Se	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes US	T Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes US	T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes Wa	ste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Oth	er:			
Soil and Water Testing Lab:	No				