

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 8/19/2024 | Area of state conducts work |
|---|---|-----------|--|
| A1 Environmental Services Inc PO Box 59 Greenville, NC 27835 | Phone (252) 531-1284 Fax Website www.aes-nc.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| Company | Listing Submitted | 1/18/2024 | Area of state conducts work |
| Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 | Phone (336) 282-3586 Fax (336) 282-3587 Website AdadvancedEnvironmental.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: <u>Yes</u> Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <u>Yes</u> Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 6/26/2024 | Area of state conducts work |
|---|---|---------------------|--|
| BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028 | Phone (336) 337-6001 Fax Website www.buckeye-elm.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <u>Yes</u> UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <u>Yes</u> Other: | | |
| Company | Listing Submitted | 1/10/2022 | Area of state conducts work |
| Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 | Phone (828) 277-0100 Fax (828) 277-0110 Website www.blecorp.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: <u>Yes</u> Containment Sump Testing: <u>Yes</u> Corrosion Protection Design Experts: <u>Yes</u> Corrosion Protection System Repairs: <u>Yes</u> Corrosion Protection System Testing: <u>Yes</u> Leak Detection Equipment Operability Check: <u>Yes</u> Leak Detection Monitoring Services: <u>Yes</u> Line Tightness Testing: <u>Yes</u> | Overfill Prevention Equipment Operability Check: <u>Yes</u> Statistical Inventory Reconciliation Services: <u>Yes</u> Spill Prevention Equipment Testing: <u>Yes</u> Tank Tightness Testing: <u>Yes</u> UST Internal Inspections (Integrity Assessments): <u>Yes</u> UST Internal Lining Inspections: <u>Yes</u> Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: <u>Yes</u> Waste Disposal and Treatment: <u>Yes</u> Other: | Trust Fund Projects | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 5/18/2022 | Area of state conducts work |
|---|---|-----------|---|
| Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 | Phone (910) 383-1044 Fax Website www.capefearengineering.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: | | |

| Company | Listing Submitted | 5/18/2022 | Area of state conducts work |
|---|---|-----------|---|
| Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 | Phone (910) 383-1044 Fax Website www.capefearengineering.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 4/5/2023 | Area of state conducts work |
|---|---|----------|---|
| CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 | Phone (910) 452-5861 Fax Website www.CatlinUSA.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 | Phone (704) 394-6913 Fax Website www.cdge.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: Yes Soil and Water Testing Lab: Yes | UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 1/20/2022 | Area of state conducts work |
|---|-------------------|---|---|
| COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: |
| Line Tightness Testing: | No | | UST System Removal: |
| | | | Yes |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | Yes |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | QED MOBILE LAB TPH - SOIL |
| Soil and Water Testing Lab: | Yes | | |
| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
| Crompco, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462 Phone (610) 278-7203 Fax (610) 278-7621 Website www.crompco.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | Yes | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: |
| Containment Sump Testing: | Yes | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: |
| Corrosion Protection System Testing: | Yes | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: |
| Leak Detection Equipment Operability Check: | Yes | UST Internal Lining Inspections: | UST System Installation - Complete Systems: |
| Leak Detection Monitoring Services: | Yes | Other: | UST Piping/Sump Installation: |
| Line Tightness Testing: | Yes | | UST System Removal: |
| | | | Yes |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | Yes |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | Yes |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 9/28/2022 | Area of state conducts work |
|---|---|-----------|--|
| D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 | Phone (336) 214-9012 Fax Website www.dhgriffin.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <u>Yes</u> Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <u>Yes</u> Other: Vacuum Truck Services | | |

| Company | Listing Submitted | 4/5/2023 | Area of state conducts work |
|---|---|----------|---|
| East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 | Phone (919) 349-5969 Fax Website eastcoastenv.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <u>Yes</u> Spill Bucket Installation Repair: <u>Yes</u> UST Equipment Installation - Other: <u>Yes</u> UST Equipment Repair: <u>Yes</u> UST System Installation - Complete Systems: No UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: <u>Yes</u> Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 7/2/2024 | Area of state conducts work |
|---|---|--|---|
| Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377 Phone (910) 843-4456 Fax (910) 843-5376 Website www.environmentalinc.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: Liquid/Hydro Excavate Vac Truck Services | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: Yes Soil and Water Testing Lab: Yes | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: OSRO Certified US Coast Guard Contractor | | |
| Company | Listing Submitted | 7/16/2024 | Area of state conducts work |
| EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605 Phone (864) 236-9010 Fax Website www.envirosouth.com | | | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 1/4/2022 | Area of state conducts work |
|--|--|---|---|
| EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 | Phone (336) 763-6025 Fax Website envirotrac.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: No |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: No |
| Line Tightness Testing: | No | | UST System Removal: Yes |
| Environmental Service Firms | | | Other: |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | Yes |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | Yes | | |
| Company | Listing Submitted | 1/3/2022 | Area of state conducts work |
| Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 | Phone (336) 725-5844 Fax Website www.evocorp.net | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: No |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: No |
| Line Tightness Testing: | No | | UST System Removal: Yes |
| Environmental Service Firms | | | Other: Vacuum Truck Services |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | Yes |
| Oil and Solvent Recycling: | Yes | Other: Transportation Services | |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 7/12/2023 | Area of state conducts work |
|---|-------------------|---|---|
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | Yes |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |
| Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Phone (303) 770-8884 Fax (303) 770-3636 Website www.Gallowayus.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | Yes | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | UST/AST System Design |
| Line Tightness Testing: | No | | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | Yes |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | UST/AST System Design |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
|---|---|------------|--|
| Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 | Phone (704) 837-7174 Fax Website www.geohydro.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| Company | Listing Submitted | 1/3/2022 | Area of state conducts work |
| Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 | Phone (704) 845-4010 Fax (704) 845-4012 Website grienv.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 7/3/2024 | Area of state conducts work |
|---|---|----------|---|
| Groundwater Manage. Associates 4300 Sapphire Court Suite 100 Greenville, NC 27834 | Phone (252) 758-3310 Fax Website www.gma-nc.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

| Company | Listing Submitted | 11/16/2023 | Area of state conducts work |
|---|---|------------|---|
| Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 | Phone (252) 758-3310 Fax Website www.gma-nc.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | | Area of state conducts work |
|---|---|------------|---|
| GTA Associates, Inc. 701 Peninsula Lane, Suite B Charlotte, NC 28226 | Phone (704) 553-2300 Fax (704) 553-2400 Website www.gtaeng.com | 4/20/2023 | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| Company | Listing Submitted | | Area of state conducts work |
| Highlands Environmental Solutions, Inc. 8410-d Falls of Neuse Raleigh, NC 27615 | Phone (919) 848-3155 Fax Website www.HESfast.com | 12/30/2021 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 4/11/2023 | Area of state conducts work |
|--|--|-----------|---|
| INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115 | Phone (704) 662-8192 Fax (704) 662-8194 Website | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| Company | Listing Submitted | 5/15/2023 | Area of state conducts work |
| JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560 | Phone (919) 744-4391 Fax Website jfpetrogroup.com/services/environmentalcompliance | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: <u>Yes</u> Containment Sump Testing: <u>Yes</u> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <u>Yes</u> Leak Detection Monitoring Services: <u>Yes</u> Line Tightness Testing: <u>Yes</u> | Overfill Prevention Equipment Operability Check: <u>Yes</u> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <u>Yes</u> Tank Tightness Testing: <u>Yes</u> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: <u>Yes</u> Leak Detection Equipment Installation Servicing: <u>Yes</u> Spill Bucket Installation Repair: <u>Yes</u> UST Equipment Installation - Other: <u>Yes</u> UST Equipment Repair: <u>Yes</u> UST System Installation - Complete Systems: <u>Yes</u> UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: <u>Yes</u> Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 1/5/2022 | Area of state conducts work |
|---|---|------------|---|
| Johnson, Spellman & Associates, Inc. 350 Research Ct. Suite 130 Peachtree Corners, GA 30092 | Phone (770) 447-4555 Fax Website | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: Engineering- Design Services | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: Engineering-Design Services |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other: Engineering-Design Services | | |
| Company | Listing Submitted | 12/20/2022 | Area of state conducts work |
| Jones Covey Group 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730 | Phone (888) 972-7581 Fax (909) 484-0300 Website | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes | Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 1/31/2022 | Area of state conducts work |
|---|---|-----------------------------|---|
| McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 | Phone (757) 420-9252 Fax (757) 424-2874 Website www.mccallumtestinglabs.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732 | Phone (904) 814-3680 Fax Website mgfenvironmental.com | Listing Submitted 4/20/2023 | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 9/8/2022 | Area of state conducts work |
|--|-------------------|---|---|
| Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610 Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: |
| Line Tightness Testing: | No | | UST System Removal: |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | <u>Yes</u> |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |
| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
| NCCPM 7300 glenwood ave. raleigh, NC 27612 Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: |
| Line Tightness Testing: | No | | UST System Removal: |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | Engineering on UST Installations |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 7/2/2024 | Area of state conducts work |
|---|--|-----------|--|
| Paragon Environmental Consultants, Inc. P.O. Box 157 Thomasville, NC 27361 Phone (336) 669-6037 Fax (336) 476-7708 Website | | | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No | Overfill Prevention Equipment Operability Check: No | | Dispenser Meter Repair/Calibration: No |
| Containment Sump Testing: No | Statistical Inventory Reconciliation Services: No | | Leak Detection Equipment Installation Servicing: No |
| Corrosion Protection Design Experts: No | Spill Prevention Equipment Testing: No | | Spill Bucket Installation Repair: No |
| Corrosion Protection System Repairs: No | Tank Tightness Testing: No | | UST Equipment Installation - Other: No |
| Corrosion Protection System Testing: No | UST Internal Inspections (Integrity Assessments): No | | UST Equipment Repair: No |
| Leak Detection Equipment Operability Check: No | UST Internal Lining Inspections: No | | UST System Installation - Complete Systems: No |
| Leak Detection Monitoring Services: No | Other: | | UST Piping/Sump Installation: No |
| Line Tightness Testing: No | | | UST System Removal: No |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No | UST Compliance Consultants: No | | |
| Environmental Engineer/Geologist - Site Checks: <u>Yes</u> | UST Equipment Verification: No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> | Waste Disposal and Treatment: No | | |
| Oil and Solvent Recycling: No | Other: | | |
| Soil and Water Testing Lab: No | | | |
| Company | Listing Submitted | 11/1/2023 | Area of state conducts work |
| Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782 Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com | | | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No | Overfill Prevention Equipment Operability Check: No | | Dispenser Meter Repair/Calibration: No |
| Containment Sump Testing: No | Statistical Inventory Reconciliation Services: No | | Leak Detection Equipment Installation Servicing: No |
| Corrosion Protection Design Experts: No | Spill Prevention Equipment Testing: No | | Spill Bucket Installation Repair: No |
| Corrosion Protection System Repairs: No | Tank Tightness Testing: No | | UST Equipment Installation - Other: No |
| Corrosion Protection System Testing: No | UST Internal Inspections (Integrity Assessments): No | | UST Equipment Repair: No |
| Leak Detection Equipment Operability Check: No | UST Internal Lining Inspections: No | | UST System Installation - Complete Systems: No |
| Leak Detection Monitoring Services: No | Other: | | UST Piping/Sump Installation: No |
| Line Tightness Testing: No | | | UST System Removal: <u>Yes</u> |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: <u>Yes</u> | UST Compliance Consultants: <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: <u>Yes</u> | UST Equipment Verification: No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> | Waste Disposal and Treatment: <u>Yes</u> | | |
| Oil and Solvent Recycling: No | Other: | | |
| Soil and Water Testing Lab: <u>Yes</u> | | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
|---|---|------------|---|
| Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 | Phone (704) 335-8801 Fax (704) 342-1672 Website www.petrolemequipment.net | | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes | Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other: | | Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: | | |
| Company | Listing Submitted | 3/31/2022 | Area of state conducts work |
| Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 | Phone (980) 781-1000 Fax Website www.petroleumtec.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: Tank Cleaning | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: Tank Cleaning |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: Tank Cleaning | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | | Area of state conducts work |
|--|--------------------------|---|---|
| Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607 Phone (919) 954-9700 Fax Website www.piedmontgeologic.com | 8/19/2024 | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | <u>Yes</u> |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |
| Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285 Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com | 11/1/2023 | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | <u>Yes</u> |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | <u>Yes</u> |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 10/12/2022 | Area of state conducts work |
|---|---|------------|---|
| Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409 | Phone (910) 790-8265 Fax Website www.oil-tank.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
| Precision Tank Service 737 Zimmer Road Fort Mill , SC 29707 | Phone (704) 892-8600 Fax (704) 892-8711 Website www.precisiontankservice.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes | Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: Yes UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 1/3/2022 | Area of state conducts work | | |
|--|-------------------|---|---|--|------------|
| Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Phone (336) 335-3174 Fax (336) 691-0648 Website www.PyramidEnvironmental.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | | |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors | | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | Yes |
| | | | | Other: | |
| Environmental Service Firms | | | | | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | Yes | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | Yes | | | | |
| Company | Listing Submitted | 4/4/2023 | Area of state conducts work | | |
| Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Phone (704) 694-8359 Fax Website www.regionalenv.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No | | |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors | | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| | | | | Other: | |
| Environmental Service Firms | | | | | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | Yes | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | Yes | | | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
|---|---|------------|---|
| Sensible Solutions Environmental, P. C. P. O. Box 3074 Chapel Hill, NC 27515 | Phone (336) 263-0965 Fax Website www.sensible-solutions-environmental.com | | Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: Residential USTs | | |
| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
| Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732 | Phone (828) 508-4510 Fax Website singletonenvironmental.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 7/30/2024 | Area of state conducts work |
|---|-------------------|---|---|
| SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401 Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | Yes |
| Oil and Solvent Recycling: | Yes | Other: | Fuel Polishing |
| Soil and Water Testing Lab: | No | | |

| Company | Listing Submitted | 8/15/2024 | Area of state conducts work |
|--|-------------------|---|---|
| Terracon 7327- G West Friendly Avenue Greensboro, NC 27410 Phone (336) 854-8135 Fax Website https://www.terracon.com/ | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No |
| Leak Detection Monitoring Services: | No | Other: | |
| Line Tightness Testing: | No | | |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | Yes |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 12/30/2021 | Area of state conducts work |
|--|-------------------|---|---|
| Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: |
| Containment Sump Testing: | <u>Yes</u> | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: |
| Line Tightness Testing: | No | | UST System Removal: |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | <u>Yes</u> |
| Oil and Solvent Recycling: | No | Other: | |
| Soil and Water Testing Lab: | <u>Yes</u> | | |

| Company | Listing Submitted | 3/6/2024 | Area of state conducts work |
|---|-------------------|---|---|
| Titan Environmental Group 2005 Citation Drive Garner, NC 27529 Phone (984) 200-6825 Fax Website www.titanenvirogroup.com | | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Dispenser Meter Repair/Calibration: |
| Containment Sump Testing: | No | Statistical Inventory Reconciliation Services: | Leak Detection Equipment Installation Servicing: |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Spill Bucket Installation Repair: |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | UST Equipment Installation - Other: |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | UST Equipment Repair: |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | UST System Installation - Complete Systems: |
| Leak Detection Monitoring Services: | No | Other: | UST Piping/Sump Installation: |
| Line Tightness Testing: | No | | UST System Removal: |
| | | | Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | <u>Yes</u> |
| Oil and Solvent Recycling: | <u>Yes</u> | Other: | |
| Soil and Water Testing Lab: | No | | |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | Listing Submitted | 8/27/2024 | Area of state conducts work |
|---|---|-----------|---|
| UES Professional Solutions 29, Inc. 10121 Pineville Distribution Street Pineville, NC 28134 | Phone (704) 504-1717 Fax (704) 504-1125 Website www.teamues.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |
| Company | Listing Submitted | 11/1/2023 | Area of state conducts work |
| Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 | Phone (919) 469-3340 Fax Website www.withersravenel.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring | | | UST Equipment Service Contractors |
| Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No | Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: | | Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other: |
| Environmental Service Firms | | | |
| Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No | UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other: | | |