UST Service Provider List (All) - Leak Detection Testing Companies O	<b>UST Service Pro</b>	vider List (All) -	Leak Detection	Testing Co	ompanies On
--	------------------------	--------------------	----------------	------------	-------------

Company		Listing Submitted	6/27/2024	Area of state conducts work	
Cobb Environmental & Technical Services, Inc. Phone (662) 841-0995				Coastal (East of I-95): Yes	
P. O. Box 1602		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
Tupelo, MS 38802				Mountains (West of I-77): Yes	
		Website cobbenv.com		would west of 1-77). Tes	
Comp	oliance T	esting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironme	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/14/2024	Area of state conducts work	
Environmental Petroleum Services		Phone (877) 297-6763		Coastal (East of I-95): No	
1234 Gordon Park Rd		Fax	Central (West of I-95 and East of I-77): Yes		
Augusta, GA 30901					
		Website <u>www.keepmecompliant.net</u>		Mountains (West of I-77): Yes	
Сотр	oliance T	Website www.keepmecompliant.net  Testing and Monitoring		UST Equipmment Service Contractors	
Comp  Automatic Line Leak Detector Testing:	oliance T <u>Yes</u>		<u>Yes</u>		Yes
		esting and Monitoring	<u>Yes</u> No	UST Equipmment Service Contractors	Yes Yes
Automatic Line Leak Detector Testing:	Yes	Cesting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes Yes Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes Yes Yes Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes Yes Yes Yes No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes Yes Yes Yes Yes Yes No Yes No Yes No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Cental Service Firms UST Compliance Consultants:	No Yes Yes No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes Yes Yes Yes Yes No Yes No Yes No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  Cental Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes No No No	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

UST Service Provider List (All) - Leak Detection	on Testing Companies Only
--	---------------------------

Company		or Liot (7 til)	Listing Submitted	5/15/2023	Area of state conducts work	
JF Petroleum Group	Ph	one (919) 744-43	91		Coastal (East of I-95): Yes	
100 Perimeter Park Drive		Fax			Central (West of I-95 and East of I-77): Yes	
Suite H					Mountains (West of I-77): Yes	
Morrisville, NC 27560	Website jfpetrogroup.com/services/environmentalcompliance			Mountains (west of 1-77): Yes		
Comp	oliance Testing	and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	Yes O	verfill Prevention Equi	pment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes S	atistical Iventory Reco	onciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		oill Prevention Equipm		<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		ank Tightness Testing		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			s (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u> U	ST Internal Lining Insp	pections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes O	ther:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironmental S	ervice Firms			Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consu	ultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verifica	ation:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and Tre	eatment:	No		
Oil and Solvent Recycling:	No O	ther:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group	Ph	one (888) 972-75	81		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-03	600		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730		(000) 10 1 00			Mountains (West of I-77): Yes	
	Web	site			Mountains (West of 1-77). 163	
Comp	oliance Testing	and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	Yes O	verfill Prevention Equi	pment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes S	atistical Iventory Reco	onciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u> S	oill Prevention Equipm	ent Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	Yes Ta	ank Tightness Testing	:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u> U	ST Internal Inspection	s (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u> U	ST Internal Lining Insp	pections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes O	ther:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental S	ervice Firms			Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consu	ultants:	<u>Yes</u>		
1		ST Equipment Verifica		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	or Equipment veniles				
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu		aste Disposal and Tre		No		
	No W					

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING	Pho	ne (813) 671-9065		Coastal (East of I-95): Yes	3
451 APOLLO BEACH BOULEVARD	F	ax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	6
APOLLO BEACH, FL 33572	Website WWW.VALLEYTANK.COM		Mountains (West of I-77): Yes		
Comp	liance Testing a	nd Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u> Ove	fill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Stat	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tanl	Tank Tightness Testing:		UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes Othe	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	vironmental Se	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No UST	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Was	te Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Othe	er:			
Soil and Water Testing Lab:	No				