UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		Listing Submitted		Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.	Pł	one (252) 237-6047		Coastal (East of I-95): Yes	
PO Box 502		Fax (252) 237-5507		Central (West of I-95 and East of I-77): Yes	
711 S. Goldsboro St.		(===) ==: ===:		Mountains (West of I-77): No	
Wilson, NC 27893	Web	site <u>www.peswilson.com</u>		Wouldains (West of 1-77). No	
Comp	liance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes S	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	oill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No O	her:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmental S	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		aste Disposal and Treatment:	No		
Oil and Solvent Recycling:		her:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Bay Compliance and Testing LLC	Pł	one (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	Web	site https://baycomplianceandtesting.com/		Modificants (West of 1-17). No	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes O	verfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes S	atistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	oill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u> U	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u> U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	NI-	her:		UST Piping/Sump Installation:	No
Edak Detection Worldening Corvices.	No O				NI.
Line Tightness Testing:	No U			UST System Removal:	No
Line Tightness Testing:				UST System Removal: Other:	INO
Line Tightness Testing:	Yes nvironmental S		No		INO
Line Tightness Testing:	Yes nvironmental S	ervice Firms	No No		NO
Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes No U No U	ervice Firms ST Compliance Consultants:			NO
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes No U No U No W	ervice Firms ST Compliance Consultants: ST Equipment Verification:	No		NO

Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704		Phone (828) 277-0100 Fax (828) 277-0110 Website www.blecorp.com		Coastal (East of I-95): Ye		
Arden, NC 28704		· ,		Central (West of I-95 and East of I-77): Ye		
		Website www.blecom.com		Central (West of I-95 and East of I-77): Yes		
		WWW.DIGOOIP.COIII	Mountains (West of I-77): Yes			
Com	pliance To	esting and Monitoring		UST Equipmment Service Contractors	5	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No	
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No	
E	nvironme	ental Service Firms		Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>			
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>			
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>			
Oil and Solvent Recycling:	No	Other: Trust F	und Projects			
Soil and Water Testing Lab:	No					

Crompco, LLC	ı	Phone (610) 278-7203		Coastal (East of I-95): Ye	s
1815 Gallagher Road		Fax (610) 278-7621		Central (West of I-95 and East of I-77): Ye	s
Figinodin Weeting, FA 19402	We	ebsite www.crompco.com		Mountains (West of I-77): Ye	s
Comp	liance Testi	ng and Monitoring		UST Equipmment Service Contractors	•
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Fax (610) 278-7621 Website www.crompco.com UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation Servicing: Spill Bucket Installation Pepair: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: UST System Removal: Other: Westornmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Vestornmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No	No				
En	vironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service	ce Pro	vider List (All) - Leak Detectic	on Testing C	Companies Only	
Company		Listing Submit		Area of state conducts work	
C-Store Services, Inc.		Phone (919) 662-0798		Coastal (East of I-95): Yes	
7129 Hidden Valley Trail		Fax (919) 662-0711		Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529		Website		Mountains (West of I-77): No	
Comr		sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	<u>res</u> No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: UST-27 monthl		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No		.,	UST System Removal:	Yes
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submit	tted 5/14/2024	Area of state conducts work	
Environmental Petroleum Services		Phone (877) 297-6763		Coastal (East of I-95): No	
1234 Gordon Park Rd		Fax		Central (West of I-95 and East of I-77): Yes	
Augusta, GA 30901				Mountains (West of I-77): Yes	
		Website www.keepmecompliant.net			
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Orange de la Directa ette a Orante de Tractica de	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>				
	<u>Yes</u> No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Equipment Operability Check:				UST System Removal:	<u>Yes</u> <u>Yes</u>
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No <u>Yes</u>				
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No <u>Yes</u>	Other:	No	UST System Removal:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No <u>Yes</u> nvironmen	Other: htal Service Firms	No No	UST System Removal:	
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No <u>Yes</u> nvironmen No No	Other: Intal Service Firms UST Compliance Consultants:		UST System Removal:	

Oil and Solvent Recycling:

Soil and Water Testing Lab:

No

No

Other:

UST Service Provider List (All) - Leak Detection Testing Companies

Company		Listing Submitte	ed 10/26/2021	Area of state conducts work	
Guardian Fueling Technologies	F	Phone (919) 729-6980		Coastal (East of I-95): Yes	
5116 Departure Drive		Fax (919) 769-2919		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616		(010) 700 2010			
	We	bsite <u>www.guardianfueltech.com</u>		Mountains (West of I-77): No	
Comp	oliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other: SafeGuard UST Inspection	n Services	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	No
Ei	nvironmental	Service Firms		Other: FuelGuard fuel polishing / tank	cleaning
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitte	ed 5/15/2023	Area of state conducts work	
JF Petroleum Group	F	Phone (919) 744-4391		Coastal (East of I-95): Yes	
-		(010) / 11 1001			
100 Perimeter Park Drive				Central (West of I-95 and East of I-77): Yes	
Suite H		Fax		Central (West of I-95 and East of I-77): Yes	
	We		talcompliance	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Suite H Morrisville, NC 27560		Fax	talcompliance		
Suite H Morrisville, NC 27560	oliance Testir	Fax bsite jfpetrogroup.com/services/environmen	talcompliance Yes	Mountains (West of I-77): Yes	
Suite H Morrisville, NC 27560 Comp	oliance Testir <u>Yes</u>	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring		Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing:	oliance Testir Yes Yes	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	<u>Yes</u>
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes Yes No	Fax bbsite ifpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Diance Testin Yes Yes No No	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	<u>Yes</u> No <u>Yes</u>	Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No No	Fax bsite jfpetrogroup.com/services/environmen ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No No Yes	Fax Absite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No No No Yes	Fax besite ifpetrogroup.com/services/environment and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes	Fax besite ifpetrogroup.com/services/environment and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes Yes Yes	Fax besite ifpetrogroup.com/services/environment ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	Yes No Yes Yes No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes Yes Yes Yes You	Fax Absite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Yes Yes No No No Yes Yes Yes Yes Yes You	Fax bisite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	Yes No Yes Yes No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
Suite H Morrisville, NC 27560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes No No No Yes Yes Yes Yes Yes No	Fax bisite ifpetrogroup.com/services/environmen Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No Yes	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		Li	isting Submitted	1/5/2022	Area of state conducts work	
Johnson, Spellman & Associates, Inc.		Phone (770) 447-4555			Coastal (East of I-95): Yes	;
350 Research Ct.		Fax			Central (West of I-95 and East of I-77): Yes	
Suite 130		·				
Peachtree Corners, GA 30092	V	Vebsite			Mountains (West of I-77): Yes	i
Comp	liance Tes	ting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation S	ervices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	r.	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Er	ngineering- Design Sei	rvices	UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironment	al Service Firms			Other: Engineering-Design	Services
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other: E	ngineering-Design Sei	rvices		
Soil and Water Testing Lab:	No					
Company		Li	isting Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581			Coastal (East of I-95): Yes	;
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300			Central (West of I-95 and East of I-77): Yes	;
Rancho Cucamonga, CA 91730		• •			Mountains (West of I-77): Yes	
	V	Vebsite			mountaine (reset et 111).	
Сотр	liance Tes	ting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation S	ervices:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing	:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity /	Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
LE : (0 1 10 10 10 10 10 10	NI-	Waste Disposal and Treatment:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	NO	waste Disposal and Treatment.				
Oil and Solvent Recycling:	No No	Other:				

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company			Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment and Service, Inc.	F	Phone	(704) 335-8801		Coastal (East of I-95): No	
4125 Sinclair Street		Fax			Central (West of I-95 and East of I-77): Yes	
PO Box 1949		· ux	(101,012 1012		Mountains (West of I-77): Yes	
Denver, NC 28037	We	ebsite	www.petroleumequipment.net		Mountains (West of 1-77): Yes	
Comp	oliance Testin	ng and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:			evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			ternal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Int	ternal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironmental	Service	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste [Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service	F	Phone	(704) 892-8600		Coastal (East of I-95): Yes	
737 Zimmer Road		Fax	(704) 892-8711		Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707			(Mountains (West of I-77): Yes	
	We	ebsite	www.precisiontankservice.com		woultains (west of 1-77). Tes	
Comp	oliance Testir	ng and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Int	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Int	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental	Service	ce Firms		Other:	
t e e e e e e e e e e e e e e e e e e e	NIa	UST Co	ompliance Consultants:	<u>Yes</u>		
Emergency Cleanup - Spill/Release:	No					
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:			quipment Verification:	No		
	No	UST Eq	quipment Verification: Disposal and Treatment:	No No		
Environmental Engineer/Geologist - Site Checks:	No No	UST Eq				

UST S	ervice Pro	ovider List (All) - Leak Detection	Testing (Companies Only	
Company		Listing Submitte			
Superior Services		Phone (828) 698-6286		Coastal (East of I-95): Ye	es
PO Box 982 Hendersonville, NC		Fax (828) 698-6294		Central (West of I-95 and East of I-77): Ye	es
Tionacionimo, rec		Website www.superiorservices.com		Mountains (West of I-77): Ye	es
	Compliance Te	esting and Monitoring		UST Equipmment Service Contractors	S
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No

Yes

Yes

No

UST Equipment Repair:

UST System Removal:

Other:

UST Piping/Sump Installation:

UST System Installation - Complete Systems:

3 3 3					
Environmental Engineer/Geologist - Site Checks:	No UST Equipment Verification: No				
Environmental Engineer/Geologist Soil and GW Cleanu	No No	Waste Disposal and Treatment:			
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091		Coastal (East of I-95): Yes	
100 E. Ruffin Street Mebane, NC 27302		Fax (919) 563-9095	Central (West of I-95 and East of I-77): Yes		
INEDANE, NO 27302		Website www.terraquestpc.com		Mountains (West of I-77): Yes	S
Comp	UST Equipmment Service Contractors				
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironm	nental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		

UST Internal Inspections (Integrity Assessments):

Other: Repair and lining, AST Inspections, Repairs and Lining

UST Internal Lining Inspections:

UST Compliance Consultants:

Oil and Solvent Recycling:

Soil and Water Testing Lab:

Corrosion Protection System Testing:

Leak Detection Monitoring Services:

Emergency Cleanup - Spill/Release:

Line Tightness Testing:

Leak Detection Equipment Operability Check:

Yes

Yes

No

Yes

No

Environmental Service Firms

Other:

No

Yes

No

No

No

No

UST Service Provider List (All) - Leak Detection Testing Companies Only

Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING	Pho	ne (813) 671-9065		Coastal (East of I-95): Yes	3
451 APOLLO BEACH BOULEVARD	F	ax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	3
APOLLO BEACH, FL 33572	Websi	te <u>WWW.VALLEYTANK.COM</u>		Mountains (West of I-77): Yes	;
Comp	UST Equipmment Service Contractors				
Automatic Line Leak Detector Testing:	<u>Yes</u> Ove	fill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes Stat	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tan	Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes Othe	er:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	vironmental Se	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No UST	Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Was	te Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Othe	er:			
Soil and Water Testing Lab:	No				