

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Petroleum Equipment Service of Wilson, Inc. PO Box 502 711 S. Goldsboro St. Wilson, NC 27893	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	8/19/2024	Area of state conducts work
A1 Environmental Services Inc PO Box 59 Greenville, NC 27835	Phone (252) 531-1284 Fax Website www.aes-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/18/2024	Area of state conducts work
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Phone (336) 282-3586 Fax (336) 282-3587 Website AdadvancedEnvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	7/19/2022	Area of state conducts work
B & M WEST CONSTRUCTION CO OF TEXAS DBA D. 209 E BADCOCK BLVD MULBERRY, FL 33860 Phone (863) 519-4441 Fax (863) 519-4407 Website DWSHOUPE.COM			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Bay Compliance and Testing LLC P.O. Box 16628 Chesapeake, VA 23328	Phone (757) 410-5974 Fax Website https://baycomplianceandtesting.com/		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	Yes		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	6/26/2024	Area of state conducts work
BUCKEYE ELM CONTRACTING, LLC PO Box 1026 MOCKSVILLE, NC 27028	Phone (336) 337-6001 Fax Website www.buckeye-elm.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	4/5/2023	Area of state conducts work
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405	Phone (910) 452-5861 Fax Website www.CatlinUSA.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	6/27/2024	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602 Tupelo, MS 38802	Phone (662) 841-0995 Fax (662) 841-0810 Website cobbenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/20/2022	Area of state conducts work
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: Yes	UST Compliance Consultants: Yes UST Equipment Verification: No Waste Disposal and Treatment: No Other: QED MOBILE LAB TPH - SOIL		
Company	Listing Submitted	12/30/2021	Area of state conducts work
Crompco, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462	Phone (610) 278-7203 Fax (610) 278-7621 Website www.crompco.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	9/24/2021	Area of state conducts work
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Phone (919) 662-0798 Fax (919) 662-0711 Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	UST-27 monthly inspection
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: No UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Company	Listing Submitted	9/28/2022	Area of state conducts work
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Phone (336) 214-9012 Fax Website www.dhgriffin.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	Vacuum Truck Services
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	4/5/2023	Area of state conducts work
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Phone (919) 349-5969 Fax Website eastcoastenv.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No	Overfill Prevention Equipment Operability Check: No	Dispenser Meter Repair/Calibration: No	Leak Detection Equipment Installation Servicing: Yes
Containment Sump Testing: No	Statistical Inventory Reconciliation Services: No	Leak Detection Equipment Installation Servicing: Yes	Spill Bucket Installation Repair: Yes
Corrosion Protection Design Experts: No	Spill Prevention Equipment Testing: No	UST Equipment Installation - Other: Yes	UST Equipment Repair: Yes
Corrosion Protection System Repairs: No	Tank Tightness Testing: No	UST System Installation - Complete Systems: No	UST Piping/Sump Installation: Yes
Corrosion Protection System Testing: No	UST Internal Inspections (Integrity Assessments): No	UST System Removal: Yes	Other: Yes
Leak Detection Equipment Operability Check: No	UST Internal Lining Inspections: No		
Leak Detection Monitoring Services: No	Other: No		
Line Tightness Testing: No			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes	UST Compliance Consultants: Yes		
Environmental Engineer/Geologist - Site Checks: Yes	UST Equipment Verification: Yes		
Environmental Engineer/Geologist Soil and GW Cleanu: Yes	Waste Disposal and Treatment: No		
Oil and Solvent Recycling: No	Other: No		
Soil and Water Testing Lab: No			
Company	Listing Submitted	7/2/2024	Area of state conducts work
Environmental Hydrogeological Consultants, Inc. DB PO Box 902 Red Springs, NC 28377 Phone (910) 843-4456 Fax (910) 843-5376 Website www.environmentalinc.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No	Overfill Prevention Equipment Operability Check: No	Dispenser Meter Repair/Calibration: No	Leak Detection Equipment Installation Servicing: No
Containment Sump Testing: No	Statistical Inventory Reconciliation Services: No	Leak Detection Equipment Installation Servicing: No	Spill Bucket Installation Repair: No
Corrosion Protection Design Experts: No	Spill Prevention Equipment Testing: No	UST Equipment Installation - Other: No	UST Equipment Repair: No
Corrosion Protection System Repairs: No	Tank Tightness Testing: No	UST System Installation - Complete Systems: No	UST Piping/Sump Installation: No
Corrosion Protection System Testing: No	UST Internal Inspections (Integrity Assessments): No	UST System Removal: Yes	Other: Liquid/Hydro Excavate Vac Truck Services
Leak Detection Equipment Operability Check: No	UST Internal Lining Inspections: No		
Leak Detection Monitoring Services: No	Other: No		
Line Tightness Testing: No			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: Yes	UST Compliance Consultants: No		
Environmental Engineer/Geologist - Site Checks: No	UST Equipment Verification: No		
Environmental Engineer/Geologist Soil and GW Cleanu: No	Waste Disposal and Treatment: Yes		
Oil and Solvent Recycling: Yes	Other: OSRO Certified US Coast Guard Contractor		
Soil and Water Testing Lab: Yes			

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	5/14/2024	Area of state conducts work
Environmental Petroleum Services 1234 Gordon Park Rd Augusta, GA 30901 Phone (877) 297-6763 Fax Website www.keepmecompliant.net			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: No Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	7/16/2024	Area of state conducts work
EnviroSouth, Inc. 3440 Augusta Road Greenville, SC 29605 Phone (864) 236-9010 Fax Website www.envirosouth.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: Yes Environmental Engineer/Geologist Soil and GW Cleanu: Yes Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/4/2022	Area of state conducts work
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410	Phone (336) 763-6025 Fax Website envirotrac.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: Yes
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	Yes		
Company	Listing Submitted	1/3/2022	Area of state conducts work
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107	Phone (336) 725-5844 Fax Website www.evocorp.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: Yes
			Other: Vacuum Truck Services
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	Transportation Services
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208	Phone (704) 837-7174 Fax Website www.geohydro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	1/3/2022	Area of state conducts work
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112	Phone (704) 845-4010 Fax (704) 845-4012 Website grienv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	11/16/2023	Area of state conducts work
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834	Phone (252) 758-3310 Fax Website www.gma-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: Yes
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	10/26/2021	Area of state conducts work
Guardian Fueling Technologies 5116 Departure Drive Raleigh, NC 27616	Phone (919) 729-6980 Fax (919) 769-2919 Website www.guardianfueltech.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	Yes	Other: SafeGuard UST Inspection Services	UST System Installation - Complete Systems: Yes
Line Tightness Testing:	No		UST Piping/Sump Installation: Yes
			UST System Removal: No
			Other: FuelGuard fuel polishing / tank cleaning
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/25/2022	Area of state conducts work
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Phone (770) 917-8846 Fax (770) 917-0921 Website www.harcoservices.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: Yes
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: Yes
Line Tightness Testing:	No		UST System Removal: Yes
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	4/11/2023	Area of state conducts work
INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115 Phone (704) 662-8192 Fax (704) 662-8194 Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: Yes
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	5/15/2023	Area of state conducts work
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560	Phone (919) 744-4391 Fax Website jfpetrogroup.com/services/environmentalcompliance		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: Yes Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: Yes Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	12/20/2022	Area of state conducts work
Jones Covey Group 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730	Phone (888) 972-7581 Fax (909) 484-0300 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: Yes Containment Sump Testing: Yes Corrosion Protection Design Experts: Yes Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Leak Detection Equipment Operability Check: Yes Leak Detection Monitoring Services: Yes Line Tightness Testing: Yes	Overfill Prevention Equipment Operability Check: Yes Statistical Inventory Reconciliation Services: Yes Spill Prevention Equipment Testing: Yes Tank Tightness Testing: Yes UST Internal Inspections (Integrity Assessments): Yes UST Internal Lining Inspections: Yes Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: Yes Spill Bucket Installation Repair: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other:		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	5/30/2024	Area of state conducts work
Marley Trucking & Demolition Inc. 1768 Old Humble Mill Road Asheboro, NC 27205 Phone (336) 382-7132 Fax Website			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	5/30/2024	Area of state conducts work
MERRITT COMMERCIAL SERVICES LLC 217 STRICKLAND RD WHIGHAM, GA 39897 Phone (228) 516-0498 Fax Website https://www.mcs-petroleum-div.com/			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	4/20/2023	Area of state conducts work
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732	Phone (904) 814-3680 Fax Website mgfenvironmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	11/1/2023	Area of state conducts work
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782	Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	12/30/2021	Area of state conducts work
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037	Phone (704) 335-8801 Fax (704) 342-1672 Website www.petroleumequipment.net		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	8/19/2024	Area of state conducts work
Piedmont Geologic, P.C. 6003-145 Chapel Hill Road Raleigh, NC 27607	Phone (919) 954-9700 Fax Website www.piedmontgeologic.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285	Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: <u>Yes</u> Other:		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	10/12/2022	Area of state conducts work
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409	Phone (910) 790-8265 Fax Website www.oil-tank.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	12/30/2021	Area of state conducts work
Precision Tank Service 737 Zimmer Road Fort Mill , SC 29707	Phone (704) 892-8600 Fax (704) 892-8711 Website www.precisiontankservice.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/3/2022	Area of state conducts work
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Phone (336) 335-3174 Fax (336) 691-0648 Website www.PyramidEnvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			Yes
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	Yes		
Company	Listing Submitted	7/30/2024	Area of state conducts work
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401 Phone (910) 763-6274 Fax (910) 763-6132 Website www.srrenviro.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			Yes
			Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes
Oil and Solvent Recycling:	Yes	Other:	Fuel Polishing
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	3/6/2024	Area of state conducts work
Titan Environmental Group 2005 Citation Drive Garner, NC 27529	Phone (984) 200-6825 Fax Website www.titanenvirogroup.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>
Oil and Solvent Recycling:	<u>Yes</u>	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	1/31/2023	Area of state conducts work
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968	Phone (205) 577-1035 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted			Area of state conducts work
VITAL FUEL SYSTEMS INC. 1076 CLASSIC ROAD APEX, NC 27540	10/5/2021	Phone (919) 303-7374 Fax (919) 303-7399 Website WWW.VITALFUELSYSTEMS.COM		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No		Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <u>Yes</u> Spill Bucket Installation Repair: <u>Yes</u> UST Equipment Installation - Other: <u>Yes</u> UST Equipment Repair: <u>Yes</u> UST System Installation - Complete Systems: <u>Yes</u> UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No		UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted			Area of state conducts work
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	11/1/2023	Phone (919) 469-3340 Fax Website www.withersravenel.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No		Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No		UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		