

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Petroleum Equipment Service of Wilson, Inc.</b> PO Box 502 711 S. Goldsboro St. Wilson, NC 27893	<b>Phone</b> (252) 237-6047 <b>Fax</b> (252) 237-5507 <b>Website</b> <a href="http://www.peswilson.com">www.peswilson.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	1/18/2024	Area of state conducts work
<b>Advanced Environmental Services, Inc.</b> PO Box 38218 Greensboro, NC 27438	<b>Phone</b> (336) 282-3586 <b>Fax</b> (336) 282-3587 <b>Website</b> <a href="http://AdadvancedEnvironmental.com">AdadvancedEnvironmental.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	7/19/2022	Area of state conducts work
<b>B &amp; M WEST CONSTRUCTION CO OF TEXAS DBA D.</b> 209 E BADCOCK BLVD MULBERRY, FL 33860  <b>Phone</b> (863) 519-4441 <b>Fax</b> (863) 519-4407  <b>Website</b> <a href="http://DWSHOUPE.COM">DWSHOUPE.COM</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Bay Compliance and Testing LLC</b> P.O. Box 16628 Chesapeake, VA 23328  <b>Phone</b> (757) 410-5974 <b>Fax</b>  <b>Website</b> <a href="https://baycomplianceandtesting.com/">https://baycomplianceandtesting.com/</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	6/26/2024	Area of state conducts work
<b>BUCKEYE ELM CONTRACTING, LLC</b> PO Box 1026 MOCKSVILLE, NC 27028	<b>Phone</b> (336) 337-6001  <b>Fax</b>  <b>Website</b> <a href="http://www.buckeye-elm.com">www.buckeye-elm.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <b><u>Yes</u></b> UST Piping/Sump Installation: <b><u>Yes</u></b> UST System Removal: <b><u>Yes</u></b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b><u>Yes</u></b> Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b><u>Yes</u></b> Other:		
Company	Listing Submitted	4/5/2023	Area of state conducts work
<b>CATLIN Engineers and Scientists</b> 220 Old Dairy Road Wilmington, NC 28405	<b>Phone</b> (910) 452-5861  <b>Fax</b>  <b>Website</b> <a href="http://www.CatlinUSA.com">www.CatlinUSA.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b><u>Yes</u></b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b><u>Yes</u></b> Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b><u>Yes</u></b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/20/2022	Area of state conducts work
<b>COHESION, INC</b> 5216 YATES MILL POND RD RALEIGH, NC 27606  <b>Phone</b> (919) 233-8626 <b>Fax</b> <b>Website</b> <a href="http://WWW.COHESION-INC.COM">WWW.COHESION-INC.COM</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	QED MOBILE LAB TPH - SOIL
Soil and Water Testing Lab:	<u>Yes</u>		
Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Crompco, LLC</b> 1815 Gallagher Road Plymouth Meeting, PA 19462  <b>Phone</b> (610) 278-7203 <b>Fax</b> (610) 278-7621 <b>Website</b> <a href="http://www.crompco.com">www.crompco.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	
Line Tightness Testing:	<u>Yes</u>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	9/24/2021	Area of state conducts work
<b>C-Store Services, Inc.</b> 7129 Hidden Valley Trail Garner, NC 27529  <b>Phone</b> (919) 662-0798 <b>Fax</b> (919) 662-0711  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	UST-27 monthly inspection
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: No UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Company	Listing Submitted	9/28/2022	Area of state conducts work
<b>D. H. Griffin Wrecking Company</b> 4716 Hilltop Road Greensboro, NC 27407  <b>Phone</b> (336) 214-9012 <b>Fax</b>  <b>Website</b> <a href="http://www.dhgriffin.com">www.dhgriffin.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	Vacuum Truck Services
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	4/6/2023	Area of state conducts work
<b>East Coast Environmental, PA</b> 3815 Junction Boulevard Raleigh , NC 27603	<b>Phone</b> (919) 349-5969  <b>Fax</b>  <b>Website</b> <a href="http://eastcoastenv.com">eastcoastenv.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <u>Yes</u> UST Equipment Installation - Other: <u>Yes</u> UST Equipment Repair: <u>Yes</u> UST System Installation - Complete Systems: No UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: <u>Yes</u> Waste Disposal and Treatment: No Other:		

Company	Listing Submitted	4/5/2023	Area of state conducts work
<b>East Coast Environmental, PA</b> 3815 Junction Boulevard Raleigh, NC 27603	<b>Phone</b> (919) 349-5969  <b>Fax</b>  <b>Website</b> <a href="http://eastcoastenv.com">eastcoastenv.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <u>Yes</u> Spill Bucket Installation Repair: <u>Yes</u> UST Equipment Installation - Other: <u>Yes</u> UST Equipment Repair: <u>Yes</u> UST System Installation - Complete Systems: No UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: <u>Yes</u> Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	5/14/2024	Area of state conducts work
<b>Environmental Petroleum Services</b> 1234 Gordon Park Rd Augusta, GA 30901	<b>Phone</b> (877) 297-6763  <b>Fax</b>  <b>Website</b> <a href="http://www.keepmecompliant.net">www.keepmecompliant.net</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	1/4/2022	Area of state conducts work
<b>EnviroTrac Ltd.</b> 7343 West Friendly Avenue Suite J Greensboro, NC 27410	<b>Phone</b> (336) 763-6025  <b>Fax</b>  <b>Website</b> <a href="http://envirotrac.com">envirotrac.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<b>Yes</b>		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/3/2022	Area of state conducts work
<b>Evo Corporation</b> 1703 Vargrave Street Winston-Salem, NC 27107	<b>Phone</b> (336) 725-5844  <b>Fax</b>  <b>Website</b> <a href="http://www.evocorp.net">www.evocorp.net</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: <b>Yes</b>
Environmental Service Firms			Other: Vacuum Truck Services
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	Transportation Services
Soil and Water Testing Lab:	No		
Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Geo-Hydro Engineers, Inc.</b> 2748 Interstate Street Suite A Charlotte, NC 28208	<b>Phone</b> (704) 837-7174  <b>Fax</b>  <b>Website</b> <a href="http://www.geohydro.com">www.geohydro.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration: No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing: No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair: No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other: No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair: No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems: No
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation: No
Line Tightness Testing:	No		UST System Removal: <b>Yes</b>
Environmental Service Firms			Other:
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		



## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/3/2022	Area of state conducts work
<b>Geological Resources, Inc.</b> 3502 Hayes Road Monroe, NC 28112  <b>Phone</b> (704) 845-4010 <b>Fax</b> (704) 845-4012  <b>Website</b> <a href="http://grienv.com">grienv.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b><u>Yes</u></b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b><u>Yes</u></b> Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/16/2023	Area of state conducts work
<b>Groundwater Management Associates, Inc.</b> 4300 Sapphire Court Suite 100 Greenville, NC 27834  <b>Phone</b> (252) 758-3310 <b>Fax</b>  <b>Website</b> <a href="http://www.gma-nc.com">www.gma-nc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b><u>Yes</u></b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	10/26/2021	Area of state conducts work
<b>Guardian Fueling Technologies</b> 5116 Departure Drive Raleigh, NC 27616  <b>Phone</b> (919) 729-6980 <b>Fax</b> (919) 769-2919  <b>Website</b> <a href="http://www.guardianfueltech.com">www.guardianfueltech.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other: SafeGuard UST Inspection Services	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: No Other: FuelGuard fuel polishing / tank cleaning
Company	Listing Submitted	1/25/2022	Area of state conducts work
<b>HARCO Services LLC</b> PO Box 2347 Kennesaw, GA 30156  <b>Phone</b> (770) 917-8846 <b>Fax</b> (770) 917-0921  <b>Website</b> <a href="http://www.harcoservices.com">www.harcoservices.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	4/11/2023	Area of state conducts work
<b>INENCO, Inc.</b> 132 W. Statesville Avenue Mooresville, NC 27115	<b>Phone</b> (704) 662-8192 <b>Fax</b> (704) 662-8194  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b><u>Yes</u></b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b><u>Yes</u></b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	5/15/2023	Area of state conducts work
<b>JF Petroleum Group</b> 100 Perimeter Park Drive Suite H Morrisville, NC 27560	<b>Phone</b> (919) 744-4391 <b>Fax</b>  <b>Website</b> <a href="http://jfpetrogroup.com/services/environmentalcompliance">jfpetrogroup.com/services/environmentalcompliance</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b><u>Yes</u></b> Containment Sump Testing: <b><u>Yes</u></b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b><u>Yes</u></b> Leak Detection Monitoring Services: <b><u>Yes</u></b> Line Tightness Testing: <b><u>Yes</u></b>	Overfill Prevention Equipment Operability Check: <b><u>Yes</u></b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b><u>Yes</u></b> Tank Tightness Testing: <b><u>Yes</u></b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b><u>Yes</u></b> Leak Detection Equipment Installation Servicing: <b><u>Yes</u></b> Spill Bucket Installation Repair: <b><u>Yes</u></b> UST Equipment Installation - Other: <b><u>Yes</u></b> UST Equipment Repair: <b><u>Yes</u></b> UST System Installation - Complete Systems: <b><u>Yes</u></b> UST Piping/Sump Installation: <b><u>Yes</u></b> UST System Removal: <b><u>Yes</u></b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b><u>Yes</u></b> UST Equipment Verification: <b><u>Yes</u></b> Waste Disposal and Treatment: No Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/20/2022	Area of state conducts work
<b>Jones Covey Group</b> 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730  <b>Phone</b> (888) 972-7581 <b>Fax</b> (909) 484-0300  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	<b>Yes</b>
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: No Other:
Company	Listing Submitted	5/30/2024	Area of state conducts work
<b>Marley Trucking &amp; Demolition Inc.</b> 1768 Old Humble Mill Road Asheboro, NC 27205  <b>Phone</b> (336) 382-7132 <b>Fax</b>  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	5/30/2024	Area of state conducts work		
<b>MERRITT COMMERCIAL SERVICES LLC</b> 217 STRICKLAND RD WHIGHAM, GA 39897	<b>Phone</b> (228) 516-0498  <b>Fax</b>  <b>Website</b> <a href="https://www.mcs-petroleum-div.com/">https://www.mcs-petroleum-div.com/</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted	4/20/2023	Area of state conducts work		
<b>MGF Environmental, PLLC</b> 288 Gap Creek Rd Fletcher, NC 28732	<b>Phone</b> (904) 814-3680  <b>Fax</b>  <b>Website</b> <a href="http://mgfenvironmental.com">mgfenvironmental.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes		
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	2/28/2022	Area of state conducts work
<b>Parliament Petroleum Services LLC</b> 3277 Neely Ferry Rd Laurens, SC 29360	<b>Phone</b> (864) 871-8058  <b>Fax</b>  <b>Website</b> <a href="http://Parliamentpetroleumservices.com">Parliamentpetroleumservices.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <u>Yes</u> Leak Detection Equipment Installation Servicing: <u>Yes</u> Spill Bucket Installation Repair: <u>Yes</u> UST Equipment Installation - Other: <u>Yes</u> UST Equipment Repair: <u>Yes</u> UST System Installation - Complete Systems: <u>Yes</u> UST Piping/Sump Installation: <u>Yes</u> UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
<b>Peak Hydrogeologic, PLLC</b> 470 Hogback Mtn Rd Tryon, NC 28782	<b>Phone</b> (828) 817-5209  <b>Fax</b>  <b>Website</b> <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <u>Yes</u> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <u>Yes</u> Environmental Engineer/Geologist - Site Checks: <u>Yes</u> Environmental Engineer/Geologist Soil and GW Cleanu: <u>Yes</u> Oil and Solvent Recycling: No Soil and Water Testing Lab: <u>Yes</u>	UST Compliance Consultants: <u>Yes</u> UST Equipment Verification: No Waste Disposal and Treatment: <u>Yes</u> Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Petroleum Equipment and Service, Inc.</b> 4125 Sinclair Street PO Box 1949 Denver, NC 28037	<b>Phone</b> (704) 335-8801 <b>Fax</b> (704) 342-1672 <b>Website</b> <a href="http://www.petroleumequipment.net">www.petroleumequipment.net</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	11/1/2023	Area of state conducts work
<b>Pilot Geological , PLLC</b> PO Box 128 743 Park Lawn Court Kernersville, NC 27285	<b>Phone</b> (336) 870-3095 <b>Fax</b> (336) 310-4527 <b>Website</b> <a href="http://www.pilotenviro.com">www.pilotenviro.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	4/20/2023	Area of state conducts work
<b>Practical Environmental Solutions</b> 5634 Harvest Grove Lane Wilmington, NC 28049  <b>Phone</b> (910) 790-8265 <b>Fax</b> <b>Website</b> <a href="http://www.oil-tank.com">www.oil-tank.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No	Overfill Prevention Equipment Operability Check: No	Dispenser Meter Repair/Calibration: No	Leak Detection Equipment Installation Servicing: No
Containment Sump Testing: No	Statistical Inventory Reconciliation Services: No	Spill Bucket Installation Repair: No	UST Equipment Installation - Other: No
Corrosion Protection Design Experts: No	Spill Prevention Equipment Testing: No	UST Equipment Repair: No	UST System Installation - Complete Systems: No
Corrosion Protection System Repairs: No	Tank Tightness Testing: No	UST Piping/Sump Installation: No	UST System Removal: <b>Yes</b>
Corrosion Protection System Testing: No	UST Internal Inspections (Integrity Assessments): No	Other: UST Abandonment In-place, State Compliance	
Leak Detection Equipment Operability Check: No	UST Internal Lining Inspections: No		
Leak Detection Monitoring Services: No	Other:		
Line Tightness Testing: No			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No	UST Compliance Consultants: No		
Environmental Engineer/Geologist - Site Checks: <b>Yes</b>	UST Equipment Verification: No		
Environmental Engineer/Geologist Soil and GW Cleanu <b>Yes</b>	Waste Disposal and Treatment: No		
Oil and Solvent Recycling: No	Other:		
Soil and Water Testing Lab: <b>Yes</b>			
Company	Listing Submitted	10/12/2022	Area of state conducts work
<b>Practical Environmental Solutions. PC</b> 5634 Harvest Grove Ln Wilmington, NC 28409  <b>Phone</b> (910) 790-8265 <b>Fax</b> <b>Website</b> <a href="http://www.oil-tank.com">www.oil-tank.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No	Overfill Prevention Equipment Operability Check: No	Dispenser Meter Repair/Calibration: No	Leak Detection Equipment Installation Servicing: No
Containment Sump Testing: No	Statistical Inventory Reconciliation Services: No	Spill Bucket Installation Repair: No	UST Equipment Installation - Other: No
Corrosion Protection Design Experts: No	Spill Prevention Equipment Testing: No	UST Equipment Repair: No	UST System Installation - Complete Systems: No
Corrosion Protection System Repairs: No	Tank Tightness Testing: No	UST Piping/Sump Installation: No	UST System Removal: <b>Yes</b>
Corrosion Protection System Testing: No	UST Internal Inspections (Integrity Assessments): No	Other: UST Abandonment In-place, State Compliance	
Leak Detection Equipment Operability Check: No	UST Internal Lining Inspections: No		
Leak Detection Monitoring Services: No	Other:		
Line Tightness Testing: No			
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No	UST Compliance Consultants: No		
Environmental Engineer/Geologist - Site Checks: <b>Yes</b>	UST Equipment Verification: No		
Environmental Engineer/Geologist Soil and GW Cleanu <b>Yes</b>	Waste Disposal and Treatment: No		
Oil and Solvent Recycling: No	Other:		
Soil and Water Testing Lab: <b>Yes</b>			



## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	12/30/2021	Area of state conducts work
<b>Precision Tank Service</b> 737 Zimmer Road Fort Mill , SC 29707  <b>Phone</b> (704) 892-8600 <b>Fax</b> (704) 892-8711  <b>Website</b> <a href="http://www.precisiontankservice.com">www.precisiontankservice.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
Company	Listing Submitted	1/3/2022	Area of state conducts work
<b>Pyramid Environmental &amp; Engineering, PC</b> 503 Industrial Avenue Greensboro, NC 27406  <b>Phone</b> (336) 335-3174 <b>Fax</b> (336) 691-0648  <b>Website</b> <a href="http://www.PyramidEnvironmental.com">www.PyramidEnvironmental.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<b>Yes</b>		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	6/29/2021	Area of state conducts work
<b>SR&amp;R Environmental, Inc.</b> 4920 Highway 421 N. Wilmington, NC 28401-	<b>Phone</b> (910) 763-6274 <b>Fax</b> (910) 763-6132 <b>Website</b> <a href="http://www.srrenviro.com">www.srrenviro.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	Vacuum Truck Services
Soil and Water Testing Lab:	No		
Company	Listing Submitted	3/6/2024	Area of state conducts work
<b>Titan Environmental Group</b> 2005 Citation Drive Garner, NC 27529	<b>Phone</b> (984) 200-6825 <b>Fax</b> <b>Website</b> <a href="http://www.titanenvirogroup.com">www.titanenvirogroup.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted	1/31/2023	Area of state conducts work
<b>Valor Construction LLC</b> PO Box 680654 Fort Payne, AL 35968  <b>Phone</b> (205) 577-1035 <b>Fax</b> <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <b><u>Yes</u></b> UST Piping/Sump Installation: <b><u>Yes</u></b> UST System Removal: <b><u>Yes</u></b> Other:
Company	Listing Submitted	10/5/2021	Area of state conducts work
<b>VITAL FUEL SYSTEMS INC.</b> 1076 CLASSIC ROAD APEX, NC 27540  <b>Phone</b> (919) 303-7374 <b>Fax</b> (919) 303-7399 <b>Website</b> <a href="http://WWW.VITALFUELSYSTEMS.COM">WWW.VITALFUELSYSTEMS.COM</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
Environmental Service Firms			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b><u>Yes</u></b> Spill Bucket Installation Repair: <b><u>Yes</u></b> UST Equipment Installation - Other: <b><u>Yes</u></b> UST Equipment Repair: <b><u>Yes</u></b> UST System Installation - Complete Systems: <b><u>Yes</u></b> UST Piping/Sump Installation: <b><u>Yes</u></b> UST System Removal: <b><u>Yes</u></b> Other:

## UST Service Provider List (All) - UST Equipment Service Contractors Only

Company	Listing Submitted			Area of state conducts work
<b>Withers Ravenel, Inc.</b> 115 MacKenan Drive Cary, NC 27591	<b>Phone</b> (919) 469-3340  <b>Fax</b>  <b>Website</b> <a href="http://www.withersravenel.com">www.withersravenel.com</a>	11/1/2023	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b><u>Yes</u></b> Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b><u>Yes</u></b> Environmental Engineer/Geologist - Site Checks: <b><u>Yes</u></b> Environmental Engineer/Geologist Soil and GW Cleanu: <b><u>Yes</u></b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b><u>Yes</u></b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			