<u>Yes</u>
<u>Yes</u>
No
<u>Yes</u>

		UST Service Provider List (All)		
Company		Listing Submitted	5/17/2021	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889				Mountains (West of I-77): Yes	
	\	Website www.aes-nc.com			
Com	pliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/15/2021	Area of state conducts work	
		Listing Submitted Phone (919) 777-8543	4/15/2021	Area of state conducts work Coastal (East of I-95): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1		Phone (919) 777-8543	4/15/2021	Coastal (East of I-95): Yes	
Company American UST Compliance Testing			4/15/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1	\	Phone (919) 777-8543	4/15/2021	Coastal (East of I-95): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510		Phone (919) 777-8543 Fax	4/15/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510		Phone (919) 777-8543 Fax Website	4/15/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510	pliance Tes	Phone (919) 777-8543 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Com Automatic Line Leak Detector Testing:	pliance Tes <u>Yes</u>	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes Yes Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Tes Yes Yes No	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u>
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No Yes No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No <u>Yes</u> No <u>Yes</u>
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes Yes No Yes Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes Yes No Yes Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Yes Yes No No Yes Yes No No No No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes No No No No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No

		UST Service Provider List ((All)		
Company		Listing Submitted	` /	Area of state conducts work	
Apex Engineering, PC		Phone (301) 417-0200		Coastal (East of I-95): Yes	
15850 Crabbs Branch Way		Fax (301) 975-0169		Central (West of I-95 and East of I-77): Yes	
Suite 200		()		Mountains (West of I-77): Yes	
Rockville, Maryland 20855-	W	ebsite <u>www.apexcos.com</u>		meaname (west every). Tes	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	Yes				
Company		Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS I	DBA D.	Listing Submitted Phone (863) 519-4441	7/19/2022		
B & M WEST CONSTRUCTION CO OF TEXAS I	DBA D.	Phone (863) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
	DBA D.		7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD		Phone (863) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	W	Phone (863) 519-4441 Fax (863) 519-4407	7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	W	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM	7/19/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	W pliance Testi	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing:	W pliance Testi No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Testi No No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi No No No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Wipliance Testi No No No No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Windows Testi No No No No No No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Windows Testi No No No No No No No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No No No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windows Policy P	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windows Policy P	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Windows Policy P	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Wipliance Testi No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Wipliance Testi No	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (863) 519-4441 Fax (863) 519-4407 ebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes

		UST Service Provider List (All)		
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Bay Compliance and Testing LLC	Р	hone (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	We	bsite https://baycomplianceandtesting.com/			
Comp	oliance Testin	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes S	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	JST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	JST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No l	JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No l	JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/10/2022	Area of state conducts work	
	P	<u> </u>	1/10/2022		
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road	Р	hone (828) 277-0100	1/10/2022	Coastal (East of I-95): Yes	
Bunnell-Lammons Engineering, Inc.	Р	<u> </u>	1/10/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Bunnell-Lammons Engineering, Inc. 130 Oval Road		hone (828) 277-0100	1/10/2022	Coastal (East of I-95): Yes	
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	We	hone (828) 277-0100 Fax (828) 277-0110	1/10/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	We	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com	1/10/2022 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	Webliance Testin	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Compa	Webliance Testin Yes Yes	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	Webliance Testin Yes Yes Yes Yes	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Websiance Testin Yes Yes Yes Yes Yes	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We pliance Testin Yes (hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Dverfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Webliance Testin Yes	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: JST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Webliance Testin Yes	hone (828) 277-0100 Fax (828) 277-0110 bisite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webliance Testin Yes (Solution	hone (828) 277-0100 Fax (828) 277-0110 bisite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webliance Testin Yes (Y	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webliance Testin Yes	hone (828) 277-0100 Fax (828) 277-0110 bisite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Engergency Cleanup - Spill/Release:	Websiance Testin Yes	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Websiliance Testin Yes (Some Section of the Section	hone (828) 277-0100 Fax (828) 277-0110 bsite www.blecorp.com g and Monitoring Dverfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Cape Fear Engineering, Inc.		Phone (910) 383-1044		Coastal (East of I-95): Yes	
151 Poole Road		Fax		Central (West of I-95 and East of I-77): No	
Suite 100 Leland, NC 28451				Mountains (West of I-77): No	
Leiand, NC 20431	V	Vebsite www.capefearengineering.com			
Con	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
F	Environment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Clean	u <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Cape Fear Engineering, Inc.		Phone (910) 383-1044		Coastal (East of I-95): Yes	
151 Poole Road		Fax		Central (West of I-95 and East of I-77): No	
Suite 100					
Leland, NC 28451	V	Vebsite www.capefearengineering.com		Mountains (West of I-77): No	
Con	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
F	Environment	al Service Firms	_	Other:	
	No	UST Compliance Consultants:	<u>Yes</u>		
Emergency Cleanup - Spill/Release:					
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
	<u>Yes</u>	UST Equipment Verification: Waste Disposal and Treatment:	No <u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>				
mergency Cleanup - Spill/Release:					

		UST Service Provider List (AII)		
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc.		Phone (423) 895-1500		Coastal (East of I-95): Yes	
916 Egypt Rd.		Fax		Central (West of I-95 and East of I-77): Yes	
Bluff City, NC 37618		Website		Mountains (West of I-77): Yes	
_					
		sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Ei	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/5/2023	Area of state conducts work	
CATLIN Engineers and Scientists		Phone (910) 452-5861	170/2020	Coastal (East of I-95): Yes	
220 Old Dairy Road					
Wilmington, NC 28405		Fax		Central (West of I-95 and East of I-77): Yes	
Trainington, red 20 too		Website www.CatlinUSA.com		Mountains (West of I-77): No	
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
	140				140
Corrosion Protection System Renairs:	No	Tank Tightness Testing:	No	HST Equipment Installation - Other	Nο
Corrosion Protection System Repairs:	No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:		UST Equipment Repair: UST System Installation - Complete Systems:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No	UST Equipment Repair: UST System Installation - Complete Systems:	No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No nvironmen	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No No No No nvironmen Yes	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No Yes	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No nvironmen Yes Yes	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No Yes No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No No No No Prironmen Yes Yes Yes	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No Yes	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No nvironmen Yes Yes	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No Yes No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No

		UST Service	Provider List (AII)		
Company			Listing Submitted	4/5/2023	Area of state conducts work	
CDG, Inc.		Phone (704) 394-6913			Coastal (East of I-95): Yes	
4301 Taggart Creek Road		Fax			Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28208					Mountains (West of I-77): Yes	
	V	/ebsite <u>www.cdge.com</u>			,	
Comp	pliance Tes	ing and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipme	ent Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconci	liation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Ir	ntegrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspect	ions:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
E	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultar	nts:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification	n:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatm		Yes		
Oil and Solvent Recycling:	<u>Yes</u>	Other:				
Soil and Water Testing Lab:	<u>Yes</u>					
Company			Listing Submitted	5/26/2021	Area of state conducts work	
Christopher Dunlap, P.G.		Phone (828) 505-6301			Coastal (East of I-95): No	
166 Michigan Avenue		Fax			Central (West of I-95 and East of I-77): Yes	.
Asheville, NC 28806					Mountains (West of I-77): Yes	
	V	lebsite			Modificants (West of 1-77). Tes	
Comp	pliance Tes	ing and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipme	ent Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconci	liation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Ir	ntegrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspect	ions:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
E	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultar	nts:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification	n:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatm	nent:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

		UST Service Provider List (All)		
Company		Listing Submitted	5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc	.	Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
871 South Green Street Tupelo, MS 38804		Website www.cobbenv.com		Mountains (West of I-77): Yes	
Come	olionee To			UST Equipmment Service Contractors	
_		sting and Monitoring	Vaa		Vaa
Automatic Line Leak Detector Testing: Containment Sump Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	<u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	<u>Yes</u> No	Spill Prevention Equipment Testing:		Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	<u>Yes</u> No	UST Equipment Installation - Other:	Yes Yes
Corrosion Protection System Testing:	<u>res</u> <u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u> <u>Yes</u>
Leak Detection Equipment Operability Check:	<u>res</u> <u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes	Other:	110	UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
		ntal Service Firms		Other:	
			Vac		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No No	UST Equipment Verification: Waste Disposal and Treatment:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No No	Other:	No		
Soil and Water Testing Lab:	No	Other.			
Soil and Water Testing Lab.	INO				
Company		Listing Submitted	1/20/2022	Area of state conducts work	
COHESION, INC		Phone (919) 233-8626	1/20/2022	Area of state conducts work Coastal (East of I-95): Yes	
COHESION, INC 5216 YATES MILL POND RD			1/20/2022		
COHESION, INC		Phone (919) 233-8626 Fax	1/20/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
COHESION, INC 5216 YATES MILL POND RD		Phone (919) 233-8626	1/20/2022	Coastal (East of I-95): Yes	
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606		Phone (919) 233-8626 Fax	1/20/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606		Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM	1/20/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison of the Compariso	oliance Te	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison of the compariso	oliance Te No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No No	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 233-8626 Fax Website WWW.COHESION-INC.COM sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted		Area of state conducts work	
Conklin Corrosion Control LLC		Phone (704) 560-9154		Coastal (East of I-95): Yes	
118 Oak Point Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Stony Point, NC 28678				Mountains (West of I-77): Yes	
	\	Website benconklincc@gmail.com		,	
Com	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/21/2023	Area of state conducts work	
Conklin Corrosion Control LLC		Phone (704) 560-9154		Coastal (East of I-95): Yes	
Conklin Corrosion Control LLC 118 Oak Point Lane		Phone (704) 560-9154		Central (West of I-95 and East of I-77): Yes	
		Phone (704) 560-9154 Fax		Central (West of I-95 and East of I-77): Yes	
118 Oak Point Lane	١	,			
118 Oak Point Lane Stony Point, NC 28678		Fax		Central (West of I-95 and East of I-77): Yes	
118 Oak Point Lane Stony Point, NC 28678		Fax Website benconklincc@gmail.com	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
118 Oak Point Lane Stony Point, NC 28678	oliance Tes	Fax Website benconklincc@gmail.com sting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
118 Oak Point Lane Stony Point, NC 28678 Com Automatic Line Leak Detector Testing:	oliance Tes No	Fax Website benconklincc@gmail.com sting and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
118 Oak Point Lane Stony Point, NC 28678 Comparing Line Leak Detector Testing: Containment Sump Testing:	No No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
118 Oak Point Lane Stony Point, NC 28678 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	No No No <u>Yes</u>	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No <u>Yes</u> <u>Yes</u>	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No Yes Yes Yes Yes	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No Yes Yes Yes No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No No No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No No No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No No Yes Yes Yes No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
118 Oak Point Lane Stony Point, NC 28678 Comparison Point, NC 28678 Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No Yes Yes Yes No	Fax Website benconklincc@gmail.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Pro	ovider List (A	AII)		
Company			isting Submitted		Area of state conducts work	
Crompco, LLC		Phone (610) 278-7203			Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462					Mountains (West of I-77): Yes	
	W	debsite <u>www.crompco.com</u>			,	
Comp	oliance Test	ing and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation S	Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	j:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Ei	nvironmenta	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company		III	isting Submitted	9/24/2021	Area of state conducts work	
		<u>-</u>	isting oublinition		Alloa of otato oomaaoto work	
			isting outsimited	0/2 1/2021		
C-Store Services, Inc.		Phone (919) 662-0798	isting Cashintea	0/2 1/202 1	Coastal (East of I-95): Yes	
			isting outsinition	0,2 1,202	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
C-Store Services, Inc. 7129 Hidden Valley Trail	W	Phone (919) 662-0798	isting outsinities	0,2 ,,202 ,	Coastal (East of I-95): Yes	
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529		Phone (919) 662-0798 Fax (919) 662-0711		0,2,1,202	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529		Phone (919) 662-0798 Fax (919) 662-0711 /ebsite		Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comp	oliance Test	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring	rability Check:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	Yes Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparison Line Leak Detector Testing:	oliance Test No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Open	rability Check: Services:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No Yes	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S	rability Check: Services:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparing Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Yes No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing	rability Check: Services: J:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Yes No No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Opel Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing:	rability Check: Services: J:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparison Comparison Comparison Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Yes No No No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections:	rability Check: Services: J:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections:	rability Check: Services: J: Assessments):	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes No
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections:	rability Check: Services: J: Assessments):	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes No Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections: Other:	rability Check: Services: J: Assessments):	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections: Other:	rability Check: Services: J: Assessments):	Yes No Yes No No No pection	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No Yes No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	rability Check: Services: J: Assessments):	Yes No Yes No No No Dection	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes No	Phone (919) 662-0798 Fax (919) 662-0711 /ebsite ing and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections: Other: Al Service Firms UST Compliance Consultants: UST Equipment Verification:	rability Check: Services: J: Assessments):	Yes No Yes No No No Dection	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes

		UST Service Provider L	_ist (All)		
Company		Listing Sub		Area of state conducts work	
D. H. Griffin Wrecking Company		Phone (336) 214-9012		Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407				Mountains (West of I-77): Yes	
	V	Vebsite www.dhgriffin.com		,	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check	k: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessment	s): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes		Truck Services		
Soil and Water Testing Lab:	No				
Company		Listing Sub	mitted 4/5/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Coastal (East of I-95): Yes	
3815 Junction Boulevard		·			
Raleigh, NC 27603		Fax		Central (West of I-95 and East of I-77): Yes	
	V	Vebsite <u>eastcoastenv.com</u>		Mountains (West of I-77): No	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check	k: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments	s): No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Leak Detection Monitoring Services:				UST System Removal:	Yes
Leak Detection Monitoring Services: Line Tightness Testing:	No				
Line Tightness Testing:	No	al Service Firms		Other:	
Line Tightness Testing:	No nvironment		Yes		
Line Tightness Testing: Energency Cleanup - Spill/Release:	No nvironment <u>Yes</u>	UST Compliance Consultants:	<u>Yes</u> Yes		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironment Yes Yes	UST Compliance Consultants: UST Equipment Verification:	Yes Yes No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No nvironment Yes Yes	UST Compliance Consultants:	<u>Yes</u>		
Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironment Yes Yes Yes Yes	UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	<u>Yes</u>		

		UST Service Provider List (AII)		
Company		Listing Submitted	4/6/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh , NC 27603				Mountains (West of I-77): No	
	W	ebsite eastcoastenv.com		,	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/4/2022	Area of state conducts work	
Company EnviroTrac Ltd.		Listing Submitted Phone (336) 763-6025	1/4/2022	Area of state conducts work Coastal (East of I-95): Yes	
EnviroTrac Ltd. 7343 West Friendly Avenue		Phone (336) 763-6025	1/4/2022	Coastal (East of I-95): Yes	
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J			1/4/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
EnviroTrac Ltd. 7343 West Friendly Avenue		Phone (336) 763-6025	1/4/2022	Coastal (East of I-95): Yes	
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410	W	Phone (336) 763-6025 Fax	1/4/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410	W	Phone (336) 763-6025 Fax ebsite envirotrac.com	1/4/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp	W oliance Testi	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comparison Compa	W pliance Testi No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Testi No No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi No No No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Windows Testion No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Woliance Testi No No No No No No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Woliance Testi No No No No No No No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wollance Testi No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wollance Testi No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	Woliance Testi No	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 763-6025 Fax ebsite envirotrac.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

	-	UST Service	Provider List (A	ΔΙΙ)		
Company			Listing Submitted	1/3/2022	Area of state conducts work	
Evo Corporation		Phone (336) 725-5844			Coastal (East of I-95): Yes	6
1703 Vargrave Street		Fax			Central (West of I-95 and East of I-77): Yes	3
Winston-Salem, NC 27107	147	.1			Mountains (West of I-77): Yes	
	VV	ebsite <u>www.evocorp.ne</u>	<u>. </u>			
Comp	pliance Testi	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipme	ent Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconcil	iation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (In	ntegrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspecti	ons:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms			Other: Vacuum Truck	Services
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultan	ts:	No		
Environmental Engineer/Geologist - Site Checks:	No .	UST Equipment Verification		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatm		Yes		
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Transportation Se			
Soil and Water Testing Lab:	No		'			
Company			Listing Submitted	7/12/2023	Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800			Coastal (East of I-95): Yes	6
625 Huntsman Court		Fax (704) 853-3949			Central (West of I-95 and East of I-77): Yes	
Gastonia, NC 28054		(101) 000 0010				
	W	ebsite www.excelengr.c	<u>com</u>		Mountains (West of I-77): Yes	5
Comp	pliance Testi	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipme	ent Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconcil	iation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment	Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (In	ntegrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspecti	ions:	No	UST System Installation - Complete Systems:	No
The state of the s					UST Piping/Sump Installation:	No
Leak Detection Monitoring Services:	No	Other:			oor riping/ourip installation.	140
	No No	Other:			UST System Removal:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No	Other: I Service Firms				
Leak Detection Monitoring Services: Line Tightness Testing:	No		uts:	Yes	UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing:	No nvironmenta	I Service Firms		Yes No	UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No nvironmenta No <u>Yes</u>	I Service Firms UST Compliance Consultan	:		UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironmenta No <u>Yes</u>	I Service Firms UST Compliance Consultan UST Equipment Verification	:	No	UST System Removal:	
Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No nvironmenta No Yes Yes	I Service Firms UST Compliance Consultan UST Equipment Verification Waste Disposal and Treatm	:	No	UST System Removal:	

		UST Service Pro	ovider List (A	4II)		
Company		L	isting Submitted	11/1/2023	Area of state conducts work	
Excel Environmental Associates, PLLC	F	Phone (704) 853-0800			Coastal (East of I-95): Yes	
625 Huntsman Court		Fax (704) 853-3949			Central (West of I-95 and East of I-77): Yes	
Gastonia, NC 28054					Mountains (West of I-77): Yes	
	We	ebsite <u>www.excelengr.com</u>			•	
Comp	oliance Testir	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Ope	erability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation S	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	g:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		Yes		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:		Other:				
Soil and Water Testing Lab:	No					
Company		L	_isting Submitted	1/1/2022	Area of state conducts work	
Galloway	F	Phone (303) 770-8884			Coastal (East of I-95): Yes	
6162 South Willow Drive		Fax (303) 770-3636			Central (West of I-95 and East of I-77): Yes	
Suite 320		(303) 110-3030				
Greenwood Village, CO 80111	We	ebsite <u>www.Gallowayus.com</u>			Mountains (West of I-77): Yes	
Comp	oliance Testir	ng and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Ope	erability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation S	· · · · · · · · · · · · · · · · · · ·	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing	g:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	-	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	•	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	UST/AST System [Design	UST Piping/Sump Installation:	No
Line Tightness Testing:	No		•	-	UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		Yes		
Environmental Engineer/Geologist - Site Checks:						
Environmental Engineer/Geologist - Site Onecks.	No	UST Equipment Verification:		No		
		UST Equipment Verification: Waste Disposal and Treatment:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	UST/AST Svstem [No		
	No		UST/AST System [No		

		UST Service Provider List (AII)		
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Geo-Hydro Engineers, Inc.		Phone (704) 837-7174		Coastal (East of I-95): Yes	
2748 Interstate Street		Fax		Central (West of I-95 and East of I-77): Yes	
Suite A Charlotte, NC 28208				Mountains (West of I-77): Yes	
Chanotte, NO 20200	W	ebsite www.geohydro.com		,	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/3/2022	Area of state conducts work	
· ·		Listing Submitted	1/3/2022	Area of state conducts work	
Geological Resources, Inc.		Phone (704) 845-4010	1/3/2022	Coastal (East of I-95): Yes	
Geological Resources, Inc. 3502 Hayes Road		Phone (704) 845-4010	1/3/2022	Coastal (East of I-95): Yes	
Geological Resources, Inc.		Phone (704) 845-4010	1/3/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Geological Resources, Inc. 3502 Hayes Road		Phone (704) 845-4010	173/2022	Coastal (East of I-95): Yes	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112	W	Phone (704) 845-4010 Fax (704) 845-4012	173/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112	W	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112	W pliance Testi	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Compa	W pliance Testi No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Line Leak Detector Testing: Containment Sump Testing:	W pliance Testi No No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi No No No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W pliance Testi No No No No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Windows Testi No No No No No No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Windows Testi No No No No No No No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windows Policies (No. No. No. No. No. No. No. No. No. No.	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windows Policies (No. No. No. No. No. No. No. No. No. No.	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wind pliance Testi No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	Wind pliance Testi No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Webliance Testi No	Phone (704) 845-4010 Fax (704) 845-4012 ebsite grienv.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (All)		
Company		Listing Submitted	. ,	Area of state conducts work	
Groundwater Management Associates, Inc.		Phone (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100 Greenville, NC 27834				Mountains (West of I-77): Yes	
Greenville, NC 27034	W	ebsite <u>www.gma-nc.com</u>			
Comp	pliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
Company GTA Associates, In.c		Listing Submitted Phone (704) 553-2300	4/20/2023	Area of state conducts work Coastal (East of I-95): No	
• •		Phone (704) 553-2300	4/20/2023	Coastal (East of I-95): No	
GTA Associates, In.c			4/20/2023	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
GTA Associates, In.c 701 Peninsula Lane, Suite B		Phone (704) 553-2300	4/20/2023	Coastal (East of I-95): No	
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226	w	Phone (704) 553-2300 Fax (704) 553-2400	4/20/2023	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226	w	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com	4/20/2023 No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comp	W pliance Testi	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Leak Detector Testing:	W pliance Testi No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Leak Detector Testing: Containment Sump Testing:	W pliance Testi No No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Comparison Comparison Comparison Protection Design Experts:	W pliance Testi No No No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Comparison Comparison Protection Design Experts: Corrosion Protection System Repairs:	W pliance Testi No No No No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Windows Testi No No No No No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Windows Testi No No No No No No No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Comparison Comparison Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Comparison Comparison Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Wopliance Testi No	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226 Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 553-2300 Fax (704) 553-2400 ebsite www.gtaeng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

: Yes
: Yes
: No
ctors
<u>Yes</u>
g: <u>Yes</u>
<u>Yes</u>
<u>Yes</u>
<u>Yes</u>
<u>Yes</u>
<u>Yes</u>
No
/ tank cleaning
: Yes
: Yes
: Yes
: Yes
ctors
ctors No
ctors No g: No
ctors No g: No No
ctors No g: No No No
ctors No g: No No No No
g: No No No No Yes
ctors No No No No No No Yes Yes
ctors No No No No No No Yes Yes
ctors No No No No No No Yes Yes
ctors No No No No No No Yes Yes
ctors No No No No No No Yes Yes

es
es
es
s
No
es
es
,5
S
No
<u>Yes</u>

		UST Service Provider List ((All)		
Company		Listing Submitted	5/15/2023	Area of state conducts work	
JF Petroleum Group	1	Phone (919) 744-4391		Coastal (East of I-95): Yes	i
100 Perimeter Park Drive		Fax		Central (West of I-95 and East of I-77): Yes	;
Suite H Morrisville, NC 27560				Mountains (West of I-77): Yes	;
Wornsville, NC 27500	We	bsite jfpetrogroup.com/services/environmenta	lcompliance	(*********************************	
Comp	oliance Testi	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/5/2022	Area of state conducts work	
Johnson, Spellman & Associates, Inc.	1	Phone (770) 447-4555		Coastal (East of I-95): Yes	;
350 Research Ct.		Fax		Central (West of I-95 and East of I-77): Yes	;
Suite 130				Mountains (West of I-77): Yes	
Peachtree Corners, GA 30092	We	bsite		mountains (west of 177).	•
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:		Other: Engineering- Design S	Services	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other: Engineering-Design S	Services
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling: Soil and Water Testing Lab:	No	Other: Engineering-Design S	Services		

		UST Service Provider List ((All)		
Company		Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730				Mountains (West of I-77): Yes	
	\	Website		,	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/10/2021	Area of state conducts work	
Company Martin & Slagle GeoSciences, PA		Phone 8286347741	8/10/2021	Area of state conducts work Coastal (East of I-95): No	
Martin & Slagle GeoSciences, PA 173 Sloan Road			8/10/2021	Coastal (East of I-95): No	
Martin & Slagle GeoSciences, PA		Phone 8286347741 Fax	8/10/2021	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Martin & Slagle GeoSciences, PA 173 Sloan Road	1	Phone 8286347741	8/10/2021	Coastal (East of I-95): No	
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734		Phone 8286347741 Fax	8/10/2021	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734		Phone 8286347741 Fax Website martinandslagle.com	8/10/2021 No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comp	pliance Tes	Phone 8286347741 Fax Website martinandslagle.com sting and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparison Line Leak Detector Testing:	pliance Tes	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparing Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparing Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone 8286347741 Fax Website martinandslagle.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List ((All)		
Company		Listing Submitted		Area of state conducts work	
McCallum, P.C.		Phone (757) 420-9252		Coastal (East of I-95): Yes	
1808 Hayward Avenue		Fax (757) 424-2874		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23320				Mountains (West of I-77): No	
	W	/ebsite www.mccallumtestinglabs.com		,	
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
MGF Environmental, PLLC		Phone (904) 814-3680	,,_,,_,	Coastal (East of I-95): No	
288 Gap Creek Rd					
Fletcher, NC 28732		Fax		Central (West of I-95 and East of I-77): Yes	
	W	ebsite mgfenvironmental.com		Mountains (West of I-77): Yes	
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
	162				
	<u>Yes</u> ≀ Yes	· ·			
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes		
		· ·			

		U	ST Service Provider List	(All)		
Company			Listing Submitte	· /	Area of state conducts work	
Mid-Atlantic Associates, Inc.		Phone	(919) 250-9918		Coastal (East of I-95): Yes	
409 Rogers View Ct		Fax			Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27610					Mountains (West of I-77): Yes	
		Website	www.maaonline.com		,	
Comp	oliance Te	esting and	l Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pr	evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No		ightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST In	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST In	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironme	ntal Servi	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Ed	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste	Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitte	d 12/30/2021	Area of state conducts work	
NCPCM		Phone	(919) 782-4411		Coastal (East of I-95): Yes	
7300 glenwood ave.		Fax	(919) 782-4414		Central (West of I-95 and East of I-77): Yes	
raleigh, NC 27612			()		Mountains (West of I-77): Yes	
		Website	www.ncpcm.org		Wouldains (West Of 1-77). 163	
Comp	oliance Te	esting and	l Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pr	evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST In	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No		ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
		Other			LICT Dining/Cump Installation	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	
Leak Detection Monitoring Services: Line Tightness Testing:	No No	Otner:			UST System Removal:	No
Line Tightness Testing:	No	otner:	ce Firms			
Line Tightness Testing:	No	ntal Servi	ce Firms ompliance Consultants:	<u>Yes</u>	UST System Removal:	
Line Tightness Testing:	No nvironme	ntal Servio		<u>Yes</u> No	UST System Removal:	
Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No nvironme No No	ntal Servio UST Co UST Ec	ompliance Consultants:		UST System Removal:	
Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironme No No	ntal Servio UST Co UST Ec	ompliance Consultants: quipment Verification:	No No	UST System Removal:	

		JST Service Provider List (AII)		
Company		Listing Submitted	2/28/2022	Area of state conducts work	
Parliament Petroleum Services LLC	Phor	e (864) 871-8058		Coastal (East of I-95): No	
3277 Neely Ferry Rd	Fa	x		Central (West of I-95 and East of I-77): No	
Laurens, SC 29360				Mountains (West of I-77): Yes	
	Websit	Parliamentpetroleumservices.com			
Comp	liance Testing a	nd Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Over	ill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	No Statis	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Tank	Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No Othe	:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental Ser	vice Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST	Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		Equipment Verification:	No		
		e Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Othe				
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Peak Hydrogeologic, PLLC	Phon	e (828) 817-5209		Coastal (East of I-95): No	
470 Hogback Mtn Rd	Fa			Central (West of I-95 and East of I-77): Yes	
Tryon, NC 28782	1 6	^			
	Websit	https://peakhydrogeologic.com		Mountains (West of I-77): Yes	
Comp	liance Testing a	nd Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Over	ill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No Statis	stical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No Spill	Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank	Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No UST	Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No UST	Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Othe	T		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
En	vironmental Ser	vice Firms		Other:	
	Yes UST	Compliance Consultants:	Yes		
Emergency Cleanup - Spill/Release:					
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes UST	Equipment Verification:	No		
Environmental Engineer/Geologist - Site Checks:		Equipment Verification: e Disposal and Treatment:			
Environmental Engineer/Geologist - Site Checks:		e Disposal and Treatment:	Yes		
mergency Cleanup - Spill/Release	163				

		UST Service Provider	List (All)		
Company		Listing Sul		Area of state conducts work	
Petroleum Tec		Phone (980) 781-1000		Coastal (East of I-95): Yes	
5420 Powerhouse Ct		Fax		Central (West of I-95 and East of I-77): Yes	
Concord, NC 28027				Mountains (West of I-77): Yes	
	VV	debsite www.petroleumtec.com		, , , , , , , , , , , , , , , , , , ,	
Comp	oliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Che	eck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessmen	nts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	Tank Cleaning	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	Il Service Firms		Other: Tank Clea	eaning
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:	Tank Cleaning		
Soil and Water Testing Lab:	No		_		
Company		Listing Sul	bmitted 11/1/	2023 Area of state conducts work	
Pilot Geological , PLLC		Phone (336) 870-3095		Coastal (East of I-95): Yes	
PO Box 128		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
743 Park Lawn Court		147 (000) 010 1021			
Kernersville, NC 27285				Mountains (West of L.77), Voc	
	W	ebsite <u>www.pilotenviro.com</u>		Mountains (West of I-77): Yes	
Comp		rebsite www.pilotenviro.com		Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:			eck: No	UST Equipmment Service Contractors	No
_	pliance Testi	ing and Monitoring	eck: No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No No
Automatic Line Leak Detector Testing:	pliance Testi No	ing and Monitoring Overfill Prevention Equipment Operability Che		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Testi No No	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Testi No No No	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Testi No No No No	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment	No No No nts): No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	No No No nts): No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	No No No nts): No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessmer UST Internal Lining Inspections: Other:	No No No nts): No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	No No No nts): No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No N	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants:	No No No No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No nts): No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	ing and Monitoring Overfill Prevention Equipment Operability Che Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessmer UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company Listing Submitted 4/20/2023 Area of state conducts work Practical Environmental Solutions Phone (910) 790-8265 Coastal (East of I-95): Yes	
Practical Environmental Solutions Phone (910) 790-8265	
Codstat (Edst of 1-30). 16:	3
5634 Harvest Grove Lane Fax Central (West of I-95 and East of I-77): Yes	3
Wilmington, NC 28049 Mountains (West of I-77): No	
Website www.oil-tank.com	
Compliance Testing and Monitoring UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration:	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal:	<u>Yes</u>
Environmental Service Firms Other: UST Abandonment In-place, State Co	mpliance
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No	
Oil and Solvent Recycling: No Other:	
Soil and Water Testing Lab: Yes	
Company Listing Submitted 10/12/2022 Area of state conducts work	
Practical Environmental Solutions. PC Phone (910) 790-8265 Coastal (East of I-95): Yes	3
5634 Harvest Grove Ln Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28409	,
Website www.oil-tank.com Mountains (West of I-77): No	
Compliance Testing and Monitoring UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration:	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal:	<u>Yes</u>
Environmental Service Firms Other:	
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No	
Oil and Solvent Recycling: No Other:	
Soil and Water Testing Lab: Yes	

		UST Service Provider List (All)		
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service		Phone (704) 892-8600		Coastal (East of I-95): Yes	
737 Zimmer Road		Fax (704) 892-8711		Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707				Mountains (West of I-77): Yes	
	VV	ebsite www.precisiontankservice.com		,	
Com	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Е	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
0					
Company		Listing Submitted	1/3/2022	Area of state conducts work	
		Phone (336) 335-3174	1/3/2022	Area of state conducts work Coastal (East of I-95): Yes	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue		Phone (336) 335-3174	1/3/2022	Coastal (East of I-95): Yes	
Pyramid Environmental & Engineering, PC			1/3/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue		Phone (336) 335-3174	1/3/2022	Coastal (East of I-95): Yes	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406	W	Phone (336) 335-3174 Fax (336) 691-0648	1/3/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406	W	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring	1/3/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406	W pliance Testi	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Com Automatic Line Leak Detector Testing:	W pliance Testi No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Testi No No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparing Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi No No No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W pliance Testi No No No No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Windowski with the policy of t	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Windows Testi No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windowski with the control of the co	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wind pliance Testi No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windowski with the state of the	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Wind pliance Testi No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Wind pliance Testing No	Phone (336) 335-3174 Fax (336) 691-0648 ebsite www.PyramidEnvironmental.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No Ves No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provide	r List (All)		
Company		Listing S	ubmitted 4/4/2	023 Area of state conducts work	
Regional Environmental PLLC		Phone (704) 694-8359		Coastal (East of I-95): Yes	
9016 Hazel Forest Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Fuquay Varina, NC 27526				Mountains (West of I-77): No	
	1	Website www.regionalenv.com		mountains (ross s. r. r).	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Ch	neck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessm	ents): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing S	ubmitted 12/30/2	021 Area of state conducts work	
Sensible Solutions Environmental, P. C.		Phone (336) 263-0965		Coastal (East of I-95): No	
P. O. Box 3074		Fax		Central (West of I-95 and East of I-77): Yes	
Chapel Hill, NC 27515		Tux			
	1	Website www.sensible-solutions-enviror	mental.com	Mountains (West of I-77): No	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Ch	neck: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessm	ents): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	Residential USTs		
Soil and Water Testing Lab:	No				

		UST Service Provider List (AII)		
Company		Listing Submitted		Area of state conducts work	
Singleton Environmental, Inc.		Phone (828) 508-4510		Coastal (East of I-95): Yes	
PO Box 604		Fax		Central (West of I-95 and East of I-77): Yes	
Fletcher, NC 28732				Mountains (West of I-77): Yes	
	W	/ebsite singletonenvironmental.com			
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	6/29/2021	Area of state conducts work	
SR&R Environmental, Inc.		Phone (910) 763-6274		Coastal (East of I-95): Yes	
4920 Highway 421 N.		Fax (910) 763-6132		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28401-		(010) 100 0102			
	W	/ebsite <u>www.srrenviro.com</u>		Mountains (West of I-77): No	
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
0" 10 1 10 "	V	Other: Vacuum Truck S	ervices		
Oil and Solvent Recycling:	<u>Yes</u>	Vaccam Track C	0111000		
Soil and Water Testing Lab:	<u>Yes</u> No	vacuum muck o	0.11000		

		UST Service Provider List	(All)		
Company		Listing Submitted	` /	Area of state conducts work	
Superior Services		Phone (828) 698-6286		Coastal (East of I-95): Yes	
PO Box 982		Fax (828) 698-6294		Central (West of I-95 and East of I-77): Yes	
Hendersonville, NC				Mountains (West of I-77): Yes	
		Website www.superiorservices.com		•	
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Repair and lining, AST Inspections, Repairs an	d Lining	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Company Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091	12/30/2021	Area of state conducts work Coastal (East of I-95): Yes	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street		Phone (919) 563-9091	12/30/2021	Coastal (East of I-95): Yes	
Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091	12/30/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street	١	Phone (919) 563-9091	12/30/2021	Coastal (East of I-95): Yes	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302		Phone (919) 563-9091 Fax (919) 563-9095	12/30/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302		Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com	12/30/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comp	pliance Tes	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Compar	pliance Tes	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes No <u>Yes</u>	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No <u>Yes</u> No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No No No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No Yes No No No No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No No No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No Yes No Yes No Yes Yes Yes	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Environmental Engineer/Geologist - Site Checks:	No Yes No Yes Yes Yes	Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List	(All)		
Company		Listing Submitted	` '	Area of state conducts work	
Titan Environmental Group		Phone (984) 200-6825		Coastal (East of I-95): Yes	
2005 Citation Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529	W	ebsite www.titanenvirogroup.com		Mountains (West of I-77): Yes	
_		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/26/2022	Area of state conducts work	
UST Corrosion Management, Inc.		Phone (888) 822-2431		Coastal (East of I-95): Yes	
2764 Pleasant Rd #10714		Fax (803) 802-0561		Central (West of I-95 and East of I-77): Yes	
Fort Mill, SC 29708		(000) 001 000		Mountains (West of I-77): Yes	
	W	ebsite <u>www.ustcorrosion.com</u>		Wouldains (West Of 1-77). 163	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No No	Waste Disposal and Treatment: Other:	No		
			No		

		UST Service Provider List (All)		
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING		Phone (813) 671-9065		Coastal (East of I-95): Yes	
451 APOLLO BEACH BOULEVARD		Fax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	
APOLLO BEACH, FL 33572	W	ebsite WWW.VALLEYTANK.COM		Mountains (West of I-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/31/2023	Area of state conducts work	
Company Valor Construction LLC		Listing Submitted Phone (205) 577-1035	1/31/2023	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (205) 577-1035	1/31/2023	Coastal (East of I-95): Yes	
Valor Construction LLC			1/31/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Valor Construction LLC PO Box 680654		Phone (205) 577-1035	1/31/2023	Coastal (East of I-95): Yes	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968	W	Phone (205) 577-1035 Fax	1/31/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968	W	Phone (205) 577-1035 Fax ebsite	1/31/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Line Leak Detector Testing: Containment Sump Testing:	W Dliance Testi	Phone (205) 577-1035 Fax ebsite ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W Dliance Testi No No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	W Dliance Testi No No No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Woliance Testi No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Woliance Testi No No No No No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Woliance Testi No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wobliance Testi No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Wobliance Testi No	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (205) 577-1035 Fax ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>

		UST Service Provider List (All)		
Company		Listing Submitted	. ,	Area of state conducts work	
VITAL FUEL SYSTEMS INC.		Phone (919) 303-7374		Coastal (East of I-95): Yes	
1076 CLASSIC ROAD		Fax (919) 303-7399		Central (West of I-95 and East of I-77): Yes	
APEX, NC 27540	10/	NAME AND AND A STATE OF THE COMMENT		Mountains (West of I-77): Yes	
	VV	ebsite <u>WWW.VITALFUELSYSTEMS.COM</u>			
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
·					
Company		Listing Submitted	11/1/2023	Area of state conducts work	
_		Listing Submitted Phone (919) 469-3340	11/1/2023		
Company Withers Ravenel, Inc. 115 MacKenan Drive		Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
Company Withers Ravenel, Inc.			11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Withers Ravenel, Inc. 115 MacKenan Drive		Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	W	Phone (919) 469-3340 Fax	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	W	Phone (919) 469-3340 Fax ebsite www.withersravenel.com	11/1/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	Wo	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing:	Wo pliance Testi No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	Wo pliance Testi No No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Wo pliance Testi No No No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Pliance Testi No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Pliance Testi No No No No No No No No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Pliance Testi No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testi No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Pliance Testi No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Pliance Testi No	Phone (919) 469-3340 Fax ebsite www.withersravenel.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No