

## UST Service Provider List (Central)

Company		Listing Submitted		12/30/2021		Area of state conducts work		
Petroleum Equipment Service of Wilson, Inc. PO Box 502 711 S. Goldsboro St. Wilson, NC 27893		Phone	(252) 237-6047				Coastal (East of I-95):	Yes
		Fax	(252) 237-5507				Central (West of I-95 and East of I-77):	Yes
		Website	www.peswilson.com				Mountains (West of I-77):	No
Compliance Testing and Monitoring						UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes		Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes		Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No				UST System Removal:		Yes	
Environmental Service Firms						Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	No							

Company		Listing Submitted		1/18/2024		Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438		Phone	(336) 282-3586		Coastal (East of I-95):		Yes
		Fax	(336) 282-3587		Central (West of I-95 and East of I-77):		Yes
		Website	AdadvancedEnvironmental.com		Mountains (West of I-77):		Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company			Listing Submitted	5/17/2021	Area of state conducts work
<b>AES of Greenville LLC</b> 141 S. Market Street Washington, NC 27889			<b>Phone</b> (252) 758-3311 <b>Fax</b> (252) 481-5814 <b>Website</b> <a href="http://www.aes-nc.com">www.aes-nc.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	4/15/2021	Area of state conducts work
<b>American UST Compliance Testing</b> 180 BPW Club Rd. A-1 Carrboro, NC 27510			<b>Phone</b> (919) 777-8543 <b>Fax</b> <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Central)

Company				Listing Submitted	5/17/2021	Area of state conducts work	
Apex Engineering, PC 15850 Crabbs Branch Way Suite 200 Rockville, Maryland 20855-		Phone (301) 417-0200  Fax (301) 975-0169  Website <a href="http://www.apexc.com">www.apexc.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company				Listing Submitted	7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS DBA D. 209 E BADCOCK BLVD MULBERRY, FL 33860		Phone (863) 519-4441  Fax (863) 519-4407  Website <a href="http://DWSHOUPE.COM">DWSHOUPE.COM</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		<u>Yes</u>	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		<u>Yes</u>	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company			Listing Submitted	1/10/2022	Area of state conducts work
<b>Bunnell-Lammons Engineering, Inc.</b> 130 Oval Road Arden, NC 28704			<b>Phone</b> (828) 277-0100 <b>Fax</b> (828) 277-0110 <b>Website</b> <a href="http://www.blecorp.com">www.blecorp.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:		Trust Fund Projects	
Soil and Water Testing Lab:	No				
Company			Listing Submitted	11/1/2023	Area of state conducts work
<b>Catholic Protection Services, Inc.</b> 916 Egypt Rd. Bluff City, NC 37618			<b>Phone</b> (423) 895-1500 <b>Fax</b> <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Central)

Company				Listing Submitted		4/5/2023		Area of state conducts work	
<b>CATLIN Engineers and Scientists</b> 220 Old Dairy Road Wilmington, NC 28405				<b>Phone</b> (910) 452-5861 <b>Fax</b> <b>Website</b> <a href="http://www.CatlinUSA.com">www.CatlinUSA.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		4/5/2023		Area of state conducts work	
<b>CDG, Inc.</b> 4301 Taggart Creek Road Charlotte, NC 28208				<b>Phone</b> (704) 394-6913 <b>Fax</b> <b>Website</b> <a href="http://www.cdge.com">www.cdge.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	No		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>						
Oil and Solvent Recycling:	<u>Yes</u>	Other:							
Soil and Water Testing Lab:	<u>Yes</u>								

Company		Listing Submitted		4/5/2023		Area of state conducts work	
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913  Fax  Website <a href="http://www.cdge.com">www.cdge.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

## UST Service Provider List (Central)

Company		Listing Submitted		5/26/2021		Area of state conducts work	
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806		Phone (828) 505-6301  Fax  Website				Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		5/14/2021		Area of state conducts work	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804		Phone (662) 841-0995  Fax (662) 841-0810  Website <a href="http://www.cobbenv.com">www.cobbenv.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:			Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:			Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:			Yes
Line Tightness Testing:	No			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		5/14/2021		Area of state conducts work	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804		Phone	(662) 841-0995			Coastal (East of I-95): Yes	
		Fax	(662) 841-0810			Central (West of I-95 and East of I-77): Yes	
		Website	www.cobbenv.com			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:			Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:			Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:			Yes
Line Tightness Testing:	No			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						



## UST Service Provider List (Central)

Company				Listing Submitted	1/20/2022	Area of state conducts work	
COHESION, INC 5216 YATES MILL POND RD RALEIGH, NC 27606				Phone	(919) 233-8626	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
				Fax			
				Website	WWW.COHESION-INC.COM		
Compliance Testing and Monitoring						UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	QED MOBILE LAB TPH - SOIL				
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	11/21/2023	Area of state conducts work	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678				Phone	(704) 560-9154	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
				Fax			
				Website	benconklincc@gmail.com		
Compliance Testing and Monitoring						UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		10/11/2023		Area of state conducts work	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678		Phone (704) 560-9154  Fax  Website <a href="mailto:benconklincc@gmail.com">benconklincc@gmail.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
<b>Crompco, LLC</b> 1815 Gallagher Road Plymouth Meeting, PA 19462		<b>Phone</b>	(610) 278-7203				<b>Coastal (East of I-95):</b> Yes
		<b>Fax</b>	(610) 278-7621				<b>Central (West of I-95 and East of I-77):</b> Yes
		<b>Website</b>	<a href="http://www.crompco.com">www.crompco.com</a>				<b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<b><u>Yes</u></b>	Overfill Prevention Equipment Operability Check:	<b><u>Yes</u></b>	Dispenser Meter Repair/Calibration:		<b><u>Yes</u></b>	
Containment Sump Testing:	<b><u>Yes</u></b>	Statistical Inventory Reconciliation Services:	<b><u>Yes</u></b>	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b><u>Yes</u></b>	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b><u>Yes</u></b>	UST Equipment Installation - Other:		<b><u>Yes</u></b>	
Corrosion Protection System Testing:	<b><u>Yes</u></b>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		<b><u>Yes</u></b>	
Leak Detection Equipment Operability Check:	<b><u>Yes</u></b>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	<b><u>Yes</u></b>	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	<b><u>Yes</u></b>			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b><u>Yes</u></b>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b><u>Yes</u></b>				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						



## UST Service Provider List (Central)

Company		Listing Submitted		9/24/2021		Area of state conducts work		
C-Store Services, Inc. 7129 Hidden Valley Trail Garner, NC 27529		Phone	(919) 662-0798				Coastal (East of I-95):	Yes
		Fax	(919) 662-0711				Central (West of I-95 and East of I-77):	Yes
		Website					Mountains (West of I-77):	No
Compliance Testing and Monitoring						UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes		Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes		Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	UST-27 monthly inspection		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No				UST System Removal:		Yes	
Environmental Service Firms						Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	No							

Company		Listing Submitted		9/28/2022		Area of state conducts work	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407		Phone (336) 214-9012  Fax  Website <a href="http://www.dhgriffin.com">www.dhgriffin.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Vacuum Truck Services				
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		4/5/2023		Area of state conducts work	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603		Phone (919) 349-5969  Fax  Website <a href="http://eastcoastenv.com">eastcoastenv.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		4/6/2023		Area of state conducts work	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh , NC 27603		Phone (919) 349-5969  Fax  Website <a href="http://eastcoastenv.com">eastcoastenv.com</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No			
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	1/4/2022	Area of state conducts work	
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410		Phone (336) 763-6025  Fax  Website <a href="http://envirotrac.com">envirotrac.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	1/3/2022	Area of state conducts work	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107		Phone (336) 725-5844  Fax  Website <a href="http://www.evocorp.net">www.evocorp.net</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other: Vacuum Truck Services			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:	Transportation Services				
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	11/1/2023	Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Website <a href="http://www.excelengr.com">www.excelengr.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	7/12/2023	Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Website <a href="http://www.excelengr.com">www.excelengr.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		7/12/2023		Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone	(704) 853-0800			Coastal (East of I-95): Yes	
		Fax	(704) 853-3949			Central (West of I-95 and East of I-77): Yes	
		Website	<a href="http://www.excelengr.com">www.excelengr.com</a>			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	1/1/2022	Area of state conducts work	
<b>Galloway</b> 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111		<b>Phone</b> (303) 770-8884 <b>Fax</b> (303) 770-3636 <b>Website</b> <a href="http://www.Gallowayus.com">www.Gallowayus.com</a>				<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	UST/AST System Design	UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	UST/AST System Design				
Soil and Water Testing Lab:	No						

Company				Listing Submitted	12/30/2021	Area of state conducts work	
<b>Geo-Hydro Engineers, Inc.</b> 2748 Interstate Street Suite A Charlotte, NC 28208		<b>Phone</b> (704) 837-7174 <b>Fax</b> <b>Website</b> <a href="http://www.geohydro.com">www.geohydro.com</a>				<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208		Phone (704) 837-7174  Fax  Website <a href="http://www.geohydro.com">www.geohydro.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		1/3/2022		Area of state conducts work	
<b>Geological Resources, Inc.</b> 3502 Hayes Road Monroe, NC 28112		<b>Phone</b> (704) 845-4010 <b>Fax</b> (704) 845-4012 <b>Website</b> <a href="http://grienv.com">grienv.com</a>				<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/16/2023		Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone (252) 758-3310  Fax  Website <a href="http://www.gma-nc.com">www.gma-nc.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						



## UST Service Provider List (Central)

Company		Listing Submitted		4/20/2023		Area of state conducts work	
GTA Associates, In.c 701 Peninsula Lane, Suite B Charlotte, NC 28226		Phone (704) 553-2300 Fax (704) 553-2400 Website www.gtaeng.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		10/26/2021		Area of state conducts work	
Guardian Fueling Technologies 5116 Departure Drive Raleigh, NC 27616		Phone (919) 729-6980 Fax (919) 769-2919 Website www.guardianfueltech.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	Yes	Other: SafeGuard UST Inspection Services		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other: FuelGuard fuel polishing / tank cleaning			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	1/25/2022	Area of state conducts work	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156		Phone (770) 917-8846  Fax (770) 917-0921  Website <a href="http://www.harcoservices.com">www.harcoservices.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	12/30/2021	Area of state conducts work	
Highlands Environmental Solutions, Inc. 8410-d Falls of Neuse Raleigh, NC 27615		Phone (919) 848-3155  Fax  Website <a href="http://www.HESfast.com">www.HESfast.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted		4/11/2023		Area of state conducts work	
<b>INENCO, Inc.</b> 132 W. Statesville Avenue Mooresville, NC 27115				<b>Phone</b> (704) 662-8192 <b>Fax</b> (704) 662-8194 <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		5/15/2023		Area of state conducts work	
<b>JF Petroleum Group</b> 100 Perimeter Park Drive Suite H Morrisville, NC 27560				<b>Phone</b> (919) 744-4391 <b>Fax</b> <b>Website</b> <a href="http://jfpetrogroup.com/services/environmentalcompliance">jfpetrogroup.com/services/environmentalcompliance</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>			Dispenser Meter Repair/Calibration:	<u>Yes</u>		
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	<u>Yes</u>		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>			Spill Bucket Installation Repair:	<u>Yes</u>		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>			UST Equipment Installation - Other:	<u>Yes</u>		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	<u>Yes</u>		
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	<u>Yes</u>		
Leak Detection Monitoring Services:	<u>Yes</u>	Other:				UST Piping/Sump Installation:	<u>Yes</u>		
Line Tightness Testing:	<u>Yes</u>					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

## UST Service Provider List (Central)

Company		Listing Submitted	1/5/2022	Area of state conducts work	
<b>Johnson, Spellman &amp; Associates, Inc.</b> 350 Research Ct. Suite 130 Peachtree Corners, GA 30092		<b>Phone</b> (770) 447-4555  <b>Fax</b>  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	Engineering- Design Services	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms				Other:	Engineering-Design Services
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	Engineering-Design Services		
Soil and Water Testing Lab:	No				

Company		Listing Submitted	12/20/2022	Area of state conducts work	
<b>Jones Covey Group</b> 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730		<b>Phone</b> (888) 972-7581  <b>Fax</b> (909) 484-0300  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Environmental Service Firms				Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Central)

Company				Listing Submitted		8/10/2021		Area of state conducts work	
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734				Phone 8286347741  Fax  Website martinandslagle.com		Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		Yes				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

Company				Listing Submitted		4/20/2023		Area of state conducts work	
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732				Phone (904) 814-3680  Fax  Website mgfenvironmental.com		Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		Yes	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		Yes				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

## UST Service Provider List (Central)

Company		Listing Submitted		9/8/2022		Area of state conducts work	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610		Phone (919) 250-9918  Fax (919) 250-9950  Website <a href="http://www.maaonline.com">www.maaonline.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
NCCPM 7300 glenwood ave. raleigh, NC 27612		Phone (919) 782-4411  Fax (919) 782-4414  Website <a href="http://www.ncpcm.org">www.ncpcm.org</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	Engineering on UST Installations				
Soil and Water Testing Lab:	No						



## UST Service Provider List (Central)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782		Phone (828) 817-5209  Fax  Website <a href="https://peakhydrogeologic.com">https://peakhydrogeologic.com</a>				Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037		Phone (704) 335-8801  Fax (704) 342-1672  Website <a href="http://www.petroleumequipment.net">www.petroleumequipment.net</a>				Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:			<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:			<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:			<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:			<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:			<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:			<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company			Listing Submitted	5/14/2021	Area of state conducts work	
<b>Petroleum Solutions Inc.</b> 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606			<b>Phone</b> (919) 605-1979 <b>Fax</b> (919) 773-1704 <b>Website</b> <a href="http://www.petrolemsolutionsinc.net">www.petrolemsolutionsinc.net</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> No	
Compliance Testing and Monitoring			UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<b>Yes</b>	Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>	Spill Bucket Installation Repair:	<b>Yes</b>	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<b>Yes</b>	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<b>Yes</b>	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<b>Yes</b>	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<b>Yes</b>	
Line Tightness Testing:	No			UST System Removal:	<b>Yes</b>	
Environmental Service Firms			Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

  

Company			Listing Submitted	3/31/2022	Area of state conducts work	
<b>Petroleum Tec</b> 5420 Powerhouse Ct Concord, NC 28027			<b>Phone</b> (980) 781-1000 <b>Fax</b> <b>Website</b> <a href="http://www.petroleumtec.com">www.petroleumtec.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	No	Other:	Tank Cleaning	UST Piping/Sump Installation:	No	
Line Tightness Testing:	No			UST System Removal:	No	
Environmental Service Firms			Other:			Tank Cleaning
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>			
Oil and Solvent Recycling:	No	Other:	Tank Cleaning			
Soil and Water Testing Lab:	No					

## UST Service Provider List (Central)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Phone (336) 870-3095 Fax (336) 310-4527 Website <a href="http://www.pilotenviro.com">www.pilotenviro.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		4/20/2023		Area of state conducts work	
Practical Environmental Solutions 5634 Harvest Grove Lane Wilmington, NC 28049		Phone (910) 790-8265 Fax Website <a href="http://www.oil-tank.com">www.oil-tank.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other: UST Abandonment In-place, State Compliance			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

## UST Service Provider List (Central)

Company		Listing Submitted		10/12/2022		Area of state conducts work	
Practical Environmental Solutions. PC 5634 Harvest Grove Ln Wilmington, NC 28409		Phone (910) 790-8265  Fax  Website <a href="http://www.oil-tank.com">www.oil-tank.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Precision Tank Service 737 Zimmer Road Fort Mill , SC 29707		Phone (704) 892-8600  Fax (704) 892-8711  Website <a href="http://www.precisiontankservice.com">www.precisiontankservice.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	Yes			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted	1/3/2022	Area of state conducts work	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406		Phone (336) 335-3174  Fax (336) 691-0648  Website <a href="http://www.PyramidEnvironmental.com">www.PyramidEnvironmental.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	4/4/2023	Area of state conducts work	
Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526		Phone (704) 694-8359  Fax  Website <a href="http://www.regionalenv.com">www.regionalenv.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

## UST Service Provider List (Central)

Company				Listing Submitted		12/30/2021		Area of state conducts work	
Sensible Solutions Environmental, P. C. P. O. Box 3074 Chapel Hill, NC 27515				Phone (336) 263-0965  Fax  Website <a href="http://www.sensible-solutions-environmental.com">www.sensible-solutions-environmental.com</a>		Coastal (East of I-95): No  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:		Residential USTs				
Soil and Water Testing Lab:		No							

Company				Listing Submitted		12/30/2021		Area of state conducts work	
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732				Phone (828) 508-4510  Fax  Website <a href="http://singletonenvironmental.com">singletonenvironmental.com</a>		Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							



## UST Service Provider List (Central)

Company		Listing Submitted		6/29/2021		Area of state conducts work	
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401-		Phone (910) 763-6274 Fax (910) 763-6132 Website <a href="http://www.srrenviro.com">www.srrenviro.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:	Vacuum Truck Services				
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Superior Services PO Box 982 Hendersonville, NC		Phone (828) 698-6286 Fax (828) 698-6294 Website <a href="http://www.superiorservices.com">www.superiorservices.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other: repair and lining, AST Inspections, Repairs and Lining		UST Piping/Sump Installation:		No	
Line Tightness Testing:	Yes			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302		Phone (919) 563-9091 Fax (919) 563-9095 Website <a href="http://www.terraquestpc.com">www.terraquestpc.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company		Listing Submitted		3/6/2024		Area of state conducts work	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529		Phone (984) 200-6825 Fax Website <a href="http://www.titanenvirogroup.com">www.titanenvirogroup.com</a>				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company				Listing Submitted		1/26/2022		Area of state conducts work	
UST Corrosion Management, Inc. 2764 Pleasant Rd #10714 Fort Mill, SC 29708				Phone (888) 822-2431 Fax (803) 802-0561 Website <a href="http://www.ustcorrosion.com">www.ustcorrosion.com</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	No		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		7/14/2022		Area of state conducts work	
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572				Phone (813) 671-9065 Fax (866) 328-9796 Website <a href="http://WWW.VALLEYTANK.COM">WWW.VALLEYTANK.COM</a>		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	Yes	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	Yes					UST System Removal:	No		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

## UST Service Provider List (Central)

Company				Listing Submitted	1/31/2023	Area of state conducts work	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968		Phone (205) 577-1035  Fax  Website				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	10/5/2021	Area of state conducts work	
VITAL FUEL SYSTEMS INC. 1076 CLASSIC ROAD APEX, NC 27540		Phone (919) 303-7374  Fax (919) 303-7399  Website <a href="http://WWW.VITALFUELSYSTEMS.COM">WWW.VITALFUELSYSTEMS.COM</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		10/5/2021		Area of state conducts work	
VITAL FUEL SYSTEMS INC. 1076 CLASSIC ROAD APEX, NC 27540		Phone	(919) 303-7374			Coastal (East of I-95): Yes	
		Fax	(919) 303-7399			Central (West of I-95 and East of I-77): Yes	
		Website	WWW.VITALFUELSYSTEMS.COM			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	Yes		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

## UST Service Provider List (Central)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340  Fax  Website <a href="http://www.withersravenel.com">www.withersravenel.com</a>				Coastal (East of I-95): Yes  Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						