		UST Service Provider List (Co	oastal)		
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.		Phone (252) 237-6047		Coastal (East of I-95): Yes	
PO Box 502		Fax (252) 237-5507		Central (West of I-95 and East of I-77): Yes	
711 S. Goldsboro St. Wilson, NC 27893	W	Alabatta		Mountains (West of I-77): No	
		Website www.peswilson.com			
Comp	pliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/18/2024	Area of state conducts work	
Advanced Environmental Services, Inc.		Phone (336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax (336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438				Mountains (West of I-77): Yes	
	V	Website AdavancedEnvironmental.com		mountaine (reset et 111).	
Comp	pliance Test	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
				UST System Removal:	<u>Yes</u>
Line Tightness Testing:	No				
		tal Service Firms		Other:	
		tal Service Firms UST Compliance Consultants:	No	Other:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	nvironment Yes Yes		No No	Other:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	nvironment Yes Yes	UST Compliance Consultants:		Other:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	nvironment Yes Yes	UST Compliance Consultants: UST Equipment Verification:	No	Other:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	nvironment Yes Yes Yes	UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No	Other:	

		UST Service Provider List (Co	oastal)		
Company		Listing Submitted	5/17/2021	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889				Mountains (West of I-77): Yes	
		Website www.aes-nc.com		,	
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Jon and Trailor Footing Lab.					
Company	110	Listing Submitted	4/15/2021	Area of state conducts work	
-		Listing Submitted Phone (919) 777-8543	4/15/2021	Area of state conducts work Coastal (East of I-95): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1			4/15/2021	Coastal (East of I-95): Yes	
Company American UST Compliance Testing		Phone (919) 777-8543	4/15/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1		Phone (919) 777-8543	4/15/2021	Coastal (East of I-95): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510		Phone (919) 777-8543 Fax	4/15/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510		Phone (919) 777-8543 Fax Website	4/15/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp	oliance Te	Phone (919) 777-8543 Fax Website sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing:	oliance Te Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Te Yes Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Dliance Te Yes Yes No	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u>
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No <u>Yes</u> No <u>Yes</u> No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	oliance Te Yes Yes No No Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No <u>Yes</u> No <u>Yes</u>
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> No <u>Yes</u> No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves No No Yes Yes No Yes No Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Ves No No Yes No No Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: otal Service Firms UST Compliance Consultants:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves No No Yes No No Yes	Phone (919) 777-8543 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No

		UST Service Provider List (C	Coastal)		
Company		Listing Submitte		Area of state conducts work	
Apex Engineering, PC		Phone (301) 417-0200		Coastal (East of I-95): Yes	
15850 Crabbs Branch Way		Fax (301) 975-0169		Central (West of I-95 and East of I-77): Yes	
Suite 200 Rockville, Maryland 20855-				Mountains (West of I-77): Yes	
Trockvino, iviaryiana 20000	V	Vebsite <u>www.apexcos.com</u>		,	
Comp	oliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	Yes				
Company		Listing Submitte	ed 7/19/2022	Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS I	DBA D.	Phone (863) 519-4441		Coastal (East of I-95): Yes	
209 E BADCOCK BLVD				Central (West of I-95 and East of I-77): Yes	
		Fax (863) 519-4407			
MULBERRY, FL 33860		,			
MULBERRY, FL 33860	W	Fax (863) 519-4407 Vebsite DWSHOUPPE.COM		Mountains (West of I-77): Yes	
		. ,			
		Vebsite DWSHOUPPE.COM	No	Mountains (West of I-77): Yes	No
Сотр	pliance Test	Vebsite <u>DWSHOUPPE.COM</u> ting and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Comp Automatic Line Leak Detector Testing:	pliance Test No	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Test No No	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Test No No No	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No N	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Vebsite DWSHOUPPE.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
Bay Compliance and Testing LLC		Phone (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	We	ebsite https://baycomplianceandtesting.com/		mountains (troot of 111). He	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:		Other:			
Soil and Water Testing Lab:	No				
	-				
Company	-	Listing Submitted	1/10/2022	Area of state conducts work	
Company			1/10/2022		
		Phone (828) 277-0100	1/10/2022	Coastal (East of I-95): Yes	
Company Bunnell-Lammons Engineering, Inc.			1/10/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road	l	Phone (828) 277-0100	1/10/2022	Coastal (East of I-95): Yes	
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	We	Phone (828) 277-0100 Fax (828) 277-0110	1/10/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	We pliance Testi	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com	1/10/2022 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704	We pliance Testi Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing:	We pliance Testi Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	Webpliance Testing Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Webpliance Testing Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes Yes Yes Yes Yes Yes Yes	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 Pebsite www.blecorp.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Engergency Cleanup - Spill/Release:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes Yes Yes Yes Yes Yes Yes Yes Yes Y	Phone (828) 277-0100 Fax (828) 277-0110 ebsite www.blecorp.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Cape Fear Engineering, Inc.		Phone (910) 383-1044		Coastal (East of I-95): Yes	
151 Poole Road		Fax		Central (West of I-95 and East of I-77): No	
Suite 100				Mountains (West of I-77): No	
Leland, NC 28451	V	Vebsite www.capefearengineering.com		mountains (West St 177). No	
Com	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/18/2022	Area of state conducts work	
Company Cape Fear Engineering, Inc.		Listing Submitted Phone (910) 383-1044	5/18/2022	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (910) 383-1044	5/18/2022	Coastal (East of I-95): Yes	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100			5/18/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Cape Fear Engineering, Inc. 151 Poole Road	V	Phone (910) 383-1044	5/18/2022	Coastal (East of I-95): Yes	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451		Phone (910) 383-1044 Fax	5/18/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451		Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com	5/18/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com	pliance Tes	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing:	pliance Tes No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cape Fear Engineering, Inc. 151 Poole Road Suite 100 Leland, NC 28451 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (910) 383-1044 Fax Vebsite www.capefearengineering.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Cathodic Protection Services, Inc.		Phone (423) 895-1500		Coastal (East of I-95): Yes	
916 Egypt Rd.		Fax		Central (West of I-95 and East of I-77): Yes	
Bluff City, NC 37618				Mountains (West of I-77): Yes	
	V	Vebsite			
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/5/2023	Area of state conducts work	
• •			4/5/2023		
Company CATLIN Engineers and Scientists 220 Old Dairy Road		Phone (910) 452-5861	4/5/2023	Coastal (East of I-95): Yes	
CATLIN Engineers and Scientists			4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road	V	Phone (910) 452-5861	4/5/2023	Coastal (East of I-95): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405		Phone (910) 452-5861 Fax	4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405		Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com	4/5/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp	oliance Tes	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Comp	oliance Tes No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Comparison Comparison Containment Sump Testing:	No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Engergency Cleanup - Spill/Release:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
CATLIN Engineers and Scientists 220 Old Dairy Road Wilmington, NC 28405 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (910) 452-5861 Fax Vebsite www.CatlinUSA.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company CDG, Inc. Phone (704) 394-6913 Fax Website www.cdge.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Lining Inspections: No UST System Removal: No UST System Removal: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: No UST System Installation: No UST System Removal: No U			UST Service Provider List (C	oastal)		
### Charlotte, NC 28208 Fax Website Www.cdge.com Website Www.cdge.com Worksoft 1-77); Yes Mountains (West of 1-77); Yes Mountains (West of 1-77); Yes Worksoft 1-77); Yes Wor	Company		Listing Submitted	d 4/5/2023	Area of state conducts work	
Website www.cdge.com Website www.cdge.com Wountains (West of I-77): Yes	CDG, Inc.		Phone (704) 394-6913		Coastal (East of I-95): Yes	
Website WWW.cdge.com			Fax		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring UST Equipment Service Contractors	Charlotte, NC 28208				Mountains (West of I-77): Yes	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Chack: No Statistical Inventory Reconciliation Services: No Tank Tightness Testing: No Statistical Inventory Reconciliation Services: No Outosion Protection System Repairs: No Sylil Prevention Equipment Testing: No UST Equipment Repairs: No UST Equipment Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repairs: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installati		V	Vebsite <u>www.cdge.com</u>		,	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Tark Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Inspections: No UST System Installation - Complete Systems: No UST Sequence of System Testing: No UST Sequence Installation - Complete Systems: No UST Sequence Installation - Complete Systems: No UST Sequenc	Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Lining Inspections: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Priping Symp Installation: No UST System Removal: Yes UST System Remova	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corresion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No Leak Detection Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Equipment Service Internal Internal Integrity Assessments (Integrity Assessments): No UST Equipment Repairs: No UST Equipment Service Internal Internal Integrity Assessments (Integrity Assessments): No UST Equipment Repairs: No UST Equipment Service Internal Integrity Assessments (Integrity Assessments): No UST Equipment Service Integrity Repairs: No UST Equipment Service Integrity Repairs: No UST Equipment Repairs: Yes Statistical Ventory Reconciliation Repairs: Yes UST Internal Integrity Report Repairs: Yes UST Repairment	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Quarternal Cleak Detection Monitoring Services: No Other: No UST System Installation: No UST System Removal: No UST Corrosion Protection System Regards: No UST Corrosion Protection System Regards: No UST Corrosion Protection System Regards: No UST Corrosion Protection System Removal: No UST System Installation: No UST System Installation: No UST System Installation: No UST Equipment Service Contractors Referen Street Central (West of I-95 and East of I-77): Yes Website www.cobbenv.com Website www.cobbenv.com Website www.cobbenv.com UST Equipment Service Contractors Referen Street Tupelo, MS 38804 Website www.cobbenv.com UST Equipment Service Contractors Resident System Regards: No UST Equipment Service Contractors Ves Corrosion Protection System Testing: No UST Equipment Service Contractors Yes Corrosion Protection System Repairs: No UST Equipment Service No UST System Installation - Corrolete Sy	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No Other: No Other: UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST System Remov	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: Line Tightness Testing: No Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes UST Equipment Verification: Yes UST Equipment Verification: Yes UST Equipment Verification: Yes Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes UST Equipment Verification: Yes UST Equipment Service: Verification: Yes UST Equipment Issualization Services: No UST Equipment Issualization Services: No UST Equipment Issualization Service: Yes Corrosion Protection System Repairs: Yes UST Equipment Issualization Complete Systems: Yes Corrosion Protection System Repairs: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Issualization: Yes UST Equipment Issualization Complete Systems: Yes Corrosion Protection System Repairs: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Yes UST Equipment Repair: Yes UST Equipment Installation Complete Systems: Yes Corrosion Protection System Repairs: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Yes UST Equipment Repair: Yes UST Equipment Operability Check: Yes	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: No	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist - Site Checks: Ves UST Compliance Consultants: Ves Waste Disposal and Treatment: Yes Other: Ves Other (Ge2) 841-0995 Fax (Ge2) 841-0910	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: Yes Coll and Solvent Recycling: Yes Other: Company	Line Tightness Testing:	No			UST System Removal:	No
Environmental Engineer/Geologist - Site Checks: Yes Waste Disposal and Treatment: Yes Cother: View Waste Disposal and Treatment: Yes Other: Company Listing Submitted 5/14/2021 Area of state conducts work Cobb Environmental & Technical Services, Inc. Phone (662) 841-0995 Cast 1602, Tupelo, MS 38802 Fax (662) 841-0810 Cother: Tupelo, MS 38804 Website www.cobbenv.com Compliance Testing and Monitoring Website www.cobbenv.com Compliance Testing: Yes Substited International Service Firms Corrosion Protection Design Experts: No Spill Prevention Equipment Operability Check: Yes UST Equipment Installation - Other: Yes UST Equipment Repair: Yes UST Internal Lining Inspections: No UST Equipment Operability Check: Yes UST System Installation - Complete Systems: Yes Cherrical West Installation: Yes UST System Removal: Yes UST System Removal: Ye	Er	nvironment	al Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: Yes Waste Disposal and Treatment: Yes Cother: Vigos Other: Company Listing Submitted 5/14/2021 Area of state conducts work Cobb Environmental & Technical Services, Inc. Phone (662) 841-0995 Fax (662) 841-0910 Constant Green Street Tupelo, MS 38802 Fax (662) 841-0810 Submitted Submitte	Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu Yes Yes Other: Vies Other: Company Listing Submitted 5/14/2021 Company Environmental & Technical Services, Inc. Phone (662) 841-0995 P. O. Box 1602, Tupelo, MS 38802 P. Fax (662) 841-0810 Phone (662) 841-0910 Prevention Equipment Street Tupelo, MS 38804 Website www.cobbenv.com Compliance Testing Libe Leak Detector Testing: Vies Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Corrosion Protection System Repairs: Corrosion Protection System Testing: Vies UST Internal Inspections (Integrity Assessments): Leak Detection Equipment Operability Check: Vies Other: Wish Internal Lining Inspections (Integrity Assessments): No UST Equipment Netallation - Complete Systems: Vies Other: Leak Detection Monitoring Services: No UST Equipment Installation - Complete Systems: Vies Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No UST Equipment Repair: Vies Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No UST Equipment Repair: Vies Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No UST Equipment Repair: Vies Other: Vies Othe						
Oil and Solvent Recycling: Soil and Water Testing Lab: Company Listing Submitted 5/14/2021 Area of state conducts work Cobb Environmental & Technical Services, Inc. Phone (662) 841-0995 P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Website www.cobbenv.com Compliance Testing and Monitoring Containment Sump Testing: Yes Overfill Prevention Equipment Operability Check: Yes Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Outroliation Protection Design Experts: No Spill Prevention Equipment Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Installation Servicing: Yes UST Internal Lining Inspections: No UST Equipment Installation - Complete Systems: Yes UST Internal Lining Inspections: No UST Equipment Repairs: Yes UST Internal Lining Inspections: No UST Equipment Installation - Complete Systems: Yes UST Internal Lining Inspections: No UST Equipment Repairs: Yes UST Piping/Sump Installation: Yes UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Equipment Services: No UST Equipment Installation: Yes UST System Removal: Other:						
Company Listing Submitted 5/14/2021 Area of state conducts work Cobb Environmental & Technical Services, Inc. Phone (662) 841-0995 P. O. Box 1602, Tupelo, MS 38802 Fax (662) 841-0810 Fax (662) 841-0810 Website www.cobbenv.com Compliance Testing and Monitoring Website www.cobbenv.com Website www.cobbenv.com Compliance Testing: Yes Overfill Prevention Equipment Operability Check: Yes Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Equipment Installation Controsion Protection System Repairs: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Yes Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes Leak Detection Equipment Operability Check: Yes Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Environmental Engineer/Geologist Soil and GW Clean No Waste Disposal and Treatment: No Other:						
Cobb Environmental & Technical Services, Inc. Phone (662) 841-0995 P. O. Box 1602, Tupelo, MS 38802 Pax (662) 841-0810 Website www.cobbenv.com Compliance Testing and Monitoring Containment Sump Testing: Ves Overfill Prevention Equipment Operability Check: Yes Oursion Protection System Repairs: Ves UST Equipment Installation - Other: Ves Other: Corrosion Protection System Repairs: Ves UST Internal Lining Inspections: No UST Equipment Installation - Other: Ves UST Equipment Repair: Ves UST Equipment Installation - Other: Ves UST Equipment Repair: Ves UST Equipment Repair: Ves UST Equipment Installation - Other: Ves UST Equipment Repair: Ves UST Equipment Installation - Other: Ves UST System Installation - Complete Systems: Ves UST Piping/Sump Installation: Ves UST System Removal: Ves UST System Remova	Soil and Water Testing Lab:	Yes				
P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Website www.cobbenv.com Website www.cobbenv.com	Company		Listing Submitted	d 5/14/2021	Area of state conducts work	
P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804 Website www.cobbenv.com Website www.cobbenv.com	Cobb Environmental & Technical Services, Inc).	Phone (662) 841-0995		Coastal (East of I-95): Yes	
## Mountains (West of I-77): Yes Compliance Testing and Monitoring Sassa	•					
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Otrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Tank Tightness Testing: No UST Internal Lining Inspections: No UST Equipment Installation Repair: Yes Otrosion Protection System Repairs: Yes UST Internal Lining Inspections: No UST System Installation - Other: Yes UST System Installation - Other: Yes UST System Installation - Complete Systems: Yes UST Internal Lining Inspections: Yes UST System Installation: Yes UST System Removal:	871 South Green Street		1 dx (002) 041-0010			
Automatic Line Leak Detector Testing: Yes Overfill Prevention Equipment Operability Check: Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Yes Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Yes Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST System Installation: Yes UST System Removal: Yes	Tupelo, MS 38804	V	Vebsite www.cobbenv.com		Mountains (West of I-77): Yes	
Containment Sump Testing: Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection System Repairs: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation Servicing: Yes Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: Yes Leak Detection System Testing: Yes UST Internal Lining Inspections: No UST System Installation - Complete Systems: Yes UST Piping/Sump Installation: Yes UST System Removal: U	Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Containment Sump Testing: Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Testing: Yes Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): Leak Detection Equipment Operability Check: Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No UST Equipment Repair: Yes UST System Installation - Complete Systems: Yes UST System Installation: UST System Installation: UST System Removal: UST System Removal: Yes U	Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	Yes
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Yes Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Yes Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No UST System Installation - Complete Systems: Yes Leak Detection Monitoring Services: Yes Other: UST Piping/Sump Installation: Yes UST System Removal: UST System Removal: Yes UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Other:	Containment Sump Testing:				Leak Detection Equipment Installation Servicing:	
Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No Leak Detection Monitoring Services: Yes Other: Line Tightness Testing: No Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No UST System Installation - Complete Systems: Yes Leak Detection Monitoring Services: Yes Other: UST Piping/Sump Installation: Yes UST System Removal: Yes Other:	Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Leak Detection Monitoring Services: Yes Other: UST Piping/Sump Installation: Yes Line Tightness Testing: No UST System Removal: Yes Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Line Tightness Testing: No Environmental Service Firms Yes	Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Line Tightness Testing: No Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Oil and Solvent Recycling: No Other:	Line Tightness Testing:				UST System Removal:	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Er	nvironment	al Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other:		No				
Oil and Solvent Recycling: No Other:		No				
			·			
		No				

UST Service Provider List (Coastal) Company Listing Submitted 1/20/2022 Area of state conducts work COHESION, INC Phone (919) 233-8626 Coastal (East of I-95):	
COHESION, INC Phone (919) 233-8626 Coastal (Fast of I-95):	
Oddid (Last of 199).	Yes
5216 YATES MILL POND RD Fax Central (West of I-95 and East of I-77):	Yes
RALEIGH, NC 27606 Mountains (West of I-77):	No
Website WWW.COHESION-INC.COM	
Compliance Testing and Monitoring UST Equipmment Service Contractor	ors
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration:	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal:	<u>Yes</u>
Environmental Service Firms Other:	
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No	
Oil and Solvent Recycling: No Other: QED MOBILE LAB TPH - SOIL	
Soil and Water Testing Lab: Yes	
Company Listing Submitted 10/11/2023 Area of state conducts work	
Conklin Corrosion Control LLC Phone (704) 560-9154 Coastal (East of I-95):	Yes .
118 Oak Point Lane Fax Central (West of I-95 and East of I-77):	Yes .
Stony Point, NC 28678 Mountains (West of I-77):	
Website benconklincc@gmail.com	163
Compliance Testing and Monitoring UST Equipmment Service Contractor	ors
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration:	No
	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	
	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	No No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	
Containment Sump Testing: Corrosion Protection Design Experts: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Ves Tank Tightness Testing: No UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Corrosion Protection System Testing: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: No UST Internal Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Corrosion Protection Design Experts: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: No Other: Line Tightness Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: Other: Corrosion Protection Design Experts: No UST Equipment Installation - Other: UST Equipment Repair: UST System Installation: UST System Removal: Other:	No No No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No	No No No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection System Testing: Leak Detection Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: UST System Removal: Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Installation Repair: UST Equipment Installation - Other: UST System Installation - Complete Systems: UST System Removal: Other:	No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Conklin Corrosion Control LLC		Phone (704) 560-9154		Coastal (East of I-95): Yes	
118 Oak Point Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Stony Point, NC 28678	14/	halfa haraaaliinaa @aaaallaaaa		Mountains (West of I-77): Yes	
	VV	ebsite benconklincc@gmail.com			
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC		Phone (610) 278-7203		Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621		Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462		(6.0) = 0.0		Mountains (West of I-77): Yes	
	W	ebsite <u>www.crompco.com</u>		widulitailis (West of 1-77). Tes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling: Soil and Water Testing Lab:	No No	Waste Disposal and Treatment: Other:	No		

UST Service Provider List (Coastal)	
Company Listing Submitted 9/24/2021 Area of state co	onducts work
C-Store Services, Inc. Phone (919) 662-0798 Coastal	(East of I-95): Yes
7129 Hidden Valley Trail Fax (919) 662-0711 Central (West of I-95 and	d East of I-77): Yes
Garner, NC 27529 Mountains	(West of I-77): No
Website	` ,
Compliance Testing and Monitoring UST Equipmment Se	ervice Contractors
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: <u>Yes</u> Dispenser Meter Repair/Calibrate	
Containment Sump Testing: Yes Statistical Iventory Reconciliation Services: No Leak Detection Equipment Insta	•
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Spill Bucket Installation Repair:	Yes Yes
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Otto	ther: Yes
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Comp	olete Systems: No
Leak Detection Monitoring Services: No Other: UST-27 monthly inspection UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing: No UST System Removal:	<u>Yes</u>
Environmental Service Firms Other:	
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No	
Oil and Solvent Recycling: No Other:	
Soil and Water Testing Lab: No	
Company Listing Culmitted 0/20/2022 Area of state of	
Company Listing Submitted 9/28/2022 Area of state co	onducts work
	onducts work (East of I-95): Yes
D. H. Griffin Wrecking Company 4716 Hilltop Road Phone (336) 214-9012 Coastal Fax Central (West of I-95 and	(East of I-95): Yes
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Phone (336) 214-9012 Coastal Central (West of I-95 and	(East of I-95): Yes d East of I-77): Yes
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Phone (336) 214-9012 Coastal Central (West of I-95 and	(East of I-95): Yes
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Phone (336) 214-9012 Coastal Central (West of I-95 and Mountains	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Phone (336) 214-9012 Fax Website www.dhgriffin.com Coastal Central (West of I-95 and Mountains)	d East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Coastal Central (West of I-95 and Mountains of Mountains of Mountains of Mountains of Compliance Testing and Monitoring UST Equipmment Se	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibrate	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibrat Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Insta	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Containment Sump Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibrat Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Bucket Installation Repair:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Containment Sump Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibrat Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Ott	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Dispenser Meter Repair/Calibrate Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: No UST Equipment Installation - Ott Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: Leak Detection Monitoring Services: No UST System Removal: No UST Piping/Sump Installation: UST System Removal:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Repairs: No UST Internal Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation: No UST Spilm Protections: No UST System Installation: No UST Piping/Sump Installation:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections: No UST Internal Lining Inspections: No UST System Installation - Computer No UST Piping/Sump Installation: UST Piping/Sump Installation: UST Piping/Sump Installation: UST Piping/Sump Installation: UST System Removal:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibrat Containment Sump Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Comp Leak Detection Equipment Operability Check: No Other: Environmental Service Firms Constal Containment Sump Testing: No Dispenser Meter Repair/Calibrat Leak Detection Design Experts: No Dispenser Meter Repair/Calibrat Leak Detection Design Experts: No Spill Bucket Installation Equipment Installation - Other: UST Equipment Installation - Other: UST System Installation - Comp UST System Installation: UST System Removal: Other:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Wountains UST Equipment Set Containment Set Containment Sump Testing: No Overfill Prevention Equipment Operability Check: No Leak Detection Equipment Insta Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Equipment Installation - Othen Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Comp UST System Installation - Comp UST System Removal: UST System Removal: Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407 Website www.dhgriffin.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibrat Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Insta Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Repair: Leak Detection Monitoring Services: No Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Service No UST Equipment Verification: No UST Equipment Service No UST Equipment Service No UST Equipment Service No UST Equipment Service No UST System Removal: Other:	(East of I-95): Yes d East of I-77): Yes (West of I-77): Yes ervice Contractors tion: No allation Servicing: No ther: No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	4/6/2023	Area of state conducts work	
East Coast Environmental, PA		Phone (919) 349-5969		Coastal (East of I-95): Yes	
3815 Junction Boulevard		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh , NC 27603				Mountains (West of I-77): No	
	W	/ebsite eastcoastenv.com			
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
-					
Company		Listing Submitted	4/5/2023	Area of state conducts work	
Company East Coast Environmental, PA		Phone (919) 349-5969	4/5/2023	Area of state conducts work Coastal (East of I-95): Yes	
East Coast Environmental, PA 3815 Junction Boulevard		Phone (919) 349-5969	4/5/2023	Coastal (East of I-95): Yes	
East Coast Environmental, PA			4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
East Coast Environmental, PA 3815 Junction Boulevard	w	Phone (919) 349-5969	4/5/2023	Coastal (East of I-95): Yes	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603		Phone (919) 349-5969 Fax	4/5/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603		Phone (919) 349-5969 Fax /ebsite eastcoastenv.com	4/5/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603	pliance Test	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No Yes
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comparison Leak Detector Testing:	pliance Test No	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Test No No	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Test No No No	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	<u>Yes</u> <u>Yes</u>
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes Yes No
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes No Yes
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes No Yes
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No N	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes
East Coast Environmental, PA 3815 Junction Boulevard Raleigh, NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 349-5969 Fax /ebsite eastcoastenv.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes No Yes

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
EnviroTrac Ltd.		Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Suite J Greensboro, NC 27410				Mountains (West of I-77): Yes	
Greensboro, NC 27410		Website envirotrac.com			
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	1/3/2022	Area of state conducts work	
Company Evo Corporation		Phone (336) 725-5844	1/3/2022	Area of state conducts work Coastal (East of I-95): Yes	
Evo Corporation 1703 Vargrave Street			1/3/2022		
Evo Corporation		Phone (336) 725-5844 Fax	1/3/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Evo Corporation 1703 Vargrave Street		Phone (336) 725-5844	1/3/2022	Coastal (East of I-95): Yes	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107		Phone (336) 725-5844 Fax	1/3/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107		Phone (336) 725-5844 Fax Website www.evocorp.net	1/3/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Te	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	,
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Te	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No No	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107 Composition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 725-5844 Fax Website www.evocorp.net sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: utal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No No Vo	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No

		UST Service Provider List (Co	oastal)		
Company		Listing Submitted	7/12/2023	Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800		Coastal (East of I-95): Yes	;
625 Huntsman Court		Fax (704) 853-3949		Central (West of I-95 and East of I-77): Yes	;
Gastonia, NC 28054	10	Valacita		Mountains (West of I-77): Yes	;
	V\	Vebsite <u>www.excelengr.com</u>			
Comp	pliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Eı	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
Company Excel Environmental Associates, PLLC		Phone (704) 853-0800	11/1/2023	Area of state conducts work Coastal (East of I-95): Yes	i
Excel Environmental Associates, PLLC 625 Huntsman Court			11/1/2023		
Excel Environmental Associates, PLLC	10	Phone (704) 853-0800 Fax (704) 853-3949	11/1/2023	Coastal (East of I-95): Yes	;
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	;
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	;
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparing Automatic Line Leak Detector Testing:		Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check:	11/1/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	;
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Test	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	;
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Test	Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No N	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 853-0800 Fax (704) 853-3949 Vebsite www.excelengr.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No

		UST Service Provider List (Coastal)		
Company		Listing Submi	tted 1/1/2022	Area of state conducts work	
Galloway		Phone (303) 770-8884		Coastal (East of I-95): Yes	i
6162 South Willow Drive		Fax (303) 770-3636		Central (West of I-95 and East of I-77): Yes	;
Suite 320 Greenwood Village, CO 80111		Website www.Gallowayus.com		Mountains (West of I-77): Yes	i
Comr	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: UST/AST Sy	stem Design	UST Piping/Sump Installation:	No
Line Tightness Testing:	No	·	-	UST System Removal:	No
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other: UST/AST Sy.	stem Design		
Soil and Water Testing Lab:	No		-		
Company		Listing Submi	tted 12/30/2021	Area of state conducts work	
Company Geo-Hydro Engineers, Inc.		Listing Submi Phone (704) 837-7174	tted 12/30/2021	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (704) 837-7174	tted 12/30/2021	Coastal (East of I-95): Yes	
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A			tted 12/30/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	;
Geo-Hydro Engineers, Inc. 2748 Interstate Street		Phone (704) 837-7174	tted 12/30/2021	Coastal (East of I-95): Yes	;
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208		Phone (704) 837-7174 Fax	tted 12/30/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	;
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208		Phone (704) 837-7174 Fax Website www.geohydro.com	12/30/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	;
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp	oliance Te	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Compa	oliance Te No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 837-7174 Fax Website www.geohydro.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST	Service Provider Lis	st (Coa	astal)		
Company			Listing Su	bmitted	1/3/2022	Area of state conducts work	
Geological Resources, Inc.		Phone	(704) 845-4010			Coastal (East of I-95): Yes	
3502 Hayes Road		Fax	(704) 845-4012			Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28112						Mountains (West of I-77): Yes	
		Website	grienv.com			,	
Comp	oliance Te	esting and	Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Operability Che	eck:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	al Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Int	ernal Inspections (Integrity Assessme	nts):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Int	ernal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Servic	e Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Co	empliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	Yes		uipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu			Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						
Company			Listing Su	bmitted	11/16/2023	Area of state conducts work	
Groundwater Management Associates, Inc.		Phone	(252) 758-3310			Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax	,			Central (West of I-95 and East of I-77): Yes	
Suite 100		Tux					
Greenville, NC 27834		Website	www.gma-nc.com			Mountains (West of I-77): Yes	
Comp	oliance Te	esting and	Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Operability Che	eck:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	al Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Int	ernal Inspections (Integrity Assessme	nts):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Int	ernal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Servic	e Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	empliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>		uipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste I	Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

		UST	Service Provider List	t (Coastal)		
Company			Listing Sub	mitted 10/26/2021	Area of state conducts work	
Guardian Fueling Technologies		Phone	(919) 729-6980		Coastal (East of I-95): Yes	
5116 Departure Drive		Fax	(919) 769-2919		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616					Mountains (West of I-77): No	
	V	Website	www.guardianfueltech.com		,	
Comp	pliance Tes	sting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill I	Prevention Equipment Operability Check	k: <u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistic	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No		evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No		ghtness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No		ernal Inspections (Integrity Assessment	ts): No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Inte	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	SafeGuard UST Insp	ection Services	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	No
E	nvironment	tal Servic	ce Firms		Other: FuelGuard fuel polishing / tank of	cleaning
Emergency Cleanup - Spill/Release:	No	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste D	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Sub	mitted 1/25/2022	Area of state conducts work	
Company HARCO Services LLC		Phone	Listing Sub (770) 917-8846	mitted 1/25/2022	Area of state conducts work Coastal (East of I-95): Yes	
HARCO Services LLC PO Box 2347			(770) 917-8846	mitted 1/25/2022	Coastal (East of I-95): Yes	
HARCO Services LLC		Phone Fax		mitted 1/25/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
HARCO Services LLC PO Box 2347	V		(770) 917-8846	mitted 1/25/2022	Coastal (East of I-95): Yes	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156		Fax Website	(770) 917-8846 (770) 917-0921	mitted 1/25/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156		Fax Website sting and	(770) 917-8846 (770) 917-0921 www.harcoservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comp	pliance Tes	Fax Website sting and Overfill	(770) 917-8846 (770) 917-0921 www.harcoservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of the Comparison of t	pliance Tes No	Fax Website sting and Overfill I Statistic	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Check	·k: No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes No No	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	ck: No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Tes No No No	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Interest of the Company of the Com	ck: No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	ck: No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No N	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Interest of the Company of the Com	k: No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No Yes Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Interest of the Company of the Com	k: No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Website Sting and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessment: ernal Lining Inspections:	k: No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No Yes Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Checked Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessment: ernal Lining Inspections:	k: No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No Yes Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Corrosion Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other: tal Servic UST Co	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Check all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessment ernal Lining Inspections:	k: No No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No Yes Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other: tal Servic UST Co UST Eq	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Check all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessment ernal Lining Inspections: ce Firms compliance Consultants:	k: No No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No Yes Yes
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other: tal Servic UST Co UST Eq	(770) 917-8846 (770) 917-0921 www.harcoservices.com Monitoring Prevention Equipment Operability Check all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessment ernal Lining Inspections: ce Firms cmpliance Consultants: puipment Verification:	k: No No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No Yes Yes

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Highlands Environmental Solutions, Inc.		Phone (919) 848-3155		Coastal (East of I-95): Yes	
8410-d Falls of Neuse		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615				Mountains (West of I-77): Yes	
		Website www.HESfast.com		,	
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/11/2023	Area of state conducts work	
INENCO, Inc.		Phone (704) 662-8192		Coastal (East of I-95): Yes	
132 W. Statesville Avenue		Fax (704) 662-8194		Central (West of I-95 and East of I-77): Yes	
Mooresville, NC 27115				Mountains (West of I-77): Yes	
		Website		would all s (west of 1-77).	
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List (Co	oastai)		
Company		Listing Submitted		Area of state conducts work	
JF Petroleum Group		Phone (919) 744-4391		Coastal (East of I-95): Yes	
100 Perimeter Park Drive		Fax		Central (West of I-95 and East of I-77): Yes	;
Suite H				Mountains (West of I-77): Yes	
Morrisville, NC 27560		Website jfpetrogroup.com/services/environmental	<u>lcompliance</u>	mountains (vost of 177).	
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/5/2022	Area of state conducts work	
Johnson, Spellman & Associates, Inc.		Phone (770) 447-4555		Coastal (East of I-95): Yes	i
350 Research Ct.		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 130					
Peachtree Corners, GA 30092		Website		Mountains (West of I-77): Yes	
		Website sting and Monitoring		UST Equipmment Service Contractors	
·			<u>Yes</u>		No
Comp	pliance Te	sting and Monitoring	<u>Yes</u> No	UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	pliance Te	esting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Engineering- Design S	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Engineering- Design Sental Service Firms	No No No No No Services	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Engineering- Design S	No No No No Services	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Engineering- Design S	No No No No Services Yes Yes No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted		Area of state conducts work	
Jones Covey Group		Phone	(888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax	(909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730			,		Mountains (West of I-77): Yes	
	We	ebsite				
Comp	oliance Testi	ng and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill I	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistic	al Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:			ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			ernal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:			ernal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:		Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental	I Servic	e Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	mpliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste D	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	1/31/2022	Area of state conducts work	
Company McCallum, P.C.	ı	Phone		1/31/2022	Area of state conducts work Coastal (East of I-95): Yes	
McCallum, P.C. 1808 Hayward Avenue	ı	Phone Fax	(757) 420-9252	1/31/2022	Coastal (East of I-95): Yes	
McCallum, P.C.	ı	_	(757) 420-9252 (757) 424-2874	1/31/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
McCallum, P.C. 1808 Hayward Avenue		_	(757) 420-9252	1/31/2022	Coastal (East of I-95): Yes	
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320		Fax ebsite	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com	1/31/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320	We	Fax ebsite ing and	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com	1/31/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comp	We pliance Testin No	Fax ebsite ing and Overfill	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparison Compariso	We pliance Testin No No	Fax ebsite ng and Overfill I Statistic	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparison of the Compariso	We Dliance Testin No No No	ebsite ing and Overfill I Statistic Spill Pre	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparition of the comparities	We pliance Testin No No No No No	ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No No	ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparition of the same of the s	No No No No No No No No No No	Fax ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Fax ebsite Ing and Overfill I Statistics Spill Pre Tank Tig UST Inte UST Inte Other:	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other: I Servic UST Co	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other: I Servic UST Co UST Eq	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
McCallum, P.C. 1808 Hayward Avenue Chesapeake, VA 23320 Comparition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	ebsite Ing and Overfill I Statistic Spill Pre Tank Tig UST Inte UST Inte Other: I Servic UST Co UST Eq	(757) 420-9252 (757) 424-2874 www.mccallumtestinglabs.com Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: EE Firms Impliance Consultants: uipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Coastal)		
Company		Listing Submitt		Area of state conducts work	
Mid-Atlantic Associates, Inc.		Phone (919) 250-9918		Coastal (East of I-95): Yes	
409 Rogers View Ct		Fax (919) 250-9950		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27610		(,		Mountains (West of I-77): Yes	
	,	Website www.maaonline.com			
Com	pliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitt	ed 12/30/2021	Area of state conducts work	
Company NCPCM			red 12/30/2021		
		Phone (919) 782-4411	red 12/30/2021	Coastal (East of I-95): Yes	
NCPCM			ed 12/30/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
NCPCM 7300 glenwood ave.	,	Phone (919) 782-4411	ed 12/30/2021	Coastal (East of I-95): Yes	
NCPCM 7300 glenwood ave. raleigh, NC 27612		Phone (919) 782-4411 Fax (919) 782-4414	ed 12/30/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
NCPCM 7300 glenwood ave. raleigh, NC 27612		Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org	ed 12/30/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
NCPCM 7300 glenwood ave. raleigh, NC 27612	pliance Tes	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing:	pliance Tes	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No No No	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes No No No No	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
NCPCM 7300 glenwood ave. raleigh, NC 27612 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Coastal)		
Company		Listing Submit	tted 5/14/2021	Area of state conducts work	
Petroleum Solutions Inc.		Phone (919) 605-1979		Coastal (East of I-95): Yes	s
3012 Whitehart Ln.		Fax (919) 773-1704		Central (West of I-95 and East of I-77): Yes	s
819 Purser Drive		,		Mountains (West of I-77): No	
Raleigh, NC 27606	'	Website <u>www.petroleumsolutionsinc.net</u>		mountaine (trooter 117). He	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submit	tted 3/31/2022	Area of state conducts work	
Company Petroleum Tec		Phone (980) 781-1000	tted 3/31/2022	Area of state conducts work Coastal (East of I-95): Yes	s
Petroleum Tec 5420 Powerhouse Ct			3/31/2022	Coastal (East of I-95): Yes	
Petroleum Tec		Phone (980) 781-1000 Fax	3/31/2022	Coastal (East of I-95): Yes	s
Petroleum Tec 5420 Powerhouse Ct	,	Phone (980) 781-1000	3/31/2022	Coastal (East of I-95): Yes	s
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027		Phone (980) 781-1000 Fax	10 3/31/2022	Coastal (East of I-95): Yes	s s
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027		Phone (980) 781-1000 Fax Website www.petroleumtec.com	3/31/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	s s
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027	oliance Tes	Phone (980) 781-1000 Fax Website www.petroleumtec.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	s s
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Compa	oliance Tes No	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	s s No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	s s s No No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	S S NO NO NO
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	S S S NO NO NO NO
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	NO NO NO NO NO
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Ta	No No No No No ank Cleaning	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Ta tal Service Firms UST Compliance Consultants:	No No No No No No ank Cleaning	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No No
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (980) 781-1000 Fax Website www.petroleumtec.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Ta tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No ank Cleaning	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No No

		UST Service Provider List (Co	oastal)		
Company		Listing Submitted		Area of state conducts work	
Pilot Geological , PLLC		Phone (336) 870-3095		Coastal (East of I-95): Yes	
PO Box 128		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
743 Park Lawn Court Kernersville, NC 27285	14	delicate a constitute and a cons		Mountains (West of I-77): Yes	
Tromorovino, Tro 27200	V\	Vebsite www.pilotenviro.com		,	
Comp	oliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/20/2023	Area of state conducts work	
Practical Environmental Solutions		Phone (910) 790-8265		Coastal (East of I-95): Yes	
5634 Harvest Grove Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28049				Mountains (West of L-77): No	
Wilmington, NC 28049	W	Vebsite www.oil-tank.com		Mountains (West of I-77): No	
				Mountains (West of I-77): No UST Equipmment Service Contractors	
		Vebsite www.oil-tank.com	No		No
Сотр	oliance Test	Vebsite www.oil-tank.com	No No	UST Equipmment Service Contractors	No No
Comp Automatic Line Leak Detector Testing:	oliance Test No	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No N	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Vebsite www.oil-tank.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No Yes

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Practical Environmental Solutions. PC		Phone (910) 790-8265		Coastal (East of I-95): Yes	
5634 Harvest Grove Ln		Fax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28409				Mountains (West of I-77): No	
	W	Vebsite www.oil-tank.com		,	
Comp	oliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	-		
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service		Phone (704) 892-8600		Coastal (East of I-95): Yes	
737 Zimmer Road		,			
Fort Mill , SC 29707		Fax (704) 892-8711		Central (West of I-95 and East of I-77): Yes	
	W	Vebsite www.precisiontankservice.com		Mountains (West of I-77): Yes	
Comp	oliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:					
Son and water resting Lab.	No		I		

		UST Service Provider List (C	oastal)		
Company		Listing Submitted		Area of state conducts work	
Pyramid Environmental & Engineering, PC		Phone (336) 335-3174		Coastal (East of I-95): Yes	
503 Industrial Avenue		Fax (336) 691-0648		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27406		Website		Mountains (West of I-77): Yes	
		Website www.PyramidEnvironmental.com			
Com	pliance T	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironme	ental Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	4/4/2023	Area of state conducts work	
Regional Environmental PLLC		Phone (704) 694-8359		Coastal (East of I-95): Yes	
9016 Hazel Forest Drive		Phone (704) 694-8359 Fax			
				Central (West of I-95 and East of I-77): Yes	
9016 Hazel Forest Drive					
9016 Hazel Forest Drive Fuquay Varina, NC 27526	pliance T	Fax		Central (West of I-95 and East of I-77): Yes	
9016 Hazel Forest Drive Fuquay Varina, NC 27526	pliance T No	Fax Website www.regionalenv.com	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
9016 Hazel Forest Drive Fuquay Varina, NC 27526		Fax Website www.regionalenv.com esting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing:	No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No Tronme No Yes	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
9016 Hazel Forest Drive Fuquay Varina, NC 27526 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: E Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Tronme	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ental Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Tronme	Fax Website www.regionalenv.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ental Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company Listing Submitted 12/30/2021 Area of state conducts work Coastal (East of I-95); Yes Singleton Environmental, Inc. Phone (828) 508-4510 Fax Website singleton environmental com Website singleton environmental environmental com Website singleton environmental			UST Service Provider L	ist (Coastal)		
Po Box 604 Feltcher, NC 28732 Website singletonenvironmental.com Compliance Testing and Monitoring Automatic Line Leak Detection Persperting and Monitoring Automatic Line Leak Detection Repairs: No Overlianner Sump Testing: No Statistical Ventroly Reconciliation Services: No Spill Prevention Equipment Operability Check: No Spill Prevention Equipment Resting: No Spill Sucket Installation Repairs: No Spill Sucket Installation Repairs: No Spill Sucket Installation Complete Systems: No UST Installation Repairs: No UST System Installation - Complete Systems: No UST System Removal: No UST System Remo	Company		Listing \$	Submitted 12/30/2021	Area of state conducts work	
Website Singletonenvironmental.com Workship W	Singleton Environmental, Inc.		Phone (828) 508-4510		Coastal (East of I-95): Yes	s
Website Singletonenvironmental.com Single			Fax		Central (West of I-95 and East of I-77): Yes	s
Compliance Testing and Monitoring	Fletcher, NC 28732				Mountains (West of I-77): Yes	S
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Cortainment Sump Testing: No Ostatistical Ventory Accordiation Services: No Corrosion Protection Design Experts: No Osphil Prevention Equipment Testing: No Corrosion Protection Design Experts: No Osphil Prevention Equipment Testing: No Ostrosion Protection System Repairs: No Ostrosion Protection System Statistical Ventory Reposition System Repairs: No Ostrosion Protection Design Experts: No Ostrosion Protection Design Experts: No Ostrosion Protection System Repairs: N		W	ebsite singletonenvironmental.com			
Contrainment Sump Testing: No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Installation Servicing: No Spill Buckat Installation Repair: No Spill Buckat Installation Repair: No UST Equipment Installation Other: No UST Equipment Repair: No Other: Emergency Cleanup - Spill/Release: Fax (910) 763-6274 Fax (910) 763-6274 Fax (910) 763-6274 Fax (910) 763-6132 Fax (Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	•
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tark Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repairs: No UST Equipment Compile Installation - Other: No UST Equipment Repairs: No UST Equipment Repair: No UST Equipment Repairs: No UST Equipment Repair: No UST Equipment Equipment Repair: No UST Equipment Equipment Repair: No UST Equipment Equipment Equipment Repair: No UST Equipment Equipment Equipment Repair: No UST Equipment Equ	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability C	heck: No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Removal: No UST System Removal: No UST System Removal: No UST System Removal: No Other: Emurgency Cleanup - Spill/Release: No UST Compliance Consultants: No Other: No Oth	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections: (Integrity Assessments): No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation: Complete Systems: No UST System Installation: Complete Systems: No UST System Installation: Complete Systems: No UST System Installation: No UST Internal Installation: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation: No UST Equipment Service Contractors Company	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST Pyping/Sump Installation - Complete Systems: No UST System Removal: No U	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: No Other: No Other: Company SRR Environmental Inc. SRR Environment	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessm	nents): No	UST Equipment Repair:	No
Line Tightness Testing: No Environmental Service Firms	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Environmental Service Firms Emergency Cleanup - Spill/Releases: No UST Compliance Consultants: No No UST Compliance Consultants: No No UST Compliance Consultants: No No UST Equipment Verification: No No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Internal Lining Inspections: No UST Equipment Verification: No UST Equipment Internal Lining Submitted 6/29/2021 Area of state conducts work Company Listing Submitted 6/29/2021 Area of state conducts work Coastal (East of I-95): Yes Coastal (East of I-95): Yes Verification: No Ust Internal Lining Inspections: No Ust Internal Lining Inspections: No Ust Equipment Internal Lining Inspections: No Ust Equipment Internal Lining Inspections: No Ust Equipment Repair: No Ust Equipment Repair: No Ust System Installation: No Ust Equipment Internal Lining Inspections: No Ust Equipment Installation: No Ust Piping/Sump Installation: No Ust Equipment Installation Repair: No Ust Equipment Installation Repair: No Ust Equipment Installation Complete Systems: No Ust Equipment Installation Complete Systems: No Ust Equipment Installation: No Ust Internal Lining Inspections: No Ust Equipment Installation Complete Systems: No Ust Piping/Sump Installation: No Ust System Installation: No Ust System Installation: No Ust Equipment Perification: No Ust Equipment Perification: No Ust Equipment Perification: No Ust Equipment Perification: No Ust Equipment Repair: No Ust System Installation Complete Systems: No Ust System Installation: No U	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No UST System Repair: N	Line Tightness Testing:	No			UST System Removal:	No
Environmental Engineer/Geologist - Site Checks: Yes Waste Disposal and Treatment: No Other: O	Er	nvironmenta	al Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu Yes No Other: Soil and Solvent Recycling: Soil and Water Testing Lab: Company SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401- Website www.srrenviro.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconcillation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Linepsections (Integrity Assessments): No UST Internal Lining Inspections: No UST System Removal: No UST System R	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Oil and Solvent Recycling: Soil and Water Testing Lab: No Company Elisting Submitted 6/29/2021 Area of state conducts work Costal (East of I-95): Yes 4920 Highway 421 N. Wilmington, NC 28401- Website www.srrenviro.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Cortainment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No Leak Detection Monitoring UST Equipment Service Website www.srrenviro.com UST Equipment Service Contractors No Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST System Installation: No UST Equipment System: No UST System Installation: No UST System Removal: UST System Removal: UST System Removal: UST System Removal: Other: Environmental Engineer/Geologist - Side Checks: No UST Equipment Verification: No Ust Equipment Verification: No Ust Equipment Verification: No Ust Equipment Repair: Other: Vacuum Truck Services	Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Soil and Water Testing Lab: No No		Yes		No		
Company R&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401- Website www.srrenviro.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Brucket Installation Repair: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Internal Inspections: No UST System Installation - Complete Systems: No Other: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: No Waste Disposal and Treatment: Yes Other: Vacuum Truck Services	Oil and Solvent Recycling:	No	Other:			
SR&R Environmental, Inc. 4920 Highway 421 N. Wilmington, NC 28401- Compliance Testing and Monitoring Lust Equipment Service Contractors No Overfill Prevention Equipment Operability Check: No Corrosion Protection System Repairs: No UST Internal Lining Inspections: No UST Equipment Operability Check: No Leak Detector Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment Operability Check: No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Piping/Sump Installation Complete Systems: No UST System Removal: Yes Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Oil and Solvent Recycling: Yes Other: Vacuum Truck Services	Soil and Water Testing Lab:	No				
4920 Highway 421 N. Wilmington, NC 28401- Website www.srrenviro.com Website www.srrenviro.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Octainment Sump Testing: No Statistical Iventory Reconciliation Services: No Ocrrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections: No UST Internal Inspections: No UST Internal Inspections: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Other: No UST System Installation: No UST Piping/Sump Installation: No UST System Removal: Yes UST System Removal: Yes Other: Vacuum Truck Services	Company		Listing S	Submitted 6/29/2021	Area of state conducts work	
Website www.srrenviro.com Website www.srrenviro.com Website www.srrenviro.com Website www.srrenviro.com Mountains (West of I-77): No Website www.srrenviro.com Mountains (West of I-77): No Website www.srrenviro.com Mountains (West of I-77): No Website www.srrenviro.com Website www.srrenviro.com Mountains (West of I-77): No Website www.srrenviro.com Website www.srrenviro.com Website www.srrenviro.com Mountains (West of I-77): No Website www.srrenviro.com Website www.srrenviro.com Wountains (West of I-77): No Website www.srrenviro.com No Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Servicing: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: UST System Removal: Yes Other: West Other: Vacuum Truck Services Waste Disposal and Treatment: Yes Other: Vacuum Truck Services	SR&R Environmental, Inc.		Phone (910) 763-6274		Coastal (East of I-95): Yes	S
Website www.srrenviro.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation Servicing: No UST Equipment Installation Poperation Repair: No UST Equipment Installation Poperation Repair: No UST Equipment Installation Poperation Repair: No UST Equipment Installation Poperation No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes UST System Removal: Yes Other: Vacuum Truck Services			Fax (910) 763-6132		Central (West of I-95 and East of I-77): Yes	s
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Ocorrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Lining Inspections: No Other: Environmental Service Firms Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Other: Vacuum Truck Services UST Equipment Service Contractors Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Leak Detection Equipment Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Installation - Other: UST Equipment Installation - Other: UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Other: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Other: Vacuum Truck Services	Wilmington, NC 28401-		(6.6) 166 6.62			
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: UST System Removal: UST System Removal: UST System Removal: Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Repair: No UST System Removal: Other: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Other: Vacuum Truck Services		W	debsite www.srrenviro.com		Wouldains (West of 1-77). No	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: Line Tightness Testing: No Other: Environmental Service Firms Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: Vacuum Truck Services: No Spill Prevention Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Removal: Yes Other: Vacuum Truck Services	Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	•
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No Leak Detection Monitoring Services: No Other: No UST Internal Lining Inspections: No UST Piping/Sump Installation - Complete Systems: No Line Tightness Testing: No UST Compliance Consultants: No UST System Removal: Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Verification: Vacuum Truck Services	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability C	heck: No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection System Testing: No UST Internal Lining Inspections: No UST Equipment Repair: No Leak Detection Monitoring Services: No Other: UST System Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: UST System Installation: No UST System Installation: No UST System Removal: Yes Corrosion Protection System Repairs: No UST Equipment Protection: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes Corrosion Protection System Repair: No UST Equipment Protection: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes Corrosion Protection System Testing: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Coll and Solvent Recycling: Yes Other: Vacuum Truck Services Vacuum Truck Service Vacuum Tr	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No Other: UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: UST System Installation: No UST System Removal: Ves Other: Other: Other: Other: Vacuum Truck Services	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No Leak Detection Monitoring Services: No Other: UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: Yes Other: Other: Value UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation - Complete Systems: No UST System Installation: UST System Installation: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Installation: UST System Installation:	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: Ves UST System Removal: Yes Other: UST Piping/Sump Installation: No UST System Removal: Yes Other: Other: Valuation: No UST System Removal: Yes Other: Valuation: No UST Piping/Sump Installation: No UST System Removal: Yes Other: Valuation:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessm	nents): No	UST Equipment Repair:	No
Line Tightness Testing: Environmental Service Firms	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Environmental Service Firms Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Oil and Solvent Recycling: Yes Other: Vacuum Truck Services	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Oil and Solvent Recycling: Vacuum Truck Services	Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Oil and Solvent Recycling: Yes Other: Vacuum Truck Services	Er	nvironmenta	al Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Oil and Solvent Recycling: Yes Other: Vacuum Truck Services	Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Oil and Solvent Recycling: Yes Other: Vacuum Truck Services	Environmental Engineer/Geologist - Site Checks:		UST Equipment Verification:	No		
	Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	<u>Yes</u>		
Soil and Water Testing Lab: No	Oil and Solvent Recycling:	Yes	Other: Vac	uum Truck Services		
	The state of the s					

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING		Phone (813) 671-9065		Coastal (East of I-95): Yes	
451 APOLLO BEACH BOULEVARD		Fax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	
APOLLO BEACH, FL 33572	١	Website <u>WWW.VALLEYTANK.COM</u>		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Er	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/31/2023	Area of state conducts work	
Company Valor Construction LLC		Phone (205) 577-1035	1/31/2023	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (205) 577-1035	1/31/2023	Coastal (East of I-95): Yes	
Valor Construction LLC			1/31/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Valor Construction LLC PO Box 680654	\	Phone (205) 577-1035	1/31/2023	Coastal (East of I-95): Yes	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968		Phone (205) 577-1035 Fax	1/31/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968		Phone (205) 577-1035 Fax Website	1/31/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Tes	Phone (205) 577-1035 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Tes No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (205) 577-1035 Fax Nebsite Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No Yes
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (205) 577-1035 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparition Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (205) 577-1035 Fax Nebsite Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Stal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (205) 577-1035 Fax Nebsite Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No <u>Yes</u> <u>Yes</u>

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted	10/5/2021	Area of state conducts work	
VITAL FUEL SYSTEMS INC.		Phone (919) 303-7374		Coastal (East of I-95): Yes	
1076 CLASSIC ROAD		Fax (919) 303-7399		Central (West of I-95 and East of I-77): Yes	
APEX, NC 27540				Mountains (West of I-77): Yes	
	1	Website WWW.VITALFUELSYSTEMS.COM			
Com	pliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/1/2023	Area of state conducts work	
• •			11/1/2023		
Company Withers Ravenel, Inc. 115 MacKenan Drive		Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
Withers Ravenel, Inc.			11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Withers Ravenel, Inc. 115 MacKenan Drive	,	Phone (919) 469-3340	11/1/2023	Coastal (East of I-95): Yes	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340 Fax	11/1/2023	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340 Fax Website www.withersravenel.com	11/1/2023 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591	pliance Tes	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Compariso	pliance Tes	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591 Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No