

UST Service Provider List (Mountains)

Company		Listing Submitted		1/18/2024		Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438		Phone (336) 282-3586 Fax (336) 282-3587 Website AdadvancedEnvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		5/17/2021		Area of state conducts work	
AES of Greenville LLC 141 S. Market Street Washington, NC 27889		Phone (252) 758-3311 Fax (252) 481-5814 Website www.aes-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	Yes			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company			Listing Submitted	4/15/2021	Area of state conducts work
American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510			Phone (919) 777-8543 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	5/17/2021	Area of state conducts work
Apex Engineering, PC 15850 Crabbs Branch Way Suite 200 Rockville, Maryland 20855-			Phone (301) 417-0200 Fax (301) 975-0169 Website www.apexc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				

UST Service Provider List (Mountains)

Company		Listing Submitted		7/19/2022		Area of state conducts work	
B & M WEST CONSTRUCTION CO OF TEXAS DBA D. 209 E BADCOCK BLVD MULBERRY, FL 33860		Phone (863) 519-4441 Fax (863) 519-4407 Website DWSHOUPE.COM				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		1/10/2022		Area of state conducts work	
Bunnell-Lammons Engineering, Inc. 130 Oval Road Arden, NC 28704		Phone (828) 277-0100 Fax (828) 277-0110 Website www.blecorp.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	Yes			UST System Removal:		No	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:	Trust Fund Projects				
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Cathodic Protection Services, Inc. 916 Egypt Rd. Bluff City, NC 37618		Phone (423) 895-1500 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		4/5/2023		Area of state conducts work	
CDG, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913 Fax Website www.cdge.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

UST Service Provider List (Mountains)

Company				Listing Submitted	5/26/2021	Area of state conducts work	
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806		Phone (828) 505-6301 Fax Website				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc. P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804		Phone (662) 841-0995 Fax (662) 841-0810 Website www.cobbenv.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/21/2023		Area of state conducts work	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678		Phone (704) 560-9154 Fax Website benconklincc@gmail.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		10/11/2023		Area of state conducts work	
Conklin Corrosion Control LLC 118 Oak Point Lane Stony Point, NC 28678		Phone (704) 560-9154 Fax Website benconklincc@gmail.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462		Phone (610) 278-7203 Fax (610) 278-7621 Website www.crompco.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company		Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company 4716 Hilltop Road Greensboro, NC 27407		Phone (336) 214-9012 Fax Website www.dhgriffin.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:	Vacuum Truck Services		
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	1/4/2022	Area of state conducts work	
EnviroTrac Ltd. 7343 West Friendly Avenue Suite J Greensboro, NC 27410		Phone (336) 763-6025 Fax Website envirotrac.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company				Listing Submitted	1/3/2022	Area of state conducts work	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107		Phone (336) 725-5844 Fax Website www.evocorp.net				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other: Vacuum Truck Services			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Transportation Services				
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone (704) 853-0800 Fax (704) 853-3949 Website www.excelengr.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		7/12/2023		Area of state conducts work		
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone	(704) 853-0800				Coastal (East of I-95):	Yes
		Fax	(704) 853-3949				Central (West of I-95 and East of I-77):	Yes
		Website	www.excelengr.com				Mountains (West of I-77):	Yes
Compliance Testing and Monitoring						UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No		
Line Tightness Testing:	No			UST System Removal:		No		
Environmental Service Firms						Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes					
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	No							

UST Service Provider List (Mountains)

Company		Listing Submitted		1/1/2022		Area of state conducts work	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111		Phone (303) 770-8884 Fax (303) 770-3636 Website www.Gallowayus.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	UST/AST System Design	UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	UST/AST System Design				
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208		Phone (704) 837-7174 Fax Website www.geohydro.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		1/3/2022		Area of state conducts work	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28112		Phone (704) 845-4010 Fax (704) 845-4012 Website grienv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/16/2023		Area of state conducts work	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone (252) 758-3310 Fax Website www.gma-nc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	1/25/2022	Area of state conducts work	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156		Phone (770) 917-8846 Fax (770) 917-0921 Website www.harcoservices.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	12/30/2021	Area of state conducts work	
Highlands Environmental Solutions, Inc. 8410-d Falls of Neuse Raleigh, NC 27615		Phone (919) 848-3155 Fax Website www.HESfast.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms							
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Highlands Environmental Solutions, Inc. 8410-d Falls of Neuse Raleigh, NC 27615		Phone (919) 848-3155 Fax Website www.HESfast.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted		4/11/2023		Area of state conducts work	
INENCO, Inc. 132 W. Statesville Avenue Mooresville, NC 27115				Phone (704) 662-8192 Fax (704) 662-8194 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		5/15/2023		Area of state conducts work	
JF Petroleum Group 100 Perimeter Park Drive Suite H Morrisville, NC 27560				Phone (919) 744-4391 Fax Website jfpetrogroup.com/services/environmentalcompliance		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>			Dispenser Meter Repair/Calibration:	<u>Yes</u>		
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	<u>Yes</u>		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>			Spill Bucket Installation Repair:	<u>Yes</u>		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>			UST Equipment Installation - Other:	<u>Yes</u>		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	<u>Yes</u>		
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	<u>Yes</u>		
Leak Detection Monitoring Services:	<u>Yes</u>	Other:				UST Piping/Sump Installation:	<u>Yes</u>		
Line Tightness Testing:	<u>Yes</u>					UST System Removal:	<u>Yes</u>		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

UST Service Provider List (Mountains)

Company			Listing Submitted	1/5/2022	Area of state conducts work
Johnson, Spellman & Associates, Inc. 350 Research Ct. Suite 130 Peachtree Corners, GA 30092			Phone (770) 447-4555 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	Engineering- Design Services	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms			Other: Engineering-Design Services		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	Engineering-Design Services		
Soil and Water Testing Lab:	No				

Company			Listing Submitted	12/20/2022	Area of state conducts work
Jones Covey Group 9595 Lucas Ranch Rd STE 100 Rancho Cucamonga, CA 91730			Phone (888) 972-7581 Fax (909) 484-0300 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	8/10/2021	Area of state conducts work	
Martin & Slagle GeoSciences, PA 173 Sloan Road Franklin, NC 28734			Phone 8286347741 Fax Website martinandslagle.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	4/20/2023	Area of state conducts work	
MGF Environmental, PLLC 288 Gap Creek Rd Fletcher, NC 28732			Phone (904) 814-3680 Fax Website mgfenvironmental.com			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		9/8/2022		Area of state conducts work	
Mid-Atlantic Associates, Inc. 409 Rogers View Ct Raleigh, NC 27610		Phone (919) 250-9918 Fax (919) 250-9950 Website www.maaonline.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
NPCCM 7300 glenwood ave. raleigh, NC 27612		Phone (919) 782-4411 Fax (919) 782-4414 Website www.ncpcm.org		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	Engineering on UST Installations				
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		2/28/2022		Area of state conducts work	
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360		Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		<u>Yes</u>	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		<u>Yes</u>	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		<u>Yes</u>	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		<u>Yes</u>	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		<u>Yes</u>	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		<u>Yes</u>	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		<u>Yes</u>	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Peak Hydrogeologic, PLLC 470 Hogback Mtn Rd Tryon, NC 28782		Phone (828) 817-5209 Fax Website https://peakhydrogeologic.com				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

UST Service Provider List (Mountains)

Company			Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037			Phone (704) 335-8801 Fax (704) 342-1672 Website www.petroleumequipment.net		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>	
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>	
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>	
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>	
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>	
Environmental Service Firms					Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

Company			Listing Submitted	3/31/2022	Area of state conducts work	
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027			Phone (980) 781-1000 Fax Website www.petroleumtec.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	No	Other:	Tank Cleaning	UST Piping/Sump Installation:	No	
Line Tightness Testing:	No			UST System Removal:	No	
Environmental Service Firms					Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>			
Oil and Solvent Recycling:	No	Other:	Tank Cleaning			
Soil and Water Testing Lab:	No					

UST Service Provider List (Mountains)

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Pilot Geological , PLLC PO Box 128 743 Park Lawn Court Kernersville, NC 27285		Phone (336) 870-3095 Fax (336) 310-4527 Website www.pilotenviro.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Precision Tank Service 737 Zimmer Road Fort Mill , SC 29707		Phone (704) 892-8600 Fax (704) 892-8711 Website www.precisiontankservice.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company	Listing Submitted		12/30/2021	Area of state conducts work	
Precision Tank Service 737 Zimmer Road Fort Mill , SC 29707	Phone (704) 892-8600 Fax (704) 892-8711 Website www.precisiontankservice.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring			UST Equipmment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company		Listing Submitted		1/3/2022		Area of state conducts work	
Pyramid Environmental & Engineering, PC 503 Industrial Avenue Greensboro, NC 27406		Phone	(336) 335-3174	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
		Fax	(336) 691-0648				
		Website	www.PyramidEnvironmental.com				
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		12/30/2021		Area of state conducts work	
Singleton Environmental, Inc. PO Box 604 Fletcher, NC 28732		Phone (828) 508-4510 Fax Website singletonenvironmental.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted	12/30/2021	Area of state conducts work	
Superior Services PO Box 982 Hendersonville, NC		Phone (828) 698-6286 Fax (828) 698-6294 Website www.superiorservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: repair and lining, AST Inspections, Repairs and Lining		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company		Listing Submitted	12/30/2021	Area of state conducts work	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302		Phone (919) 563-9091 Fax (919) 563-9095 Website www.terraquestpc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	Yes				

UST Service Provider List (Mountains)

Company				Listing Submitted	3/6/2024	Area of state conducts work	
Titan Environmental Group 2005 Citation Drive Garner, NC 27529		Phone (984) 200-6825 Fax Website www.titanenvirogroup.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	1/26/2022	Area of state conducts work	
UST Corrosion Management, Inc. 2764 Pleasant Rd #10714 Fort Mill, SC 29708		Phone (888) 822-2431 Fax (803) 802-0561 Website www.ustcorrosion.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		1/26/2022		Area of state conducts work	
UST Corrosion Management, Inc. 2764 Pleasant Rd #10714 Fort Mill, SC 29708		Phone	(888) 822-2431			Coastal (East of I-95): Yes	
		Fax	(803) 802-0561			Central (West of I-95 and East of I-77): Yes	
		Website	www.ustcorrosion.com			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		7/14/2022		Area of state conducts work	
VALLEY TANK TESTING 451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572		Phone (813) 671-9065 Fax (866) 328-9796 Website WWW.VALLEYTANK.COM		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		1/31/2023		Area of state conducts work	
Valor Construction LLC PO Box 680654 Fort Payne, AL 35968		Phone (205) 577-1035 Fax Website				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	Yes		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		10/5/2021		Area of state conducts work	
VITAL FUEL SYSTEMS INC. 1076 CLASSIC ROAD APEX, NC 27540		Phone (919) 303-7374 Fax (919) 303-7399 Website WWW.VITALFUELSYSTEMS.COM				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			Yes
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			Yes
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			Yes
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			Yes
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			Yes
Line Tightness Testing:	No			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340 Fax Website www.withersravenel.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/1/2023		Area of state conducts work	
Withers Ravenel, Inc. 115 MacKenan Drive Cary, NC 27591		Phone (919) 469-3340 Fax Website www.withersravenel.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						